



MN_Clay County_Frederick Martin Hotel_0001
Exterior, north elevation, camera facing south.



MN_Clay County_Frederick Martin Hotel_0002
Exterior, north and west elevations, camera facing southeast.



MN_Clay County_Frederick Martin Hotel_0003

Exterior, west and south elevations, camera facing northeast.



MN_Clay County_Frederick Martin Hotel_0004
Exterior, south and east elevations, camera facing northwest.



MN_Clay County_Frederick Martin Hotel_0005
Exterior, primary entrance at north elevation, camera facing south.



MN_Clay County_Frederick Martin Hotel_0006
Exterior, secondary entrance at east elevation, camera facing west.



MN_Clay County_Frederick Martin Hotel_0007
Interior, view of public lobby including access to vertical circulation, Level 1, camera facing southeast.



MN_Clay County_Frederick Martin Hotel_0008
Interior, view of bank lobby including secondary entrance, Level 1, camera facing northwest.



MN_Clay County_Frederick Martin Hotel_0009
Interior, view of office space with parquet flooring, Level 2, camera facing east.



MN_Clay County_Frederick Martin Hotel_0010
Interior, view of corridor, Level 3 (Levels 2-6 typical), camera facing north.



MN_Clay County_Frederick Martin Hotel_0011

Interior, view of office space, Level 5 (condition typical of office spaces on Levels 2-6), camera facing east.





MN_Clay County_Frederick Martin Hotel_0013
Interior, view of dumb waiters, Level 2, camera facing north.



MN_Clay County_Frederick Martin Hotel_0014
Interior, view of ribbon windows, Level 7, camera facing northeast.



MN_Clay County_Frederick Martin Hotel_0015
Interior, view of Level 7, camera facing north/northwest.



MN_Clay County_Frederick Martin Hotel_0016
Interior, view of Level 7, camera facing south.




MN_Clay County_Frederick Martin Hotel_0017

17 of 23

Exterior, view of Level 7 sunshade track, corrugated metal paneling, and ribbon windows, south elevation, camera facing east/northeast.



MN_Clay County_Frederick Martin Hotel_0018
Interior, view of typical original aluminum window, Level 4, camera facing east.





MN_Clay County_Frederick Martin Hotel_0020
Interior, view of door at Level 2, camera facing west/northwest.



MN_Clay County_Frederick Martin Hotel_0021
Interior, view of parquet flooring in Lower Level, camera facing southeast.



MN_Clay County_Frederick Martin Hotel_0022
Interior, view of linoleum tile in Lower Level, camera facing west.

