


Administration

5. Centennial Office Building: exterior stone joint failure



5. Centennial Office Building: ceiling and window leaks



5. Centennial Office Building: exterior wall leak




5. Centennial Office Building: external sealant failure



5. Centennial Office Building: roof not draining correctly



6. Capital Monuments and Memorials*: Women's Suffrage
(*The CAAPB also proposes this project as their #1 priority)



6. Capital Monuments and Memorials: Women's Suffrage



6. Capital Monuments and Memorials: Roy Wilkins (Intended to be an interactive memorial, moving parts no longer function correctly)




6. Capital Monuments and Memorials: USS Ward Gun

This gun is from the USS Ward, the ship that fired the first US shots at Pearl Harbor. The ship included service members from St. Paul, MN.



11. State Office Building: wood veneer separating in hearing chambers



11. State Office Building: ceiling settlement cracking (same area, multiple floors)



11. State Office Building: old and damaged workstations



11. State Office Building: outdated electrical systems



11. State Office Building: cracked floor slab

