

CORRECTIONS

Asset Preservation:

1. MCF-Stillwater pipe



1. MCF-Stillwater Window



1. MCF-Faribault Deterioration



1. MCF-Moose Lake water running in due to roof and run-off from outside parking lot.



1. MCF-Moose Lake tunnel corrosion



1. MCF-Lino Lakes Tuckpointing



4. MCF-St. Cloud Plumbing and Ventilation:



6. MCF-Moose Lake Master Control Renovation:

Current control center lacks space, has inadequate air quality and distribution, and security equipment is open and seen from the window that offenders pass by.

