MINNESOTA ENTERPRISE REAL PROPERTY FACILITY CONDITION ASSESSMENT (FCA) REPORT

2019

DEPARTMENT OF ADMINISTRATION
ENTERPRISE REAL PROPERTY

ABSTRACT:

The Minnesota Enterprise Real Property Facility Condition Assessment Report is a comprehensive report depicting the conditions of all of Minnesota State's owned buildings in a standardized and objective means. This report is intended to be used to compare agency to agency buildings, and to justify bonding projects and asset preservation funding.

The report is derived from a single enterprise database and application (ARCHIBUS). All assessment data is gathered using the standardized Minnesota Facility Condition Assessment (FCA) Process. This process was a combined effort developed by the Enterprise Real Property Program (ERPP), Facility Engineering Associates (FEA), and a steering team led by key agency representatives in 2013.

MINNESOTA FCA PROCESS:

(FCA) Facility Condition Assessment: Is an industry term that describes the process of professionally analyzing the condition of a group of facilities that may vary in terms of age, design, construction methods, and materials, in order to determine the overall state of the facility. (FCA is essentially a method for walking through a building, rating the conditions of various building systems, and documenting the information to get an overall picture of what state the building is in.)

The standardized Minnesota FCA Process is based on the Backlog of Maintenance and Repair (BMAR) FCA Process approach.

> *"The "BMAR FCA Process" is named after the process developed by NASA in the 1990s in response to the need to develop a more reliable FCA process with a reasonable level of effort."*
>
> *(FEA, 2013)*

All costs generated by the Minnesota FCA Process and ARCHIBUS application are derived from up-to-date RS-Means Construction Costs. The BMAR approach requires the following to develop and implement the process:

- **Development of 23 Cost Models;**
- **Standardizing how Current Replacement Value (CRV) will be calculated;**
- **An agreed upon 1-5 scoring method;**
- **Standardizing how Deferred Maintenance (DM) will be calculated;**
- **Standardizing how Adjusted Deferred Maintenance (ADM) will be calculated;**
- **Standardizing a Facility Condition Index (FCI) calculation and ratings;**
- **Standardizing a Reference Field Guide.**

23 Cost Models:

Developed to address the majority of agency's buildings. The cost models are numbered M01 through M23 and each is based on a combination of type of construction and potential uses. The models are designed based on Level 3 UniFormat II building classification systems. All costs were produced from RS-Means Construction Cost data. Cost data was applied to the cost model's UniFormat classification system ids called cost model matrix ids, or also referred to as system unit costs. The cost model matrix id costs/system unit costs are used to calculate CRV, DM and FCI.

Current Replacement Value (CRV):

Calculated dollar amount representing the estimated cost to replace a building. CRV is based on RS-Means construction costs for basic Labor, Materials, and Equipment. (CRV costs are estimates and DO NOT depict actual construction project costs.) A system quantity is needed from the building being assessed and is applied as a multiplying factor to the system unit cost. Example: a system quantity for a building's foundation would be 100,000 square feet which is the building's footprint square footage. CRV is calculated as…

BUILDING CRV = (SUM OF SYSTEMS CRV)

SYSTEMS CRV = (SYSTEM UNIT COST * SYSTEM QUANTITY)

1-5 scoring method:

Systems are scored from 5 (best) to 1 (worst). The score is determined from a combination of conditions based on the established deficiency ranges and the rules established in the MN Field Reference Guide.

Condition rating 1 = Crisis
Condition rating 2 = Poor
Condition rating 3 = Fair
Condition rating 4 = Good
Condition rating 5 = Excellent

Deferred Maintenance (DM):

Based on the standardization of cost models and the adoption of a rule-based rating system. The DM for a given system is algorithm-based, as required of a 'best practice' FCA process. (DM costs are estimates and DO NOT depict actual construction project costs.) Applied to each system for a given building, the process yields justifiable, repeatable results. DM is calculated as…

BUILDING DM = (SUM OF SYSTEMS DM)

SYSTEMS DM = (SYSTEM CRV * %DM)

Condition rating 1 = 100% DM
Condition rating 2 = 75% DM
Condition rating 3 = 33% DM
Condition rating 4 = 10% DM
Condition rating 5 = 2% DM

Adjusted Deferred Maintenance (ADM):

The ADM is a lower and more reasonable value than the DM value. It is intended to derive only the local condition rating 1 and 2 items (Crisis and Poor) from all systems regardless of the system rating. The ADM value is perceived as the backlog needed to be taken care of to bring a building's overall condition rating to an acceptable Fair rating. (ADM costs are estimates and DO NOT depict actual construction project costs.) ADM is calculated as…

BUILDING ADM = (SUM OF SYSTEMS ADM)

SYSTEMS ADM = (SYSTEM CRV * %CRV)

Condition rating 1 = 100% CRV
Condition rating 2 = 100% CRV
Condition rating 3 = 3.75% CRV
Condition rating 4 = 1.00% CRV
Condition rating 5 = 0.25% CRV

Facility Condition Index (FCI) calculation and ratings:

The industry-standard FCI is the condition metric calculated for each building. The FCI provides an excellent means for maintenance prioritization based on overall building conditions, and provides insight to problem areas, neglected building systems, or where maintenance needs to be applied based on limited funds. FCI is calculated as…

BUILDING FCI = (SUM OF BUILDING DM) / (SUM OF BUILDING CRV)

Rating Scale:

Excellent = *Building FCI < 0.05*
Good = *0.05 < Building FCI < 0.15*
Fair = *0.15 < Building FCI < 0.30*
Poor = *0.30 < Building FCI < 0.50*
Crisis = *Building FCI > 0.50*

Reference Field Guide:

Each assessor receives a Reference Field Guide in which they are trained to use throughout the entire assessment process. The Reference Field Guide along with calibration training maintains objectivity to the FCA process. The guide contains all UniFormat systems that should be evaluated with clear criteria for rating the condition of each system.

SUMMARY

MINNESOTA OWNED BUILDINGS:

- 19 State Agencies with custodial control
- 4,832 buildings
- 33,384,872 square feet

(Totals are excluding Department of Military Affairs federally funded 1,250 buildings – 2,990,764 square feet)

FCA DATA:

- 99.9% of buildings assessed
- $9,384,424,431 Current Replacement Value
- $1,703,352,754 Deferred Maintenance Value
- $734,843,711 Adjusted Deferred Maintenance Value
- 39 years of age (average age of buildings)
- 39% buildings over the age of 40 years

REPORT DETAILS

Agency	Percentage of Completed FCA Square Footage	Totals for agency		Totals for Completed FCAs	
B04-Department of Agriculture	100%	Total Building Count:	1	Total Completed Building FCA Count:	1
		Total Gross Square Footage:	8,304	Total Completed FCA Square Footage:	8,304
B13-Department of Commerce	100%	Total Building Count:	1	Total Completed Building FCA Count:	1
		Total Gross Square Footage:	3,216	Total Completed FCA Square Footage:	3,216
B22-Employment and Economic Development	100%	Total Building Count:	2	Total Completed Building FCA Count:	2
		Total Gross Square Footage:	27,051	Total Completed FCA Square Footage:	27,051
B43-Iron Range Resources	99.9%	Total Building Count:	64	Total Completed Building FCA Count:	63
		Total Gross Square Footage:	301,514	Total Completed FCA Square Footage:	301,314
B9D-Amateur Sports Commission	100%	Total Building Count:	24	Total Completed Building FCA Count:	24
		Total Gross Square Footage:	807,054	Total Completed FCA Square Footage:	807,054
E25-Perpich Center	100%	Total Building Count:	5	Total Completed Building FCA Count:	5
		Total Gross Square Footage:	176,361	Total Completed FCA Square Footage:	176,361
E40-Historical Society	100%	Total Building Count:	153	Total Completed Building FCA Count:	153
		Total Gross Square Footage:	1,284,098	Total Completed FCA Square Footage:	1,284,098

Agency	Percentage of Completed FCA Square Footage	Totals for agency		Totals for Completed FCAs	
E44-Minnesota State Academies	100%	Total Building Count:	19	Total Completed Building FCA Count:	19
		Total Gross Square Footage:	424,709	Total Completed FCA Square Footage:	424,709
E77-MN Zoological Garden	100%	Total Building Count:	123	Total Completed Building FCA Count:	123
		Total Gross Square Footage:	647,692	Total Completed FCA Square Footage:	647,692
G02-Department of Administration	100%	Total Building Count:	30	Total Completed Building FCA Count:	30
		Total Gross Square Footage:	5,531,893	Total Completed FCA Square Footage:	5,531,893
G62-MN State Retirement Systems	100%	Total Building Count:	2	Total Completed Building FCA Count:	2
		Total Gross Square Footage:	259,837	Total Completed FCA Square Footage:	259,837
H55-Department of Human Services	100%	Total Building Count:	160	Total Completed Building FCA Count:	160
		Total Gross Square Footage:	2,535,241	Total Completed FCA Square Footage:	2,535,241
H75-MN Veterans Homes	100%	Total Building Count:	66	Total Completed Building FCA Count:	66
		Total Gross Square Footage:	1,254,186	Total Completed FCA Square Footage:	1,254,186
P01-Military Affairs	100%	Total Building Count:	67	Total Completed Building FCA Count:	67
		Total Gross Square Footage:	2,587,697	Total Completed FCA Square Footage:	2,587,697
P07-Department of Public Safety	100%	Total Building Count:	6	Total Completed Building FCA Count:	6
		Total Gross Square Footage:	20,360	Total Completed FCA Square Footage:	20,360

Agency	Percentage of Completed FCA Square Footage	Totals for agency		Totals for Completed FCAs	
P78-Department of Corrections	100%	Total Building Count:	325	Total Completed Building FCA Count:	325
		Total Gross Square Footage:	7,470,951	Total Completed FCA Square Footage:	7,470,951
R29-Department of Natural Resources	100%	Total Building Count:	2,877	Total Completed Building FCA Count:	2,877
		Total Gross Square Footage:	3,400,421	Total Completed FCA Square Footage:	3,400,421
R32-Pollution Control Agency	100%	Total Building Count:	18	Total Completed Building FCA Count:	18
		Total Gross Square Footage:	25,198	Total Completed FCA Square Footage:	25,198
T79-Department of Transportation	99.6%	Total Building Count:	889	Total Completed Building FCA Count:	884
		Total Gross Square Footage:	6,619,092	Total Completed FCA Square Footage:	6,593,033
Totals	99.9%	Total Building Count:	4,832	Total Completed Building FCA Count:	4,826
		Total Gross Square Footage:	33,384,872	Total Completed FCA Square Footage:	33,358,613

This report was run on 9/3/2019

All totals include buildings in a status of '1 Active-Owned', '6 Inactive-Owned, and '10 Active Under-Construction'.

P01-Military Affairs quantities for completed FCA square footage only includes State supported Armories. Federally supported buildings are not included.

T79-Department of Transportation quantities for completed FCA square footage does not include radio tower equipment facilities.

Number of Owned Buildings by Agency



9/3/2019

Square Footage of Owned Buildings and Assessed Buildings by Agency



9/3/2019

Replacement Value by Agency



9/3/2019

Deferred Maintenance by Agency



9/3/2019

The State Of Minnesota currently has a building portfolio with an **<u>average age of 39 years</u>**.

"The largest and most expensive of all asset renewal projects tend to occur during the 4th life stage. As a result, significant funds will need to be reinvested in the building and the standard operating and maintenance budgets will need to be revisited. Some of the assets have been replaced over the preceding 30-40 years and the owners and manager are now operating a building with assets at a variety of different ages. There is no longer a single baseline and the facility managers are tasked with tracking the different assets." (https://www.rdh.com/long-buildings-last/)



Number of Owned Buildings by Age



Number of Buildings by FCI Rating



LOCATION OF 267 CRISIS CONDITION BUILDINGS



LOCATION OF 719 POOR CONDITION BUILDINGS



Value of Deferred Maintenance by FCI Rating



Number of Buildings and Value of Deferred Maintenance by FCI Rating



Square Footage and Value of Deferred Maintenance by FCI Rating



Number of Buildings by FCI Rating 2015-2019



Square Footage by FCI Rating 2015-2019



Value of Deferred Maintenance by FCI Rating 2015-2019



Average Cost of Deferred Maintenance/System by FCI Rating



		FCI Rating Scoreboard					
Agency ID		Total	Crisis	Poor	Fair	Good	Excellent
Total	Project - Count	4,826	267	719	1,757	1,597	486
	Exterior Gross SqFt	33,358,613	1,274,075	4,669,323	11,720,206	12,059,820	3,635,188
	Current Replacement Value	$9,384,424,431	$212,364,428	$1,261,031,325	$3,508,854,299	$2,874,162,704	$1,528,011,674
	Deferred Maintenance	$1,703,352,754	$135,752,170	$452,010,694	$779,814,932	$287,968,563	$47,806,394
B04-Department of Agriculture	Project - Count	1			1		
	Exterior Gross SqFt	8,304			8,304		
	Current Replacement Value	$7,266,177			$7,266,177		
	Deferred Maintenance	$1,504,337			$1,504,337		
B13-Department of Commerce	Project - Count	1		1			
	Exterior Gross SqFt	3,216		3,216			
	Current Replacement Value	$827,431		$827,431			
	Deferred Maintenance	$334,339		$334,339			
B22-Employment and Economic Development	Project - Count	2				2	
	Exterior Gross SqFt	27,051				27,051	
	Current Replacement Value	$6,987,671				$6,987,671	
	Deferred Maintenance	$691,540				$691,540	
B43-Iron Range Resources	Project - Count	63	6	19	20	13	5
	Exterior Gross SqFt	301,314	66,864	56,003	135,183	42,599	665.18
	Current Replacement Value	$62,810,771	$5,897,408	$11,214,402	$34,684,104	$10,818,770	$196,087
	Deferred Maintenance	$16,485,322	$3,924,372	$3,821,995	$7,597,493	$1,135,583	$5,878
B9D-Amateur Sports Commission	Project - Count	24	1	3	5	15	
	Exterior Gross SqFt	807,054	5,006	63,905	516,131	222,012	
	Current Replacement Value	$182,312,460	$1,200,443	$14,750,586	$118,220,936	$48,140,496	
	Deferred Maintenance	$44,761,857	$637,679	$6,851,504	$30,857,616	$6,415,058	
E25-Perpich Center	Project - Count	5			3	1	1
	Exterior Gross SqFt	176,361			124,953	46,968	4,440
	Current Replacement Value	$38,634,848			$26,942,975	$11,045,977	$645,895
	Deferred Maintenance	$7,100,110			$6,301,876	$785,316	$12,918
E40-Historical Society	Project - Count	153	17	35	63	28	10
	Exterior Gross SqFt	1,284,098	93161.15	235,659	340,395	584,277	30,605
	Current Replacement Value	$329,782,217	$35,467,684	$72,513,516	$107,299,578	$106,416,481	$8,084,957
	Deferred Maintenance	$85,359,842	$22,096,764	$27,085,998	$22,846,204	$13,113,734	$217,142
E44-Minnesota State Academies	Project - Count	19	1	6	5	6	1
	Exterior Gross SqFt	424,709	7,107	54,262	114,916	221,549	26,874
	Current Replacement Value	$117,715,365	$1,522,531	$14,982,150	$35,665,254	$59,550,289	$5,995,142
	Deferred Maintenance	$23,333,201	$1,277,367	$5,427,737	$8,602,154	$7,901,793	$124,151
E77-MN Zoological Garden	Project - Count	123	2	17	42	48	14
	Exterior Gross SqFt	647,692	3,792	60,430	406,714	165,579	11,178
	Current Replacement Value	$186,124,735	$1,367,879	$22,925,970	$115,599,118	$42,588,550	$3,643,218
	Deferred Maintenance	$35,809,322	$940,949	$7,285,129	$24,202,676	$3,291,970	$88,598
G02-Department of Administration	Project - Count	30	1	2	6	16	5
	Exterior Gross SqFt	5,531,893	57,143	526,880	774,585	2,723,374	1,449,912
	Current Replacement Value	$1,796,608,880	$14,541,554	$56,036,777	$185,321,268	$625,137,513	$915,571,767
	Deferred Maintenance	$161,448,917	$9,830,951	$22,531,938	$43,939,922	$53,449,407	$31,696,700

Agency ID		Total	Crisis	Poor	Fair	Good	Excellent
G62-MN State Retirement Systems	Project - Count	2				2	
	Exterior Gross SqFt	259,837				259,837	
	Current Replacement Value	$48,836,924				$48,836,924	
	Deferred Maintenance	$2,850,583				$2,850,583	
H55-Department of Human Services	Project - Count	160	6	26	71	42	15
	Exterior Gross SqFt	2,535,241	123,339	549,123	1,105,400	681,845	75,534
	Current Replacement Value	$1,032,376,225	$38,463,298	$173,562,358	$401,661,111	$244,575,826	$174,113,632
	Deferred Maintenance	$192,218,113	$20,392,141	$61,966,288	$83,101,180	$23,006,460	$3,752,044
H75-MN Veterans Homes	Project - Count	66	6	10	12	23	15
	Exterior Gross SqFt	1,254,186	40,421	262,145	258,525	384,334	308,760
	Current Replacement Value	$327,850,657	$6,966,879	$59,089,182	$78,448,231	$106,939,125	$76,407,239
	Deferred Maintenance	$57,809,831	$4,469,673	$23,056,403	$17,703,765	$9,995,437	$2,584,553
P01-Military Affairs	Project - Count	67		21	24	20	2
	Exterior Gross SqFt	2,587,697		956,221	652,224	836,042	143,210
	Current Replacement Value	$634,076,999		$219,674,375	$175,065,976	$202,897,241	$36,439,406
	Deferred Maintenance	$140,942,433		$81,717,265	$39,464,938	$18,861,034	$899,197
P07-Department of Public Safety	Project - Count	6			3	3	
	Exterior Gross SqFt	20,360			18,933	1,427	
	Current Replacement Value	$4,816,224			$4,680,003	$136,222	
	Deferred Maintenance	$985,284			$970,578	$14,706	
P78-Department of Corrections	Project - Count	325	15	59	150	94	7
	Exterior Gross SqFt	7,470,951	345,252	1,255,313	3,151,047	2,488,350	230,989
	Current Replacement Value	$2,665,141,983	$58,693,405	$495,314,028	$1,334,674,863	$724,149,094	$52,310,593
	Deferred Maintenance	$594,971,613	$36,627,240	$167,731,646	$308,211,741	$81,037,599	$1,363,386
R29-Department of Natural Resources	Project - Count	2,877	192	464	1,093	869	259
	Exterior Gross SqFt	3,400,421	512,668	431,473	1,245,680	985,976	224,624
	Current Replacement Value	$644,663,107	$46,100,847	$87,032,854	$266,931,697	$197,825,653	$46,772,055
	Deferred Maintenance	$148,432,771	$33,985,497	$32,702,158	$57,822,301	$22,650,460	$1,272,356
R32-Pollution Control Agency	Project - Count	18	1	1	7	8	1
	Exterior Gross SqFt	25,198	64	8,107	12,290	4,637	100
	Current Replacement Value	$11,329,612	$6,719	$921,422	$1,565,701	$8,826,226	$9,545
	Deferred Maintenance	$1,507,560	$3,688	$285,476	$335,089	$883,116	$191
T79-Department of Transportation	Project - Count	884	19	55	252	407	151
	Exterior Gross SqFt	6,593,033	19,259	206,587	2,854,927	2,383,966	1,128,295
	Current Replacement Value	$1,286,262,146	$2,135,782	$32,186,273	$614,827,308	$429,290,646	$207,822,137
	Deferred Maintenance	$186,805,779	$1,565,850	$11,212,819	$126,353,061	$41,884,768	$5,789,281

This report was created on 9/3/2019.

		System Rating Scoreboard					
Agency ID		Total	Crisis	Poor	Fair	Good	Excellent
Total	System - Count	60,064	691	3,578	19,182	24,261	12,352
	Current Replacement Value	$9,384,424,431	$105,456,528	$493,697,757	$2,545,247,604	$3,285,677,846	$2,954,344,695
	Deferred Maintenance	$1,703,352,754	$105,456,528	$370,276,300	$839,933,769	$328,594,616	$59,091,540
	Adjusted DM	$734,843,711	$105,456,528	$493,697,757	$95,446,785	$32,856,778	$7,385,862
B04-Department of Agriculture	System - Count	19		2	6	10	1
	Current Replacement Value	$7,266,177		$359,422	$2,407,710	$4,378,070	$120,975
	Deferred Maintenance	$1,504,337		$269,567	$794,544	$437,807	$2,420
	Adjusted DM	$493,794		$359,422	$90,289	$43,781	$302
B13-Department of Commerce	System - Count	26	3	8	6	6	3
	Current Replacement Value	$827,431	$70,120	$222,816	$237,033	$161,708	$135,755
	Deferred Maintenance	$334,339	$70,120	$167,112	$78,221	$16,171	$2,715
	Adjusted DM	$303,781	$70,120	$222,816	$8,889	$1,617	$339
B22-Employment and Economic Development	System - Count	49			8	22	19
	Current Replacement Value	$6,987,671			$874,043	$3,510,420	$2,603,208
	Deferred Maintenance	$691,540			$288,434	$351,042	$52,064
	Adjusted DM	$74,389			$32,777	$35,104	$6,508
B43-Iron Range Resources	System - Count	770	7	80	285	197	201
	Current Replacement Value	$62,810,771	$235,931	$8,553,749	$23,813,405	$17,143,766	$13,063,919
	Deferred Maintenance	$16,485,322	$235,931	$6,415,311	$7,858,424	$1,714,377	$261,278
	Adjusted DM	$9,886,780	$235,931	$8,553,749	$893,003	$171,438	$32,660
B9D-Amateur Sports Commission	System - Count	371	9	38	73	210	41
	Current Replacement Value	$182,312,460	$3,991,725	$12,029,746	$74,105,373	$68,116,709	$24,068,907
	Deferred Maintenance	$44,761,857	$3,991,725	$9,022,310	$24,454,773	$6,811,671	$481,378
	Adjusted DM	$19,541,762	$3,991,725	$12,029,746	$2,778,951	$681,167	$60,172
E25-Perpich Center	System - Count	146	2	4	39	43	58
	Current Replacement Value	$38,634,848	$692,173	$1,281,137	$12,346,726	$11,079,602	$13,235,209
	Deferred Maintenance	$7,100,110	$692,173	$960,853	$4,074,420	$1,107,960	$264,704
	Adjusted DM	$2,580,197	$692,173	$1,281,137	$463,002	$110,796	$33,088
E40-Historical Society	System - Count	2,063	62	194	632	890	285
	Current Replacement Value	$329,782,217	$12,013,762	$39,597,768	$82,578,291	$156,063,379	$39,529,017
	Deferred Maintenance	$85,359,842	$12,013,762	$29,698,326	$27,250,836	$15,606,338	$790,580
	Adjusted DM	$56,367,672	$12,013,762	$39,597,768	$3,096,686	$1,560,634	$98,823
E44-Minnesota State Academies	System - Count	453	11	30	169	204	39
	Current Replacement Value	$117,715,365	$929,206	$6,964,559	$29,157,728	$74,315,603	$6,348,268
	Deferred Maintenance	$23,333,201	$929,206	$5,223,419	$9,622,050	$7,431,560	$126,965
	Adjusted DM	$9,746,206	$929,206	$6,964,559	$1,093,415	$743,156	$15,871
E77-MN Zoological Garden	System - Count	1,579	5	104	466	537	467
	Current Replacement Value	$186,124,735	$233,069	$6,258,317	$70,515,030	$67,877,360	$41,240,959
	Deferred Maintenance	$35,809,322	$233,069	$4,693,738	$23,269,960	$6,787,736	$824,819
	Adjusted DM	$9,917,576	$233,069	$6,258,317	$2,644,314	$678,774	$103,102
G02-Department of Administration	System - Count	854	20	29	159	311	335
	Current Replacement Value	$1,796,608,880	$15,146,796	$26,954,487	$163,721,616	$503,030,026	$1,087,755,954
	Deferred Maintenance	$161,448,917	$15,146,796	$20,215,865	$54,028,133	$50,303,003	$21,755,119
	Adjusted DM	$55,990,534	$15,146,796	$26,954,487	$6,139,561	$5,030,300	$2,719,390

Agency ID		Total	Crisis	Poor	Fair	Good	Excellent
G62-MN State Retirement Systems	System - Count	52		1	2	26	23
	Current Replacement Value	$48,836,924		$88,817	$620,839	$20,206,850	$27,920,417
	Deferred Maintenance	$2,850,583		$66,613	$204,877	$2,020,685	$558,408
	Adjusted DM	$383,968		$88,817	$23,281	$202,069	$69,801
H55-Department of Human Services	System - Count	3,227	53	235	946	1,139	854
	Current Replacement Value	$1,032,376,225	$10,736,044	$98,221,110	$220,857,651	$261,024,799	$441,536,621
	Deferred Maintenance	$192,218,113	$10,736,044	$73,665,832	$72,883,025	$26,102,480	$8,830,732
	Adjusted DM	$120,953,405	$10,736,044	$98,221,110	$8,282,162	$2,610,248	$1,103,842
H75-MN Veterans Homes	System - Count	1,224	50	138	219	430	387
	Current Replacement Value	$327,850,657	$5,217,641	$26,119,872	$54,354,190	$127,777,794	$114,381,160
	Deferred Maintenance	$57,809,831	$5,217,641	$19,589,904	$17,936,883	$12,777,779	$2,287,623
	Adjusted DM	$34,939,526	$5,217,641	$26,119,872	$2,038,282	$1,277,778	$285,953
P01-Military Affairs	System - Count	1,941	9	120	711	780	321
	Current Replacement Value	$634,076,999	$1,762,929	$46,282,877	$240,506,529	$227,153,281	$118,371,383
	Deferred Maintenance	$140,942,433	$1,762,929	$34,712,158	$79,367,154	$22,728,226	$2,371,966
	Adjusted DM	$59,632,262	$1,762,929	$46,282,877	$9,018,995	$2,271,533	$295,928
P07-Department of Public Safety	System - Count	78		1	32	26	19
	Current Replacement Value	$4,816,224		$405,084	$1,517,665	$1,534,651	$1,358,825
	Deferred Maintenance	$985,284		$303,813	$500,829	$153,465	$27,176
	Adjusted DM	$480,740		$405,084	$56,912	$15,347	$3,397
P78-Department of Corrections	System - Count	6,190	89	317	2,322	2,427	1,035
	Current Replacement Value	$2,665,141,983	$26,530,687	$132,527,533	$1,107,646,803	$944,413,657	$454,023,303
	Deferred Maintenance	$594,971,613	$26,530,687	$99,395,650	$365,523,445	$94,441,366	$9,080,466
	Adjusted DM	$211,174,169	$26,530,687	$132,527,533	$41,536,755	$9,444,137	$1,135,058
R29-Department of Natural Resources	System - Count	29,335	327	1,759	10,397	12,528	4,324
	Current Replacement Value	$644,663,107	$20,937,351	$44,702,068	$193,785,814	$278,868,062	$106,369,812
	Deferred Maintenance	$148,432,771	$20,937,351	$33,529,533	$63,951,378	$27,887,006	$2,127,503
	Adjusted DM	$75,960,992	$20,937,351	$44,702,068	$7,266,968	$2,788,681	$265,925
R32-Pollution Control Agency	System - Count	165		8	26	121	10
	Current Replacement Value	$11,329,612		$209,610	$1,047,967	$10,038,527	$33,507
	Deferred Maintenance	$1,507,560		$157,208	$345,829	$1,003,853	$670
	Adjusted DM	$349,378		$209,610	$39,299	$100,385	$84
T79-Department of Transportation	System - Count	11,522	44	510	2,684	4,354	3,930
	Current Replacement Value	$1,286,262,146	$6,959,096	$42,918,783	$265,153,190	$508,983,581	$462,247,495
	Deferred Maintenance	$186,805,779	$6,959,096	$32,189,088	$87,500,553	$50,912,093	$9,244,950
	Adjusted DM	$66,066,578	$6,959,096	$42,918,783	$9,943,245	$5,089,836	$1,155,619

This report was created on 9/3/2019.

DEPARTMENT OF ADMINISTRATION
ENTERPRISE REAL PROPERTY

Facility Condition Assessments (FCA) by Agency

9/4/2019

Report Note: This report includes all agency facility condition assessment totals for all agencies with assessed buildings. This report is intended to be used for Enterprise FCA reporting. Report is grouped by agency name and ordered by ascending agency code.

Agency: B04 - Agriculture

FCI Rating:	Fair	**Current Replacement Value:**	$7,266,177	**Ext. Gross Area:**	8,304
Facility Condition Index:	0.21	**Deferred Maintenance:**	$1,504,337	**Building Count:**	1

Agency: B13 - Department of Commerce

FCI Rating:	Poor	**Current Replacement Value:**	$827,431	**Ext. Gross Area:**	3,216
Facility Condition Index:	0.40	**Deferred Maintenance:**	$334,339	**Building Count:**	1

Agency: B22 - Department of Employment & Economic Development

FCI Rating:	Good	**Current Replacement Value:**	$6,987,671	**Ext. Gross Area:**	27,051
Facility Condition Index:	0.10	**Deferred Maintenance:**	$691,540	**Building Count:**	2

Agency: B43 - Iron Range Resource

FCI Rating:	Fair	**Current Replacement Value:**	$62,810,771	**Ext. Gross Area:**	301,314
Facility Condition Index:	0.26	**Deferred Maintenance:**	$16,485,322	**Building Count:**	63

Agency: B9D - Amateur Sports Commission

FCI Rating:	Fair	**Current Replacement Value:**	$182,312,460	**Ext. Gross Area:**	807,054
Facility Condition Index:	0.25	**Deferred Maintenance:**	$44,761,857	**Building Count:**	24

Agency: E25 - Perpich Center

FCI Rating:	Fair	**Current Replacement Value:**	$38,634,848	**Ext. Gross Area:**	176,361
Facility Condition Index:	0.18	**Deferred Maintenance:**	$7,100,110	**Building Count:**	5

Agency: E40 - Historical Society

FCI Rating:	Fair	**Current Replacement Value:**	$329,782,217	**Ext. Gross Area:**	1,284,098
Facility Condition Index:	0.26	**Deferred Maintenance:**	$85,359,842	**Building Count:**	153

Agency: E44 - Minnesota State Academies

FCI Rating:	Fair	**Current Replacement Value:**	$117,715,365	**Ext. Gross Area:**	424,709
Facility Condition Index:	0.20	**Deferred Maintenance:**	$23,333,201	**Building Count:**	19

Agency: E77 - Minnesota Zoological Garden

FCI Rating:	Fair	**Current Replacement Value:**	$186,124,735	**Ext. Gross Area:**	647,692
Facility Condition Index:	0.19	**Deferred Maintenance:**	$35,809,322	**Building Count:**	123

Agency: G02 - Department of Administration

FCI Rating:	Good	**Current Replacement Value:**	$1,796,608,880	**Ext. Gross Area:**	5,531,893
Facility Condition Index:	0.09	**Deferred Maintenance:**	$161,448,917	**Building Count:**	30

Agency: G62 - MN State Retirement Systems

FCI Rating:	Good	**Current Replacement Value:**	$48,836,924	**Ext. Gross Area:**	259,837
Facility Condition Index:	0.06	**Deferred Maintenance:**	$2,850,583	**Building Count:**	2

Agency: H55 - Department of Human Services

FCI Rating:	Fair	**Current Replacement Value:**	$1,032,376,225	**Ext. Gross Area:**	2,535,241
Facility Condition Index:	0.19	**Deferred Maintenance:**	$192,218,113	**Building Count:**	160

Agency: H75 - Minnesota Veterans Affairs

FCI Rating:	Fair	**Current Replacement Value:**	$327,850,657	**Ext. Gross Area:**	1,254,186
Facility Condition Index:	0.18	**Deferred Maintenance:**	$57,809,831	**Building Count:**	66

Agency: P01 - Military Affairs

FCI Rating:	Fair	**Current Replacement Value:**	$634,076,999	**Ext. Gross Area:**	2,587,697
Facility Condition Index:	0.22	**Deferred Maintenance:**	$140,942,433	**Building Count:**	67

Agency: P07 - Public Safety

FCI Rating:	Fair	**Current Replacement Value:**	$4,816,224	**Ext. Gross Area:**	20,360
Facility Condition Index:	0.20	**Deferred Maintenance:**	$985,284	**Building Count:**	6

Agency: P78 - Department of Corrections

FCI Rating:	Fair	**Current Replacement Value:**	$2,665,141,983	**Ext. Gross Area:**	7,470,951
Facility Condition Index:	0.22	**Deferred Maintenance:**	$594,971,613	**Building Count:**	325

Agency: R29 - Department of Natural Resources

FCI Rating:	Fair	**Current Replacement Value:**	$644,657,931	**Ext. Gross Area:**	3,400,421
Facility Condition Index:	0.23	**Deferred Maintenance:**	$148,431,235	**Building Count:**	2,877

Agency: R32 - Pollution Control Agency

FCI Rating:	Good	**Current Replacement Value:**	$11,329,612	**Ext. Gross Area:**	25,198
Facility Condition Index:	0.13	**Deferred Maintenance:**	$1,507,560	**Building Count:**	18

Agency: T79 - Department of Transportation

FCI Rating:	Good	**Current Replacement Value:**	$1,286,262,146	**Ext. Gross Area:**	6,593,033
Facility Condition Index:	0.15	**Deferred Maintenance:**	$186,805,779	**Building Count:**	884

DEPARTMENT OF ADMINISTRATION
ENTERPRISE REAL PROPERTY

Facility Condition Assessments (FCA) by Building

9/4/2019

Report Note: This report includes all agency facility condition assessment totals for each agency and each building assessed. This report is intended to be used for Enterprise FCA reporting. Report is grouped by agency name and site code, and ordered by ascending building code.

Agency: B04 - Agriculture

FCI Rating:	Fair	**Current Replacement Value:**	$7,266,177	**Ext. Gross Area:**	8,304
Facility Condition Index:	0.21	**Deferred Maintenance:**	$1,504,337	**Building Count:**	1

Site: B04100 - East Grand Forks

Building Code:	B0410000312	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$7,266,177
Building Name:	East Grand Forks Potato Inspection	**Address:**	312 4th Ave NE	**Deferred Maintenance:**	$1,504,337
Facility Condition Index:	0.21 - Fair	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	8,304

Agency: B13 - Department of Commerce

FCI Rating:	Poor	**Current Replacement Value:**	$827,431	**Ext. Gross Area:**	3,216
Facility Condition Index:	0.40	**Deferred Maintenance:**	$334,339	**Building Count:**	1

Site: B13000 - Master Scale

Building Code:	B1300000001	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$827,431
Building Name:	Master Scale	**Address:**	475 Prior Ave	**Deferred Maintenance:**	$334,339
Facility Condition Index:	0.40 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,216

Agency: B22 - Department of Employment & Economic Development

FCI Rating:	Good	**Current Replacement Value:**	$6,987,671	**Ext. Gross Area:**	27,051
Facility Condition Index:	0.10	**Deferred Maintenance:**	$691,540	**Building Count:**	2

Site: B22000 - St. Cloud UI Call Center

Building Code:	B2200000427	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,884,238
Building Name:	Unemployment Call Center	**Address:**	111 Lincoln Ave	**Deferred Maintenance:**	$146,194
Facility Condition Index:	0.08 - Good	**City Code:**	St. Cloud	**Ext. Gross Area:**	6,325

Site: B22001 - Minneapolis South WFC

Building Code:	B2200000227	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$5,103,432
Building Name:	Mpls South Service Office	**Address:**	777 East Lake Street	**Deferred Maintenance:**	$545,346
Facility Condition Index:	0.11 - Good	**City Code:**	Minneapolis	**Ext. Gross Area:**	20,726

Agency: B43 - Iron Range Resource

FCI Rating:	Fair	**Current Replacement Value:**	$62,810,771	**Ext. Gross Area:**	301,314
Facility Condition Index:	0.26	**Deferred Maintenance:**	$16,485,322	**Building Count:**	63

Site: B43000 - Mineland Reclamation & Ironworld

Building Code:	B4300000269	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$34,526
Building Name:	Fest Park/Grounds	**Address:**	Hwy 169	**Deferred Maintenance:**	$17,454
Facility Condition Index:	0.51 - Crisis	**City Code:**	Chisholm	**Ext. Gross Area:**	400
Building Code:	B4300000469	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$6,379,163
Building Name:	Amphitheatre	**Address:**	Hwy 169	**Deferred Maintenance:**	$2,165,988
Facility Condition Index:	0.34 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	23,542
Building Code:	B4300000669	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$3,752,014
Building Name:	Interp Ctr	**Address:**	Hwy 169	**Deferred Maintenance:**	$2,621,825
Facility Condition Index:	0.70 - Crisis	**City Code:**	Chisholm	**Ext. Gross Area:**	41,410
Building Code:	B4300000769	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$184,070
Building Name:	Geology Wing	**Address:**	Hwy 169	**Deferred Maintenance:**	$89,276
Facility Condition Index:	0.49 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	2,000
Building Code:	B4300000869	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$3,531,031
Building Name:	Control Bldg	**Address:**	Hwy 169	**Deferred Maintenance:**	$1,119,149
Facility Condition Index:	0.32 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	9,573
Building Code:	B4300001069	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$929,150
Building Name:	Energy Bldg	**Address:**	Hwy 169	**Deferred Maintenance:**	$237,034
Facility Condition Index:	0.26 - Fair	**City Code:**	Chisholm	**Ext. Gross Area:**	5,640
Building Code:	B4300001469	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$339,192
Building Name:	Railroad Maint Bldg	**Address:**	Hwy 169	**Deferred Maintenance:**	$142,741
Facility Condition Index:	0.42 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	4,400
Building Code:	B4300001569	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$947,684
Building Name:	Research Library	**Address:**	Hwy 169	**Deferred Maintenance:**	$541,738
Facility Condition Index:	0.57 - Crisis	**City Code:**	Chisholm	**Ext. Gross Area:**	14,798
Building Code:	B4300001669	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$63,722
Building Name:	CCC Building	**Address:**	Hwy 169	**Deferred Maintenance:**	$22,637
Facility Condition Index:	0.36 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	1,064
Building Code:	B4300002069	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$941,824
Building Name:	Ethnic Arts Center	**Address:**	Hwy 169	**Deferred Maintenance:**	$623,318
Facility Condition Index:	0.66 - Crisis	**City Code:**	Chisholm	**Ext. Gross Area:**	8,600

Building Code:	B4300002169	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$244,444
Building Name:	Amph Maint	**Address:**	Hwy 169	**Deferred Maintenance:**	$101,536
Facility Condition Index:	0.42 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	1,827
Building Code:	B4300002669	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$324,416
Building Name:	Pavilion	**Address:**	Hwy 169	**Deferred Maintenance:**	$56,934
Facility Condition Index:	0.18 - Fair	**City Code:**	Chisholm	**Ext. Gross Area:**	6,112
Building Code:	B4300002869	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$7,236
Building Name:	Warehouse	**Address:**	Hwy 169	**Deferred Maintenance:**	$2,388
Facility Condition Index:	0.33 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	6,794
Building Code:	B4300003069	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,460,368
Building Name:	Mineland Recreation	**Address:**	Hwy 169	**Deferred Maintenance:**	$585,848
Facility Condition Index:	0.17 - Fair	**City Code:**	Chisholm	**Ext. Gross Area:**	8,626
Building Code:	B4300003269	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$182,483
Building Name:	Children Play Area Bldg	**Address:**	Hwy 169	**Deferred Maintenance:**	$99,618
Facility Condition Index:	0.55 - Crisis	**City Code:**	Chisholm	**Ext. Gross Area:**	1,600
Building Code:	B4300003369	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$50,309
Building Name:	Wilpen Depot	**Address:**	Hwy 169	**Deferred Maintenance:**	$16,602
Facility Condition Index:	0.33 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	540
Building Code:	B4300003469	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$88,775
Building Name:	Depot Bathrooms	**Address:**	Hwy 169	**Deferred Maintenance:**	$39,311
Facility Condition Index:	0.44 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	180
Building Code:	B4300003569	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$92,864
Building Name:	Exhibit Storage	**Address:**	Hwy 169	**Deferred Maintenance:**	$30,645
Facility Condition Index:	0.33 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	4,726
Building Code:	B4300003769	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$73,161
Building Name:	Bunk House	**Address:**	Hwy 169	**Deferred Maintenance:**	$16,198
Facility Condition Index:	0.22 - Fair	**City Code:**	CHISHOLM	**Ext. Gross Area:**	433
Building Code:	B4300003869	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$630
Building Name:	Trappers Shack	**Address:**	Hwy 169	**Deferred Maintenance:**	$208
Facility Condition Index:	0.33 - Poor	**City Code:**	Chisholm	**Ext. Gross Area:**	240
Building Code:	B4300003969	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$2,096
Building Name:	Gazebo	**Address:**		**Deferred Maintenance:**	$692
Facility Condition Index:	0.33 - Poor	**City Code:**	CHISHOLM	**Ext. Gross Area:**	200

Site: B43001 - Giants Ridge

Building Code:	B4300100168	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,877
Building Name:	Calgary Lift Bldg - Bottom	**Address:**	Co. Road 138	**Deferred Maintenance:**	$20,421
Facility Condition Index:	0.53 - Crisis	**City Code:**	Biwabik	**Ext. Gross Area:**	55
Building Code:	B4300100169	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,270
Building Name:	Calgary Lift Bldg - Top	**Address:**		**Deferred Maintenance:**	$10,931
Facility Condition Index:	0.47 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	55
Building Code:	B4300100170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$42,835
Building Name:	Chamonix Lift Bldg. - Bottom	**Address:**		**Deferred Maintenance:**	$17,315
Facility Condition Index:	0.40 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	68
Building Code:	B4300100171	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$39,412
Building Name:	Chamonix Lift Bldg - Top	**Address:**		**Deferred Maintenance:**	$17,896
Facility Condition Index:	0.45 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	55
Building Code:	B4300100172	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,270
Building Name:	Helsinki Lift Bldg - Bottom	**Address:**		**Deferred Maintenance:**	$10,217
Facility Condition Index:	0.44 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	55
Building Code:	B4300100173	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,270
Building Name:	Helsinki Lift Bldg - Top	**Address:**		**Deferred Maintenance:**	$10,217
Facility Condition Index:	0.44 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	55
Building Code:	B4300100174	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,915
Building Name:	Rocky Top Lift Bldg-Bottom	**Address:**		**Deferred Maintenance:**	$8,494
Facility Condition Index:	0.30 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	75
Building Code:	B4300100175	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,968
Building Name:	Rocky Top Lift Bldg-Top	**Address:**		**Deferred Maintenance:**	$7,879
Facility Condition Index:	0.27 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	75
Building Code:	B4300100176	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$64,530
Building Name:	Sarejavo Lift Bldg-Bottom	**Address:**		**Deferred Maintenance:**	$1,291
Facility Condition Index:	0.02 - Excellent	**City Code:**	Biwabik	**Ext. Gross Area:**	68
Building Code:	B4300100177	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$55,629
Building Name:	Sarejavo Lift Bldg-Top	**Address:**		**Deferred Maintenance:**	$1,113
Facility Condition Index:	0.02 - Excellent	**City Code:**	BIWABIK	**Ext. Gross Area:**	55
Building Code:	B4300100178	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,347
Building Name:	J-Bar Lift Bldg	**Address:**		**Deferred Maintenance:**	$1,984
Facility Condition Index:	0.21 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	57
Building Code:	B4300101869	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,907,630
Building Name:	Maintenance Bldg	**Address:**	Co. Road 138	**Deferred Maintenance:**	$454,496
Facility Condition Index:	0.24 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	8,061

Building Code:	B4300102569	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$3,013,436
Building Name:	Ski Chalet	**Address:**	Co. Road 138	**Deferred Maintenance:**	$585,156
Facility Condition Index:	0.19 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	23,883
Building Code:	B4300103969	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$130,688
Building Name:	Bunker Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$27,433
Facility Condition Index:	0.21 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	324
Building Code:	B4300104069	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$55,582
Building Name:	Quarry Pump House	**Address:**	Co. Road 138	**Deferred Maintenance:**	$4,633
Facility Condition Index:	0.08 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	405
Building Code:	B4300104169	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,498,761
Building Name:	Quarry Maint. Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$1,923,710
Facility Condition Index:	0.30 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	6,105
Building Code:	B4300104269	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$50,899
Building Name:	Soil Bin Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$15,754
Facility Condition Index:	0.31 - Poor	**City Code:**	Biwabik	**Ext. Gross Area:**	554
Building Code:	B4300104369	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,331,499
Building Name:	Burnt Onion Maint. Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$208,588
Facility Condition Index:	0.09 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	14,565
Building Code:	B4300104469	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$56,762
Building Name:	Legend Pump House	**Address:**	Co. Road 138	**Deferred Maintenance:**	$2,750
Facility Condition Index:	0.05 - Excellent	**City Code:**	Biwabik	**Ext. Gross Area:**	390
Building Code:	B4300104569	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,222,977
Building Name:	Golf General Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$72,022
Facility Condition Index:	0.06 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	6,152
Building Code:	B4300104570	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$652,577
Building Name:	Legend Golf Starter Bldg	**Address:**		**Deferred Maintenance:**	$122,284
Facility Condition Index:	0.19 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	53
Building Code:	B4300104571	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$694,252
Building Name:	Legend Golf Cart Storage Bldg	**Address:**		**Deferred Maintenance:**	$86,716
Facility Condition Index:	0.12 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	5,736
Building Code:	B4300104769	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,827
Building Name:	Ski Patrol Shelter Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$1,443
Facility Condition Index:	0.12 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	99
Building Code:	B4300104770	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,167
Building Name:	Ski Patrol Sarejavo Upper	**Address:**		**Deferred Maintenance:**	$462
Facility Condition Index:	0.04 - Excellent	**City Code:**	BIWABIK	**Ext. Gross Area:**	99

Building Code:	B4300104771	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,004
Building Name:	Ski Patrol Rocky Top Upper	**Address:**		**Deferred Maintenance:**	$1,782
Facility Condition Index:	0.22 - Fair	**City Code:**	BIWABIK	**Ext. Gross Area:**	67
Building Code:	B4300104869	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$13,404
Building Name:	GR Pod Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$976
Facility Condition Index:	0.07 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	195
Building Code:	B4300104969	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,210,555
Building Name:	Storage Bldg	**Address:**	Co. Road 138	**Deferred Maintenance:**	$78,945
Facility Condition Index:	0.07 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	6,181
Building Code:	B4300104970	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,998
Building Name:	The Quarry Golf Starter Bldg	**Address:**		**Deferred Maintenance:**	$263
Facility Condition Index:	0.04 - Excellent	**City Code:**	Biwabik	**Ext. Gross Area:**	53
Building Code:	B4300104971	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,603,310
Building Name:	The Quarry Clubhouse	**Address:**		**Deferred Maintenance:**	$633,009
Facility Condition Index:	0.14 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	3,895
Building Code:	B4300104972	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$253,074
Building Name:	The Quarry Fertilizer Bldg	**Address:**		**Deferred Maintenance:**	$14,187
Facility Condition Index:	0.06 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	1,687
Building Code:	B4300105069	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,378
Building Name:	Alpine Timing Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$8,267
Facility Condition Index:	0.08 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	1,147
Building Code:	B4300105169	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$118,214
Building Name:	Nordic Timing Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$11,489
Facility Condition Index:	0.10 - Good	**City Code:**	BIWABIK	**Ext. Gross Area:**	1,284
Building Code:	B4300105269	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$8,799
Building Name:	Alpine Starter Bldg.	**Address:**	Co. Road 138	**Deferred Maintenance:**	$1,593
Facility Condition Index:	0.18 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	56
Building Code:	B4300105270	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,178
Building Name:	Helsinki Starter Bldg-North	**Address:**		**Deferred Maintenance:**	$5,325
Facility Condition Index:	0.28 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	52
Building Code:	B4300105271	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,693
Building Name:	Helsinki Starter Bldg-South	**Address:**		**Deferred Maintenance:**	$6,564
Facility Condition Index:	0.28 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	56
Building Code:	B4300105272	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,551
Building Name:	Magic Carpet Bldg	**Address:**		**Deferred Maintenance:**	$2,494
Facility Condition Index:	0.16 - Fair	**City Code:**	Biwabik	**Ext. Gross Area:**	44

Building Code:	B4300105569	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$167,825
Building Name:	GR Pump House	**Address:**	Co. Road 138	**Deferred Maintenance:**	$11,171
Facility Condition Index:	0.07 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	1,044

Building Code:	B4300105669	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,874
Building Name:	GR Valve House	**Address:**	Co. Road 138	**Deferred Maintenance:**	$4,136
Facility Condition Index:	0.13 - Good	**City Code:**	Biwabik	**Ext. Gross Area:**	209

Site: B43002 - Administration

Building Code:	B4300200169	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$696,597
Building Name:	Morton Storage Bldg	**Address:**	HWY 53 South	**Deferred Maintenance:**	$186,101
Facility Condition Index:	0.27 - Fair	**City Code:**	Eveleth	**Ext. Gross Area:**	6,247

Building Code:	B4300201169	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$5,779,758
Building Name:	Administration Bldg	**Address:**	HWY 53 South	**Deferred Maintenance:**	$1,520,669
Facility Condition Index:	0.26 - Fair	**City Code:**	Eveleth	**Ext. Gross Area:**	17,965

Building Code:	B4300205869	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$7,945,730
Building Name:	IRRRB Delta Bldg.	**Address:**	Hwy 37 & Alaska Ave.	**Deferred Maintenance:**	$1,251,411
Facility Condition Index:	0.16 - Fair	**City Code:**	GILBERT	**Ext. Gross Area:**	32,740

Building Code:	B4300205969	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$3,158,292
Building Name:	IRRRB Larex Bldg.	**Address:**	1101 NW 3rd Street	**Deferred Maintenance:**	$602,599
Facility Condition Index:	0.19 - Fair	**City Code:**	COHASSET	**Ext. Gross Area:**	18,586

Agency: B9D - Amateur Sports Commission

FCI Rating:	Fair	**Current Replacement Value:**	$182,312,460	**Ext. Gross Area:**	807,054
Facility Condition Index:	0.25	**Deferred Maintenance:**	$44,761,857	**Building Count:**	24

Site: B9D170 - Amateur Sports Blaine

Building Code:	B9D17000100	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$29,456,445
Building Name:	Sports Hall	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$4,400,088
Facility Condition Index:	0.15 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	146,884
Building Code:	B9D17000101	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$8,732,755
Building Name:	Stadium	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$3,923,540
Facility Condition Index:	0.45 - Poor	**City Code:**	BLAINE	**Ext. Gross Area:**	40,407
Building Code:	B9D17000102	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$4,435,128
Building Name:	Dormitory	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,136,441
Facility Condition Index:	0.26 - Fair	**City Code:**	BLAINE	**Ext. Gross Area:**	20,514
Building Code:	B9D17000103	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,997,071
Building Name:	Bike Track	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$2,918,799
Facility Condition Index:	0.49 - Poor	**City Code:**	BLAINE	**Ext. Gross Area:**	23,056
Building Code:	B9D17000104	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$335,328
Building Name:	Maintenance Shed	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$83,172
Facility Condition Index:	0.25 - Fair	**City Code:**	BLAINE	**Ext. Gross Area:**	2,445
Building Code:	B9D17000105	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,760
Building Name:	Pump House #1	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$9,164
Facility Condition Index:	0.44 - Poor	**City Code:**	BLAINE	**Ext. Gross Area:**	441
Building Code:	B9D17000107	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$11,544,681
Building Name:	Event Center	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,320,313
Facility Condition Index:	0.11 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	42,108
Building Code:	B9D17000108	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$59,127,755
Building Name:	Super Rink	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$17,439,040
Facility Condition Index:	0.29 - Fair	**City Code:**	BLAINE	**Ext. Gross Area:**	250,000
Building Code:	B9D17000109	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$54,305,424
Building Name:	Super Rink Addition	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$12,195,550
Facility Condition Index:	0.22 - Fair	**City Code:**	BLAINE	**Ext. Gross Area:**	242,947
Building Code:	B9D17000110	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$1,124,457
Building Name:	Club House	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$112,656
Facility Condition Index:	0.10 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	5,850

Building Code:	B9D17000111	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,200,443
Building Name:	Turf Maintenance	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$637,679
Facility Condition Index:	0.53 - Crisis	**City Code:**	BLAINE	**Ext. Gross Area:**	5,006
Building Code:	B9D17000112	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$114,181
Building Name:	Pump House #2	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$13,094
Facility Condition Index:	0.11 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	121
Building Code:	B9D17000113	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$171,427
Building Name:	Club House Concession	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$23,927
Facility Condition Index:	0.14 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	474
Building Code:	B9D17000115	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,301
Building Name:	Velodrome Concessions	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$3,413
Facility Condition Index:	0.20 - Fair	**City Code:**	BLAINE	**Ext. Gross Area:**	226
Building Code:	B9D17000116	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$49,036
Building Name:	Velodrome Press Box	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$6,482
Facility Condition Index:	0.13 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	560
Building Code:	B9D17000117	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$5,473,860
Building Name:	Event Center Expansion	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$517,333
Facility Condition Index:	0.09 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	22,296
Building Code:	B9D17000118	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$50,929
Building Name:	Picnic Shelter D	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$7,453
Facility Condition Index:	0.15 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	1,092
Building Code:	B9D17000119	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$50,929
Building Name:	Picnic Shelter E	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$5,093
Facility Condition Index:	0.10 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	1,092
Building Code:	B9D17000120	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$16,921
Building Name:	Picnic Shelter H	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,426
Facility Condition Index:	0.08 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	256
Building Code:	B9D17000121	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$16,921
Building Name:	Picnic Shelter I	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,426
Facility Condition Index:	0.08 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	256
Building Code:	B9D17000122	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$16,921
Building Name:	Picnic Shelter J	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,426
Facility Condition Index:	0.08 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	256
Building Code:	B9D17000123	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,929
Building Name:	Picnic Shelter K	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,446
Facility Condition Index:	0.08 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	256

Building Code:	B9D17000124	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,929
Building Name:	Picnic Shelter L	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,446
Facility Condition Index:	0.08 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	256

Building Code:	B9D17000125	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,929
Building Name:	Picnic Shelter M	**Address:**	1700 105th Ave NE	**Deferred Maintenance:**	$1,446
Facility Condition Index:	0.08 - Good	**City Code:**	BLAINE	**Ext. Gross Area:**	256

Agency: E25 - Perpich Center

FCI Rating:	Fair	**Current Replacement Value:**	$38,634,848	**Ext. Gross Area:**	176,361
Facility Condition Index:	0.18	**Deferred Maintenance:**	$7,100,110	**Building Count:**	5

Site: E25000 - Perpich Center for Arts Education

Building Code:	E2500000327	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,941,500
Building Name:	Gaia - PDI/RAC	**Address:**	6105 Olson Memorial Highway	**Deferred Maintenance:**	$1,192,178
Facility Condition Index:	0.24 - Fair	**City Code:**	Golden Valley	**Ext. Gross Area:**	14,771
Building Code:	E2500000427	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$8,906,629
Building Name:	Delta - Dormitory	**Address:**	6135 Olson Memorial Highway	**Deferred Maintenance:**	$2,251,725
Facility Condition Index:	0.25 - Fair	**City Code:**	Golden Valley	**Ext. Gross Area:**	44,342
Building Code:	E2500000627	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$13,094,846
Building Name:	Administration-East	**Address:**	6125 Olson Memorial Highway	**Deferred Maintenance:**	$2,857,974
Facility Condition Index:	0.22 - Fair	**City Code:**	Golden Valley	**Ext. Gross Area:**	65,840
Building Code:	E2500000727	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$11,045,977
Building Name:	Administration-West	**Address:**	6125 Olson Memorial Highway	**Deferred Maintenance:**	$785,316
Facility Condition Index:	0.07 - Good	**City Code:**	Golden Valley	**Ext. Gross Area:**	46,968
Building Code:	E2500000827	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$645,895
Building Name:	Warehouse	**Address:**	6153 Olson Memorial Highway	**Deferred Maintenance:**	$12,918
Facility Condition Index:	0.02 - Excellent	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	4,440

Agency: E40 - Historical Society

FCI Rating:	Fair	**Current Replacement Value:**	$329,782,217	**Ext. Gross Area:**	1,284,098
Facility Condition Index:	0.26	**Deferred Maintenance:**	$85,359,842	**Building Count:**	153

Site: E40001 - Solomon Comstock House

Building Code:	E4000100101	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$118,188
Building Name:	Ice House	**Address:**	508 8th Street South	**Deferred Maintenance:**	$27,224
Facility Condition Index:	0.23 - Fair	**City Code:**	Moorhead	**Ext. Gross Area:**	957
Building Code:	E4000100102	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,281,457
Building Name:	Comstock House	**Address:**	508 8th Street South	**Deferred Maintenance:**	$883,776
Facility Condition Index:	0.69 - Crisis	**City Code:**	Moorhead	**Ext. Gross Area:**	3,660

Site: E40002 - W. H. Folsom House

Building Code:	E4000200201	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$60,112
Building Name:	Folsom Garage	**Address:**	272 West Government Street	**Deferred Maintenance:**	$13,578
Facility Condition Index:	0.23 - Fair	**City Code:**	Taylors Falls	**Ext. Gross Area:**	470
Building Code:	E4000200202	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$884,135
Building Name:	Folsom House	**Address:**	272 West Government Street	**Deferred Maintenance:**	$338,930
Facility Condition Index:	0.38 - Poor	**City Code:**	Taylors Falls	**Ext. Gross Area:**	3,710
Building Code:	E4000200203	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,339
Building Name:	Well House	**Address:**	272 West Government Street	**Deferred Maintenance:**	$2,418
Facility Condition Index:	0.29 - Fair	**City Code:**	Taylors Falls	**Ext. Gross Area:**	64

Site: E40003 - Forest History Center

Building Code:	E4000300301	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$67,840
Building Name:	Root Cellar, Lumber Camp	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$19,036
Facility Condition Index:	0.28 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	320
Building Code:	E4000300302	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$145,317
Building Name:	Rest Room Building	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$88,316
Facility Condition Index:	0.61 - Crisis	**City Code:**	Grand Rapids	**Ext. Gross Area:**	414
Building Code:	E4000300303	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,833,842
Building Name:	Visitors Center	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$321,448
Facility Condition Index:	0.18 - Fair	**City Code:**	Grand Rapids	**Ext. Gross Area:**	7,835
Building Code:	E4000300304	**Cost Model Name:**	Tower	**Current Replacement Value:**	$23,377
Building Name:	Ranger Tower, MFS Complex	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$2,338
Facility Condition Index:	0.10 - Good	**City Code:**	Grand Rapids	**Ext. Gross Area:**	64

Building Code:	E4000300305	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$6,170
Building Name:	Outhouse, Men, Lumber Cam	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$375
Facility Condition Index:	0.06 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	48
Building Code:	E4000300306	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$81,888
Building Name:	Office/Store, Lumber Camp	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$17,413
Facility Condition Index:	0.21 - Fair	**City Code:**	Grand Rapids	**Ext. Gross Area:**	320
Building Code:	E4000300307	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$164,565
Building Name:	Patrolman Garage, MFS Com	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$78,764
Facility Condition Index:	0.48 - Poor	**City Code:**	Grand Rapids	**Ext. Gross Area:**	392
Building Code:	E4000300308	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$400,776
Building Name:	Horse Barn, Lumber Camp	**Address:**	2609 CountyRoad 76	**Deferred Maintenance:**	$143,065
Facility Condition Index:	0.36 - Poor	**City Code:**	Grand Rapids	**Ext. Gross Area:**	2,160
Building Code:	E4000300309	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$55,150
Building Name:	Filer Shack, Lumber Camp	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$5,321
Facility Condition Index:	0.10 - Good	**City Code:**	Grand Rapids	**Ext. Gross Area:**	324
Building Code:	E4000300310	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$628,671
Building Name:	Maintenance Building	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$140,748
Facility Condition Index:	0.22 - Fair	**City Code:**	Grand Rapids	**Ext. Gross Area:**	3,000
Building Code:	E4000300311	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$295,476
Building Name:	Bunk House, Lumber Camp	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$95,942
Facility Condition Index:	0.32 - Poor	**City Code:**	Grand Rapids	**Ext. Gross Area:**	1,500
Building Code:	E4000300312	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$454,091
Building Name:	Dining Hall, Lumber Camp	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$67,537
Facility Condition Index:	0.15 - Good	**City Code:**	Grand Rapids	**Ext. Gross Area:**	2,040
Building Code:	E4000300313	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,258
Building Name:	Patrolman's Cabin, MFS Co	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$6,689
Facility Condition Index:	0.16 - Fair	**City Code:**	Grand Rapids	**Ext. Gross Area:**	176
Building Code:	E4000300314	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$102,502
Building Name:	Blacksmith Shop, Lumber C	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$18,765
Facility Condition Index:	0.18 - Fair	**City Code:**	Grand Rapids	**Ext. Gross Area:**	500
Building Code:	E4000300316	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$96,026
Building Name:	River Wanigan, Lumber Camp	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$24,295
Facility Condition Index:	0.25 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	336
Building Code:	E4000300317	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$48,898
Building Name:	Picnic Pavilion	**Address:**	2609 County Road 76	**Deferred Maintenance:**	$5,648
Facility Condition Index:	0.12 - Good	**City Code:**	Grand Rapids	**Ext. Gross Area:**	840

Building Code: E4000300318
Building Name: Trail Head Pavilion
Facility Condition Index: 0.08 - Good

Cost Model Name: Open Air Shelter
Address: 2609 County Road 76
City Code: Grand Rapids

Current Replacement Value: $48,830
Deferred Maintenance: $3,920
Ext. Gross Area: 420

Building Code: E4000300319
Building Name: Trail Screened Pavilion
Facility Condition Index: 0.05 - Excellent

Cost Model Name: Open Air Shelter
Address: 2609 County Road 76
City Code: Grand Rapids

Current Replacement Value: $60,187
Deferred Maintenance: $2,863
Ext. Gross Area: 400

Building Code: E4000300320
Building Name: Outhouse, Women, Lumber C
Facility Condition Index: 0.06 - Good

Cost Model Name: Single-story Restroom Facility
Address: 2609 County Road 76
City Code: Grand Rapids

Current Replacement Value: $3,652
Deferred Maintenance: $237
Ext. Gross Area: 30

Building Code: E4000300321
Building Name: Patrolman Tool Shed, MFS C
Facility Condition Index: 0.33 - Poor

Cost Model Name: Utility Shed
Address: 2609 County Road 76
City Code: Grand Rapids

Current Replacement Value: $1,958
Deferred Maintenance: $640
Ext. Gross Area: 15

Building Code: E4000300322
Building Name: Patrolman Outhouse, MFS C
Facility Condition Index: 0.34 - Poor

Cost Model Name: Single-story Restroom Facility
Address: 2609 County Road 76
City Code: Grand Rapids

Current Replacement Value: $1,668
Deferred Maintenance: $572
Ext. Gross Area: 20

Site: E40004 - Fort Ridgely

Building Code: E4000400401
Building Name: Commissary
Facility Condition Index: 0.28 - Fair

Cost Model Name: Single-family Residence
Address: Rt. 1, Box 65
City Code: Fairfax

Current Replacement Value: $2,025,318
Deferred Maintenance: $572,346
Ext. Gross Area: 4,700

Building Code: E4000400402
Building Name: Powder Magazine
Facility Condition Index: 0.21 - Fair

Cost Model Name: Single-family Residence
Address: Rt. 1, Box 65
City Code: Fairfax

Current Replacement Value: $55,672
Deferred Maintenance: $11,867
Ext. Gross Area: 360

Site: E40005 - Grand Mound

Building Code: E4000500501
Building Name: Visitor Center
Facility Condition Index: 0.64 - Crisis

Cost Model Name: Single-story Office/Public Access Facility
Address: 6749 Highway 11
City Code: INTL. FALLS

Current Replacement Value: $737,281
Deferred Maintenance: $471,724
Ext. Gross Area: 4,195

Building Code: E4000500503
Building Name: Storage Shed
Facility Condition Index: 0.26 - Fair

Cost Model Name: Utility Shed
Address: 6749 Highway 11
City Code: INTL. FALLS

Current Replacement Value: $15,244
Deferred Maintenance: $4,037
Ext. Gross Area: 80

Site: E40007 - Harkin Store

Building Code: E4000700701
Building Name: Harkin Store
Facility Condition Index: 0.36 - Poor

Cost Model Name: Single-family Residence
Address: Box 112
City Code: New Ulm

Current Replacement Value: $187,220
Deferred Maintenance: $67,172
Ext. Gross Area: 895

Building Code:	E4000700702	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,055,665
Building Name:	Harkin Residence	**Address:**	Box 112	**Deferred Maintenance:**	$337,091
Facility Condition Index:	0.32 - Poor	**City Code:**	New Ulm	**Ext. Gross Area:**	3,403

Site: E40008 - Historic Forestville

Building Code:	E4000800801	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$96,237
Building Name:	Wagon Barn	**Address:**	Forestville State Park	**Deferred Maintenance:**	$21,643
Facility Condition Index:	0.22 - Fair	**City Code:**	Preston	**Ext. Gross Area:**	800
Building Code:	E4000800802	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$131,412
Building Name:	Granary	**Address:**	Forestville State Park	**Deferred Maintenance:**	$64,522
Facility Condition Index:	0.49 - Poor	**City Code:**	Preston	**Ext. Gross Area:**	468
Building Code:	E4000800803	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$2,750,942
Building Name:	Store/Residence	**Address:**	Forestville State Park	**Deferred Maintenance:**	$848,731
Facility Condition Index:	0.31 - Poor	**City Code:**	Preston	**Ext. Gross Area:**	5,288
Building Code:	E4000800804	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$396,538
Building Name:	Barn	**Address:**	Forestville State Park	**Deferred Maintenance:**	$169,065
Facility Condition Index:	0.43 - Poor	**City Code:**	Preston	**Ext. Gross Area:**	4,640
Building Code:	E4000800806	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$719
Building Name:	Outhouse	**Address:**	Forestville State Park	**Deferred Maintenance:**	$165
Facility Condition Index:	0.23 - Fair	**City Code:**	Preston	**Ext. Gross Area:**	10
Building Code:	E4000800807	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,737
Building Name:	Chicken Coop	**Address:**	Forestville State Park	**Deferred Maintenance:**	$786
Facility Condition Index:	0.21 - Fair	**City Code:**	Preston	**Ext. Gross Area:**	50
Building Code:	E4000800808	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$396,148
Building Name:	Visitor Services Building	**Address:**	Forestville State Park	**Deferred Maintenance:**	$64,753
Facility Condition Index:	0.16 - Fair	**City Code:**	Preston	**Ext. Gross Area:**	2,500
Building Code:	E4000800809	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$74,992
Building Name:	Weigh House	**Address:**	Forestville State Park	**Deferred Maintenance:**	$17,386
Facility Condition Index:	0.23 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	450
Building Code:	E4000800810	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$2,360
Building Name:	Lift Station Shanty	**Address:**	21899 COUNTY ROAD 118	**Deferred Maintenance:**	$686
Facility Condition Index:	0.29 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	64

Site: E40009 - Historic Fort Snelling

Building Code:	E4000900901	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,840,394
Building Name:	Round Tower	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$1,196,149
Facility Condition Index:	0.65 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,929
Building Code:	E4000900902	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$72,786
Building Name:	Building 31 (Powder Mag)	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$54,590
Facility Condition Index:	0.75 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	169
Building Code:	E4000900903	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,027,013
Building Name:	Building 22	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$1,342,794
Facility Condition Index:	0.44 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	8,307
Building Code:	E4000900904	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,305,468
Building Name:	Hospital	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$148,486
Facility Condition Index:	0.11 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	8,141
Building Code:	E4000900905	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$2,617,591
Building Name:	Commandant's House	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$537,428
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	5,334
Building Code:	E4000900906	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$944,942
Building Name:	Shops	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$194,644
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,673
Building Code:	E4000900907	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$176,099
Building Name:	School	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$11,714
Facility Condition Index:	0.07 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	842
Building Code:	E4000900908	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,763,606
Building Name:	Building 30, Barn	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$1,217,354
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	18,051
Building Code:	E4000900909	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$9,143,427
Building Name:	History (Visitor) Center	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$4,785,045
Facility Condition Index:	0.52 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	30,835
Building Code:	E4000900910	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$962,555
Building Name:	Powder Magazine	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$33,441
Facility Condition Index:	0.03 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,092
Building Code:	E4000900911	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$43,510
Building Name:	Gun Shed	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$7,001
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	427
Building Code:	E4000900912	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,433,726
Building Name:	Long Barracks (Wood)	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$295,649
Facility Condition Index:	0.09 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	11,675

Building Code:	E4000900913	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$364,977
Building Name:	Guard House	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$30,489
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,949
Building Code:	E4000900914	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,186,432
Building Name:	Pentagonal Tower (N. Batt	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$31,322
Facility Condition Index:	0.03 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	822
Building Code:	E4000900915	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$249,741
Building Name:	Gate House	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$75,114
Facility Condition Index:	0.30 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	398
Building Code:	E4000900916	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,483,214
Building Name:	Commissary	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$204,740
Facility Condition Index:	0.14 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	6,619
Building Code:	E4000900917	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$189,291
Building Name:	Sutler Store	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$19,434
Facility Condition Index:	0.10 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	824
Building Code:	E4000900918	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,864,438
Building Name:	Hexagonal Tower (S. Batte	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$1,330,084
Facility Condition Index:	0.71 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,686
Building Code:	E4000900919	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,989,641
Building Name:	Short Barracks (Stone)	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$311,669
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	7,963
Building Code:	E4000900920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,807,545
Building Name:	Officers Quarters'	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$458,991
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	15,499
Building Code:	E4000900921	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$930,210
Building Name:	Semi-Circular Bat. (Half	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$293,064
Facility Condition Index:	0.32 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,963
Building Code:	E4000900924	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$12,862,176
Building Name:	Building 17	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$3,764,550
Facility Condition Index:	0.29 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	52,150
Building Code:	E4000900925	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$13,616,351
Building Name:	Building 18 and Link	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$3,589,781
Facility Condition Index:	0.26 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	54,972
Building Code:	E4000900926	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,902
Building Name:	Well House	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$490
Facility Condition Index:	0.10 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	34

Building Code:	E4000900927	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$656,787
Building Name:	Wall Line, Limestone	**Address:**	Historic Fort Snelling	**Deferred Maintenance:**	$377,752
Facility Condition Index:	0.58 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,818
Building Code:	E4000900928	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$138,407
Building Name:	Storage Bunker by #17/18	**Address:**		**Deferred Maintenance:**	$30,026
Facility Condition Index:	0.22 - Fair	**City Code:**		**Ext. Gross Area:**	300

Site: E40010 - James J. Hill House

Building Code:	E4001001001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$52,495
Building Name:	Garage	**Address:**	240 Summit Ave.	**Deferred Maintenance:**	$11,137
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	342
Building Code:	E4001001002	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$22,271,017
Building Name:	James J. Hill House	**Address:**	240 Summit Ave.	**Deferred Maintenance:**	$8,533,640
Facility Condition Index:	0.38 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	35,948
Building Code:	E4001001003	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$369,302
Building Name:	James J. Hill Gate House	**Address:**	242 Summit Ave.	**Deferred Maintenance:**	$150,300
Facility Condition Index:	0.41 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	867

Site: E40011 - Jeffers Petroglyphs

Building Code:	E4001101104	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$998,288
Building Name:	Visitor Center	**Address:**	County Road 2	**Deferred Maintenance:**	$191,491
Facility Condition Index:	0.19 - Fair	**City Code:**	Jeffers	**Ext. Gross Area:**	4,540
Building Code:	E4001101105	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$44,880
Building Name:	Storage Shed	**Address:**	County Road 2	**Deferred Maintenance:**	$14,810
Facility Condition Index:	0.33 - Poor	**City Code:**	JEFFERS	**Ext. Gross Area:**	144

Site: E40012 - Lac Qui Parle Mission

Building Code:	E4001201201	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$287,308
Building Name:	Mission Chapel	**Address:**	151 Pioneer Dr., Box 303	**Deferred Maintenance:**	$68,716
Facility Condition Index:	0.24 - Fair	**City Code:**	Montevideo	**Ext. Gross Area:**	900

Site: E40014 - Charles A. Lindbergh House

Building Code:	E4001401401	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,736,781
Building Name:	Visitor Center	**Address:**	1200 Lindbergh Drive South	**Deferred Maintenance:**	$890,494
Facility Condition Index:	0.33 - Poor	**City Code:**	Little Falls	**Ext. Gross Area:**	10,700

Building Code:	E4001401402	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,531,151
Building Name:	Lindbergh House	**Address:**	1200 Lindbergh Drive South	**Deferred Maintenance:**	$157,803
Facility Condition Index:	0.10 - Good	**City Code:**	Little Falls	**Ext. Gross Area:**	4,426
Building Code:	E4001401403	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$43,793
Building Name:	Ice House	**Address:**	1200 Lindbergh Drive South	**Deferred Maintenance:**	$14,926
Facility Condition Index:	0.34 - Poor	**City Code:**	Little Falls	**Ext. Gross Area:**	300
Building Code:	E4001401405	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,677
Building Name:	Storage Shed	**Address:**	1200 Lindbergh Drive South	**Deferred Maintenance:**	$4,545
Facility Condition Index:	0.22 - Fair	**City Code:**	Little Falls	**Ext. Gross Area:**	192
Building Code:	E4001401406	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$6,663
Building Name:	WPA Stone Wall Shelter	**Address:**	1200 Lindbergh Drive South	**Deferred Maintenance:**	$133
Facility Condition Index:	0.02 - Excellent	**City Code:**	Little Falls	**Ext. Gross Area:**	100

Site: E40015 - Lower Sioux Agency

Building Code:	E4001501501	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,132,805
Building Name:	Visitor Center	**Address:**	Rt. 1, Box 125	**Deferred Maintenance:**	$211,226
Facility Condition Index:	0.19 - Fair	**City Code:**	Morton	**Ext. Gross Area:**	3,850
Building Code:	E4001501502	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$83,607
Building Name:	Garage	**Address:**	Rt. 1, Box 125	**Deferred Maintenance:**	$26,053
Facility Condition Index:	0.31 - Poor	**City Code:**	Morton	**Ext. Gross Area:**	700
Building Code:	E4001501503	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$935,508
Building Name:	Stone Warehouse	**Address:**	Rt. 1, Box 125	**Deferred Maintenance:**	$148,220
Facility Condition Index:	0.16 - Fair	**City Code:**	Morton	**Ext. Gross Area:**	1,806

Site: E40016 - Mille Lacs Indian Museum

Building Code:	E4001600001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$11,090
Building Name:	Storage Building	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$1,109
Facility Condition Index:	0.10 - Good	**City Code:**	Onamia	**Ext. Gross Area:**	165
Building Code:	E4001601601	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,117,401
Building Name:	Trading Post	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$148,663
Facility Condition Index:	0.13 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	4,400
Building Code:	E4001601602	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$6,962,780
Building Name:	Museum	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$1,532,764
Facility Condition Index:	0.22 - Fair	**City Code:**	Onamia	**Ext. Gross Area:**	28,000

Building Code:	E4001601603	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$693,492
Building Name:	Ayers House	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$47,162
Facility Condition Index:	0.07 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	2,460
Building Code:	E4001601604	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$37,715
Building Name:	Ayer Storage Shed	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$10,163
Facility Condition Index:	0.27 - Fair	**City Code:**	Onamia	**Ext. Gross Area:**	485
Building Code:	E4001601605	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$14,357
Building Name:	Cabin #1	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$4,351
Facility Condition Index:	0.30 - Poor	**City Code:**	Onamia	**Ext. Gross Area:**	165
Building Code:	E4001601606	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$14,357
Building Name:	Cabin #2	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$3,046
Facility Condition Index:	0.21 - Fair	**City Code:**	Onamia	**Ext. Gross Area:**	165
Building Code:	E4001601607	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$14,618
Building Name:	Cabin #3 / Shed	**Address:**	43411 Oodena Drive	**Deferred Maintenance:**	$3,102
Facility Condition Index:	0.21 - Fair	**City Code:**	Onamia	**Ext. Gross Area:**	168

Site: E40017 - Minnehaha Depot

Building Code:	E4001701701	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$149,459
Building Name:	Minnehaha Depot	**Address:**	Minnehaha Park	**Deferred Maintenance:**	$26,586
Facility Condition Index:	0.18 - Fair	**City Code:**	Minneapolis	**Ext. Gross Area:**	461

Site: E40018 - Snake River Fur Post

Building Code:	E4001801801	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$2,800
Building Name:	Women's Outhouse	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$1,652
Facility Condition Index:	0.59 - Crisis	**City Code:**	Pine City	**Ext. Gross Area:**	16
Building Code:	E4001801802	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$2,800
Building Name:	Men's Outhouse	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$1,652
Facility Condition Index:	0.59 - Crisis	**City Code:**	Pine City	**Ext. Gross Area:**	16
Building Code:	E4001801803	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$332,596
Building Name:	Fur Post	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$63,777
Facility Condition Index:	0.19 - Fair	**City Code:**	Pine City	**Ext. Gross Area:**	1,367
Building Code:	E4001801804	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$121,755
Building Name:	Picnic Shelter	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$80,681
Facility Condition Index:	0.66 - Crisis	**City Code:**	Pine City	**Ext. Gross Area:**	1,275

Building Code:	E4001801806	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,880
Building Name:	Tractor Shed	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$6,128
Facility Condition Index:	0.27 - Fair	**City Code:**	Pine City	**Ext. Gross Area:**	200
Building Code:	E4001801807	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$119,466
Building Name:	Maintenance Shop	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$24,758
Facility Condition Index:	0.21 - Fair	**City Code:**	Pine City	**Ext. Gross Area:**	1,008
Building Code:	E4001801808	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,729,339
Building Name:	Visitor Center	**Address:**	12551 Voyageur Lane	**Deferred Maintenance:**	$662,684
Facility Condition Index:	0.24 - Fair	**City Code:**	Pine City	**Ext. Gross Area:**	10,460

Site: E40019 - Oliver H. Kelley Farm

Building Code:	E4001901901	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$5,767
Building Name:	Corn Crib	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$1,903
Facility Condition Index:	0.33 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	84
Building Code:	E4001901902	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$1,691
Building Name:	Outhouse	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$1,202
Facility Condition Index:	0.71 - Crisis	**City Code:**	Elk River	**Ext. Gross Area:**	16
Building Code:	E4001901905	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$9,140
Building Name:	Pig Shed / Pen (South)	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$3,016
Facility Condition Index:	0.33 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	120
Building Code:	E4001901907	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$594,022
Building Name:	Barn	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$71,824
Facility Condition Index:	0.12 - Good	**City Code:**	Elk River	**Ext. Gross Area:**	2,583
Building Code:	E4001901908	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$2,742
Building Name:	Pig Shed / Pen (North)	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$905
Facility Condition Index:	0.33 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	36
Building Code:	E4001901909	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,311,948
Building Name:	Farm House	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$394,378
Facility Condition Index:	0.30 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	4,809
Building Code:	E4001901910	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$4,874
Building Name:	Calf Shed / Pen	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$1,609
Facility Condition Index:	0.33 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	64
Building Code:	E4001901911	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$21,161
Building Name:	Chicken House	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$5,678
Facility Condition Index:	0.27 - Fair	**City Code:**	Elk River	**Ext. Gross Area:**	128

Building Code:	E4001901912	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$9,140
Building Name:	Sheep Shed / Pen	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$3,016
Facility Condition Index:	0.33 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	120
Building Code:	E4001901913	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$36,558
Building Name:	Animal Shelter	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$12,064
Facility Condition Index:	0.33 - Poor	**City Code:**	Elk River	**Ext. Gross Area:**	480
Building Code:	E4001901914	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$40,726
Building Name:	Machine Shed	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$8,606
Facility Condition Index:	0.21 - Fair	**City Code:**	Elk River	**Ext. Gross Area:**	474
Building Code:	E4001901917	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$403,337
Building Name:	Multipurpose Building	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$10,358
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELK RIVER	**Ext. Gross Area:**	2,720
Building Code:	E4001901918	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,691,143
Building Name:	Visitor Center	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$123,532
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELK RIVER	**Ext. Gross Area:**	20,575
Building Code:	E4001901919	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$380,094
Building Name:	Maintenance Building	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$7,602
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELK RIVER	**Ext. Gross Area:**	2,016
Building Code:	E4001901920	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$271,222
Building Name:	Animal Barn	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$5,424
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELK RIVER	**Ext. Gross Area:**	1,568
Building Code:	E4001901921	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$67,939
Building Name:	Guest Animal Shelter	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$1,359
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELK RIVER	**Ext. Gross Area:**	576
Building Code:	E4001901922	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$55,385
Building Name:	Picnic Shelter	**Address:**	15788 Kelley Farm Road	**Deferred Maintenance:**	$1,108
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELK RIVER	**Ext. Gross Area:**	736

Site: E40020 - Alexander Ramsey House

Building Code:	E4002002001	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$431,516
Building Name:	Carriage Barn	**Address:**	265 S. Exchange St.	**Deferred Maintenance:**	$97,942
Facility Condition Index:	0.23 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	2,648
Building Code:	E4002002002	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$5,049,436
Building Name:	Ramsey House	**Address:**	265 S. Exchange St.	**Deferred Maintenance:**	$1,732,650
Facility Condition Index:	0.34 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	12,487

Building Code:	E4002002004	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,670
Building Name:	Equipment Shed	**Address:**	265 S. Exchange St.	**Deferred Maintenance:**	$1,055
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	120

Site: E40021 - Split Rock Lighthouse

Building Code:	E4002102101	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,298,936
Building Name:	Dwelling #3	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$404,777
Facility Condition Index:	0.31 - Poor	**City Code:**	Two Harbors	**Ext. Gross Area:**	2,124
Building Code:	E4002102102	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$131,176
Building Name:	Oil House/Storage	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$33,246
Facility Condition Index:	0.25 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	311
Building Code:	E4002102103	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$282,569
Building Name:	Fog Signal Building	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$40,272
Facility Condition Index:	0.14 - Good	**City Code:**	Two Harbors	**Ext. Gross Area:**	991
Building Code:	E4002102104	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,414
Building Name:	Pump House	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$7,749
Facility Condition Index:	0.58 - Crisis	**City Code:**	Two Harbors	**Ext. Gross Area:**	80
Building Code:	E4002102105	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$33,812
Building Name:	Tram House	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$10,212
Facility Condition Index:	0.30 - Poor	**City Code:**	Two Harbors	**Ext. Gross Area:**	144
Building Code:	E4002102106	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,329,038
Building Name:	Dwelling #2	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$203,342
Facility Condition Index:	0.15 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	2,124
Building Code:	E4002102107	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$134,193
Building Name:	Storage Barn #2	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$23,779
Facility Condition Index:	0.18 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	768
Building Code:	E4002102108	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$125,573
Building Name:	Storage Barn #3	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$22,917
Facility Condition Index:	0.18 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	768
Building Code:	E4002102109	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,636,129
Building Name:	Visitor Center	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$715,743
Facility Condition Index:	0.15 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	14,013
Building Code:	E4002102110	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$459,334
Building Name:	Lighthouse	**Address:**	3713 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$125,730
Facility Condition Index:	0.27 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	733

Building Code: E4002102111
Building Name: Dwelling #1
Facility Condition Index: 0.25 - Fair

Cost Model Name: Single-family Residence
Address: Split Rock Lighthouse
City Code: Two Harbors

Current Replacement Value: $1,306,001
Deferred Maintenance: $320,049
Ext. Gross Area: 2,124

Building Code: E4002102113
Building Name: Storage Garage - Maintena
Facility Condition Index: 0.07 - Good

Cost Model Name: Single-story Work Facility
Address: 3713 Split Rock Lighthouse Rd
City Code: Two Harbors

Current Replacement Value: $134,279
Deferred Maintenance: $9,276
Ext. Gross Area: 576

Building Code: E4002102114
Building Name: Storage Garage
Facility Condition Index: 0.08 - Good

Cost Model Name: Single-story Work Facility
Address: 3713 Split Rock Lighthouse Rd
City Code: Two Harbors

Current Replacement Value: $87,907
Deferred Maintenance: $7,198
Ext. Gross Area: 576

Building Code: E4002102115
Building Name: Well House
Facility Condition Index: 0.16 - Fair

Cost Model Name: Single-story Work Facility
Address: 3713 Split Rock Lighthouse Rd
City Code: Two Harbors

Current Replacement Value: $8,758
Deferred Maintenance: $1,429
Ext. Gross Area: 36

Building Code: E4002102116
Building Name: Vending Hut
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Shelter
Address: 3713 Split Rock Lighthouse Rd
City Code: Two Harbors

Current Replacement Value: $4,868
Deferred Maintenance: $487
Ext. Gross Area: 80

Site: E40022 - Upper Sioux Agency

Building Code: E4002202201
Building Name: House/Duplex
Facility Condition Index: 0.21 - Fair

Cost Model Name: Single-family Residence
Address: Rt. 2, Box 92
City Code: Granite Falls

Current Replacement Value: $280,888
Deferred Maintenance: $58,890
Ext. Gross Area: 1,871

Site: E40023 - W. W. Mayo House

Building Code: E4002302301
Building Name: W. W. Mayo House
Facility Condition Index: 0.25 - Fair

Cost Model Name: Single-family Residence
Address: 118 N. Main Street
City Code: Le Sueur

Current Replacement Value: $598,583
Deferred Maintenance: $149,957
Ext. Gross Area: 2,275

Site: E40024 - Sibley House Historic Site

Building Code: E4002402401
Building Name: DuPuis House
Facility Condition Index: 0.24 - Fair

Cost Model Name: Single-family Residence
Address: 1357 Sibley Memorial Highway
City Code: Mendota

Current Replacement Value: $1,699,331
Deferred Maintenance: $414,303
Ext. Gross Area: 4,909

Building Code: E4002402402
Building Name: Sibley House
Facility Condition Index: 0.20 - Fair

Cost Model Name: Single-family Residence
Address: 1357 Sibley Memorial Highway
City Code: Mendota

Current Replacement Value: $2,265,247
Deferred Maintenance: $451,274
Ext. Gross Area: 5,373

Building Code: E4002402403
Building Name: Faribault House
Facility Condition Index: 0.15 - Fair

Cost Model Name: Single-family Residence
Address: 1357 Sibley Memorial Highway
City Code: Mendota

Current Replacement Value: $1,996,811
Deferred Maintenance: $302,042
Ext. Gross Area: 4,650

Building Code:	E4002402404	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$185,211
Building Name:	Cold Store	**Address:**	1357 Sibley Memorial Highway	**Deferred Maintenance:**	$18,608
Facility Condition Index:	0.10 - Good	**City Code:**	Mendota	**Ext. Gross Area:**	372
Building Code:	E4002402405	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$114,560
Building Name:	Well House	**Address:**	1357 Sibley Memorial Highway	**Deferred Maintenance:**	$14,641
Facility Condition Index:	0.13 - Good	**City Code:**	Mendota	**Ext. Gross Area:**	344
Building Code:	E4002402406	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$296,921
Building Name:	Caretaker's Cottage	**Address:**	1357 Sibley Memorial Highway	**Deferred Maintenance:**	$73,164
Facility Condition Index:	0.25 - Fair	**City Code:**	Mendota	**Ext. Gross Area:**	772
Building Code:	E4002402407	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$35,702
Building Name:	Caretaker's Garage	**Address:**	1357 Sibley Memorial Highway	**Deferred Maintenance:**	$8,957
Facility Condition Index:	0.25 - Fair	**City Code:**	Mendota	**Ext. Gross Area:**	532
Building Code:	E4002402409	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$31,043
Building Name:	Powderhouse	**Address:**	1357 Sibley Memorial Highway	**Deferred Maintenance:**	$11,255
Facility Condition Index:	0.36 - Poor	**City Code:**	Mendota	**Ext. Gross Area:**	246

Site: E40026 - 1500 Mississippi Street

Building Code:	E4002602601	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$14,855,622
Building Name:	1500 Mississippi	**Address:**	1500 Mississippi Street	**Deferred Maintenance:**	$6,549,643
Facility Condition Index:	0.44 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	68,272

Site: E40027 - Birch Coulee Battlefield

Building Code:	E4002702701	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$19,865
Building Name:	Picnic Shelter	**Address:**		**Deferred Maintenance:**	$1,986
Facility Condition Index:	0.10 - Good	**City Code:**		**Ext. Gross Area:**	400
Building Code:	E4002702702	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$1,854
Building Name:	Porta-potty Shelter	**Address:**		**Deferred Maintenance:**	$1,173
Facility Condition Index:	0.63 - Crisis	**City Code:**		**Ext. Gross Area:**	24

Site: E40032 - Kellogg Center

Building Code:	E4003203201	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$11,079,715
Building Name:	Kellogg Center	**Address:**	328 Kellogg Boulevard West	**Deferred Maintenance:**	$3,623,930
Facility Condition Index:	0.33 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	60,000

Site: E40033 - Mill City Museum

Building Code:	E4003303301	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$33,852,770
Building Name:	Mill - Engine Houses - Wheat House	**Address:**		**Deferred Maintenance:**	$5,884,604
Facility Condition Index:	0.17 - Fair	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	75,000
Building Code:	E4003303302	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$147,440
Building Name:	Mill Office	**Address:**		**Deferred Maintenance:**	$37,420
Facility Condition Index:	0.25 - Fair	**City Code:**		**Ext. Gross Area:**	960
Building Code:	E4003303303	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$5,180,936
Building Name:	Mill Ruins Courtyard	**Address:**		**Deferred Maintenance:**	$4,521,330
Facility Condition Index:	0.87 - Crisis	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	9,512
Building Code:	E4003303304	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$650,421
Building Name:	Wheel House	**Address:**		**Deferred Maintenance:**	$483,782
Facility Condition Index:	0.74 - Crisis	**City Code:**		**Ext. Gross Area:**	3,904
Building Code:	E4003303305	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$2,743,728
Building Name:	Feed Elevator	**Address:**		**Deferred Maintenance:**	$846,597
Facility Condition Index:	0.31 - Poor	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	4,690
Building Code:	E4003303306	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$13,750,126
Building Name:	Elevator #1 - Train Shed - Conveyor	**Address:**		**Deferred Maintenance:**	$7,810,109
Facility Condition Index:	0.57 - Crisis	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	25,613

Site: G02310 - Capitol Complex

Building Code:	G0231011562	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$90,234,677
Building Name:	History Center	**Address:**	345 Kellogg Blvd. West	**Deferred Maintenance:**	$11,339,336
Facility Condition Index:	0.13 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	517,555

Agency: E44 - Minnesota State Academies

FCI Rating:	Fair	**Current Replacement Value:**	$117,715,365	**Ext. Gross Area:**	424,709
Facility Condition Index:	0.20	**Deferred Maintenance:**	$23,333,201	**Building Count:**	19

Site: E44001 - Deaf Academy

Building Code:	E4400100566	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,861
Building Name:	Central Gas Meter Building	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$8,534
Facility Condition Index:	0.33 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	208
Building Code:	E4400100766	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$1,522,531
Building Name:	Laundry Bldg.	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$1,277,367
Facility Condition Index:	0.84 - Crisis	**City Code:**	Faribault	**Ext. Gross Area:**	7,107
Building Code:	E4400100866	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$4,195,071
Building Name:	Power Plant	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$584,232
Facility Condition Index:	0.14 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	18,056
Building Code:	E4400100966	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$18,863,088
Building Name:	Tate Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$2,757,683
Facility Condition Index:	0.15 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	62,207
Building Code:	E4400101266	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$3,861,299
Building Name:	Pollard Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$580,009
Facility Condition Index:	0.15 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	16,746
Building Code:	E4400101766	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$6,390,240
Building Name:	Rodman Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$1,683,202
Facility Condition Index:	0.26 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	22,649
Building Code:	E4400101966	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$4,755,707
Building Name:	Smith Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$622,189
Facility Condition Index:	0.13 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	25,512
Building Code:	E4400102018	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$5,995,142
Building Name:	Wilkins Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$124,151
Facility Condition Index:	0.02 - Excellent	**City Code:**	FARIBAULT	**Ext. Gross Area:**	26,874
Building Code:	E4400102166	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$6,022,766
Building Name:	Quinn Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$882,629
Facility Condition Index:	0.15 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	22,175
Building Code:	E4400102666	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$7,777,722
Building Name:	Lauritsen Gymnasium	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$2,503,960
Facility Condition Index:	0.32 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	25,975

Building Code:	E4400102766	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$18,917,505
Building Name:	Noyes Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$4,745,548
Facility Condition Index:	0.25 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	54,195
Building Code:	E4400102866	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$5,306,458
Building Name:	Mott Hall	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$2,265,788
Facility Condition Index:	0.43 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	13,769
Building Code:	E4400103066	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,722
Building Name:	Electrical Service Vault	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$7,481
Facility Condition Index:	0.23 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	125
Building Code:	E4400103166	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$192,214
Building Name:	Garage MSAD (Rodman Garage)	**Address:**	615 Olof Hanson Drive	**Deferred Maintenance:**	$77,171
Facility Condition Index:	0.40 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	1,926

Site: E44002 - Blind Academy

Building Code:	E4400200255	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$708,370
Building Name:	A + House	**Address:**	400 SE 6th Ave.	**Deferred Maintenance:**	$48,875
Facility Condition Index:	0.07 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	4,182
Building Code:	E4400200266	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$1,216,376
Building Name:	Torger Lien (Industrial Building)	**Address:**	400 SE 6th Ave.	**Deferred Maintenance:**	$382,132
Facility Condition Index:	0.31 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	6,933
Building Code:	E4400201666	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$6,463,487
Building Name:	Library for the Blind & P	**Address:**	400 SE 6th Ave.	**Deferred Maintenance:**	$1,585,914
Facility Condition Index:	0.25 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	21,201
Building Code:	E4400201866	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$25,005,286
Building Name:	Lysen - Gillen Learning Center	**Address:**	400 SE 6th Ave.	**Deferred Maintenance:**	$3,006,185
Facility Condition Index:	0.12 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	89,417
Building Code:	E4400202266	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$463,519
Building Name:	Maintenance Building	**Address:**	400 SE 6th Ave.	**Deferred Maintenance:**	$190,151
Facility Condition Index:	0.41 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	5,451

Agency: E77 - Minnesota Zoological Garden

FCI Rating:	Fair	**Current Replacement Value:**	$186,124,735	**Ext. Gross Area:**	647,692
Facility Condition Index:	0.19	**Deferred Maintenance:**	$35,809,322	**Building Count:**	123

Site: E77700 - MN ZOO

Building Code:	E7770000220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$570,135
Building Name:	Isolation Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$186,900
Facility Condition Index:	0.33 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,982
Building Code:	E7770000305	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$19,537,438
Building Name:	MBC - Section -A-B- Admin-Education	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$3,204,561
Facility Condition Index:	0.16 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	80,139
Building Code:	E7770000520	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,910,509
Building Name:	Central Plaza Office - Tiger Hold	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$325,003
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	10,754
Building Code:	E7770000625	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$11,588,538
Building Name:	Bldg A - Animal Health	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$3,547,756
Facility Condition Index:	0.31 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	18,781
Building Code:	E7770000755	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$171,874
Building Name:	Replay Park Restroom	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$30,881
Facility Condition Index:	0.18 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	585
Building Code:	E7770000855	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$711,098
Building Name:	Conservation Carousel	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$15,813
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	5,236
Building Code:	E7770000865	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$1,063,890
Building Name:	Fire Suppression Building	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$21,278
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	50
Building Code:	E7770000875	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,774
Building Name:	Carousel Token Shelter	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$150
Facility Condition Index:	0.03 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	97
Building Code:	E7770001220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$228,584
Building Name:	Bldg H - Camel Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$82,040
Facility Condition Index:	0.36 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,683
Building Code:	E7770001625	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$4,748,361
Building Name:	Bldg B - Internal Services	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,453,607
Facility Condition Index:	0.31 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	16,681

Building Code:	E7770001945	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$606,304
Building Name:	Generator Discovery Bay	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$62,476
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	149
Building Code:	E7770002220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$133,404
Building Name:	Bldg J - Horse Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$37,915
Facility Condition Index:	0.28 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,204
Building Code:	E7770002625	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$916,139
Building Name:	Pole Bldg - Vehicle Maint	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$222,210
Facility Condition Index:	0.24 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	7,172
Building Code:	E7770002725	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$732,336
Building Name:	Bldg C - Vehicle Maint Garage	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$190,757
Facility Condition Index:	0.26 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,912
Building Code:	E7770003220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$163,255
Building Name:	Bldg K - Camel Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$58,296
Facility Condition Index:	0.36 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,202
Building Code:	E7770003625	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$451,634
Building Name:	Greenhouse Headhouse	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$183,102
Facility Condition Index:	0.41 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,890
Building Code:	E7770003725	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,355,020
Building Name:	Greenhouse	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$931,320
Facility Condition Index:	0.69 - Crisis	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	3,666
Building Code:	E7770004220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$194,945
Building Name:	Bldg L - Moose Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$44,613
Facility Condition Index:	0.23 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,200
Building Code:	E7770004625	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$880,604
Building Name:	Bldg EF - Large Animal Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$256,452
Facility Condition Index:	0.29 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,735
Building Code:	E7770005230	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,297,764
Building Name:	Bldg M - Monorail Maint	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$291,812
Facility Condition Index:	0.22 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	7,561
Building Code:	E7770005240	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,858
Building Name:	Monorail Maint Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$9,629
Facility Condition Index:	0.75 - Crisis	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	126
Building Code:	E7770005625	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$582,137
Building Name:	Bldg G - Hay Storage	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$207,134
Facility Condition Index:	0.36 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	7,852

Building Code:	E7770005720	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$175,152
Building Name:	Dhole Gazebo	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$17,514
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,102
Building Code:	E7770006230	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$120,529
Building Name:	Bldg N - Monorail Switch Gear	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$54,684
Facility Condition Index:	0.45 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	236
Building Code:	E7770006310	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$67,692,035
Building Name:	MBC - Section -C-D-E-F- Tropics	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$14,479,857
Facility Condition Index:	0.21 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	192,142
Building Code:	E7770006320	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$327,538
Building Name:	Butterfly Tent	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$64,475
Facility Condition Index:	0.20 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	4,539
Building Code:	E7770006330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,211
Building Name:	Butterfly Containment Building	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$5,762
Facility Condition Index:	0.44 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	102
Building Code:	E7770006340	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$20,951
Building Name:	Endangered Butterfly Tent	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$4,927
Facility Condition Index:	0.24 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	336
Building Code:	E7770006635	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,570,372
Building Name:	Bldg H - Central Heat Plant	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,221,099
Facility Condition Index:	0.34 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	3,165
Building Code:	E7770007240	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,521,616
Building Name:	Bison - Pronghorn Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$186,711
Facility Condition Index:	0.07 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	22,229
Building Code:	E7770007320	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$164,455
Building Name:	Bison Garage	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$6,698
Facility Condition Index:	0.04 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	952
Building Code:	E7770007420	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$163,627
Building Name:	Bison Holding Hay Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$43,543
Facility Condition Index:	0.27 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	729
Building Code:	E7770007520	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$12,815
Building Name:	Bison Holding Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$5,331
Facility Condition Index:	0.42 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	220
Building Code:	E7770007625	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,258,331
Building Name:	Warehouse-Maintenance Support	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$314,878
Facility Condition Index:	0.25 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	11,317

Building Code:	E7770008220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$389,229
Building Name:	Caribou Barn A	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$95,205
Facility Condition Index:	0.24 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,649
Building Code:	E7770008225	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$153,585
Building Name:	Caribou Barn B	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$50,897
Facility Condition Index:	0.33 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,121
Building Code:	E7770008320	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$63,648
Building Name:	Giraffe Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$8,619
Facility Condition Index:	0.14 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	517
Building Code:	E7770008420	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,196
Building Name:	Zebra Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$3,704
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	387
Building Code:	E7770008520	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,196
Building Name:	Gazelle Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,932
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	387
Building Code:	E7770008620	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,217
Building Name:	Oryx Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$3,402
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	387
Building Code:	E7770008720	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,361
Building Name:	Africa Holding Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$14,514
Facility Condition Index:	0.40 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	346
Building Code:	E7770008820	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$12,815
Building Name:	Africa Holding Hay Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$973
Facility Condition Index:	0.08 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	220
Building Code:	E7770009220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$377,005
Building Name:	Musk Ox Bldg A	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$113,264
Facility Condition Index:	0.30 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,608
Building Code:	E7770009225	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$275,924
Building Name:	Musk Ox Bldg B	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$58,308
Facility Condition Index:	0.21 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,515
Building Code:	E7770009320	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$29,010
Building Name:	Musk Ox Viewing Shelter	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$10,571
Facility Condition Index:	0.36 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	287
Building Code:	E7770009420	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,642
Building Name:	Dinos Ticket Booth	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,123
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	50

Building Code:	E7770009430	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,274
Building Name:	Dinos Ticket Booth 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$780
Facility Condition Index:	0.18 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	33
Building Code:	E7770009440	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$39,677
Building Name:	Dinos Gift Tent	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$7,139
Facility Condition Index:	0.18 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	995
Building Code:	E7770010510	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$214,485
Building Name:	East Entrance	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$23,189
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	469
Building Code:	E7770011220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$328,870
Building Name:	Bldg V - Takin Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$90,366
Facility Condition Index:	0.27 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,335
Building Code:	E7770012245	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$862,509
Building Name:	Bird Holding - Galaxie Ave	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$162,063
Facility Condition Index:	0.19 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,990
Building Code:	E7770013255	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$755,080
Building Name:	Amphitheater Bird Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$169,411
Facility Condition Index:	0.22 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	3,127
Building Code:	E7770013355	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,633,214
Building Name:	Amphitheater	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$449,973
Facility Condition Index:	0.17 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	11,980
Building Code:	E7770013365	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$91,005
Building Name:	Lancer Tiger Treats	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$30,499
Facility Condition Index:	0.34 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	621
Building Code:	E7770013375	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$747,778
Building Name:	Tiger Lair	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$93,661
Facility Condition Index:	0.13 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,773
Building Code:	E7770013455	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$334,879
Building Name:	Amphitheater Restroom	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$50,845
Facility Condition Index:	0.15 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,098
Building Code:	E7770013555	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$67,632
Building Name:	Summit - Lancer Vending Booth	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$17,225
Facility Condition Index:	0.25 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	269
Building Code:	E7770013655	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$121,837
Building Name:	Picnic Tent 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$24,637
Facility Condition Index:	0.20 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,954

Building Code:	E7770013755	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$121,837
Building Name:	Picnic Tent 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$12,184
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,954
Building Code:	E7770013855	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$36,174
Building Name:	Picnic Tent 3	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$5,194
Facility Condition Index:	0.14 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	800
Building Code:	E7770015235	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$73,810
Building Name:	Cement Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$17,548
Facility Condition Index:	0.24 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	494
Building Code:	E7770015315	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$8,207,565
Building Name:	MBC - Section -G- MN Trail	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,340,889
Facility Condition Index:	0.29 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	27,265
Building Code:	E7770016150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$888,842
Building Name:	Black Bear Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$55,577
Facility Condition Index:	0.06 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,123
Building Code:	E7770017340	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$394,441
Building Name:	Monorail Station	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$43,850
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,824
Building Code:	E7770019640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,300,207
Building Name:	Life Support Discovery Bay	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$609,306
Facility Condition Index:	0.18 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	13,677
Building Code:	E7770019740	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$345,881
Building Name:	Marketing Trailer	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$88,908
Facility Condition Index:	0.26 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,381
Building Code:	E7770020145	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,568,213
Building Name:	Farm House	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$276,578
Facility Condition Index:	0.18 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	7,264
Building Code:	E7770020245	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$214,639
Building Name:	Goat - Sheep Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$42,965
Facility Condition Index:	0.20 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,168
Building Code:	E7770020345	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$372,295
Building Name:	Granary	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$46,334
Facility Condition Index:	0.12 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,149
Building Code:	E7770020445	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$506,614
Building Name:	Grain Elevator	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$55,726
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,524

Building Code:	E7770020545	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$191,075
Building Name:	Machine Shed	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$13,929
Facility Condition Index:	0.07 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,586
Building Code:	E7770020645	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$93,294
Building Name:	Chicken House	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$7,957
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,499
Building Code:	E7770020745	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$177,866
Building Name:	Swine Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$17,773
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	877
Building Code:	E7770020845	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$804,961
Building Name:	Dairy Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$79,339
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	5,494
Building Code:	E7770020945	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$151,258
Building Name:	Horse Barn	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$21,856
Facility Condition Index:	0.14 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,267
Building Code:	E7770021015	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,224
Facility Condition Index:	0.17 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021025	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$737
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021035	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 3	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,631
Facility Condition Index:	0.22 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021045	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 4	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,144
Facility Condition Index:	0.16 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021055	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 5	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,018
Facility Condition Index:	0.14 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021065	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 6	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,018
Facility Condition Index:	0.14 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021075	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,367
Building Name:	Farm Shelter 7	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,018
Facility Condition Index:	0.14 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154

Building Code:	E7770021085	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,802
Building Name:	Farm Shelter 8	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,046
Facility Condition Index:	0.12 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	154
Building Code:	E7770021095	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,191
Building Name:	Farm Loading Shelter	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$192
Facility Condition Index:	0.04 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	127
Building Code:	E7770021105	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$13,380
Building Name:	Pony Shed 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$806
Facility Condition Index:	0.06 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	185
Building Code:	E7770021115	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$13,380
Building Name:	Pony Shed 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$604
Facility Condition Index:	0.05 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	185
Building Code:	E7770022145	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$112,277
Building Name:	Concrete - Stave Silo	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$13,008
Facility Condition Index:	0.12 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	185
Building Code:	E7770022245	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$42,381
Building Name:	Metal Silo	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$6,939
Facility Condition Index:	0.16 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	181
Building Code:	E7770029640	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$22,363,318
Building Name:	Discovery Bay	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,453,877
Facility Condition Index:	0.07 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	73,585
Building Code:	E7770030050	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$13,447
Building Name:	Lakeside Terrace	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$269
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	355
Building Code:	E7770030150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,308,839
Building Name:	Bear - Otter Life Support	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$114,852
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	4,183
Building Code:	E7770030250	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,170,752
Building Name:	Bear - Otter Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$136,763
Facility Condition Index:	0.06 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	4,485
Building Code:	E7770030350	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,020,622
Building Name:	Leopard Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$94,334
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,828
Building Code:	E7770030450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$168,538
Building Name:	Wild Boar Holding	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$15,002
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	734

Building Code:	E7770030550	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$144,183
Building Name:	RGC Log Cabin	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$13,871
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	992
Building Code:	E7770030650	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$909,331
Building Name:	Education Event Center	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$78,661
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,670
Building Code:	E7770030750	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$353,144
Building Name:	Lancer Central Plaza	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$39,491
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,173
Building Code:	E7770030850	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,905
Building Name:	SSA Gift Outlet	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,268
Facility Condition Index:	0.04 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	365
Building Code:	E7770030950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$139,622
Building Name:	Plaza Restroom Facilities	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$8,704
Facility Condition Index:	0.06 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	862
Building Code:	E7770031050	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$29,198
Building Name:	Takin Viewing Shelter 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,956
Facility Condition Index:	0.10 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	268
Building Code:	E7770031150	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$29,198
Building Name:	Takin Viewing Shelter 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$3,847
Facility Condition Index:	0.13 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	268
Building Code:	E7770031350	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$32,765
Building Name:	Tiger Base Camp	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$5,099
Facility Condition Index:	0.16 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	406
Building Code:	E7770032050	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$785,080
Building Name:	Leopard Viewing	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$21,009
Facility Condition Index:	0.03 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	738
Building Code:	E7770032150	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$37,934
Building Name:	Boar Viewing	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$1,025
Facility Condition Index:	0.03 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	336
Building Code:	E7770032250	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$675,708
Building Name:	Bear Viewing 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$16,603
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	665
Building Code:	E7770032350	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,137,922
Building Name:	Bear Viewing 2 - Cave	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$95,297
Facility Condition Index:	0.08 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	3,160

Building Code:	E7770032450	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$184,404
Building Name:	Otter Viewing 1 - Entry	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$9,795
Facility Condition Index:	0.05 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	677
Building Code:	E7770032550	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,023,677
Building Name:	Otter Viewing 2 - Primary	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$83,956
Facility Condition Index:	0.08 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,448
Building Code:	E7770032650	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$86,485
Building Name:	Bear Tunnel	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$7,812
Facility Condition Index:	0.09 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	531
Building Code:	E7770040050	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$78,749
Building Name:	Lancer Pavilion	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,618
Facility Condition Index:	0.03 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,400
Building Code:	E7770040155	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$24,334
Building Name:	Tattoo Cabin	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,624
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	127
Building Code:	E7770050135	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$473,998
Building Name:	Classroom Unit 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$86,434
Facility Condition Index:	0.18 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,248
Building Code:	E7770050235	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$473,998
Building Name:	Classroom Unit 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$104,796
Facility Condition Index:	0.22 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	2,326
Building Code:	E7770050335	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$142,348
Building Name:	Classroom Storage	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$36,548
Facility Condition Index:	0.26 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	821
Building Code:	E7770070135	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,330,032
Building Name:	Lancer - SSA - Maint Warehouse	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$214,722
Facility Condition Index:	0.16 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	5,297
Building Code:	E7770070136	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,414
Building Name:	Parking Storage Bldg	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$9,700
Facility Condition Index:	0.20 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	490
Building Code:	E7770075050	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,398
Building Name:	Cars for Courage Booth	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,504
Facility Condition Index:	0.30 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	63
Building Code:	E7770080135	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$189,433
Building Name:	Water's Edge Picnic Shelter	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$59,673
Facility Condition Index:	0.32 - Poor	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,654

Building Code:	E7770080235	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$170,666
Building Name:	Shady Oaks Picnic Shelter 1	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$18,929
Facility Condition Index:	0.11 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,702
Building Code:	E7770080335	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$174,257
Building Name:	Shady Oaks Picnic Shelter 2	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$42,909
Facility Condition Index:	0.25 - Fair	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	1,654
Building Code:	E7770080435	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,171
Building Name:	Chrysalis Building	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$2,520
Facility Condition Index:	0.05 - Good	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	231
Building Code:	E7770080535	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$26,884
Building Name:	Hoop House B	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$538
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	337
Building Code:	E7770080635	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$26,724
Building Name:	Hoop House A	**Address:**	13000 Zoo Boulevard	**Deferred Maintenance:**	$534
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLE VALLEY	**Ext. Gross Area:**	335

Agency: G02 - Department of Administration

FCI Rating:	Good	**Current Replacement Value:**	$1,796,608,880	**Ext. Gross Area:**	5,531,893
Facility Condition Index:	0.09	**Deferred Maintenance:**	$161,448,917	**Building Count:**	30

Site: G02310 - Capitol Complex

Building Code:	G0231010062	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$694,818,890
Building Name:	Capitol Building	**Address:**	75 Rev. Dr Martin Luther King	**Deferred Maintenance:**	$24,190,603
Facility Condition Index:	0.03 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	374,561
Building Code:	G0231010162	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$20,333,910
Building Name:	Administration Building	**Address:**	50 Sherburne Avenue	**Deferred Maintenance:**	$1,676,093
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	80,100
Building Code:	G0231010362	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$96,573,471
Building Name:	Minnesota Senate Building	**Address:**	95 University Avenue West	**Deferred Maintenance:**	$2,076,207
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	296,589
Building Code:	G0231010462	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$74,790,363
Building Name:	State Office Bldg	**Address:**	100 Rev. Dr Martin Luther King	**Deferred Maintenance:**	$20,024,037
Facility Condition Index:	0.27 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	290,138
Building Code:	G0231010562	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$67,077,719
Building Name:	Transportation Building	**Address:**	395 John Ireland Blvd	**Deferred Maintenance:**	$7,245,493
Facility Condition Index:	0.11 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	374,649
Building Code:	G0231010662	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$20,615,912
Building Name:	Veterans Service Building	**Address:**	20 West 12th Street	**Deferred Maintenance:**	$1,843,372
Facility Condition Index:	0.09 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	87,648
Building Code:	G0231010762	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$81,673,393
Building Name:	Centennial Office Building	**Address:**	658 Cedar Avenue	**Deferred Maintenance:**	$16,916,803
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	317,893
Building Code:	G0231010962	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$6,745,681
Building Name:	Maintenance Building	**Address:**	691 N. Robert Street	**Deferred Maintenance:**	$882,789
Facility Condition Index:	0.13 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	28,118
Building Code:	G0231011062	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$12,847,770
Building Name:	Powerhouse	**Address:**	9 East Aurora	**Deferred Maintenance:**	$5,699,513
Facility Condition Index:	0.44 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	22,001
Building Code:	G0231011462	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$14,541,554
Building Name:	Ford Building	**Address:**	117 University Avenue	**Deferred Maintenance:**	$9,830,951
Facility Condition Index:	0.68 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	57,143

Building Code:	G0231011862	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$6,403,703
Building Name:	Governor's Residence	**Address:**	1006 Summit Avenue	**Deferred Maintenance:**	$1,527,321
Facility Condition Index:	0.24 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	16,935
Building Code:	G0231012462	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$55,444,184
Building Name:	Judicial Center	**Address:**	25 Rev Dr Martin Luther King Jr Blv	**Deferred Maintenance:**	$6,068,040
Facility Condition Index:	0.11 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	336,639
Building Code:	G0231023762	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$11,582,286
Building Name:	321 Grove St. #1	**Address:**	321 Grove	**Deferred Maintenance:**	$2,973,456
Facility Condition Index:	0.26 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	49,498
Building Code:	G0231023862	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,165,588
Building Name:	321 Grove St. #2	**Address:**	603 Pine	**Deferred Maintenance:**	$98,678
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	7,709
Building Code:	G0231023962	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$119,170,035
Building Name:	Stassen Building	**Address:**	600 North Robert	**Deferred Maintenance:**	$11,957,935
Facility Condition Index:	0.10 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	470,317
Building Code:	G0231025569	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,746,791
Building Name:	Ely Revenue Services Building	**Address:**	760 East Minor Drive	**Deferred Maintenance:**	$418,260
Facility Condition Index:	0.09 - Good	**City Code:**	Ely	**Ext. Gross Area:**	15,931
Building Code:	G0231025792	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$5,562,532
Building Name:	BCA Bemidji	**Address:**	3700 North Norris Court NW	**Deferred Maintenance:**	$429,562
Facility Condition Index:	0.08 - Good	**City Code:**	Bemidji	**Ext. Gross Area:**	26,854
Building Code:	G0231025862	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,739,552
Building Name:	Carriage House	**Address:**	1006 Summit Avenue	**Deferred Maintenance:**	$212,806
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,269
Building Code:	G0231026362	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$72,686,597
Building Name:	BCA Maryland	**Address:**	1430 Maryland Ave East	**Deferred Maintenance:**	$4,113,927
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	239,524
Building Code:	G0231026962	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$260,361
Building Name:	Governor's Storage Bldg	**Address:**	1006 Summit Ave	**Deferred Maintenance:**	$49,091
Facility Condition Index:	0.19 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,487
Building Code:	G0231027162	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$85,849,403
Building Name:	MDA/MDH Lab	**Address:**	601 North Robert Street	**Deferred Maintenance:**	$6,106,273
Facility Condition Index:	0.07 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	181,019
Building Code:	G0231027262	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$82,279,765
Building Name:	Freeman Office Building	**Address:**	625 North Robert Street	**Deferred Maintenance:**	$4,000,099
Facility Condition Index:	0.05 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	374,746

Building Code:	G0231027362	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$113,471,774
Building Name:	Andersen Office Building	**Address:**	540 Cedar Street	**Deferred Maintenance:**	$7,101,160
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	414,068
Building Code:	G0231028862	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$9,450,263
Building Name:	Surplus Services Warehouse	**Address:**	5420 Old Highway 8	**Deferred Maintenance:**	$802,891
Facility Condition Index:	0.08 - Good	**City Code:**	Arden Hills	**Ext. Gross Area:**	46,395
Building Code:	G0231040262	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$10,611,162
Building Name:	Administration Ramp	**Address:**	504 Capitol Blvd	**Deferred Maintenance:**	$2,449,213
Facility Condition Index:	0.23 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	98,634
Building Code:	G0231040862	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$43,189,006
Building Name:	Centennial Ramp	**Address:**	W. Central Pk Pl & Columbus	**Deferred Maintenance:**	$16,832,425
Facility Condition Index:	0.39 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	504,879
Building Code:	G0231040962	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$18,375,998
Building Name:	Ramp F	**Address:**	424 Rice Street	**Deferred Maintenance:**	$545,575
Facility Condition Index:	0.03 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	179,126
Building Code:	G0231042562	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$17,615,867
Building Name:	State Office Ramp	**Address:**	106 Aurora Avenue	**Deferred Maintenance:**	$1,588,039
Facility Condition Index:	0.09 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	141,162
Building Code:	G0231044162	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$23,461,705
Building Name:	14th Street Ramp	**Address:**	135 East 14th Street	**Deferred Maintenance:**	$2,904,089
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	269,974
Building Code:	G0231047462	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$23,523,643
Building Name:	Andersen Ramp	**Address:**	540 Cedar Street	**Deferred Maintenance:**	$884,216
Facility Condition Index:	0.04 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	224,890

Agency: G62 - MN State Retirement Systems

FCI Rating:	Good	**Current Replacement Value:**	$48,836,924	**Ext. Gross Area:**	259,837
Facility Condition Index:	0.06	**Deferred Maintenance:**	$2,850,583	**Building Count:**	2

Site: G02310 - Capitol Complex

Building Code:	G6231025162	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$38,078,532
Building Name:	Retirement Systems	**Address:**	60 Empire Drive	**Deferred Maintenance:**	$2,174,834
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	145,147

Building Code:	G6231046262	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$10,758,392
Building Name:	Retirement Systems Ramp	**Address:**	60 Empire Drive	**Deferred Maintenance:**	$675,749
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	114,690

Agency: H55 - Department of Human Services

FCI Rating:	Fair	**Current Replacement Value:**	$1,032,376,225	**Ext. Gross Area:**	2,535,241
Facility Condition Index:	0.19	**Deferred Maintenance:**	$192,218,113	**Building Count:**	160

Site: H55200 - ANOKA METRO R.T.C.

Building Code:	H5520000690	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$1,766,873
Building Name:	Como Apartment	**Address:**	690 Como Ave	**Deferred Maintenance:**	$554,755
Facility Condition Index:	0.31 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	12,662
Building Code:	H552033010A	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$33,628,935
Building Name:	A - Building	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$4,326,606
Facility Condition Index:	0.13 - Good	**City Code:**	ANOKA	**Ext. Gross Area:**	116,227
Building Code:	H5520330111	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$22,162,169
Building Name:	Miller Building	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$7,983,476
Facility Condition Index:	0.36 - Poor	**City Code:**	ANOKA	**Ext. Gross Area:**	85,340
Building Code:	H5520330117	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$18,267,946
Building Name:	Food Service	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$6,798,243
Facility Condition Index:	0.37 - Poor	**City Code:**	ANOKA	**Ext. Gross Area:**	68,106
Building Code:	H5520330125	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$52,856
Building Name:	Miller Lift Station - MC7	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$12,158
Facility Condition Index:	0.23 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	91
Building Code:	H5520330138	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$342,943
Building Name:	Pole Barn/Storage Bldg.	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$8,870
Facility Condition Index:	0.03 - Excellent	**City Code:**	ANOKA	**Ext. Gross Area:**	2,420
Building Code:	H5520330139	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$278,423
Building Name:	Grounds Shop/Storage	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$96,339
Facility Condition Index:	0.35 - Poor	**City Code:**	ANOKA	**Ext. Gross Area:**	2,594
Building Code:	H5520330140	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$228,517
Building Name:	Metal Pole Barn	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$45,387
Facility Condition Index:	0.20 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	1,949
Building Code:	H55203301BC	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$9,785,250
Building Name:	B & C Building	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$1,925,014
Facility Condition Index:	0.20 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	35,311
Building Code:	H55203301DE	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$9,878,131
Building Name:	D & E Building	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$1,760,969
Facility Condition Index:	0.18 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	36,115

Building Code:	H55203301GH	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$11,524,068
Building Name:	G & H Building	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$2,751,809
Facility Condition Index:	0.24 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	35,417
Building Code:	H55203301LK	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$921,777
Building Name:	Connecting Link	**Address:**	3301 7TH Ave. N.	**Deferred Maintenance:**	$141,489
Facility Condition Index:	0.15 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	3,139

Site: H55300 - BRAINERD REGIONAL H.S.C.

Building Code:	H5530000018	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$401,783
Building Name:	Storage Building 18	**Address:**	11690 State Avenue	**Deferred Maintenance:**	$89,571
Facility Condition Index:	0.22 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	2,600
Building Code:	H5530000020	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$9,143,549
Building Name:	MNCARE Building 20	**Address:**	11630 State Avenue	**Deferred Maintenance:**	$1,077,760
Facility Condition Index:	0.12 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	31,654
Building Code:	H5530000021	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$22,908,510
Building Name:	MSHS Building 21	**Address:**	11615 State Avenue	**Deferred Maintenance:**	$11,691,952
Facility Condition Index:	0.51 - Crisis	**City Code:**	BRAINERD	**Ext. Gross Area:**	49,371
Building Code:	H5530000022	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$12,066,387
Building Name:	Office Building 22	**Address:**	11600 State Avenue	**Deferred Maintenance:**	$2,942,775
Facility Condition Index:	0.24 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	67,455
Building Code:	H5530000041	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$282,785
Building Name:	Screened Building	**Address:**	11600 State Avenue	**Deferred Maintenance:**	$35,891
Facility Condition Index:	0.13 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,681
Building Code:	H5530000042	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$3,002,604
Building Name:	Tunnel System - BRHSC	**Address:**	11600 State Avenue	**Deferred Maintenance:**	$837,288
Facility Condition Index:	0.28 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	16,330
Building Code:	H5530000045	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,226
Building Name:	STORAGE SHED	**Address:**	11600 STATE AVENUE	**Deferred Maintenance:**	$6,197
Facility Condition Index:	0.34 - Poor	**City Code:**	BRAINERD	**Ext. Gross Area:**	196

Site: H55400 - MSHS - Cambridge

Building Code:	H5540000001	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,244,960
Building Name:	Home 1	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$292,548
Facility Condition Index:	0.23 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	3,381

Building Code:	H5540000002	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,090,040
Building Name:	Home 2	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$233,355
Facility Condition Index:	0.21 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	5,965
Building Code:	H5540000003	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$795,768
Building Name:	Home 3	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$121,789
Facility Condition Index:	0.15 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	3,384
Building Code:	H5540000004	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,111,539
Building Name:	Home 4	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$218,782
Facility Condition Index:	0.20 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	5,967
Building Code:	H5540000005	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$744,151
Building Name:	Home 5	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$139,210
Facility Condition Index:	0.19 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	3,390
Building Code:	H5540000006	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$959,301
Building Name:	Home 6	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$214,694
Facility Condition Index:	0.22 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	5,959
Building Code:	H5540000007	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,071,852
Building Name:	Home 7	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$152,603
Facility Condition Index:	0.14 - Good	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	4,775
Building Code:	H5540000008	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$937,654
Building Name:	Home 8	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$139,825
Facility Condition Index:	0.15 - Good	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	4,134
Building Code:	H5540000017	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$7,288,136
Building Name:	Rec./Maintenance	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$2,196,638
Facility Condition Index:	0.30 - Poor	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	29,542
Building Code:	H5540000018	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$11,158,528
Building Name:	Admin.& Program Support	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$3,708,060
Facility Condition Index:	0.33 - Poor	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	52,228
Building Code:	H5540000024	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$2,911
Building Name:	Lift Station - Mc24	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$328
Facility Condition Index:	0.11 - Good	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	28
Building Code:	H5540000027	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$6,628,333
Building Name:	Vocational Train-Mshs	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$2,887,847
Facility Condition Index:	0.44 - Poor	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	24,872
Building Code:	H5540000028	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,294,300
Building Name:	MSHS - Power Plant	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$1,162,665
Facility Condition Index:	0.27 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	13,265

Building Code:	H5540000031	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$257,138
Building Name:	Paint Storage Bldg.	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$70,078
Facility Condition Index:	0.27 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	1,929
Building Code:	H5540000046	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$1,632,633
Building Name:	Tunnel System - Mshs	**Address:**	1425 E Rum River Drive So	**Deferred Maintenance:**	$460,029
Facility Condition Index:	0.28 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	8,958

Site: H55500 - CBS

Building Code:	H5550004DP1	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$860,223
Building Name:	Kenyon - Blaine	**Address:**	12949 Kenyon St NE	**Deferred Maintenance:**	$157,001
Facility Condition Index:	0.18 - Fair	**City Code:**	BLAINE	**Ext. Gross Area:**	4,851
Building Code:	H5550004DP2	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$705,528
Building Name:	6th Ave - Pine City	**Address:**	215 6Th Ave SE	**Deferred Maintenance:**	$116,147
Facility Condition Index:	0.16 - Fair	**City Code:**	PINE CITY	**Ext. Gross Area:**	3,363
Building Code:	H5550005123	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$726,797
Building Name:	Dean - Champlin	**Address:**	310 Dean Ave E	**Deferred Maintenance:**	$130,735
Facility Condition Index:	0.18 - Fair	**City Code:**	CHAMPLIN	**Ext. Gross Area:**	2,572
Building Code:	H5550005125	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$863,481
Building Name:	Rosewood - Dayton	**Address:**	14080 Rosewood Ln N	**Deferred Maintenance:**	$129,296
Facility Condition Index:	0.15 - Good	**City Code:**	DAYTON	**Ext. Gross Area:**	4,266
Building Code:	H5550005139	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$610,924
Building Name:	220th Street - Scandia	**Address:**	15565 220Th Street	**Deferred Maintenance:**	$105,062
Facility Condition Index:	0.17 - Fair	**City Code:**	SCANDIA	**Ext. Gross Area:**	3,225
Building Code:	H5550005143	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$627,496
Building Name:	Iverson - Forest Lake	**Address:**	22500 Iverson Ave	**Deferred Maintenance:**	$166,639
Facility Condition Index:	0.27 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	3,460
Building Code:	H5550005302	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$673,037
Building Name:	W 6th St - West Concord	**Address:**	406 West 6Th St	**Deferred Maintenance:**	$111,198
Facility Condition Index:	0.17 - Fair	**City Code:**	WEST CONCORD	**Ext. Gross Area:**	3,629
Building Code:	H5550005331	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$860,555
Building Name:	Old Shakopee - Bloomington	**Address:**	10101 1St Ave S	**Deferred Maintenance:**	$87,789
Facility Condition Index:	0.10 - Good	**City Code:**	BLOOMINGTON	**Ext. Gross Area:**	3,524
Building Code:	H5550005367	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$627,695
Building Name:	Summerset - Rochester	**Address:**	5405 Hwy63 So	**Deferred Maintenance:**	$138,284
Facility Condition Index:	0.22 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	3,387

Building Code:	H5550005658	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$868,870
Building Name:	Park Avenue - Faribault	**Address:**	2307 Park Ave NW	**Deferred Maintenance:**	$132,224
Facility Condition Index:	0.15 - Fair	**City Code:**	FARIBAULT	**Ext. Gross Area:**	4,268
Building Code:	H5550005659	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$876,763
Building Name:	Highland - Northfield	**Address:**	300 Highland Ave	**Deferred Maintenance:**	$87,708
Facility Condition Index:	0.10 - Good	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	4,496
Building Code:	H5550005660	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$798,088
Building Name:	3rd Street - Faribault	**Address:**	1011 3Rd Street SE	**Deferred Maintenance:**	$149,014
Facility Condition Index:	0.19 - Fair	**City Code:**	FARIBAULT	**Ext. Gross Area:**	4,446
Building Code:	H5550005661	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$884,055
Building Name:	Donnelly - Farmington	**Address:**	20345 Donnelly Ave	**Deferred Maintenance:**	$51,704
Facility Condition Index:	0.06 - Good	**City Code:**	FARMINGTON	**Ext. Gross Area:**	5,010
Building Code:	H5550005662	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$912,936
Building Name:	Crystal - Burnsville	**Address:**	1101 W Crystal Lake Rd	**Deferred Maintenance:**	$135,803
Facility Condition Index:	0.15 - Good	**City Code:**	BURNSVILLE	**Ext. Gross Area:**	5,573
Building Code:	H5550005663	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$989,656
Building Name:	Sciota - Northfield	**Address:**	1375 310Th St E (Sciota	**Deferred Maintenance:**	$152,014
Facility Condition Index:	0.15 - Fair	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	4,234
Building Code:	H5550005664	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$729,068
Building Name:	Sibley - Eagan	**Address:**	3034 Sibley Memorial Hwy	**Deferred Maintenance:**	$131,973
Facility Condition Index:	0.18 - Fair	**City Code:**	EAGAN	**Ext. Gross Area:**	2,963
Building Code:	H5550005665	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$838,678
Building Name:	Scott Ave.- Golden Valley	**Address:**	3220 Scott Ave	**Deferred Maintenance:**	$148,446
Facility Condition Index:	0.18 - Fair	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	4,190
Building Code:	H5550005666	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$838,678
Building Name:	19Th Avenue - Mpls.	**Address:**	3740 19Th Ave So	**Deferred Maintenance:**	$127,026
Facility Condition Index:	0.15 - Fair	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	4,347
Building Code:	H5550005667	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$838,678
Building Name:	41St Avenue - Mpls.	**Address:**	3740 41St Ave So	**Deferred Maintenance:**	$145,656
Facility Condition Index:	0.17 - Fair	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	4,349
Building Code:	H5550005668	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$850,761
Building Name:	Prestwick - Brooklyn Pk	**Address:**	8920 Prestwick Circle N	**Deferred Maintenance:**	$129,576
Facility Condition Index:	0.15 - Fair	**City Code:**	BROOKLYN PARK	**Ext. Gross Area:**	4,313
Building Code:	H5550005669	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$850,761
Building Name:	89Th Crescent-Brooklyn Pk	**Address:**	5422 89Th Crescent No	**Deferred Maintenance:**	$128,414
Facility Condition Index:	0.15 - Fair	**City Code:**	BROOKLYN PARK	**Ext. Gross Area:**	4,322

Building Code:	H5550005673	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$838,678
Building Name:	4th Ave - Richfield	**Address:**	6637 4Th Ave So	**Deferred Maintenance:**	$76,408
Facility Condition Index:	0.09 - Good	**City Code:**	RICHFIELD	**Ext. Gross Area:**	3,809
Building Code:	H5550005674	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$883,533
Building Name:	91St Crescent-Brooklyn Pk	**Address:**	5209 91St Crescent	**Deferred Maintenance:**	$87,906
Facility Condition Index:	0.10 - Good	**City Code:**	BROOKLYN PARK	**Ext. Gross Area:**	4,317
Building Code:	H5550005682	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$836,743
Building Name:	Eaves Way - Farmington	**Address:**	20359 Eaves Way	**Deferred Maintenance:**	$132,209
Facility Condition Index:	0.16 - Fair	**City Code:**	FARMINGTON	**Ext. Gross Area:**	2,920
Building Code:	H5550005708	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$707,063
Building Name:	7th Avenue - Faribault	**Address:**	813 SW 7Th Ave	**Deferred Maintenance:**	$122,412
Facility Condition Index:	0.17 - Fair	**City Code:**	FARIBAULT	**Ext. Gross Area:**	3,367
Building Code:	H5550005709	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$858,398
Building Name:	Second Street - Morristown	**Address:**	400 Sw Second St	**Deferred Maintenance:**	$105,334
Facility Condition Index:	0.12 - Good	**City Code:**	MORRISTOWN	**Ext. Gross Area:**	3,713
Building Code:	H5550005710	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$899,459
Building Name:	Ableman - Warsaw	**Address:**	23450 Falls Ave	**Deferred Maintenance:**	$118,300
Facility Condition Index:	0.13 - Good	**City Code:**	WARSAW	**Ext. Gross Area:**	3,675
Building Code:	H5550005711	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$948,077
Building Name:	Jefferson - Northfield	**Address:**	1904 Jefferson Rd	**Deferred Maintenance:**	$145,689
Facility Condition Index:	0.15 - Fair	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	3,031
Building Code:	H5550005713	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$968,726
Building Name:	Allen Path - Faribault	**Address:**	54 Allen Path	**Deferred Maintenance:**	$198,732
Facility Condition Index:	0.21 - Fair	**City Code:**	FARIBAULT	**Ext. Gross Area:**	3,521
Building Code:	H5550005714	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$849,976
Building Name:	Canby Court - Northfield	**Address:**	8631 Canby Court	**Deferred Maintenance:**	$174,439
Facility Condition Index:	0.21 - Fair	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	3,544
Building Code:	H5550005715	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$565,214
Building Name:	8Th Avenue - Owatonna	**Address:**	2020 8Th Ave NE	**Deferred Maintenance:**	$111,424
Facility Condition Index:	0.20 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	3,432
Building Code:	H5550005716	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$588,733
Building Name:	32Nd Avenue - Owatonna	**Address:**	300 SW 32Nd Ave	**Deferred Maintenance:**	$124,490
Facility Condition Index:	0.21 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	3,153
Building Code:	H5550005717	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$858,558
Building Name:	Bethesda - Alexandria	**Address:**	123 Bethesda St Nw	**Deferred Maintenance:**	$90,846
Facility Condition Index:	0.11 - Good	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	4,429

Building Code:	H5550005718	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,769,985
Building Name:	Old Hwy 4 - Biwabik	**Address:**	101 Old Hwy 4 - Po#205	**Deferred Maintenance:**	$455,282
Facility Condition Index:	0.26 - Fair	**City Code:**	BIWABIK	**Ext. Gross Area:**	9,265
Building Code:	H5550005719	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,388,555
Building Name:	13th Ave - East Grand Forks	**Address:**	2134/2132 13Th Ave Nw	**Deferred Maintenance:**	$190,015
Facility Condition Index:	0.14 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	6,437
Building Code:	H5550005721	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$496,553
Building Name:	140th Avenue - Mahnomen	**Address:**	2559 140Th Avenue	**Deferred Maintenance:**	$89,096
Facility Condition Index:	0.18 - Fair	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	2,521
Building Code:	H5550005722	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,177,937
Building Name:	63rd Avenue - Moorhead	**Address:**	820 63Rd Avenue N	**Deferred Maintenance:**	$135,808
Facility Condition Index:	0.12 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	6,012
Building Code:	H5550005723	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$974,935
Building Name:	4th Street - Moose Lake	**Address:**	305 4Th Street - Po#495	**Deferred Maintenance:**	$175,701
Facility Condition Index:	0.18 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	4,891
Building Code:	H5550005724	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,304,445
Building Name:	Baker - Redwood Falls	**Address:**	205 Baker Drive	**Deferred Maintenance:**	$155,260
Facility Condition Index:	0.12 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	4,870
Building Code:	H5550005725	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,165,520
Building Name:	Swan Lake - Duluth	**Address:**	1423 Swan Lake Road	**Deferred Maintenance:**	$164,907
Facility Condition Index:	0.14 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	4,852
Building Code:	H5550005726	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,127,400
Building Name:	7th Ave - Virginia	**Address:**	700 S 7Th Avenue	**Deferred Maintenance:**	$250,637
Facility Condition Index:	0.22 - Fair	**City Code:**	VIRGINIA	**Ext. Gross Area:**	4,807
Building Code:	H5550005727	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$741,726
Building Name:	Jennifer - Hermantown	**Address:**	5668 W Arrowhead Road	**Deferred Maintenance:**	$103,706
Facility Condition Index:	0.14 - Good	**City Code:**	HERMANTOWN	**Ext. Gross Area:**	2,617
Building Code:	H5550005728	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$764,830
Building Name:	Maple Grove - Hermantown	**Address:**	5223 Maple Grove Road	**Deferred Maintenance:**	$211,925
Facility Condition Index:	0.28 - Fair	**City Code:**	HERMANTOWN	**Ext. Gross Area:**	3,201
Building Code:	H5550005729	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$476,361
Building Name:	Loon Dr - Pine City	**Address:**	12433 Loon Drive	**Deferred Maintenance:**	$155,353
Facility Condition Index:	0.33 - Poor	**City Code:**	PINE CITY	**Ext. Gross Area:**	2,340
Building Code:	H5550005731	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$764,930
Building Name:	Middle River-Redwood Falls	**Address:**	630 Middle Street	**Deferred Maintenance:**	$90,305
Facility Condition Index:	0.12 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	2,965

Building Code:	H5550005732	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$764,930
Building Name:	Falls Place - Redwood Falls	**Address:**	628 Middle Street	**Deferred Maintenance:**	$83,902
Facility Condition Index:	0.11 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	2,961
Building Code:	H5550005DP1	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$709,770
Building Name:	Hershey - Lakeville	**Address:**	20086 Hershey Ave W(#1)	**Deferred Maintenance:**	$117,730
Facility Condition Index:	0.17 - Fair	**City Code:**	LAKEVILLE	**Ext. Gross Area:**	3,422
Building Code:	H5550005DP2	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$668,529
Building Name:	17Th Street - Rochester	**Address:**	448 17Th St SW	**Deferred Maintenance:**	$133,130
Facility Condition Index:	0.20 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	3,401
Building Code:	H5550005DP3	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,503,620
Building Name:	12th Street - Austin	**Address:**	1000 12Th St SW	**Deferred Maintenance:**	$207,541
Facility Condition Index:	0.14 - Good	**City Code:**	AUSTIN	**Ext. Gross Area:**	4,308
Building Code:	H5550005DP4	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$870,534
Building Name:	1st Ave - Kasson	**Address:**	1101 1St Ave NE	**Deferred Maintenance:**	$131,128
Facility Condition Index:	0.15 - Fair	**City Code:**	KASSON	**Ext. Gross Area:**	4,864
Building Code:	H5550005DP5	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,243,242
Building Name:	Shumway - Faribault	**Address:**	1805 Shumway	**Deferred Maintenance:**	$181,643
Facility Condition Index:	0.15 - Good	**City Code:**	FARIBAULT	**Ext. Gross Area:**	4,876
Building Code:	H5550005DP6	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,117,822
Building Name:	Jonquil - Lakeville	**Address:**	17041 Jonquil Ave (#2)	**Deferred Maintenance:**	$257,293
Facility Condition Index:	0.23 - Fair	**City Code:**	LAKEVILLE	**Ext. Gross Area:**	4,445
Building Code:	H5550005DP7	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,200,041
Building Name:	Dell Road - Eden Prairie	**Address:**	7198 Dell Rd (A)	**Deferred Maintenance:**	$239,388
Facility Condition Index:	0.20 - Fair	**City Code:**	EDEN PRAIRIE	**Ext. Gross Area:**	4,889
Building Code:	H5550005DP8	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,040,910
Building Name:	Oakland - Bloomington	**Address:**	8634 Oakland Ave	**Deferred Maintenance:**	$114,575
Facility Condition Index:	0.11 - Good	**City Code:**	BLOOMINGTON	**Ext. Gross Area:**	4,900
Building Code:	H5550005DP9	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,218,097
Building Name:	Chatham Way- Eden Prairie	**Address:**	6204 Chatham Way (B)	**Deferred Maintenance:**	$165,852
Facility Condition Index:	0.14 - Good	**City Code:**	EDEN PRAIRIE	**Ext. Gross Area:**	4,903
Building Code:	H55500G5139	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$82,200
Building Name:	220th St - Scandia-Garage/Shed	**Address:**	15565 220Th Street	**Deferred Maintenance:**	$38,033
Facility Condition Index:	0.46 - Poor	**City Code:**	SCANDIA	**Ext. Gross Area:**	854
Building Code:	H55500G5143	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$74,384
Building Name:	Iverson -Forest Lake - Garage	**Address:**	22500 Iverson Ave	**Deferred Maintenance:**	$14,641
Facility Condition Index:	0.20 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	578

Building Code:	H55500G5367	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$56,278
Building Name:	Summerset - Rochester - Garage	**Address:**	5405 Hwy63 So	**Deferred Maintenance:**	$2,624
Facility Condition Index:	0.05 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	672
Building Code:	H55500G5662	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,855
Building Name:	Crystal - Burnsville - Garage	**Address:**	1101 W Crystal Lake Rd	**Deferred Maintenance:**	$6,228
Facility Condition Index:	0.26 - Fair	**City Code:**	BURNSVILLE	**Ext. Gross Area:**	256
Building Code:	H55500G5708	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$37,992
Building Name:	7th Ave - Faribault - Garage	**Address:**	813 SW 7Th Ave	**Deferred Maintenance:**	$12,097
Facility Condition Index:	0.32 - Poor	**City Code:**	FARIBAULT	**Ext. Gross Area:**	294
Building Code:	H55500G5721	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$160,442
Building Name:	140th Avenue - Mahnomen-Garage	**Address:**	2559 140Th Avenue	**Deferred Maintenance:**	$20,904
Facility Condition Index:	0.13 - Good	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	1,292
Building Code:	H55500G5724	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,066
Building Name:	Baker-Garage-Redwood Falls	**Address:**	205 Baker Drive	**Deferred Maintenance:**	$1,487
Facility Condition Index:	0.09 - Good	**City Code:**	Redwood Falls	**Ext. Gross Area:**	120
Building Code:	H55500G5727	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$137,064
Building Name:	Jennifer - Hermantown - Garage	**Address:**	5668 W Arrowhead Road	**Deferred Maintenance:**	$93,817
Facility Condition Index:	0.68 - Crisis	**City Code:**	HERMANTOWN	**Ext. Gross Area:**	1,188
Building Code:	H55500G5728	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,868
Building Name:	Maple Grove-Hermantown-Garage	**Address:**	5223 Maple Grove Road	**Deferred Maintenance:**	$59,704
Facility Condition Index:	0.57 - Crisis	**City Code:**	HERMANTOWN	**Ext. Gross Area:**	909
Building Code:	H55500S5367	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$155,902
Building Name:	Summerset - Rochester - Shed	**Address:**	5405 Hwy63 So	**Deferred Maintenance:**	$109,171
Facility Condition Index:	0.70 - Crisis	**City Code:**	ROCHESTER	**Ext. Gross Area:**	1,762
Building Code:	H55500S5716	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$39,157
Building Name:	32nd Ave-Owatonna-Garage/Shop	**Address:**	300 SW 32Nd Ave	**Deferred Maintenance:**	$4,521
Facility Condition Index:	0.12 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	329
Building Code:	H5550SS5716	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,429
Building Name:	32nd Ave - Owatonna-Shed	**Address:**	300 SW 32Nd Ave	**Deferred Maintenance:**	$7,220
Facility Condition Index:	0.41 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	114

Site: H55700 - MOOSE LAKE MSOP

Building Code:	H5570000001	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$103,235,845
Building Name:	MSOP Main	**Address:**	1111 Highway 73	**Deferred Maintenance:**	$25,033,276
Facility Condition Index:	0.24 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	186,477

Building Code:	H5570000002	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$73,655,800
Building Name:	MSOP Complex	**Address:**	1111 Highway 73	**Deferred Maintenance:**	$3,995,718
Facility Condition Index:	0.05 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	158,096
Building Code:	H5570000005	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$4,616,314
Building Name:	Loading Dock Building	**Address:**	1111 Highway 73	**Deferred Maintenance:**	$142,181
Facility Condition Index:	0.03 - Excellent	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	13,968
Building Code:	H5570000006	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$37,102,254
Building Name:	MSOP Support Building	**Address:**	1111 Highway 73	**Deferred Maintenance:**	$2,338,803
Facility Condition Index:	0.06 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	98,481
Building Code:	H5570000007	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$773,395
Building Name:	Vehicle Garage	**Address:**	1111 Highway 73	**Deferred Maintenance:**	$25,434
Facility Condition Index:	0.03 - Excellent	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	3,960
Building Code:	H5570000008	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$211,093
Building Name:	Maintenance Garage	**Address:**	1111 Highway 73	**Deferred Maintenance:**	$7,745
Facility Condition Index:	0.04 - Excellent	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	1,147

Site: H55800 - ST. PETER R.T.C.

Building Code:	H5580000001	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$35,291,008
Building Name:	Shantz	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$4,631,034
Facility Condition Index:	0.13 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	80,776
Building Code:	H5580000002	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$33,538,268
Building Name:	Pexton Hall	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$8,673,445
Facility Condition Index:	0.26 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	91,029
Building Code:	H5580000003	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$38,211,045
Building Name:	Bartlett Hall	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$13,166,571
Facility Condition Index:	0.34 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	88,309
Building Code:	H5580000004	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$8,125,147
Building Name:	Tomlinson Hall	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$4,173,823
Facility Condition Index:	0.51 - Crisis	**City Code:**	ST. PETER	**Ext. Gross Area:**	23,255
Building Code:	H5580000005	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$403,898
Building Name:	Gluek Building	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$108,675
Facility Condition Index:	0.27 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	1,742
Building Code:	H5580000007	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,735
Building Name:	Storage Shed - Mc8	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$8,349
Facility Condition Index:	0.38 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	168

Building Code:	H5580000008	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$84,966
Building Name:	Gazebo/Paula Olson	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$17,091
Facility Condition Index:	0.20 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	648
Building Code:	H5580000010	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$13,402,405
Building Name:	Pedersen Bldg-Sprtc	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$3,458,716
Facility Condition Index:	0.26 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	45,532
Building Code:	H5580000016	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$45,788
Building Name:	Liberty Hall Garage	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$2,510
Facility Condition Index:	0.05 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	660
Building Code:	H5580000017	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$78,578
Building Name:	Carpenter Garage	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$18,336
Facility Condition Index:	0.23 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	896
Building Code:	H5580000020	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$59,920
Building Name:	Rec. Van Garage (Left)	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$29,946
Facility Condition Index:	0.50 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	528
Building Code:	H5580000021	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$56,296
Building Name:	Rec. Van Garage (Right)	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$21,195
Facility Condition Index:	0.38 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	528
Building Code:	H5580000022	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,862
Building Name:	Garden Center/Garage	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$5,114
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	484
Building Code:	H5580000025	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$13,902,600
Building Name:	Green Acres	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,942,445
Facility Condition Index:	0.14 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	40,299
Building Code:	H5580000026	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$14,371,095
Building Name:	Sunrise	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$4,783,708
Facility Condition Index:	0.33 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	40,294
Building Code:	H5580000037	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$6,275,993
Building Name:	Johnson Hall	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,755,010
Facility Condition Index:	0.28 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	23,822
Building Code:	H5580000051	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$23,971,020
Building Name:	Old Center Building	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$9,386,570
Facility Condition Index:	0.39 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	55,055
Building Code:	H5580000060	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$18,313,752
Building Name:	Kitchen/Warehouse	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$5,632,928
Facility Condition Index:	0.31 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	48,659

Building Code:	H5580000061	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$109,343
Building Name:	Garage	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$32,584
Facility Condition Index:	0.30 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	974
Building Code:	H5580000062	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$151,739
Building Name:	Bedrock Car Wash	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$56,074
Facility Condition Index:	0.37 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	905
Building Code:	H5580000063	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$328,266
Building Name:	Grounds Garage (Office)	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$149,492
Facility Condition Index:	0.46 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	1,500
Building Code:	H5580000065	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$8,376,280
Building Name:	Vocational Building	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,494,953
Facility Condition Index:	0.18 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	24,724
Building Code:	H5580000069	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$52,426
Building Name:	Gas Control Building	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$3,923
Facility Condition Index:	0.07 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	217
Building Code:	H5580000070	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$14,928,110
Building Name:	Power Plant	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$2,667,807
Facility Condition Index:	0.18 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	8,564
Building Code:	H5580000071	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$7,031,807
Building Name:	Tunnel System	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$4,263,675
Facility Condition Index:	0.61 - Crisis	**City Code:**	ST. PETER	**Ext. Gross Area:**	46,854
Building Code:	H5580000072	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,375,495
Building Name:	Maintenance Shop	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$2,405,223
Facility Condition Index:	0.45 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	12,862
Building Code:	H5580000076	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$44,951
Building Name:	Pump House South	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$9,507
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	228
Building Code:	H5580000082	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,085,489
Building Name:	Root Cellar	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$456,236
Facility Condition Index:	0.42 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	5,532
Building Code:	H5580000090	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,376,737
Building Name:	Dairy Barn	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,405,850
Facility Condition Index:	0.42 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	15,119
Building Code:	H5580000098	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,224,018
Building Name:	Mechanics Garage	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$269,701
Facility Condition Index:	0.22 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	6,463

Building Code:	H5580000099	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$132,060,831
Building Name:	Minn. Security Hospital	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$20,833,890
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	331,082
Building Code:	H5580000101	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$322,950
Building Name:	Vehicle Storage Shed	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$22,063
Facility Condition Index:	0.07 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	2,400
Building Code:	H5580000103	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$131,789
Building Name:	Upper Access Point	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$13,951
Facility Condition Index:	0.11 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	64
Building Code:	H5580000104	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$133,903
Building Name:	Lower Access Point	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$31,872
Facility Condition Index:	0.24 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	64
Building Code:	H5580000105	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$144,643
Building Name:	Pexton Access Point	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$10,781
Facility Condition Index:	0.07 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	64
Building Code:	H5580000106	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$13,339,216
Building Name:	Forensic Nursing Home	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,331,535
Facility Condition Index:	0.10 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	36,349
Building Code:	H5580000107	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$4,211,813
Building Name:	Activity Building	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$384,047
Facility Condition Index:	0.09 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	11,200
Building Code:	H5580000108	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$22,610
Building Name:	Salt Storage	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$6,659
Facility Condition Index:	0.29 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	351
Building Code:	H5580000109	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$7,475,207
Building Name:	Forest View	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$352,422
Facility Condition Index:	0.05 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	25,007
Building Code:	H5580000110	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,958
Building Name:	J.H. South Storage Shed 1	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,131
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	148
Building Code:	H5580000111	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,153
Building Name:	J.H. North Storage Shed 2	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,175
Facility Condition Index:	0.19 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	99
Building Code:	H5580000112	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,606
Building Name:	F.V. South Storage Shed 1	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$152
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	99

Building Code:	H5580000113	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,606
Building Name:	F.V. North Storage Shed 2	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$152
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	99
Building Code:	H5580000114	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$38,691
Building Name:	Gluek Screen Gazebo	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$6,757
Facility Condition Index:	0.17 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	523
Building Code:	H5580000115	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,673
Building Name:	Gluek Storage Shed	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$9,070
Facility Condition Index:	0.38 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	331
Building Code:	H5580000116	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$76,180
Building Name:	Erickson Drive Access	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,524
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	135
Building Code:	H5580000117	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$160,420,450
Building Name:	PRAIRIE VIEW	**Address:**	100 FREEMAN DRIVE	**Deferred Maintenance:**	$3,208,409
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	26,170
Building Code:	H5580000118	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,482
Building Name:	Storage Shed MSOP	**Address:**	100 FREEMAN DRIVE	**Deferred Maintenance:**	$10,821
Facility Condition Index:	0.32 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	193
Building Code:	H5580000119	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,671
Building Name:	Green Acres Storage Shed	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$153
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	99
Building Code:	H5580000120	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$95,876
Building Name:	Sheppard Drive Lot Storage Shed	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$1,918
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	1,461
Building Code:	H5580000121	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,671
Building Name:	Prairie View South Storage Shed	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$153
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	99
Building Code:	H5580000122	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,671
Building Name:	Prairie View North Storage Shed	**Address:**	100 Freeman Drive	**Deferred Maintenance:**	$153
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	99
Building Code:	H5580000123	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,671
Building Name:	OUTER YARD REC SHED	**Address:**	100 FREEMAN DRIVE	**Deferred Maintenance:**	$153
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PETER	**Ext. Gross Area:**	99

Agency: H75 - Minnesota Veterans Affairs

FCI Rating:	Fair	**Current Replacement Value:**	$327,850,657	**Ext. Gross Area:**	1,254,186
Facility Condition Index:	0.18	**Deferred Maintenance:**	$57,809,831	**Building Count:**	66

Site: H75DUC - Duluth Cemetery

Building Code:	H75DUC00101	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$594,711
Building Name:	DUC Admin Bldg.	**Address:**	4777 HWY 53	**Deferred Maintenance:**	$11,894
Facility Condition Index:	0.02 - Excellent	**City Code:**	SAGINAW	**Ext. Gross Area:**	2,600
Building Code:	H75DUC00102	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,637,079
Building Name:	DUC Maintenance Bldg.	**Address:**	4777 HWY 53	**Deferred Maintenance:**	$32,742
Facility Condition Index:	0.02 - Excellent	**City Code:**	SAGINAW	**Ext. Gross Area:**	4,800
Building Code:	H75DUC00103	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$185,108
Building Name:	DUC Committal Bldg.	**Address:**	4777 HWY 53	**Deferred Maintenance:**	$3,702
Facility Condition Index:	0.02 - Excellent	**City Code:**	SAGINAW	**Ext. Gross Area:**	1,600

Site: H75FVH - Fergus Falls

Building Code:	H75FVH00001	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$30,675,725
Building Name:	Fergus Vets Home	**Address:**	1821 N. Park St.	**Deferred Maintenance:**	$3,685,715
Facility Condition Index:	0.12 - Good	**City Code:**	Fergus Falls	**Ext. Gross Area:**	127,684
Building Code:	H75FVH00102	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$976,075
Building Name:	FVH 102 Bldg. 2	**Address:**	1821 North Park St B2	**Deferred Maintenance:**	$742,193
Facility Condition Index:	0.76 - Crisis	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	5,797
Building Code:	H75FVH00103	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$561,624
Building Name:	FVH 103 Bldg. 3	**Address:**	1821 North Park St B3	**Deferred Maintenance:**	$47,992
Facility Condition Index:	0.09 - Good	**City Code:**	Fergus Falls	**Ext. Gross Area:**	4,000

Site: H75HVH - Hastings

Building Code:	H75HVH00018	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$31,237
Building Name:	Building 18 - Pavillion	**Address:**	1200 E. 18th St. B18	**Deferred Maintenance:**	$8,353
Facility Condition Index:	0.27 - Fair	**City Code:**	Hastings	**Ext. Gross Area:**	800
Building Code:	H75HVH00019	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$10,345,783
Building Name:	Building 19 - Water Tower	**Address:**	1200 East 18th Street B19	**Deferred Maintenance:**	$572,531
Facility Condition Index:	0.06 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	1,790
Building Code:	H75HVH10319	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$6,229,078
Building Name:	Building 20	**Address:**	1200 East 18th Street B20	**Deferred Maintenance:**	$771,327
Facility Condition Index:	0.12 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	26,276

Building Code:	H75HVH10819	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$3,363,335
Building Name:	Building 24	**Address:**	1200 East 18th Street B24	**Deferred Maintenance:**	$275,062
Facility Condition Index:	0.08 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	9,868
Building Code:	H75HVH11019	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$20,213,423
Building Name:	Building 23	**Address:**	1200 East 18th Street B23	**Deferred Maintenance:**	$5,238,103
Facility Condition Index:	0.26 - Fair	**City Code:**	Hastings	**Ext. Gross Area:**	99,348
Building Code:	H75HVH11319	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$36,864
Building Name:	Building 22 - Park Toilet	**Address:**	1200 E. 18th St B22	**Deferred Maintenance:**	$5,231
Facility Condition Index:	0.14 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	248
Building Code:	H75HVH11519	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$11,137
Building Name:	Building 35 - Tool Shed	**Address:**	1200 East 18th St B35	**Deferred Maintenance:**	$6,894
Facility Condition Index:	0.62 - Crisis	**City Code:**	Hastings	**Ext. Gross Area:**	241
Building Code:	H75HVH11619	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$4,535,793
Building Name:	Building 25	**Address:**	1200 East 18th Street B25	**Deferred Maintenance:**	$1,494,178
Facility Condition Index:	0.33 - Poor	**City Code:**	Hastings	**Ext. Gross Area:**	18,746
Building Code:	H75HVH11719	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,352,899
Building Name:	Building 33 - Garage	**Address:**	1200 East 18th Street B33	**Deferred Maintenance:**	$228,312
Facility Condition Index:	0.17 - Fair	**City Code:**	Hastings	**Ext. Gross Area:**	5,740
Building Code:	H75HVH12019	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$11,914,729
Building Name:	Building 30 - Power House	**Address:**	1200E. 18th St. B30	**Deferred Maintenance:**	$2,529,190
Facility Condition Index:	0.21 - Fair	**City Code:**	Hastings	**Ext. Gross Area:**	15,036
Building Code:	H75HVH12119	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$72,715
Building Name:	Screen House	**Address:**	1200 E. 18th St B SH	**Deferred Maintenance:**	$8,849
Facility Condition Index:	0.12 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	672
Building Code:	H75HVH12319	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$283,690
Building Name:	Building 36	**Address:**	1200 East 18th Street B36	**Deferred Maintenance:**	$18,000
Facility Condition Index:	0.06 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	3,213
Building Code:	H75HVH12419	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$112,661
Building Name:	Bldg 32 - #3 Well	**Address:**	1200 East 18th Street #3 Well	**Deferred Maintenance:**	$12,242
Facility Condition Index:	0.11 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	198
Building Code:	H75HVH12619	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$33,217
Building Name:	Building 28 -Tool Shed	**Address:**	1200 East 18th Street B28	**Deferred Maintenance:**	$16,418
Facility Condition Index:	0.49 - Poor	**City Code:**	Hastings	**Ext. Gross Area:**	572
Building Code:	H75HVH12719	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$933,918
Building Name:	Building 34	**Address:**	1200 East 18th Street B34	**Deferred Maintenance:**	$650,502
Facility Condition Index:	0.70 - Crisis	**City Code:**	HASTINGS	**Ext. Gross Area:**	8,044

Building Code:	H75HVH13019	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$4,117,169
Building Name:	Building 1 - Detox	**Address:**	1200 E. 18th St. B1	**Deferred Maintenance:**	$2,055,696
Facility Condition Index:	0.50 - Poor	**City Code:**	Hastings	**Ext. Gross Area:**	21,325
Building Code:	H75HVH13119	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$3,479,003
Building Name:	Building 2 - Detox	**Address:**	1200 E. 18th St B2	**Deferred Maintenance:**	$1,931,770
Facility Condition Index:	0.56 - Crisis	**City Code:**	Hastings	**Ext. Gross Area:**	19,067
Building Code:	H75HVH17A	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$1,039,174
Building Name:	Tunnel A	**Address:**	1200 E. 18th St.TA	**Deferred Maintenance:**	$58,767
Facility Condition Index:	0.06 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	3,600
Building Code:	H75HVH17B	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$302,824
Building Name:	Tunnel B	**Address:**	1200 E. 18th St. TB	**Deferred Maintenance:**	$10,035
Facility Condition Index:	0.03 - Excellent	**City Code:**	Hastings	**Ext. Gross Area:**	1,100
Building Code:	H75HVH17C1	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$432,989
Building Name:	Tunnel C1	**Address:**	1200 E. 18th St. TC1	**Deferred Maintenance:**	$49,312
Facility Condition Index:	0.11 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	1,500
Building Code:	H75HVH17C2	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$452,183
Building Name:	Tunnel C2	**Address:**	1200 E. 18th St. TC2	**Deferred Maintenance:**	$29,469
Facility Condition Index:	0.07 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	1,400
Building Code:	H75HVH17D	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$216,269
Building Name:	Tunnel D	**Address:**	1200 E. 18th St TD	**Deferred Maintenance:**	$12,722
Facility Condition Index:	0.06 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	710
Building Code:	H75HVH17E	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$1,861,172
Building Name:	Tunnel E	**Address:**	1200 E. 18th St. TE	**Deferred Maintenance:**	$519,542
Facility Condition Index:	0.28 - Fair	**City Code:**	Hastings	**Ext. Gross Area:**	6,040
Building Code:	H75HVH17F	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$517,828
Building Name:	Tunnel F	**Address:**	1200 E. 18th St, TF	**Deferred Maintenance:**	$30,462
Facility Condition Index:	0.06 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	1,700
Building Code:	H75HVH17G	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$274,144
Building Name:	Tunnel G	**Address:**	1200 E. 18th St. TG	**Deferred Maintenance:**	$17,978
Facility Condition Index:	0.07 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	900
Building Code:	H75HVH17H	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$97,473
Building Name:	Tunnel H	**Address:**	1200 E, 18th St. TH	**Deferred Maintenance:**	$35,291
Facility Condition Index:	0.36 - Poor	**City Code:**	Hastings	**Ext. Gross Area:**	320
Building Code:	H75HVH17J	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$484,794
Building Name:	Tunnel J	**Address:**	1200 E. 18th St. TJ	**Deferred Maintenance:**	$16,066
Facility Condition Index:	0.03 - Excellent	**City Code:**	Hastings	**Ext. Gross Area:**	1,761

Building Code:	H75HVH17K	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$141,777
Building Name:	Tunnel K	**Address:**	1200 E. 18th St. TK	**Deferred Maintenance:**	$4,698
Facility Condition Index:	0.03 - Excellent	**City Code:**	Hastings	**Ext. Gross Area:**	515
Building Code:	H75HVH17L	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$430,561
Building Name:	Tunnel L	**Address:**	1200 E. 18th St. TL	**Deferred Maintenance:**	$14,269
Facility Condition Index:	0.03 - Excellent	**City Code:**	Hastings	**Ext. Gross Area:**	1,564
Building Code:	H75HVH17N	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$131,369
Building Name:	Tunnel N	**Address:**	1200 E. 18th St. TN	**Deferred Maintenance:**	$7,867
Facility Condition Index:	0.06 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	443
Building Code:	H75HVHHUD	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$700,993
Building Name:	HUD House	**Address:**		**Deferred Maintenance:**	$70,436
Facility Condition Index:	0.10 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	2,415

Site: H75LFC - Little Falls

Building Code:	H75CEM00101	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$930,977
Building Name:	Admin Building	**Address:**	15550 Hwy 115	**Deferred Maintenance:**	$151,454
Facility Condition Index:	0.16 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	4,123
Building Code:	H75CEM00201	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,421,716
Building Name:	Maintenance building	**Address:**	15550 Hwy 115	**Deferred Maintenance:**	$255,069
Facility Condition Index:	0.18 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	6,910

Site: H75LVH - Luverne

Building Code:	H75LVH10167	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$19,393,754
Building Name:	Luverne Vets Home	**Address:**	1300 N. Kniss	**Deferred Maintenance:**	$3,987,055
Facility Condition Index:	0.21 - Fair	**City Code:**	Luverne	**Ext. Gross Area:**	68,226

Site: H75MVH - Minneapolis

Building Code:	H75MVH00127	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$3,063,031
Building Name:	MVH 001 Tunnels between 1,2,4,10, 1	**Address:**	5101 Minnehaha Ave S	**Deferred Maintenance:**	$760,030
Facility Condition Index:	0.25 - Fair	**City Code:**	Minneapolis	**Ext. Gross Area:**	10,000
Building Code:	H75MVH00227	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$1,041,710
Building Name:	MVH 002 Deep tunnel	**Address:**	5101 Minnehaha Ave S.	**Deferred Maintenance:**	$471,754
Facility Condition Index:	0.45 - Poor	**City Code:**	Minneapolis	**Ext. Gross Area:**	4,000
Building Code:	H75MVH10127	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$4,085,111
Building Name:	Building 4	**Address:**	5101 Minnehaha Ave S B4	**Deferred Maintenance:**	$473,368
Facility Condition Index:	0.12 - Good	**City Code:**	Minneapolis	**Ext. Gross Area:**	16,384

Building Code:	H75MVH10327	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,672,309
Building Name:	Building 18 - Warehouse	**Address:**	5101 Minnehaha Ave S B18	**Deferred Maintenance:**	$300,274
Facility Condition Index:	0.11 - Good	**City Code:**	Minneapolis	**Ext. Gross Area:**	15,537
Building Code:	H75MVH10527	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$10,323,325
Building Name:	Building 14-A	**Address:**	5101 Minnehaha Ave S B14-A	**Deferred Maintenance:**	$2,404,365
Facility Condition Index:	0.23 - Fair	**City Code:**	Minneapolis	**Ext. Gross Area:**	11,779
Building Code:	H75MVH10627	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,510,860
Building Name:	Building 2	**Address:**	5101 Minnehaha Ave S B2	**Deferred Maintenance:**	$1,449,231
Facility Condition Index:	0.32 - Poor	**City Code:**	Minneapolis	**Ext. Gross Area:**	16,894
Building Code:	H75MVH10727	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$17,933,009
Building Name:	Building 6	**Address:**	5101 Minnehaha Ave S B6	**Deferred Maintenance:**	$8,685,293
Facility Condition Index:	0.48 - Poor	**City Code:**	Minneapolis	**Ext. Gross Area:**	77,479
Building Code:	H75MVH10827	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$9,141,578
Building Name:	Building 16	**Address:**	5101 Minnehaha Ave S B16	**Deferred Maintenance:**	$1,191,862
Facility Condition Index:	0.13 - Good	**City Code:**	Minneapolis	**Ext. Gross Area:**	38,540
Building Code:	H75MVH11027	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,336,706
Building Name:	Building 15	**Address:**	5101 Minnehaha Ave S B15	**Deferred Maintenance:**	$792,472
Facility Condition Index:	0.18 - Fair	**City Code:**	Minneapolis	**Ext. Gross Area:**	17,468
Building Code:	H75MVH11127	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,280,908
Building Name:	Building 12A	**Address:**	5101 MInnehaha Ave S B12-A	**Deferred Maintenance:**	$538,378
Facility Condition Index:	0.42 - Poor	**City Code:**	Minneapolis	**Ext. Gross Area:**	5,400
Building Code:	H75MVH11227	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,818,379
Building Name:	Building 10	**Address:**	5101 Minnehaha Ave S B10	**Deferred Maintenance:**	$1,814,928
Facility Condition Index:	0.38 - Poor	**City Code:**	Minneapolis	**Ext. Gross Area:**	15,514
Building Code:	H75MVH11527	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,277,239
Building Name:	Building 13	**Address:**	5101 Minnehaha Ave S B13	**Deferred Maintenance:**	$895,479
Facility Condition Index:	0.70 - Crisis	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	5,484
Building Code:	H75MVH11827	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$3,605,262
Building Name:	Building 1	**Address:**	5101 Minnehaha Ave S B1	**Deferred Maintenance:**	$829,819
Facility Condition Index:	0.23 - Fair	**City Code:**	Minneapolis	**Ext. Gross Area:**	13,054
Building Code:	H75MVH11927	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$4,959,004
Building Name:	Building 14 - Powerhouse	**Address:**	5101 Minnehaha Ave S B14	**Deferred Maintenance:**	$425,712
Facility Condition Index:	0.09 - Good	**City Code:**	Minneapolis	**Ext. Gross Area:**	3,483
Building Code:	H75MVH12007	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$289,506
Building Name:	Building 12	**Address:**	5101 Minnehaha Ave S B12	**Deferred Maintenance:**	$242,834
Facility Condition Index:	0.84 - Crisis	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	1,788

Building Code:	H75MVH19001	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$29,749,137
Building Name:	Building 19	**Address:**	5101 Minnehaha Ave S B19	**Deferred Maintenance:**	$1,874,520
Facility Condition Index:	0.06 - Good	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	118,972
Building Code:	H75MVH20001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,412,552
Building Name:	Building 20	**Address:**	5101 Minnehaha Ave S B20	**Deferred Maintenance:**	$28,251
Facility Condition Index:	0.02 - Excellent	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	1,600
Building Code:	H75MVH21001	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$43,220,844
Building Name:	Building 21	**Address:**	5101 MInnehaha Ave S	**Deferred Maintenance:**	$1,884,506
Facility Condition Index:	0.04 - Excellent	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	109,814
Building Code:	H75MVH22001	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$26,051,848
Building Name:	Building 22	**Address:**	5101 Minnehaha Ave South	**Deferred Maintenance:**	$521,037
Facility Condition Index:	0.02 - Excellent	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	175,366

Site: H75PRC - Preston

Building Code:	H75PRC00101	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$654,095
Building Name:	Administration Bldg	**Address:**	715 HWY 52	**Deferred Maintenance:**	$31,531
Facility Condition Index:	0.05 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	2,293
Building Code:	H75PRC00102	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$983,099
Building Name:	Maintenance Bldg	**Address:**	715 HWY 52	**Deferred Maintenance:**	$19,662
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	4,025
Building Code:	H75PRC00103	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$247,834
Building Name:	Committal Shelter	**Address:**	715 HWY 52	**Deferred Maintenance:**	$4,957
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	1,003
Building Code:	H75PRC00104	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$52,740
Building Name:	Irrigation Pump House	**Address:**	715 HWY 52	**Deferred Maintenance:**	$1,055
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	120

Site: H75SVH - Silver Bay

Building Code:	H75SVH00001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$885,564
Building Name:	Storage Shop	**Address:**	45 Banks BLVD	**Deferred Maintenance:**	$55,739
Facility Condition Index:	0.06 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	4,800
Building Code:	H75SVH00002	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$7,372
Building Name:	Gazebo	**Address:**	45 Banks Blvd	**Deferred Maintenance:**	$147
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	600

Building Code:	H75SVH10139	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$20,720,664
Building Name:	Silver Bay Vets Home	**Address:**	45 Banks Blvd.	**Deferred Maintenance:**	$6,495,235
Facility Condition Index:	0.31 - Poor	**City Code:**	Silver Bay	**Ext. Gross Area:**	101,895

Agency: P01 - Military Affairs

FCI Rating:	Fair	**Current Replacement Value:**	$634,076,999	**Ext. Gross Area:**	2,587,697
Facility Condition Index:	0.22	**Deferred Maintenance:**	$140,942,433	**Building Count:**	67

Site: P01146 - FARIBAULT AFRC

Building Code:	P0114620002	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$21,237,106
Building Name:	Faribault TACC	**Address:**	3000 West Airport Drive	**Deferred Maintenance:**	$1,906,798
Facility Condition Index:	0.09 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	64,482
Building Code:	P0114620061	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$81,922
Building Name:	Unheated Storage Building	**Address:**	3000 WEST AIRPORT DR	**Deferred Maintenance:**	$8,192
Facility Condition Index:	0.10 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	720

Site: P01670 - AHATS

Building Code:	P0167001002	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$9,276,473
Building Name:	AHATS Hamiline Ave RC	**Address:**	4761 HAMLINE AVE N	**Deferred Maintenance:**	$977,683
Facility Condition Index:	0.11 - Good	**City Code:**	Arden Hills	**Ext. Gross Area:**	60,413
Building Code:	P0167001003	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$11,444,557
Building Name:	Ben Franklin Readiness Center	**Address:**	1536 BEN FRANKLIN DR	**Deferred Maintenance:**	$399,300
Facility Condition Index:	0.03 - Excellent	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	62,560

Site: P01774 - Stillwater RC

Building Code:	P0177411002	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$24,994,849
Building Name:	Stillwater Readiness Center	**Address:**	250 Maryknoll Dr N	**Deferred Maintenance:**	$499,897
Facility Condition Index:	0.02 - Excellent	**City Code:**	STILLWATER	**Ext. Gross Area:**	80,650

Site: P01818 - CAMBRIDGE RC

Building Code:	P0181816001	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$19,019,088
Building Name:	Cambridge Armory	**Address:**	505 SPIRIT RIVER DRVE S.	**Deferred Maintenance:**	$1,832,452
Facility Condition Index:	0.10 - Good	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	57,062

Site: P01A10 - ALBERT LEA

Building Code:	P01A1023001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$10,490,747
Building Name:	Albert Lea TACC and MVSB	**Address:**	410 Prospect Ave	**Deferred Maintenance:**	$2,591,530
Facility Condition Index:	0.25 - Fair	**City Code:**	Albert Lea	**Ext. Gross Area:**	28,791

Site: P01A15 - ALEXANDRIA

Building Code: P01A1502001
Building Name: Alexandria TACC
Facility Condition Index: 0.23 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 310 Broadway
City Code: Alexandria

Current Replacement Value: $6,101,864
Deferred Maintenance: $1,423,953
Ext. Gross Area: 28,151

Site: P01A20 - ANOKA

Building Code: P01A2001001
Building Name: Anoka TACC
Facility Condition Index: 0.37 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 408 E Main St
City Code: Anoka

Current Replacement Value: $4,764,519
Deferred Maintenance: $1,786,290
Ext. Gross Area: 16,419

Site: P01A25 - APPLETON

Building Code: P01A2502001
Building Name: Appleton NG TACC
Facility Condition Index: 0.32 - Poor

Cost Model Name: Low-rise Office Building, 2 to 4 story
Address: 25 N Munsterman St
City Code: Appleton

Current Replacement Value: $7,521,203
Deferred Maintenance: $2,371,521
Ext. Gross Area: 29,292

Site: P01A35 - AUSTIN

Building Code: P01A3525001
Building Name: Austin Armory
Facility Condition Index: 0.23 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 800 21st St NE
City Code: Austin

Current Replacement Value: $6,078,186
Deferred Maintenance: $1,378,193
Ext. Gross Area: 21,878

Site: P01A40 - BEMIDJI

Building Code: P01A4003001
Building Name: Bemidji TACC
Facility Condition Index: 0.18 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 1430 23rd St NW
City Code: Bemidji

Current Replacement Value: $5,549,641
Deferred Maintenance: $978,293
Ext. Gross Area: 21,006

Site: P01A47 - BLOOMINGTON

Building Code: P01A4707001
Building Name: Bloomington TACC
Facility Condition Index: 0.29 - Fair

Cost Model Name: Single-story Office/Public Access Facility
Address: 330 W 98th Street
City Code: Bloomington

Current Replacement Value: $10,249,880
Deferred Maintenance: $3,023,136
Ext. Gross Area: 41,731

Site: P01A50 - BRAINERD

Building Code: P01A5001001
Building Name: Brainerd TACC
Facility Condition Index: 0.35 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 1115 Wright Street
City Code: Brainerd

Current Replacement Value: $9,078,206
Deferred Maintenance: $3,135,868
Ext. Gross Area: 38,569

Site: P01A53 - BROOKLYN PARK

Building Code:	P01A5302001	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$10,279,599
Building Name:	Brooklyn Park TACC	**Address:**	5500 85th Ave N	**Deferred Maintenance:**	$1,392,258
Facility Condition Index:	0.14 - Good	**City Code:**	Brooklyn Park	**Ext. Gross Area:**	29,499

Site: P01A55 - CHISHOLM

Building Code:	P01A5504001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,796,457
Building Name:	Chisholm TACC	**Address:**	900 W Lake St	**Deferred Maintenance:**	$1,201,916
Facility Condition Index:	0.21 - Fair	**City Code:**	Chisholm	**Ext. Gross Area:**	18,166

Site: P01A60 - CLOQUET

Building Code:	P01A6011001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,281,291
Building Name:	Cloquet TACC	**Address:**	801 Hwy 33 South	**Deferred Maintenance:**	$1,481,861
Facility Condition Index:	0.24 - Fair	**City Code:**	Cloquet TACC	**Ext. Gross Area:**	27,244

Site: P01A63 - COTTAGE GROVE

Building Code:	P01A6309001	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$10,705,502
Building Name:	Cottage Grove TACC	**Address:**	8180 Belden Blvd S	**Deferred Maintenance:**	$4,805,486
Facility Condition Index:	0.45 - Poor	**City Code:**	Cottage Grove	**Ext. Gross Area:**	54,428

Site: P01A65 - CROOKSTON

Building Code:	P01A6502001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$7,210,342
Building Name:	Crookston	**Address:**	1801 University Av N	**Deferred Maintenance:**	$1,930,873
Facility Condition Index:	0.27 - Fair	**City Code:**	Crookston	**Ext. Gross Area:**	21,484

Site: P01A75 - DETROIT LAKES

Building Code:	P01A7507001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,992,503
Building Name:	Detroit Lakes TACC	**Address:**	1220 Rossman Ave	**Deferred Maintenance:**	$651,805
Facility Condition Index:	0.13 - Good	**City Code:**	Detroit Lakes	**Ext. Gross Area:**	16,201

Site: P01A85 - DULUTH

Building Code:	P01A8510001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$14,072,642
Building Name:	Duluth TACC	**Address:**	4015 Airpark Blvd	**Deferred Maintenance:**	$3,599,721
Facility Condition Index:	0.26 - Fair	**City Code:**	Duluth	**Ext. Gross Area:**	42,470

Site: P01A95 - FAIRMONT

Building Code:	P01A9522001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,631,938
Building Name:	Fairmont TACC	**Address:**	700 Fairlakes Ave	**Deferred Maintenance:**	$938,781
Facility Condition Index:	0.14 - Good	**City Code:**	Fairmont	**Ext. Gross Area:**	18,948

Site: P01B05 - FERGUS FALLS

Building Code:	P01B0508001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,051,815
Building Name:	Fergus Falls TACC	**Address:**	321 E Cecil Street	**Deferred Maintenance:**	$2,501,144
Facility Condition Index:	0.41 - Poor	**City Code:**	Fergus Falls	**Ext. Gross Area:**	19,925

Site: P01B10 - GRAND RAPIDS

Building Code:	P01B1013001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,304,214
Building Name:	Grand Rapids TACC	**Address:**	930 NE 1st Ave	**Deferred Maintenance:**	$2,526,088
Facility Condition Index:	0.40 - Poor	**City Code:**	Grand Rapids	**Ext. Gross Area:**	20,730

Site: P01B15 - HASTINGS ARMORY

Building Code:	P01B1510001	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,781,665
Building Name:	Hastings TACC	**Address:**	3050 Hwy 316 S	**Deferred Maintenance:**	$410,780
Facility Condition Index:	0.09 - Good	**City Code:**	Hastings	**Ext. Gross Area:**	18,451

Site: P01B20 - HIBBING ARMORY AND FMS

Building Code:	P01B2005001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,804,608
Building Name:	Hibbing TACC	**Address:**	2310 Brooklyn Drive	**Deferred Maintenance:**	$1,901,082
Facility Condition Index:	0.28 - Fair	**City Code:**	Hibbing	**Ext. Gross Area:**	29,352

Site: P01B25 - HUTCHINSON ARMORY

Building Code:	P01B2510001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,360,563
Building Name:	Hutchinson TACC	**Address:**	1200 Hwy 22 S	**Deferred Maintenance:**	$853,916
Facility Condition Index:	0.16 - Fair	**City Code:**	Hutchinson	**Ext. Gross Area:**	17,823

Site: P01B27 - INVER GOVE HEIGHT ARMORY

Building Code:	P01B2714001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$11,611,219
Building Name:	Inver Grove Hts TACC	**Address:**	8076 Babcock Trail	**Deferred Maintenance:**	$3,011,600
Facility Condition Index:	0.26 - Fair	**City Code:**	Inver Grove Heig	**Ext. Gross Area:**	42,392

Site: P01B30 - JACKSON ARMORY

Building Code: P01B3014001
Building Name: Jackson TACC
Facility Condition Index: 0.14 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 108 Cty Road 51
City Code: Jackson

Current Replacement Value: $6,624,843
Deferred Maintenance: $936,874
Ext. Gross Area: 18,893

Site: P01B35 - LITCHFIELD ARMORY

Building Code: P01B3509001
Building Name: Litchfield TACC
Facility Condition Index: 0.13 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 525 Gillman Ave N
City Code: Litchfield

Current Replacement Value: $4,502,688
Deferred Maintenance: $599,497
Ext. Gross Area: 14,891

Site: P01B40 - CAMP RIPLEY TRAINING SITE

Building Code: P01B4002002
Building Name: Old School House
Facility Condition Index: 0.35 - Poor

Cost Model Name: Low-rise Office Building, 2 to 4 story
Address: 15000 Hwy 115
City Code: Little Falls

Current Replacement Value: $414,941
Deferred Maintenance: $144,519
Ext. Gross Area: 2,256

Building Code: P01B4006078
Building Name: EMTC
Facility Condition Index: 0.08 - Good

Cost Model Name: Single-story Educational Facility
Address: 15000 Hwy 115
City Code: Little Falls

Current Replacement Value: $4,108,415
Deferred Maintenance: $319,661
Ext. Gross Area: 22,306

Building Code: P01B4011001
Building Name: Camp Ripley Armory
Facility Condition Index: 0.34 - Poor

Cost Model Name: Single-story Educational Facility
Address: 15000 Hwy 115
City Code: Little Falls

Current Replacement Value: $16,039,190
Deferred Maintenance: $5,470,378
Ext. Gross Area: 98,722

Site: P01B50 - LUVERNE ARMORY

Building Code: P01B5013001
Building Name: Luverne TACC
Facility Condition Index: 0.36 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 309 S Freeman Ave
City Code: Luverne

Current Replacement Value: $6,243,925
Deferred Maintenance: $2,251,475
Ext. Gross Area: 29,172

Site: P01B55 - MADISON ARMORY

Building Code: P01B5503001
Building Name: Madison TACC
Facility Condition Index: 0.30 - Poor

Cost Model Name: Low-rise Office Building, 2 to 4 story
Address: 504 3rd Street
City Code: Madison

Current Replacement Value: $7,931,858
Deferred Maintenance: $2,394,975
Ext. Gross Area: 37,384

Site: P01B60 - MANKATO ARMORY

Building Code: P01B6021002
Building Name: Mankato Armory
Facility Condition Index: 0.17 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 100 Martin Luther King Jr Dr.
City Code: Mankato

Current Replacement Value: $17,040,562
Deferred Maintenance: $2,893,287
Ext. Gross Area: 46,449

Site: P01B65 - MARSHAL ARMORY

Building Code:	P01B6508001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,323,382
Building Name:	Marshall TACC	**Address:**	500 Artillery Drive	**Deferred Maintenance:**	$1,715,329
Facility Condition Index:	0.32 - Poor	**City Code:**	Marshall	**Ext. Gross Area:**	16,833

Site: P01B75 - MINNEAPOLIS ARMORY

Building Code:	P01B7503001	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$5,998,022
Building Name:	Minneapolis TACC	**Address:**	1025 Broadway St NE	**Deferred Maintenance:**	$1,260,453
Facility Condition Index:	0.21 - Fair	**City Code:**	Minneapolis	**Ext. Gross Area:**	36,074

Site: P01B80 - MONTEVIDEO ARMORY

Building Code:	P01B8004001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$11,784,004
Building Name:	Montevideo TACC	**Address:**	711 S 17th Street	**Deferred Maintenance:**	$2,752,096
Facility Condition Index:	0.23 - Fair	**City Code:**	Montevideo	**Ext. Gross Area:**	38,667

Site: P01B82 - MONTICELLO

Building Code:	P01B8207001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,245,541
Building Name:	Monticello TACC	**Address:**	505 Walnut St	**Deferred Maintenance:**	$190,985
Facility Condition Index:	0.15 - Fair	**City Code:**	Monticello	**Ext. Gross Area:**	31,085

Site: P01B85 - MOORHEAD ARMORY

Building Code:	P01B8506001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$9,462,559
Building Name:	Moorhead TACC	**Address:**	1002 15th Ave N	**Deferred Maintenance:**	$4,072,168
Facility Condition Index:	0.43 - Poor	**City Code:**	Moorhead	**Ext. Gross Area:**	52,763

Site: P01B90 - MORRIS ARMORY

Building Code:	P01B9005001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,541,544
Building Name:	Morris TACC	**Address:**	810 Iowa Ave	**Deferred Maintenance:**	$1,130,764
Facility Condition Index:	0.17 - Fair	**City Code:**	Morris	**Ext. Gross Area:**	28,265

Site: P01C00 - NEW ULM ARMORY

Building Code:	P01C0016001	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$8,149,335
Building Name:	New Ulm TACC	**Address:**	205 N Broadway	**Deferred Maintenance:**	$3,281,750
Facility Condition Index:	0.40 - Poor	**City Code:**	New Ulm	**Ext. Gross Area:**	32,514

Site: P01C15 - OLIVIA ARMORY

Building Code:	P01C1505001	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$5,980,476
Building Name:	Olivia TACC	**Address:**	910 W Lincoln	**Deferred Maintenance:**	$1,961,652
Facility Condition Index:	0.33 - Poor	**City Code:**	Olivia	**Ext. Gross Area:**	29,630

Site: P01C25 - ORTONVILLE ARMORY

Building Code:	P01C2501001	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$9,167,262
Building Name:	Ortonville TACC	**Address:**	309 Madison Ave	**Deferred Maintenance:**	$2,625,123
Facility Condition Index:	0.29 - Fair	**City Code:**	Ortonville	**Ext. Gross Area:**	28,837

Site: P01C30 - OWATONNA ARMORY

Building Code:	P01C3024001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,580,105
Building Name:	Owatonna TACC	**Address:**	2323 Bridge Street W	**Deferred Maintenance:**	$1,010,406
Facility Condition Index:	0.18 - Fair	**City Code:**	Owatonna	**Ext. Gross Area:**	18,939

Site: P01C40 - PINE CITY ARMORY

Building Code:	P01C4012001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,806,560
Building Name:	Pine City TACC	**Address:**	1305 Main Street S	**Deferred Maintenance:**	$618,974
Facility Condition Index:	0.13 - Good	**City Code:**	Pine City	**Ext. Gross Area:**	15,488

Site: P01C45 - PIPESTONE ARMORY

Building Code:	P01C4512001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,153,034
Building Name:	Pipestone TACC	**Address:**	421 2nd Ave SW	**Deferred Maintenance:**	$1,003,752
Facility Condition Index:	0.24 - Fair	**City Code:**	Pipestone	**Ext. Gross Area:**	15,091

Site: P01C55 - RED WING ARMORY

Building Code:	P01C5519001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,987,988
Building Name:	Red Wing TACC	**Address:**	855 E 7th Street	**Deferred Maintenance:**	$644,777
Facility Condition Index:	0.11 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	18,527

Site: P01C60 - REDWOOD FALLS ARMORY

Building Code:	P01C6011001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,426,888
Building Name:	Redwood Falls TACC	**Address:**	530 Hwy 101 N	**Deferred Maintenance:**	$571,290
Facility Condition Index:	0.13 - Good	**City Code:**	Redwood Falls	**Ext. Gross Area:**	18,730

Site: P01C65 - ROCHESTER RC and FMS

Building Code:	P01C6526001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$10,464,080
Building Name:	Rochester TACC	**Address:**	1715 Marion Road	**Deferred Maintenance:**	$1,354,363
Facility Condition Index:	0.13 - Good	**City Code:**	ROCHESTER	**Ext. Gross Area:**	34,180

Building Code:	P01C6526155	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$788,990
Building Name:	OMS #2	**Address:**	1715 Marion Road	**Deferred Maintenance:**	$187,751
Facility Condition Index:	0.24 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	3,283

Site: P01C67 - ROSEMOUNT ARMORY

Building Code:	P01C6708001	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$44,084,901
Building Name:	Rosemount TACC	**Address:**	13865 S Robert Trail	**Deferred Maintenance:**	$16,258,241
Facility Condition Index:	0.37 - Poor	**City Code:**	Rosemount	**Ext. Gross Area:**	171,262

Site: P01C70 - ROSEVILLE ARMORY

Building Code:	P01C7006001	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$23,592,097
Building Name:	Roseville TACC	**Address:**	211 N McCarrons Blvd	**Deferred Maintenance:**	$9,661,397
Facility Condition Index:	0.41 - Poor	**City Code:**	Roseville	**Ext. Gross Area:**	53,966

Site: P01C74 - St Cloud AASF

Building Code:	P01C7406155	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$36,777,825
Building Name:	St Cloud AASF	**Address:**	2185 45TH AVE SE	**Deferred Maintenance:**	$1,921,897
Facility Condition Index:	0.05 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	246,492

Site: P01C75 - ST CLOUD RC

Building Code:	P01C7506001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$9,165,662
Building Name:	St Cloud TACC	**Address:**	1710 VETERANS DR	**Deferred Maintenance:**	$4,017,302
Facility Condition Index:	0.44 - Poor	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	54,257

Site: P01C80 - ST JAMES ARMORY AND MVSB

Building Code:	P01C8015001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,064,583
Building Name:	St James TACC	**Address:**	521 ARMSTRONG BLVD N	**Deferred Maintenance:**	$636,550
Facility Condition Index:	0.13 - Good	**City Code:**	ST. JAMES	**Ext. Gross Area:**	16,176

Site: P01C90 - ST PAUL CEDAR ST ARMORY

Building Code:	P01C9004002	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$35,397,125
Building Name:	Cedar Street TACC	**Address:**	600 CEDAR ST	**Deferred Maintenance:**	$2,057,310
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	124,567

Site: P01C95 - ST PAUL AASF

Building Code:	P01C9504003	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$23,553,768
Building Name:	AASF And TACC	**Address:**	206 AIRPORT RD	**Deferred Maintenance:**	$7,467,966
Facility Condition Index:	0.32 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	143,250

Site: P01D00 - ST PAUL EAST ARMORY

Building Code:	P01D0004001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,682,117
Building Name:	East St Paul TACC	**Address:**	1530 E MARYLAND AVE	**Deferred Maintenance:**	$938,059
Facility Condition Index:	0.17 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	19,936

Site: P01D05 - WEST ST PAUL ARMORY

Building Code:	P01D0505001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,150,002
Building Name:	W. St Paul TACC	**Address:**	1346 S ROBERT ST	**Deferred Maintenance:**	$2,329,706
Facility Condition Index:	0.45 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	18,148

Site: P01D10 - ST PETER ARMORY

Building Code:	P01D1017001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,085,288
Building Name:	St Peter TACC	**Address:**	1120 N SWIFT ST	**Deferred Maintenance:**	$1,655,600
Facility Condition Index:	0.41 - Poor	**City Code:**	ST. PETER	**Ext. Gross Area:**	16,891

Site: P01D15 - SAUK CENTRE ARMORY

Building Code:	P01D1504001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,496,918
Building Name:	Sauk Centre TACC	**Address:**	628 3rd Street	**Deferred Maintenance:**	$1,154,479
Facility Condition Index:	0.21 - Fair	**City Code:**	Sauk Centre	**Ext. Gross Area:**	27,221

Site: P01D25 - THIEF RIVER FALLS ARMORY

Building Code:	P01D2501001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,344,071
Building Name:	Thief River Falls TACC	**Address:**	250 Emil St.	**Deferred Maintenance:**	$767,998
Facility Condition Index:	0.14 - Good	**City Code:**	Thief River Fall	**Ext. Gross Area:**	15,117

Site: P01D45 - WADENA ARMORY

Building Code:	P01D4509001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,071,532
Building Name:	Wadena TACC	**Address:**	517 N Jefferson	**Deferred Maintenance:**	$1,908,411
Facility Condition Index:	0.31 - Poor	**City Code:**	Wadena	**Ext. Gross Area:**	19,808

Site: P01D60 - WILLMAR ARMORY AND FMS

Building Code:	P01D6007001	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$3,091,883
Building Name:	Willmar TACC	**Address:**	614 Hwy 71 N	**Deferred Maintenance:**	$313,092
Facility Condition Index:	0.10 - Good	**City Code:**	Willmar	**Ext. Gross Area:**	24,902

Site: P01D70 - WINONA ARMORY

Building Code:	P01D7027001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,980,437
Building Name:	Winona TACC	**Address:**	1303 Homer Road	**Deferred Maintenance:**	$941,710
Facility Condition Index:	0.16 - Fair	**City Code:**	Winona	**Ext. Gross Area:**	17,889

Agency: P07 - Public Safety

FCI Rating:	Fair	**Current Replacement Value:**	$4,816,224	**Ext. Gross Area:**	20,360
Facility Condition Index:	0.20	**Deferred Maintenance:**	$985,284	**Building Count:**	6

Site: P07100 - Arden Hills Driver Exam Site

Building Code:	P0710000001	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$1,672,460
Building Name:	ARDEN HILLS - DRIVERS LICENSE	**Address:**	5400 Old Hwy 8	**Deferred Maintenance:**	$268,462
Facility Condition Index:	0.16 - Fair	**City Code:**	Arden Hills	**Ext. Gross Area:**	7,785
Building Code:	P0710000002	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$62,230
Building Name:	ARDEN HILLS - MISC STORAGE	**Address:**	5400 Old Hwy 8	**Deferred Maintenance:**	$6,306
Facility Condition Index:	0.10 - Good	**City Code:**	Arden Hills	**Ext. Gross Area:**	639
Building Code:	P0710000003	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,595
Building Name:	ARDEN HILL - MISC STORAGE #2	**Address:**	5400 Old Hwy 8	**Deferred Maintenance:**	$1,786
Facility Condition Index:	0.13 - Good	**City Code:**	Arden Hills	**Ext. Gross Area:**	150

Site: P07200 - Eagan Driver Exam Site

Building Code:	P0720000001	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$2,991,851
Building Name:	EAGAN - DRIVERS LICENSE	**Address:**	2070 Cliff Road	**Deferred Maintenance:**	$698,598
Facility Condition Index:	0.23 - Fair	**City Code:**	Eagan	**Ext. Gross Area:**	10,998
Building Code:	P0720000002	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$60,397
Building Name:	EAGAN - MISC STORAGE	**Address:**	2070 Cliff Road	**Deferred Maintenance:**	$6,613
Facility Condition Index:	0.11 - Good	**City Code:**	Eagan	**Ext. Gross Area:**	638
Building Code:	P0720000003	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,692
Building Name:	EAGAN - MISC STORAGE #2	**Address:**	2070 Cliff Road	**Deferred Maintenance:**	$3,518
Facility Condition Index:	0.22 - Fair	**City Code:**	Eagan	**Ext. Gross Area:**	150

Agency: P78 - Department of Corrections

FCI Rating:	Fair	**Current Replacement Value:**	$2,665,141,983	**Ext. Gross Area:**	7,470,951
Facility Condition Index:	0.22	**Deferred Maintenance:**	$594,971,613	**Building Count:**	325

Site: P78103 - Moose Lake

Building Code:	P7810300001	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$11,072,525
Building Name:	Unit 1	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$3,361,145
Facility Condition Index:	0.30 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	28,892
Building Code:	P7810300002	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$9,145,028
Building Name:	Unit 2	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$2,519,645
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	28,847
Building Code:	P7810300003	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$11,189,717
Building Name:	Unit 3	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$3,292,928
Facility Condition Index:	0.29 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	28,847
Building Code:	P7810300004	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$13,792,619
Building Name:	Unit 4 Segregation/OSI	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$4,353,369
Facility Condition Index:	0.32 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	28,895
Building Code:	P7810300005	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$89,116
Building Name:	Storage Building D	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$63,209
Facility Condition Index:	0.71 - Crisis	**City Code:**	Moose Lake	**Ext. Gross Area:**	1,006
Building Code:	P7810300006	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$86,721
Building Name:	Pump House #1	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$19,792
Facility Condition Index:	0.23 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	302
Building Code:	P7810300007	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$149,984
Building Name:	Storage Building A	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$109,334
Facility Condition Index:	0.73 - Crisis	**City Code:**	Moose Lake	**Ext. Gross Area:**	1,708
Building Code:	P7810300008	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$14,254,278
Building Name:	Unit 8	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$4,255,880
Facility Condition Index:	0.30 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	34,704
Building Code:	P7810300009	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$22,489
Building Name:	Storage Building B	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$6,327
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	288
Building Code:	P781030000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$14,632,802
Building Name:	Perimeter Fence	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$4,828,825
Facility Condition Index:	0.33 - Poor	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	131,160

Building Code:	P7810300010	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$14,256,342
Building Name:	Unit 10 - ANNEX	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$3,969,513
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	34,714
Building Code:	P7810300011	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,765
Building Name:	Pump House #2	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$1,392
Facility Condition Index:	0.12 - Good	**City Code:**	Moose Lake	**Ext. Gross Area:**	48
Building Code:	P7810300012	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$185,798
Building Name:	Storage Building E	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$149,646
Facility Condition Index:	0.81 - Crisis	**City Code:**	Moose Lake	**Ext. Gross Area:**	1,564
Building Code:	P7810300015	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,162
Building Name:	Storage Building C	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$13,345
Facility Condition Index:	0.46 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	384
Building Code:	P7810300035	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$6,176,345
Building Name:	Unit 35	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$2,002,490
Facility Condition Index:	0.32 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	18,492
Building Code:	P7810300050	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$10,442,086
Building Name:	Bldg 50 Area H	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$2,220,274
Facility Condition Index:	0.21 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	33,494
Building Code:	P7810300051	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$13,076,626
Building Name:	Bldg 50 L Wing W Visit	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$3,699,991
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	37,822
Building Code:	P7810300052	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$12,585,034
Building Name:	Bldg 50 K Wing E HS	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$3,570,005
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	37,576
Building Code:	P7810300053	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$16,014,574
Building Name:	Bldg 50 J "S" Wing	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$4,992,829
Facility Condition Index:	0.31 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	41,449
Building Code:	P7810300054	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$15,013,317
Building Name:	Area M - Building 54, 56	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$4,198,784
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	29,674
Building Code:	P7810300060	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$5,372,430
Building Name:	Bldg 60	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$1,526,432
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	13,677
Building Code:	P7810300064	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$13,355,551
Building Name:	Bldg 64	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$4,341,279
Facility Condition Index:	0.33 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	20,742

Building Code:	P7810300065	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$6,843,833
Building Name:	Bldg 65	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$1,806,774
Facility Condition Index:	0.26 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	18,715
Building Code:	P7810300070	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,558,377
Building Name:	Power Plant	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$1,467,423
Facility Condition Index:	0.22 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	27,581
Building Code:	P7810300074	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,810,235
Building Name:	Maintenance	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$339,797
Facility Condition Index:	0.19 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	7,922
Building Code:	P7810300080	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$21,503,878
Building Name:	Industry	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$3,787,322
Facility Condition Index:	0.18 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	72,955
Building Code:	P7810300082	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$95,888
Building Name:	Truck Gate	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$26,374
Facility Condition Index:	0.28 - Fair	**City Code:**	Moose Lake	**Ext. Gross Area:**	430
Building Code:	P7810300083	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$6,722,027
Building Name:	Gymnasium	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$816,799
Facility Condition Index:	0.12 - Good	**City Code:**	Moose Lake	**Ext. Gross Area:**	16,218
Building Code:	P7810300084	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$863,429
Building Name:	Bldg 84	**Address:**	1000 Lake Shore Drive	**Deferred Maintenance:**	$101,519
Facility Condition Index:	0.12 - Good	**City Code:**	Moose Lake	**Ext. Gross Area:**	3,600
Building Code:	P7810300085	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$541,368
Building Name:	Silo	**Address:**	100 Lake Shore Drive	**Deferred Maintenance:**	$178,651
Facility Condition Index:	0.33 - Poor	**City Code:**	Moose Lake	**Ext. Gross Area:**	3,696

Site: P78114 - Rush City

Building Code:	P7811400001	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$14,786,514
Building Name:	Admin	**Address:**	7600 525th Street	**Deferred Maintenance:**	$2,289,997
Facility Condition Index:	0.15 - Fair	**City Code:**	Rush City	**Ext. Gross Area:**	54,710
Building Code:	P7811400002	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$97,941,983
Building Name:	Support	**Address:**	7600 525th Street	**Deferred Maintenance:**	$13,016,018
Facility Condition Index:	0.13 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	192,755
Building Code:	P7811400003	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$16,902,487
Building Name:	Complex 1	**Address:**	7600 525th Street	**Deferred Maintenance:**	$2,393,742
Facility Condition Index:	0.14 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	47,497

Building Code:	P7811400004	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$16,640,965
Building Name:	Complex 3	**Address:**	7600 525th Street	**Deferred Maintenance:**	$1,552,400
Facility Condition Index:	0.09 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	46,734
Building Code:	P7811400007	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$17,094,783
Building Name:	Complex 4	**Address:**	7600 525th Street	**Deferred Maintenance:**	$1,704,186
Facility Condition Index:	0.10 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	46,733
Building Code:	P7811400008	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$16,876,132
Building Name:	Complex 2	**Address:**	7600 525th Street	**Deferred Maintenance:**	$1,672,010
Facility Condition Index:	0.10 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	47,497
Building Code:	P7811400009	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,637,704
Building Name:	Generator Bldg	**Address:**	7600 525th Street	**Deferred Maintenance:**	$232,626
Facility Condition Index:	0.09 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	2,360
Building Code:	P781140000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$11,521,433
Building Name:	Perimeter Fence	**Address:**	7600 - 525th Street	**Deferred Maintenance:**	$1,152,143
Facility Condition Index:	0.10 - Good	**City Code:**	RUSH CITY	**Ext. Gross Area:**	119,052
Building Code:	P7811400010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$81,144
Building Name:	Greenhouse 1	**Address:**	7600 525th Street	**Deferred Maintenance:**	$31,963
Facility Condition Index:	0.39 - Poor	**City Code:**	RUSH CITY	**Ext. Gross Area:**	1,040
Building Code:	P7811400011	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$77,192
Building Name:	Greenhouse 2	**Address:**	7600 525th Street	**Deferred Maintenance:**	$33,297
Facility Condition Index:	0.43 - Poor	**City Code:**	RUSH CITY	**Ext. Gross Area:**	1,040
Building Code:	P7811400020	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$426,225
Building Name:	Program Building	**Address:**	7600 525th Street	**Deferred Maintenance:**	$100,522
Facility Condition Index:	0.24 - Fair	**City Code:**	Rush City	**Ext. Gross Area:**	2,532
Building Code:	P7811400028	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$65,349
Building Name:	Garage	**Address:**	7600 525th Street	**Deferred Maintenance:**	$18,636
Facility Condition Index:	0.29 - Fair	**City Code:**	Rush City	**Ext. Gross Area:**	720
Building Code:	P7811400030	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$432,847
Building Name:	Outside Construction #45	**Address:**	7600 525th Street	**Deferred Maintenance:**	$52,142
Facility Condition Index:	0.12 - Good	**City Code:**	Rush City	**Ext. Gross Area:**	2,881

Site: P78550 - Lino Lakes

Building Code:	P785500000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$16,191,375
Building Name:	Perimter Fence	**Address:**	7525 4th	**Deferred Maintenance:**	$12,672,383
Facility Condition Index:	0.78 - Crisis	**City Code:**	LINO LAKES	**Ext. Gross Area:**	146,356

Building Code:	P7855000102	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$3,909,943
Building Name:	J-1 Kellogg	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$745,574
Facility Condition Index:	0.19 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	18,757
Building Code:	P7855000202	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$13,156,440
Building Name:	A Power House	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$2,466,850
Facility Condition Index:	0.19 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	11,137
Building Code:	P7855000302	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,653
Building Name:	M Pump House	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$7,712
Facility Condition Index:	0.22 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	180
Building Code:	P7855000402	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$4,941,460
Building Name:	L-2 Sibley	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,253,706
Facility Condition Index:	0.25 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	12,032
Building Code:	P7855000502	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$601,535
Building Name:	S Maintenance Garage	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$86,439
Facility Condition Index:	0.14 - Good	**City Code:**	Lino Lakes	**Ext. Gross Area:**	3,836
Building Code:	P7855000602	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,653
Building Name:	N Valve House	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$11,591
Facility Condition Index:	0.33 - Poor	**City Code:**	Lino Lakes	**Ext. Gross Area:**	180
Building Code:	P7855000902	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$5,584,559
Building Name:	J-2 Andrews	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,206,057
Facility Condition Index:	0.22 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	18,757
Building Code:	P7855001002	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$18,234,932
Building Name:	H Food Service	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$4,945,145
Facility Condition Index:	0.27 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	27,100
Building Code:	P7855001102	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$983,521
Building Name:	T Building	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$397,565
Facility Condition Index:	0.40 - Poor	**City Code:**	Lino Lakes	**Ext. Gross Area:**	6,078
Building Code:	P7855001202	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$34,618,129
Building Name:	B Building	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$7,863,727
Facility Condition Index:	0.23 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	89,076
Building Code:	P7855001302	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$699,227
Building Name:	A Control Center	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$132,734
Facility Condition Index:	0.19 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	2,245
Building Code:	P7855001402	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,383,389
Building Name:	F-2 Administration	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$484,919
Facility Condition Index:	0.20 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	10,178

Building Code:	P7855001602	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,817,504
Building Name:	J-3 Carver	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$806,829
Facility Condition Index:	0.17 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	18,757
Building Code:	P7855001702	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,547,194
Building Name:	E Building	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,623,985
Facility Condition Index:	0.64 - Crisis	**City Code:**	Lino Lakes	**Ext. Gross Area:**	10,397
Building Code:	P7855001802	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$13,250
Building Name:	Truck Gate	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,605
Facility Condition Index:	0.12 - Good	**City Code:**	Lino Lakes	**Ext. Gross Area:**	99
Building Code:	P7855002002	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$4,814,988
Building Name:	L-1 Mayo	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,240,430
Facility Condition Index:	0.26 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	12,560
Building Code:	P7855002102	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,384,577
Building Name:	F-1 LRC	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$325,663
Facility Condition Index:	0.14 - Good	**City Code:**	Lino Lakes	**Ext. Gross Area:**	9,019
Building Code:	P7855002202	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$7,444,738
Building Name:	G Operations	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,318,019
Facility Condition Index:	0.18 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	28,668
Building Code:	P7855002302	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$9,199,590
Building Name:	K-4	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,636,644
Facility Condition Index:	0.18 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	24,175
Building Code:	P7855002401	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$9,155,151
Building Name:	K-3	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$1,730,648
Facility Condition Index:	0.19 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	24,176
Building Code:	P7855002402	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$8,697,498
Building Name:	C Activities	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$2,666,970
Facility Condition Index:	0.31 - Poor	**City Code:**	Lino Lakes	**Ext. Gross Area:**	35,094
Building Code:	P7855002802	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,265,851
Building Name:	U Building	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$247,618
Facility Condition Index:	0.20 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	8,875
Building Code:	P7855002901	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$45,149
Building Name:	Outside Maintenance Storage Garage	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$7,761
Facility Condition Index:	0.17 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	624
Building Code:	P7855003102	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$303,521
Building Name:	Engineer Pole Barn	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$49,440
Facility Condition Index:	0.16 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	2,911

Building Code:	P7855003202	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$25,271,789
Building Name:	Triad	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$3,303,451
Facility Condition Index:	0.13 - Good	**City Code:**	Lino Lakes	**Ext. Gross Area:**	59,908
Building Code:	P7855003302	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$3,642,430
Building Name:	Education	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$334,731
Facility Condition Index:	0.09 - Good	**City Code:**	Lino Lakes	**Ext. Gross Area:**	11,138
Building Code:	P7855003402	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$24,609
Building Name:	MCO	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$5,342
Facility Condition Index:	0.22 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	123
Building Code:	P7855003502	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$11,111,322
Building Name:	Q Building	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$2,936,645
Facility Condition Index:	0.26 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	31,091
Building Code:	P7855003702	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$39,123,960
Building Name:	South Housing	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$3,135,242
Facility Condition Index:	0.08 - Good	**City Code:**	Lino Lakes	**Ext. Gross Area:**	93,397
Building Code:	P7855003902	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$97,406
Building Name:	U Building Annex	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$47,096
Facility Condition Index:	0.48 - Poor	**City Code:**	Lino Lakes	**Ext. Gross Area:**	696
Building Code:	P7855004102	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$214,637
Building Name:	Trades Pole Barn	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$46,749
Facility Condition Index:	0.22 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	2,400
Building Code:	P7855004202	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$120,750
Building Name:	Green House	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$48,178
Facility Condition Index:	0.40 - Poor	**City Code:**	Lino Lakes	**Ext. Gross Area:**	1,256
Building Code:	P7855004302	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,250
Building Name:	Religious Storage	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$6,505
Facility Condition Index:	0.46 - Poor	**City Code:**	Lino Lakes	**Ext. Gross Area:**	120
Building Code:	P7855004304	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$4,337,878
Building Name:	East Tunnels	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$939,974
Facility Condition Index:	0.22 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	15,064
Building Code:	P7855004403	**Cost Model Name:**	Tunnel	**Current Replacement Value:**	$4,228,086
Building Name:	West Tunnel	**Address:**	7525 4th Avenue	**Deferred Maintenance:**	$699,963
Facility Condition Index:	0.17 - Fair	**City Code:**	Lino Lakes	**Ext. Gross Area:**	18,149

Site: P78620 - Stillwater

Building Code:	P786200000A	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$4,091,448
Building Name:	#27 Perimeter Wall	**Address:**	970 Picket Street	**Deferred Maintenance:**	$590,528
Facility Condition Index:	0.14 - Good	**City Code:**	BAYPORT	**Ext. Gross Area:**	105,521
Building Code:	P786200000B	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$1,632,756
Building Name:	Perimeter Fence	**Address:**		**Deferred Maintenance:**	$163,276
Facility Condition Index:	0.10 - Good	**City Code:**	BAYPORT	**Ext. Gross Area:**	105,521
Building Code:	P7862000282	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$72,558,020
Building Name:	Power House - #19	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$17,479,880
Facility Condition Index:	0.24 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	28,655
Building Code:	P7862000582	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$6,102,378
Building Name:	Health Services #10	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$515,824
Facility Condition Index:	0.08 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	20,933
Building Code:	P7862000882	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$12,907,676
Building Name:	Security Center/C-Annex #9	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$2,424,763
Facility Condition Index:	0.19 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	29,171
Building Code:	P7862001282	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$58,423,830
Building Name:	Industry Bldg #18	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$21,990,416
Facility Condition Index:	0.38 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	124,776
Building Code:	P7862001382	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,067,670
Building Name:	Industry #26	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$1,056,588
Facility Condition Index:	0.21 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	18,400
Building Code:	P7862001482	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$323,142
Building Name:	Utility #22	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$93,823
Facility Condition Index:	0.29 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	1,038
Building Code:	P7862001582	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,255,791
Building Name:	Vehicle Maint Garage #42	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$213,993
Facility Condition Index:	0.17 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	4,602
Building Code:	P7862001782	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$8,574,907
Building Name:	MN Security Unit #35	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$2,254,660
Facility Condition Index:	0.26 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	20,638
Building Code:	P7862001882	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,149,127
Building Name:	Building Maintenance #24	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$355,312
Facility Condition Index:	0.17 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	10,378
Building Code:	P7862001982	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$20,448,227
Building Name:	Kitchen #15	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$2,766,167
Facility Condition Index:	0.14 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	39,035

Building Code:	P7862002082	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$51,228,117
Building Name:	Industry Bldg #20	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$16,610,259
Facility Condition Index:	0.32 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	125,768
Building Code:	P7862002182	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$29,512,078
Building Name:	Cell Hall D #12	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$7,307,137
Facility Condition Index:	0.25 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	62,862
Building Code:	P7862002482	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,671,263
Building Name:	Main Corridor #6	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$773,675
Facility Condition Index:	0.17 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	23,935
Building Code:	P7862002782	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$20,331,294
Building Name:	Industry /Plt Op #25	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$4,965,974
Facility Condition Index:	0.24 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	63,288
Building Code:	P7862002882	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,970,795
Building Name:	Computer for Schools #49	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$893,971
Facility Condition Index:	0.23 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	10,430
Building Code:	P7862003082	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$15,002,892
Building Name:	Education #13	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$4,268,915
Facility Condition Index:	0.28 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	46,987
Building Code:	P7862003182	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,234,590
Building Name:	Chapel #7	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$222,945
Facility Condition Index:	0.18 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	3,929
Building Code:	P7862003482	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$12,053,107
Building Name:	Dining Room #14	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$3,741,560
Facility Condition Index:	0.31 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	16,008
Building Code:	P7862003582	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$22,790,893
Building Name:	Administration #1	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$4,665,792
Facility Condition Index:	0.20 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	55,006
Building Code:	P7862003782	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$73,264,645
Building Name:	Cell Hall A #5	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$21,901,525
Facility Condition Index:	0.30 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	154,500
Building Code:	P7862004082	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,184,401
Building Name:	Grainery Storage #50	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$187,799
Facility Condition Index:	0.16 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	5,046
Building Code:	P7862004182	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$7,333,531
Building Name:	Recreation #11	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$1,670,498
Facility Condition Index:	0.23 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	26,178

Building Code:	P7862004482	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,070,648
Building Name:	Outside Construction #45	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$315,017
Facility Condition Index:	0.29 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	9,094
Building Code:	P7862004582	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$59,030,531
Building Name:	Cell Hall B #3	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$12,132,132
Facility Condition Index:	0.21 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	154,684
Building Code:	P7862004782	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,987,568
Building Name:	Admin West Annex #4	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$1,096,889
Facility Condition Index:	0.22 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	18,265
Building Code:	P7862005282	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$4,509,664
Building Name:	Young Conference Center #28	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$634,599
Facility Condition Index:	0.14 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	10,225
Building Code:	P7862005482	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,601
Building Name:	Scale House #48	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$2,623
Facility Condition Index:	0.19 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	65
Building Code:	P7862005582	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$10,201,354
Building Name:	Generator #1 Bldg #38	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$1,064,188
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	1,617
Building Code:	P7862005682	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$42,011,789
Building Name:	Industry Bldg #21	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$6,514,410
Facility Condition Index:	0.16 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	87,762
Building Code:	P7862005782	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$232,846
Building Name:	Canteen/Property #16	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$76,808
Facility Condition Index:	0.33 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	16,227
Building Code:	P7862005882	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$3,622,710
Building Name:	Control Unit #2	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$809,412
Facility Condition Index:	0.22 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	10,767
Building Code:	P7862005982	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$268,471
Building Name:	Greenhouse Office #30	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$32,805
Facility Condition Index:	0.12 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	999
Building Code:	P7862006282	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,689,733
Building Name:	Discipline #8	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$206,529
Facility Condition Index:	0.12 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	3,835
Building Code:	P7862006382	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,402,658
Building Name:	Flammable Storage #41	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$230,769
Facility Condition Index:	0.16 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	4,976

Building Code:	P7862006482	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$9,548,134
Building Name:	West Warehouse # 37	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$4,564,019
Facility Condition Index:	0.48 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	58,545
Building Code:	P7862006582	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$9,768,230
Building Name:	East Warehouse #36	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$4,339,306
Facility Condition Index:	0.44 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	66,706
Building Code:	P7862006682	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$3,519,100
Building Name:	Root Cellar #40	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$604,467
Facility Condition Index:	0.17 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	5,492
Building Code:	P7862006882	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$302,598
Building Name:	Residence Garage #29	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$84,760
Facility Condition Index:	0.28 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	1,056
Building Code:	P7862006982	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$352,821
Building Name:	Storage Shed #60	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$105,926
Facility Condition Index:	0.30 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	2,704
Building Code:	P7862007182	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$441,724
Building Name:	Butler Building #57	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$245,301
Facility Condition Index:	0.56 - Crisis	**City Code:**	Bayport	**Ext. Gross Area:**	3,405
Building Code:	P7862007282	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$777,653
Building Name:	Pole Barn Storage #58	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$115,062
Facility Condition Index:	0.15 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	6,050
Building Code:	P7862007682	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$511,540
Building Name:	Ice House Storage #54	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$51,154
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	1,061
Building Code:	P7862007782	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$518,662
Building Name:	Machine Storage #44	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$132,531
Facility Condition Index:	0.26 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	4,038
Building Code:	P7862008081	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$121,992
Building Name:	Green House #79	**Address:**	970 Pickett Street N	**Deferred Maintenance:**	$40,257
Facility Condition Index:	0.33 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	2,195
Building Code:	P7862008082	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$320,590
Building Name:	C/O Transporation Garage #43	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$74,846
Facility Condition Index:	0.23 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	3,072
Building Code:	P7862008084	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$79,453
Building Name:	Sally Port #73	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$18,233
Facility Condition Index:	0.23 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	163

Building Code:	P7862008085	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$206,143
Building Name:	Green House #74	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$70,999
Facility Condition Index:	0.34 - Poor	**City Code:**	Bayport	**Ext. Gross Area:**	1,771
Building Code:	P7862008086	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$289,635
Building Name:	Green House #75	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$77,061
Facility Condition Index:	0.27 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	2,195
Building Code:	P7862008087	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,114
Building Name:	71 -Storage	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$111
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	93
Building Code:	P7862008088	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$107,759
Building Name:	Guard Tower #1	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$9,394
Facility Condition Index:	0.09 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	395
Building Code:	P7862008089	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$103,838
Building Name:	Guard Tower #2	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$10,384
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	389
Building Code:	P7862008090	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$139,842
Building Name:	Guard Tower #3	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$18,700
Facility Condition Index:	0.13 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	489
Building Code:	P7862008091	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$116,979
Building Name:	Guard Tower #4	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$11,698
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	394
Building Code:	P7862008092	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$108,474
Building Name:	Guard Tower #5	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$10,847
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	396
Building Code:	P7862008093	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$122,892
Building Name:	Guard Tower #6	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$12,289
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	459
Building Code:	P7862008094	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$111,848
Building Name:	Guard Tower #7	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$11,185
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	395
Building Code:	P7862008095	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$702
Building Name:	72 -Storage	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$70
Facility Condition Index:	0.10 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	92
Building Code:	P7862008096	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$241,592
Building Name:	Industry Pass Bldg #76	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$38,258
Facility Condition Index:	0.16 - Fair	**City Code:**	Bayport	**Ext. Gross Area:**	768

Building Code:	P7862008097	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$220,371
Building Name:	South Gate Officers Station #77	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$6,608
Facility Condition Index:	0.03 - Excellent	**City Code:**	Bayport	**Ext. Gross Area:**	480
Building Code:	P7862008100	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$21,573,682
Building Name:	Segregation Bldg #17	**Address:**	970 Pickett Street No	**Deferred Maintenance:**	$1,134,506
Facility Condition Index:	0.05 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	60,977
Building Code:	P7862008101	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$672,955
Building Name:	Water Treatment #78	**Address:**		**Deferred Maintenance:**	$49,170
Facility Condition Index:	0.07 - Good	**City Code:**	Bayport	**Ext. Gross Area:**	3,487

Site: P78630 - Oak Park Heights

Building Code:	P786300000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$16,379,146
Building Name:	Perimeter Fences	**Address:**	5329 Osgood Avenue N	**Deferred Maintenance:**	$1,637,915
Facility Condition Index:	0.10 - Good	**City Code:**	OAK PARK HEIGHTS	**Ext. Gross Area:**	149,854
Building Code:	P7863000100	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$12,934,134
Building Name:	Complex 1	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$2,238,715
Facility Condition Index:	0.17 - Fair	**City Code:**	Stillwater	**Ext. Gross Area:**	30,842
Building Code:	P7863000200	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$10,444,503
Building Name:	Complex 2	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,777,880
Facility Condition Index:	0.17 - Fair	**City Code:**	Stillwater	**Ext. Gross Area:**	34,810
Building Code:	P7863000300	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$12,351,561
Building Name:	Complex 3	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,522,212
Facility Condition Index:	0.12 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	31,629
Building Code:	P7863000400	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$12,735,984
Building Name:	Complex 4	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,612,732
Facility Condition Index:	0.13 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	30,841
Building Code:	P7863000500	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$12,077,218
Building Name:	Complex 5	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,497,392
Facility Condition Index:	0.12 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	30,079
Building Code:	P7863000600	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$13,800,199
Building Name:	Complex 6	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,691,604
Facility Condition Index:	0.12 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	34,199
Building Code:	P7863000700	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$9,417,226
Building Name:	Complex 7	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,471,938
Facility Condition Index:	0.16 - Fair	**City Code:**	Stillwater	**Ext. Gross Area:**	20,086

Building Code:	P7863000800	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$14,991,208
Building Name:	Complex 8	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,935,490
Facility Condition Index:	0.13 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	42,209
Building Code:	P7863000900	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$9,030,709
Building Name:	Gym/Chapel	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,106,085
Facility Condition Index:	0.12 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	26,849
Building Code:	P7863001000	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$32,685,183
Building Name:	Core Building	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$6,925,354
Facility Condition Index:	0.21 - Fair	**City Code:**	Stillwater	**Ext. Gross Area:**	61,932
Building Code:	P7863001100	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$8,788,522
Building Name:	Warehouse/Garage/Range	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$1,218,548
Facility Condition Index:	0.14 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	27,862
Building Code:	P7863001200	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$26,599
Building Name:	Communications Bldg	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$2,620
Facility Condition Index:	0.10 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	180
Building Code:	P7863001300	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$189,548
Building Name:	Polebarn/Storage	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$36,008
Facility Condition Index:	0.19 - Fair	**City Code:**	Stillwater	**Ext. Gross Area:**	2,880
Building Code:	P7863001400	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$1,660,469
Building Name:	Bridge	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$171,148
Facility Condition Index:	0.10 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	2,016
Building Code:	P7863001500	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$674,012
Building Name:	Boiler Building	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$64,122
Facility Condition Index:	0.10 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	799
Building Code:	P7863001600	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$18,863,581
Building Name:	ACU	**Address:**	5329 Osgood Avenue North	**Deferred Maintenance:**	$2,751,760
Facility Condition Index:	0.15 - Good	**City Code:**	Stillwater	**Ext. Gross Area:**	46,711

Site: P78640 - Shakopee

Building Code:	P7864000001	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$151,734,343
Building Name:	Core	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$33,717,754
Facility Condition Index:	0.22 - Fair	**City Code:**	Shakopee	**Ext. Gross Area:**	72,934
Building Code:	P7864000002	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$6,408,830
Building Name:	Bldg D Roosevelt	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$1,720,423
Facility Condition Index:	0.27 - Fair	**City Code:**	Shakopee	**Ext. Gross Area:**	11,786

Building Code:	P7864000003	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$3,680,478
Building Name:	Bldg G Novello	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$510,965
Facility Condition Index:	0.14 - Good	**City Code:**	Shakopee	**Ext. Gross Area:**	8,695
Building Code:	P7864000004	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$9,080,581
Building Name:	Bldg H Power Plant	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$2,765,472
Facility Condition Index:	0.30 - Poor	**City Code:**	Shakopee	**Ext. Gross Area:**	4,144
Building Code:	P7864000005	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$4,315,110
Building Name:	Bldg J Anthony	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$1,003,873
Facility Condition Index:	0.23 - Fair	**City Code:**	Shakopee	**Ext. Gross Area:**	11,786
Building Code:	P7864000006	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$6,724,865
Building Name:	Bldg K Broker	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$942,647
Facility Condition Index:	0.14 - Good	**City Code:**	Shakopee	**Ext. Gross Area:**	18,674
Building Code:	P7864000007	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$6,724,987
Building Name:	Bldg L Bethune	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$1,230,155
Facility Condition Index:	0.18 - Fair	**City Code:**	Shakopee	**Ext. Gross Area:**	18,676
Building Code:	P7864000008	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$3,653,453
Building Name:	Bldg M Mead	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$611,271
Facility Condition Index:	0.17 - Fair	**City Code:**	Shakopee	**Ext. Gross Area:**	5,142
Building Code:	P7864000009	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$16,179,070
Building Name:	Bldg N Parks	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$1,828,515
Facility Condition Index:	0.11 - Good	**City Code:**	Shakopee	**Ext. Gross Area:**	32,470
Building Code:	P786400000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$10,612,422
Building Name:	Perimeter Fences	**Address:**	1010 West Sixth Avenue	**Deferred Maintenance:**	$212,759
Facility Condition Index:	0.02 - Excellent	**City Code:**	SHAKOPEE	**Ext. Gross Area:**	58,500
Building Code:	P7864000010	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$2,355,903
Building Name:	Bldg F Higbee	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$345,360
Facility Condition Index:	0.15 - Good	**City Code:**	Shakopee	**Ext. Gross Area:**	10,450
Building Code:	P7864000012	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$15,487,591
Building Name:	Bldg P Monahan	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$963,830
Facility Condition Index:	0.06 - Good	**City Code:**	Shakopee	**Ext. Gross Area:**	41,220
Building Code:	P7864000013	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$362,572
Building Name:	Greenhouse	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$119,649
Facility Condition Index:	0.33 - Poor	**City Code:**	Shakopee	**Ext. Gross Area:**	6,331
Building Code:	P7864000014	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$4,163,104
Building Name:	Bldg E Tubman	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$941,419
Facility Condition Index:	0.23 - Fair	**City Code:**	Shakopee	**Ext. Gross Area:**	11,790

Building Code:	P7864000015	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$563,054
Building Name:	Garage	**Address:**	1010 West 6th Avenue	**Deferred Maintenance:**	$62,330
Facility Condition Index:	0.11 - Good	**City Code:**	Shakopee	**Ext. Gross Area:**	1,781

Site: P78760 - Red Wing

Building Code:	P787600000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$7,341,133
Building Name:	Perimeter Fences	**Address:**	1079 Hwy 292	**Deferred Maintenance:**	$146,823
Facility Condition Index:	0.02 - Excellent	**City Code:**	RED WING	**Ext. Gross Area:**	97,572
Building Code:	P7876000010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$534,640
Building Name:	Barn #1	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$248,580
Facility Condition Index:	0.46 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	4,630
Building Code:	P7876000030	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$10,097,970
Building Name:	Dayton #30	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$1,036,627
Facility Condition Index:	0.10 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	20,209
Building Code:	P7876000031	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$86,403
Building Name:	Garage #31	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$3,445
Facility Condition Index:	0.04 - Excellent	**City Code:**	Red Wing	**Ext. Gross Area:**	611
Building Code:	P7876000032	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$724,305
Building Name:	Garage #32	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$81,528
Facility Condition Index:	0.11 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	4,201
Building Code:	P7876000033	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$22,824
Building Name:	Gas Metering House	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$3,270
Facility Condition Index:	0.14 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	142
Building Code:	P7876000125	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$25,683,969
Building Name:	Industrial Building #10	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$7,476,969
Facility Condition Index:	0.29 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	46,895
Building Code:	P7876000160	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$165,053
Building Name:	Garden Storage #16	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$80,100
Facility Condition Index:	0.49 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	848
Building Code:	P7876000180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$225,296
Building Name:	Storage Building #18	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$22,179
Facility Condition Index:	0.10 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	1,950
Building Code:	P7876000325	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$582,285
Building Name:	Auto Shop #14	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$91,914
Facility Condition Index:	0.16 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	2,547

Building Code:	P7876000800	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$51,451
Building Name:	Flammable Storage #8	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$7,432
Facility Condition Index:	0.14 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	192
Building Code:	P7876000900	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$49,000
Building Name:	Deep Well Pump House #9	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$21,274
Facility Condition Index:	0.43 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	220
Building Code:	P7876000925	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,455,102
Building Name:	Maintenance Office #6	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$449,109
Facility Condition Index:	0.31 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	3,655
Building Code:	P7876001125	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$938,087
Building Name:	Green House #11	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$351,400
Facility Condition Index:	0.37 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	3,540
Building Code:	P7876001321	**Cost Model Name:**	Parking Structure	**Current Replacement Value:**	$700,290
Building Name:	Root Cellar #15	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$51,861
Facility Condition Index:	0.07 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	3,663
Building Code:	P7876001425	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$2,970,612
Building Name:	Duke #5	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$1,137,363
Facility Condition Index:	0.38 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	9,880
Building Code:	P7876001525	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,633,162
Building Name:	Cabinet Shop #12	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$218,662
Facility Condition Index:	0.13 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	3,959
Building Code:	P7876001625	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$815,783
Building Name:	Welding Shop #7	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$140,606
Facility Condition Index:	0.17 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	1,528
Building Code:	P7876001925	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,811,396
Building Name:	Food Prep #19	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$312,973
Facility Condition Index:	0.11 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	8,846
Building Code:	P7876002325	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$11,314,212
Building Name:	School #25	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$1,369,423
Facility Condition Index:	0.12 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	34,908
Building Code:	P7876002400	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$15,629,131
Building Name:	Vocational Building	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$368,666
Facility Condition Index:	0.02 - Excellent	**City Code:**	Red Wing	**Ext. Gross Area:**	25,628
Building Code:	P7876002425	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$6,241,373
Building Name:	LaSalle #21	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$1,221,760
Facility Condition Index:	0.20 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	13,739

Building Code:	P7876002525	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$3,186,766
Building Name:	Transition House #28	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$143,384
Facility Condition Index:	0.04 - Excellent	**City Code:**	Red Wing	**Ext. Gross Area:**	6,660
Building Code:	P7876002725	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$24,922,658
Building Name:	Admin/Centennial Hall	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$9,963,986
Facility Condition Index:	0.40 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	70,748
Building Code:	P7876002825	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$2,465,648
Building Name:	Yale #27	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$489,671
Facility Condition Index:	0.20 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	7,487
Building Code:	P7876002925	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$3,369,022
Building Name:	Brown #29	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$314,251
Facility Condition Index:	0.09 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	7,441
Building Code:	P7876003425	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$4,468,807
Building Name:	Grinnell #4	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$1,346,623
Facility Condition Index:	0.30 - Poor	**City Code:**	Red Wing	**Ext. Gross Area:**	13,368
Building Code:	P7876003525	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$3,238,145
Building Name:	Knox #20	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$821,735
Facility Condition Index:	0.25 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	9,830
Building Code:	P7876003625	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$2,192,131
Building Name:	Stanford #2	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$389,902
Facility Condition Index:	0.18 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	7,462
Building Code:	P7876003825	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$2,694,238
Building Name:	Princeton #26	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$376,575
Facility Condition Index:	0.14 - Good	**City Code:**	Red Wing	**Ext. Gross Area:**	7,935
Building Code:	P7876004125	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$2,588,414
Building Name:	Harvard #3	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$475,316
Facility Condition Index:	0.18 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	7,534
Building Code:	P7876006254	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$507,346
Building Name:	Laundry #24	**Address:**	1079 Highway 292	**Deferred Maintenance:**	$107,767
Facility Condition Index:	0.21 - Fair	**City Code:**	Red Wing	**Ext. Gross Area:**	1,977

Site: P78780 - TOGO

Building Code:	P7878010001	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$548,890
Building Name:	Barracks #2	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$78,116
Facility Condition Index:	0.14 - Good	**City Code:**	Togo	**Ext. Gross Area:**	3,484

Building Code:	P7878010002	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$376,699
Building Name:	Green Storage Building	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$58,308
Facility Condition Index:	0.15 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	2,020
Building Code:	P7878010003	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$821,027
Building Name:	Challenge	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$175,868
Facility Condition Index:	0.21 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	3,599
Building Code:	P7878010004	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$1,239,320
Building Name:	Barracks #1	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$310,092
Facility Condition Index:	0.25 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	8,085
Building Code:	P7878010005	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$2,465,200
Building Name:	CD Services/Health Services	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$256,830
Facility Condition Index:	0.10 - Good	**City Code:**	Togo	**Ext. Gross Area:**	10,825
Building Code:	P7878010006	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$19,863
Building Name:	Pump House	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$2,480
Facility Condition Index:	0.12 - Good	**City Code:**	Togo	**Ext. Gross Area:**	187
Building Code:	P7878010007	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$318,973
Building Name:	Education	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$39,094
Facility Condition Index:	0.12 - Good	**City Code:**	Togo	**Ext. Gross Area:**	2,223
Building Code:	P7878010008	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$131,879
Building Name:	Industry	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$34,858
Facility Condition Index:	0.26 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	1,629
Building Code:	P7878010009	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$1,167,032
Building Name:	Gym	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$129,963
Facility Condition Index:	0.11 - Good	**City Code:**	Togo	**Ext. Gross Area:**	5,852
Building Code:	P7878010010	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$263,216
Building Name:	Chapel	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$35,098
Facility Condition Index:	0.13 - Good	**City Code:**	Togo	**Ext. Gross Area:**	1,244
Building Code:	P7878010011	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,848
Building Name:	Ski Chalet	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$31,848
Facility Condition Index:	1.00 - Crisis	**City Code:**	TOGO	**Ext. Gross Area:**	406
Building Code:	P7878010012	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$24,014
Building Name:	Gym - Water Pump 3	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$2,870
Facility Condition Index:	0.12 - Good	**City Code:**	Togo	**Ext. Gross Area:**	217
Building Code:	P7878010013	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,219,002
Building Name:	Maintenance/Receiving	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$149,800
Facility Condition Index:	0.12 - Good	**City Code:**	Togo	**Ext. Gross Area:**	4,171

Building Code:	P7878010014	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$925,841
Building Name:	Food Service	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$131,271
Facility Condition Index:	0.14 - Good	**City Code:**	Togo	**Ext. Gross Area:**	3,270
Building Code:	P7878010015	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$539,044
Building Name:	SQ	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$106,502
Facility Condition Index:	0.20 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	3,617
Building Code:	P7878010016	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$711,563
Building Name:	Administration	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$161,853
Facility Condition Index:	0.23 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	2,860
Building Code:	P7878010017	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$191,037
Building Name:	Wash Bay	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$17,752
Facility Condition Index:	0.09 - Good	**City Code:**	Togo	**Ext. Gross Area:**	1,500
Building Code:	P7878010018	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,188
Building Name:	Lumber Storage	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$11,383
Facility Condition Index:	0.39 - Poor	**City Code:**	Togo	**Ext. Gross Area:**	296
Building Code:	P7878010019	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$868,440
Building Name:	Lakeside	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$195,698
Facility Condition Index:	0.23 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	5,581
Building Code:	P7878010020	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$890,898
Building Name:	CIP Offices	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$216,537
Facility Condition Index:	0.24 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	6,277
Building Code:	P7878010021	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$602,676
Building Name:	CIP Property	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$152,295
Facility Condition Index:	0.25 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	3,046
Building Code:	P7878010023	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,849
Building Name:	B2 Storage Shed	**Address:**	62741 County Road 551	**Deferred Maintenance:**	$3,589
Facility Condition Index:	0.24 - Fair	**City Code:**	Togo	**Ext. Gross Area:**	98

Site: P78830 - St Cloud

Building Code:	P7883000001	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,185,195
Building Name:	HR/Finance	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$209,640
Facility Condition Index:	0.18 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	3,692
Building Code:	P788300000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$29,220,010
Building Name:	Perimeter Wall & Fences	**Address:**	2305 Minnesota Blvd SE	**Deferred Maintenance:**	$15,510,718
Facility Condition Index:	0.53 - Crisis	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	135,320

Building Code:	P7883000071	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$182,617
Building Name:	Truck Gate	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$82,478
Facility Condition Index:	0.45 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	704
Building Code:	P7883001071	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$98,181
Building Name:	Guard Tower	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$23,027
Facility Condition Index:	0.23 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	129
Building Code:	P7883001171	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$17,042,128
Building Name:	Education	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$4,875,862
Facility Condition Index:	0.29 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	57,813
Building Code:	P7883001270	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$25,440,907
Building Name:	Gymnasium	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$6,379,200
Facility Condition Index:	0.25 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	45,449
Building Code:	P7883001271	**Cost Model Name:**	Multi-story Educational Facility	**Current Replacement Value:**	$15,088,728
Building Name:	Industries Building	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$3,775,894
Facility Condition Index:	0.25 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	49,506
Building Code:	P7883001771	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,502,259
Building Name:	Sticker Shop	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$335,242
Facility Condition Index:	0.22 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	8,586
Building Code:	P7883002571	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$31,703,086
Building Name:	B House	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$9,856,747
Facility Condition Index:	0.31 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	36,159
Building Code:	P7883003671	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$30,485,635
Building Name:	Food Service Laundry	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$7,738,360
Facility Condition Index:	0.25 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	36,107
Building Code:	P7883004671	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$5,377,682
Building Name:	Health Services (Old)	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$1,443,660
Facility Condition Index:	0.27 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	6,945
Building Code:	P7883004771	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,545,620
Building Name:	GPPI	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$576,938
Facility Condition Index:	0.23 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	8,883
Building Code:	P7883004871	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$9,611,303
Building Name:	Reshape/B-Annex/Canteen	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$2,900,581
Facility Condition Index:	0.30 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	20,073
Building Code:	P7883005171	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$8,332,088
Building Name:	Auto Body/Maint Shop	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$2,156,676
Facility Condition Index:	0.26 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	14,448

Building Code:	P7883005871	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,267,033
Building Name:	License Plant	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$1,121,258
Facility Condition Index:	0.34 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	9,556
Building Code:	P7883006171	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,837,102
Building Name:	Mason Shop	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$534,904
Facility Condition Index:	0.19 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	8,815
Building Code:	P7883006571	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$31,056,769
Building Name:	C House	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$9,931,790
Facility Condition Index:	0.32 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	36,793
Building Code:	P7883006670	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$39,687,397
Building Name:	E House	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$13,466,856
Facility Condition Index:	0.34 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	46,134
Building Code:	P7883006671	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,742,562
Building Name:	Upper/Lower E Complex	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$901,162
Facility Condition Index:	0.19 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	13,413
Building Code:	P7883007170	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$22,252,635
Building Name:	D House	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$6,298,590
Facility Condition Index:	0.28 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	24,693
Building Code:	P7883007171	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$28,579,542
Building Name:	Segregation	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$8,768,275
Facility Condition Index:	0.31 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	34,282
Building Code:	P7883007271	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,031,981
Building Name:	Main Corridors	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$577,410
Facility Condition Index:	0.28 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	6,571
Building Code:	P7883007370	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$31,535,174
Building Name:	A House	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$9,590,431
Facility Condition Index:	0.30 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	36,681
Building Code:	P7883007371	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$985,045
Building Name:	Orientation Complex	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$136,212
Facility Condition Index:	0.14 - Good	**City Code:**	St. Cloud	**Ext. Gross Area:**	3,516
Building Code:	P7883007471	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,124,274
Building Name:	Power Plant	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$3,428,159
Facility Condition Index:	0.11 - Good	**City Code:**	St. Cloud	**Ext. Gross Area:**	12,453
Building Code:	P7883007571	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,526,432
Building Name:	Plant Operations Office	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$1,812,248
Facility Condition Index:	0.40 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	13,726

Building Code:	P7883007671	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$169,433
Building Name:	Pump Station	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$102,042
Facility Condition Index:	0.60 - Crisis	**City Code:**	St. Cloud	**Ext. Gross Area:**	720
Building Code:	P7883007771	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$17,830,284
Building Name:	Administration	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$4,652,368
Facility Condition Index:	0.26 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	55,138
Building Code:	P7883007871	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,737,987
Building Name:	Training Barn	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$512,077
Facility Condition Index:	0.29 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	8,155
Building Code:	P7883007971	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$404,946
Building Name:	Payloader/Snow Plow Bldg	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$89,552
Facility Condition Index:	0.22 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	4,323
Building Code:	P7883008171	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$465,681
Building Name:	Steamfitter/Plumbers	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$143,001
Facility Condition Index:	0.31 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	2,259
Building Code:	P7883008271	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$596,659
Building Name:	Paint Shop	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$130,867
Facility Condition Index:	0.22 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	2,528
Building Code:	P7883008371	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$11,650,821
Building Name:	Dining Rm/Warehouse	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$3,282,417
Facility Condition Index:	0.28 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	37,647
Building Code:	P7883008571	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$399,791
Building Name:	Cardboard Storage	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$87,486
Facility Condition Index:	0.22 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	4,000
Building Code:	P7883008771	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$501,510
Building Name:	Clinton Building	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$165,498
Facility Condition Index:	0.33 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	3,772
Building Code:	P7883008871	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$423,873
Building Name:	South Quonset	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$88,297
Facility Condition Index:	0.21 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	4,214
Building Code:	P7883009071	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$228,645
Building Name:	Outside Grounds	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$78,312
Facility Condition Index:	0.34 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	1,327
Building Code:	P7883009171	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$144,201
Building Name:	Slaughter House	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$115,482
Facility Condition Index:	0.80 - Crisis	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	873

Building Code:	P7883009271	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$328,758
Building Name:	Staff Trip Car Shed	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$45,089
Facility Condition Index:	0.14 - Good	**City Code:**	St. Cloud	**Ext. Gross Area:**	2,640
Building Code:	P7883009371	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$461,740
Building Name:	Inside Grounds	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$162,761
Facility Condition Index:	0.35 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	2,551
Building Code:	P7883009471	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,732,726
Building Name:	Industries Warehouse	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$442,411
Facility Condition Index:	0.26 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	9,793
Building Code:	P7883009571	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$26,034
Building Name:	Shooting Range Building	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$6,530
Facility Condition Index:	0.25 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	248
Building Code:	P7883009671	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$173,679
Building Name:	Recreation Building	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$44,913
Facility Condition Index:	0.26 - Fair	**City Code:**	St. Cloud	**Ext. Gross Area:**	576
Building Code:	P7883009771	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$767,990
Building Name:	Old Mason Shop	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$316,453
Facility Condition Index:	0.41 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	2,562
Building Code:	P7883009871	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$167,460
Building Name:	Car Wash	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$20,014
Facility Condition Index:	0.12 - Good	**City Code:**	St. Cloud	**Ext. Gross Area:**	1,213
Building Code:	P7883009971	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,546,911
Building Name:	Root Cellar	**Address:**	2305 Minnesota Boulevard S.E.	**Deferred Maintenance:**	$764,983
Facility Condition Index:	0.49 - Poor	**City Code:**	St. Cloud	**Ext. Gross Area:**	7,452

Site: P78890 - Willow River

Building Code:	P7889000001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$351,199
Building Name:	Pole Building	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$71,230
Facility Condition Index:	0.20 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	3,341
Building Code:	P7889000002	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$67,294
Building Name:	Storage Shed	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$19,700
Facility Condition Index:	0.29 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	246
Building Code:	P7889000003	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$174,436
Building Name:	Classroom 7	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$45,815
Facility Condition Index:	0.26 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	862

Building Code:	P7889000004	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$998,928
Building Name:	Property Building	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$150,315
Facility Condition Index:	0.15 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	4,524
Building Code:	P7889000006	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,155
Building Name:	Storage Garage	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$5,959
Facility Condition Index:	0.10 - Good	**City Code:**	Willow River	**Ext. Gross Area:**	503
Building Code:	P7889000007	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$400,501
Building Name:	Education Building	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$88,772
Facility Condition Index:	0.22 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	3,362
Building Code:	P7889000258	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$1,220,989
Building Name:	CD Program Building	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$134,277
Facility Condition Index:	0.11 - Good	**City Code:**	Willow River	**Ext. Gross Area:**	7,624
Building Code:	P7889000358	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,967,372
Building Name:	Kitchen	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$462,344
Facility Condition Index:	0.16 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	5,086
Building Code:	P7889001258	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,024,172
Building Name:	Maintenance Building	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$229,382
Facility Condition Index:	0.22 - Fair	**City Code:**	Willow River	**Ext. Gross Area:**	4,592
Building Code:	P7889001458	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,737,752
Building Name:	Administration	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$196,979
Facility Condition Index:	0.11 - Good	**City Code:**	Willow River	**Ext. Gross Area:**	4,946
Building Code:	P7889001558	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$9,388,634
Building Name:	Barracks Building	**Address:**	86032 County Highway 61	**Deferred Maintenance:**	$867,719
Facility Condition Index:	0.09 - Good	**City Code:**	Willow River	**Ext. Gross Area:**	23,564

Site: P78900 - Faribault

Building Code:	P7890000002	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$6,411,930
Building Name:	Pine	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$1,341,732
Facility Condition Index:	0.21 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	25,282
Building Code:	P7890000003	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$31,091,228
Building Name:	Industry / MINNCOR	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$5,823,471
Facility Condition Index:	0.19 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	156,152
Building Code:	P7890000004	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$558,668
Building Name:	Master Control	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$55,472
Facility Condition Index:	0.10 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	2,254

Building Code:	P7890000005	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$169,437
Building Name:	Grounds Building	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$39,799
Facility Condition Index:	0.23 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	1,258
Building Code:	P7890000007	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,204,303
Building Name:	Walnut	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$254,177
Facility Condition Index:	0.21 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	6,480
Building Code:	P789000000A	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$23,779,140
Building Name:	Perimeter Fences	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,377,914
Facility Condition Index:	0.10 - Good	**City Code:**	FARIBAULT	**Ext. Gross Area:**	306,000
Building Code:	P7890000010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$183,750
Building Name:	Upholstery Shop	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$68,364
Facility Condition Index:	0.37 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	1,485
Building Code:	P7890000011	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$26,981,400
Building Name:	Main Warehouse	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$7,620,665
Facility Condition Index:	0.28 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	56,657
Building Code:	P7890000013	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$546,036
Building Name:	Paint Shop	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$98,697
Facility Condition Index:	0.18 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	3,008
Building Code:	P7890000014	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,721,608
Building Name:	Sycamore	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$824,701
Facility Condition Index:	0.17 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	18,887
Building Code:	P7890000015	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$21,879,661
Building Name:	Power Plant	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$3,549,799
Facility Condition Index:	0.16 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	41,468
Building Code:	P7890000021	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$445,868
Building Name:	Mason Shed	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$310,455
Facility Condition Index:	0.70 - Crisis	**City Code:**	Faribault	**Ext. Gross Area:**	4,180
Building Code:	P7890000023	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$9,332,732
Building Name:	Dakota	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$3,081,198
Facility Condition Index:	0.33 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	40,717
Building Code:	P7890000026	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,113
Building Name:	Pump House #2	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$8,936
Facility Condition Index:	0.29 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	249
Building Code:	P7890000027	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,567
Building Name:	Pump House #1	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$13,231
Facility Condition Index:	0.38 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	264

Building Code:	P7890000030	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$12,359,630
Building Name:	Aspen	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,359,586
Facility Condition Index:	0.19 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	34,558
Building Code:	P7890000038	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$10,645,617
Building Name:	Fern	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$4,216,499
Facility Condition Index:	0.40 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	46,564
Building Code:	P7890000043	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$5,934,280
Building Name:	Sierra/Holly	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$1,542,058
Facility Condition Index:	0.26 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	20,122
Building Code:	P7890000044	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$7,442,517
Building Name:	Willow	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$1,194,205
Facility Condition Index:	0.16 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	36,686
Building Code:	P7890000045	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$9,205,158
Building Name:	Birch	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,030,615
Facility Condition Index:	0.22 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	34,558
Building Code:	P7890000049	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,469,355
Building Name:	Laundry	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$1,167,387
Facility Condition Index:	0.18 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	37,050
Building Code:	P7890000081	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,815,012
Building Name:	Bus Barn/Equip Storage	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$938,614
Facility Condition Index:	0.52 - Crisis	**City Code:**	FARIBAULT	**Ext. Gross Area:**	11,328
Building Code:	P7890000082	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$318,005
Building Name:	General Storage	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$318,005
Facility Condition Index:	1.00 - Crisis	**City Code:**	FARIBAULT	**Ext. Gross Area:**	4,549
Building Code:	P7890000083	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$390,955
Building Name:	Calf Barn	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$90,384
Facility Condition Index:	0.23 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	4,112
Building Code:	P7890000084	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,170,031
Building Name:	Mechanics Shop	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$402,411
Facility Condition Index:	0.34 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	6,782
Building Code:	P7890000086	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$37,093
Building Name:	Truck Gate-FRB	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$5,486
Facility Condition Index:	0.15 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	200
Building Code:	P7890000093	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$4,953,423
Building Name:	Segregation	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$714,350
Facility Condition Index:	0.14 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	14,301

Building Code:	P7890000096	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$86,793
Building Name:	Refrigerator Building	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$44,127
Facility Condition Index:	0.51 - Crisis	**City Code:**	FARIBAULT	**Ext. Gross Area:**	760
Building Code:	P7890000097	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,586,736
Building Name:	Root Cellar	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$576,600
Facility Condition Index:	0.36 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	5,177
Building Code:	P7890000098	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$7,573,412
Building Name:	Tunnel - Inside	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,377,326
Facility Condition Index:	0.31 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	24,650
Building Code:	P7890000099	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$6,857,043
Building Name:	Tunnel - Outside	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$4,392,090
Facility Condition Index:	0.64 - Crisis	**City Code:**	FARIBAULT	**Ext. Gross Area:**	22,680
Building Code:	P7890000111	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$11,648,564
Building Name:	Food Service Bldg	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$1,240,448
Facility Condition Index:	0.11 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	37,285
Building Code:	P7890000166	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$8,031,474
Building Name:	Maple	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,484,757
Facility Condition Index:	0.31 - Poor	**City Code:**	Faribault	**Ext. Gross Area:**	24,066
Building Code:	P7890000266	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$18,483,641
Building Name:	Linden	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$4,330,275
Facility Condition Index:	0.23 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	50,344
Building Code:	P7890000666	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$10,642,329
Building Name:	Roger's Memorial Act	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,640,622
Facility Condition Index:	0.25 - Fair	**City Code:**	Faribault	**Ext. Gross Area:**	62,034
Building Code:	P7890000901	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$25,534,882
Building Name:	K2	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,414,751
Facility Condition Index:	0.09 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	85,945
Building Code:	P7890000902	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$23,231,043
Building Name:	K3	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,551,238
Facility Condition Index:	0.11 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	85,944
Building Code:	P7890000903	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$25,426,672
Building Name:	K4	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,476,366
Facility Condition Index:	0.10 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	85,945
Building Code:	P7890000904	**Cost Model Name:**	Correctional Facility Housing Unit	**Current Replacement Value:**	$23,834,732
Building Name:	K1	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$2,573,245
Facility Condition Index:	0.11 - Good	**City Code:**	Faribault	**Ext. Gross Area:**	85,945

Building Code:	P7890001000	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$15,234,367
Building Name:	Intake and Receiving Building	**Address:**	1101 Linden Lane	**Deferred Maintenance:**	$481,701
Facility Condition Index:	0.03 - Excellent	**City Code:**	Faribault	**Ext. Gross Area:**	41,538

Agency: R29 - Department of Natural Resources

FCI Rating:	Fair	**Current Replacement Value:**	$644,657,931	**Ext. Gross Area:**	3,400,421
Facility Condition Index:	0.23	**Deferred Maintenance:**	$148,431,235	**Building Count:**	2,877

Site: R290001 - Afton State Park

Building Code:	R2900600090	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$60,669
Building Name:	Afton SP Picnic Shelter 1	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$16,063
Facility Condition Index:	0.26 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	637
Building Code:	R2900600100	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$107,453
Building Name:	Afton SP Sanitation	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$26,305
Facility Condition Index:	0.24 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	418
Building Code:	R2900601150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$307,119
Building Name:	Afton SP Shop	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$79,950
Facility Condition Index:	0.26 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	1,929
Building Code:	R2900601160	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,356
Building Name:	Afton SP Oil House	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$4,432
Facility Condition Index:	0.22 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	100
Building Code:	R2900601170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$392,976
Building Name:	Afton SP Contact Station	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$48,032
Facility Condition Index:	0.12 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	1,200
Building Code:	R2900601180	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$925,239
Building Name:	Afton SP Trails Ctr	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$395,471
Facility Condition Index:	0.43 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	3,125
Building Code:	R2900601710	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,704
Building Name:	Afton SP Vault Toilet	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,297
Facility Condition Index:	0.34 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	27
Building Code:	R2900601720	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,704
Building Name:	Afton SP Vault Toilet	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,297
Facility Condition Index:	0.34 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	27
Building Code:	R2900601730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,704
Building Name:	Afton SP Backpack CG Vault Toilet	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$2,489
Facility Condition Index:	0.26 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	28
Building Code:	R2900601830	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$97,828
Building Name:	Afton SP Picnic Shelter 1	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$29,194
Facility Condition Index:	0.30 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	1,080

Building Code:	R2900602120	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$327,063
Building Name:	Afton SP Cold Storage	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$48,431
Facility Condition Index:	0.15 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	2,991
Building Code:	R2900602250	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$51,363
Building Name:	Afton SP Vault Toilet Concrete	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$5,136
Facility Condition Index:	0.10 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	102
Building Code:	R2900602260	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,867
Building Name:	Afton SP Group CG 1 Adirondack	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$2,926
Facility Condition Index:	0.33 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	79
Building Code:	R2900602270	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,813
Building Name:	Afton SP Backpack CG Adirondack	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,796
Facility Condition Index:	0.39 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	146
Building Code:	R2900602280	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,867
Building Name:	Afton SP Backpack CG Adirondack	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,170
Facility Condition Index:	0.36 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	87
Building Code:	R2900602320	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,477
Building Name:	Afton SP Backpack CG Adirondack	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$4,108
Facility Condition Index:	0.75 - Crisis	**City Code:**	HASTINGS	**Ext. Gross Area:**	55
Building Code:	R2900602330	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$5,461
Building Name:	Afton SP Cold Storage	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$2,175
Facility Condition Index:	0.40 - Poor	**City Code:**	HASTINGS	**Ext. Gross Area:**	135
Building Code:	R2900602340	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$55,728
Building Name:	Afton Grp CG 1 Big Blue Stem Cabin	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,314
Facility Condition Index:	0.06 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	296
Building Code:	R2900602350	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,134
Building Name:	Afton Grp CG 1 ADA Blue Bird Cabin	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,190
Facility Condition Index:	0.06 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	296
Building Code:	R2900602360	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,382
Building Name:	Afton Grp CG 1 ADA White Pine Cabin	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$3,987
Facility Condition Index:	0.07 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	296
Building Code:	R2900602370	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$55,728
Building Name:	Afton SP Group CG 1 Bur Oak Cabin	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$6,385
Facility Condition Index:	0.11 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	296
Building Code:	R2900602430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,143
Building Name:	Afton SP Backpack CG Vault Concrete	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$403
Facility Condition Index:	0.02 - Excellent	**City Code:**	HASTINGS	**Ext. Gross Area:**	47

Building Code:	R2900602440	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$6,814
Building Name:	Afton SP Grp CG 1 Picnic Shelter 1	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$543
Facility Condition Index:	0.08 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	120
Building Code:	R2900602450	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$62,942
Building Name:	Afton SP Group CG 1 East Yurt	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$5,806
Facility Condition Index:	0.09 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	365
Building Code:	R2900602460	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$62,942
Building Name:	Afton SP Group CG 1 West Yurt	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$5,806
Facility Condition Index:	0.09 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	365
Building Code:	R2900602470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,143
Building Name:	Afton SP Group CG 1 Vault Concrete	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$403
Facility Condition Index:	0.02 - Excellent	**City Code:**	HASTINGS	**Ext. Gross Area:**	51
Building Code:	R2900602480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,682
Building Name:	Afton SP Backpack CG Vault Concrete	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$514
Facility Condition Index:	0.02 - Excellent	**City Code:**	HASTINGS	**Ext. Gross Area:**	51
Building Code:	R2900602490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,682
Building Name:	Afton SP Group CG 1 Vault Concrete	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$514
Facility Condition Index:	0.02 - Excellent	**City Code:**	HASTINGS	**Ext. Gross Area:**	51
Building Code:	R2900602500	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,682
Building Name:	Afton SP Group CG 2 Vault Concrete	**Address:**	6959 PELLER AVE S	**Deferred Maintenance:**	$514
Facility Condition Index:	0.02 - Excellent	**City Code:**	HASTINGS	**Ext. Gross Area:**	51

Site: R290002 - Aitkin

Building Code:	R2900306230	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$2,765,510
Building Name:	Aitkin Office	**Address:**	1200 MINNESOTA AVE S	**Deferred Maintenance:**	$469,073
Facility Condition Index:	0.17 - Fair	**City Code:**	AITKIN	**Ext. Gross Area:**	17,304
Building Code:	R2900306550	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$290,071
Building Name:	Aitkin Boat Storage	**Address:**	1200 MINNESOTA AVE S	**Deferred Maintenance:**	$62,636
Facility Condition Index:	0.22 - Fair	**City Code:**	AITKIN	**Ext. Gross Area:**	3,129
Building Code:	R2900307130	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,647
Building Name:	Aitkin Cold Storage	**Address:**	1200 MINNESOTA AVE S	**Deferred Maintenance:**	$6,945
Facility Condition Index:	0.24 - Fair	**City Code:**	AITKIN	**Ext. Gross Area:**	229

Site: R290003 - Appleton

Building Code:	R2900403960	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,440
Building Name:	Appleton Pump House	**Address:**	25 N MUNSTERMAN ST	**Deferred Maintenance:**	$369
Facility Condition Index:	0.02 - Excellent	**City Code:**	APPLETON	**Ext. Gross Area:**	100
Building Code:	R2900404970	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$180,311
Building Name:	Appleton Shop	**Address:**	25 N MUNSTERMAN ST	**Deferred Maintenance:**	$71,488
Facility Condition Index:	0.40 - Poor	**City Code:**	APPLETON	**Ext. Gross Area:**	1,440

Site: R290004 - Banning State Park

Building Code:	R2900300830	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$257,498
Building Name:	Banning SP Shop	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$97,286
Facility Condition Index:	0.38 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	1,531
Building Code:	R2900300840	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$249,797
Building Name:	Banning SP CG Sanitation	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$85,639
Facility Condition Index:	0.34 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	694
Building Code:	R2900300850	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$123,289
Building Name:	Banning SP Sanitation	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$72,238
Facility Condition Index:	0.59 - Crisis	**City Code:**	SANDSTONE	**Ext. Gross Area:**	348
Building Code:	R2900303690	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$253,478
Building Name:	Banning SP Office	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$80,370
Facility Condition Index:	0.32 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	979
Building Code:	R2900303780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,588
Building Name:	Banning SP Oil House	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$6,220
Facility Condition Index:	0.35 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	104
Building Code:	R2900303830	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$427,115
Building Name:	Banning SP Residence	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$136,827
Facility Condition Index:	0.32 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	3,189
Building Code:	R2900304940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,871
Building Name:	Banning SP Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$2,520
Facility Condition Index:	0.26 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900304950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,872
Building Name:	Banning SP Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$2,776
Facility Condition Index:	0.26 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	25
Building Code:	R2900304960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,153
Building Name:	Banning SP Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$3,393
Facility Condition Index:	0.33 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	25

Building Code:	R2900304970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,323
Building Name:	Banning SP Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$2,440
Facility Condition Index:	0.26 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	25
Building Code:	R2900305130	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$126,225
Building Name:	Banning SP Shop Area Cold Storage	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$50,971
Facility Condition Index:	0.40 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	1,259
Building Code:	R2900306580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,887
Building Name:	Banning SP CG Site 32 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$3,894
Facility Condition Index:	0.30 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	39
Building Code:	R2900306990	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$36,706
Building Name:	Banning SP CG Cabin	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$3,472
Facility Condition Index:	0.09 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	196
Building Code:	R2900307290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,142
Building Name:	Banning CG Sites 12/13 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$1,117
Facility Condition Index:	0.07 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	48
Building Code:	R2900307300	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,142
Building Name:	Banning SP CG Site 9 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$1,117
Facility Condition Index:	0.07 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	48
Building Code:	R2900308420	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,576
Building Name:	Banning SP CG Recycling Center	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$1,470
Facility Condition Index:	0.32 - Poor	**City Code:**	SANDSTONE	**Ext. Gross Area:**	49

Site: R290005 - Bear Head Lake State Park

Building Code:	R2900201460	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$277,752
Building Name:	Bear Head Lake SP Shop	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$57,821
Facility Condition Index:	0.21 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	1,441
Building Code:	R2900201480	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$26,513
Building Name:	Bear Head Lake SP Cold Storage	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,918
Facility Condition Index:	0.07 - Good	**City Code:**	ELY	**Ext. Gross Area:**	520
Building Code:	R2900201520	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$64,123
Building Name:	Bear Head Lk CG Fish Cleaning House	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$7,017
Facility Condition Index:	0.11 - Good	**City Code:**	ELY	**Ext. Gross Area:**	195
Building Code:	R2900201530	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$120,736
Building Name:	Bear Head Lake SP Sanitation	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$21,969
Facility Condition Index:	0.18 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	483

Building Code:	R2900201540	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$147,198
Building Name:	Bear Head Lake CG C-Loop Sanitation	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$32,604
Facility Condition Index:	0.22 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	506
Building Code:	R2900203830	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,984
Building Name:	Bear Head Lake SP Oil House	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$2,508
Facility Condition Index:	0.11 - Good	**City Code:**	ELY	**Ext. Gross Area:**	96
Building Code:	R2900204330	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$560,581
Building Name:	Bear Head Lake SP Lodging House	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$55,359
Facility Condition Index:	0.10 - Good	**City Code:**	ELY	**Ext. Gross Area:**	2,656
Building Code:	R2900205290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,927
Building Name:	Bear Head Lk Grp CG Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$4,628
Facility Condition Index:	0.36 - Poor	**City Code:**	ELY	**Ext. Gross Area:**	36
Building Code:	R2900205300	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,927
Building Name:	Bear Head Lk Grp CG Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$4,628
Facility Condition Index:	0.36 - Poor	**City Code:**	ELY	**Ext. Gross Area:**	36
Building Code:	R2900205310	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,927
Building Name:	Bear Head Lk CG A-Loop Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$3,295
Facility Condition Index:	0.25 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	36
Building Code:	R2900205320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,927
Building Name:	Bear Head Lk CG A-Loop Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$3,295
Facility Condition Index:	0.25 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	36
Building Code:	R2900205330	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,927
Building Name:	Bear Head Lk CG C-Loop Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$3,295
Facility Condition Index:	0.25 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	36
Building Code:	R2900205340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,011
Building Name:	Bear Head N Bay Boat Lnd Vault Toil	**Address:**	9301 Bear Head State Park Rd	**Deferred Maintenance:**	$2,070
Facility Condition Index:	0.16 - Fair	**City Code:**	Ely	**Ext. Gross Area:**	30
Building Code:	R2900206650	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$36,461
Building Name:	Bear Head Lake SP Garage	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$5,627
Facility Condition Index:	0.15 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	436
Building Code:	R2900207420	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$45,070
Building Name:	Bear Head Lake SP Picnic Shelter 2	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,434
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	832
Building Code:	R2900207430	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,016
Building Name:	Bear Head Lake SP Spring House	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$3,279
Facility Condition Index:	0.09 - Good	**City Code:**	ELY	**Ext. Gross Area:**	140

Building Code:	R2900207630	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$400,190
Building Name:	Bear Head Lake SP Contact Station	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$73,745
Facility Condition Index:	0.18 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	1,214
Building Code:	R2900207690	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$44,633
Building Name:	Bear Head Lk CG Camper Cabin	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$3,528
Facility Condition Index:	0.08 - Good	**City Code:**	ELY	**Ext. Gross Area:**	264
Building Code:	R2900207880	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$326,701
Building Name:	Bear Head Lake SP Sanitation	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$25,436
Facility Condition Index:	0.08 - Good	**City Code:**	ELY	**Ext. Gross Area:**	1,147
Building Code:	R2900208620	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,082
Building Name:	Bear Head Lake SP Cold Storage	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$593
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	120
Building Code:	R2900208780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,728
Building Name:	Bear Head Lk CG B-Loop Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,234
Facility Condition Index:	0.07 - Good	**City Code:**	ELY	**Ext. Gross Area:**	47
Building Code:	R2900208790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,728
Building Name:	Bear Head Lk CG B-Loop Vault Toilet	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,577
Facility Condition Index:	0.09 - Good	**City Code:**	ELY	**Ext. Gross Area:**	47
Building Code:	R2900208980	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$45,037
Building Name:	Bear Head Lk CG White Cedar Cabin	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,136
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	288
Building Code:	R2900208990	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$43,802
Building Name:	Bear Head Lk CG Camper Cabin	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,111
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	288
Building Code:	R2900209000	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$44,477
Building Name:	Bear Head Lk CG Red Pine Cabin	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,454
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	288
Building Code:	R2900209010	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$45,037
Building Name:	Bear Head Lk CG Quaking Aspen Cabin	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,466
Facility Condition Index:	0.03 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	288
Building Code:	R2900209270	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$463,920
Building Name:	Bear Head Lake SP Trails Center	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$10,627
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	1,685
Building Code:	R2900210510	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$55,437
Building Name:	Bear Head Lk CG Cabin Loop Vault	**Address:**	9301 BEAR HEAD STATE PARK R	**Deferred Maintenance:**	$1,109
Facility Condition Index:	0.02 - Excellent	**City Code:**	ELY	**Ext. Gross Area:**	48

Site: R290006 - Beaver Creek Valley State Park

Building Code:	R2900500720	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$43,964
Building Name:	BCV SP Picnic Area Sanitation	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$10,272
Facility Condition Index:	0.23 - Fair	**City Code:**	CALEDONIA	**Ext. Gross Area:**	317
Building Code:	R2900500730	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$218,751
Building Name:	BCV SP Picnic Area Recreation Hall	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$24,540
Facility Condition Index:	0.11 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	1,639
Building Code:	R2900500740	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$152,099
Building Name:	BCV SP Drive-In CG Sanitation	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$50,795
Facility Condition Index:	0.33 - Poor	**City Code:**	CALEDONIA	**Ext. Gross Area:**	554
Building Code:	R2900500750	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$519,469
Building Name:	Beaver Creek Valley SP Contact Sta	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$103,567
Facility Condition Index:	0.20 - Fair	**City Code:**	CALEDONIA	**Ext. Gross Area:**	2,468
Building Code:	R2900500760	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$225,125
Building Name:	Beaver Creek Valley SP Shop	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$16,904
Facility Condition Index:	0.08 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	1,529
Building Code:	R2900502590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,772
Building Name:	Beaver Creek Valley SP Vault Toilet	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$5,563
Facility Condition Index:	0.26 - Fair	**City Code:**	CALEDONIA	**Ext. Gross Area:**	64
Building Code:	R2900503050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,772
Building Name:	Beaver Creek Valley SP Vault Toilet	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$4,355
Facility Condition Index:	0.20 - Fair	**City Code:**	CALEDONIA	**Ext. Gross Area:**	64
Building Code:	R2900503060	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,772
Building Name:	Beaver Creek Valley SP Vault Toilet	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$9,471
Facility Condition Index:	0.44 - Poor	**City Code:**	CALEDONIA	**Ext. Gross Area:**	64
Building Code:	R2900504780	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$71,890
Building Name:	Beaver Creek Valley SP Cabin	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$4,227
Facility Condition Index:	0.06 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	314
Building Code:	R2900505030	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,191
Building Name:	Beaver Creek Valley SP Shed	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$4,294
Facility Condition Index:	0.47 - Poor	**City Code:**	CALEDONIA	**Ext. Gross Area:**	100
Building Code:	R2900505040	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,772
Building Name:	Beaver Creek Valley SP Vault Toilet	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$1,613
Facility Condition Index:	0.07 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	64

Site: R290007 - Big Bog SRA

Building Code:	R2900100510	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,661
Building Name:	Big Bog SRA South Unit Pump House	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$569
Facility Condition Index:	0.12 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	16
Building Code:	R2900103810	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$365,802
Building Name:	Big Bog SRA South Unit Shop	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$58,248
Facility Condition Index:	0.16 - Fair	**City Code:**	WASKISH	**Ext. Gross Area:**	1,866
Building Code:	R2900106600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,539
Building Name:	Big Bog SRA South Old Lakesde Vault	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$2,690
Facility Condition Index:	0.26 - Fair	**City Code:**	WASKISH	**Ext. Gross Area:**	30
Building Code:	R2900106610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,265
Building Name:	Big Bog SRA South Changing House	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$1,283
Facility Condition Index:	0.30 - Poor	**City Code:**	WASKISH	**Ext. Gross Area:**	40
Building Code:	R2900107690	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$311,152
Building Name:	Big Bog SRA South Unit Sanitation	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$30,462
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	902
Building Code:	R2900107700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$27,398
Building Name:	Big Bog SRA South Fish Cleaning Hse	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$2,740
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	345
Building Code:	R2900107710	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$74,074
Building Name:	Big Bog SRA South Picnic Shelter 2	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$7,407
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	825
Building Code:	R2900107740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,010
Building Name:	Big Bog SRA South Campground Vault	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$1,701
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	48
Building Code:	R2900107750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,010
Building Name:	Big Bog SRA South New Lakesde Vault	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$1,701
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	48
Building Code:	R2900107790	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$42,379
Building Name:	Big Bog SRA South Unit Pump House	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$4,238
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	128
Building Code:	R2900108020	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,120
Building Name:	Big Bog SRA South Cabin 2 Vault	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$1,712
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	48
Building Code:	R2900108030	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$36,355
Building Name:	Big Bog SRA North Unit Vault Toilet	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$3,636
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	102

Building Code:	R2900108040	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$60,919
Building Name:	Big Bog SRA South Camper Cabin 1	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$5,163
Facility Condition Index:	0.08 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	264
Building Code:	R2900108050	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$70,940
Building Name:	Big Bog SRA South Camper Cabin 2	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$6,165
Facility Condition Index:	0.09 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	264
Building Code:	R2900108060	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$70,940
Building Name:	Big Bog SRA South Camper Cabin 3	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$6,165
Facility Condition Index:	0.09 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	264
Building Code:	R2900108070	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,185
Building Name:	Big Bog SRA South Camper Cabin 4	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$4,789
Facility Condition Index:	0.08 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	264
Building Code:	R2900108080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$70,940
Building Name:	Big Bog SRA South Camper Cabin 5	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$6,165
Facility Condition Index:	0.09 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	264
Building Code:	R2900108090	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$68,956
Building Name:	Big Bog SRA North Picnic Shelter 2	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$6,896
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	768
Building Code:	R2900108290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,120
Building Name:	Big Bog SRA South Cabin Vault	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$1,712
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	48
Building Code:	R2900108650	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$914,708
Building Name:	Big Bog SRA South Contact Station	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$115,783
Facility Condition Index:	0.13 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	3,037
Building Code:	R2900108770	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$1,082
Building Name:	Big Bog SRA North Interp Unoccupied	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$108
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	25
Building Code:	R2900108790	**Cost Model Name:**	Tower	**Current Replacement Value:**	$18,700
Building Name:	Big Bog SRA South Unit Fire Tower	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$1,870
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	49
Building Code:	R2900207790	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$47,320
Building Name:	Big Bog SRA Camper Cabin 6	**Address:**	55716 HWY 72 NE	**Deferred Maintenance:**	$4,732
Facility Condition Index:	0.10 - Good	**City Code:**	WASKISH	**Ext. Gross Area:**	336

Site: R290008 - Big Stone Lake State Park

Building Code:	R2900401680	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,789,739
Building Name:	Big Stone Lake SP Bonanza Ed Ctr	**Address:**	31167 Big Stone Lake Park Road	**Deferred Maintenance:**	$470,361
Facility Condition Index:	0.26 - Fair	**City Code:**	CLINTON	**Ext. Gross Area:**	4,971
Building Code:	R2900401700	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$373,797
Building Name:	Big Stone Lake SP Contact Sta	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$77,065
Facility Condition Index:	0.21 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	1,588
Building Code:	R2900401710	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$85,824
Building Name:	Big Stone Lake SP Shop	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$19,450
Facility Condition Index:	0.23 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	768
Building Code:	R2900401720	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$75,439
Building Name:	Big Stone Lake SP Cold Storage	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$14,958
Facility Condition Index:	0.20 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	900
Building Code:	R2900403260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,470
Building Name:	BSL SP Meadowbrook Upr Vault Toilet	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$3,050
Facility Condition Index:	0.24 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	32
Building Code:	R2900403270	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,543
Building Name:	BSL SP Meadowbrook Low Vault Toilet	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$2,957
Facility Condition Index:	0.26 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	32
Building Code:	R2900404070	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$373,569
Building Name:	BSL SP Meadowbrook Sanitation	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$100,654
Facility Condition Index:	0.27 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	933
Building Code:	R2900404770	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,101
Building Name:	Big Stone Lake SP Bonanza Vault	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$1,422
Facility Condition Index:	0.07 - Good	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	48
Building Code:	R2900404780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$19,951
Building Name:	Big Stone Lake SP Bonanza Vault	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$2,479
Facility Condition Index:	0.12 - Good	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	48
Building Code:	R2900404840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,790
Building Name:	BSL SP Meadowbrook Pump House	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$5,411
Facility Condition Index:	0.46 - Poor	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	38
Building Code:	R2900404850	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$24,590
Building Name:	Big Stone Lake SP Shed	**Address:**	35889 MEADOWBROOK STATE P/	**Deferred Maintenance:**	$4,869
Facility Condition Index:	0.20 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	123
Building Code:	R2900405800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$37,823
Building Name:	BSL SP Meadowbrook Concrete Vault	**Address:**	35889 Meadowbrook State Park	**Deferred Maintenance:**	$910
Facility Condition Index:	0.02 - Excellent	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	47

Site: R290009 - Blue Mounds State Park

Building Code:	R2900400680	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$428,385
Building Name:	Blue Mounds SP HQ Contact Station	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$69,012
Facility Condition Index:	0.16 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	1,216
Building Code:	R2900400690	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$76,159
Building Name:	Blue Mounds SP HQ Residence Garage	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$25,132
Facility Condition Index:	0.33 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	768
Building Code:	R2900400700	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$171,278
Building Name:	Blue Mounds SP HQ Open Shed	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$43,507
Facility Condition Index:	0.25 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	2,808
Building Code:	R2900400710	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$729,648
Building Name:	Blue Mounds SP Interp Center	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$291,630
Facility Condition Index:	0.40 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	3,916
Building Code:	R2900400730	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$99,773
Building Name:	Blue Mounds SP Picnic Shelter 2	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$32,925
Facility Condition Index:	0.33 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	576
Building Code:	R2900400740	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$93,736
Building Name:	Blue Mounds SP HQ Cold Storage	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$34,576
Facility Condition Index:	0.37 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	1,160
Building Code:	R2900400750	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$610,069
Building Name:	Blue Mounds SP Residence	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$240,585
Facility Condition Index:	0.39 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	2,959
Building Code:	R2900400770	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$205,376
Building Name:	Blue Mounds SP Sanitation	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$67,774
Facility Condition Index:	0.33 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	596
Building Code:	R2900400780	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$301,579
Building Name:	Blue Mounds SP HQ Shop	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$79,286
Facility Condition Index:	0.26 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	1,500
Building Code:	R2900402690	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$195,489
Building Name:	Blue Mounds SP CG Sanitation	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$58,885
Facility Condition Index:	0.30 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	658
Building Code:	R2900403340	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,696
Building Name:	Blue Mounds SP HQ Oil House	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$2,210
Facility Condition Index:	0.33 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	68

Building Code:	R2900403830	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,219
Building Name:	Blue Mounds SP HQ Granary Storage	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$1,888
Facility Condition Index:	0.18 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	67
Building Code:	R2900404180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,919
Building Name:	Blue Mounds Group CG Vault Toilet	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$2,289
Facility Condition Index:	0.26 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	36
Building Code:	R2900404190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,919
Building Name:	Blue Mounds Group CG Vault Toilet	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$2,338
Facility Condition Index:	0.26 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	36
Building Code:	R2900404200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,919
Building Name:	Blue Mounds SP CG Vault Toilet	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$2,289
Facility Condition Index:	0.26 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	38
Building Code:	R2900404290	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,822
Building Name:	Blue Mounds SP Pump House	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$10,566
Facility Condition Index:	0.44 - Poor	**City Code:**	LUVERNE	**Ext. Gross Area:**	80
Building Code:	R2900404400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,388
Building Name:	Blue Mounds SP CG Vault Toilet	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$4,115
Facility Condition Index:	0.24 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	38
Building Code:	R2900404720	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$433,078
Building Name:	Blue Mounds SP CG Sanitation	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$10,446
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUVERNE	**Ext. Gross Area:**	1,113
Building Code:	R2900405020	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,752
Building Name:	Blue Mounds SP HQ Firewood Shed	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$1,642
Facility Condition Index:	0.29 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	49
Building Code:	R2900405070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,919
Building Name:	Blue Mounds SP Vault Toilet	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$2,149
Facility Condition Index:	0.24 - Fair	**City Code:**	LUVERNE	**Ext. Gross Area:**	24
Building Code:	R2900405440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,661
Building Name:	Blue Mounds Beach Vault Concrete	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$374
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUVERNE	**Ext. Gross Area:**	40
Building Code:	R2900405450	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$11,547
Building Name:	Blue Mounds SP CG Tipi	**Address:**	1410 161ST ST	**Deferred Maintenance:**	$1,155
Facility Condition Index:	0.10 - Good	**City Code:**	LUVERNE	**Ext. Gross Area:**	174

Site: R290010 - Buffalo River State Park

Building Code:	R2900103150	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$247,351
Building Name:	Buffalo River SP Trails Center	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$40,605
Facility Condition Index:	0.16 - Fair	**City Code:**	GLYNDON	**Ext. Gross Area:**	795
Building Code:	R2900103160	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$629,772
Building Name:	Buffalo River SP Priarie Vw CG San	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$321,239
Facility Condition Index:	0.51 - Crisis	**City Code:**	GLYNDON	**Ext. Gross Area:**	1,283
Building Code:	R2900103170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$124,562
Building Name:	Buffalo River PraV CG Hist San Bldg	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$57,268
Facility Condition Index:	0.46 - Poor	**City Code:**	GLYNDON	**Ext. Gross Area:**	576
Building Code:	R2900103180	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$585,135
Building Name:	Buffalo River SP Beach Area San	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$89,393
Facility Condition Index:	0.15 - Fair	**City Code:**	GLYNDON	**Ext. Gross Area:**	1,165
Building Code:	R2900103190	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$50,294
Building Name:	Buffalo Riv Prairie Vw CG Pumphouse	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$5,360
Facility Condition Index:	0.11 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	141
Building Code:	R2900103200	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$216,335
Building Name:	Buffalo River SP Shop	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$32,412
Facility Condition Index:	0.15 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	1,531
Building Code:	R2900103210	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$74,964
Building Name:	Buffalo River SP Residence Garage	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$7,715
Facility Condition Index:	0.10 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	720
Building Code:	R2900103220	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$444,435
Building Name:	Buffalo River SP Residence	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$87,728
Facility Condition Index:	0.20 - Fair	**City Code:**	GLYNDON	**Ext. Gross Area:**	408
Building Code:	R2900105370	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$150,598
Building Name:	Buffalo Riv Beach Ar Picnic Shel 2	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$21,833
Facility Condition Index:	0.14 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	617
Building Code:	R2900105870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,556
Building Name:	Buffalo River Picnic Ar Mens Vault	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$1,650
Facility Condition Index:	0.16 - Fair	**City Code:**	GLYNDON	**Ext. Gross Area:**	31
Building Code:	R2900105880	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,556
Building Name:	Buffalo River Picnic Ar Wmns Vault	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$1,650
Facility Condition Index:	0.16 - Fair	**City Code:**	GLYNDON	**Ext. Gross Area:**	31
Building Code:	R2900106380	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$244,221
Building Name:	Buffalo River SP Contact Sta	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$18,086
Facility Condition Index:	0.07 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	1,043

Building Code:	R2900106700	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,356
Building Name:	Buffalo River Prairie Vw CG Vault	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$1,768
Facility Condition Index:	0.12 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	43
Building Code:	R2900106710	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,391
Building Name:	Buffalo River SP Pioneer Camp Vault	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$1,921
Facility Condition Index:	0.13 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	42
Building Code:	R2900107870	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$152,242
Building Name:	Buffalo River SP Pool Water Trtmnt	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$21,162
Facility Condition Index:	0.14 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	1,800
Building Code:	R2900107890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,739
Building Name:	Buffalo River SP Group Camp Vault	**Address:**	565 155TH ST S, HWY 10	**Deferred Maintenance:**	$2,165
Facility Condition Index:	0.13 - Good	**City Code:**	GLYNDON	**Ext. Gross Area:**	48
Building Code:	R2900109580	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$423,716
Building Name:	Buffalo River SP Prairie Vw CG San	**Address:**	656 155TH ST S, HWY 10	**Deferred Maintenance:**	$8,474
Facility Condition Index:	0.02 - Excellent	**City Code:**	GLYNDON	**Ext. Gross Area:**	1,316

Site: R290011 - Camden State Park

Building Code:	R2900401470	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$165,281
Building Name:	Camden SP Picnic Shelter 2	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$53,743
Facility Condition Index:	0.33 - Poor	**City Code:**	LYND	**Ext. Gross Area:**	1,440
Building Code:	R2900401510	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$908,407
Building Name:	Camden SP Bath House	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$299,774
Facility Condition Index:	0.33 - Poor	**City Code:**	LYND	**Ext. Gross Area:**	2,068
Building Code:	R2900401530	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$214,341
Building Name:	Camden Lower Picnic Area Sanitation	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$67,769
Facility Condition Index:	0.32 - Poor	**City Code:**	LYND	**Ext. Gross Area:**	435
Building Code:	R2900401540	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$186,684
Building Name:	Camden SP Group CG Picnic Shelter 2	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$57,491
Facility Condition Index:	0.31 - Poor	**City Code:**	LYND	**Ext. Gross Area:**	1,032
Building Code:	R2900401570	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$200,603
Building Name:	Camden Lower Residence Cold Storage	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$24,042
Facility Condition Index:	0.12 - Good	**City Code:**	LYND	**Ext. Gross Area:**	880
Building Code:	R2900401590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$361,208
Building Name:	Camden SP Old Residence Garage	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$32,956
Facility Condition Index:	0.09 - Good	**City Code:**	LYND	**Ext. Gross Area:**	1,526

Building Code:	R2900401600	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$610,636
Building Name:	Camden SP Redwood Lodge	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$59,156
Facility Condition Index:	0.10 - Good	**City Code:**	LYND	**Ext. Gross Area:**	1,636
Building Code:	R2900402610	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$578,113
Building Name:	Camden SP Upper CG Residence	**Address:**	1895 CAMDEN PARK RD	**Deferred Maintenance:**	$171,301
Facility Condition Index:	0.30 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	1,632
Building Code:	R2900402620	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$344,456
Building Name:	Camden SP Shop	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$81,868
Facility Condition Index:	0.24 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	1,800
Building Code:	R2900402630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$244,041
Building Name:	Camden SP Cold Storage	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$48,875
Facility Condition Index:	0.20 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	1,920
Building Code:	R2900402640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$87,277
Building Name:	Camden SP Upper Residence Garage	**Address:**	1895 CAMDEN PARK RD	**Deferred Maintenance:**	$26,525
Facility Condition Index:	0.30 - Poor	**City Code:**	LYND	**Ext. Gross Area:**	720
Building Code:	R2900402650	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$448,965
Building Name:	Camden SP Contact Station	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$30,003
Facility Condition Index:	0.07 - Good	**City Code:**	LYND	**Ext. Gross Area:**	1,308
Building Code:	R2900402660	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,923
Building Name:	Camden SP Oil House	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$6,427
Facility Condition Index:	0.25 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	120
Building Code:	R2900402890	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$122,901
Building Name:	Camden SP Group CG Sanitation	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$45,965
Facility Condition Index:	0.37 - Poor	**City Code:**	LYND	**Ext. Gross Area:**	432
Building Code:	R2900403030	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$413,295
Building Name:	Camden SP Upper CG Sanitation	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$108,889
Facility Condition Index:	0.26 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	1,200
Building Code:	R2900403440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,442
Building Name:	Camden SP Horse CG W Vault Toilet	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$2,842
Facility Condition Index:	0.25 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	24
Building Code:	R2900403450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,504
Building Name:	Camden SP Horse CG M Vault Toilet	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$2,862
Facility Condition Index:	0.25 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	24
Building Code:	R2900403460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,773
Building Name:	Camden SP Picnic Area Vault Toilet	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$2,951
Facility Condition Index:	0.25 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	24

Building Code:	R2900403470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,773
Building Name:	Camden SP Picnic Area Vault Toilet	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$2,951
Facility Condition Index:	0.25 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	24
Building Code:	R2900404080	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$341,863
Building Name:	Camden SP Lower CG Sanitation	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$93,068
Facility Condition Index:	0.27 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	916
Building Code:	R2900404510	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,359
Building Name:	Camden SP Brawner Lake Vault Toilet	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$5,806
Facility Condition Index:	0.26 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	64
Building Code:	R2900404960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Camden SP Lower CG Vault Toilet	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$3,416
Facility Condition Index:	0.20 - Fair	**City Code:**	LYND	**Ext. Gross Area:**	47
Building Code:	R2900405290	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$46,017
Building Name:	Camden SP Wood Shed	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$4,602
Facility Condition Index:	0.10 - Good	**City Code:**	LYND	**Ext. Gross Area:**	140
Building Code:	R2900405490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,534
Building Name:	Camden SP Upper CG Vault Concrete	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$689
Facility Condition Index:	0.05 - Good	**City Code:**	LYND	**Ext. Gross Area:**	81
Building Code:	R2900405500	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,534
Building Name:	Camden SP Upper CG Vault Concrete	**Address:**	1897 CAMDEN PARK RD	**Deferred Maintenance:**	$785
Facility Condition Index:	0.06 - Good	**City Code:**	LYND	**Ext. Gross Area:**	81

Site: R290012 - Cascade River State Park

Building Code:	R2900201250	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$383,869
Building Name:	Cascade River SP Shop	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$71,175
Facility Condition Index:	0.19 - Fair	**City Code:**	LUTSEN	**Ext. Gross Area:**	1,523
Building Code:	R2900201260	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,969
Building Name:	Cascade SP Shop Area Cold Storage	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$4,870
Facility Condition Index:	0.30 - Poor	**City Code:**	LUTSEN	**Ext. Gross Area:**	103
Building Code:	R2900201290	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$51,717
Building Name:	Cascade Shop Area Firewood Storage	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$7,557
Facility Condition Index:	0.15 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	538
Building Code:	R2900201310	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$195,631
Building Name:	Cascade Riv SP CG Picnic Shelter 2	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$20,620
Facility Condition Index:	0.11 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	780

Building Code:	R2900201340	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$71,361
Building Name:	Cascade River SP CG Spring House	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$18,794
Facility Condition Index:	0.26 - Fair	**City Code:**	LUTSEN	**Ext. Gross Area:**	168
Building Code:	R2900204250	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,034
Building Name:	Cascade SP Shop Area Oil House	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$1,503
Facility Condition Index:	0.10 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	102
Building Code:	R2900204380	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$214,747
Building Name:	Cascade River SP Office	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$22,505
Facility Condition Index:	0.10 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	960
Building Code:	R2900205380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,179
Building Name:	Cascade Riv SP Grp CG Vault Toilet	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$2,533
Facility Condition Index:	0.21 - Fair	**City Code:**	LUTSEN	**Ext. Gross Area:**	33
Building Code:	R2900205390	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,258
Building Name:	Cascade River SP CG Vault Toilet	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$2,427
Facility Condition Index:	0.17 - Fair	**City Code:**	LUTSEN	**Ext. Gross Area:**	30
Building Code:	R2900205400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,258
Building Name:	Cascade River SP CG Vault Toilet	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$2,427
Facility Condition Index:	0.17 - Fair	**City Code:**	LUTSEN	**Ext. Gross Area:**	31
Building Code:	R2900207460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,513
Building Name:	Cascade SP Picnic Area Vault Toilet	**Address:**	3550 W HWY 61	**Deferred Maintenance:**	$3,715
Facility Condition Index:	0.26 - Fair	**City Code:**	LUTSEN	**Ext. Gross Area:**	31
Building Code:	R2900208660	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,747
Building Name:	Cascade Riv SP HQ Area Vault Toilet	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$1,383
Facility Condition Index:	0.07 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	47
Building Code:	R2900208670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,747
Building Name:	Cascade Riv SP CG B/C Vault Toilet	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$1,383
Facility Condition Index:	0.07 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	50
Building Code:	R2900208680	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,747
Building Name:	Cascade River SP CG Vault Toilet	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$1,383
Facility Condition Index:	0.07 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	49
Building Code:	R2900208830	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$101,445
Building Name:	Cascade River SP Cold Storage	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$11,331
Facility Condition Index:	0.11 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	1,020
Building Code:	R2900208840	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$316,489
Building Name:	Cascade River SP Dormitory	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$37,673
Facility Condition Index:	0.12 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	1,740

Building Code:	R2900210020	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$13,415
Building Name:	Cascade River SP BP01 Adirondack	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$474
Facility Condition Index:	0.04 - Excellent	**City Code:**	LUTSEN	**Ext. Gross Area:**	65
Building Code:	R2900210030	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$1,742
Building Name:	Cascade River SP BP01 Pit Toilet	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$35
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUTSEN	**Ext. Gross Area:**	16
Building Code:	R2900210040	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,527
Building Name:	Cascade River SP BP02 Adirondack	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$881
Facility Condition Index:	0.09 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	80
Building Code:	R2900210050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$1,742
Building Name:	Cascade River SP BP02 Pit Toilet	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$35
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUTSEN	**Ext. Gross Area:**	16
Building Code:	R2900210060	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,527
Building Name:	Cascade River SP BP03 Adirondack	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$846
Facility Condition Index:	0.09 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	80
Building Code:	R2900210070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$1,742
Building Name:	Cascade River SP BP03 Pit Toilet	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$35
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUTSEN	**Ext. Gross Area:**	16
Building Code:	R2900210080	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,090
Building Name:	Cascade River SP BP04 Adirondack	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$912
Facility Condition Index:	0.09 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	90
Building Code:	R2900210090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$1,742
Building Name:	Cascade River SP BP04 Pit Toilet	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$35
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUTSEN	**Ext. Gross Area:**	16
Building Code:	R2900210100	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,731
Building Name:	Cascade River SP BP05 Adirondack	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$755
Facility Condition Index:	0.08 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	110
Building Code:	R2900210110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$1,742
Building Name:	Cascade River SP BP05 Pit Toilet	**Address:**	3997 W HWY 61	**Deferred Maintenance:**	$35
Facility Condition Index:	0.02 - Excellent	**City Code:**	LUTSEN	**Ext. Gross Area:**	16
Building Code:	R2900210470	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$388,015
Building Name:	Cascade River SP CG Sanitation	**Address:**	3481 W HWY 61	**Deferred Maintenance:**	$20,244
Facility Condition Index:	0.05 - Good	**City Code:**	LUTSEN	**Ext. Gross Area:**	1,200

Site: R290013 - Charles A Lindbergh State Park

Building Code:	R2900301020	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$163,008
Building Name:	CA Lindbergh SP Contact Station	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$21,158
Facility Condition Index:	0.13 - Good	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	793
Building Code:	R2900301030	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$124,159
Building Name:	CA Lindbergh SP Tenant Farmhouse	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$124,159
Facility Condition Index:	1.00 - Crisis	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	1,036
Building Code:	R2900301040	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$49,959
Building Name:	CA Lindbergh SP Garage	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$20,323
Facility Condition Index:	0.41 - Poor	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	660
Building Code:	R2900301050	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$281,150
Building Name:	CA Lindbergh SP Picnic Area Shel 2	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$58,636
Facility Condition Index:	0.21 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	1,278
Building Code:	R2900301060	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$202,637
Building Name:	CA Lindbergh SP Pic Ar Pumphouse	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$72,126
Facility Condition Index:	0.36 - Poor	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	448
Building Code:	R2900301070	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$149,902
Building Name:	CA Lindbergh SP CG Sanitation	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$22,988
Facility Condition Index:	0.15 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	678
Building Code:	R2900301080	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$140,578
Building Name:	CA Lindbergh SP Picnic Area San	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$33,640
Facility Condition Index:	0.24 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	336
Building Code:	R2900303770	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$47,001
Building Name:	CA Lindbergh SP Cold Storage	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$19,139
Facility Condition Index:	0.41 - Poor	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	248
Building Code:	R2900304120	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$292,577
Building Name:	CA Lindbergh SP Shop	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$72,711
Facility Condition Index:	0.25 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	1,800
Building Code:	R2900304220	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,805
Building Name:	CA Lindbergh SP Oil House	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$1,080
Facility Condition Index:	0.10 - Good	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	104
Building Code:	R2900304750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,295
Building Name:	CA Lindbergh Picnic Area Wms Vault	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$2,508
Facility Condition Index:	0.27 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	34
Building Code:	R2900304760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,447
Building Name:	CA Lindbergh SP CG Vault Toilet	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$2,664
Facility Condition Index:	0.26 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	34

Building Code:	R2900306730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,887
Building Name:	CA Lindbergh Group CG Vault Toilet	**Address:**	1615 LINDBERGH DR S	**Deferred Maintenance:**	$1,939
Facility Condition Index:	0.15 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	41
Building Code:	R2900306980	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,786
Building Name:	CA Lindbergh SP Cold Storage	**Address:**	17912 GROUSE RD	**Deferred Maintenance:**	$8,249
Facility Condition Index:	0.15 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	960

Site: R290014 - Crow Wing State Park

Building Code:	R2900300860	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$40,829
Building Name:	Crow Wing SP Grp CG Picnic Sheltr 2	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$3,590
Facility Condition Index:	0.09 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	320
Building Code:	R2900300870	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$479,734
Building Name:	Crow Wing SP S Picnic Area San Bldg	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$90,712
Facility Condition Index:	0.19 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,488
Building Code:	R2900300880	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$244,541
Building Name:	Crow Wing SP CG Sanitation	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$59,889
Facility Condition Index:	0.24 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	640
Building Code:	R2900300890	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$452,186
Building Name:	Crow Wing SP Residence	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$129,428
Facility Condition Index:	0.29 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	2,546
Building Code:	R2900300900	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$102,859
Building Name:	Crow Wing SP HQ Area Cold Storage	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$46,626
Facility Condition Index:	0.45 - Poor	**City Code:**	BRAINERD	**Ext. Gross Area:**	968
Building Code:	R2900300910	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$320,630
Building Name:	Crow Wing SP Shop	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$67,236
Facility Condition Index:	0.21 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,920
Building Code:	R2900300920	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$99,127
Building Name:	Crow Wing SP HQ Area Office	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$20,082
Facility Condition Index:	0.20 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	526
Building Code:	R2900300930	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$195,649
Building Name:	Crow Wing SP HQ Area Cold Storage	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$95,030
Facility Condition Index:	0.49 - Poor	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,070
Building Code:	R2900303590	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,490
Building Name:	Crow Wing SP Shop Area Oil House	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$875
Facility Condition Index:	0.07 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	96

Building Code:	R2900304590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,913
Building Name:	Crow Wing SP CG Mens A-Loop Vault	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$3,271
Facility Condition Index:	0.33 - Poor	**City Code:**	BRAINERD	**Ext. Gross Area:**	28
Building Code:	R2900304600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,913
Building Name:	Crow Wing SP CG Womens A-Loop Vault	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$3,843
Facility Condition Index:	0.39 - Poor	**City Code:**	BRAINERD	**Ext. Gross Area:**	28
Building Code:	R2900305140	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,255
Building Name:	Crow Wing SP Group CG Vault Toilet	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$1,994
Facility Condition Index:	0.15 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	40
Building Code:	R2900305170	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$207,226
Building Name:	Crow Wing SP Interp Center	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$46,622
Facility Condition Index:	0.22 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,440
Building Code:	R2900306800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,396
Building Name:	Crow Wing SP CG C Vault Toilet	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$2,036
Facility Condition Index:	0.15 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	40
Building Code:	R2900306810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,396
Building Name:	Crow Wing SP N Picnic Ar Vault Toil	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$1,736
Facility Condition Index:	0.13 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	40
Building Code:	R2900306820	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$45,340
Building Name:	Crow Wing SP CG Cabin	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$8,809
Facility Condition Index:	0.19 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	264
Building Code:	R2900307110	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$108,308
Building Name:	Crow Wing SP Cold Storage	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$9,903
Facility Condition Index:	0.09 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,154
Building Code:	R2900307270	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,575
Building Name:	Crow Wing SP S Picnic Ar Vault Toil	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$1,149
Facility Condition Index:	0.07 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	47
Building Code:	R2900307370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,919
Building Name:	Crow Wing SP CG Spring House	**Address:**	3124 STATE PARK RD	**Deferred Maintenance:**	$321
Facility Condition Index:	0.07 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	36

Site: R290015 - Cuyuna Country SRA

Building Code:	R2900209040	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$255,387
Building Name:	Cuyuna Portsmouth CG Sanitation	**Address:**	307 3RD ST	**Deferred Maintenance:**	$152,676
Facility Condition Index:	0.60 - Crisis	**City Code:**	IRONTON	**Ext. Gross Area:**	864

Building Code:	R2900209340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$26,079
Building Name:	Cuyuna Portsmouth M Vault Concrete	**Address:**	17951 COUNTY RD 30	**Deferred Maintenance:**	$522
Facility Condition Index:	0.02 - Excellent	**City Code:**	CROSBY	**Ext. Gross Area:**	48
Building Code:	R2900209350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$26,079
Building Name:	Cuyuna Pennington M Vault Concrete	**Address:**	19406 NORTH RD	**Deferred Maintenance:**	$522
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	48
Building Code:	R2900209360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$26,079
Building Name:	Cuyuna Sagamore Mine Vault Concrete	**Address:**	20141 SAGAMORE RD	**Deferred Maintenance:**	$522
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	48
Building Code:	R2900209370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,694
Building Name:	Cuyuna Croft Mine Site Cold Storage	**Address:**	307 3RD ST	**Deferred Maintenance:**	$9,694
Facility Condition Index:	1.00 - Crisis	**City Code:**	IRONTON	**Ext. Gross Area:**	96
Building Code:	R2900209380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,157
Building Name:	Cuyuna Croft Mine Vault Concrete	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,043
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	96
Building Code:	R2900209950	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$60,866
Building Name:	Cuyuna Yawkey Mine Lake Yurt 1	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,217
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	314
Building Code:	R2900209960	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,312
Building Name:	Cuyuna Yawkey Mine Lake Picnic 1	**Address:**	307 3RD ST	**Deferred Maintenance:**	$346
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	144
Building Code:	R2900209970	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$60,866
Building Name:	Cuyuna Yawkey Mine Lake Yurt 2	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,217
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	314
Building Code:	R2900209980	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,312
Building Name:	Cuyuna Yawkey Mine Lake Picnic 2	**Address:**	307 3RD ST	**Deferred Maintenance:**	$346
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	144
Building Code:	R2900209990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$55,417
Building Name:	Cuyuna Yawkey Mine Vault Concrete	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,108
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	120
Building Code:	R2900210000	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$60,866
Building Name:	Cuyuna Yawkey Mine Lake Yurt 3	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,217
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	314
Building Code:	R2900210010	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,312
Building Name:	Cuyuna Yawkey Mine Lake Picnic 3	**Address:**	307 3RD ST	**Deferred Maintenance:**	$346
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	144

Building Code:	R2900210290	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$41,781
Building Name:	Cuyuna Huntington Water Treatment	**Address:**		**Deferred Maintenance:**	$1,072
Facility Condition Index:	0.03 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	192
Building Code:	R2900210300	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$71,003
Building Name:	Cuyuna Huntington Picnic Shelter 1	**Address:**		**Deferred Maintenance:**	$4,912
Facility Condition Index:	0.07 - Good	**City Code:**	IRONTON	**Ext. Gross Area:**	600
Building Code:	R2900210310	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,709
Building Name:	Cuyuna Huntington Vault Concrete	**Address:**		**Deferred Maintenance:**	$554
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	102
Building Code:	R2900210320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,709
Building Name:	Cuyuna Country SRA Vault Concrete	**Address:**		**Deferred Maintenance:**	$554
Facility Condition Index:	0.02 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	102
Building Code:	R2900306060	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$259,399
Building Name:	Cuyuna Country SRA Office	**Address:**	307 3RD ST	**Deferred Maintenance:**	$51,028
Facility Condition Index:	0.20 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	1,568
Building Code:	R2900306430	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$198,166
Building Name:	Cuyuna Croft Mine Site Sanitation	**Address:**	307 3RD ST	**Deferred Maintenance:**	$13,345
Facility Condition Index:	0.07 - Good	**City Code:**	IRONTON	**Ext. Gross Area:**	624
Building Code:	R2900306440	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$7,374
Building Name:	Cuyuna Croft Mine Site Concession	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,142
Facility Condition Index:	0.15 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	101
Building Code:	R2900306450	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$55,395
Building Name:	Cuyuna Croft M Cuyler Adam's Office	**Address:**	307 3RD ST	**Deferred Maintenance:**	$13,132
Facility Condition Index:	0.24 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	508
Building Code:	R2900306460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$31,812
Building Name:	Cuyuna Croft Mine Site Vault Toilet	**Address:**	307 3RD ST	**Deferred Maintenance:**	$8,097
Facility Condition Index:	0.25 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	96
Building Code:	R2900306470	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$60,357
Building Name:	Cuyuna Croft Mine Site Crosby House	**Address:**	307 3RD ST	**Deferred Maintenance:**	$26,105
Facility Condition Index:	0.43 - Poor	**City Code:**	IRONTON	**Ext. Gross Area:**	576
Building Code:	R2900306480	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$12,411
Building Name:	Cuyuna Croft M Martinetto Residence	**Address:**	307 3RD ST	**Deferred Maintenance:**	$8,499
Facility Condition Index:	0.68 - Crisis	**City Code:**	IRONTON	**Ext. Gross Area:**	144
Building Code:	R2900306490	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$32,927
Building Name:	Cuyuna Croft Mine SIte Office	**Address:**	307 3RD ST	**Deferred Maintenance:**	$2,841
Facility Condition Index:	0.09 - Good	**City Code:**	IRONTON	**Ext. Gross Area:**	240

Building Code:	R2900306500	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$88,384
Building Name:	Cuyuna Croft Mine Interp Occupied	**Address:**	307 3RD ST	**Deferred Maintenance:**	$2,341
Facility Condition Index:	0.03 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	713
Building Code:	R2900306510	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$593,636
Building Name:	Cuyuna Croft Mine Interp Occupied	**Address:**	307 3RD ST	**Deferred Maintenance:**	$26,431
Facility Condition Index:	0.04 - Excellent	**City Code:**	IRONTON	**Ext. Gross Area:**	3,780
Building Code:	R2900306520	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$30,079
Building Name:	Cuyuna Croft Mine Engineer's Office	**Address:**	307 3RD ST	**Deferred Maintenance:**	$4,670
Facility Condition Index:	0.16 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	256
Building Code:	R2900306530	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$629,792
Building Name:	Cuyuna Croft Mine Interp Occupied	**Address:**	307 3RD ST	**Deferred Maintenance:**	$131,677
Facility Condition Index:	0.21 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	3,116
Building Code:	R2900307280	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,575
Building Name:	Cuyuna Portsmouth CG Vault Toilet	**Address:**	307 3RD ST	**Deferred Maintenance:**	$1,149
Facility Condition Index:	0.07 - Good	**City Code:**	IRONTON	**Ext. Gross Area:**	47

Site: R290016 - Father Hennepin State Park

Building Code:	R2900300940	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$319,938
Building Name:	Father Hennepin SP Shop	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$108,820
Facility Condition Index:	0.34 - Poor	**City Code:**	ISLE	**Ext. Gross Area:**	1,523
Building Code:	R2900300960	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$390,853
Building Name:	Father Hennepin SP Residence	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$108,314
Facility Condition Index:	0.28 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	1,751
Building Code:	R2900300970	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$177,828
Building Name:	Father Hennepin SP Picnic Shelter 2	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$23,116
Facility Condition Index:	0.13 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	1,620
Building Code:	R2900300980	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$158,011
Building Name:	Father Hennepin SP Picnic Shelter 1	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$41,438
Facility Condition Index:	0.26 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	1,512
Building Code:	R2900301000	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$46,338
Building Name:	FH SP Lakeview CG Fish Cleaning Hse	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$11,854
Facility Condition Index:	0.26 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	288
Building Code:	R2900301010	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$136,972
Building Name:	Father Hennepin SP Beach Sanitation	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$59,741
Facility Condition Index:	0.44 - Poor	**City Code:**	ISLE	**Ext. Gross Area:**	432

Building Code:	R2900303050	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$84,770
Building Name:	Father Hennepin SP HQ Cold Storage	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$41,429
Facility Condition Index:	0.49 - Poor	**City Code:**	ISLE	**Ext. Gross Area:**	816
Building Code:	R2900303400	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$357,795
Building Name:	FH SP Maple Grove CG Sanitation	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$93,875
Facility Condition Index:	0.26 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	1,120
Building Code:	R2900303420	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$124,299
Building Name:	Father Hennepin SP Boat House	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$38,439
Facility Condition Index:	0.31 - Poor	**City Code:**	ISLE	**Ext. Gross Area:**	972
Building Code:	R2900304170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,497
Building Name:	Father Hennepin SP HQ Oil House	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$1,612
Facility Condition Index:	0.10 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	96
Building Code:	R2900304260	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$245,813
Building Name:	Father Hennepin SP Office	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$54,703
Facility Condition Index:	0.22 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	897
Building Code:	R2900304480	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$390,076
Building Name:	FH SP Lakeview CG Sanitation	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$92,928
Facility Condition Index:	0.24 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	1,092
Building Code:	R2900306790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,883
Building Name:	Father Henn SP Picnic Vault Toilet	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$923
Facility Condition Index:	0.07 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	40
Building Code:	R2900307160	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,365
Building Name:	FH SP Lakeview CG Rght Mens Vault	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$895
Facility Condition Index:	0.05 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	47
Building Code:	R2900307170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,365
Building Name:	FH SP Lakeview CG Left Wms Vault	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$594
Facility Condition Index:	0.04 - Excellent	**City Code:**	ISLE	**Ext. Gross Area:**	47
Building Code:	R2900307180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,365
Building Name:	FH SP Maple Grove CG Rt Mens Vault	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$594
Facility Condition Index:	0.04 - Excellent	**City Code:**	ISLE	**Ext. Gross Area:**	47
Building Code:	R2900307190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,365
Building Name:	FH SP Maple Grv CG Left Wms Vault	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$842
Facility Condition Index:	0.05 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	48
Building Code:	R2900307770	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,534
Building Name:	Father Henn SP Wood Cold Storage	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$551
Facility Condition Index:	0.02 - Excellent	**City Code:**	ISLE	**Ext. Gross Area:**	387

Building Code:	R2900307780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,326
Building Name:	Father Henn SP Boat Vault Toilet	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$1,140
Facility Condition Index:	0.07 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	48
Building Code:	R2900308280	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,903
Building Name:	FH SP Group CG Vault Concrete	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$1,058
Facility Condition Index:	0.02 - Excellent	**City Code:**	ISLE	**Ext. Gross Area:**	102

Site: R290017 - Flandrau State Park

Building Code:	R2900400320	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,285,727
Building Name:	Flandrau SP Res Garage/Cold Storage	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$306,537
Facility Condition Index:	0.24 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	2,350
Building Code:	R2900400330	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,410,406
Building Name:	Flandrau SP Residence	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$270,214
Facility Condition Index:	0.19 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	2,560
Building Code:	R2900400350	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$123,163
Building Name:	Flandrau SP Group CG Cabin 1	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$33,654
Facility Condition Index:	0.27 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400360	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$147,918
Building Name:	Flandrau SP Group CG Cabin 2	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$67,882
Facility Condition Index:	0.46 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400370	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$147,918
Building Name:	Flandrau SP Group CG Cabin 3	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$41,823
Facility Condition Index:	0.28 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400380	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$147,918
Building Name:	Flandrau SP Group CG Cabin 4	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$45,352
Facility Condition Index:	0.31 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400390	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$93,141
Building Name:	Flandrau SP Group CG Cabin 5	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$28,164
Facility Condition Index:	0.30 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400400	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$123,265
Building Name:	Flandrau SP Group CG Cabin 6	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$37,702
Facility Condition Index:	0.31 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400410	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$127,222
Building Name:	Flandrau SP Group CG Cabin 7	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$38,522
Facility Condition Index:	0.30 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	720

Building Code:	R2900400420	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$147,918
Building Name:	Flandrau SP Group CG Cabin 8	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$50,228
Facility Condition Index:	0.34 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	720
Building Code:	R2900400430	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$214,070
Building Name:	Flandrau SP Group CG Mens San Bldg	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$60,382
Facility Condition Index:	0.28 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	522
Building Code:	R2900400440	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$214,070
Building Name:	Flandrau SP Group CG Women San Bldg	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$43,227
Facility Condition Index:	0.20 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	522
Building Code:	R2900400450	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$695,561
Building Name:	Flandrau SP Group CG Dining Hall	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$173,349
Facility Condition Index:	0.25 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	2,701
Building Code:	R2900400460	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,386,384
Building Name:	Flandrau SP Bath House	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$235,320
Facility Condition Index:	0.17 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	4,250
Building Code:	R2900400470	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$430,439
Building Name:	Flandrau SP Semi-Modern Stone Cabin	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$8,609
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	700
Building Code:	R2900400510	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,170,379
Building Name:	Flandrau SP Shop	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$318,783
Facility Condition Index:	0.27 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	3,800
Building Code:	R2900400530	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$335,479
Building Name:	Flandrau SP Group CG Cabin	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$128,851
Facility Condition Index:	0.38 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	1,908
Building Code:	R2900403100	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$53,013
Building Name:	Flandrau SP Pump House	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$12,852
Facility Condition Index:	0.24 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	675
Building Code:	R2900403120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,291
Building Name:	Flandrau SP Picnic Ar Vault Toilet	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$5,523
Facility Condition Index:	0.26 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	64
Building Code:	R2900403170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,342
Building Name:	Flandrau SP Rustic CG Vault Toilet	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$7,043
Facility Condition Index:	0.33 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	64
Building Code:	R2900403180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,396
Building Name:	Flandrau SP Rustic CG Vault Toilet	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$5,461
Facility Condition Index:	0.26 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	64

Building Code:	R2900404020	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$390,931
Building Name:	Flandrau SP Contact Station	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$66,682
Facility Condition Index:	0.17 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	1,311
Building Code:	R2900404140	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,928
Building Name:	Flandrau SP Oil House	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$4,243
Facility Condition Index:	0.33 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	100
Building Code:	R2900404550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,396
Building Name:	Flandrau SP Beach Hse Vault Toilet	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$4,431
Facility Condition Index:	0.21 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	64
Building Code:	R2900404560	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$51,940
Building Name:	Flandrau SP Wood Cold Storage	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$17,140
Facility Condition Index:	0.33 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	600
Building Code:	R2900404650	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$323,344
Building Name:	Flandrau SP Semi-Modern Sanitation	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$17,676
Facility Condition Index:	0.05 - Good	**City Code:**	NEW ULM	**Ext. Gross Area:**	1,000
Building Code:	R2900404860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,396
Building Name:	Flandrau SP Group CG Vault Toilet	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$3,274
Facility Condition Index:	0.15 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	64
Building Code:	R2900405220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,837
Building Name:	Flandrau SP Vault Concrete	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$517
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	48
Building Code:	R2900405230	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,303
Building Name:	Flandrau SP Camper Cabin 1	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$2,824
Facility Condition Index:	0.05 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	288
Building Code:	R2900405240	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,303
Building Name:	Flandrau SP Camper Cabin 2	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$2,824
Facility Condition Index:	0.05 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	288
Building Code:	R2900405430	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$732,088
Building Name:	Flandrau SP Wood Shed	**Address:**	1300 SUMMIT AVE	**Deferred Maintenance:**	$15,274
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	280
Building Code:	R2900405810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$29,857
Building Name:	Flandrau State Park SM Vault Toilet	**Address:**	1300 Summit Ave	**Deferred Maintenance:**	$629
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	0
Building Code:	R2900405820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$31,684
Building Name:	Flandrau SP Rustic Double Vault	**Address:**	1300 Summit Ave	**Deferred Maintenance:**	$634
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW ULM	**Ext. Gross Area:**	102

Site: R290018 - Forestville-Mystery Cave State Park

Building Code:	R2900501410	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$729,142
Building Name:	F-MC SP Main CG Sanitation	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$70,037
Facility Condition Index:	0.10 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	1,702
Building Code:	R2900501470	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$42,699
Building Name:	F-MC SP Main CG Pump House	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$4,800
Facility Condition Index:	0.11 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	121
Building Code:	R2900501480	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$211,617
Building Name:	F-MC SP Group CG Cold Storage	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$54,151
Facility Condition Index:	0.26 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	1,952
Building Code:	R2900501860	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$1,031,319
Building Name:	F-MC SP Picnic Area Sanitation	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$177,742
Facility Condition Index:	0.17 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	2,800
Building Code:	R2900501880	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$255,838
Building Name:	F-MC SP Forestville Shop	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$38,385
Facility Condition Index:	0.15 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	1,460
Building Code:	R2900501890	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,456
Building Name:	F-MC SP Oil House	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,321
Facility Condition Index:	0.06 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	103
Building Code:	R2900501950	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$274,889
Building Name:	F-MC SP Forestville Contact Station	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$35,643
Facility Condition Index:	0.13 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	901
Building Code:	R2900502080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,187,980
Building Name:	F-MC SP Residence	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$581,762
Facility Condition Index:	0.49 - Poor	**City Code:**	PRESTON	**Ext. Gross Area:**	3,539
Building Code:	R2900502090	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$109,529
Building Name:	F-MC SP Mystery Cave Shop	**Address:**	21071 COUNTY RD 118	**Deferred Maintenance:**	$11,159
Facility Condition Index:	0.10 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	1,500
Building Code:	R2900502150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$47,659
Building Name:	F-MC SP Cave Entrance Bldg	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$5,105
Facility Condition Index:	0.11 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	306
Building Code:	R2900502870	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,501
Building Name:	F-MC SP Mystery Cave Wood Shed	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$14,687
Facility Condition Index:	0.72 - Crisis	**City Code:**	PRESTON	**Ext. Gross Area:**	192

Building Code:	R2900502890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Main CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$2,425
Facility Condition Index:	0.20 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Main CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$3,086
Facility Condition Index:	0.26 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Main CG B Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$3,086
Facility Condition Index:	0.26 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Main CG B Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$3,086
Facility Condition Index:	0.26 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Group CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$3,086
Facility Condition Index:	0.26 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Group CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$4,293
Facility Condition Index:	0.36 - Poor	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,672
Building Name:	F-MC SP Group CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$4,167
Facility Condition Index:	0.36 - Poor	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900502960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Group CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$3,086
Facility Condition Index:	0.26 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900504190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Main CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,879
Facility Condition Index:	0.16 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900504200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Main CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$2,540
Facility Condition Index:	0.21 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900504210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Horse CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$2,540
Facility Condition Index:	0.21 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35
Building Code:	R2900504220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,057
Building Name:	F-MC SP Horse CG Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$2,540
Facility Condition Index:	0.21 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	35

Building Code:	R2900505020	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,851,515
Building Name:	F-MC SP Mystery Cave Contact Sta	**Address:**	21071 COUNTY RD 118	**Deferred Maintenance:**	$117,661
Facility Condition Index:	0.06 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	5,307
Building Code:	R2900505180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	F-MC SP Horse CG S Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,213
Facility Condition Index:	0.07 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	47
Building Code:	R2900505190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	F-MC SP Horse CG E Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,213
Facility Condition Index:	0.07 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	47
Building Code:	R2900505200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	F-MC SP Parking Area Vault Toilet	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,213
Facility Condition Index:	0.07 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	47
Building Code:	R2900505250	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$37,583
Building Name:	F-MC SP Amphitheatre	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,259
Facility Condition Index:	0.03 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	410
Building Code:	R2900505510	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,535
Building Name:	F-MC SP Horse CG Vault Concrete	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$511
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	47
Building Code:	R2900505850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$56,504
Building Name:	F-MC SP Vault Concrete	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,130
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	104
Building Code:	R2900505860	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$79,116
Building Name:	F-MC SP Pine Camper Cabin	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,582
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	390
Building Code:	R2900505870	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$79,116
Building Name:	F-MC SP Owl Camper Cabin	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,582
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	390
Building Code:	R2900505880	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$93,651
Building Name:	F-MC SP Lily Camper Cabin	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,873
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	390
Building Code:	R2900505890	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$93,651
Building Name:	F-MC SP Mink Camper Cabin	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,873
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	390
Building Code:	R2900505900	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$69,032
Building Name:	F-MC SP Trout Camper Cabin	**Address:**	21071 CTY 118	**Deferred Maintenance:**	$1,381
Facility Condition Index:	0.02 - Excellent	**City Code:**	PRESTON	**Ext. Gross Area:**	390

Site: R290019 - Fort Ridgely State Park

Building Code:	R2900400790	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$50,861
Building Name:	Fort Ridgely SP Cold Storage	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$11,142
Facility Condition Index:	0.22 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	200
Building Code:	R2900400800	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$543,931
Building Name:	Fort Ridgely SP Trails Center	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$157,670
Facility Condition Index:	0.29 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	2,400
Building Code:	R2900400810	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$825,575
Building Name:	Fort Ridgely SP Picnic Shelter 2	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$101,949
Facility Condition Index:	0.12 - Good	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,560
Building Code:	R2900400820	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$235,061
Building Name:	Fort Ridgely SP Shop	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$73,140
Facility Condition Index:	0.31 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,155
Building Code:	R2900400830	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$674,975
Building Name:	Ft Ridgely SP Rustic CG Pic Shel 2	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$423,685
Facility Condition Index:	0.63 - Crisis	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,304
Building Code:	R2900400840	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,434,766
Building Name:	Fort Ridgely SP Residence Garage	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$469,281
Facility Condition Index:	0.33 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,938
Building Code:	R2900400860	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$246,481
Building Name:	Fort Ridgely SP Creekside CG San	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$74,312
Facility Condition Index:	0.30 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	522
Building Code:	R2900400880	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$177,594
Building Name:	Fort Ridgely SP Picnic Area San	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$47,534
Facility Condition Index:	0.27 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	405
Building Code:	R2900400900	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$837,194
Building Name:	Fort Ridgely SP Residence	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$332,784
Facility Condition Index:	0.40 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	2,210
Building Code:	R2900402910	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$210,767
Building Name:	Fort Ridgely SP Cold Storage	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$94,907
Facility Condition Index:	0.45 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,820
Building Code:	R2900402920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$122,749
Building Name:	Fort Ridgely SP Shop Cold Storage	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$40,507
Facility Condition Index:	0.33 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,404

Building Code:	R2900403500	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,312
Building Name:	Fort Ridgely SP Oil House	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$3,826
Facility Condition Index:	0.31 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	96
Building Code:	R2900403820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,229
Building Name:	Fort Ridgely SP Creekside CG Vault	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$2,108
Facility Condition Index:	0.26 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	24
Building Code:	R2900403930	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$208,677
Building Name:	Fort Ridgely SP Contact Station	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$65,904
Facility Condition Index:	0.32 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	645
Building Code:	R2900404050	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$840,043
Building Name:	Fort Ridgely SP Interp Center	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$277,214
Facility Condition Index:	0.33 - Poor	**City Code:**	FAIRFAX	**Ext. Gross Area:**	1,506
Building Code:	R2900404420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,229
Building Name:	Fort Ridgely SP Vault Toilet	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$1,659
Facility Condition Index:	0.20 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	24
Building Code:	R2900404440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,038
Building Name:	Fort Ridgely SP Picnic Vault Toilet	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$3,410
Facility Condition Index:	0.21 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	48
Building Code:	R2900404470	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$99,008
Building Name:	Fort Ridgely SP Horse CG Lodgng Hse	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$19,555
Facility Condition Index:	0.20 - Fair	**City Code:**	FAIRFAX	**Ext. Gross Area:**	480
Building Code:	R2900404480	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$55,039
Building Name:	Fort Ridgely SP Horse CG Shed	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$8,018
Facility Condition Index:	0.15 - Good	**City Code:**	FAIRFAX	**Ext. Gross Area:**	750
Building Code:	R2900404490	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$24,110
Building Name:	Fort Ridgely SP Horse CG Cold Stor	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$3,308
Facility Condition Index:	0.14 - Good	**City Code:**	FAIRFAX	**Ext. Gross Area:**	176
Building Code:	R2900404500	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$215,766
Building Name:	Fort Ridgely SP Horse CG Sanitation	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$22,713
Facility Condition Index:	0.11 - Good	**City Code:**	FAIRFAX	**Ext. Gross Area:**	884
Building Code:	R2900404750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,458
Building Name:	Fort Ridgely SP Grp CG Vault Toilet	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$1,254
Facility Condition Index:	0.08 - Good	**City Code:**	FAIRFAX	**Ext. Gross Area:**	48
Building Code:	R2900404760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,164
Building Name:	Fort Ridgely SP Vault Toilet	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$1,233
Facility Condition Index:	0.08 - Good	**City Code:**	FAIRFAX	**Ext. Gross Area:**	47

Building Code:	R2900405190	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,934
Building Name:	Fort Ridgely SP Golf Crse Pumphouse	**Address:**	72158 CO RD 30	**Deferred Maintenance:**	$359
Facility Condition Index:	0.02 - Excellent	**City Code:**	FAIRFAX	**Ext. Gross Area:**	64

Site: R290020 - Fort Snelling State Park

Building Code:	R2900600110	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$534,988
Building Name:	Fort Snelling SP Contact Station	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$83,746
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,967
Building Code:	R2900600180	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$196,723
Building Name:	Fort Snelling SP Picnic San 1	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$54,440
Facility Condition Index:	0.28 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	501
Building Code:	R2900600190	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$197,987
Building Name:	Fort Snelling SP Picnic San 2	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$55,239
Facility Condition Index:	0.28 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	501
Building Code:	R2900600200	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$5,243,524
Building Name:	Fort Snelling SP Chapel	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$2,092,520
Facility Condition Index:	0.40 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	13,968
Building Code:	R2900600220	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$171,534
Building Name:	Fort Snelling SP Beach Bath House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$38,117
Facility Condition Index:	0.22 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	576
Building Code:	R2900600230	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$102,331
Building Name:	Fort Snelling SP Beach Concession	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$25,120
Facility Condition Index:	0.25 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	576
Building Code:	R2900600240	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$192,521
Building Name:	Fort Snelling SP Beach Sanitation	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$29,018
Facility Condition Index:	0.15 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	576
Building Code:	R2900601110	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$464,899
Building Name:	Fort Snelling SP Shop	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$95,906
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	2,477
Building Code:	R2900601120	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$202,641
Building Name:	Fort Snelling SP Picnic San 3	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$54,749
Facility Condition Index:	0.27 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	501
Building Code:	R2900601130	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$239,889
Building Name:	Fort Snelling SP Picnic Shelter 2	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$28,504
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,887

Building Code:	R2900601960	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$343,773
Building Name:	Fort Snelling SP Shop Cold Storage	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$39,845
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,927
Building Code:	R2900601970	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,012,708
Building Name:	Fort Snelling SP Interp Center	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$349,366
Facility Condition Index:	0.17 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	7,022
Building Code:	R2900602000	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$190,636
Building Name:	Fort Snelling SP Picnic Shelter 1	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$41,404
Facility Condition Index:	0.22 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	880
Building Code:	R2900602300	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,167
Building Name:	Fort Snelling SP Cold Storage Barn	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$393
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	65
Building Code:	R2900602310	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,294
Building Name:	Fort Snelling SP Chapel Cold Storag	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$1,374
Facility Condition Index:	0.19 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	80
Building Code:	R2900690530	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$684,614
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$684,614
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	15,750
Building Code:	R2900690540	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$769,376
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$769,376
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	17,700
Building Code:	R2900690550	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$2,217,410
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$2,217,410
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	51,013
Building Code:	R2900690560	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$82,892
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$82,892
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	2,700
Building Code:	R2900690570	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$300,867
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$300,867
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	9,800
Building Code:	R2900690620	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$98,242
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$98,242
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,200
Building Code:	R2900690630	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$521,611
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$521,611
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	12,000

Building Code:	R2900690640	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$165,784
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$165,784
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	5,400
Building Code:	R2900690650	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$738,948
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$738,948
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	17,000
Building Code:	R2900690660	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$300,867
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$300,867
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	9,800
Building Code:	R2900690670	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$821,537
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$821,537
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	18,900
Building Code:	R2900690760	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$512,917
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$512,917
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	11,800
Building Code:	R2900691010	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$1,903,879
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$1,903,879
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	43,800
Building Code:	R2900691020	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$634,626
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$634,626
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	14,600
Building Code:	R2900691030	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$634,626
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$634,626
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	14,600
Building Code:	R2900691120	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$116,663
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$116,663
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,800
Building Code:	R2900691510	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$886,738
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$886,738
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	20,400
Building Code:	R2900691520	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$128,943
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$128,943
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,200
Building Code:	R2900691530	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$128,943
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$128,943
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,200

Building Code:	R2900691540	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$147,364
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$147,364
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,800
Building Code:	R2900691550	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$132,627
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$132,627
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,320
Building Code:	R2900691560	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$132,627
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$132,627
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,320
Building Code:	R2900691570	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$436,849
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$436,849
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	10,050
Building Code:	R2900691580	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$147,364
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$147,364
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,800
Building Code:	R2900691590	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$128,943
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$128,943
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,200
Building Code:	R2900691600	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$147,364
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$147,364
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,800
Building Code:	R2900691610	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$182,564
Building Name:	Lodging House	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$182,564
Facility Condition Index:	1.00 - Crisis	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,200
Building Code:	R2900691750	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$134,656
Building Name:	Fort Snelling SP Up Bluff Clubhouse	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$37,251
Facility Condition Index:	0.28 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	700
Building Code:	R2900691780	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$125,971
Building Name:	Fort Snelling Golf Course Cold Stor	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$55,233
Facility Condition Index:	0.44 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,000
Building Code:	R2900691820	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$162,591
Building Name:	Fort Snelling Golf Course Cold Stor	**Address:**	101 SNELLING LAKE RD	**Deferred Maintenance:**	$68,701
Facility Condition Index:	0.42 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,000

Site: R290021 - Frontenac State Park

Building Code:	R2900500430	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$23,987
Building Name:	Frontenac SP Trails Center	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$5,394
Facility Condition Index:	0.22 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	152
Building Code:	R2900500460	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,438
Building Name:	Frontenac SP Wood Cold Storage	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,235
Facility Condition Index:	0.22 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	149
Building Code:	R2900500470	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$212,144
Building Name:	Frontenac SP Picnic Area Sanitation	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$78,623
Facility Condition Index:	0.37 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	979
Building Code:	R2900500480	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$198,538
Building Name:	Frontenac SP CG Sanitation	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$94,300
Facility Condition Index:	0.47 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	668
Building Code:	R2900500490	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$23,261
Building Name:	Frontenac SP Grp CG Old Picnic Shel	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$17,446
Facility Condition Index:	0.75 - Crisis	**City Code:**	LAKE CITY	**Ext. Gross Area:**	209
Building Code:	R2900502070	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$125,315
Building Name:	Frontenac SP Shop	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$19,784
Facility Condition Index:	0.16 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	1,792
Building Code:	R2900502630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$7,951
Building Name:	Frontenac SP CG Site 1 Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$2,081
Facility Condition Index:	0.26 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,192
Building Name:	Frontenac SP Walk-in CG Vault Toil	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,278
Facility Condition Index:	0.32 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,150
Building Name:	Frontenac SP CG Ste 39 Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,504
Facility Condition Index:	0.37 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,329
Building Name:	Frontenac SP Grp CG Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,307
Facility Condition Index:	0.42 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,690
Building Name:	Frontenac SP Grp CG Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$3,727
Facility Condition Index:	0.29 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,909
Building Name:	Frontenac SP CG ADA Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$3,600
Facility Condition Index:	0.36 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64

Building Code:	R2900503490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,006
Building Name:	Frontenac SP Picnic Ar Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$2,145
Facility Condition Index:	0.24 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503750	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$262,189
Building Name:	Frontenac SP Contact Station	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$35,460
Facility Condition Index:	0.14 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	1,389
Building Code:	R2900504360	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$37,800
Building Name:	Frontenac SP Grp CG New Picnic Shel	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$6,184
Facility Condition Index:	0.16 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	328
Building Code:	R2900504370	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$499,271
Building Name:	Frontenac SP Main Shop	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$41,717
Facility Condition Index:	0.08 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	4,515
Building Code:	R2900504380	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$12,343
Building Name:	Frontenac SP Picnic Area Shelter 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$1,365
Facility Condition Index:	0.11 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	150
Building Code:	R2900504600	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,872
Building Name:	Frontenac SP Sled Hill Adirondack	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$2,378
Facility Condition Index:	0.22 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	100
Building Code:	R2900504620	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$12,773
Building Name:	Frontenac SP Sand Pt Trl Adirondack	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$6,794
Facility Condition Index:	0.53 - Crisis	**City Code:**	LAKE CITY	**Ext. Gross Area:**	100
Building Code:	R2900505390	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$11,740
Building Name:	Frontenac SP Picnic Shelter 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$306
Facility Condition Index:	0.03 - Excellent	**City Code:**	LAKE CITY	**Ext. Gross Area:**	125

Site: R290022 - Glacial Lakes State Park

Building Code:	R2900102210	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$147,898
Building Name:	Glacial Lakes SP Grp CG Picnic Shel	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$14,790
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	1,152
Building Code:	R2900102220	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$135,979
Building Name:	Glacial Lakes SP Swimming Area San	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$28,327
Facility Condition Index:	0.21 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	432
Building Code:	R2900102230	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$163,981
Building Name:	Glacial Lakes SP Lower CG San Bldg	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$45,612
Facility Condition Index:	0.28 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	640

Building Code:	R2900102270	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,322
Building Name:	Glacial Lakes SP Grp CG Pumphouse	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$3,247
Facility Condition Index:	0.29 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	37
Building Code:	R2900102280	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,770
Building Name:	Glacial Lakes SP Lower CG Pumphouse	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$3,877
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	121
Building Code:	R2900102290	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$143,620
Building Name:	Glacial Lakes SP Shop	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$29,435
Facility Condition Index:	0.20 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	1,538
Building Code:	R2900105770	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,576
Building Name:	Glacial Lakes SP Hill BP Mens Vault	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$1,058
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	30
Building Code:	R2900105780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,576
Building Name:	Glacial Lakes SP Hill BP Women Valt	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$1,058
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	30
Building Code:	R2900105790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,188
Building Name:	Glacial Lakes Grp CG SE Picnic Valt	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$2,095
Facility Condition Index:	0.13 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	48
Building Code:	R2900105800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,188
Building Name:	Glacial Lakes Grp CG SE Picnic Vlt2	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$3,225
Facility Condition Index:	0.20 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	48
Building Code:	R2900106660	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,200
Building Name:	Glacial Lakes SP Lowr CG Vault Toil	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$1,837
Facility Condition Index:	0.13 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	42
Building Code:	R2900106670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,963
Building Name:	Glacial Lakes SP Oakridge CG Vault	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$2,099
Facility Condition Index:	0.15 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	42
Building Code:	R2900106680	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,200
Building Name:	Glacial Lakes SP Oakridge Vault 2	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$2,177
Facility Condition Index:	0.15 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	42
Building Code:	R2900106690	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,200
Building Name:	Glacial Lakes SP Beach Park Vault	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$2,177
Facility Condition Index:	0.15 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	42
Building Code:	R2900107260	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$448,403
Building Name:	Glacial Lakes SP Residence	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$76,185
Facility Condition Index:	0.17 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	2,809

Building Code:	R2900107820	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$284,710
Building Name:	Glacial Lakes SP Contact Sta	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$14,850
Facility Condition Index:	0.05 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	923
Building Code:	R2900107830	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$103,496
Building Name:	Glacial Lakes SP Shop Pole Building	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$10,350
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	1,536
Building Code:	R2900107990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,435
Building Name:	Glacial Lakes Horse CG Vault Toilet	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$3,299
Facility Condition Index:	0.20 - Fair	**City Code:**	STARBUCK	**Ext. Gross Area:**	48
Building Code:	R2900108250	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,442
Building Name:	Glacial Lakes SP Coneflower Cabin	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$5,520
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	264
Building Code:	R2900108260	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,465
Building Name:	Glacial Lakes SP Wood Shed	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$2,247
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	112
Building Code:	R2900108460	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$61,703
Building Name:	Glacial Lakes SP Kettle Cabin	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$6,170
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	288
Building Code:	R2900108470	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$60,854
Building Name:	Glacial Lakes SP Kame Cabin	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$6,085
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	288
Building Code:	R2900108480	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,948
Building Name:	Glacial Lakes SP Esker Cabin	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$6,895
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	288
Building Code:	R2900108490	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$63,785
Building Name:	Glacial Lakes SP Glacial Erractic	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$6,379
Facility Condition Index:	0.10 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	288
Building Code:	R2900108540	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,732
Building Name:	Glacial Lakes Upr CG Vault Concret	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$435
Facility Condition Index:	0.02 - Excellent	**City Code:**	STARBUCK	**Ext. Gross Area:**	40
Building Code:	R2900108570	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$59,214
Building Name:	Glacial Lakes SP Friends Cabin	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$8,486
Facility Condition Index:	0.14 - Good	**City Code:**	STARBUCK	**Ext. Gross Area:**	264
Building Code:	R2900109220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$4,746
Building Name:	Glacial Lakes SP Baby Lake Pit	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$1,566
Facility Condition Index:	0.33 - Poor	**City Code:**	STARBUCK	**Ext. Gross Area:**	16

Building Code:	R2900109230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$2,533
Building Name:	Glacial Lakes SP Kettle Lake Pit	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$836
Facility Condition Index:	0.33 - Poor	**City Code:**	STARBUCK	**Ext. Gross Area:**	16
Building Code:	R2900109240	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$2,533
Building Name:	Glacial Lakes SP Oak Backpack Pit	**Address:**	25022 CO RD 41	**Deferred Maintenance:**	$836
Facility Condition Index:	0.33 - Poor	**City Code:**	STARBUCK	**Ext. Gross Area:**	16

Site: R290023 - Glendalough State Park

Building Code:	R2900105990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,251
Building Name:	Glendalough Lakeside Carriage Hse	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$74,914
Facility Condition Index:	0.72 - Crisis	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	912
Building Code:	R2900106060	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$599,368
Building Name:	Glendalough Lakeside Trails Center	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$102,552
Facility Condition Index:	0.17 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	2,361
Building Code:	R2900106080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$535,406
Building Name:	Glendalough Lakeside Lodge	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$92,138
Facility Condition Index:	0.17 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	1,965
Building Code:	R2900106090	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$245,790
Building Name:	Glendalough Game F Seed drying bldg	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$55,462
Facility Condition Index:	0.23 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	2,156
Building Code:	R2900106100	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$95,923
Building Name:	Glendalough Game Farm Metal Storage	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$21,784
Facility Condition Index:	0.23 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	1,456
Building Code:	R2900106120	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$185,763
Building Name:	Glendalough Game F Seed Proces Bldg	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$33,332
Facility Condition Index:	0.18 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	1,600
Building Code:	R2900106260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,789
Building Name:	Glendalough Walk-in CG Vault Toilet	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$2,075
Facility Condition Index:	0.15 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900106270	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$91,586
Building Name:	Glendalough SP Walk-in CG Cabin 12	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$9,159
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	299
Building Code:	R2900106280	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,444
Building Name:	Glendalough SP Walk-in CG Cabin 6	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$6,844
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	299

Building Code:	R2900106290	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,444
Building Name:	Glendalough SP Walk-in CG Cabin 10	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$6,844
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	299
Building Code:	R2900106300	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$134,388
Building Name:	Glendalough SP Walk-in CG San Bldg	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$17,181
Facility Condition Index:	0.13 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	400
Building Code:	R2900106310	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$85,386
Building Name:	Glendalough SP Walk-in CG Cabin 3	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$8,539
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	299
Building Code:	R2900106320	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$16,856
Building Name:	Glendalough Walk-in CG Cold Storage	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$1,686
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	106
Building Code:	R2900106330	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$60,063
Building Name:	Glendalough MStark Picnic Shelter 1	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$6,006
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	928
Building Code:	R2900106870	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$37,223
Building Name:	Glendalough Lakeside Electric Shed	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$13,802
Facility Condition Index:	0.37 - Poor	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	288
Building Code:	R2900106880	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,504
Building Name:	Glendalough SP Old Wood Storage	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$4,567
Facility Condition Index:	0.70 - Crisis	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	80
Building Code:	R2900106890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,789
Building Name:	Glendalough MStark Picnic Ar Vault	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$2,724
Facility Condition Index:	0.20 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900108000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,283
Building Name:	Glendalough Canoe-in CG Vault Toil	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$1,208
Facility Condition Index:	0.07 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	48
Building Code:	R2900108390	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$127,640
Building Name:	Glendalough Game F West Metal Bldg	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$34,241
Facility Condition Index:	0.27 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	2,040
Building Code:	R2900108620	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$498,622
Building Name:	Glendalough SP Game Farm Office	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$39,371
Facility Condition Index:	0.08 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	1,850
Building Code:	R2900108630	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$165,561
Building Name:	Glendalough SP Info Center	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$16,556
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	1,024

Building Code:	R2900109190	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$49,139
Building Name:	Glendalough Canoe-in CG Yurt	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$4,914
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	256
Building Code:	R2900109200	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$68,113
Building Name:	Glendalough Canoe-in CG ADA Yurt	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$6,811
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	370
Building Code:	R2900109260	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$10,721
Building Name:	Glendalough Walk-in CG Wood Storage	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$1,082
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	290
Building Code:	R2900109470	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,797
Building Name:	Glendalough MStark Picnic Pumphouse	**Address:**	24869 WHITETAIL LN	**Deferred Maintenance:**	$380
Facility Condition Index:	0.10 - Good	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	48

Site: R290024 - Gooseberry Falls State Park

Building Code:	R2900202050	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$1,391,477
Building Name:	Gooseberry Falls SP Sanitation	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$143,427
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	3,082
Building Code:	R2900202060	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$68,241
Building Name:	Gooseberry Falls SP Icehouse	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$6,905
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	328
Building Code:	R2900202080	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$148,179
Building Name:	Gooseberry F CG Cold H20 Sanitation	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$80,373
Facility Condition Index:	0.54 - Crisis	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	394
Building Code:	R2900202090	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$949,106
Building Name:	Gooseberry Falls SP Recreation Hall	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$100,251
Facility Condition Index:	0.11 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	1,679
Building Code:	R2900202100	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$1,113,429
Building Name:	Gooseberry Falls SP Lakeview Shel	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$89,979
Facility Condition Index:	0.08 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	1,740
Building Code:	R2900202110	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$110,399
Building Name:	Gooseberry Falls SP Pump House	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$11,040
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	180
Building Code:	R2900202130	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$275,238
Building Name:	Gooseberry Falls SP Trickle Filter	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$31,251
Facility Condition Index:	0.11 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	915

Building Code:	R2900202140	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$188,994
Building Name:	Gooseberry Falls SP Cncrse San Bldg	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$9,284
Facility Condition Index:	0.05 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	600
Building Code:	R2900202160	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$130,834
Building Name:	Gooseberry Falls SP Well House	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$23,470
Facility Condition Index:	0.18 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	221
Building Code:	R2900202170	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$740,540
Building Name:	Gooseberry Falls SP Residence	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$95,366
Facility Condition Index:	0.13 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	2,236
Building Code:	R2900202180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$719,092
Building Name:	Gooseberry Falls SP Office Shp	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$90,177
Facility Condition Index:	0.13 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	4,947
Building Code:	R2900202200	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,521,496
Building Name:	Gooseberry Falls SP Old Visitor Ctr	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$276,921
Facility Condition Index:	0.18 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	4,298
Building Code:	R2900202230	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$120,023
Building Name:	Gooseberry Falls SP Caretaker Cabin	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$52,793
Facility Condition Index:	0.44 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	311
Building Code:	R2900202250	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$72,384
Building Name:	Gooseberry Falls SP GG Stone Shel	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$21,484
Facility Condition Index:	0.30 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	228
Building Code:	R2900202260	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$27,453
Building Name:	Gooseberry Falls SP 5th Falls Shel	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$14,313
Facility Condition Index:	0.52 - Crisis	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	152
Building Code:	R2900202270	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$27,453
Building Name:	Gooseberry Falls SP GG Log Shelter	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$14,313
Facility Condition Index:	0.52 - Crisis	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	152
Building Code:	R2900202290	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$89,282
Building Name:	Gooseberry Falls SP Water Tower	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$35,142
Facility Condition Index:	0.39 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	259
Building Code:	R2900203950	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$23,436
Building Name:	Gooseberry Falls SP Incinerator	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$16,443
Facility Condition Index:	0.70 - Crisis	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	64
Building Code:	R2900203990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$65,595
Building Name:	Gooseberry Falls SP Residnce Garage	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$12,684
Facility Condition Index:	0.19 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	586

Building Code:	R2900204340	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$539,446
Building Name:	Gooseberry Falls SP Sanitation	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$50,059
Facility Condition Index:	0.09 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	1,202
Building Code:	R2900204530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$720,430
Building Name:	Gooseberry Falls SP Cold Storage	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$85,958
Facility Condition Index:	0.12 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	4,284
Building Code:	R2900205450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Gooseberry Falls SP Vault Toilet	**Address:**	3206 Hwy 61	**Deferred Maintenance:**	$2,310
Facility Condition Index:	0.17 - Fair	**City Code:**	Two Harbors	**Ext. Gross Area:**	35
Building Code:	R2900205460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Gooseberry Falls SP Vault Toilet	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$3,075
Facility Condition Index:	0.23 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	35
Building Code:	R2900205470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,463
Building Name:	Gooseberry Falls Low CG Vault Toil	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$666
Facility Condition Index:	0.04 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	45
Building Code:	R2900205490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,463
Building Name:	Gooseberry Falls Up CG Vault Toilet	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$666
Facility Condition Index:	0.04 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	45
Building Code:	R2900205550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Gooseberry Falls SP Vault Toilet	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$2,310
Facility Condition Index:	0.17 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	35
Building Code:	R2900207540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$22,150
Building Name:	Gooseberry Falls SP Wood Storage	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$837
Facility Condition Index:	0.04 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	259
Building Code:	R2900207580	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,305,962
Building Name:	Gooseberry Falls SP Visitor Center	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$704,714
Facility Condition Index:	0.16 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	11,779
Building Code:	R2900207620	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$105,265
Building Name:	Gooseberry Falls SP Contct Station	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$4,362
Facility Condition Index:	0.04 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	447
Building Code:	R2900207900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,463
Building Name:	Gooseberry Falls Grp CG Vault Toil	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$2,103
Facility Condition Index:	0.12 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	45
Building Code:	R2900207910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,463
Building Name:	Gooseberry Falls Grp CG Vault Toil	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$2,103
Facility Condition Index:	0.12 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	45

Building Code:	R2900207920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,463
Building Name:	Gooseberry Falls Grp CG Vault Toil	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$1,291
Facility Condition Index:	0.07 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	45
Building Code:	R2900210340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$26,411
Building Name:	Gooseberry Falls CG Vault Concrete	**Address:**	3206 HWY 61	**Deferred Maintenance:**	$528
Facility Condition Index:	0.02 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	42

Site: R290025 - Grand Portage State Park

Building Code:	R2900208150	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Grand Portage SP Vault Toilet	**Address:**	9393 E HWY 61	**Deferred Maintenance:**	$3,225
Facility Condition Index:	0.19 - Fair	**City Code:**	GRAND PORTAGE	**Ext. Gross Area:**	41
Building Code:	R2900209020	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,203,584
Building Name:	Grand Portage SP Interp Ctr	**Address:**	9393 E HWY 61	**Deferred Maintenance:**	$44,072
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND PORTAGE	**Ext. Gross Area:**	6,057
Building Code:	R2900210200	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,932
Building Name:	Grand Portage SP Recycle Center	**Address:**	9393 E HWY 61	**Deferred Maintenance:**	$498
Facility Condition Index:	0.03 - Excellent	**City Code:**	GRAND PORTAGE	**Ext. Gross Area:**	253
Building Code:	R2900210210	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$46,580
Building Name:	Grand Portage SP Picnic Shelter 1	**Address:**	9393 E HWY 61	**Deferred Maintenance:**	$932
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND PORTAGE	**Ext. Gross Area:**	415
Building Code:	R2900210490	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$107,256
Building Name:	Grand Portage SP Garage	**Address:**	9393 E HWY 61	**Deferred Maintenance:**	$2,145
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND PORTAGE	**Ext. Gross Area:**	576

Site: R290026 - Great River Bluffs State Park

Building Code:	R2900500880	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,566
Building Name:	Great River Bluffs SP Pump House	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$5,135
Facility Condition Index:	0.29 - Fair	**City Code:**	WINONA	**Ext. Gross Area:**	67
Building Code:	R2900500920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$112,592
Building Name:	Great River Bluffs SP Shop	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$67,736
Facility Condition Index:	0.60 - Crisis	**City Code:**	WINONA	**Ext. Gross Area:**	1,166
Building Code:	R2900502640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,557
Building Name:	Great River Bluffs CG Vault Toilet	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$2,412
Facility Condition Index:	0.21 - Fair	**City Code:**	WINONA	**Ext. Gross Area:**	35

Building Code:	R2900502650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,557
Building Name:	Great River Bluffs CG Vault Toilet	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$2,412
Facility Condition Index:	0.21 - Fair	**City Code:**	WINONA	**Ext. Gross Area:**	35
Building Code:	R2900502660	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,557
Building Name:	Great River Bluffs CG Vault Toilet	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$2,292
Facility Condition Index:	0.20 - Fair	**City Code:**	WINONA	**Ext. Gross Area:**	35
Building Code:	R2900503760	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$239,864
Building Name:	Great River Bluffs SP CG Sanitation	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$38,694
Facility Condition Index:	0.16 - Fair	**City Code:**	WINONA	**Ext. Gross Area:**	749
Building Code:	R2900505050	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,346
Building Name:	Great River Bluffs SP Adirondack	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$3,084
Facility Condition Index:	0.33 - Poor	**City Code:**	WINONA	**Ext. Gross Area:**	100
Building Code:	R2900505070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,128
Building Name:	Great River Bluffs SP Vault Concret	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$3,413
Facility Condition Index:	0.10 - Good	**City Code:**	WINONA	**Ext. Gross Area:**	64
Building Code:	R2900505280	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$223,701
Building Name:	Great River Bluffs SP Cold Storage	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$24,829
Facility Condition Index:	0.11 - Good	**City Code:**	WINONA	**Ext. Gross Area:**	2,400
Building Code:	R2900505410	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$46,241
Building Name:	Great River Bluffs SP Info Center	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$1,441
Facility Condition Index:	0.03 - Excellent	**City Code:**	WINONA	**Ext. Gross Area:**	654
Building Code:	R2900505420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,061
Building Name:	Great River Bluffs SP Vault Concret	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$661
Facility Condition Index:	0.02 - Excellent	**City Code:**	WINONA	**Ext. Gross Area:**	62
Building Code:	R2900505430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,061
Building Name:	Great River Bluffs SP Vault Concret	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$661
Facility Condition Index:	0.02 - Excellent	**City Code:**	WINONA	**Ext. Gross Area:**	62
Building Code:	R2900505440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,061
Building Name:	Great River Bluffs SP Vault Concret	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$661
Facility Condition Index:	0.02 - Excellent	**City Code:**	WINONA	**Ext. Gross Area:**	62
Building Code:	R2900505470	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$740,727
Building Name:	Great River Bluffs SP Office	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$17,446
Facility Condition Index:	0.02 - Excellent	**City Code:**	WINONA	**Ext. Gross Area:**	2,326
Building Code:	R2900505580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,664
Building Name:	Great River Bluffs SP Vault Concret	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$373
Facility Condition Index:	0.02 - Excellent	**City Code:**	WINONA	**Ext. Gross Area:**	35

Site: R290027 - Hayes Lake State Park

Building Code:	R2900102160	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$412,134
Building Name:	Hayes Lake SP Residence	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$55,670
Facility Condition Index:	0.14 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	2,288
Building Code:	R2900102170	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$75,752
Building Name:	Hayes Lake SP HQ Cold Storage	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$16,113
Facility Condition Index:	0.21 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	494
Building Code:	R2900102180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$107,740
Building Name:	Hayes Lake SP HQ Cold Storage	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$15,881
Facility Condition Index:	0.15 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	864
Building Code:	R2900102190	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$207,312
Building Name:	Hayes Lake SP HQ Area Shop	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$44,870
Facility Condition Index:	0.22 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	1,500
Building Code:	R2900104330	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$485,988
Building Name:	Hayes Lake SP CG Sanitation	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$73,335
Facility Condition Index:	0.15 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	1,280
Building Code:	R2900104340	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,694
Building Name:	Hayes Lake SP Pump House	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$2,120
Facility Condition Index:	0.15 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	48
Building Code:	R2900104730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,882
Building Name:	Hayes Lake Picnic Area Vault Toilet	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$2,277
Facility Condition Index:	0.26 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	24
Building Code:	R2900104740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,074
Building Name:	Hayes Lake Picnic Area Vault Toilet	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$1,527
Facility Condition Index:	0.19 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	24
Building Code:	R2900104750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,074
Building Name:	Hayes Lake SP Mens Vault Toilet	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$2,010
Facility Condition Index:	0.25 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	24
Building Code:	R2900104760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,882
Building Name:	Hayes Lake SP CG Vault Toilet	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$2,277
Facility Condition Index:	0.26 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	24
Building Code:	R2900105290	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$62,455
Building Name:	Hayes Lake SP Fish Cleaning House	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$12,856
Facility Condition Index:	0.21 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	192

Building Code:	R2900105530	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,292
Building Name:	Hayes Lake SP Fire Tower	**Address:**	RIVER	**Deferred Maintenance:**	$5,046
Facility Condition Index:	0.33 - Poor	**City Code:**	WANNASKA	**Ext. Gross Area:**	64
Building Code:	R2900105940	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$54,060
Building Name:	Hayes Lake SP CG Timber Edge Cabin	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$5,406
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	240
Building Code:	R2900105950	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$49,916
Building Name:	Hayes Lake SP Lakeside Cabin	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$5,398
Facility Condition Index:	0.11 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	240
Building Code:	R2900106200	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$75,520
Building Name:	Hayes Lake Picnic Area Shelter 2	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$7,552
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	864
Building Code:	R2900106440	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$49,162
Building Name:	Hayes Lake SP Residence Garage	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$6,169
Facility Condition Index:	0.13 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	576
Building Code:	R2900106550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,500
Building Name:	Hayes Lake SP CG Vault Toilet	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$1,750
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	48
Building Code:	R2900107810	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$221,616
Building Name:	Hayes Lake SP Contact Station	**Address:**	48990 CTY RD 4	**Deferred Maintenance:**	$20,966
Facility Condition Index:	0.09 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	796

Site: R290028 - Hill Annex Mine State Park

Building Code:	R2900204750	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,169
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$5,706
Facility Condition Index:	0.70 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	64
Building Code:	R2900204760	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$1,460,391
Building Name:	Hill Annex Mine SP Clubhouse	**Address:**	880 GARY ST	**Deferred Maintenance:**	$342,360
Facility Condition Index:	0.23 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	7,535
Building Code:	R2900204770	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,832
Building Name:	Hill Annex Mine SP Old Contact Sta	**Address:**	880 GARY ST	**Deferred Maintenance:**	$6,695
Facility Condition Index:	0.98 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	48
Building Code:	R2900204780	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$929,849
Building Name:	Hill Annex Mine SP Office	**Address:**	880 GARY ST	**Deferred Maintenance:**	$440,976
Facility Condition Index:	0.47 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	3,140

Building Code:	R2900204790	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$842,740
Building Name:	Hill Annex Mine SP Electric Shop	**Address:**	880 GARY ST	**Deferred Maintenance:**	$436,189
Facility Condition Index:	0.52 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	4,059
Building Code:	R2900204800	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,505
Building Name:	Hill Annex Mine SP Pay Master Shed	**Address:**	880 GARY ST	**Deferred Maintenance:**	$3,034
Facility Condition Index:	0.21 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	85
Building Code:	R2900204810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,602
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$2,839
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	64
Building Code:	R2900204820	**Cost Model Name:**	Tower	**Current Replacement Value:**	$18,167
Building Name:	Hill Annex Mine SP Water Tower	**Address:**	880 GARY ST	**Deferred Maintenance:**	$13,625
Facility Condition Index:	0.75 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	92
Building Code:	R2900204830	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,457
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$5,101
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	115
Building Code:	R2900204840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,376
Building Name:	Hill Annex Mine SP Blasting Shed	**Address:**	880 GARY ST	**Deferred Maintenance:**	$1,774
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	40
Building Code:	R2900204850	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,449
Building Name:	Hill Annex Mine SP Shed	**Address:**	880 GARY ST	**Deferred Maintenance:**	$7,453
Facility Condition Index:	0.29 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	66
Building Code:	R2900204860	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$221,785
Building Name:	Hill Annex Mine SP Garage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$90,305
Facility Condition Index:	0.41 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	1,722
Building Code:	R2900204870	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,934
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$4,598
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	91
Building Code:	R2900204880	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,891,678
Building Name:	Hill Annex Mine SP 7-Stall Garage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$1,235,932
Facility Condition Index:	0.65 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	14,405
Building Code:	R2900204890	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,411,309
Building Name:	Hill Annex Mine SP Repair Shop	**Address:**	880 GARY ST	**Deferred Maintenance:**	$2,242,015
Facility Condition Index:	0.66 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	13,787
Building Code:	R2900204900	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$326,858
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$83,842
Facility Condition Index:	0.26 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	2,556

Building Code:	R2900204910	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,165,633
Building Name:	Hill Annex Mine SP Ore Crush Bldg	**Address:**	880 GARY ST	**Deferred Maintenance:**	$651,334
Facility Condition Index:	0.56 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	10,276
Building Code:	R2900204920	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,757
Building Name:	Hill Annex Mine SP Shed	**Address:**	880 GARY ST	**Deferred Maintenance:**	$29,133
Facility Condition Index:	0.81 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	160
Building Code:	R2900204930	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,182
Building Name:	Hill Annex Mine SP Shed	**Address:**	880 GARY ST	**Deferred Maintenance:**	$26,779
Facility Condition Index:	0.83 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	144
Building Code:	R2900204940	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$273,794
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$105,711
Facility Condition Index:	0.39 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	2,112
Building Code:	R2900204950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$43,578
Building Name:	Hill Annex Mine SP Garage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$22,570
Facility Condition Index:	0.52 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	490
Building Code:	R2900204960	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,791
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$27,729
Facility Condition Index:	0.82 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	290
Building Code:	R2900204970	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$21,842
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$7,208
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	280
Building Code:	R2900204980	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,931
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$18,528
Facility Condition Index:	0.38 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	462
Building Code:	R2900204990	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$49,069
Building Name:	Hill Annex Mine SP Old Office	**Address:**	880 GARY ST	**Deferred Maintenance:**	$48,020
Facility Condition Index:	0.98 - Crisis	**City Code:**	CALUMET	**Ext. Gross Area:**	173
Building Code:	R2900205000	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,505
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$7,097
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	160
Building Code:	R2900205010	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,129
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$5,323
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	120
Building Code:	R2900205020	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,839
Building Name:	Hill Annex Mine SP Shed	**Address:**	880 GARY ST	**Deferred Maintenance:**	$1,597
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	36

Building Code:	R2900205030	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$2,151
Building Name:	Hill Annex Mine SP HazMat Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$710
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	16
Building Code:	R2900205040	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$10,957
Building Name:	Hill Annex Mine SP Office	**Address:**	880 GARY ST	**Deferred Maintenance:**	$3,616
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	160
Building Code:	R2900205050	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205060	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205070	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205080	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205090	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205100	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205110	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,413
Building Name:	Hill Annex Mine SP Pump House	**Address:**	880 GARY ST	**Deferred Maintenance:**	$9,046
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	400
Building Code:	R2900205120	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,273
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$3,390
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	120
Building Code:	R2900205130	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,273
Building Name:	Hill Annex Mine SP Cold Storage	**Address:**	880 GARY ST	**Deferred Maintenance:**	$3,390
Facility Condition Index:	0.33 - Poor	**City Code:**	CALUMET	**Ext. Gross Area:**	120

Site: R290029 - Interstate State Park

Building Code:	R2900301260	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$161,839
Building Name:	Interstate SP Office	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$17,293
Facility Condition Index:	0.11 - Good	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	804
Building Code:	R2900301270	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$46,202
Building Name:	Interstate SP Pump House	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$12,797
Facility Condition Index:	0.28 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	140
Building Code:	R2900301280	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$140,622
Building Name:	Interstate SP Pothole Cold Storage	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$25,093
Facility Condition Index:	0.18 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	352
Building Code:	R2900301340	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$241,728
Building Name:	Interstate SP Pothole Concession	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$66,786
Facility Condition Index:	0.28 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,637
Building Code:	R2900301350	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$441,202
Building Name:	Interstate SP Pothole Interp Center	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$80,923
Facility Condition Index:	0.18 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,600
Building Code:	R2900301440	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$371,597
Building Name:	Interstate SP Picnic Shelter 2	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$55,301
Facility Condition Index:	0.15 - Good	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,750
Building Code:	R2900301450	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$707,666
Building Name:	Interstate SP Campground Sanitation	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$241,277
Facility Condition Index:	0.34 - Poor	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,770
Building Code:	R2900303250	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$369,411
Building Name:	Interstate SP Shop	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$82,812
Facility Condition Index:	0.22 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,807
Building Code:	R2900303460	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$440,780
Building Name:	Interstate SP Sanitation	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$82,297
Facility Condition Index:	0.19 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,100
Building Code:	R2900303800	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$235,045
Building Name:	Interstate SP Picnic Shelter 2	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$31,858
Facility Condition Index:	0.14 - Good	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,007
Building Code:	R2900304100	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,161
Building Name:	Interstate SP Oil House	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$3,112
Facility Condition Index:	0.19 - Fair	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	96
Building Code:	R2900306280	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$40,966
Building Name:	Interstate SP Cold Storage	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$5,070
Facility Condition Index:	0.12 - Good	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	384

Building Code:	R2900306920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$147,676
Building Name:	Interstate SP Cold Storage	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$20,919
Facility Condition Index:	0.14 - Good	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	1,440
Building Code:	R2900307380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$51,825
Building Name:	Interstate SP Vault Toilet Concrete	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$5,183
Facility Condition Index:	0.10 - Good	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	102
Building Code:	R2900307420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,258
Building Name:	Interstate SP Vault Toilet	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$607
Facility Condition Index:	0.04 - Excellent	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	47
Building Code:	R2900307430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,258
Building Name:	Interstate SP Vault Toilet	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$607
Facility Condition Index:	0.04 - Excellent	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	47
Building Code:	R2900308240	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,913
Building Name:	Interstate Group CG Vault Concrete	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$518
Facility Condition Index:	0.02 - Excellent	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	51
Building Code:	R2900308250	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,913
Building Name:	Interstate Group CG Vault Concrete	**Address:**	307 MILLTOWN RD	**Deferred Maintenance:**	$518
Facility Condition Index:	0.02 - Excellent	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	51

Site: R290030 - Itasca State Park

Building Code:	R2900100150	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Itasca Pine Rdg CG Pine E Uni Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	30
Building Code:	R2900100160	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Itasca Pine Rdg CG Poplar E Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	30
Building Code:	R2900100170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Itasca Pine Rdg CG Poplar W Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	30
Building Code:	R2900100180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Itasca Pine Rdg CG Pine W Uni Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	30
Building Code:	R2900100190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Itasca Bear Paw CG Ice House Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	30

Building Code:	R2900100210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Itasca Bear Paw CG Walk-in Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	30
Building Code:	R2900100250	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$130,117
Building Name:	Itasca SP Boat Shop Log Picnic Shel	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$15,271
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	867
Building Code:	R2900100270	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,064
Building Name:	Itasca SP Tower Area Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,040
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35
Building Code:	R2900100290	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,748
Building Name:	Itasca SP Red Pine/Ozawi Adirondack	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,567
Facility Condition Index:	0.33 - Poor	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	111
Building Code:	R2900100300	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,748
Building Name:	Itasca SP Desoto/Eagle Adirondack	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$475
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	111
Building Code:	R2900100310	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,748
Building Name:	Itasca SP Deer Prk/Alton Adirondack	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,106
Facility Condition Index:	0.23 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	111
Building Code:	R2900100940	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,220
Building Name:	Itasca SP McKay Lake Adirondack	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,749
Facility Condition Index:	0.65 - Crisis	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	111
Building Code:	R2900100970	**Cost Model Name:**	Tower	**Current Replacement Value:**	$16,204
Building Name:	Itasca SP Aiton Heights Fire Tower	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,620
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	64
Building Code:	R2900101370	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$420,947
Building Name:	Itasca SP Old HQ Office	**Address:**	27841 FOREST LN	**Deferred Maintenance:**	$72,510
Facility Condition Index:	0.17 - Fair	**City Code:**	SHEVLIN	**Ext. Gross Area:**	1,926
Building Code:	R2900101380	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$74,427
Building Name:	Itasca SP Old HQ Residence Garage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$11,248
Facility Condition Index:	0.15 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	565
Building Code:	R2900101390	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$688,196
Building Name:	Itasca SP Residence	**Address:**	27859 FOREST LN	**Deferred Maintenance:**	$104,244
Facility Condition Index:	0.15 - Fair	**City Code:**	SHEVLIN	**Ext. Gross Area:**	3,118
Building Code:	R2900101400	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$237,042
Building Name:	Itasca SP Picnic Sanitation	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$38,513
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	481

Building Code:	R2900101410	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$516,466
Building Name:	Itasca SP Museum	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$74,342
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,887
Building Code:	R2900101430	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$1,009,621
Building Name:	Itasca SP Beach Bath House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$126,437
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,516
Building Code:	R2900101450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$92,212
Building Name:	Itasca SP Boat House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$19,824
Facility Condition Index:	0.21 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,019
Building Code:	R2900101460	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$156,390
Building Name:	Itasca SP Ozawindib Lake Cabin	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$27,042
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	697
Building Code:	R2900101470	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$655,842
Building Name:	Itasca SP Ozawindib Dining Hall	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$86,935
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,218
Building Code:	R2900101490	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$276,218
Building Name:	Itasca SP Ozawindib Rental Cabin	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$65,809
Facility Condition Index:	0.24 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	870
Building Code:	R2900101500	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,473
Building Name:	Itasca SP Douglas Clubhouse Storage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$849
Facility Condition Index:	0.24 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	19
Building Code:	R2900101510	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$32,115
Building Name:	Itasca SP North Contact Station	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$6,926
Facility Condition Index:	0.22 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	123
Building Code:	R2900101550	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$1,073,515
Building Name:	Itasca SP Youth Hostel	**Address:**	27910 FOREST LN	**Deferred Maintenance:**	$263,048
Facility Condition Index:	0.25 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	7,173
Building Code:	R2900101560	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$245,031
Building Name:	Itasca Cardboard Recycling Storage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$27,913
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,616
Building Code:	R2900101570	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$112,425
Building Name:	Itasca SP Boat Shop 3-Stall Garage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$19,604
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	945
Building Code:	R2900101580	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$80,068
Building Name:	Itasca SP Boat Shop Lumber Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$21,733
Facility Condition Index:	0.27 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,240

Building Code:	R2900101590	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,507
Building Name:	Itasca SP Bike Rental Pump Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,688
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	37
Building Code:	R2900101600	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,783,543
Building Name:	Itasca SP Shop	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$429,973
Facility Condition Index:	0.24 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	8,956
Building Code:	R2900101610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$43,251
Building Name:	Itasca SP Boat Shop Oil House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$5,095
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	216
Building Code:	R2900101620	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$191,469
Building Name:	Itasca SP Boat Shop Plumbers Shop	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$23,200
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,036
Building Code:	R2900101630	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$167,788
Building Name:	Itasca SP CCC Water Tower Shop Yard	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$28,058
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	331
Building Code:	R2900101640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$157,903
Building Name:	Itasca SP Boat Shop 5-Stall Garage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$19,734
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,519
Building Code:	R2900101650	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$351,610
Building Name:	Itasca SP Douglas Lodge Cabin 16	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$68,632
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	880
Building Code:	R2900101660	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$126,136
Building Name:	Itasca Pine Ridge CG Contact Sta	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$24,823
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	342
Building Code:	R2900101670	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$937,885
Building Name:	Itasca Bear Paw CG Old Store	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$70,146
Facility Condition Index:	0.07 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,921
Building Code:	R2900101680	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$312,397
Building Name:	Itasca Bear Paw CG South Sanitation	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$73,704
Facility Condition Index:	0.24 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	443
Building Code:	R2900101690	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$959,518
Building Name:	Itasca Bear Paw CG Shower/Toilet	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$144,589
Facility Condition Index:	0.15 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,606
Building Code:	R2900101700	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$180,431
Building Name:	Itasca Bear Paw CG North Sanitation	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$44,414
Facility Condition Index:	0.25 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	280

Building Code:	R2900101710	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$66,618
Building Name:	Itasca Bear Paw CG Old Log Pumphse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$11,237
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	159
Building Code:	R2900101720	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$130,358
Building Name:	Itasca Bear Paw CG Ice House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$13,036
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	830
Building Code:	R2900101730	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$52,973
Building Name:	Itasca Bear Paw CG Fish Cleang Hse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$10,074
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	187
Building Code:	R2900101740	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$112,326
Building Name:	Itasca SP Bear Paw Cabin 1	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$16,738
Facility Condition Index:	0.15 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	362
Building Code:	R2900101750	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$146,175
Building Name:	Itasca SP Bear Paw Cabin 2	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$28,407
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	363
Building Code:	R2900101760	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$124,434
Building Name:	Itasca SP Bear Paw Cabin 3	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$25,204
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	363
Building Code:	R2900101770	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$146,119
Building Name:	Itasca SP Bear Paw Cabin 4	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$25,934
Facility Condition Index:	0.18 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	363
Building Code:	R2900101780	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$146,119
Building Name:	Itasca SP Bear Paw Cabin 5	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$25,070
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	363
Building Code:	R2900101790	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$147,201
Building Name:	Itasca SP Bear Paw Cabin 6	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$26,559
Facility Condition Index:	0.18 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	363
Building Code:	R2900101800	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$181,398
Building Name:	Itasca Pine Ridge CG Pump House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$19,453
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	414
Building Code:	R2900101810	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$255,873
Building Name:	Itasca Pine Rdg CG Oak Loop San Bld	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$60,821
Facility Condition Index:	0.24 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	670
Building Code:	R2900101830	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$258,069
Building Name:	Itasca Pine Rdg CG Maple Loop San	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$47,967
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	670

Building Code:	R2900101850	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$44,846
Building Name:	Itasca SP Old HQ 2-Stall Garage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$4,485
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	634
Building Code:	R2900101910	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,584,431
Building Name:	Itasca SP Douglas Lodge Forest Inn	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$373,104
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	6,690
Building Code:	R2900101920	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$303,031
Building Name:	Itasca SP Forest Inn Stone Toilet	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$58,170
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	422
Building Code:	R2900101930	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$2,009,762
Building Name:	Itasca SP Douglas Lodge Dormitory	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$284,007
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	5,655
Building Code:	R2900101940	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$5,189,059
Building Name:	Itasca SP Douglas Lodge	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$737,772
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	14,521
Building Code:	R2900101950	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$1,334,569
Building Name:	Itasca SP Douglas Nicollet Court	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$775,233
Facility Condition Index:	0.58 - Crisis	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	8,280
Building Code:	R2900101960	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$694,674
Building Name:	Itasca SP Douglas Lodge Fourplex	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$69,467
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,100
Building Code:	R2900101970	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$1,295,701
Building Name:	Itasca SP Douglas Lodge Clubhouse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$193,131
Facility Condition Index:	0.15 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	3,715
Building Code:	R2900101980	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$314,703
Building Name:	Itasca SP Douglas Lodge Cabin 11	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$46,893
Facility Condition Index:	0.15 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	769
Building Code:	R2900101990	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$111,588
Building Name:	Itasca SP Douglas Lodge Cabin 1	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$23,975
Facility Condition Index:	0.21 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	512
Building Code:	R2900102000	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$166,590
Building Name:	Itasca SP Douglas Lodge Cabin 4	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$33,612
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	768
Building Code:	R2900102010	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$304,674
Building Name:	Itasca SP Douglas Lodge Cabin 5	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$33,448
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	851

Building Code:	R2900102020	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$423,181
Building Name:	Itasca SP Douglas Lodge Cabin 6	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$67,873
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,280
Building Code:	R2900102030	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$393,586
Building Name:	Itasca SP Douglas Lodge Cabin 7	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$39,359
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,128
Building Code:	R2900102040	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$291,719
Building Name:	Itasca SP Douglas Lodge Cabin 8	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$33,241
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	810
Building Code:	R2900102050	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$338,877
Building Name:	Itasca SP Douglas Lodge Cabin 9	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$33,888
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,035
Building Code:	R2900102060	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$388,178
Building Name:	Itasca SP Douglas Lodge Cabin 10	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$62,456
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,184
Building Code:	R2900102070	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$410,314
Building Name:	Itasca SP Douglas Lodge Cabin 12	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$57,305
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,178
Building Code:	R2900102080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$378,850
Building Name:	Itasca SP Douglas Lodge Cabin 14	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$44,568
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	512
Building Code:	R2900102090	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$145,808
Building Name:	Itasca SP Douglas Lodge Cabin 15	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$23,864
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	512
Building Code:	R2900102100	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$18,964
Building Name:	Itasca SP Boat Shop Area Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,896
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	366
Building Code:	R2900102110	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$163,223
Building Name:	Itasca SP Douglas Lodge Pump House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$26,409
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	178
Building Code:	R2900102120	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$95,379
Building Name:	Itasca SP Douglas Old Timers Cabin	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$9,538
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	455
Building Code:	R2900102140	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$26,042
Building Name:	Itasca Boat Landing Fish Cleang Hse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$4,656
Facility Condition Index:	0.18 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	167

Building Code:	R2900102150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,526
Building Name:	Itasca Pine Rdg CG Reg Wood Storage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$10,471
Facility Condition Index:	0.25 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	336
Building Code:	R2900103380	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$625,714
Building Name:	Itasca SP FOR Site Residence	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$84,947
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	3,471
Building Code:	R2900103390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$408,239
Building Name:	Itasca SP FOR 3-Stall Warehouse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$74,168
Facility Condition Index:	0.18 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,519
Building Code:	R2900103420	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,367
Building Name:	Itasca SP FOR 1-Stall Garage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$4,574
Facility Condition Index:	0.15 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	267
Building Code:	R2900103440	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$39,515
Building Name:	Itasca SP FOR Pump House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$7,564
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	186
Building Code:	R2900103450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$176,261
Building Name:	Itasca SP FOR 4-Stall Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$27,488
Facility Condition Index:	0.16 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,561
Building Code:	R2900104390	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$193,526
Building Name:	Itasca Bear Paw Pumphouse by Cabins	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$24,317
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	292
Building Code:	R2900104400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,870
Building Name:	Itasca SP CG Registration Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,934
Facility Condition Index:	0.22 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	73
Building Code:	R2900104410	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$110,000
Building Name:	Itasca SP Boat Shop Wegmans Store	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$29,801
Facility Condition Index:	0.27 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	509
Building Code:	R2900104420	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$37,454
Building Name:	Itasca SP Boat Shop Well Pump House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$8,246
Facility Condition Index:	0.22 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	205
Building Code:	R2900104430	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$138,201
Building Name:	Itasca SP Elk Lake CG Cabin	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$126,102
Facility Condition Index:	0.91 - Crisis	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	481
Building Code:	R2900104440	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$46,952
Building Name:	Itasca SP Elk Lake CG Dining Hall	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$17,600
Facility Condition Index:	0.37 - Poor	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	533

Building Code:	R2900104450	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,740
Building Name:	Itasca SP Pumphouse on Lake Trail	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$18,607
Facility Condition Index:	0.55 - Crisis	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	221
Building Code:	R2900104770	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,752
Building Name:	Itasca SP Douglas Fish Cleaning Hse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,774
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900104780	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$14,706
Building Name:	Itasca SP Water Tower Near Hostel	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,259
Facility Condition Index:	0.22 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	289
Building Code:	R2900104820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$7,963
Building Name:	Itasca SP Douglas Boat Tour U Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$992
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	24
Building Code:	R2900104830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,003
Building Name:	Itasca SP Boat Landing Unisex Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,237
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	29
Building Code:	R2900104840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,316
Building Name:	Itasca SP HW Mens Vault Near Picnic	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,235
Facility Condition Index:	0.15 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	24
Building Code:	R2900104850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,316
Building Name:	Itasca SP HW Wmn Vault Near Picnic	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,027
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	24
Building Code:	R2900104860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,316
Building Name:	Itasca SP Elk Lake CG Mens Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,027
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	24
Building Code:	R2900104870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,316
Building Name:	Itasca SP Elk Lake CG Womens Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,027
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	24
Building Code:	R2900104880	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,007
Building Name:	Itasca SP North Contact Sta Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,096
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	24
Building Code:	R2900106140	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$71,736
Building Name:	Itasca SP Nicolette Cabin	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$14,039
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	572
Building Code:	R2900106220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$363,297
Building Name:	Itasca SP Gift Warehouse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$50,954
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,943

Building Code:	R2900106340	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$143,896
Building Name:	Itasca SP Boat Shop Quonset Storage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$17,940
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	974
Building Code:	R2900106530	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,463
Building Name:	Itasca Pine Rdg CG Registra Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,841
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106540	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,463
Building Name:	Itasca Pine Rdg CG Maple Loop Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,841
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106620	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,413
Building Name:	Itasca SP Aiton Hts Fire Tower Cab	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$541
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	64
Building Code:	R2900106630	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,821
Building Name:	Itasca SP Lake Oza Cabin Wood Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$465
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	40
Building Code:	R2900106640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,463
Building Name:	Itasca SP Bison Kill Vault Toilet	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,217
Facility Condition Index:	0.15 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106650	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,603
Building Name:	Itasca SP Ozawindib Well House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$971
Facility Condition Index:	0.27 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	16
Building Code:	R2900106810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,463
Building Name:	Itasca Pine Rdg CG Spruce E Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,217
Facility Condition Index:	0.15 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,463
Building Name:	Itasca Pine Rdg CG Oak Loop Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,793
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106830	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$36,991
Building Name:	Itasca SP Douglas Lodge Kiosk	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,699
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	360
Building Code:	R2900107150	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$44,744
Building Name:	Itasca SP Ozawindib Pumphouse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$4,723
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	200
Building Code:	R2900107160	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$349,201
Building Name:	Itasca Pine Rdg CG Spruce Loop San	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$46,420
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,154

Building Code:	R2900107170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$788,941
Building Name:	Itasca SP Douglas Admin Office	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$99,433
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	3,947
Building Code:	R2900107180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$42,183
Building Name:	Itasca SP Douglas Admin Pumphouse	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$5,896
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	563
Building Code:	R2900107190	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,405,340
Building Name:	Itasca SP Douglas Jacob Brower Ctr	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$487,587
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	13,481
Building Code:	R2900107270	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$88,913
Building Name:	Itasca SP Douglas East Contact Sta	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$15,938
Facility Condition Index:	0.18 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	265
Building Code:	R2900107280	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$349,201
Building Name:	Itasca Pine Rdg CG Pine Loop San	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$34,920
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,154
Building Code:	R2900107590	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$796,639
Building Name:	Itasca SP Douglas Lodge Suites 1	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$87,319
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	4,253
Building Code:	R2900107600	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$699,564
Building Name:	Itasca SP Douglas Lodge Suites 2	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$77,611
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	4,253
Building Code:	R2900107800	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$381,631
Building Name:	Itasca SP Ozawindib Sanitation	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$38,163
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,121
Building Code:	R2900107840	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$3,245,991
Building Name:	Itasca SP HW Mary Gibbs Center	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$157,083
Facility Condition Index:	0.05 - Excellent	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	6,156
Building Code:	R2900107900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,739
Building Name:	Itasca SP ADA Vault Toilet	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,674
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900107910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,739
Building Name:	Itasc SP Ozawindib Cabin Vault toil	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,360
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900108170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,324
Building Name:	Itasca SP HW Gibbs Well House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,732
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	96

Building Code:	R2900108280	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$25,927
Building Name:	Itasca SP Doug Cabin 16 Screen Shel	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,593
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	166
Building Code:	R2900108420	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$40,449
Building Name:	Itasca SP Doug Refrigerated Storage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$809
Facility Condition Index:	0.02 - Excellent	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	180
Building Code:	R2900109340	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$69,761
Building Name:	Itasca SP Amphitheater	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,395
Facility Condition Index:	0.02 - Excellent	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	310
Building Code:	R2900109690	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$140,088
Building Name:	Itasca SP - Bert's Cabins Cabin #1	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$17,064
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	603
Building Code:	R2900109700	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$258,792
Building Name:	Itasca SP - Bert's Cabins Cabin #2	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$25,879
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	960
Building Code:	R2900109710	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$137,335
Building Name:	Itasca SP - Bert's Cabins Cabin #3	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$14,176
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	510
Building Code:	R2900109720	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$211,117
Building Name:	Itasca SP - Bert's Cabins Cabin #4	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$21,112
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	906
Building Code:	R2900109730	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$167,392
Building Name:	Itasca SP - Bert's Cabins Cabin #5	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$20,478
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	739
Building Code:	R2900109740	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$89,241
Building Name:	Itasca SP - Bert's Cabins Cabin #6	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$12,544
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	383
Building Code:	R2900109750	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$230,939
Building Name:	Itasca SP - Bert's Cabins Cabin #7	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$23,094
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,013
Building Code:	R2900109760	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$233,438
Building Name:	Itasca SP - Bert's Cabins Cabin #8	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$23,344
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,070
Building Code:	R2900109770	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$218,693
Building Name:	Itasca SP - Bert's Cabins Cabin #9	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$21,869
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	921

Building Code:	R2900109780	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$211,888
Building Name:	Itasca SP - Bert's Cabins Cabin #10	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$21,189
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	906
Building Code:	R2900109790	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$79,793
Building Name:	Itasca SP - Bert's Cabins Cabin #11	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$8,286
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	354
Building Code:	R2900109800	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$102,410
Building Name:	Itasca SP - Bert's Cabins Cabin #12	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$12,399
Facility Condition Index:	0.12 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	426
Building Code:	R2900109810	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$480,101
Building Name:	Itasca SP - Bert's Residence	**Address:**	15782 WILDERNESS DRIVE	**Deferred Maintenance:**	$70,862
Facility Condition Index:	0.15 - Good	**City Code:**	LAKE ITASCA	**Ext. Gross Area:**	1,820
Building Code:	R2900109820	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$341,445
Building Name:	Itasca SP - Bert's SHOP	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$83,732
Facility Condition Index:	0.25 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,140
Building Code:	R2900109830	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$133,215
Building Name:	Itasca SP - Bert's Lg Storage Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$13,322
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,700
Building Code:	R2900109840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,517
Building Name:	Itasca SP - Bert's Ice House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$24,388
Facility Condition Index:	0.75 - Crisis	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	216
Building Code:	R2900109850	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$13,641
Building Name:	Itasca SP - Bert's Open Store Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$6,087
Facility Condition Index:	0.45 - Poor	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	288
Building Code:	R2900109860	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$24,085
Building Name:	Itasca SP - Bert's Wood Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$7,948
Facility Condition Index:	0.33 - Poor	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	480
Building Code:	R2900109870	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$119,758
Building Name:	Itasca SP - Bert's Detached Garage	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$11,976
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	952
Building Code:	R2900109880	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,138
Building Name:	Itasca SP - Bert's Pool House	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,266
Facility Condition Index:	0.15 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	64
Building Code:	R2900109890	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$83,530
Building Name:	Itasca SP - Bert's Laundry	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$11,025
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	588

Building Code:	R2900109900	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,171
Building Name:	Itasca SP - Bert's Homestead Shack	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,317
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	64
Building Code:	R2900109910	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,603
Building Name:	Itasca SP - Bert's Fish Cleaning Ho	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$331
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	25

Site: R290031 - Jay Cooke State Park

Building Code:	R2900200510	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$47,495
Building Name:	Jay Cooke SP Shop/Recycling/Wood	**Address:**	780 HWY 210	**Deferred Maintenance:**	$7,854
Facility Condition Index:	0.17 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	576
Building Code:	R2900200570	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,415,091
Building Name:	Jay Cooke SP River Inn Interp Ctr	**Address:**	780 HWY 210	**Deferred Maintenance:**	$292,847
Facility Condition Index:	0.21 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	4,464
Building Code:	R2900200580	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$276,808
Building Name:	Jay Cooke SP Oldenburg Sanitation	**Address:**	780 HWY 210	**Deferred Maintenance:**	$132,924
Facility Condition Index:	0.48 - Poor	**City Code:**	CARLTON	**Ext. Gross Area:**	756
Building Code:	R2900200590	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$457,561
Building Name:	Jay Cooke Oldenburg Picnic Shelter	**Address:**	780 HWY 210	**Deferred Maintenance:**	$121,280
Facility Condition Index:	0.27 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	1,300
Building Code:	R2900200600	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$83,223
Building Name:	Jay Cooke SP Spring House	**Address:**	780 HWY 210	**Deferred Maintenance:**	$27,463
Facility Condition Index:	0.33 - Poor	**City Code:**	CARLTON	**Ext. Gross Area:**	195
Building Code:	R2900200630	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$343,930
Building Name:	Jay Cooke SP Historic Residence	**Address:**	780 HWY 210	**Deferred Maintenance:**	$197,034
Facility Condition Index:	0.57 - Crisis	**City Code:**	CARLTON	**Ext. Gross Area:**	1,258
Building Code:	R2900203710	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$398,554
Building Name:	Jay Cooke SP Shop	**Address:**	780 HWY 210	**Deferred Maintenance:**	$111,881
Facility Condition Index:	0.28 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	2,061
Building Code:	R2900206740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,118
Building Name:	Jay Cooke SP Grp CG Men Vault Toil	**Address:**	780 HWY 210	**Deferred Maintenance:**	$3,339
Facility Condition Index:	0.33 - Poor	**City Code:**	CARLTON	**Ext. Gross Area:**	30
Building Code:	R2900206750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,118
Building Name:	Jay Cooke SP Grp CG Wom Vault Toil	**Address:**	780 HWY 210	**Deferred Maintenance:**	$3,339
Facility Condition Index:	0.33 - Poor	**City Code:**	CARLTON	**Ext. Gross Area:**	30

Building Code:	R2900206770	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,118
Building Name:	Jay Cooke SP Contact Sta Vault Toil	**Address:**	780 HWY 210	**Deferred Maintenance:**	$3,293
Facility Condition Index:	0.33 - Poor	**City Code:**	CARLTON	**Ext. Gross Area:**	30
Building Code:	R2900207930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,341
Building Name:	Jay Cooke SP CG Site 32 Vault Toil	**Address:**	780 HWY 210	**Deferred Maintenance:**	$1,063
Facility Condition Index:	0.07 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	41
Building Code:	R2900207940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,341
Building Name:	Jay Cooke SP CG Site 76 Vault Toil	**Address:**	780 HWY 210	**Deferred Maintenance:**	$1,063
Facility Condition Index:	0.07 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	41
Building Code:	R2900207950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,341
Building Name:	Jay Cooke SP CG Site 78 Vault Toil	**Address:**	780 HWY 210	**Deferred Maintenance:**	$1,063
Facility Condition Index:	0.07 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	41
Building Code:	R2900208630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	Jay Cooke SP CG Vault Toilet	**Address:**	780 HWY 210	**Deferred Maintenance:**	$1,213
Facility Condition Index:	0.07 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	51
Building Code:	R2900208640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,575
Building Name:	Jay Cooke SP CG Vault Toilet	**Address:**	780 HWY 210	**Deferred Maintenance:**	$1,557
Facility Condition Index:	0.10 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	51
Building Code:	R2900208800	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$836,888
Building Name:	Jay Cooke SP Contact Station	**Address:**	780 HWY 210	**Deferred Maintenance:**	$83,094
Facility Condition Index:	0.10 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	2,173
Building Code:	R2900208810	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$36,621
Building Name:	Jay Cooke SP HQ Wood Shed	**Address:**	780 HWY 210	**Deferred Maintenance:**	$2,141
Facility Condition Index:	0.06 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	320
Building Code:	R2900208940	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$80,217
Building Name:	Jay Cooke SP CG Slate Cabin	**Address:**	780 HWY 210	**Deferred Maintenance:**	$3,258
Facility Condition Index:	0.04 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	335
Building Code:	R2900208950	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$80,217
Building Name:	Jay Cooke SP CG Agate Cabin	**Address:**	780 HWY 210	**Deferred Maintenance:**	$3,258
Facility Condition Index:	0.04 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	335
Building Code:	R2900208960	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$80,217
Building Name:	Jay Cooke SP CG Gabbro Cabin	**Address:**	780 HWY 210	**Deferred Maintenance:**	$3,258
Facility Condition Index:	0.04 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	335
Building Code:	R2900208970	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$105,445
Building Name:	Jay Cooke SP CG Shale Cabin	**Address:**	780 HWY 210	**Deferred Maintenance:**	$4,828
Facility Condition Index:	0.05 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	335

Building Code:	R2900209050	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$87,871
Building Name:	Jay Cooke SP CG Basalt Cabin	**Address:**	780 HWY 210	**Deferred Maintenance:**	$4,023
Facility Condition Index:	0.05 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	296
Building Code:	R2900209420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,157
Building Name:	Jay Cooke SP CG Vault Concrete	**Address:**	780 HWY 210	**Deferred Maintenance:**	$5,232
Facility Condition Index:	0.10 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	96
Building Code:	R2900210480	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$107,268
Building Name:	Jay Cooke SP Solar Garage	**Address:**	780 HWY 210	**Deferred Maintenance:**	$4,032
Facility Condition Index:	0.04 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	642
Building Code:	R2900210660	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,656
Building Name:	Jay Cooke Oldenburg Vault Concrete	**Address:**	780 Hwy 210	**Deferred Maintenance:**	$513
Facility Condition Index:	0.02 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	51

Site: R290032 - Judge CR Magney State Park

Building Code:	R2900200820	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$319,739
Building Name:	Judge CR Magney SP Office	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$84,001
Facility Condition Index:	0.26 - Fair	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	1,110
Building Code:	R2900200830	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$156,261
Building Name:	Judge CR Magney SP Shop	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$36,054
Facility Condition Index:	0.23 - Fair	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	720
Building Code:	R2900200850	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$42,693
Building Name:	Judge CR Magney SP Contct Station	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$4,269
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	260
Building Code:	R2900200870	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,543
Building Name:	Judge CR Magney SP Spring House	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$4,872
Facility Condition Index:	0.23 - Fair	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	64
Building Code:	R2900200880	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$46,202
Building Name:	Judge CR Magney SP Cold Storage	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$11,223
Facility Condition Index:	0.24 - Fair	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	480
Building Code:	R2900204190	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,941
Building Name:	Judge CR Magney SP Cold Storage	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$8,350
Facility Condition Index:	0.70 - Crisis	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	128
Building Code:	R2900204310	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$56,327
Building Name:	Judge CR Magney SP Garage	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$4,383
Facility Condition Index:	0.08 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	576

Building Code:	R2900205910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,966
Building Name:	Judge CR Magney SP Vault Toilet	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$1,442
Facility Condition Index:	0.12 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	30
Building Code:	R2900207410	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$290,227
Building Name:	Judge CR Magney SP CG Sanitation	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$29,023
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	850
Building Code:	R2900207600	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$159,517
Building Name:	Judge CR Magney SP Water Tower	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$15,674
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	308
Building Code:	R2900208160	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Judge CR Magney SP CG Vault Toilet	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$2,094
Facility Condition Index:	0.12 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	42
Building Code:	R2900208170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Judge CR Magney SP CG Vault Toilet	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$2,883
Facility Condition Index:	0.17 - Fair	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	42
Building Code:	R2900208180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Judge CR Magney SP CG Vault Toilet	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$1,701
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	42
Building Code:	R2900209510	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,421
Building Name:	Judge CR Magney SP Shed	**Address:**	4051 E HWY 61	**Deferred Maintenance:**	$128
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	65

Site: R290033 - Kilen Woods State Park

Building Code:	R2900401210	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$101,818
Building Name:	Kilen Woods SP Cold Storage	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$33,605
Facility Condition Index:	0.33 - Poor	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	880
Building Code:	R2900401250	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$351,141
Building Name:	Kilen Woods SP Trails Center	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$136,092
Facility Condition Index:	0.39 - Poor	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	1,643
Building Code:	R2900404350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,043
Building Name:	Kilen Woods SP Vault Toilet	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$1,827
Facility Condition Index:	0.23 - Fair	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	24
Building Code:	R2900404680	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$326,083
Building Name:	Kilen Woods SP Contact Station	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$16,596
Facility Condition Index:	0.05 - Good	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	900

Building Code:	R2900404690	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$417,116
Building Name:	Kilen Woods SP Sanitation	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$9,498
Facility Condition Index:	0.02 - Excellent	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	1,070
Building Code:	R2900404700	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$317,586
Building Name:	Kilen Woods SP Shop	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$6,352
Facility Condition Index:	0.02 - Excellent	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	2,020
Building Code:	R2900405200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,043
Building Name:	Kilen Woods SP Grp CG Vault Toilet	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$1,859
Facility Condition Index:	0.23 - Fair	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	24
Building Code:	R2900405210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,043
Building Name:	Kilen Woods SP Vault Toilet	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$1,859
Facility Condition Index:	0.23 - Fair	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	24
Building Code:	R2900405420	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$2,308
Building Name:	Kilen Woods SP Firewood Shed	**Address:**	50200 860TH ST	**Deferred Maintenance:**	$231
Facility Condition Index:	0.10 - Good	**City Code:**	LAKEFIELD	**Ext. Gross Area:**	24

Site: R290034 - Lac Qui Parle State Park

Building Code:	R2900400910	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$152,423
Building Name:	Lac Qui Parle SP Lower CG Sanitatio	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$73,602
Facility Condition Index:	0.48 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	331
Building Code:	R2900400920	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$499,217
Building Name:	Lac Qui Parle SP Office	**Address:**	3749 STATE PARK RD	**Deferred Maintenance:**	$178,369
Facility Condition Index:	0.36 - Poor	**City Code:**	MONTEVIDEO	**Ext. Gross Area:**	2,554
Building Code:	R2900400930	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$98,198
Building Name:	LQParle SP Horse Camp Picnic Shel 1	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$32,405
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	960
Building Code:	R2900400940	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$326,091
Building Name:	Lac Qui Parle SP Lower CG Map Shel	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$107,610
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	1,936
Building Code:	R2900400950	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$231,798
Building Name:	Lac Qui Parle SP Low CG Pic Shel 2	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$76,493
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	1,299
Building Code:	R2900400960	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$137,110
Building Name:	Lac Qui Parle SP Lower CG Bathhouse	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$45,246
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	430

Building Code:	R2900400970	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$253,799
Building Name:	Lac Qui Parle SP Shop	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$75,880
Facility Condition Index:	0.30 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	1,500
Building Code:	R2900400980	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,540
Building Name:	Lac Qui Parle SP Shop Ar Oil House	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$5,109
Facility Condition Index:	0.31 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	120
Building Code:	R2900400990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$112,314
Building Name:	Lac Qui Parle SP Shop Cold Storage	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$46,425
Facility Condition Index:	0.41 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	837
Building Code:	R2900402880	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$25,672
Building Name:	Lac Qui Parle SP Contact Station	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$8,472
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	189
Building Code:	R2900403540	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,844
Building Name:	Lac Qui Parle SP Lower CG Vault	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$2,266
Facility Condition Index:	0.26 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	24
Building Code:	R2900403550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,844
Building Name:	Lac Qui Parle SP Lower CG Vault	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$2,266
Facility Condition Index:	0.26 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	24
Building Code:	R2900403640	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,587
Building Name:	Lac Qui Parle SP Shop Wood Storage	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$3,164
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	80
Building Code:	R2900403990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,694
Building Name:	Lac Qui Parle SP Vault Toilet	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$2,222
Facility Condition Index:	0.26 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	24
Building Code:	R2900404000	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,057
Building Name:	Lac Qui Parle SP Lower CG Pumphouse	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$6,289
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	78
Building Code:	R2900404410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,200
Building Name:	LQParle SP Horse Camp Vault Toilet	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$4,388
Facility Condition Index:	0.26 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	48
Building Code:	R2900404670	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$379,866
Building Name:	Lac Qui Parle SP Upper CG Sanitatio	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$43,885
Facility Condition Index:	0.12 - Good	**City Code:**	WATSON	**Ext. Gross Area:**	882
Building Code:	R2900404980	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,861
Building Name:	Lac Qui Parle SP Upper CG Vault	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$5,219
Facility Condition Index:	0.29 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	47

Building Code:	R2900404990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,861
Building Name:	Lac Qui Parle SP Upper CG Vault	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$3,493
Facility Condition Index:	0.20 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	47
Building Code:	R2900405000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,861
Building Name:	Lac Qui Parle SP Upper CG Vault	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$3,318
Facility Condition Index:	0.19 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	47
Building Code:	R2900405010	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,861
Building Name:	Lac Qui Parle SP Upper CG Vault	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$3,493
Facility Condition Index:	0.20 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	47
Building Code:	R2900405140	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$61,002
Building Name:	Lac Qui Parle SP Upper CG Cabin 1	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$6,100
Facility Condition Index:	0.10 - Good	**City Code:**	WATSON	**Ext. Gross Area:**	310
Building Code:	R2900405150	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$61,002
Building Name:	Lac Qui Parle SP Upper CG Cabin 2	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$6,100
Facility Condition Index:	0.10 - Good	**City Code:**	WATSON	**Ext. Gross Area:**	310
Building Code:	R2900405160	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$61,002
Building Name:	Lac Qui Parle SP Upper CG Cabin 3	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$6,100
Facility Condition Index:	0.10 - Good	**City Code:**	WATSON	**Ext. Gross Area:**	310
Building Code:	R2900405260	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,745
Building Name:	Lac Qui Parle SP Lower CG Wood Stor	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$195
Facility Condition Index:	0.02 - Excellent	**City Code:**	WATSON	**Ext. Gross Area:**	96
Building Code:	R2900405370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$29,504
Building Name:	Lac Qui Parle SP Low CG Vault Concr	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$590
Facility Condition Index:	0.02 - Excellent	**City Code:**	WATSON	**Ext. Gross Area:**	51
Building Code:	R2900405380	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,587
Building Name:	Lac Qui Parle SP Upper CG Shed	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$1,592
Facility Condition Index:	0.17 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	18

Site: R290035 - Lake Bemidji State Park

Building Code:	R2900102330	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$296,462
Building Name:	Lake Bemidji SP Beach San/Cabanas	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$42,350
Facility Condition Index:	0.14 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	748
Building Code:	R2900102340	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$270,397
Building Name:	Lake Bemidji SP CG Oak Lane San	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$38,965
Facility Condition Index:	0.14 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	840

Building Code:	R2900102360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$360,271
Building Name:	Lake Bemidji SP Shop	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$72,656
Facility Condition Index:	0.20 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,743
Building Code:	R2900102370	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$63,921
Building Name:	Lake Bemidji SP Residence Garage	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$7,823
Facility Condition Index:	0.12 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	720
Building Code:	R2900102380	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,984
Building Name:	Lake Bemidji SP Oil House	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,563
Facility Condition Index:	0.14 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	72
Building Code:	R2900102390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$99,020
Building Name:	Lake Bemidji SP Trails Storage	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$16,927
Facility Condition Index:	0.17 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	820
Building Code:	R2900102400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,134
Building Name:	Lake Bemidji SP Pump House	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$5,495
Facility Condition Index:	0.24 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	72
Building Code:	R2900102410	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$499,231
Building Name:	Lake Bemidji SP Grp CG Dining Hall	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$109,297
Facility Condition Index:	0.22 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,600
Building Code:	R2900102420	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$438,869
Building Name:	Lake Bemidji SP Office	**Address:**	3296 STATE PARK RD NE	**Deferred Maintenance:**	$61,282
Facility Condition Index:	0.14 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,879
Building Code:	R2900102460	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$113,943
Building Name:	Lake Bemidji SP Historic Log San	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$22,632
Facility Condition Index:	0.20 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	506
Building Code:	R2900102480	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$456,791
Building Name:	Lake Bemidji SP Beach Picnic Shel	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$46,922
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,830
Building Code:	R2900104210	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$918,161
Building Name:	Lake Bemidji SP Contact Station	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$123,244
Facility Condition Index:	0.13 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	5,457
Building Code:	R2900104220	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$435,004
Building Name:	Lake Bemidji SP CG Aspen Lane San	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$97,970
Facility Condition Index:	0.23 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,120
Building Code:	R2900105230	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,010
Building Name:	Lake Bemidji SP Oil House	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,422
Facility Condition Index:	0.19 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	96

Building Code:	R2900105700	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,505
Building Name:	Lake Bemidji SP Bass Crk Mens Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,050
Facility Condition Index:	0.12 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	24
Building Code:	R2900105710	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$7,868
Building Name:	Lake Bemidji SP Bass Crk Wmns Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,290
Facility Condition Index:	0.16 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	24
Building Code:	R2900105720	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,785
Building Name:	Lake Bemidji SP Boat Launch Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$3,320
Facility Condition Index:	0.28 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	35
Building Code:	R2900105750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,505
Building Name:	Lake Bemidji SP Picnic Mens Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,050
Facility Condition Index:	0.12 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	24
Building Code:	R2900105760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,484
Building Name:	Lake Bemidji SP Picnic Wmns Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,043
Facility Condition Index:	0.12 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	24
Building Code:	R2900106780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,266
Building Name:	Lake Bemidji SP Picnic Amphitheater	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$5,115
Facility Condition Index:	0.24 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	165
Building Code:	R2900107030	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$115,954
Building Name:	Lake Bemidji SP Metal Storage Shop	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$11,595
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,120
Building Code:	R2900107210	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$414,241
Building Name:	Lake Bemidji SP CG Pine Lane San	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$46,664
Facility Condition Index:	0.11 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,140
Building Code:	R2900107220	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$25,642
Building Name:	Lake Bemidji SP Bass Crk Adirondack	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,564
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	168
Building Code:	R2900107230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,718
Building Name:	Lake Bemidji SP Main Parking Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,835
Facility Condition Index:	0.19 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	42
Building Code:	R2900107880	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,120
Building Name:	Lake Bemidji SP CG Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,712
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	48
Building Code:	R2900108300	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,120
Building Name:	Lake Bemidji SP Bog Walk Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,712
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	48

Building Code:	R2900108580	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$25,350
Building Name:	Lake Bemidji SP Fish Cleaning House	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,535
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	325
Building Code:	R2900109050	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$53,827
Building Name:	Lake Bemidji SP Tamarack Cabin	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$5,383
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	250
Building Code:	R2900109060	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$53,827
Building Name:	Lake Bemidji SP Spruce Cabin	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$5,383
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	250
Building Code:	R2900109070	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$53,827
Building Name:	Lake Bemidji SP Balsam Cabin	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,956
Facility Condition Index:	0.04 - Excellent	**City Code:**	BEMIDJI	**Ext. Gross Area:**	250
Building Code:	R2900109080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$53,827
Building Name:	Lake Bemidji SP Maple Cabin	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$4,630
Facility Condition Index:	0.09 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	250
Building Code:	R2900109090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$28,863
Building Name:	Lake Bemidji Tmrck Cab Concr Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,886
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	51
Building Code:	R2900109100	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$28,863
Building Name:	Lake Bemidji SP Maple Cabin Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,886
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	51
Building Code:	R2900109110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$19,808
Building Name:	Lake Bemidji Aspen Ln Concr Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$396
Facility Condition Index:	0.02 - Excellent	**City Code:**	BEMIDJI	**Ext. Gross Area:**	51
Building Code:	R2900109360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$28,863
Building Name:	Lake Bemidji Lavinia Grp CG W Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$577
Facility Condition Index:	0.02 - Excellent	**City Code:**	BEMIDJI	**Ext. Gross Area:**	51
Building Code:	R2900109370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$19,808
Building Name:	Lake Bemidji Lavinia Grp CG E Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$396
Facility Condition Index:	0.02 - Excellent	**City Code:**	BEMIDJI	**Ext. Gross Area:**	51
Building Code:	R2900109380	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,829
Building Name:	Lake Bemidji Lavinia Grp CG Pumphse	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$583
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	20
Building Code:	R2900109390	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$55,282
Building Name:	Lake Bemidji Lavinia Picnic Shel 2	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$5,528
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	675

Site: R290036 - Lake Bronson State Park

Building Code:	R2900100060	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,746
Building Name:	Lake Bronson Lakeside CG Vault Toil	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$1,678
Facility Condition Index:	0.16 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	30
Building Code:	R2900102600	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$353,375
Building Name:	Lake Bronson SP Two Rivers S San	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$65,464
Facility Condition Index:	0.19 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	936
Building Code:	R2900102610	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$361,143
Building Name:	Lake Bronson SP Lakeside CG San	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$50,270
Facility Condition Index:	0.14 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	768
Building Code:	R2900102630	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$282,745
Building Name:	Lake Bronson SP Contact Sta	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$83,384
Facility Condition Index:	0.29 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	1,192
Building Code:	R2900102640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$268,429
Building Name:	Lake Bronson SP Shop	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$36,327
Facility Condition Index:	0.14 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	1,840
Building Code:	R2900102650	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$437,113
Building Name:	Lake Bronson SP Residence	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$65,530
Facility Condition Index:	0.15 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	2,558
Building Code:	R2900102660	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$300,815
Building Name:	Lake Bronson SP Dining Hall	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$57,599
Facility Condition Index:	0.19 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	1,640
Building Code:	R2900102670	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$520,479
Building Name:	Lake Bronson SP Picnic Shelter 2	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$125,916
Facility Condition Index:	0.24 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	1,840
Building Code:	R2900102680	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$311,690
Building Name:	Lake Bronson Picnic Tip Trough San	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$98,495
Facility Condition Index:	0.32 - Poor	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	696
Building Code:	R2900102690	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$277,192
Building Name:	Lake Bronson SP Two Rivers San	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$41,573
Facility Condition Index:	0.15 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	858
Building Code:	R2900102700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$39,737
Building Name:	Lake Bronson SP Wood Storage	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$6,859
Facility Condition Index:	0.17 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	520

Building Code:	R2900102710	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$236,421
Building Name:	Lake Bronson Old Residence Storage	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$57,944
Facility Condition Index:	0.25 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	1,116
Building Code:	R2900102720	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$416,618
Building Name:	Lake Bronson SP Water Tower	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$85,121
Facility Condition Index:	0.20 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	744
Building Code:	R2900102730	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$555,456
Building Name:	Lake Bronson SP Bath House	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$58,132
Facility Condition Index:	0.10 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	1,012
Building Code:	R2900104310	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$100,920
Building Name:	Lake Bronson SP Residence Garage	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$20,946
Facility Condition Index:	0.21 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	720
Building Code:	R2900105050	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,861
Building Name:	Lake Bronson SP Contact Sta Shed	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$487
Facility Condition Index:	0.06 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	80
Building Code:	R2900105280	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$67,121
Building Name:	Lake Bronson SP Fish Cleaning House	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$17,377
Facility Condition Index:	0.26 - Fair	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	192
Building Code:	R2900106230	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,522,329
Building Name:	Lake Bronson SP Visitor Center	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$174,684
Facility Condition Index:	0.11 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	5,130
Building Code:	R2900106930	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,073
Building Name:	Lake Bronson SP Pump House	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$2,614
Facility Condition Index:	0.09 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	80
Building Code:	R2900106940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,045
Building Name:	Lake Bronson SP Vault Toilet	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$1,113
Facility Condition Index:	0.07 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	42
Building Code:	R2900107950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,028
Building Name:	Lake Bronson SP Two Rvrs Vault Toil	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$1,251
Facility Condition Index:	0.07 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	48
Building Code:	R2900107960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,500
Building Name:	Lake Bronson SP Vault Toilet	**Address:**	3793 230TH ST	**Deferred Maintenance:**	$1,298
Facility Condition Index:	0.07 - Good	**City Code:**	LAKE BRONSON	**Ext. Gross Area:**	48

Site: R290037 - Lake Carlos State Park

Building Code:	R2900102890	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$148,481
Building Name:	Lake Carlos SP Hid Lk GC Bunkhse 1	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$37,042
Facility Condition Index:	0.25 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	792
Building Code:	R2900102900	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$152,900
Building Name:	Lake Carlos SP Hid Lk GC Bunkhse 2	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$38,500
Facility Condition Index:	0.25 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	792
Building Code:	R2900102910	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$336,062
Building Name:	Lake Carlos SP Hid Lk GC Craft Bldg	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$44,025
Facility Condition Index:	0.13 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,152
Building Code:	R2900102920	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$404,316
Building Name:	Lake Carlos SP Hid Lk GC Staff Resd	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$71,569
Facility Condition Index:	0.18 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	1,824
Building Code:	R2900102930	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$673,241
Building Name:	Lake Carlos SP Hid Lk GC Dininghall	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$72,842
Facility Condition Index:	0.11 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,792
Building Code:	R2900102940	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$259,426
Building Name:	Lake Carlos SP Lkvw Picnic Area San	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$35,960
Facility Condition Index:	0.14 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	549
Building Code:	R2900102950	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$78,182
Building Name:	Lake Carlos SP Lkvw Picnic Shel 2	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$8,628
Facility Condition Index:	0.11 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,025
Building Code:	R2900102960	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$167,449
Building Name:	Lake Carlos SP Lkvw Pic Water Tower	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$24,700
Facility Condition Index:	0.15 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	345
Building Code:	R2900102970	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$471,864
Building Name:	Lake Carlos SP Beach Bath House	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$183,713
Facility Condition Index:	0.39 - Poor	**City Code:**	CARLOS	**Ext. Gross Area:**	1,193
Building Code:	R2900102990	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,088
Building Name:	Lake Carlos SP Pump House	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,009
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	36
Building Code:	R2900103010	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$119,276
Building Name:	Lake Carlos SP Upper CG South San	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$29,756
Facility Condition Index:	0.25 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	400
Building Code:	R2900103030	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,484
Building Name:	Lake Carlos SP Horse Camp Pumphouse	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$2,310
Facility Condition Index:	0.27 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	64

Building Code:	R2900103050	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$318,934
Building Name:	Lake Carlos SP Lower CG East San	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$52,078
Facility Condition Index:	0.16 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	1,015
Building Code:	R2900103060	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$48,864
Building Name:	Lake Carlos SP LowCG Fish Clean Hse	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$8,335
Facility Condition Index:	0.17 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	180
Building Code:	R2900103100	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$138,430
Building Name:	Lake Carlos SP Shop	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$16,970
Facility Condition Index:	0.12 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,516
Building Code:	R2900103110	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$57,161
Building Name:	Lake Carlos SP Shop Area Garage	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$11,519
Facility Condition Index:	0.20 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	720
Building Code:	R2900104480	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$327,972
Building Name:	Lake Carlos SP Residence	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$36,693
Facility Condition Index:	0.11 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,976
Building Code:	R2900104580	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$400,849
Building Name:	Lake Carlos SP Upper CG North San	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$42,720
Facility Condition Index:	0.11 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,330
Building Code:	R2900104590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$42,295
Building Name:	Lake Carlos SP Residence Garage	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$5,483
Facility Condition Index:	0.13 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	576
Building Code:	R2900104600	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$131,547
Building Name:	Lake Carlos SP Metal Cold Storage	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$14,309
Facility Condition Index:	0.11 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,764
Building Code:	R2900106170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$498,119
Building Name:	Lake Carlos SP Interpretive Ctr	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$61,189
Facility Condition Index:	0.12 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,702
Building Code:	R2900106190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,342
Building Name:	Lake Carlos SP Lower CG Vault	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,234
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	35
Building Code:	R2900106420	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$263,269
Building Name:	Lake Carlos SP Contact Station	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$38,890
Facility Condition Index:	0.15 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,226
Building Code:	R2900106430	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$420,927
Building Name:	Lake Carlos SP Lower CG West San	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$45,497
Facility Condition Index:	0.11 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,147

Building Code:	R2900106520	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,283
Building Name:	Lake Carlos SP Lakeview Pic Vault	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,628
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	48
Building Code:	R2900106970	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$2,201
Building Name:	Lake Carlos SP Contact Sta Kiosk	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$220
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	49
Building Code:	R2900106980	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Lake Carlos SP Contact Sta Vault	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,400
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	42
Building Code:	R2900107000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Lake Carlos SP Horse Camp Vault	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$2,237
Facility Condition Index:	0.16 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	42
Building Code:	R2900107010	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Lake Carlos Inspir Pk Vault Toilet	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$3,168
Facility Condition Index:	0.23 - Fair	**City Code:**	CARLOS	**Ext. Gross Area:**	42
Building Code:	R2900107410	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$2,312
Building Name:	Lake Carlos SP Trail Kiosk	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$314
Facility Condition Index:	0.14 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	49
Building Code:	R2900107850	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$347,310
Building Name:	Lake Carlos SP Hid Lk GC Sanitation	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$46,550
Facility Condition Index:	0.13 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	1,126
Building Code:	R2900107860	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$62,279
Building Name:	Lake Carlos SP Pioneer Picnic Shel	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$6,228
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	943
Building Code:	R2900107920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,769
Building Name:	Lake Carlos SP Pioneer Grp CG Vault	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,577
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	48
Building Code:	R2900107930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,283
Building Name:	Lake Carlos SP Pioneer Grp Vault 2	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,628
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	48
Building Code:	R2900108270	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,283
Building Name:	Lake Carlos SP Lakeview Pic Vault	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$1,628
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	48
Building Code:	R2900108500	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$71,834
Building Name:	Lake Carlos SP Upp CG Raccoon Cabin	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$8,370
Facility Condition Index:	0.12 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	288

Building Code:	R2900108510	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$75,003
Building Name:	Lake Carlos SP Upper CG Frog Cabin	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$8,686
Facility Condition Index:	0.12 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	288
Building Code:	R2900108520	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$75,003
Building Name:	Lake Carlos SP Upper CG Eagle Cabin	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$8,686
Facility Condition Index:	0.12 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	288
Building Code:	R2900108530	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$75,003
Building Name:	Lake Carlos SP Upper CG Loon Cabin	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$8,686
Facility Condition Index:	0.12 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	288
Building Code:	R2900108550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$54,904
Building Name:	Lake Carlos SP Upper CG Vault Concr	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$5,490
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	102
Building Code:	R2900108640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$37,412
Building Name:	Lake Carlos SP Wood Storage	**Address:**	2601 CTY RD 38 NE	**Deferred Maintenance:**	$3,741
Facility Condition Index:	0.10 - Good	**City Code:**	CARLOS	**Ext. Gross Area:**	400

Site: R290038 - Lake Louise State Park

Building Code:	R2900500350	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$132,803
Building Name:	Lake Louise SP Picnic Ar Sanitation	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$9,859
Facility Condition Index:	0.07 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	391
Building Code:	R2900500360	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$42,699
Building Name:	Lake Louise SP Well House	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$2,682
Facility Condition Index:	0.06 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	121
Building Code:	R2900502040	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$94,234
Building Name:	Lake Louise SP Picnic Area Shel 1	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$7,290
Facility Condition Index:	0.08 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	858
Building Code:	R2900503670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Lake Louise SP Vault Toilet	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	LEROY	**Ext. Gross Area:**	35
Building Code:	R2900503870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Lake Louise SP Horse CG Vault Toil	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$3,227
Facility Condition Index:	0.27 - Fair	**City Code:**	LEROY	**Ext. Gross Area:**	35
Building Code:	R2900504170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$255,299
Building Name:	Lake Louise SP Contact Station	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$24,726
Facility Condition Index:	0.10 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	760

Building Code:	R2900504180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$302,080
Building Name:	Lake Louise SP Shop	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$37,909
Facility Condition Index:	0.13 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	2,037
Building Code:	R2900504930	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,056
Building Name:	Lake Louise SP Wood Storage Shed	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$3,045
Facility Condition Index:	0.14 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	200
Building Code:	R2900505100	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$384,849
Building Name:	Lake Louise SP CG Sanitation	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$26,573
Facility Condition Index:	0.07 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	960
Building Code:	R2900505170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	Lake Louise SP Grp CG Vault Toilet	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$2,101
Facility Condition Index:	0.13 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	47
Building Code:	R2900505210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	Lake Louise SP CG Vault Toilet	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$1,946
Facility Condition Index:	0.12 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	47
Building Code:	R2900505220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	Lake Louise SP Vault Toilet	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$2,101
Facility Condition Index:	0.13 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	47
Building Code:	R2900505230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	Lake Louise SP Picnic Ar Vault Toil	**Address:**	12385 766TH AVE	**Deferred Maintenance:**	$1,213
Facility Condition Index:	0.07 - Good	**City Code:**	LEROY	**Ext. Gross Area:**	47

Site: R290039 - Lake Maria State Park

Building Code:	R2900301090	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$166,943
Building Name:	Lake Maria SP Office	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$101,497
Facility Condition Index:	0.61 - Crisis	**City Code:**	MONTICELLO	**Ext. Gross Area:**	968
Building Code:	R2900301100	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$272,160
Building Name:	Lake Maria SP Shop	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$66,655
Facility Condition Index:	0.24 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	1,523
Building Code:	R2900301110	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,729
Building Name:	Lake Maria SP Pump House	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$7,567
Facility Condition Index:	0.21 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	121
Building Code:	R2900301120	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$408,816
Building Name:	Lake Maria SP Trails Center	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$73,130
Facility Condition Index:	0.18 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	1,600

Building Code:	R2900303210	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$123,519
Building Name:	Lake Maria SP Contact Station	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$38,643
Facility Condition Index:	0.31 - Poor	**City Code:**	MONTICELLO	**Ext. Gross Area:**	472
Building Code:	R2900303680	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,702
Building Name:	Lake Maria SP Oil House	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,911
Facility Condition Index:	0.10 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	96
Building Code:	R2900305180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$22,343
Building Name:	Lake Maria SP Shop Ar Cold Storage	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$5,264
Facility Condition Index:	0.24 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	360
Building Code:	R2900305250	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,156
Building Name:	Lake Maria SP Horse CG Vault Toilet	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$4,736
Facility Condition Index:	0.42 - Poor	**City Code:**	MONTICELLO	**Ext. Gross Area:**	36
Building Code:	R2900305280	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,156
Building Name:	Lake Maria SP Group CG Unisex Vault	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,332
Facility Condition Index:	0.12 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	36
Building Code:	R2900305290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,156
Building Name:	Lake Maria SP Group CG Vault Toilet	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,950
Facility Condition Index:	0.17 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	36
Building Code:	R2900307000	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$62,521
Building Name:	Lake Maria SP Camper Cabin C1	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$19,258
Facility Condition Index:	0.31 - Poor	**City Code:**	MONTICELLO	**Ext. Gross Area:**	264
Building Code:	R2900307010	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$64,962
Building Name:	Lake Maria SP Camper Cabin C2	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$13,706
Facility Condition Index:	0.21 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	264
Building Code:	R2900307020	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$66,353
Building Name:	Lake Maria SP Camper Cabin C3	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$13,021
Facility Condition Index:	0.20 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	264
Building Code:	R2900307250	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,258
Building Name:	Lake Maria SP Vault Toilet	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,094
Facility Condition Index:	0.07 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	47
Building Code:	R2900308140	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$52,451
Building Name:	Lake Maria SP Shop Cold Storage	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$7,762
Facility Condition Index:	0.15 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	495
Building Code:	R2900308710	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,422
Building Name:	Lake Maria SP Wood Shed	**Address:**	11411 CLEMENTA AVE	**Deferred Maintenance:**	$228
Facility Condition Index:	0.02 - Excellent	**City Code:**	MONTICELLO	**Ext. Gross Area:**	100

Site: R290040 - Lake Shetek State Park

Building Code:	R2900401280	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$327,386
Building Name:	Lake Shetek SP Recreation Hall	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$105,184
Facility Condition Index:	0.32 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	1,176
Building Code:	R2900401290	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$128,225
Building Name:	Lake Shetek SP Cabin 1	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$37,819
Facility Condition Index:	0.29 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	576
Building Code:	R2900401300	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$128,225
Building Name:	Lake Shetek SP Cabin 2	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$39,099
Facility Condition Index:	0.30 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	576
Building Code:	R2900401310	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$128,225
Building Name:	Lake Shetek SP Cabin 3	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$39,099
Facility Condition Index:	0.30 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	576
Building Code:	R2900401320	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$239,293
Building Name:	Lake Shetek SP Zuya GC Sanitation	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$113,739
Facility Condition Index:	0.48 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	720
Building Code:	R2900401330	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,016,915
Building Name:	Lake Shetek SP Zuya GC Dining Hall	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$196,906
Facility Condition Index:	0.19 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	1,725
Building Code:	R2900401340	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$78,345
Building Name:	Lake Shetek SP Picnic Ar Sanitation	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$25,495
Facility Condition Index:	0.33 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	459
Building Code:	R2900401350	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$572,198
Building Name:	Lake Shetek SP Beach Bath House	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$282,308
Facility Condition Index:	0.49 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	1,626
Building Code:	R2900401360	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$266,188
Building Name:	Lake Shetek SP Picnic Ar Shelter 2	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$87,842
Facility Condition Index:	0.33 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	494
Building Code:	R2900401370	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$295,481
Building Name:	Lake Shetek SP Shop	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$98,515
Facility Condition Index:	0.33 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	1,349
Building Code:	R2900401380	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$96,937
Building Name:	Lake Shetek SP Wood Storage	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$39,080
Facility Condition Index:	0.40 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	720

Building Code:	R2900401390	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$735,654
Building Name:	Lake Shetek SP Residence	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$221,308
Facility Condition Index:	0.30 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	2,599
Building Code:	R2900401410	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$276,284
Building Name:	Lake Shetek SP Oak Woods CG San 1	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$83,893
Facility Condition Index:	0.30 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	682
Building Code:	R2900401420	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$169,252
Building Name:	Lake Shetek SP Interp Center	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$44,940
Facility Condition Index:	0.27 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	960
Building Code:	R2900401440	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$220,483
Building Name:	Lake Shetek SP Cold Storage Barn	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$97,726
Facility Condition Index:	0.44 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	3,200
Building Code:	R2900401830	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,002
Building Name:	Lake Shetek SP Cold Storage	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$5,417
Facility Condition Index:	0.77 - Crisis	**City Code:**	CURRIE	**Ext. Gross Area:**	72
Building Code:	R2900401840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,885
Building Name:	Lake Shetek SP Pump House	**Address:**	175 CTY RD 26	**Deferred Maintenance:**	$3,430
Facility Condition Index:	0.22 - Fair	**City Code:**	WINDOM	**Ext. Gross Area:**	49
Building Code:	R2900402940	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$393,209
Building Name:	Lake Shetek SP Oak Woods CG San 2	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$77,094
Facility Condition Index:	0.20 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	1,248
Building Code:	R2900402950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$24,226
Building Name:	Lake Shetek SP Cold Storage	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$9,552
Facility Condition Index:	0.39 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	352
Building Code:	R2900403190	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$149,246
Building Name:	Lake Shetek SP Picnic Ar Shelter 1	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$41,014
Facility Condition Index:	0.27 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	1,360
Building Code:	R2900403200	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,492
Building Name:	Lake Shetek SP Cold Storage	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$14,492
Facility Condition Index:	1.00 - Crisis	**City Code:**	CURRIE	**Ext. Gross Area:**	120
Building Code:	R2900403210	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,043
Building Name:	Lake Shetek SP Cold Storage	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$11,022
Facility Condition Index:	0.85 - Crisis	**City Code:**	CURRIE	**Ext. Gross Area:**	108
Building Code:	R2900403220	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,454
Building Name:	Lake Shetek SP Oil House	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$7,144
Facility Condition Index:	0.85 - Crisis	**City Code:**	CURRIE	**Ext. Gross Area:**	70

Building Code:	R2900403230	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,062
Building Name:	Lake Shetek SP Fish Cleaning House	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$10,319
Facility Condition Index:	0.29 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	120
Building Code:	R2900403240	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,560
Building Name:	Lake Shetek SP Pump House	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,414
Facility Condition Index:	0.08 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	64
Building Code:	R2900403760	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$296,666
Building Name:	Lake Shetek SP Contact Station	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$48,741
Facility Condition Index:	0.16 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	1,329
Building Code:	R2900404030	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$40,220
Building Name:	Lake Shetek SP Historic Cabin	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$13,385
Facility Condition Index:	0.33 - Poor	**City Code:**	CURRIE	**Ext. Gross Area:**	192
Building Code:	R2900404640	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,760
Building Name:	Lake Shetek SP Oak Woods CG Cabin 1	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$11,573
Facility Condition Index:	0.20 - Fair	**City Code:**	CURRIE	**Ext. Gross Area:**	280
Building Code:	R2900404880	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Lake Shetek SP Picnic Area Vault	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,258
Facility Condition Index:	0.07 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47
Building Code:	R2900404890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Lake Shetek SP Prairie CG Vault	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,258
Facility Condition Index:	0.07 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47
Building Code:	R2900404900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Lake Shetek SP Wilderness GC Vault	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,258
Facility Condition Index:	0.07 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47
Building Code:	R2900404910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Lake Shetek SP Oak Woods CG Vault	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,258
Facility Condition Index:	0.07 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47
Building Code:	R2900404920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Lake Shetek SP Vault Toilet	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,258
Facility Condition Index:	0.07 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47
Building Code:	R2900404930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,920
Building Name:	Lake Shetek SP Oak Woods CG Vault	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$2,051
Facility Condition Index:	0.12 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47
Building Code:	R2900404940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,878
Building Name:	Lake Shetek SP Zuya GC Vault Toilet	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,254
Facility Condition Index:	0.07 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	47

Building Code:	R2900405310	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$59,411
Building Name:	Lake Shetek SP Oak Woods CG Cabin 4	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$5,941
Facility Condition Index:	0.10 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	288
Building Code:	R2900405320	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$59,411
Building Name:	Lake Shetek SP Oak Woods CG Cabin 2	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$5,941
Facility Condition Index:	0.10 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	288
Building Code:	R2900405330	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$34,761
Building Name:	Lake Shetek SP Oak Woods CG Cabin 3	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$3,578
Facility Condition Index:	0.10 - Good	**City Code:**	CURRIE	**Ext. Gross Area:**	288
Building Code:	R2900405340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$57,470
Building Name:	Lake Shetek SP Sunrise Vault Concr	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$1,149
Facility Condition Index:	0.02 - Excellent	**City Code:**	CURRIE	**Ext. Gross Area:**	102
Building Code:	R2900405350	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$213,455
Building Name:	Lake Shetek SP Sunrise E Pic Shel 1	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$8,567
Facility Condition Index:	0.04 - Excellent	**City Code:**	CURRIE	**Ext. Gross Area:**	1,312
Building Code:	R2900405360	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$213,455
Building Name:	Lake Shetek SP Sunrise W Pic Shel 1	**Address:**	163 STATE PARK RD	**Deferred Maintenance:**	$5,343
Facility Condition Index:	0.03 - Excellent	**City Code:**	CURRIE	**Ext. Gross Area:**	1,312

Site: R290041 - Maplewood State Park

Building Code:	R2900102240	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$96,355
Building Name:	Maplewood SP Trails Center	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$17,911
Facility Condition Index:	0.19 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	648
Building Code:	R2900102560	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$262,944
Building Name:	Maplewood SP Grass Lk CG Sanitation	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$54,043
Facility Condition Index:	0.21 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	837
Building Code:	R2900102570	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$201,715
Building Name:	Maplewood SP Shop	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$25,927
Facility Condition Index:	0.13 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	1,495
Building Code:	R2900102590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$86,367
Building Name:	Maplewood SP Shop Area Cold Storage	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$19,067
Facility Condition Index:	0.22 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	968
Building Code:	R2900104280	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$293,049
Building Name:	Maplewood SP Lk Lida Day Beach San	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$62,347
Facility Condition Index:	0.21 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	840

Building Code:	R2900104620	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$292,226
Building Name:	Maplewood SP Contact Station	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$54,114
Facility Condition Index:	0.19 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	925
Building Code:	R2900105100	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,921
Building Name:	Maplewood SP Grass Lk CG Lift Sta	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,854
Facility Condition Index:	0.09 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	80
Building Code:	R2900105110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,759
Building Name:	Maplewood SP Hollow CG Mens Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$4,073
Facility Condition Index:	0.26 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900105120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,759
Building Name:	Maplewood SP Hollow CG Wmns Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$4,073
Facility Condition Index:	0.26 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900105130	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,719
Building Name:	Maplewood SP Knoll CG Mens Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$5,986
Facility Condition Index:	0.38 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900105140	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,759
Building Name:	Maplewood SP Knoll CG Wmns Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$5,299
Facility Condition Index:	0.34 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900105170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Maplewood SP Lake Lida CG N Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$3,633
Facility Condition Index:	0.26 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900105430	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$52,771
Building Name:	Maplewood Grass Lk Fish Cleang Hse	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$9,914
Facility Condition Index:	0.19 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	180
Building Code:	R2900106490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Maplewood SP Lake Lida CG Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$3,571
Facility Condition Index:	0.26 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Maplewood Grass Lk Baker Cabn Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$3,571
Facility Condition Index:	0.26 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,999
Building Name:	Maplewood SP Lake Lida CG S Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$2,136
Facility Condition Index:	0.15 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900106920	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$101,918
Building Name:	Maplewood SP Grass Lk CG Knoll Cab	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$9,720
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	299

Building Code:	R2900107200	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$247,279
Building Name:	Maplewood SP Steel Pole Building	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$4,946
Facility Condition Index:	0.02 - Excellent	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	2,268
Building Code:	R2900107970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,283
Building Name:	Maplewood Beers Lk Boat Acs Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,208
Facility Condition Index:	0.07 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900107980	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,283
Building Name:	Maplewood SP Group Camp Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,208
Facility Condition Index:	0.07 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900108380	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$76,234
Building Name:	Maplewood SP Grass Lk CG Baker Cab	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$15,728
Facility Condition Index:	0.21 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	216
Building Code:	R2900108560	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$216,883
Building Name:	Maplewood Lk Lida JHanson Pic Shel	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$4,338
Facility Condition Index:	0.02 - Excellent	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	1,518
Building Code:	R2900108660	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,618
Building Name:	Maplewood Horse CG Ste 5 Adirondack	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$2,645
Facility Condition Index:	0.57 - Crisis	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	117
Building Code:	R2900108670	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$3,789
Building Name:	Maplewood Horse CG Ste 9 Adirondack	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$379
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	96
Building Code:	R2900108680	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,263
Building Name:	Maplewood Horse CG Ste18 Adirondack	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,407
Facility Condition Index:	0.33 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	108
Building Code:	R2900108690	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,666
Building Name:	Maplewood Horse CG Ste22 Adirondack	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$2,000
Facility Condition Index:	0.43 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	96
Building Code:	R2900108700	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$3,789
Building Name:	Maplewood SP Grass Lk CG Adirondack	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,251
Facility Condition Index:	0.33 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	96
Building Code:	R2900108720	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$4,105
Building Name:	Maplewood Lil Grass Bkpk Adirondack	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,355
Facility Condition Index:	0.33 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	104
Building Code:	R2900108730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$54,904
Building Name:	Maplewood Grass Lk Dbl Concr Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$5,490
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	102

Building Code:	R2900108740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$54,904
Building Name:	Maplewood Beers Lk CG Cab Concr Vau	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$5,490
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	102
Building Code:	R2900108780	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$1,488
Building Name:	Maplewood SP Office Kiosk	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$100
Facility Condition Index:	0.07 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	22
Building Code:	R2900108800	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$101,215
Building Name:	Maplewood SP Beers Lk Muskie Cabin	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$13,472
Facility Condition Index:	0.13 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	296
Building Code:	R2900108810	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$95,959
Building Name:	Maplewood SP Beers Lk Crappie Cabin	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$12,946
Facility Condition Index:	0.13 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	296
Building Code:	R2900108820	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$78,236
Building Name:	Maplewood SP Beers Lk Pike Cabin	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$13,013
Facility Condition Index:	0.17 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	296
Building Code:	R2900109030	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,228
Building Name:	Maplewood SP Trails Ctr Sugar House	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,085
Facility Condition Index:	0.02 - Excellent	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	196
Building Code:	R2900109120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$29,067
Building Name:	Maplewood SP Horse Camp Concr Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$2,907
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	54
Building Code:	R2900109130	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$29,067
Building Name:	Maplewood SP Trails Ctr Concr Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$2,907
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	54
Building Code:	R2900109140	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$29,067
Building Name:	Maplewood Lk Lida Day Concr Vault	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$2,907
Facility Condition Index:	0.10 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	54
Building Code:	R2900109330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$40,839
Building Name:	Maplewood SP Friends Storage	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$817
Facility Condition Index:	0.02 - Excellent	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	192
Building Code:	R2900109490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$54,904
Building Name:	Maplewood SP Horse CG Vault Concr	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$1,098
Facility Condition Index:	0.02 - Excellent	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	102
Building Code:	R2900109670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$3,537
Building Name:	Maplewood SP Island Area Outhouse	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$951
Facility Condition Index:	0.27 - Fair	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	24

Building Code:	R2900109680	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$134,688
Building Name:	Maplewood SP Island Area Cabin	**Address:**	39721 PARK ENTRANCE RD	**Deferred Maintenance:**	$19,376
Facility Condition Index:	0.14 - Good	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	700

Site: R290042 - McCarthy Beach State Park

Building Code:	R2900200670	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$15,619
Building Name:	McCarthy Beach SP Cold Stor Garage	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$4,360
Facility Condition Index:	0.28 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	320
Building Code:	R2900200750	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$76,640
Building Name:	McCarthy Bch Side Lk Fish Clean Hse	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$13,806
Facility Condition Index:	0.18 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	195
Building Code:	R2900200760	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$49,573
Building Name:	McCarthy Beach SP Spring House	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$5,269
Facility Condition Index:	0.11 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	143
Building Code:	R2900200790	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$218,159
Building Name:	McCarthy Beach SP Picnic Shelter 2	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$22,150
Facility Condition Index:	0.10 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	1,620
Building Code:	R2900200800	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,179
Building Name:	McCarthy Beach SP Cold Storage	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$16,003
Facility Condition Index:	0.50 - Poor	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	2,950
Building Code:	R2900203840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,311
Building Name:	McCarthy Beach SP Oil House	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$5,125
Facility Condition Index:	0.23 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	96
Building Code:	R2900204490	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$768,928
Building Name:	McCarthy Beach SP Shop	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$180,627
Facility Condition Index:	0.23 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	4,046
Building Code:	R2900205570	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,897
Building Name:	McCarthy Beach Side Lk CG Mns Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$3,034
Facility Condition Index:	0.26 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	33
Building Code:	R2900205580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,897
Building Name:	McCarthy Beach Side Lk CG Wmn Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$3,034
Facility Condition Index:	0.26 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	33
Building Code:	R2900205590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,109
Building Name:	McCarthy Bch Side Lk CG F Mns Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$2,022
Facility Condition Index:	0.18 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	31

Building Code:	R2900205600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,109
Building Name:	McCarthy Bch Side Lk CG F Wmn Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$2,022
Facility Condition Index:	0.18 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	31
Building Code:	R2900205630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,669
Building Name:	McCarthy Bch Beatrice Lk Mns Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$3,652
Facility Condition Index:	0.25 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	41
Building Code:	R2900205640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,669
Building Name:	McCarthy Bch Beatrice Lk Wmn Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$3,652
Facility Condition Index:	0.25 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	41
Building Code:	R2900205650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,541
Building Name:	McCarthy Bch Beatrice Lk Mns Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$2,877
Facility Condition Index:	0.25 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	32
Building Code:	R2900205660	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,541
Building Name:	McCarthy Bch Beatrice Lk Wmn Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$2,877
Facility Condition Index:	0.25 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	32
Building Code:	R2900207640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	McCarthy Beach SP Boat Land Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$1,326
Facility Condition Index:	0.09 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900207650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	McCarthy Beach SP Boat Land Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$1,326
Facility Condition Index:	0.09 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900207960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,859
Building Name:	McCarthy Beach SP Beach Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$1,036
Facility Condition Index:	0.09 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	33
Building Code:	R2900207970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	McCarthy Beach SP Trail Head Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$1,983
Facility Condition Index:	0.13 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900207980	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	McCarthy Beach SP Picnic Area Vault	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$2,029
Facility Condition Index:	0.13 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900208420	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$322,763
Building Name:	McCarthy Beach SP Contact Station	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$45,903
Facility Condition Index:	0.14 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	1,251
Building Code:	R2900208440	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$47,380
Building Name:	McCarthy Beach SP Cold Storage	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$1,858
Facility Condition Index:	0.04 - Excellent	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	576

Building Code:	R2900208850	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$353,289
Building Name:	McCarthy Beach SP Beach Bath House	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$76,624
Facility Condition Index:	0.22 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	1,350
Building Code:	R2900209880	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$582,403
Building Name:	McCarthy Beach Side Lk CG San Bldg	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$11,648
Facility Condition Index:	0.02 - Excellent	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	1,294
Building Code:	R2900209890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$59,522
Building Name:	McCarthy Bch Side Lk CG Vault Concr	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$1,190
Facility Condition Index:	0.02 - Excellent	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	102

Site: R290043 - Mille Lacs Kathio State Park

Building Code:	R2900301130	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$344,918
Building Name:	Mille Lacs Kathio SP HQ Shop	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$126,622
Facility Condition Index:	0.37 - Poor	**City Code:**	ONAMIA	**Ext. Gross Area:**	1,494
Building Code:	R2900301140	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$171,872
Building Name:	Mille Lacs Kathio SP HQ Cold Stor	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$44,046
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	1,008
Building Code:	R2900301190	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$196,525
Building Name:	Mille Lacs Kathio SP Sanitation	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$45,395
Facility Condition Index:	0.23 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	728
Building Code:	R2900301200	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$597,164
Building Name:	Mille Lacs Kathio SP Trail Center	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$155,852
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	2,610
Building Code:	R2900301220	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$816,533
Building Name:	Mille Lacs Kathio SP Interp Center	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$114,733
Facility Condition Index:	0.14 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	4,909
Building Code:	R2900301240	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$166,952
Building Name:	Mille Lacs Kathio SP HQ Cold Stor	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$41,092
Facility Condition Index:	0.25 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	1,500
Building Code:	R2900301250	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$69,209
Building Name:	MLKathio SP Petaga CG Fish Clean Hs	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$21,148
Facility Condition Index:	0.31 - Poor	**City Code:**	ONAMIA	**Ext. Gross Area:**	176
Building Code:	R2900303750	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$325,022
Building Name:	Mille Lacs Kathio SP HQ Contact Sta	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$69,223
Facility Condition Index:	0.21 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	1,306

Building Code:	R2900304200	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,111
Building Name:	Mille Lacs Kathio SP HQ Oil House	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$3,396
Facility Condition Index:	0.18 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	96
Building Code:	R2900304780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,127
Building Name:	MLKathio SP Ogechie CG Ste 23 Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,333
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	28
Building Code:	R2900304790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,009
Building Name:	MLKathio SP Rum River CG Wmns Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,555
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	31
Building Code:	R2900304800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,009
Building Name:	MLKathio SP Rum River CG Mens Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,555
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	31
Building Code:	R2900304810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,127
Building Name:	MLKathio SP Ogechie CG Ste7/23 Vaul	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,213
Facility Condition Index:	0.24 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	28
Building Code:	R2900305730	**Cost Model Name:**	Tower	**Current Replacement Value:**	$10,189
Building Name:	MLKathio SP Isle Harbor Fire Tower	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$7,249
Facility Condition Index:	0.71 - Crisis	**City Code:**	ONAMIA	**Ext. Gross Area:**	60
Building Code:	R2900306370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,804
Building Name:	Mille Lacs Kathio SP HQ Vault Toil	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$1,557
Facility Condition Index:	0.11 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	40
Building Code:	R2900306380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,640
Building Name:	MLKathio SP Petaga CG Cabins Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$3,551
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	40
Building Code:	R2900306390	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,130
Building Name:	MLKathio SP Petaga CG C-d-S Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$3,424
Facility Condition Index:	0.24 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	40
Building Code:	R2900306400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,677
Building Name:	MLKathio SP Petaga CG Site 37 Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$3,310
Facility Condition Index:	0.24 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	40
Building Code:	R2900306410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,877
Building Name:	MLKathio SP Petaga CG Site 62 Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$4,305
Facility Condition Index:	0.31 - Poor	**City Code:**	ONAMIA	**Ext. Gross Area:**	40
Building Code:	R2900306680	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$51,572
Building Name:	MLKathio SP Petaga CG Cabin 1	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$6,223
Facility Condition Index:	0.12 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	264

Building Code:	R2900306690	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$52,975
Building Name:	MLKathio SP Petaga CG Cabin 2	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$9,654
Facility Condition Index:	0.18 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	264
Building Code:	R2900306700	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$59,477
Building Name:	MLKathio SP Petaga CG Cabin3	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$10,065
Facility Condition Index:	0.17 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	264
Building Code:	R2900306710	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$60,940
Building Name:	MLKathio SP Petaga CG ADA Cabin 4	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$6,517
Facility Condition Index:	0.11 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	264
Building Code:	R2900306720	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,726
Building Name:	MLKathio SP Petaga CG Cabin 5	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$14,599
Facility Condition Index:	0.25 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	264
Building Code:	R2900306830	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$327,991
Building Name:	MLKathio SP Petaga CG Sanitation	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$61,941
Facility Condition Index:	0.19 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	1,177
Building Code:	R2900306890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,992
Building Name:	Mille Lacs Kathio SP Vault Toilet	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,334
Facility Condition Index:	0.26 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	28
Building Code:	R2900306900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,063
Building Name:	Mille Lacs Kathio SP Picnic Vault	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$3,661
Facility Condition Index:	0.23 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	47
Building Code:	R2900306910	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,368
Building Name:	Mille Lacs Kathio SP Cold Storage	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$5,988
Facility Condition Index:	0.53 - Crisis	**City Code:**	ONAMIA	**Ext. Gross Area:**	100
Building Code:	R2900307240	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,575
Building Name:	Mille Lacs Kathio SP Vault Toilet	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,477
Facility Condition Index:	0.16 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	47
Building Code:	R2900308190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$24,377
Building Name:	Mille Lacs Kathio SP Vault Concrete	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$488
Facility Condition Index:	0.02 - Excellent	**City Code:**	ONAMIA	**Ext. Gross Area:**	47
Building Code:	R2900308310	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,061
Building Name:	Mille Lacs Kathio SP HQ Wood Shed	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$997
Facility Condition Index:	0.03 - Excellent	**City Code:**	ONAMIA	**Ext. Gross Area:**	135
Building Code:	R2900308320	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,329
Building Name:	Mille Lacs Kathio SP HQ Salt Shed	**Address:**	15066 KATHIO STATE PARK RD	**Deferred Maintenance:**	$2,867
Facility Condition Index:	0.28 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	96

Site: R290044 - Minneopa State Park

Building Code:	R2900400540	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$298,521
Building Name:	Minneopa SP Granary Storage	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$98,046
Facility Condition Index:	0.33 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	736
Building Code:	R2900400550	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,206,440
Building Name:	Minneopa Seppmann Windmill Pumphse	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$879,416
Facility Condition Index:	0.73 - Crisis	**City Code:**	MANKATO	**Ext. Gross Area:**	2,121
Building Code:	R2900400560	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$246,033
Building Name:	Minneopa SP CG Sanitation	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$56,608
Facility Condition Index:	0.23 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	912
Building Code:	R2900400570	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$277,831
Building Name:	Minneopa SP Picnic Shelter 1	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$91,684
Facility Condition Index:	0.33 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	2,784
Building Code:	R2900400580	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$47,541
Building Name:	Minneopa SP Pump House	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$15,836
Facility Condition Index:	0.33 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	81
Building Code:	R2900400590	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$148,349
Building Name:	Minneopa SP Interp Center	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$49,487
Facility Condition Index:	0.33 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	708
Building Code:	R2900400600	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$304,539
Building Name:	Minneopa SP Sanitation	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$90,318
Facility Condition Index:	0.30 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	840
Building Code:	R2900400620	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$286,900
Building Name:	Minneopa SP Office	**Address:**	21009 547TH AVE	**Deferred Maintenance:**	$74,093
Facility Condition Index:	0.26 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	1,660
Building Code:	R2900400630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$9,002
Building Name:	Minneopa SP Shop Area Shed	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$6,751
Facility Condition Index:	0.75 - Crisis	**City Code:**	MANKATO	**Ext. Gross Area:**	320
Building Code:	R2900400640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$338,874
Building Name:	Minneopa SP Shop	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$80,756
Facility Condition Index:	0.24 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	1,596
Building Code:	R2900400660	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$103,285
Building Name:	Minneopa SP Shop Area Cold Storage	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$31,398
Facility Condition Index:	0.30 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	828

Building Code:	R2900402740	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,156
Building Name:	Minneopa SP Oil House	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$2,105
Facility Condition Index:	0.34 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	48
Building Code:	R2900403350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,269
Building Name:	Minneopa SP Picnic Ar Vault Toilet	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$574
Facility Condition Index:	0.06 - Good	**City Code:**	MANKATO	**Ext. Gross Area:**	30
Building Code:	R2900403360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,269
Building Name:	Minneopa Seppmann Windmill Vault	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$2,630
Facility Condition Index:	0.26 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	30
Building Code:	R2900403370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,269
Building Name:	Minneopa SP Picnic Area Mens Vault	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$574
Facility Condition Index:	0.06 - Good	**City Code:**	MANKATO	**Ext. Gross Area:**	30
Building Code:	R2900403380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,024
Building Name:	Minneopa SP Picnic Area Wmns Vault	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$569
Facility Condition Index:	0.06 - Good	**City Code:**	MANKATO	**Ext. Gross Area:**	30
Building Code:	R2900404310	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$66,040
Building Name:	Minneopa SP CG Site 16 Cabin	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$16,872
Facility Condition Index:	0.26 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	264
Building Code:	R2900404320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,269
Building Name:	Minneopa SP CG Site 16 Vault Toilet	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$2,630
Facility Condition Index:	0.26 - Fair	**City Code:**	MANKATO	**Ext. Gross Area:**	30
Building Code:	R2900404380	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$268,863
Building Name:	Minneopa SP Contact Station	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$30,097
Facility Condition Index:	0.11 - Good	**City Code:**	MANKATO	**Ext. Gross Area:**	1,156
Building Code:	R2900405390	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$343,764
Building Name:	Minneopa SP Quonset	**Address:**	54497 GADWALL RD	**Deferred Maintenance:**	$113,442
Facility Condition Index:	0.33 - Poor	**City Code:**	MANKATO	**Ext. Gross Area:**	5,000

Site: R290045 - Minnesota Valley SRA

Building Code:	R2900600320	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$460,802
Building Name:	MN Valley SRA Lawrence Strait House	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$151,839
Facility Condition Index:	0.33 - Poor	**City Code:**	JORDAN	**Ext. Gross Area:**	1,587
Building Code:	R2900601250	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$143,115
Building Name:	Minnesota Valley SRA Trails Center	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$30,337
Facility Condition Index:	0.21 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	768

Building Code:	R2900601350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,276
Building Name:	MN Valley SRA Walk-in Vault Toilet	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$6,887
Facility Condition Index:	0.34 - Poor	**City Code:**	JORDAN	**Ext. Gross Area:**	64
Building Code:	R2900601360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,976
Building Name:	MN Valley SRA Walk-in Vault Toilet	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$2,511
Facility Condition Index:	0.28 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	28
Building Code:	R2900601370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,820
Building Name:	MN Valley SRA CG Site11 Wmn L Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$4,551
Facility Condition Index:	0.26 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	56
Building Code:	R2900601380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,820
Building Name:	MN Valley SRA CG Site11 Men R Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$5,319
Facility Condition Index:	0.30 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	56
Building Code:	R2900601390	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,553
Building Name:	MN Valley SRA CG Site24 Men L Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$2,983
Facility Condition Index:	0.19 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	56
Building Code:	R2900601400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,820
Building Name:	MN Valley SRA CG Site24 Wmn R Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$3,731
Facility Condition Index:	0.21 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	56
Building Code:	R2900601410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,976
Building Name:	MN Valley SRA Trail Ctr Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$2,295
Facility Condition Index:	0.26 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	28
Building Code:	R2900601420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,976
Building Name:	MN Valley SRA Trail Ctr Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$2,295
Facility Condition Index:	0.26 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	28
Building Code:	R2900601430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,976
Building Name:	MN Valley SRA Grp CG Picnic Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$3,044
Facility Condition Index:	0.34 - Poor	**City Code:**	JORDAN	**Ext. Gross Area:**	28
Building Code:	R2900601440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,199
Building Name:	MN Valley SRA Grp CG Picnic Vault	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$2,325
Facility Condition Index:	0.15 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	48
Building Code:	R2900601850	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$389,731
Building Name:	Minnesota Valley SRA Shop	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$70,455
Facility Condition Index:	0.18 - Fair	**City Code:**	JORDAN	**Ext. Gross Area:**	3,024
Building Code:	R2900601930	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,633
Building Name:	Minnesota Valley SRA Wood Storage	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$6,762
Facility Condition Index:	0.70 - Crisis	**City Code:**	JORDAN	**Ext. Gross Area:**	81

Building Code:	R2900602070	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$55,809
Building Name:	MN Valley SRA Carver Rap Pic Shel 2	**Address:**	19825 PARK BLVD	**Deferred Maintenance:**	$18,332
Facility Condition Index:	0.33 - Poor	**City Code:**	JORDAN	**Ext. Gross Area:**	680

Site: R290046 - Monson Lake State Park

Building Code:	R2900401000	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$200,297
Building Name:	Monson Lake SP CG Sanitation	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$67,122
Facility Condition Index:	0.34 - Poor	**City Code:**	SUNBURG	**Ext. Gross Area:**	405
Building Code:	R2900401010	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$181,791
Building Name:	Monson Lake SP Contact Station	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$26,212
Facility Condition Index:	0.14 - Good	**City Code:**	SUNBURG	**Ext. Gross Area:**	1,056
Building Code:	R2900401020	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$681,628
Building Name:	Monson Lake SP Picnic Shelter 2	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$75,683
Facility Condition Index:	0.11 - Good	**City Code:**	SUNBURG	**Ext. Gross Area:**	1,104
Building Code:	R2900404360	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,752
Building Name:	Monson Lake SP Cold Storage	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$7,503
Facility Condition Index:	0.36 - Poor	**City Code:**	SUNBURG	**Ext. Gross Area:**	240
Building Code:	R2900404370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Monson Lake SP Boat Landg Vault	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$2,039
Facility Condition Index:	0.15 - Fair	**City Code:**	SUNBURG	**Ext. Gross Area:**	38
Building Code:	R2900404870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,373
Building Name:	Monson Lake SP Picnic Area Vault	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$1,292
Facility Condition Index:	0.07 - Good	**City Code:**	SUNBURG	**Ext. Gross Area:**	47
Building Code:	R2900405400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,505
Building Name:	Monson Lake SP Shed	**Address:**	1690 15TH ST NE	**Deferred Maintenance:**	$2,351
Facility Condition Index:	0.10 - Good	**City Code:**	SUNBURG	**Ext. Gross Area:**	140

Site: R290047 - Moose Lake State Park

Building Code:	R2900203690	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$380,209
Building Name:	Moose Lake SP Cold Storage	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$216,108
Facility Condition Index:	0.57 - Crisis	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	2,484
Building Code:	R2900204320	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,448
Building Name:	Moose Lake SP Grp CG Spring House	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$6,029
Facility Condition Index:	0.64 - Crisis	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	36

Building Code:	R2900204360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$62,682
Building Name:	Moose Lake SP Shop	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$11,996
Facility Condition Index:	0.19 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	576
Building Code:	R2900205830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,845
Building Name:	Moose Lake SP CG C-Lane E Vault	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$2,047
Facility Condition Index:	0.17 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900205840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,845
Building Name:	Moose Lake SP CG C-Lane W Vault	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$2,131
Facility Condition Index:	0.18 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900205850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,598
Building Name:	Moose Lake SP Beach Picnic E Vault	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$1,556
Facility Condition Index:	0.13 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900205860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,598
Building Name:	Moose Lake SP Beach Picnic W Vault	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$1,556
Facility Condition Index:	0.13 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900205890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,598
Building Name:	Moose Lake SP Boat Landing Vault	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$2,217
Facility Condition Index:	0.19 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900205900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,341
Building Name:	Moose Lake SP Grp CG Vault Toilet	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$2,008
Facility Condition Index:	0.24 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	24
Building Code:	R2900205940	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,860
Building Name:	Moose Lake SP CG Spring House	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$6,233
Facility Condition Index:	0.48 - Poor	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	49
Building Code:	R2900207400	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$220,184
Building Name:	Moose Lake SP CG Sanitation	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$42,482
Facility Condition Index:	0.19 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	850
Building Code:	R2900207470	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$373,637
Building Name:	Moose Lake SP Heat/Cold Storage	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$53,988
Facility Condition Index:	0.14 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	2,016
Building Code:	R2900208030	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$2,626
Building Name:	Moose Lake SP Cold Storage	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$1,970
Facility Condition Index:	0.75 - Crisis	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	32
Building Code:	R2900208490	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,878
Building Name:	Moose Lake SP Cold Storage	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$3,007
Facility Condition Index:	0.38 - Poor	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	96

Building Code:	R2900208600	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,040,161
Building Name:	Moose Lake SP Interpretive Ctr	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$83,670
Facility Condition Index:	0.08 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	4,474
Building Code:	R2900208650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,575
Building Name:	Moose Lake SP CG Sites 10/11 Vault	**Address:**	4252 CTY RD 137	**Deferred Maintenance:**	$1,149
Facility Condition Index:	0.07 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	47

Site: R290048 - Myre-Big Island State Park

Building Code:	R2900500590	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$348,207
Building Name:	Myre-Big Isl SP NY Pt Grp Rec Hall	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$32,517
Facility Condition Index:	0.09 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,100
Building Code:	R2900500600	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$508,048
Building Name:	Myre-Big Island SP Interp Unocc	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$186,095
Facility Condition Index:	0.37 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,844
Building Code:	R2900500610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,111
Building Name:	Myre-Big Isl SP White Fox Pumphouse	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$2,895
Facility Condition Index:	0.08 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	108
Building Code:	R2900500640	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$188,611
Building Name:	Myre-Big Island SP Picnic Ar Shel 2	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$69,627
Facility Condition Index:	0.37 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	1,682
Building Code:	R2900500660	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$247,682
Building Name:	Myre-Big Island SP Picnic Area San	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$86,606
Facility Condition Index:	0.35 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	720
Building Code:	R2900500700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$283,890
Building Name:	Myre-Big Island SP Wood Storage	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$51,439
Facility Condition Index:	0.18 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,074
Building Code:	R2900500710	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$397,800
Building Name:	Myre-Big Isl SP NY Pt Grp Dine Hall	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$35,522
Facility Condition Index:	0.09 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,472
Building Code:	R2900501960	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$513,728
Building Name:	Myre-Big Island SP Contact Station	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$27,575
Facility Condition Index:	0.05 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,261
Building Code:	R2900502480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Isl SP NY Pt Grp Ctr Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$5,512
Facility Condition Index:	0.26 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64

Building Code:	R2900502490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,863
Building Name:	Myre-Big Isl SP NY Pt Grp Ctr Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$6,202
Facility Condition Index:	0.30 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900502500	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,667
Building Name:	Myre-Big Island SP Cold Storage	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$9,500
Facility Condition Index:	0.75 - Crisis	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	100
Building Code:	R2900502520	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$6,261
Building Name:	Myre-Big Island SP Shop Area Shed	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$3,244
Facility Condition Index:	0.52 - Crisis	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	288
Building Code:	R2900503780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,700
Building Name:	Myre-Big Island SP Shop Cold Stor	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$2,942
Facility Condition Index:	0.38 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	81
Building Code:	R2900503790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Isl SP White Fox CG Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$7,335
Facility Condition Index:	0.34 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900503800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Isl SP Big Isl CG Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$9,542
Facility Condition Index:	0.44 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Isl SP Big Isl CG Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$4,513
Facility Condition Index:	0.21 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Isl SP White Fox CG Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$5,512
Facility Condition Index:	0.26 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504490	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Island SP Picnic Ar Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$4,003
Facility Condition Index:	0.19 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504510	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,596
Building Name:	Myre-Big Isl SP Little Isl Grp Vaul	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$2,110
Facility Condition Index:	0.10 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504520	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,342
Building Name:	Myre-Big Island SP Bkpk Camp Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$6,921
Facility Condition Index:	0.34 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504530	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,342
Building Name:	Myre-Big Island SP Bkpk Camp Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$9,353
Facility Condition Index:	0.46 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64

Building Code:	R2900504540	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,518
Building Name:	Myre-Big Island SP Bkpk Camp Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$8,594
Facility Condition Index:	0.42 - Poor	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	64
Building Code:	R2900504550	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$94,220
Building Name:	Myre-Big Isl SP Big Isl CG Cabin	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$8,507
Facility Condition Index:	0.09 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	260
Building Code:	R2900504720	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,107
Building Name:	Myre-Big Island SP Wood Storage	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$2,890
Facility Condition Index:	0.08 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	240
Building Code:	R2900505090	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$490,027
Building Name:	Myre-Big Isl SP White Fox San Bldg	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$30,189
Facility Condition Index:	0.06 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	1,144
Building Code:	R2900505240	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,315
Building Name:	Myre-Big Isl SP White Fox CG Vault	**Address:**	19499 780TH AVE	**Deferred Maintenance:**	$1,213
Facility Condition Index:	0.07 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	47

Site: R290049 - Nerstrand Big Woods State Park

Building Code:	R2900500520	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,147
Building Name:	Nerstrand Big Woods SP Garage	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$4,847
Facility Condition Index:	0.12 - Good	**City Code:**	NERSTRAND	**Ext. Gross Area:**	528
Building Code:	R2900500540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$217,233
Building Name:	Nerstrand Big Woods SP Shop	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$43,810
Facility Condition Index:	0.20 - Fair	**City Code:**	NERSTRAND	**Ext. Gross Area:**	1,095
Building Code:	R2900500570	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,901
Building Name:	Nerstrand Big Woods SP Cold Storage	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$9,519
Facility Condition Index:	0.56 - Crisis	**City Code:**	NERSTRAND	**Ext. Gross Area:**	120
Building Code:	R2900500580	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$335,290
Building Name:	Nerstrand Big Woods SP Sanitation	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$153,204
Facility Condition Index:	0.46 - Poor	**City Code:**	NERSTRAND	**Ext. Gross Area:**	1,200
Building Code:	R2900502280	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$14,624
Building Name:	Nerstrand Big Woods SP Wood Shed	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$3,975
Facility Condition Index:	0.27 - Fair	**City Code:**	NERSTRAND	**Ext. Gross Area:**	262
Building Code:	R2900503860	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$15,212
Building Name:	Nerstrand Big Woods SP Recycle Shed	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$3,913
Facility Condition Index:	0.26 - Fair	**City Code:**	NERSTRAND	**Ext. Gross Area:**	341

Building Code:	R2900504140	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$707,993
Building Name:	Nerstrand Big Woods SP Contact Sta	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$95,029
Facility Condition Index:	0.13 - Good	**City Code:**	NERSTRAND	**Ext. Gross Area:**	2,760
Building Code:	R2900505110	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$389,846
Building Name:	Nerstrand Big Woods SP CG San Bldg	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$8,940
Facility Condition Index:	0.02 - Excellent	**City Code:**	NERSTRAND	**Ext. Gross Area:**	1,144
Building Code:	R2900505120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,651
Building Name:	Nerstrand Big Woods SP Grp CG Vault	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$1,164
Facility Condition Index:	0.07 - Good	**City Code:**	NERSTRAND	**Ext. Gross Area:**	47
Building Code:	R2900505560	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$2,833
Building Name:	Nerstrand Big Woods SP Wood Shed	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$57
Facility Condition Index:	0.02 - Excellent	**City Code:**	NERSTRAND	**Ext. Gross Area:**	32
Building Code:	R2900505800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,039
Building Name:	Nerstrand Big Wds SP CG Vault Concr	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$1,415
Facility Condition Index:	0.09 - Good	**City Code:**	NERSTRAND	**Ext. Gross Area:**	81
Building Code:	R2900505810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,562
Building Name:	Nerst-Big Wds SP Grp CG Vault Concr	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$1,165
Facility Condition Index:	0.07 - Good	**City Code:**	NERSTRAND	**Ext. Gross Area:**	81
Building Code:	R2900505820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,562
Building Name:	Nerst-Big Wds SP Picnic Vault Concr	**Address:**	9700 170TH ST E	**Deferred Maintenance:**	$1,534
Facility Condition Index:	0.09 - Good	**City Code:**	NERSTRAND	**Ext. Gross Area:**	81

Site: R290050 - Old Mill State Park

Building Code:	R2900102760	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$86,941
Building Name:	Old Mill SP Residence Garage	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$17,490
Facility Condition Index:	0.20 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	720
Building Code:	R2900102770	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$259,540
Building Name:	Old Mill SP Residence	**Address:**	33569 240TH AVE NW	**Deferred Maintenance:**	$33,665
Facility Condition Index:	0.13 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	2,016
Building Code:	R2900102780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$60,121
Building Name:	Old Mill SP Pump House	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$6,358
Facility Condition Index:	0.11 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	160
Building Code:	R2900102790	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$132,683
Building Name:	Old Mill SP Historic Cabin	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$24,711
Facility Condition Index:	0.19 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	672

Building Code:	R2900102800	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$69,743
Building Name:	Old Mill SP Historic Flour Mill	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$12,944
Facility Condition Index:	0.19 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	864
Building Code:	R2900102810	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$261,550
Building Name:	Old Mill SP CG Sanitation	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$62,193
Facility Condition Index:	0.24 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	825
Building Code:	R2900102820	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$181,479
Building Name:	Old Mill SP Picnic Area Sanitation	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$43,883
Facility Condition Index:	0.24 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	408
Building Code:	R2900102830	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$516,232
Building Name:	Old Mill SP Beach Bath House	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$70,710
Facility Condition Index:	0.14 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	1,320
Building Code:	R2900102840	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$295,187
Building Name:	Old Mill SP Water Tower	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$32,613
Facility Condition Index:	0.11 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	632
Building Code:	R2900102850	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$183,018
Building Name:	Old Mill SP Shop	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$21,268
Facility Condition Index:	0.12 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	1,494
Building Code:	R2900104300	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$598,286
Building Name:	Old Mill SP Picnic Area Shelter 2	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$104,326
Facility Condition Index:	0.17 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	1,312
Building Code:	R2900105380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,886
Building Name:	Old Mill SP Scout Camp Vault	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$2,936
Facility Condition Index:	0.27 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	30
Building Code:	R2900106450	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$181,555
Building Name:	Old Mill SP Contact Station	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$20,234
Facility Condition Index:	0.11 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	711
Building Code:	R2900106960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,233
Building Name:	Old Mill SP CG Vault	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$2,351
Facility Condition Index:	0.15 - Fair	**City Code:**	ARGYLE	**Ext. Gross Area:**	42
Building Code:	R2900108010	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,500
Building Name:	Old Mill SP Picnic Area Vault	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$1,750
Facility Condition Index:	0.10 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	48
Building Code:	R2900108240	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,606
Building Name:	Old Mill SP Wood Shed	**Address:**	33489 240TH AVE NW	**Deferred Maintenance:**	$861
Facility Condition Index:	0.10 - Good	**City Code:**	ARGYLE	**Ext. Gross Area:**	72

Site: R290051 - Red River SRA

Building Code:	R2900107760	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$123,401
Building Name:	Red River SRA Contact Station	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$12,340
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	413
Building Code:	R2900108100	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$158,773
Building Name:	Red River SRA Sherlock Pk South San	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$15,877
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	500
Building Code:	R2900108110	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$158,773
Building Name:	Red River SRA Sherlock Pk North San	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$15,877
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	500
Building Code:	R2900108120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,533
Building Name:	Red River SRA Sherlock Park Vault	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$2,579
Facility Condition Index:	0.16 - Fair	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	48
Building Code:	R2900108130	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,533
Building Name:	Red River SRA Sherlock Park Vault	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$1,653
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	48
Building Code:	R2900108320	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$183,616
Building Name:	Red River SRA Sherlock Pk Bathhouse	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$18,362
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	500
Building Code:	R2900108330	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$84,023
Building Name:	Red River SRA River Hgts Pic Shel 2	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$8,402
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	680
Building Code:	R2900108340	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$185,345
Building Name:	Red River SRA River Hgts Pic Shel 2	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$46,280
Facility Condition Index:	0.25 - Fair	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	1,500
Building Code:	R2900108350	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$176,954
Building Name:	Red River SRA River Hgts Pic Shel 2	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$51,906
Facility Condition Index:	0.29 - Fair	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	1,500
Building Code:	R2900108360	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$228,633
Building Name:	Red River SRA River Hgts Sanitation	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$22,863
Facility Condition Index:	0.10 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	720
Building Code:	R2900108370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,171
Building Name:	Red River SRA HQ Cold Storage	**Address:**	515 2ND ST NW	**Deferred Maintenance:**	$2,338
Facility Condition Index:	0.25 - Fair	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	80

Site: R290052 - Rice Lake State Park

Building Code:	R2900500780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$40,999
Building Name:	Rice Lake SP Picnic Area Pumphouse	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$4,856
Facility Condition Index:	0.12 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	114
Building Code:	R2900500790	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$241,306
Building Name:	Rice Lake SP CG Sanitation	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$77,941
Facility Condition Index:	0.32 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	689
Building Code:	R2900500800	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$152,953
Building Name:	Rice Lake SP Picnic Area Sanitation	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$58,534
Facility Condition Index:	0.38 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	307
Building Code:	R2900500810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$26,568
Building Name:	Rice Lake SP Cold Storage	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$8,239
Facility Condition Index:	0.31 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	182
Building Code:	R2900500820	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$818,934
Building Name:	Rice Lake SP Contact Station	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$266,544
Facility Condition Index:	0.33 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	2,329
Building Code:	R2900502030	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$90,482
Building Name:	Rice Lake SP Picnic Area Shelter 1	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$11,035
Facility Condition Index:	0.12 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	845
Building Code:	R2900503140	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,775
Building Name:	Rice Lake SP Grp CG Vault Toilet	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$3,692
Facility Condition Index:	0.34 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	30
Building Code:	R2900503150	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,577
Building Name:	Rice Lake SP Grp CG Vault Toilet	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$3,981
Facility Condition Index:	0.34 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	30
Building Code:	R2900504390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$444,309
Building Name:	Rice Lake SP Shop	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$58,763
Facility Condition Index:	0.13 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	3,024
Building Code:	R2900504400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,577
Building Name:	Rice Lake SP Boat Land Vault Toilet	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$2,389
Facility Condition Index:	0.21 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	39
Building Code:	R2900504410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,577
Building Name:	Rice Lake SP Grp CG Vault Toilet	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$2,964
Facility Condition Index:	0.26 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	39
Building Code:	R2900504420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,577
Building Name:	Rice Lake SP CG B-Loop Vault Toilet	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$4,123
Facility Condition Index:	0.36 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	39

Building Code:	R2900504430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$20,567
Building Name:	Rice Lake SP Canoe CG Vault Toilet	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$5,243
Facility Condition Index:	0.25 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	30
Building Code:	R2900505270	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,829
Building Name:	Rice Lake SP Picnic Shelter 1	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$604
Facility Condition Index:	0.33 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	51
Building Code:	R2900505400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,539
Building Name:	Rice Lake SP Wood Shed	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$6,381
Facility Condition Index:	0.67 - Crisis	**City Code:**	OWATONNA	**Ext. Gross Area:**	103
Building Code:	R2900505540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$262,697
Building Name:	Rice Lake SP 3-Stall Cold Storage	**Address:**	8485 ROSE ST	**Deferred Maintenance:**	$7,588
Facility Condition Index:	0.03 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	3,024
Building Code:	R2900505590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$28,170
Building Name:	Rice Lake SP CG Vault Concrete	**Address:**	8465 ROSE ST	**Deferred Maintenance:**	$563
Facility Condition Index:	0.02 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	118

Site: R290053 - Sakatah Lake State Park

Building Code:	R2900500950	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$356,726
Building Name:	Sakatah Lake SP Contact Station	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$85,793
Facility Condition Index:	0.24 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	1,320
Building Code:	R2900500970	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$139,797
Building Name:	Sakatah Lake SP Picnic Area San Bld	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$54,286
Facility Condition Index:	0.39 - Poor	**City Code:**	WATERVILLE	**Ext. Gross Area:**	414
Building Code:	R2900501000	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$150,160
Building Name:	Sakatah Lake SP Wood Shop	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$32,698
Facility Condition Index:	0.22 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	2,009
Building Code:	R2900501010	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$281,303
Building Name:	Sakatah Lake SP Office	**Address:**	50507 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$21,899
Facility Condition Index:	0.08 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	1,064
Building Code:	R2900501020	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,877
Building Name:	Sakatah Lake SP CG Fish Cleang Hse	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$6,768
Facility Condition Index:	0.17 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	120
Building Code:	R2900502400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,168
Building Name:	Sakatah Lake SP CG Site 42 Vault	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$4,194
Facility Condition Index:	0.20 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	64

Building Code:	R2900504020	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,221
Building Name:	Sakatah Lake SP Upper CG Vault	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$5,410
Facility Condition Index:	0.25 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	64
Building Code:	R2900504030	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,221
Building Name:	Sakatah Lake SP Picnic Area Vault	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$6,580
Facility Condition Index:	0.31 - Poor	**City Code:**	WATERVILLE	**Ext. Gross Area:**	64
Building Code:	R2900504160	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$364,489
Building Name:	Sakatah Lake SP Shop	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$41,878
Facility Condition Index:	0.11 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	2,016
Building Code:	R2900504270	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$391,805
Building Name:	Sakatah Lake SP CG Sanitation	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$41,177
Facility Condition Index:	0.11 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	1,133
Building Code:	R2900504280	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$57,646
Building Name:	Sakatah Lake SP CG Cabin	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$10,312
Facility Condition Index:	0.18 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	282
Building Code:	R2900504290	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$103,416
Building Name:	Sakatah Lake SP Shed	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$10,886
Facility Condition Index:	0.11 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	832
Building Code:	R2900504300	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,221
Building Name:	Sakatah Lake SP Lower CG Vault	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$4,420
Facility Condition Index:	0.21 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	64
Building Code:	R2900504310	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,168
Building Name:	Sakatah Lake SP CG Site 10 Vault	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$5,392
Facility Condition Index:	0.25 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	64
Building Code:	R2900504320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,168
Building Name:	Sakatah Lake SP CG Vault Toilet	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$4,403
Facility Condition Index:	0.21 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	64
Building Code:	R2900504330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$30,844
Building Name:	Sakatah Lake SP Wood Shed	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$7,086
Facility Condition Index:	0.23 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	246
Building Code:	R2900504690	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,468
Building Name:	Sakatah Lake SP Pump House	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$3,272
Facility Condition Index:	0.26 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	45
Building Code:	R2900504800	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$52
Building Name:	Sakatah Lake SP Adirondack	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$9
Facility Condition Index:	0.16 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	140

Building Code:	R2900505130	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,482
Building Name:	Sakatah Lake SP Upper CG Vault	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$1,824
Facility Condition Index:	0.14 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	40
Building Code:	R2900505140	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,164
Building Name:	Sakatah Lake SP CG Vault Toilet	**Address:**	50499 SAKATAH LAKE SP RD	**Deferred Maintenance:**	$1,442
Facility Condition Index:	0.09 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	47

Site: R290054 - Savanna Portage State Park

Building Code:	R2900305320	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$302,469
Building Name:	Savanna Portage SP Office	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$69,615
Facility Condition Index:	0.23 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	1,395
Building Code:	R2900305330	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$753,510
Building Name:	Savanna Portage SP HQ Cold Storage	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$329,441
Facility Condition Index:	0.44 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	3,382
Building Code:	R2900305340	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$612,312
Building Name:	Savanna Portage SP Residence	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$129,755
Facility Condition Index:	0.21 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	2,310
Building Code:	R2900305350	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$672,606
Building Name:	Savanna Portage SP Shop	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$212,856
Facility Condition Index:	0.32 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	3,695
Building Code:	R2900305360	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,480
Building Name:	Savanna Portage SP HQ Pump House	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$3,458
Facility Condition Index:	0.33 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	72
Building Code:	R2900305370	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$274,903
Building Name:	Savanna Portage SP Loon Lk San Bldg	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$39,720
Facility Condition Index:	0.14 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	1,425
Building Code:	R2900305390	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$179,009
Building Name:	Savanna Portage SP CG B-Loop San	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$59,073
Facility Condition Index:	0.33 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	576
Building Code:	R2900305400	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$89,856
Building Name:	Savanna Portage SP HQ Shed	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$26,129
Facility Condition Index:	0.29 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	1,020
Building Code:	R2900305410	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$33,079
Building Name:	Savanna Portage SP HQ Shed	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$9,316
Facility Condition Index:	0.28 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	520

Building Code:	R2900305420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna Portage SP Grp CG Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$1,952
Facility Condition Index:	0.31 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna Portage SP Grp CG Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$2,007
Facility Condition Index:	0.32 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,096
Building Name:	Savanna Portage SP Loon Lk Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$3,333
Facility Condition Index:	0.25 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	40
Building Code:	R2900305450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,096
Building Name:	Savanna Portage SP Savanna Lk Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$3,333
Facility Condition Index:	0.25 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	40
Building Code:	R2900305460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna PortSP Shumway CG Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$2,007
Facility Condition Index:	0.32 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna PortageSP CG Ste41 Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$2,007
Facility Condition Index:	0.32 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305770	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$141,639
Building Name:	Savanna Portage SP Lodging House	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$39,252
Facility Condition Index:	0.28 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	704
Building Code:	R2900305780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,036
Building Name:	Savanna Portage SP Shed	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$5,157
Facility Condition Index:	0.23 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	96
Building Code:	R2900305790	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$94,392
Building Name:	Savanna Portage SP Garage	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$22,134
Facility Condition Index:	0.23 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	768
Building Code:	R2900305830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,096
Building Name:	Savanna Portage SP Portage Trl Vaul	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$1,970
Facility Condition Index:	0.15 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	40
Building Code:	R2900305840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna PortSP WolfLk Boat Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$777
Facility Condition Index:	0.12 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305850	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,191
Building Name:	Savanna Portage SP SiteK Cold Stor	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$1,053
Facility Condition Index:	0.33 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29

Building Code:	R2900305860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna Portage SP E Sav R Bkp Vaul	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$622
Facility Condition Index:	0.10 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna PortSP WolfLk Bkpk Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$622
Facility Condition Index:	0.10 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305880	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,096
Building Name:	Savanna PortSP ContTrlDivBkpk Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$984
Facility Condition Index:	0.08 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	40
Building Code:	R2900305890	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna PortSP Pines Bkpk Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$622
Facility Condition Index:	0.10 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna Portage SP D Bkpk Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$622
Facility Condition Index:	0.10 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900305910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,224
Building Name:	Savanna PortSP Sav Lk Bkpk Pit Toil	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$622
Facility Condition Index:	0.10 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	29
Building Code:	R2900306100	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$48,837
Building Name:	Savanna Portage SP CG Cabin	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$8,488
Facility Condition Index:	0.17 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	252
Building Code:	R2900306960	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$262,773
Building Name:	Savanna Portage SP CG A-Loop San	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$6,568
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	880
Building Code:	R2900306970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,958
Building Name:	Savanna Portage SP CG A-Loop Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$1,328
Facility Condition Index:	0.07 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	54
Building Code:	R2900307260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,387
Building Name:	Savanna Portage SP CG Site 43 Vault	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$1,135
Facility Condition Index:	0.07 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	47
Building Code:	R2900308430	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$11,477
Building Name:	Savanna Portage SP GrpCG Adirondack	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$3,787
Facility Condition Index:	0.33 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	102
Building Code:	R2900308440	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,342
Building Name:	Savanna Portage SP HQ Cold Storage	**Address:**	55626 LAKE PLACE	**Deferred Maintenance:**	$1,103
Facility Condition Index:	0.33 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	34

Site: R290055 - Scenic State Park

Building Code:	R2900201060	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$289,094
Building Name:	Scenic SP Sanitation	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$95,035
Facility Condition Index:	0.33 - Poor	**City Code:**	BIGFORK	**Ext. Gross Area:**	800
Building Code:	R2900201070	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$54,699
Building Name:	Scenic SP Fish Cleaning House	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$10,605
Facility Condition Index:	0.19 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	180
Building Code:	R2900201080	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$386,644
Building Name:	Scenic SP Contact Station	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$35,809
Facility Condition Index:	0.09 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	1,411
Building Code:	R2900201090	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$64,433
Building Name:	Scenic SP Fish Cleaning House	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$22,790
Facility Condition Index:	0.35 - Poor	**City Code:**	BIGFORK	**Ext. Gross Area:**	180
Building Code:	R2900201100	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$169,580
Building Name:	Scenic SP Log Cabin	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$22,379
Facility Condition Index:	0.13 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	513
Building Code:	R2900201110	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$271,945
Building Name:	Scenic SP Log Sanitation	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$27,651
Facility Condition Index:	0.10 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	544
Building Code:	R2900201120	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$200,194
Building Name:	Scenic SP Water Tower	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$30,185
Facility Condition Index:	0.15 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	144
Building Code:	R2900201130	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$592,410
Building Name:	Scenic SP Chase Point Lodge	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$121,934
Facility Condition Index:	0.21 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	1,900
Building Code:	R2900201140	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$367,938
Building Name:	Scenic SP Log Sanitation	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$14,342
Facility Condition Index:	0.04 - Excellent	**City Code:**	BIGFORK	**Ext. Gross Area:**	925
Building Code:	R2900201150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$76,268
Building Name:	Scenic SP Log Cold Storage	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$10,731
Facility Condition Index:	0.14 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	432
Building Code:	R2900201160	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$68,091
Building Name:	Scenic SP Large Wood Shed	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$9,870
Facility Condition Index:	0.14 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	520

Building Code:	R2900201190	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$238,178
Building Name:	Scenic SP 3- Stall Log Garage	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$44,530
Facility Condition Index:	0.19 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	1,152
Building Code:	R2900201200	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$320,387
Building Name:	Scenic SP Cold Shop	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$81,814
Facility Condition Index:	0.26 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	2,304
Building Code:	R2900201210	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$402,899
Building Name:	Scenic SP Heated Shop	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$58,705
Facility Condition Index:	0.15 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	2,140
Building Code:	R2900201220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$103,986
Building Name:	Scenic SP Log Cold Storage Garage	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$17,148
Facility Condition Index:	0.16 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	589
Building Code:	R2900201230	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$599,501
Building Name:	Scenic SP Log Office	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$53,844
Facility Condition Index:	0.09 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	1,824
Building Code:	R2900203650	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$47,610
Building Name:	Scenic SP Spring House	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$10,613
Facility Condition Index:	0.22 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	111
Building Code:	R2900204240	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,259
Building Name:	Scenic SP Oil House	**Address:**	56956 Scenic Hwy 7	**Deferred Maintenance:**	$8,392
Facility Condition Index:	0.55 - Crisis	**City Code:**	BIGFORK	**Ext. Gross Area:**	96
Building Code:	R2900205730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,750
Building Name:	Scenic SP Lake of/Isle Wmn's Vault	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,131
Facility Condition Index:	0.17 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	20
Building Code:	R2900205740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,750
Building Name:	Scenic SP Lake of/Isle Men's Vault	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,131
Facility Condition Index:	0.17 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	20
Building Code:	R2900205750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,750
Building Name:	Scenic SP Women's Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$2,087
Facility Condition Index:	0.31 - Poor	**City Code:**	BIGFORK	**Ext. Gross Area:**	20
Building Code:	R2900205760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,750
Building Name:	Scenic SP Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$2,087
Facility Condition Index:	0.31 - Poor	**City Code:**	BIGFORK	**Ext. Gross Area:**	20
Building Code:	R2900205790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,125
Building Name:	Scenic SP Women's Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$2,577
Facility Condition Index:	0.25 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	30

Building Code:	R2900205800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,125
Building Name:	Scenic SP Mens Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$2,577
Facility Condition Index:	0.25 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	30
Building Code:	R2900205810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,843
Building Name:	Scenic SP Wood Shed	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$2,026
Facility Condition Index:	0.23 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	32
Building Code:	R2900205820	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,008
Building Name:	Scenic SP Oar Shed	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$149
Facility Condition Index:	0.05 - Excellent	**City Code:**	BIGFORK	**Ext. Gross Area:**	32
Building Code:	R2900207350	**Cost Model Name:**	Tower	**Current Replacement Value:**	$39,730
Building Name:	Scenic SP Fire Tower	**Address:**	56956 Scenic Hwy 7	**Deferred Maintenance:**	$8,010
Facility Condition Index:	0.20 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	64
Building Code:	R2900207840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,993
Building Name:	Scenic SP Chase Point Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,240
Facility Condition Index:	0.10 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	35
Building Code:	R2900207850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,993
Building Name:	Scenic SP Chase Point CG Uni Vault	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$887
Facility Condition Index:	0.07 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	35
Building Code:	R2900207860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,993
Building Name:	Scenic SP Chase Pt CG Boat Ld Vault	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,048
Facility Condition Index:	0.09 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	35
Building Code:	R2900207870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,993
Building Name:	Scenic SP Lodge Boat Landing Vault	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,048
Facility Condition Index:	0.09 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	35
Building Code:	R2900208550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,632
Building Name:	Scenic SP Unisex Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,453
Facility Condition Index:	0.09 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	48
Building Code:	R2900208730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,632
Building Name:	Scenic SP Lodge CG Uni Vault Toilet	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,232
Facility Condition Index:	0.07 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	48
Building Code:	R2900210220	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$15,483
Building Name:	Scenic SP Adirondack 1	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$7,854
Facility Condition Index:	0.51 - Crisis	**City Code:**	BIGFORK	**Ext. Gross Area:**	56
Building Code:	R2900210230	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,302
Building Name:	Scenic SP Adirondack 2	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$2,436
Facility Condition Index:	0.29 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	42

Building Code:	R2900210240	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$15,483
Building Name:	Scenic SP Adirondack 3	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$7,930
Facility Condition Index:	0.51 - Crisis	**City Code:**	BIGFORK	**Ext. Gross Area:**	56
Building Code:	R2900210250	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$12,478
Building Name:	Scenic SP Adirondack 4	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$7,762
Facility Condition Index:	0.62 - Crisis	**City Code:**	BIGFORK	**Ext. Gross Area:**	42
Building Code:	R2900210260	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$14,164
Building Name:	Scenic SP Adirondack 5	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$7,469
Facility Condition Index:	0.53 - Crisis	**City Code:**	BIGFORK	**Ext. Gross Area:**	56
Building Code:	R2900210280	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$11,094
Building Name:	Scenic SP Adirondack 6	**Address:**	56956 SCENIC HWY 7	**Deferred Maintenance:**	$1,260
Facility Condition Index:	0.11 - Good	**City Code:**	BIGFORK	**Ext. Gross Area:**	42

Site: R290056 - Schoolcraft State Park

Building Code:	R2900207010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,288
Building Name:	Schoolcraft SP Shop	**Address:**	9042 SCHOOLCRAFT LN NE	**Deferred Maintenance:**	$42,378
Facility Condition Index:	0.41 - Poor	**City Code:**	DEER RIVER	**Ext. Gross Area:**	864
Building Code:	R2900207030	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,721
Building Name:	Schoolcraft SP Oil House	**Address:**	9042 SCHOOLCRAFT LN NE	**Deferred Maintenance:**	$2,579
Facility Condition Index:	0.20 - Fair	**City Code:**	DEER RIVER	**Ext. Gross Area:**	96
Building Code:	R2900208000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,307
Building Name:	Schoolcraft SP Vault Toilet	**Address:**	9042 SCHOOLCRAFT LN NE	**Deferred Maintenance:**	$2,665
Facility Condition Index:	0.15 - Fair	**City Code:**	DEER RIVER	**Ext. Gross Area:**	50
Building Code:	R2900208020	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	Schoolcraft SP Vault Toilet	**Address:**	9042 SCHOOLCRAFT LN NE	**Deferred Maintenance:**	$1,587
Facility Condition Index:	0.15 - Fair	**City Code:**	DEER RIVER	**Ext. Gross Area:**	30
Building Code:	R2900210540	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$28,222
Building Name:	Schoolcraft SP Day Use Vault Concr	**Address:**	9042 SCHOOLCRAFT LN NE	**Deferred Maintenance:**	$564
Facility Condition Index:	0.02 - Excellent	**City Code:**	DEER RIVER	**Ext. Gross Area:**	51

Site: R290057 - Sibley State Park

Building Code:	R2900400020	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,448
Building Name:	Sibley SP Shop Area Cold Storage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$9,941
Facility Condition Index:	0.34 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	288

Building Code:	R2900400030	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$26,291
Building Name:	Sibley SP Shop Area Cold Storage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$10,786
Facility Condition Index:	0.41 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	288
Building Code:	R2900400050	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$473,657
Building Name:	Sibley SP Lakeview CG W Sanitation	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$84,959
Facility Condition Index:	0.18 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	896
Building Code:	R2900400060	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$1,012,700
Building Name:	Sibley SP Lakeview CG E Sanitation	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$107,328
Facility Condition Index:	0.11 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,687
Building Code:	R2900400070	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$463,469
Building Name:	Sibley SP Lakeview CG Picnic Shel 2	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$118,893
Facility Condition Index:	0.26 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,464
Building Code:	R2900400080	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$112,865
Building Name:	Sibley SP Lakeview CG Cold Storage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$16,898
Facility Condition Index:	0.15 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	216
Building Code:	R2900400090	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$81,099
Building Name:	Sibley SP Lkvw CG Fish Cleaning Hse	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$21,978
Facility Condition Index:	0.27 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	169
Building Code:	R2900400100	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$662,477
Building Name:	Sibley SP Beach Bath House	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$121,621
Facility Condition Index:	0.18 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	989
Building Code:	R2900400110	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$265,476
Building Name:	Sibley SP Cedar Hill Sanitation	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$91,056
Facility Condition Index:	0.34 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	522
Building Code:	R2900400120	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$232,835
Building Name:	Sibley SP Cedar Hill Pump House	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$26,085
Facility Condition Index:	0.11 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	470
Building Code:	R2900400130	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$777,041
Building Name:	Sibley SP Cedar Hill Picnic Shel 2	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$265,032
Facility Condition Index:	0.34 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,836
Building Code:	R2900400140	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$757,771
Building Name:	Sibley SP Group Center Dining Hall	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$182,901
Facility Condition Index:	0.24 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	3,552
Building Code:	R2900400160	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 8	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$25,530
Facility Condition Index:	0.15 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648

Building Code:	R2900400170	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 7	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$23,871
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648
Building Code:	R2900400180	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 6	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$23,871
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648
Building Code:	R2900400190	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 5	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$23,871
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648
Building Code:	R2900400200	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 4	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$27,412
Facility Condition Index:	0.16 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648
Building Code:	R2900400210	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 3	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$23,871
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648
Building Code:	R2900400220	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$168,567
Building Name:	Sibley SP Group Center Cabin 2	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$20,387
Facility Condition Index:	0.12 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	648
Building Code:	R2900400230	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$244,615
Building Name:	Sibley SP Group Center Rec Hall	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$98,380
Facility Condition Index:	0.40 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,200
Building Code:	R2900400240	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$425,995
Building Name:	Sibley SP Group Center Lodging Hse	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$105,568
Facility Condition Index:	0.25 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,824
Building Code:	R2900400250	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$676,490
Building Name:	Sibley SP Residence	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$177,041
Facility Condition Index:	0.26 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	2,568
Building Code:	R2900400260	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$782,971
Building Name:	Sibley SP Office	**Address:**	398 SIBLEY PARK RD NE	**Deferred Maintenance:**	$378,220
Facility Condition Index:	0.48 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	2,187
Building Code:	R2900400270	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$252,466
Building Name:	Sibley SP Shop Area Cold Storage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$100,374
Facility Condition Index:	0.40 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,608
Building Code:	R2900400280	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$462,815
Building Name:	Sibley SP Main Shop	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$157,548
Facility Condition Index:	0.34 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	2,100

Building Code:	R2900400290	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$334,090
Building Name:	Sibley SP Contact Station	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$116,416
Facility Condition Index:	0.35 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,284
Building Code:	R2900402700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$77,884
Building Name:	Sibley SP Residence Garage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$21,325
Facility Condition Index:	0.27 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	832
Building Code:	R2900402710	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$1,215,872
Building Name:	Sibley SP Interpretive Ctr	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$256,070
Facility Condition Index:	0.21 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	4,723
Building Code:	R2900402900	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,656
Building Name:	Sibley SP Shop Area HazMat Storage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$8,491
Facility Condition Index:	0.54 - Crisis	**City Code:**	NEW LONDON	**Ext. Gross Area:**	104
Building Code:	R2900402960	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$417,447
Building Name:	Sibley SP Oak Ridge CG Sanitation	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$44,376
Facility Condition Index:	0.11 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,120
Building Code:	R2900403000	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$490,470
Building Name:	Sibley SP Group Center Sanitation	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$137,736
Facility Condition Index:	0.28 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,350
Building Code:	R2900403060	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,894
Building Name:	Sibley SP Wood Storage	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$10,203
Facility Condition Index:	0.31 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	144
Building Code:	R2900403400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Sibley SP Horse CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,898
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	38
Building Code:	R2900403410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Sibley SP Horse CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,898
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	38
Building Code:	R2900403420	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$72,223
Building Name:	Sibley SP Mt Tom Observation Tower	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$15,743
Facility Condition Index:	0.22 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	440
Building Code:	R2900403690	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Sibley SP Oak Ridge CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$2,039
Facility Condition Index:	0.15 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	38
Building Code:	R2900403700	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Sibley SP Oak Ridge CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$2,039
Facility Condition Index:	0.15 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	38

Building Code:	R2900404230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,883
Building Name:	Sibley SP Lakeview CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$2,288
Facility Condition Index:	0.10 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	64
Building Code:	R2900404240	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,221
Building Name:	Sibley SP Boat Landing Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$3,047
Facility Condition Index:	0.19 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	64
Building Code:	R2900404250	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Sibley SP Mt Tom Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,857
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	38
Building Code:	R2900404260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,484
Building Name:	Sibley SP Group CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$2,402
Facility Condition Index:	0.18 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	38
Building Code:	R2900404950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,373
Building Name:	Sibley SP Picnic Area Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,817
Facility Condition Index:	0.10 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	47
Building Code:	R2900405030	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$73,333
Building Name:	Sibley SP Wastewater Cntrl Sys Bldg	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$6,728
Facility Condition Index:	0.09 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	200
Building Code:	R2900405100	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$82,922
Building Name:	Sibley SP Oak Rdg Lady Slipper Cab	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,658
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW LONDON	**Ext. Gross Area:**	288
Building Code:	R2900405110	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$82,922
Building Name:	Sibley SP Oak Ridge CG Loon Cabin	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,658
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW LONDON	**Ext. Gross Area:**	288
Building Code:	R2900405120	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$82,922
Building Name:	Sibley SP Oak Ridge CG Monarch Cab	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,658
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW LONDON	**Ext. Gross Area:**	288
Building Code:	R2900405130	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$82,922
Building Name:	Sibley SP Oak Ridge CG Walleye Cab	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$1,658
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW LONDON	**Ext. Gross Area:**	288
Building Code:	R2900405170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$36,667
Building Name:	Sibley SP Group CG Vault Toilet	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$3,641
Facility Condition Index:	0.10 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	102
Building Code:	R2900405180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$92,716
Building Name:	Sibley SP Oak Ridge CG Vault Concr	**Address:**	800 SIBLEY PARK RD NE	**Deferred Maintenance:**	$3,055
Facility Condition Index:	0.03 - Excellent	**City Code:**	NEW LONDON	**Ext. Gross Area:**	102

Site: R290058 - Lake Vermilion-Soudan Underground Mine State P

Building Code:	R2900202310	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,136,807
Building Name:	Lake Ver-Soudan SP Engine House	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$1,291,170
Facility Condition Index:	0.41 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	10,072
Building Code:	R2900202320	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,765,878
Building Name:	Lake Ver-Sdn SP Mine Ar Dry House	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$811,008
Facility Condition Index:	0.46 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	4,309
Building Code:	R2900202330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,217
Building Name:	Lake Ver-Soudan SP Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$3,422
Facility Condition Index:	0.31 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	108
Building Code:	R2900202340	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$52,246
Building Name:	Lake Ver-Soudan SP Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$16,396
Facility Condition Index:	0.31 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	364
Building Code:	R2900202350	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$762,559
Building Name:	Lake Ver-Sdn SP Mine Ore Crush Bldg	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$435,586
Facility Condition Index:	0.57 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	6,376
Building Code:	R2900202360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$271,383
Building Name:	Lake Ver-Sdn SP Mine Ar Cold Stor	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$168,256
Facility Condition Index:	0.62 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,560
Building Code:	R2900202370	**Cost Model Name:**	Tower	**Current Replacement Value:**	$18,510
Building Name:	Lake Ver-Sdn Mine Ore Crsh Twr Bldg	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$6,108
Facility Condition Index:	0.33 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,190
Building Code:	R2900202380	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,312
Building Name:	Lake Ver-Soudan SP Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$4,844
Facility Condition Index:	0.58 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	64
Building Code:	R2900202390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,363
Building Name:	Lake Ver-Sdn SP Mine Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$49,248
Facility Condition Index:	0.84 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	408
Building Code:	R2900202400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,493
Building Name:	Lake Ver-Soudan SP Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$6,387
Facility Condition Index:	0.37 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	130
Building Code:	R2900202410	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$30,156
Building Name:	Lake Ver-Soudan SP Contact Station	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$9,951
Facility Condition Index:	0.33 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	80

Building Code:	R2900202420	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$462,132
Building Name:	Lake Ver-Soudan SP Residence	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$53,665
Facility Condition Index:	0.12 - Good	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,937
Building Code:	R2900202430	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$312,612
Building Name:	Lake Ver-Soudan SP Pay Office	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$92,268
Facility Condition Index:	0.30 - Fair	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,140
Building Code:	R2900202440	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,606,752
Building Name:	Lake Ver-Soudan SP Old Machine Shop	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$1,012,424
Facility Condition Index:	0.63 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	9,740
Building Code:	R2900202450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$97,513
Building Name:	Lake Ver-Soudan SP Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$78,468
Facility Condition Index:	0.80 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,040
Building Code:	R2900202460	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$193,054
Building Name:	Lake Ver-Soudan SP Cold Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$68,498
Facility Condition Index:	0.35 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,383
Building Code:	R2900202470	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$217,716
Building Name:	Lake Ver-Soudan SP 4-Stall Garage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$129,183
Facility Condition Index:	0.59 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,260
Building Code:	R2900202480	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,885
Building Name:	Lake Ver-Soudan SP Hose Storage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$13,820
Facility Condition Index:	0.82 - Crisis	**City Code:**	SOUDAN	**Ext. Gross Area:**	160
Building Code:	R2900202500	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$141,715
Building Name:	Lake Ver-Soudan SP Pump House	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$66,503
Facility Condition Index:	0.47 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	936
Building Code:	R2900204000	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$51,906
Building Name:	Lake Ver-Soudan SP Residence Garage	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$9,884
Facility Condition Index:	0.19 - Fair	**City Code:**	SOUDAN	**Ext. Gross Area:**	576
Building Code:	R2900207380	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$752,785
Building Name:	Lake Ver-Soudan SP Shop	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$115,317
Facility Condition Index:	0.15 - Fair	**City Code:**	SOUDAN	**Ext. Gross Area:**	4,536
Building Code:	R2900209260	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$878,711
Building Name:	Lake Ver-Soudan Mine Water Trtmnt	**Address:**	4793 ARMSTRONG BAY RD W	**Deferred Maintenance:**	$87,871
Facility Condition Index:	0.10 - Good	**City Code:**	SOUDAN	**Ext. Gross Area:**	3,975
Building Code:	R2900209520	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$51,352
Building Name:	Lake Ver-Sdn SP Armstr Bay Up Vault	**Address:**	4761 ARMSTRONG BAY RD W	**Deferred Maintenance:**	$1,027
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	51

Building Code:	R2900209530	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$91,142
Building Name:	Lake Ver-Sdn SP Armstr Up Pic Shel	**Address:**	4761 ARMSTRONG BAY RD W	**Deferred Maintenance:**	$1,823
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	444
Building Code:	R2900209540	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$91,142
Building Name:	Lake Ver-Sdn SP Arms S Low Pic Shel	**Address:**	4761 ARMSTRONG BAY RD W	**Deferred Maintenance:**	$1,823
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	444
Building Code:	R2900209550	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$91,142
Building Name:	Lake Ver-Sdn SP Arms N Low Pic Shel	**Address:**	4761 ARMSTRONG BAY RD W	**Deferred Maintenance:**	$1,823
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	444
Building Code:	R2900209560	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$51,352
Building Name:	Lake Ver-Sdn SP Armst Bay Low Vault	**Address:**	4761 ARMSTRONG BAY RD W	**Deferred Maintenance:**	$1,027
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	51
Building Code:	R2900209570	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$190,950
Building Name:	Lk Ver-Sdn SP W Big Sky Pic Shel	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$3,819
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	702
Building Code:	R2900209580	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$492,311
Building Name:	Lk Ver-Sdn SP Verm Ridge CG San	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$9,846
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,077
Building Code:	R2900209590	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$190,950
Building Name:	Lk Ver-Sdn SP E Big Sky Pic Shel	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$3,819
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	702
Building Code:	R2900209600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$56,021
Building Name:	Lk Ver-Sdn SP Big Sky Vault	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$1,120
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	51
Building Code:	R2900209620	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$56,021
Building Name:	Lk Ver-Sdn Vrm Rdg 100 Series Vault	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$1,120
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	96
Building Code:	R2900209630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$56,021
Building Name:	Lk Ver-Sdn Vrm Rdg 300 Series Vault	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$1,120
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	51
Building Code:	R2900209640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$56,021
Building Name:	Lk Ver-Sdn Vrm Rdg 400 Series Vault	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$1,120
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	51
Building Code:	R2900209650	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$405,261
Building Name:	Lk Ver-Sdn SP Verm Ridge CG San 2	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$8,105
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	879

Building Code:	R2900209660	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$182,761
Building Name:	Lk Ver-Sdn SP Cedar Valley Pic Shel	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$3,655
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	702
Building Code:	R2900209670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$59,522
Building Name:	Lk Ver-Sdn SP Cedar Valley Vault	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$1,190
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	102
Building Code:	R2900209840	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$19,595
Building Name:	Lake Ver-Sdn SP Blue Heron Bunkhse	**Address:**	Blue Heron Island	**Deferred Maintenance:**	$7,183
Facility Condition Index:	0.37 - Poor	**City Code:**	SOUDAN	**Ext. Gross Area:**	131
Building Code:	R2900209940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$56,021
Building Name:	Lk Ver-Sdn SP Cable Bay WAS Vault	**Address:**	4909 VERMILION RIDGE RD	**Deferred Maintenance:**	$1,120
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	96
Building Code:	R2900210270	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$320,939
Building Name:	Lake Ver-Sdn SP Blue Heron Cabin	**Address:**	Blue Heron Island	**Deferred Maintenance:**	$34,584
Facility Condition Index:	0.11 - Good	**City Code:**	SOUDAN	**Ext. Gross Area:**	1,012
Building Code:	R2900210350	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$140,297
Building Name:	Lk Ver-Sdn SP Vrm Rdg H2O Stor Gar	**Address:**	4805 VERMILION RIDGE RD	**Deferred Maintenance:**	$2,806
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	624
Building Code:	R2900210400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$23,773
Building Name:	Lake Ver-Sdn SP Blue Heron Vault	**Address:**	Blue Heron Island	**Deferred Maintenance:**	$475
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	51
Building Code:	R2900210410	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$92,375
Building Name:	Lake Ver-Sdn Lake Lodg Water Trtmnt	**Address:**	4793 Armstrong Bay Rd W	**Deferred Maintenance:**	$1,847
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	609
Building Code:	R2900210520	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$30,261
Building Name:	Lake Ver-Sdn SP Blue Heron Shed	**Address:**	Blue Heron Island	**Deferred Maintenance:**	$3,026
Facility Condition Index:	0.10 - Good	**City Code:**	SOUDAN	**Ext. Gross Area:**	192
Building Code:	R2900210530	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$6,417
Building Name:	Lake Ver-Sdn SP Blue Heron Vault	**Address:**	Blue Heron Island	**Deferred Maintenance:**	$1,151
Facility Condition Index:	0.18 - Fair	**City Code:**	SOUDAN	**Ext. Gross Area:**	20
Building Code:	R2900210560	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$44,494
Building Name:	Lk Ver-Sdn SP Entrance Reg Kiosk	**Address:**	4887 VERMILION RIDGE RD	**Deferred Maintenance:**	$890
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	439
Building Code:	R2900210570	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$41,340
Building Name:	Lk Ver-Sdn SP Vault Toilet Utility	**Address:**	4887 VERMILION RIDGE RD	**Deferred Maintenance:**	$827
Facility Condition Index:	0.02 - Excellent	**City Code:**	SOUDAN	**Ext. Gross Area:**	112

Site: R290059 - Split Rock Creek State Park

Building Code:	R2900401030	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$146,338
Building Name:	Split Rock Creek SP Bath House	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$49,322
Facility Condition Index:	0.34 - Poor	**City Code:**	JASPER	**Ext. Gross Area:**	1,099
Building Code:	R2900401050	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$193,241
Building Name:	Split Rock Creek SP Picnic Shel 2	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$113,021
Facility Condition Index:	0.58 - Crisis	**City Code:**	JASPER	**Ext. Gross Area:**	1,200
Building Code:	R2900401060	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$318,744
Building Name:	Split Rock Creek SP Well House	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$45,563
Facility Condition Index:	0.14 - Good	**City Code:**	JASPER	**Ext. Gross Area:**	675
Building Code:	R2900401070	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$249,917
Building Name:	Split Rock Creek SP Shop	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$51,196
Facility Condition Index:	0.20 - Fair	**City Code:**	JASPER	**Ext. Gross Area:**	1,077
Building Code:	R2900401080	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$161,050
Building Name:	Split Rock Creek SP CG Sanitation	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$23,497
Facility Condition Index:	0.15 - Good	**City Code:**	JASPER	**Ext. Gross Area:**	572
Building Code:	R2900403250	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,224
Building Name:	Split Rock Creek SP Oil House	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$2,300
Facility Condition Index:	0.37 - Poor	**City Code:**	JASPER	**Ext. Gross Area:**	64
Building Code:	R2900403770	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$23,326
Building Name:	Split Rock Creek SP Fish Cleang Hse	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$5,334
Facility Condition Index:	0.23 - Fair	**City Code:**	JASPER	**Ext. Gross Area:**	180
Building Code:	R2900403900	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,481
Building Name:	Split Rock Creek SP Picnic Vault	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$4,208
Facility Condition Index:	0.26 - Fair	**City Code:**	JASPER	**Ext. Gross Area:**	47
Building Code:	R2900403910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,481
Building Name:	Split Rock Creek SP CG Vault Toilet	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$2,333
Facility Condition Index:	0.14 - Good	**City Code:**	JASPER	**Ext. Gross Area:**	47
Building Code:	R2900403920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,481
Building Name:	Split Rock Creek SP Beach ADA Vault	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$4,208
Facility Condition Index:	0.26 - Fair	**City Code:**	JASPER	**Ext. Gross Area:**	47
Building Code:	R2900404660	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$28,420
Building Name:	Split Rock Creek SP Cold Storage	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$9,379
Facility Condition Index:	0.33 - Poor	**City Code:**	JASPER	**Ext. Gross Area:**	384

Building Code:	R2900404710	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$351,882
Building Name:	Split Rock Creek SP Contact Station	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$64,333
Facility Condition Index:	0.18 - Fair	**City Code:**	JASPER	**Ext. Gross Area:**	903
Building Code:	R2900405270	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,198
Building Name:	Split Rock Creek SP Wood Storage	**Address:**	336 50TH AVE	**Deferred Maintenance:**	$2,123
Facility Condition Index:	0.41 - Poor	**City Code:**	JASPER	**Ext. Gross Area:**	48

Site: R290060 - Split Rock Lighthouse State Park

Building Code:	R2900204350	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$127,131
Building Name:	Split Rock Lighthouse SP Shop	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$12,713
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	1,083
Building Code:	R2900204370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,197
Building Name:	Split Rock Lighthouse SP Cold Stor	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$6,199
Facility Condition Index:	0.41 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	160
Building Code:	R2900204450	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$696,992
Building Name:	Split Rock Lighthouse SP Trails Ctr	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$67,990
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	2,700
Building Code:	R2900204460	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$308,616
Building Name:	Split Rock Lighthouse SP Sanitation	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$43,740
Facility Condition Index:	0.14 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	900
Building Code:	R2900204470	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$53,873
Building Name:	Split Rock Lighthouse Picnic Shel 2	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$1,077
Facility Condition Index:	0.02 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	400
Building Code:	R2900205410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,710
Building Name:	Split Rock Lighthouse Vault Toilet	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$3,864
Facility Condition Index:	0.33 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	30
Building Code:	R2900205440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,710
Building Name:	Split Rock Lighthouse Site15 Vault	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$3,864
Facility Condition Index:	0.33 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	30
Building Code:	R2900206620	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$349,556
Building Name:	Split Rock Lighthouse SP Contact St	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$32,769
Facility Condition Index:	0.09 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	1,077
Building Code:	R2900206630	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,945
Building Name:	Split Rock Lighthouse SP Cold Stor	**Address:**	3755 Split Rock Lighthouse Rd	**Deferred Maintenance:**	$3,131
Facility Condition Index:	0.39 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	48

Building Code:	R2900207710	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$352,544
Building Name:	Split Rock Lighthouse SP Shop	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$37,409
Facility Condition Index:	0.11 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	2,268
Building Code:	R2900208750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,026
Building Name:	Split Rock Lighthouse Diver's Vault	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$1,329
Facility Condition Index:	0.07 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	47
Building Code:	R2900209910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$32,070
Building Name:	SplitRock Lighthse PebBe Vault Conc	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$641
Facility Condition Index:	0.02 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	51
Building Code:	R2900209920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$32,070
Building Name:	SplitRock Lighthouse CG Vault Conc	**Address:**	3755 SPLIT ROCK LIGHTHOUSE F	**Deferred Maintenance:**	$641
Facility Condition Index:	0.02 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	51

Site: R290061 - St Croix State Park

Building Code:	R2900301500	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$766,033
Building Name:	St Croix SP Head Rapids Dining Hall	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$236,046
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	3,015
Building Code:	R2900301510	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$99,383
Building Name:	St Croix SP Head of Rapids Garage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$38,942
Facility Condition Index:	0.39 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	816
Building Code:	R2900301520	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$199,885
Building Name:	St Croix SP Head of Rapids San A	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$75,204
Facility Condition Index:	0.38 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	508
Building Code:	R2900301530	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$107,619
Building Name:	St Croix SP Head Rapids Dormitory	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$34,256
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301540	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$107,619
Building Name:	St Croix SP Head Rapids Dormitory	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$34,256
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301550	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$107,619
Building Name:	St Croix SP Head Rapids Dormitory	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$34,256
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301560	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$103,834
Building Name:	St Croix SP Head Rapids Dorm B1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$30,786
Facility Condition Index:	0.30 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576

Building Code:	R2900301570	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$103,834
Building Name:	St Croix SP Head Rapids Dorm B2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$33,007
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301580	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$103,834
Building Name:	St Croix SP Head Rapids Dorm B3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$30,786
Facility Condition Index:	0.30 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301590	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$36,307
Building Name:	St Croix SP Head Rapids San B	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$18,162
Facility Condition Index:	0.50 - Crisis	**City Code:**	HINCKLEY	**Ext. Gross Area:**	360
Building Code:	R2900301600	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$103,834
Building Name:	St Croix SP Head Rapids Dorm C1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$30,786
Facility Condition Index:	0.30 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301610	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$103,834
Building Name:	St Croix SP Head Rapids Dorm C2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$33,007
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301620	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$86,529
Building Name:	St Croix SP Head Rapids Dorm C3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$25,011
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	576
Building Code:	R2900301630	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$129,793
Building Name:	St Croix SP Head Rapids Dorm C4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$38,482
Facility Condition Index:	0.30 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	720
Building Code:	R2900301640	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$136,072
Building Name:	St Croix SP Head Rapids San C	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$43,298
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	448
Building Code:	R2900301650	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$82,023
Building Name:	St Croix SP Head Rapids Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$17,844
Facility Condition Index:	0.22 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	256
Building Code:	R2900301660	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$76,950
Building Name:	St Croix SP Head Rapids Rec Hall	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$22,427
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	540
Building Code:	R2900301670	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$121,790
Building Name:	St Croix SP Head Rapids Lodging Hse	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$29,494
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	580
Building Code:	R2900301680	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$90,536
Building Name:	St Croix SP Head Rapids Office Dorm	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$28,616
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	510

Building Code:	R2900301690	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$108,794
Building Name:	St Croix SP Head Rapids Infirmary	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$32,622
Facility Condition Index:	0.30 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	594
Building Code:	R2900301700	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$49,613
Building Name:	St Croix SP Head Rapids Cooks Shack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$15,547
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301710	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$212,617
Building Name:	St Croix SP Clayton Lk Beach San	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$24,987
Facility Condition Index:	0.12 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	624
Building Code:	R2900301730	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$666,797
Building Name:	St Croix SP St Johns Ln Dining Hall	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$203,480
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,899
Building Code:	R2900301750	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$111,629
Building Name:	St Croix SP St Johns Lodging House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$33,690
Facility Condition Index:	0.30 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	324
Building Code:	R2900301760	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$78,439
Building Name:	St Croix SP St Johns Lnd Cook Shack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$22,738
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	324
Building Code:	R2900301770	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$184,764
Building Name:	St Croix SP St Johns Lnd Infirmary	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$55,049
Facility Condition Index:	0.30 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	924
Building Code:	R2900301780	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$144,705
Building Name:	St Croix SP St Johns Lnd Office	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$45,223
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	432
Building Code:	R2900301790	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$306,501
Building Name:	St Croix SP St Johns Lnd Sanitation	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$38,181
Facility Condition Index:	0.12 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	928
Building Code:	R2900301800	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$75,095
Building Name:	St Croix SP St Johns Lnd Rec Hall	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$18,828
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	540
Building Code:	R2900301810	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$45,676
Building Name:	St Croix SP St Johns Lnd Sanitatn B	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$12,568
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	189
Building Code:	R2900301820	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,785
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240

Building Code:	R2900301830	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$8,029
Facility Condition Index:	0.30 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301840	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,076
Facility Condition Index:	0.27 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301850	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,078
Facility Condition Index:	0.34 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301860	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,261
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301870	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,261
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301880	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm B7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,785
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301890	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$6,878
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301900	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$4,505
Facility Condition Index:	0.17 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301910	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$4,715
Facility Condition Index:	0.18 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301920	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$4,183
Facility Condition Index:	0.16 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301930	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,547
Facility Condition Index:	0.21 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301940	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$4,505
Facility Condition Index:	0.17 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240

Building Code:	R2900301950	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm C7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,547
Facility Condition Index:	0.21 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900301960	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$48,183
Building Name:	St Croix SP St Johns Lnd Sanitatn C	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,793
Facility Condition Index:	0.22 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	189
Building Code:	R2900301970	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$200,279
Building Name:	St Croix SP St Johns Lnd Rec Hall C	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$34,254
Facility Condition Index:	0.17 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	704
Building Code:	R2900301980	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$200,279
Building Name:	St Croix SP St Johns Lnd Rec Hall D	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$20,068
Facility Condition Index:	0.10 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	704
Building Code:	R2900301990	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$45,676
Building Name:	St Croix SP St Johns Lnd Sanitatn D	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$21,787
Facility Condition Index:	0.48 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	189
Building Code:	R2900302000	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm D1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$6,611
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302010	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm D2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,953
Facility Condition Index:	0.23 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302020	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$19,511
Building Name:	St Croix SP St Johns Lnd Dorm D3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$15,415
Facility Condition Index:	0.79 - Crisis	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302030	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm D4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,798
Facility Condition Index:	0.22 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302040	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm D5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,536
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302050	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm D6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,536
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302060	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm D7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$6,611
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240

Building Code:	R2900302070	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$90,292
Building Name:	St Croix SP St Johns Lnd Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$29,153
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	256
Building Code:	R2900302080	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$200,279
Building Name:	St Croix SP St Johns Lnd Rec Hall A	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$22,681
Facility Condition Index:	0.11 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	704
Building Code:	R2900302090	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$48,183
Building Name:	St Croix SP St Johns Lnd Sanitatn A	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,190
Facility Condition Index:	0.11 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	189
Building Code:	R2900302100	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm A1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$6,898
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302110	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm A2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,345
Facility Condition Index:	0.35 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302120	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$26,396
Building Name:	St Croix SP St Johns Lnd Dorm A3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$6,547
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302130	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$34,453
Building Name:	St Croix SP St Johns Lnd Dorm A4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,321
Facility Condition Index:	0.27 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302140	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$34,453
Building Name:	St Croix SP St Johns Lnd Dorm A5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,920
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302150	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$34,453
Building Name:	St Croix SP St Johns Lnd Dorm A6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,072
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302160	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$34,453
Building Name:	St Croix SP St Johns Lnd Dorm A7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,122
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$696,224
Building Name:	St Croix SP Norway Pt Dining Hall	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$181,801
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,953
Building Code:	R2900302180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$183,320
Building Name:	St Croix SP Norway Pt Garage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$73,050
Facility Condition Index:	0.40 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,248

Building Code:	R2900302190	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$265,217
Building Name:	St Croix SP Norway Pt Infirmary	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$76,513
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,045
Building Code:	R2900302200	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$405,418
Building Name:	St Croix SP Norway Pt Lodging House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$110,733
Facility Condition Index:	0.27 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,395
Building Code:	R2900302210	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$106,477
Building Name:	St Croix SP Norway Pt Office	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$30,771
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	366
Building Code:	R2900302220	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$44,841
Building Name:	St Croix SP Norway Pt Sanitation A	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$13,898
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	216
Building Code:	R2900302230	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$133,238
Building Name:	St Croix SP Norway Pt Rec Hall A	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$31,412
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	636
Building Code:	R2900302240	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$136,555
Building Name:	St Croix SP Norway Pt Dormitory A1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$42,907
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302250	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,336
Building Name:	St Croix SP Norway Pt Dormitory A2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,387
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302260	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,336
Building Name:	St Croix SP Norway Pt Dormitory A3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,568
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302270	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,647
Building Name:	St Croix SP Norway Pt Dormitory A4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,826
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302280	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,336
Building Name:	St Croix SP Norway Pt Dormitory A5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302290	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,336
Building Name:	St Croix SP Norway Pt Dormitory A6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$11,154
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302300	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,336
Building Name:	St Croix SP Norway Pt Dormitory A7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$11,154
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240

Building Code:	R2900302310	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$59,611
Building Name:	St Croix SP Norway Pt Sanitation B	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$14,215
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	216
Building Code:	R2900302320	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$119,259
Building Name:	St Croix SP Norway Pt Rec Hall B	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$30,847
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	636
Building Code:	R2900302330	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory B1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302340	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory B2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302350	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory B3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302360	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory B4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302370	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$42,136
Building Name:	St Croix SP Norway Pt Dormitory B5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$11,746
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302380	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory B6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302390	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory B7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302400	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$59,624
Building Name:	St Croix SP Norway Pt Sanitation C	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$17,104
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	216
Building Code:	R2900302410	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$119,259
Building Name:	St Croix SP Norway Pt Rec Hall C	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$34,694
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	636
Building Code:	R2900302420	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory C1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240

Building Code:	R2900302430	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory C2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302440	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory C3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,475
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302450	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory C4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302460	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory C5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302470	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$36,851
Building Name:	St Croix SP Norway Pt Dormitory C6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$11,085
Facility Condition Index:	0.30 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302480	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory C7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,290
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302490	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$59,624
Building Name:	St Croix SP Norway Pt Sanitation D	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$15,415
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	216
Building Code:	R2900302500	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$136,369
Building Name:	St Croix SP Norway Pt Rec Hall D	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$35,525
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	636
Building Code:	R2900302510	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory D1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302520	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory D2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302530	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory D3	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302540	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory D4	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240

Building Code:	R2900302550	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory D5	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302560	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$40,006
Building Name:	St Croix SP Norway Pt Dormitory D6	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,825
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302570	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$39,576
Building Name:	St Croix SP Norway Pt Dormitory D7	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,648
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900302580	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$76,286
Building Name:	St Croix SP Norway Pt Rec Hall	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$15,540
Facility Condition Index:	0.20 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	600
Building Code:	R2900302590	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$335,153
Building Name:	St Croix SP Norway Pt Central San	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$25,043
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	943
Building Code:	R2900302600	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$78,873
Building Name:	St Croix SP Norway Pt Lodging House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$22,294
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	390
Building Code:	R2900302610	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$69,409
Building Name:	St Croix SP Norway Pt Cooks Shack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$15,729
Facility Condition Index:	0.23 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	390
Building Code:	R2900302620	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$95,625
Building Name:	St Croix SP Ranger Contact Station	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$25,265
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	440
Building Code:	R2900302640	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,260,861
Building Name:	St Croix SP Lodge Interp Center	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$184,063
Facility Condition Index:	0.15 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	3,915
Building Code:	R2900302650	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$53,626
Building Name:	St Croix SP Hexigon Log Wood Shed	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$23,219
Facility Condition Index:	0.43 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	441
Building Code:	R2900302660	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$899,655
Building Name:	St Croix SP Riverview CG Sanitation	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$147,447
Facility Condition Index:	0.16 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,752
Building Code:	R2900302670	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$201,030
Building Name:	St Croix SP Riverview A&B Cabin	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$49,485
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	660

Building Code:	R2900302680	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$311,190
Building Name:	St Croix SP Riverview C, D&E Cabin	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$62,796
Facility Condition Index:	0.20 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,226
Building Code:	R2900302690	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$52,148
Building Name:	St Croix SP Old Log Trl Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,453
Facility Condition Index:	0.20 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	152
Building Code:	R2900302700	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$91,439
Building Name:	St Croix SP Riverview Jack Pine Cab	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$17,781
Facility Condition Index:	0.19 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	322
Building Code:	R2900302710	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$223,266
Building Name:	St Croix SP Paint Rock Springs San	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$21,780
Facility Condition Index:	0.10 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	608
Building Code:	R2900302730	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$130,862
Building Name:	St Croix SP HQ Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$21,230
Facility Condition Index:	0.16 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	384
Building Code:	R2900302740	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$702,244
Building Name:	St Croix SP Residence 1	**Address:**	53927 YELLOW BANKS DR	**Deferred Maintenance:**	$184,300
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,654
Building Code:	R2900302750	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$110,725
Building Name:	St Croix SP Residence 1 Garage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$26,928
Facility Condition Index:	0.24 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	650
Building Code:	R2900302760	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$390,953
Building Name:	St Croix SP Residence 2	**Address:**	53848 YELLOW BANKS DRIVE	**Deferred Maintenance:**	$103,231
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,576
Building Code:	R2900302770	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$390,953
Building Name:	St Croix SP Residence 3	**Address:**	53760 YELLOW BANKS DR	**Deferred Maintenance:**	$115,037
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,576
Building Code:	R2900302780	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$142,195
Building Name:	St Croix SP Residences 2&3 Garage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$56,893
Facility Condition Index:	0.40 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,120
Building Code:	R2900302790	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$252,180
Building Name:	St Croix SP HQ Dormitory	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$70,814
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	920
Building Code:	R2900302800	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,281
Building Name:	St Croix SP HQ Dormitory Garage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$10,272
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	430

Building Code:	R2900302810	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$965,478
Building Name:	St Croix SP HQ Mechanic Shop	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$282,905
Facility Condition Index:	0.29 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,162
Building Code:	R2900302820	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,062,743
Building Name:	St Croix SP HQ Carpenter Shop	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$275,762
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,887
Building Code:	R2900302830	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,255,418
Building Name:	St Croix SP HQ Cold Storage H-13	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$160,483
Facility Condition Index:	0.13 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,618
Building Code:	R2900302840	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$141,522
Building Name:	St Croix SP HQ Oil House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$18,253
Facility Condition Index:	0.13 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	315
Building Code:	R2900302880	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$539,382
Building Name:	St Croix SP HQ Office	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$77,147
Facility Condition Index:	0.14 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,296
Building Code:	R2900302930	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$485,038
Building Name:	St Croix SP Trails Center	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$118,905
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,131
Building Code:	R2900302940	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$200,279
Building Name:	St Croix SP St Johns Lnd Rec Hall B	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$11,449
Facility Condition Index:	0.06 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	704
Building Code:	R2900302950	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,387
Building Name:	St Croix SP Trail Ctr Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$12,498
Facility Condition Index:	0.37 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	110
Building Code:	R2900302960	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$51,027
Building Name:	St Croix SP Riverview CG Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,037
Facility Condition Index:	0.18 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	131
Building Code:	R2900302970	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$247,682
Building Name:	St Croix SP HQ Lumber Shed	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$26,485
Facility Condition Index:	0.11 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	2,430
Building Code:	R2900302990	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$90,801
Building Name:	St Croix SP Riverview CG Tower	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$9,807
Facility Condition Index:	0.11 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	242
Building Code:	R2900303010	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$26,706
Building Name:	St Croix SP Bear Creek W Adirondack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,010
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	320

Building Code:	R2900303020	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$22,255
Building Name:	St Croix SP Bear Creek W Adirondack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,657
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	320
Building Code:	R2900303030	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$54,460
Building Name:	StCroix SP Crooked Crk E Adirondack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,332
Facility Condition Index:	0.13 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	320
Building Code:	R2900303040	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$54,460
Building Name:	StCroix SP Crooked Crk E Adirondack	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$7,332
Facility Condition Index:	0.13 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	320
Building Code:	R2900303230	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$422,539
Building Name:	St Croix SP Norway Pt Guest House 2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$97,248
Facility Condition Index:	0.23 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,971
Building Code:	R2900303240	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$549,859
Building Name:	St Croix SP Norway Pt Guest House 1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$73,472
Facility Condition Index:	0.13 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,971
Building Code:	R2900303500	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,412
Building Name:	St Croix SP Head Rapids Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$4,107
Facility Condition Index:	0.25 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	54
Building Code:	R2900303510	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,798
Building Name:	St Croix SP Cold Storage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$680
Facility Condition Index:	0.10 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	52
Building Code:	R2900303520	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,788
Building Name:	St Croix SP Paint Rock Spr Pumphse	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,038
Facility Condition Index:	0.11 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	36
Building Code:	R2900303530	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$77,864
Building Name:	St Croix SP Norway Pt Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$20,868
Facility Condition Index:	0.27 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	196
Building Code:	R2900303540	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$136,050
Building Name:	StCroixSP Clayton Lk Bch Pic Shel 2	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$20,329
Facility Condition Index:	0.15 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,248
Building Code:	R2900303570	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$45,299
Building Name:	St Croix SP St Johns Lodging House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$8,953
Facility Condition Index:	0.20 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	240
Building Code:	R2900304280	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$953,981
Building Name:	St Croix SP HQ Shop	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$139,778
Facility Condition Index:	0.15 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	7,013

Building Code:	R2900304290	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$367,803
Building Name:	St Croix SP HQ Concession	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$41,259
Facility Condition Index:	0.11 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,043
Building Code:	R2900304560	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,994
Building Name:	St Croix SP Sand Crk Canoe Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,441
Facility Condition Index:	0.16 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	26
Building Code:	R2900304860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,448
Building Name:	St Croix SP Clayton Lk Beach Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$2,920
Facility Condition Index:	0.26 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	35
Building Code:	R2900304880	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$5,959
Building Name:	St Croix SP East Area Vault Toilet	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$2,820
Facility Condition Index:	0.47 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	27
Building Code:	R2900304910	**Cost Model Name:**	Tower	**Current Replacement Value:**	$18,605
Building Name:	St Croix SP West Area Fire Tower	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,875
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	49
Building Code:	R2900304980	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,788
Building Name:	St Croix SP Riverview CG Pump House	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,866
Facility Condition Index:	0.19 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	36
Building Code:	R2900304990	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$24,935
Building Name:	St Croix SP Bike Picnic Shelter 1	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,106
Facility Condition Index:	0.04 - Excellent	**City Code:**	HINCKLEY	**Ext. Gross Area:**	800
Building Code:	R2900305000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,179
Building Name:	St Croix SP Old Log Trl S195 Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,859
Facility Condition Index:	0.20 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	27
Building Code:	R2900305010	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,179
Building Name:	St Croix SP Old Log Trl S195 Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,449
Facility Condition Index:	0.16 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	27
Building Code:	R2900305920	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,804
Building Name:	St Croix SP HQ Cold Storage	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$216
Facility Condition Index:	0.02 - Excellent	**City Code:**	HINCKLEY	**Ext. Gross Area:**	99
Building Code:	R2900305930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,462
Building Name:	St Croix SP Trail Ctr Vault Toilet	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$3,721
Facility Condition Index:	0.32 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	35
Building Code:	R2900305960	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,108
Building Name:	St Croix SP HQ Wood Shed	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$2,656
Facility Condition Index:	0.08 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	252

Building Code:	R2900306840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,142
Building Name:	St Croix SP Head Rapids Mess Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$3,141
Facility Condition Index:	0.21 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	47
Building Code:	R2900306850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,264
Building Name:	St Croix SP Old Log Trl S167 Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$2,049
Facility Condition Index:	0.15 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	40
Building Code:	R2900306860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,736
Building Name:	St Croix SP Paint Rock S125 Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,565
Facility Condition Index:	0.12 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	39
Building Code:	R2900307310	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,142
Building Name:	St Croix SP Little Yellow Bnk Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,117
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	47
Building Code:	R2900307320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,142
Building Name:	St Croix SP Big Eddy Canoe Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,117
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	47
Building Code:	R2900307330	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,637
Building Name:	St Croix SP Head Rapids Canoe Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,230
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	51
Building Code:	R2900307340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,314
Building Name:	St Croix SP Maple Isl Canoe Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,132
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	47
Building Code:	R2900307350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,286
Building Name:	St Croix SP Riverview CG Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,138
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	45
Building Code:	R2900307360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,862
Building Name:	St Croix SP Riverview CG S21 Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,179
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	47
Building Code:	R2900307730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,047
Building Name:	St Croix SP HQ Vault Toilet	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,191
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	48
Building Code:	R2900307740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,565
Building Name:	St Croix SP Norway Pt Vault Toilet	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$927
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	39
Building Code:	R2900307750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,787
Building Name:	St Croix SP Riverview CG Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,164
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	49

Building Code:	R2900307760	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,435
Building Name:	St Croix SP Riverview CG Recycle Sh	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$711
Facility Condition Index:	0.13 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	48
Building Code:	R2900307830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,943
Building Name:	St Croix SP St Johns Lnd Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,034
Facility Condition Index:	0.07 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	42
Building Code:	R2900307840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,993
Building Name:	St Croix SP Trail Ctr Vault Toilet	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,696
Facility Condition Index:	0.12 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	56
Building Code:	R2900307850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,993
Building Name:	St Croix SP Trail Ctr Vault Toilet	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$2,273
Facility Condition Index:	0.16 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	38
Building Code:	R2900308110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,497
Building Name:	St Croix SP Head Rapids Swim Vault	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$5,192
Facility Condition Index:	0.61 - Crisis	**City Code:**	HINCKLEY	**Ext. Gross Area:**	39
Building Code:	R2900308120	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$3,801
Building Name:	St Croix SP Head Rapids Cold Stor	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$1,356
Facility Condition Index:	0.36 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	64
Building Code:	R2900308130	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$6,332
Building Name:	St Croix SP St Johns Lnd Cold Stor	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$2,400
Facility Condition Index:	0.38 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	64
Building Code:	R2900308230	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$651,470
Building Name:	St Croix SP Old Log Trl Sanitation	**Address:**	30065 ST CROIX PARK RD	**Deferred Maintenance:**	$13,029
Facility Condition Index:	0.02 - Excellent	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,833

Site: R290062 - Temperance River State Park

Building Code:	R2900200990	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,398
Building Name:	Temperance River SP Oil House	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$6,880
Facility Condition Index:	0.34 - Poor	**City Code:**	SCHROEDER	**Ext. Gross Area:**	96
Building Code:	R2900201010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$264,413
Building Name:	Temperance River SP Shop/Cold Stor	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$58,926
Facility Condition Index:	0.22 - Fair	**City Code:**	SCHROEDER	**Ext. Gross Area:**	1,500
Building Code:	R2900201020	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$314,100
Building Name:	Temperance River SP Upper CG San	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$144,608
Facility Condition Index:	0.46 - Poor	**City Code:**	SCHROEDER	**Ext. Gross Area:**	792

Building Code:	R2900201040	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$35,024
Building Name:	Temperance River SP Wood Shed	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$5,007
Facility Condition Index:	0.14 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	384
Building Code:	R2900206780	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$361,510
Building Name:	Temperance River SP Shop	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$63,935
Facility Condition Index:	0.18 - Fair	**City Code:**	SCHROEDER	**Ext. Gross Area:**	2,016
Building Code:	R2900207520	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$363,001
Building Name:	Temperance River SP Contact Station	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$29,877
Facility Condition Index:	0.08 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	1,245
Building Code:	R2900208050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,295
Building Name:	Temperance River SP Upper CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,206
Facility Condition Index:	0.07 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208060	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Upper CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,617
Facility Condition Index:	0.10 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Upper CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,617
Facility Condition Index:	0.10 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208080	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Upper CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,834
Facility Condition Index:	0.11 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Upper CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$2,368
Facility Condition Index:	0.15 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208100	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Lower CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,985
Facility Condition Index:	0.12 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Lower CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,617
Facility Condition Index:	0.10 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Lower CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,617
Facility Condition Index:	0.10 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40
Building Code:	R2900208130	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,168
Building Name:	Temperance River SP Lower CG Vault	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,926
Facility Condition Index:	0.12 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	40

Building Code:	R2900208690	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,747
Building Name:	Temperance River SP Vault Toilet	**Address:**	7620 W HWY 61	**Deferred Maintenance:**	$1,580
Facility Condition Index:	0.08 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	47

Site: R290063 - Tettegouche State Park

Building Code:	R2900204010	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$357,029
Building Name:	Tettegouche SP Trails Center	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$124,073
Facility Condition Index:	0.35 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	1,224
Building Code:	R2900204020	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$163,625
Building Name:	Tettegouche SP Camper Cabin C	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$53,921
Facility Condition Index:	0.33 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	812
Building Code:	R2900204050	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$92,514
Building Name:	Tettegouche SP Barn (collapsed)	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$92,514
Facility Condition Index:	1.00 - Crisis	**City Code:**	SILVER BAY	**Ext. Gross Area:**	1,200
Building Code:	R2900204070	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,901
Building Name:	Tettegouche SP Cold Storage	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$8,931
Facility Condition Index:	0.34 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	120
Building Code:	R2900204080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$174,862
Building Name:	Tettegouche SP Camper Cabin B	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$57,621
Facility Condition Index:	0.33 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	896
Building Code:	R2900204090	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$126,590
Building Name:	Tettegouche SP Camper Cabin A	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$41,775
Facility Condition Index:	0.33 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	650
Building Code:	R2900204100	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$77,445
Building Name:	Tettegouche SP Camper Cabin D	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$13,574
Facility Condition Index:	0.18 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	306
Building Code:	R2900204110	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$37,202
Building Name:	Tettegouche SP Blacksmith (colapsd)	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$37,202
Facility Condition Index:	1.00 - Crisis	**City Code:**	SILVER BAY	**Ext. Gross Area:**	256
Building Code:	R2900204120	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$30,818
Building Name:	Tettegouche SP Bath House/Sauna	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$9,771
Facility Condition Index:	0.32 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	160
Building Code:	R2900204130	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$26,856
Building Name:	Tettegouche SP Boat House	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$10,444
Facility Condition Index:	0.39 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	242

Building Code:	R2900204480	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$378,235
Building Name:	Tettegouche SP Shop	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$79,993
Facility Condition Index:	0.21 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	2,555
Building Code:	R2900204500	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$510,955
Building Name:	Tettegouche SP Baptism Riv CG San	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$56,831
Facility Condition Index:	0.11 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	1,220
Building Code:	R2900205500	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Tettegouche SP Cart-In CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$4,874
Facility Condition Index:	0.36 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	35
Building Code:	R2900205540	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Tettegouche SP Cart-In CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$3,477
Facility Condition Index:	0.26 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	35
Building Code:	R2900205560	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Tettegouche SP Cart-In CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$4,874
Facility Condition Index:	0.36 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	35
Building Code:	R2900205960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Tettegouche SP Baptism Riv CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$1,938
Facility Condition Index:	0.14 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	35
Building Code:	R2900205970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Tettegouche SP Baptism Riv CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$2,570
Facility Condition Index:	0.19 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	35
Building Code:	R2900207390	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$262,320
Building Name:	Tettegouche SP Camper Cabin Sanitat	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$27,963
Facility Condition Index:	0.11 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	676
Building Code:	R2900207450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,628
Building Name:	Tettegouche SP Vault Toilet	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$2,942
Facility Condition Index:	0.22 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	35
Building Code:	R2900207660	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$361,974
Building Name:	Tettegouche SP Illgen Falls Cabin	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$35,419
Facility Condition Index:	0.10 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	884
Building Code:	R2900207670	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,836
Building Name:	Tettegouche SP Illgen Falls Shed	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$684
Facility Condition Index:	0.10 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	64
Building Code:	R2900208200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$28,704
Building Name:	Tettegouche SP Vault Toilet	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$9,128
Facility Condition Index:	0.32 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	80

Building Code:	R2900208210	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,280
Building Name:	Tettegouche SP Life Jacket Storage	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$5,530
Facility Condition Index:	0.39 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	72
Building Code:	R2900208220	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,407
Building Name:	Tettegouche SP Shed	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$3,903
Facility Condition Index:	0.31 - Poor	**City Code:**	SILVER BAY	**Ext. Gross Area:**	64
Building Code:	R2900208760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,026
Building Name:	Tettegouche SP Group CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$3,205
Facility Condition Index:	0.18 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	47
Building Code:	R2900208770	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,026
Building Name:	Tettegouche SP Group CG Vault	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$2,357
Facility Condition Index:	0.13 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	47
Building Code:	R2900208870	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,875
Building Name:	Tettegouche SP Blacksmith Bldg	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$1,092
Facility Condition Index:	0.05 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	211
Building Code:	R2900208920	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,257
Building Name:	Tettegouche SP Wood and Ice Shed	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$285
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	126
Building Code:	R2900209060	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$4,367,141
Building Name:	Tettegouche SP Visitor Center	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$87,343
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	12,738
Building Code:	R2900210550	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$32,070
Building Name:	Tettegouche SP Trailhd Vault Concr	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$641
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	51
Building Code:	R2900210840	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$100,639
Building Name:	Tettegouche SP Wood Shed	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$6,466
Facility Condition Index:	0.06 - Good	**City Code:**	SILVER BAY	**Ext. Gross Area:**	0
Building Code:	R2900210850	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$260,481
Building Name:	Tettegouche SP Picnic Shelter	**Address:**	5702 HWY 61 E	**Deferred Maintenance:**	$74,151
Facility Condition Index:	0.28 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	0
Building Code:	R2900210860	**Cost Model Name:**	Multi-story Dormitory	**Current Replacement Value:**	$1,833,364
Building Name:	Tettegouche SP ByrnesPalisade Inn	**Address:**		**Deferred Maintenance:**	$273,289
Facility Condition Index:	0.15 - Good	**City Code:**		**Ext. Gross Area:**	7,590
Building Code:	R2900210870	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,725
Building Name:	Tettegouche SP BP Wood Shed	**Address:**		**Deferred Maintenance:**	$2,879
Facility Condition Index:	0.33 - Poor	**City Code:**		**Ext. Gross Area:**	80

Site: R290064 - Upper Sioux Agency State Park

Building Code:	R2900401130	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$87,852
Building Name:	Upper Sioux Agency SP Garage	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$31,798
Facility Condition Index:	0.36 - Poor	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	576
Building Code:	R2900401150	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$762,721
Building Name:	Upper Sioux Agency SP Interp Ctr	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$331,528
Facility Condition Index:	0.43 - Poor	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	2,996
Building Code:	R2900401160	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$58,309
Building Name:	Upper Sioux Agency SP Contact Sta	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$12,723
Facility Condition Index:	0.22 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	184
Building Code:	R2900403510	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$127,714
Building Name:	Upper Sioux Agency SP Picnic Shel 1	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$12,771
Facility Condition Index:	0.10 - Good	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	1,250
Building Code:	R2900403520	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,844
Building Name:	Upper Sioux Agency SP Picnic Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$4,992
Facility Condition Index:	0.56 - Crisis	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	24
Building Code:	R2900403530	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,844
Building Name:	Upper Sioux Agency SP Picnic Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$4,274
Facility Condition Index:	0.48 - Poor	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	24
Building Code:	R2900403890	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,178
Building Name:	Upper Sioux Agency SP Shed	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$1,709
Facility Condition Index:	0.33 - Poor	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	36
Building Code:	R2900404040	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$338,957
Building Name:	Upper Sioux Agency SP Shop	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$100,387
Facility Condition Index:	0.30 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	2,008
Building Code:	R2900404160	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$382,102
Building Name:	Upper Sioux Agency SP Yellw Med San	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$81,172
Facility Condition Index:	0.21 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	1,036
Building Code:	R2900404390	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$85,926
Building Name:	Upr Sioux Agency SP Horse PicShel 1	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$8,059
Facility Condition Index:	0.09 - Good	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	841
Building Code:	R2900404570	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,922
Building Name:	Upper Sioux Agency SP Horse W Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$3,375
Facility Condition Index:	0.20 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	47

Building Code:	R2900404580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$44,113
Building Name:	Upper Sioux Agency SP Horse M Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$12,348
Facility Condition Index:	0.28 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	47
Building Code:	R2900404590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,922
Building Name:	Upper Sioux Agency SP Yel Med Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$4,320
Facility Condition Index:	0.26 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	47
Building Code:	R2900404790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,922
Building Name:	Upr Sioux Agency SP Wst Horse Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$4,320
Facility Condition Index:	0.26 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	47
Building Code:	R2900404800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,922
Building Name:	Upr Sioux Agency SP Est Horse Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$3,539
Facility Condition Index:	0.21 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	47
Building Code:	R2900404820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$32,208
Building Name:	Upper Sioux Agency SP Riversd Vault	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$2,431
Facility Condition Index:	0.08 - Good	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	90
Building Code:	R2900404830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,789
Building Name:	Upper Sioux Agency SP Vault Toilet	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$3,762
Facility Condition Index:	0.17 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	55
Building Code:	R2900405250	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$23,769
Building Name:	Upper Sioux Agency SP Wood Shed	**Address:**	5908 HWY 67	**Deferred Maintenance:**	$3,889
Facility Condition Index:	0.16 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	480

Site: R290065 - Whitewater State Park

Building Code:	R2900308760	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$92,404
Building Name:	Whitewater SP Spors Garage	**Address:**	18793 Long Bow LN	**Deferred Maintenance:**	$32,808
Facility Condition Index:	0.36 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	832
Building Code:	R2900308770	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,015,968
Building Name:	Whitewater SP Spors Residence	**Address:**	18793 Long Bow Ln	**Deferred Maintenance:**	$274,391
Facility Condition Index:	0.27 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	5,215
Building Code:	R2900501060	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$358,561
Building Name:	WWSP North Picnic Shelter 2	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$83,265
Facility Condition Index:	0.23 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	1,288
Building Code:	R2900501110	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$615,316
Building Name:	WWSP Group Camp Dining Hall	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$100,554
Facility Condition Index:	0.16 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	3,024

Building Code:	R2900501120	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$119,354
Building Name:	WWSP Group Camp Infirmary	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$9,431
Facility Condition Index:	0.08 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501130	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$111,146
Building Name:	WWSP Group Camp Cabin 7	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$13,254
Facility Condition Index:	0.12 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501140	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$106,334
Building Name:	WWSP Group Camp Cabin 6	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$12,880
Facility Condition Index:	0.12 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501150	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$106,334
Building Name:	WWSP Group Camp Cabin 5	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$11,944
Facility Condition Index:	0.11 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501160	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$101,371
Building Name:	WWSP Group Camp Cabin 1	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$17,955
Facility Condition Index:	0.18 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501170	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$112,963
Building Name:	WWSP Group Camp Cabin 2	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$12,386
Facility Condition Index:	0.11 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501180	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$102,548
Building Name:	WWSP Group Camp Cabin 3	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$17,975
Facility Condition Index:	0.18 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501200	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$255,401
Building Name:	WWSP North Picnic Area Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$32,256
Facility Condition Index:	0.13 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	552
Building Code:	R2900501220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,359
Building Name:	WWSP Shop Area Cold Storage	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$7,003
Facility Condition Index:	0.20 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	462
Building Code:	R2900501240	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$561,419
Building Name:	WWSP Group Camp Cold Storage	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$135,137
Facility Condition Index:	0.24 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	1,008
Building Code:	R2900501250	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$906,265
Building Name:	Whitewater SP Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$128,861
Facility Condition Index:	0.14 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	1,955
Building Code:	R2900501260	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$338,772
Building Name:	WWSP North Picnic Area Interp Unocc	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$77,439
Facility Condition Index:	0.23 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	765

Building Code:	R2900501270	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$77,824
Building Name:	Whitewater SP Pump House	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$17,050
Facility Condition Index:	0.22 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	168
Building Code:	R2900501290	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$235,705
Building Name:	WWSP Cedar Hill CG Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$50,550
Facility Condition Index:	0.21 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	625
Building Code:	R2900501300	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$868,831
Building Name:	WWSP Gooseberry Glen CG Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$173,895
Facility Condition Index:	0.20 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	1,652
Building Code:	R2900501320	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$452,902
Building Name:	Whitewater SP Cold Storage	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$118,225
Facility Condition Index:	0.26 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	1,914
Building Code:	R2900501330	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$235,144
Building Name:	Whitewater SP Nature Store	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$42,466
Facility Condition Index:	0.18 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	1,064
Building Code:	R2900501340	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,559,964
Building Name:	Whitewater SP Office	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$406,783
Facility Condition Index:	0.26 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	2,382
Building Code:	R2900501350	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$41,908
Building Name:	WWSP Cedar Hill CG Pump House	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$8,733
Facility Condition Index:	0.21 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	121
Building Code:	R2900501870	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$106,334
Building Name:	WWSP Group Camp Cabin 4	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$13,772
Facility Condition Index:	0.13 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	720
Building Code:	R2900501910	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$259,466
Building Name:	Whitewater SP Main Shop	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$18,138
Facility Condition Index:	0.07 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	1,800
Building Code:	R2900501920	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,373
Building Name:	WWSP Shop Area Oil House	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,315
Facility Condition Index:	0.08 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	98
Building Code:	R2900501980	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$361,673
Building Name:	WWSP Cedar Hill CG Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$59,152
Facility Condition Index:	0.16 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	961
Building Code:	R2900501990	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$567,084
Building Name:	WWSP Group Camp Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$42,909
Facility Condition Index:	0.08 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	1,560

Building Code:	R2900502850	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,691,085
Building Name:	Whitewater SP Contact Station	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$225,729
Facility Condition Index:	0.08 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	8,623
Building Code:	R2900503580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,368
Building Name:	WWSP North Picnic Area Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,336
Facility Condition Index:	0.12 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	35
Building Code:	R2900503590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,833
Building Name:	WWSP South Picnic Area Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$4,069
Facility Condition Index:	0.34 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	35
Building Code:	R2900503600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,833
Building Name:	WWSP South Picnic Area Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$4,069
Facility Condition Index:	0.34 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	35
Building Code:	R2900503620	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,456
Building Name:	WWSP Cedar Hill CG Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,720
Facility Condition Index:	0.15 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	35
Building Code:	R2900503630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,833
Building Name:	WWSP Cedar Hill CG Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,845
Facility Condition Index:	0.16 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	35
Building Code:	R2900504560	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,557
Building Name:	WWSP Cedar Hill CG Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,763
Facility Condition Index:	0.15 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	35
Building Code:	R2900504570	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$51,656
Building Name:	WWSP Cedar Hill CG Cabin	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$7,210
Facility Condition Index:	0.14 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	240
Building Code:	R2900504700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$23,032
Building Name:	Whitewater SP Cold Storage	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$3,113
Facility Condition Index:	0.14 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	675
Building Code:	R2900504970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,196
Building Name:	WWSP Goosebery Glen CG Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,568
Facility Condition Index:	0.07 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	64
Building Code:	R2900505150	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,187
Building Name:	Whitewater SP Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$2,957
Facility Condition Index:	0.19 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	47
Building Code:	R2900505160	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,013
Building Name:	Whitewater SP Vault Toilet	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,191
Facility Condition Index:	0.07 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	47

Building Code:	R2900505450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$31,995
Building Name:	WWSP Minneiska CG 2 Vault Concrete	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$640
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	62
Building Code:	R2900505460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$31,995
Building Name:	WWSP Minneiska 1&3 Vault Concrete	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$640
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	62
Building Code:	R2900505620	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$58,612
Building Name:	WWSP Minneiska CG Picnic Shelter 1	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,172
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	728
Building Code:	R2900505630	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$61,097
Building Name:	WWSP Minneiska CG Picnic Shelter 2	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,222
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	728
Building Code:	R2900505640	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$61,097
Building Name:	WWSP Minneiska CG Picnic Shelter 3	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,222
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	728
Building Code:	R2900505650	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$92,642
Building Name:	WWSP Minneiska CG Rnbow Trout Cabin	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,853
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	305
Building Code:	R2900505660	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$88,089
Building Name:	WWSP Minneiska CG Cabin	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,762
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	305
Building Code:	R2900505670	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$88,177
Building Name:	WWSP Minneiska CG Tiger Trout Cabin	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,764
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	305
Building Code:	R2900505680	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$83,959
Building Name:	WWSP Minneiska CG Brown Trout Cabin	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$1,679
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	305
Building Code:	R2900505690	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$531,756
Building Name:	WWSP Minneiska CG Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$10,635
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	1,239
Building Code:	R2900505700	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$44,792
Building Name:	WWSP Minneiska Vault Concrete	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$896
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51
Building Code:	R2900505710	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$44,792
Building Name:	WWSP Minneiska Vault Concrete	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$896
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51

Building Code:	R2900505720	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$44,792
Building Name:	WWSP Minneiska Vault Concrete	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$896
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51
Building Code:	R2900505730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$31,995
Building Name:	WWSP Minneiska Vault Concrete	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$640
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51
Building Code:	R2900505740	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$539,835
Building Name:	WWSP Minneiska CG Sanitation	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$10,797
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	1,034

Site: R290066 - Wild River State Park

Building Code:	R2900301400	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$551,438
Building Name:	Wild River SP Office	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$108,060
Facility Condition Index:	0.20 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	1,380
Building Code:	R2900301430	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$66,443
Building Name:	Wild River SP Garage	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$11,999
Facility Condition Index:	0.18 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	576
Building Code:	R2900303090	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,004
Building Name:	Wild River SP Oil House	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$5,237
Facility Condition Index:	0.31 - Poor	**City Code:**	CENTER CITY	**Ext. Gross Area:**	96
Building Code:	R2900303100	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$359,927
Building Name:	Wild River SP Shop	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$86,465
Facility Condition Index:	0.24 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	2,048
Building Code:	R2900303110	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$189,956
Building Name:	Wild River SP Cold Storage	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$27,393
Facility Condition Index:	0.14 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	1,800
Building Code:	R2900303120	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$466,740
Building Name:	Wild River SP Trails Center	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$123,662
Facility Condition Index:	0.26 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	2,000
Building Code:	R2900303130	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$721,458
Building Name:	Wild River SP Interp Center	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$217,200
Facility Condition Index:	0.30 - Poor	**City Code:**	CENTER CITY	**Ext. Gross Area:**	2,880
Building Code:	R2900303140	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$593,429
Building Name:	Wild River SP Picnic Shelter 2	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$157,672
Facility Condition Index:	0.27 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	1,152

Building Code:	R2900303150	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$270,118
Building Name:	Wild River SP CG C & D Loop Sanita	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$52,920
Facility Condition Index:	0.20 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	780
Building Code:	R2900303160	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$274,688
Building Name:	Wild River SP CG A & B Loop Sanita	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$80,636
Facility Condition Index:	0.29 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	780
Building Code:	R2900303170	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$452,293
Building Name:	Wild River SP Residence	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$124,310
Facility Condition Index:	0.27 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	1,680
Building Code:	R2900303700	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$186,713
Building Name:	Wild River SP Cold Storage	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$127,138
Facility Condition Index:	0.68 - Crisis	**City Code:**	CENTER CITY	**Ext. Gross Area:**	3,060
Building Code:	R2900304380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,159
Building Name:	Wild River SP Grp CG Site 3 Vault	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$2,760
Facility Condition Index:	0.18 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	47
Building Code:	R2900304430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,904
Building Name:	Wild River SP CG D-Loop Vault	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$2,532
Facility Condition Index:	0.26 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	31
Building Code:	R2900306110	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$275,031
Building Name:	Wild River SP Guest House	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$68,182
Facility Condition Index:	0.25 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	1,536
Building Code:	R2900306340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,072
Building Name:	Wild River SP Grp CG 6 Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$1,707
Facility Condition Index:	0.10 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	54
Building Code:	R2900306350	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$52,273
Building Name:	Wild River SP Cabin #5	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$9,933
Facility Condition Index:	0.19 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	264
Building Code:	R2900306360	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$52,273
Building Name:	Wild River SP Cabin #6	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$8,974
Facility Condition Index:	0.17 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	264
Building Code:	R2900306590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,726
Building Name:	Wild River SP Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$2,297
Facility Condition Index:	0.18 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	40
Building Code:	R2900306780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,693
Building Name:	Wild River SP Horse CG Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$1,420
Facility Condition Index:	0.11 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	40

Building Code:	R2900307200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,812
Building Name:	Wild River SP Horse CG Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$1,174
Facility Condition Index:	0.07 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	49
Building Code:	R2900307210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,258
Building Name:	Wild River SP CG C Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$1,765
Facility Condition Index:	0.12 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	47
Building Code:	R2900307220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,449
Building Name:	Wild River SP Grp CG 2 Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$1,776
Facility Condition Index:	0.14 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	39
Building Code:	R2900307230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,258
Building Name:	Wild River Cabin Area Vault Toilet	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$3,903
Facility Condition Index:	0.26 - Fair	**City Code:**	CENTER CITY	**Ext. Gross Area:**	47
Building Code:	R2900307390	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,945
Building Name:	Wild River Sunrise Vault Concrete	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$2,794
Facility Condition Index:	0.10 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	55
Building Code:	R2900307600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,841
Building Name:	Wild River Cabin Ar Vault Concrete	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$17,438
Facility Condition Index:	0.33 - Poor	**City Code:**	CENTER CITY	**Ext. Gross Area:**	104
Building Code:	R2900307610	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,926
Building Name:	Wild River SP Cabin #1	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$3,732
Facility Condition Index:	0.05 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	296
Building Code:	R2900307620	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,926
Building Name:	Wild River SP Cabin #2	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$6,529
Facility Condition Index:	0.09 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	296
Building Code:	R2900307630	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,926
Building Name:	Wild River SP Cabin #3	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$9,748
Facility Condition Index:	0.14 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	296
Building Code:	R2900307640	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$68,926
Building Name:	Wild River SP Cabin #4	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$9,218
Facility Condition Index:	0.13 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	296
Building Code:	R2900307860	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,938
Building Name:	Wild River SP Concession	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$1,285
Facility Condition Index:	0.13 - Good	**City Code:**	CENTER CITY	**Ext. Gross Area:**	80
Building Code:	R2900307870	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,947
Building Name:	Wild River SP Adirondack	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$6,794
Facility Condition Index:	0.68 - Crisis	**City Code:**	CENTER CITY	**Ext. Gross Area:**	84

Building Code:	R2900307880	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,072
Building Name:	Wild River SP Adirondack	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$2,500
Facility Condition Index:	0.35 - Poor	**City Code:**	CENTER CITY	**Ext. Gross Area:**	57
Building Code:	R2900307890	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,817
Building Name:	Wild River SP Adirondack	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$5,443
Facility Condition Index:	0.70 - Crisis	**City Code:**	CENTER CITY	**Ext. Gross Area:**	64
Building Code:	R2900307900	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,202
Building Name:	Wild River SP Adirondack	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$6,811
Facility Condition Index:	0.67 - Crisis	**City Code:**	CENTER CITY	**Ext. Gross Area:**	77
Building Code:	R2900308100	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,913
Building Name:	Wild River SP Vault Concrete	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$518
Facility Condition Index:	0.02 - Excellent	**City Code:**	CENTER CITY	**Ext. Gross Area:**	48
Building Code:	R2900308290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,913
Building Name:	Wild River SP CG A Vault Concrete	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$518
Facility Condition Index:	0.02 - Excellent	**City Code:**	CENTER CITY	**Ext. Gross Area:**	54
Building Code:	R2900308300	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,437
Building Name:	Wild River SP CG B Vault Concrete	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$549
Facility Condition Index:	0.02 - Excellent	**City Code:**	CENTER CITY	**Ext. Gross Area:**	54
Building Code:	R2900308530	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,913
Building Name:	Wild River SP CG E Vault Concrete	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$518
Facility Condition Index:	0.02 - Excellent	**City Code:**	CENTER CITY	**Ext. Gross Area:**	51

Site: R290067 - William O'Brien State Park

Building Code:	R2900600370	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$141,689
Building Name:	WOB SP Beach Area Sanitation	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$41,729
Facility Condition Index:	0.29 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	460
Building Code:	R2900600380	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$162,859
Building Name:	WOB SP Picnic Area Sanitation	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$33,580
Facility Condition Index:	0.21 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	483
Building Code:	R2900600420	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$135,069
Building Name:	WOB SP Picnic Area Picnic Shelter 1	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$34,419
Facility Condition Index:	0.25 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,620
Building Code:	R2900600460	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$368,997
Building Name:	WOB SP Savanna CG Sanitation	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$85,256
Facility Condition Index:	0.23 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,208

Building Code:	R2900601190	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$418,538
Building Name:	William O'Brien SP Residence	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$105,201
Facility Condition Index:	0.25 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	2,434
Building Code:	R2900601200	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,224,312
Building Name:	William O'Brien SP Interp Ctr	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$326,482
Facility Condition Index:	0.27 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	4,819
Building Code:	R2900601220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$66,172
Building Name:	William O'Brien SP Garage	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$10,381
Facility Condition Index:	0.16 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	625
Building Code:	R2900601230	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$162,717
Building Name:	WOB SP Picnic Area Picnic Shelter 2	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$19,356
Facility Condition Index:	0.12 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,440
Building Code:	R2900601240	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$162,717
Building Name:	WOB SP Beach Area Picnic Shelter 3	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$30,726
Facility Condition Index:	0.19 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,440
Building Code:	R2900601590	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,547
Building Name:	WOB Riverside Group CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$2,251
Facility Condition Index:	0.18 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	32
Building Code:	R2900601600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,547
Building Name:	WOB Riverside Group CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$2,251
Facility Condition Index:	0.18 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	40
Building Code:	R2900601610	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,860
Building Name:	WOB SP Riverway CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$2,483
Facility Condition Index:	0.16 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	51
Building Code:	R2900601620	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,860
Building Name:	WOB SP Riverway CG S13 Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$3,152
Facility Condition Index:	0.20 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	51
Building Code:	R2900601640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,547
Building Name:	WOB SP Savanna CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,255
Facility Condition Index:	0.10 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	32
Building Code:	R2900601650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,547
Building Name:	WOB SP Savanna CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,255
Facility Condition Index:	0.10 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	40
Building Code:	R2900601660	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,351
Building Name:	WOB SP Savanna CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$3,151
Facility Condition Index:	0.30 - Poor	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	32

Building Code:	R2900601670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,547
Building Name:	WOB SP Savanna CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,983
Facility Condition Index:	0.16 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	40
Building Code:	R2900601790	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$314,100
Building Name:	WOB SP Riverway CG Sanitation	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$79,456
Facility Condition Index:	0.25 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,170
Building Code:	R2900601860	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,351
Building Name:	WOB SP Picnic Area Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,801
Facility Condition Index:	0.17 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	32
Building Code:	R2900601870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,351
Building Name:	WOB SP Picnic Area Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,801
Facility Condition Index:	0.17 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	32
Building Code:	R2900601940	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,017,849
Building Name:	William O'Brien SP Shop	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$208,782
Facility Condition Index:	0.21 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	5,108
Building Code:	R2900602020	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$51,808
Building Name:	WOB SP Savanna CG Copas Cabin	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$12,341
Facility Condition Index:	0.24 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	264
Building Code:	R2900602080	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,848
Building Name:	WOB SP Savanna CG Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,438
Facility Condition Index:	0.13 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	35
Building Code:	R2900602090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,998
Building Name:	William O'Brien SP Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$2,840
Facility Condition Index:	0.24 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	38
Building Code:	R2900602100	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,724
Building Name:	William O'Brien SP Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$3,960
Facility Condition Index:	0.34 - Poor	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	37
Building Code:	R2900602110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,848
Building Name:	William O'Brien SP Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$2,443
Facility Condition Index:	0.23 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	35
Building Code:	R2900602140	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,155
Building Name:	William O'Brien SP Adirondack	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$7,039
Facility Condition Index:	0.69 - Crisis	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	89
Building Code:	R2900602150	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$14,377
Building Name:	William O'Brien SP Adirondack	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$10,782
Facility Condition Index:	0.75 - Crisis	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	126

Building Code:	R2900602160	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$9,356
Building Name:	William O'Brien SP Adirondack	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$7,017
Facility Condition Index:	0.75 - Crisis	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	82
Building Code:	R2900602170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$383,713
Building Name:	William O'Brien SP Contact Sta	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$39,294
Facility Condition Index:	0.10 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,551
Building Code:	R2900602190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,371
Building Name:	WOB SP Savanna CG Vault Concrete	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$5,237
Facility Condition Index:	0.10 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	104
Building Code:	R2900602200	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$49,216
Building Name:	WOB SP Savanna CG Otisville Cabin	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$6,707
Facility Condition Index:	0.14 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	296
Building Code:	R2900602210	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$49,216
Building Name:	WOB SP Savanna CG Vasa Cabin	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$7,100
Facility Condition Index:	0.14 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	296
Building Code:	R2900602230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,220
Building Name:	William O'Brien SP Vault Toilet	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$1,704
Facility Condition Index:	0.11 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	51
Building Code:	R2900602240	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$46,057
Building Name:	WOB SP Savanna CG Marine Mills Cab	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$6,022
Facility Condition Index:	0.13 - Good	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	288
Building Code:	R2900602290	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$45,191
Building Name:	William O'Brien SP Cold Storage	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$18,353
Facility Condition Index:	0.41 - Poor	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	203
Building Code:	R2900602390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$51,772
Building Name:	WOB SP Anson Cold Storage 1	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$15,037
Facility Condition Index:	0.29 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	700
Building Code:	R2900602400	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,666
Building Name:	WOB SP Anson Cold Storage 2	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$30,141
Facility Condition Index:	0.29 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	913
Building Code:	R2900602410	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$317,985
Building Name:	WOB SP Anson Heated Storage	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$55,942
Facility Condition Index:	0.18 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	2,114
Building Code:	R2900602420	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$725,718
Building Name:	WOB SP Anson Heated Storage	**Address:**	16821 O'BRIEN TRAIL N	**Deferred Maintenance:**	$184,339
Facility Condition Index:	0.25 - Fair	**City Code:**	MARINE ON ST CRO	**Ext. Gross Area:**	1,547

Site: R290068 - Zippel Bay State Park

Building Code:	R2900100700	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$130,213
Building Name:	Zippel Bay SP Sanitation	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$22,348
Facility Condition Index:	0.17 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	360
Building Code:	R2900100720	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,082
Building Name:	Zippel Bay SP Shower Bldg Vault 1	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,743
Facility Condition Index:	0.19 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900100780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,660
Building Name:	Zippel Bay SP Shower Bldg Vault 2	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$3,992
Facility Condition Index:	0.25 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900100790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,128
Building Name:	Zippel Bay SP Birch CG Unisex Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,487
Facility Condition Index:	0.19 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	35
Building Code:	R2900100800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,128
Building Name:	Zippel Bay SP Birch CG Mens Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,312
Facility Condition Index:	0.18 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	35
Building Code:	R2900100850	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,987
Building Name:	Zippel Bay SP Anglers CG Mens Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,318
Facility Condition Index:	0.19 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	32
Building Code:	R2900100890	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$2,550
Building Name:	Zippel Bay SP Pic/Beach Bathhouse	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$703
Facility Condition Index:	0.28 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	54
Building Code:	R2900101190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,083
Building Name:	Zippel Bay SP Harbor Vault Toilet	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,603
Facility Condition Index:	0.20 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	35
Building Code:	R2900101360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,050
Building Name:	Zippel Bay SP Anglers CG Uni Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$1,607
Facility Condition Index:	0.12 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	35
Building Code:	R2900102510	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$30,384
Building Name:	Zippel Bay SP Harbor Fish Clean Hse	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$8,109
Facility Condition Index:	0.27 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	180
Building Code:	R2900102520	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$127,141
Building Name:	Zippel Bay SP Office	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$19,518
Facility Condition Index:	0.15 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	720

Building Code:	R2900102530	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$107,081
Building Name:	Zippel Bay SP Contact Station	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$18,442
Facility Condition Index:	0.17 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	383
Building Code:	R2900102540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$268,045
Building Name:	Zippel Bay SP Shop	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$32,286
Facility Condition Index:	0.12 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,500
Building Code:	R2900102550	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$38,508
Building Name:	Zippel Bay SP Beach Picnic Shelter	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$6,935
Facility Condition Index:	0.18 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	308
Building Code:	R2900104720	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$37,239
Building Name:	Zippel Bay SP Open Storage by Shop	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$745
Facility Condition Index:	0.02 - Excellent	**City Code:**	WILLIAMS	**Ext. Gross Area:**	576
Building Code:	R2900105460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,050
Building Name:	Zippel Bay SP Ridge CG Vault 1	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$1,857
Facility Condition Index:	0.14 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	35
Building Code:	R2900105470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,050
Building Name:	Zippel Bay SP Ridge CG Vault 2	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$1,985
Facility Condition Index:	0.15 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	35
Building Code:	R2900106470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,660
Building Name:	ZippelBay SP Swimming Beach Vault 1	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,383
Facility Condition Index:	0.15 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900106480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,660
Building Name:	ZippelBay SP Swimming Beach Vault 2	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,383
Facility Condition Index:	0.15 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900106580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,660
Building Name:	Zippel Bay SP Lady Slipper CG Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$2,383
Facility Condition Index:	0.15 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900106590	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$24,948
Building Name:	Zippel Bay SP Harbor Picnic Shelter	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$3,561
Facility Condition Index:	0.14 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	560
Building Code:	R2900108450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,364
Building Name:	Zippel Bay SP Harbor ADA Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$347
Facility Condition Index:	0.02 - Excellent	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42

Site: R290069 - Birch Lake State Forest

Building Code:	R2900306180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$71,967
Building Name:	Birch Lake CG Cold Storage Shop	**Address:**		**Deferred Maintenance:**	$8,909
Facility Condition Index:	0.12 - Good	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	768
Building Code:	R2900306670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,093
Building Name:	Birch Lake CG Vault Toilet	**Address:**		**Deferred Maintenance:**	$2,481
Facility Condition Index:	0.19 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	40
Building Code:	R2900307670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,515
Building Name:	Birch Lake CG Site 17 Vault Toilet	**Address:**		**Deferred Maintenance:**	$1,699
Facility Condition Index:	0.16 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	32
Building Code:	R2900307680	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,515
Building Name:	Birch Lake CG Site 12 Vault Toilet	**Address:**		**Deferred Maintenance:**	$1,611
Facility Condition Index:	0.15 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	32
Building Code:	R2900307690	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,515
Building Name:	Birch Lake CG Vault Toilet	**Address:**		**Deferred Maintenance:**	$1,699
Facility Condition Index:	0.16 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	32
Building Code:	R2900307700	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,515
Building Name:	Birch Lake CG Vault Toilet	**Address:**		**Deferred Maintenance:**	$2,158
Facility Condition Index:	0.21 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	32
Building Code:	R2900307710	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,549
Building Name:	Birch Lake Grp CG Vault Toilet	**Address:**		**Deferred Maintenance:**	$1,313
Facility Condition Index:	0.14 - Good	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	29
Building Code:	R2900307720	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,837
Building Name:	Birch Lake Grp CG 35 Vault Toilet	**Address:**		**Deferred Maintenance:**	$2,903
Facility Condition Index:	0.30 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	30

Site: R290070 - Carley State Park

Building Code:	R2900503970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,023
Building Name:	Carley SP Picnic Area Vault Toilet	**Address:**	WABASHA CTY RD 4	**Deferred Maintenance:**	$9,315
Facility Condition Index:	0.44 - Poor	**City Code:**	PLAINVIEW	**Ext. Gross Area:**	64
Building Code:	R2900503980	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,023
Building Name:	Carley SP CG Right Vault Toilet	**Address:**	WABASHA CTY RD 4	**Deferred Maintenance:**	$7,149
Facility Condition Index:	0.34 - Poor	**City Code:**	PLAINVIEW	**Ext. Gross Area:**	64
Building Code:	R2900503990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,023
Building Name:	Carley SP CG Left Vault Toilet	**Address:**	WABASHA CTY RD 4	**Deferred Maintenance:**	$7,149
Facility Condition Index:	0.34 - Poor	**City Code:**	PLAINVIEW	**Ext. Gross Area:**	64

Building Code:	R2900504000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,023
Building Name:	Carley SP Grp CG Left Vault Toilet	**Address:**	WABASHA CTY RD 4	**Deferred Maintenance:**	$9,315
Facility Condition Index:	0.44 - Poor	**City Code:**	PLAINVIEW	**Ext. Gross Area:**	64
Building Code:	R2900504010	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,023
Building Name:	Carley SP Grp CG Right Vault Toilet	**Address:**	WABASHA CTY RD 4	**Deferred Maintenance:**	$9,315
Facility Condition Index:	0.44 - Poor	**City Code:**	PLAINVIEW	**Ext. Gross Area:**	64
Building Code:	R2900504730	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$52,320
Building Name:	Carley SP Picnic Area Shelter 1	**Address:**	WABASHA CTY RD 4	**Deferred Maintenance:**	$2,173
Facility Condition Index:	0.04 - Excellent	**City Code:**	PLAINVIEW	**Ext. Gross Area:**	768
Building Code:	R2900505750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,195
Building Name:	Carley SP Vault Concrete	**Address:**	19040 HWY 74	**Deferred Maintenance:**	$544
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51
Building Code:	R2900505760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,195
Building Name:	Carley SP CG Vault Concrete	**Address:**	19040 hwy 74	**Deferred Maintenance:**	$544
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51
Building Code:	R2900505780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,195
Building Name:	Carley SP Grp CG Vault Concrete	**Address:**	19040 HWY 74	**Deferred Maintenance:**	$544
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51
Building Code:	R2900505790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,195
Building Name:	Carley SP Picnic Ar Vault Concrete	**Address:**	19040 HWY 74	**Deferred Maintenance:**	$544
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	51

Site: R290071 - George H Crosby-Manitou State Park

Building Code:	R2900201370	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$66,675
Building Name:	Tettegouche SP Shop	**Address:**	7616 Co Rd 7	**Deferred Maintenance:**	$37,507
Facility Condition Index:	0.56 - Crisis	**City Code:**	FINLAND	**Ext. Gross Area:**	625
Building Code:	R2900205920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,506
Building Name:	GHCrosby-Manitou SP Vault Toilet	**Address:**	7616 Co Rd 7	**Deferred Maintenance:**	$2,584
Facility Condition Index:	0.22 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900208740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,026
Building Name:	GHCrosby-Manitou SP Vault Toilet	**Address:**	7616 Co Rd 7	**Deferred Maintenance:**	$7,013
Facility Condition Index:	0.39 - Poor	**City Code:**	FINLAND	**Ext. Gross Area:**	47

Site: R290072 - John A Latsch State Park

Building Code:	R2900504580	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$21,023
Building Name:	John Latsch SP CG Vault Toilet	**Address:**	43605 KIPP DR	**Deferred Maintenance:**	$5,359
Facility Condition Index:	0.25 - Fair	**City Code:**	WINONA	**Ext. Gross Area:**	64

Site: R290073 - Garden Island SRA

Building Code:	R2900107040	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$17,450
Building Name:	Garden Island SRA Lodging House	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$3,576
Facility Condition Index:	0.20 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	320

Site: R290074 - Cass Lake

Building Code:	R2900103460	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$31,762
Building Name:	Cass Lake Cold Storage	**Address:**	706 ASH AVE	**Deferred Maintenance:**	$7,060
Facility Condition Index:	0.22 - Fair	**City Code:**	CASS LAKE	**Ext. Gross Area:**	240
Building Code:	R2900103470	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$281,164
Building Name:	Cass Lake Office	**Address:**	706 ASH AVE	**Deferred Maintenance:**	$56,077
Facility Condition Index:	0.20 - Fair	**City Code:**	CASS LAKE	**Ext. Gross Area:**	1,534

Site: R290075 - Backus

Building Code:	R2900303740	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,793
Building Name:	Backus Oil House	**Address:**	4391 ST 87 NW	**Deferred Maintenance:**	$2,579
Facility Condition Index:	0.10 - Good	**City Code:**	BACKUS	**Ext. Gross Area:**	96
Building Code:	R2900304460	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$241,076
Building Name:	Backus Shop	**Address:**	4391 ST 87 NW	**Deferred Maintenance:**	$24,808
Facility Condition Index:	0.10 - Good	**City Code:**	BACKUS	**Ext. Gross Area:**	2,710
Building Code:	R2900306170	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$727,332
Building Name:	Backus Office	**Address:**	4391 ST 87 NW	**Deferred Maintenance:**	$77,447
Facility Condition Index:	0.11 - Good	**City Code:**	BACKUS	**Ext. Gross Area:**	4,084

Site: R290076 - Baudette Forestry

Building Code:	R2900103840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,657
Building Name:	Baudette Forestry Oil House	**Address:**	206 MAIN ST E	**Deferred Maintenance:**	$5,627
Facility Condition Index:	0.22 - Fair	**City Code:**	BAUDETTE	**Ext. Gross Area:**	124
Building Code:	R2900103870	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$512,256
Building Name:	Baudette Forestry Shop	**Address:**	206 MAIN ST E	**Deferred Maintenance:**	$72,047
Facility Condition Index:	0.14 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	2,268

Building Code:	R2900103880	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$503,864
Building Name:	Baudette Forestry Office	**Address:**	206 MAIN ST E	**Deferred Maintenance:**	$113,318
Facility Condition Index:	0.22 - Fair	**City Code:**	BAUDETTE	**Ext. Gross Area:**	3,367
Building Code:	R2900109180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$211,357
Building Name:	Baudette Forestry Fire Truck Storag	**Address:**	206 MAIN ST E	**Deferred Maintenance:**	$4,227
Facility Condition Index:	0.02 - Excellent	**City Code:**	BAUDETTE	**Ext. Gross Area:**	2,720

Site: R290077 - Blackduck

Building Code:	R2900106250	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$561,626
Building Name:	Blackduck HeatColdStorage	**Address:**	417B FORESTRY DR	**Deferred Maintenance:**	$93,175
Facility Condition Index:	0.17 - Fair	**City Code:**	BLACKDUCK	**Ext. Gross Area:**	4,896

Site: R290078 - Mississippi Headwaters State Forest

Building Code:	R2900105520	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,228
Building Name:	Mississip HW SF LaSalle Fire Tower	**Address:**	LASALLE	**Deferred Maintenance:**	$2,715
Facility Condition Index:	0.33 - Poor	**City Code:**	BAGLEY	**Ext. Gross Area:**	36

Site: R290079 - Fergus Falls

Building Code:	R2900107290	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$7,112,907
Building Name:	Fergus Falls Office	**Address:**	1509 1ST AVE N	**Deferred Maintenance:**	$997,259
Facility Condition Index:	0.14 - Good	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	29,751
Building Code:	R2900107720	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$311,219
Building Name:	Fergus Falls Anderson East	**Address:**	1509 1ST AVE N	**Deferred Maintenance:**	$50,991
Facility Condition Index:	0.16 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	2,856
Building Code:	R2900107730	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$564,590
Building Name:	Fergus Falls Anderson West	**Address:**	1509 1ST AVE N	**Deferred Maintenance:**	$133,159
Facility Condition Index:	0.24 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	3,724

Site: R290080 - Glenwood

Building Code:	R2900100220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$233,489
Building Name:	Glenwood Wildlife Metal Cold Storag	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$23,349
Facility Condition Index:	0.10 - Good	**City Code:**	GLENWOOD	**Ext. Gross Area:**	3,280
Building Code:	R2900101240	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,558
Building Name:	Glenwood Oil House	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$5,488
Facility Condition Index:	0.24 - Fair	**City Code:**	GLENWOOD	**Ext. Gross Area:**	143

Building Code:	R2900101250	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$751,669
Building Name:	Glenwood 6-Stall Storage Garage	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$68,059
Facility Condition Index:	0.09 - Good	**City Code:**	GLENWOOD	**Ext. Gross Area:**	5,000
Building Code:	R2900101260	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$314,697
Building Name:	Glenwood Fish Hatchery	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$58,176
Facility Condition Index:	0.18 - Fair	**City Code:**	GLENWOOD	**Ext. Gross Area:**	1,600
Building Code:	R2900101270	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$66,202
Building Name:	Glenwood South Garage	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$30,586
Facility Condition Index:	0.46 - Poor	**City Code:**	GLENWOOD	**Ext. Gross Area:**	744
Building Code:	R2900101290	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$37,984
Building Name:	Glenwood North Garage	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$15,224
Facility Condition Index:	0.40 - Poor	**City Code:**	GLENWOOD	**Ext. Gross Area:**	440
Building Code:	R2900101310	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$736,018
Building Name:	Glenwood Shop Office	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$105,828
Facility Condition Index:	0.14 - Good	**City Code:**	GLENWOOD	**Ext. Gross Area:**	3,931
Building Code:	R2900109320	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,498,308
Building Name:	Glenwood Office	**Address:**	23070 LAKE SHORE DR N	**Deferred Maintenance:**	$49,966
Facility Condition Index:	0.02 - Excellent	**City Code:**	GLENWOOD	**Ext. Gross Area:**	10,798

Site: R290081 - Grygla

Building Code:	R2900103970	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,506
Building Name:	Grygla Cold Storage	**Address:**	239 E PARK DR	**Deferred Maintenance:**	$1,970
Facility Condition Index:	0.12 - Good	**City Code:**	GRYGLA	**Ext. Gross Area:**	148
Building Code:	R2900103980	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$272,686
Building Name:	Grygla Residence	**Address:**	239 E PARK DR	**Deferred Maintenance:**	$31,917
Facility Condition Index:	0.12 - Good	**City Code:**	GRYGLA	**Ext. Gross Area:**	1,296
Building Code:	R2900103990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$343,120
Building Name:	Grygla Office	**Address:**	239 E PARK DR	**Deferred Maintenance:**	$49,290
Facility Condition Index:	0.14 - Good	**City Code:**	GRYGLA	**Ext. Gross Area:**	2,316
Building Code:	R2900104000	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$51,687
Building Name:	Grygla Residence Garage	**Address:**	239 E PARK DR	**Deferred Maintenance:**	$8,333
Facility Condition Index:	0.16 - Fair	**City Code:**	GRYGLA	**Ext. Gross Area:**	384

Site: R290082 - Kelliher

Building Code:	R2900103740	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$483,772
Building Name:	Kelliher Office	**Address:**	485 W MAIN ST	**Deferred Maintenance:**	$74,146
Facility Condition Index:	0.15 - Fair	**City Code:**	KELLIHER	**Ext. Gross Area:**	2,685

Site: R290083 - Nimrod

Building Code:	R2900107770	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$235,715
Building Name:	Nimrod Shop	**Address:**	30066 HUNTERSVILLE RD	**Deferred Maintenance:**	$24,552
Facility Condition Index:	0.10 - Good	**City Code:**	SEBEKA	**Ext. Gross Area:**	3,056
Building Code:	R2900109150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$96,635
Building Name:	Nimrod Fire Truck Storage	**Address:**	30066 HUNTERSVILLE RD	**Deferred Maintenance:**	$9,664
Facility Condition Index:	0.10 - Good	**City Code:**	SEBEKA	**Ext. Gross Area:**	1,056
Building Code:	R2900300560	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$306,343
Building Name:	Nimrod Office	**Address:**	30066 HUNTERSVILLE RD	**Deferred Maintenance:**	$64,758
Facility Condition Index:	0.21 - Fair	**City Code:**	SEBEKA	**Ext. Gross Area:**	2,268
Building Code:	R2900303310	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,490
Building Name:	Nimrod Oil House	**Address:**	30066 HUNTERSVILLE RD	**Deferred Maintenance:**	$1,800
Facility Condition Index:	0.14 - Good	**City Code:**	SEBEKA	**Ext. Gross Area:**	96
Building Code:	R2900305580	**Cost Model Name:**	Tower	**Current Replacement Value:**	$14,361
Building Name:	Nimrod Fire Tower	**Address:**	NIMROD	**Deferred Maintenance:**	$4,739
Facility Condition Index:	0.33 - Poor	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	36

Site: R290084 - Northome

Building Code:	R2900206930	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$437,684
Building Name:	Northome Office	**Address:**	12006 HWY 1 E	**Deferred Maintenance:**	$62,958
Facility Condition Index:	0.14 - Good	**City Code:**	NORTHOME	**Ext. Gross Area:**	2,084
Building Code:	R2900206940	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$337,252
Building Name:	Northome Heat/Cold Storage	**Address:**	12006 HWY 1 E	**Deferred Maintenance:**	$94,467
Facility Condition Index:	0.28 - Fair	**City Code:**	NORTHOME	**Ext. Gross Area:**	3,072

Site: R290085 - Spire Valley

Building Code:	R2900107680	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$424,814
Building Name:	Spire Valley Residence	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$68,105
Facility Condition Index:	0.16 - Fair	**City Code:**	REMER	**Ext. Gross Area:**	2,240
Building Code:	R2900108400	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$50,618
Building Name:	Spire Valley North Raceway Shelter	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$12,942
Facility Condition Index:	0.26 - Fair	**City Code:**	REMER	**Ext. Gross Area:**	864

Building Code:	R2900108410	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$91,394
Building Name:	Spire Valley South Raceway Shelter	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$4,191
Facility Condition Index:	0.05 - Excellent	**City Code:**	REMER	**Ext. Gross Area:**	1,560
Building Code:	R2900109940	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$29,222
Building Name:	Spire Valley Fish Tank Cover	**Address:**	1852 St 6 NE	**Deferred Maintenance:**	$584
Facility Condition Index:	0.02 - Excellent	**City Code:**	REMER	**Ext. Gross Area:**	336
Building Code:	R2900303360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$191,989
Building Name:	Spire Valley Fish Hatchery Office	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$41,542
Facility Condition Index:	0.22 - Fair	**City Code:**	REMER	**Ext. Gross Area:**	1,353
Building Code:	R2900303370	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$12,749
Building Name:	Spire Valley Shed	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$2,573
Facility Condition Index:	0.20 - Fair	**City Code:**	REMER	**Ext. Gross Area:**	288
Building Code:	R2900304180	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,524
Building Name:	Spire Valley Oil House	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$2,044
Facility Condition Index:	0.16 - Fair	**City Code:**	REMER	**Ext. Gross Area:**	96
Building Code:	R2900304550	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,285
Building Name:	Spire Valley Shed	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$6,183
Facility Condition Index:	0.55 - Crisis	**City Code:**	REMER	**Ext. Gross Area:**	120
Building Code:	R2900305160	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$25,428
Building Name:	Spire Valley Fish Feed Cold Storage	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$5,333
Facility Condition Index:	0.21 - Fair	**City Code:**	REMER	**Ext. Gross Area:**	320
Building Code:	R2900306560	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$188,360
Building Name:	Spire Valley Cold Storage	**Address:**	1852 ST 6 NE	**Deferred Maintenance:**	$18,836
Facility Condition Index:	0.10 - Good	**City Code:**	REMER	**Ext. Gross Area:**	2,880

Site: R290086 - Thief River Falls

Building Code:	R2900108150	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$672,079
Building Name:	Thief River Falls Office	**Address:**	246 125TH AVE NE	**Deferred Maintenance:**	$16,409
Facility Condition Index:	0.02 - Excellent	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	7,366
Building Code:	R2900108430	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$619,287
Building Name:	Thief River Falls Cold Storage	**Address:**	246 125TH AVE NE	**Deferred Maintenance:**	$61,929
Facility Condition Index:	0.10 - Good	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	5,856

Site: R290087 - Wannaska

Building Code:	R2900104140	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$329,621
Building Name:	Wannaska Main Office	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$49,319
Facility Condition Index:	0.15 - Good	**City Code:**	WANNASKA	**Ext. Gross Area:**	3,852
Building Code:	R2900104150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$412,518
Building Name:	Wannaska Shop Office	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$61,272
Facility Condition Index:	0.15 - Good	**City Code:**	WANNASKA	**Ext. Gross Area:**	2,402
Building Code:	R2900104260	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$36,416
Building Name:	Wannaska Garage	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$16,856
Facility Condition Index:	0.46 - Poor	**City Code:**	WANNASKA	**Ext. Gross Area:**	528
Building Code:	R2900104890	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$24,133
Building Name:	Wannaska Equipment Pole Shelter	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$2,413
Facility Condition Index:	0.10 - Good	**City Code:**	WANNASKA	**Ext. Gross Area:**	308
Building Code:	R2900106360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$57,202
Building Name:	Wannaska Tree Storage	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$11,346
Facility Condition Index:	0.20 - Fair	**City Code:**	WANNASKA	**Ext. Gross Area:**	512
Building Code:	R2900106390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$67,162
Building Name:	Wannaska Metal Garage with Lean-To	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$16,609
Facility Condition Index:	0.25 - Fair	**City Code:**	WANNASKA	**Ext. Gross Area:**	768
Building Code:	R2900106400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,991
Building Name:	Wannaska Oil House	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$3,599
Facility Condition Index:	0.13 - Good	**City Code:**	WANNASKA	**Ext. Gross Area:**	144
Building Code:	R2900108440	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,868
Building Name:	Wannaska Generator Shed	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$1,287
Facility Condition Index:	0.10 - Good	**City Code:**	WANNASKA	**Ext. Gross Area:**	96
Building Code:	R2900109160	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$147,950
Building Name:	Wannaska Fire Truck Storage	**Address:**	16945 STATE HWY 89	**Deferred Maintenance:**	$4,943
Facility Condition Index:	0.03 - Excellent	**City Code:**	WANNASKA	**Ext. Gross Area:**	1,904

Site: R290088 - Warroad

Building Code:	R2900108140	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,533,348
Building Name:	Warroad Office	**Address:**	804 CHERNE DR NW	**Deferred Maintenance:**	$30,667
Facility Condition Index:	0.02 - Excellent	**City Code:**	WARROAD	**Ext. Gross Area:**	7,759
Building Code:	R2900108180	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$451,359
Building Name:	Warroad Cold Storage	**Address:**	804 CHERNE DR NW	**Deferred Maintenance:**	$45,136
Facility Condition Index:	0.10 - Good	**City Code:**	WARROAD	**Ext. Gross Area:**	4,500

Site: R290089 - Williams

Building Code:	R2900103900	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$344,091
Building Name:	Williams Office	**Address:**	115 WILDERNESS AVE NE	**Deferred Maintenance:**	$61,893
Facility Condition Index:	0.18 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,880
Building Code:	R2900103910	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$305,287
Building Name:	Williams Heated Storage	**Address:**	277 WILDERNESS AVE NE	**Deferred Maintenance:**	$66,572
Facility Condition Index:	0.22 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,860
Building Code:	R2900103920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$42,862
Building Name:	Williams Garage	**Address:**	277 Wilderness AVE NE	**Deferred Maintenance:**	$6,898
Facility Condition Index:	0.16 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	384

Site: R290090 - Hinckley

Building Code:	R2900303180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$131,396
Building Name:	Hinckley Garage	**Address:**	306 POWER AVE N	**Deferred Maintenance:**	$43,870
Facility Condition Index:	0.33 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,440
Building Code:	R2900304470	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$637,749
Building Name:	Hinckley Hatchery	**Address:**	306 POWER AVE N	**Deferred Maintenance:**	$179,583
Facility Condition Index:	0.28 - Fair	**City Code:**	HINCKLEY	**Ext. Gross Area:**	1,600
Building Code:	R2900307920	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,650
Building Name:	Hinckley Pump House	**Address:**	306 POWER AVE N	**Deferred Maintenance:**	$6,389
Facility Condition Index:	0.34 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	68

Site: R290091 - Paul Bunyan State Forest

Building Code:	R2900100090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,505
Building Name:	Paul Bunyan SF Gulch Lake CG Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$2,173
Facility Condition Index:	0.26 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	24
Building Code:	R2900105500	**Cost Model Name:**	Tower	**Current Replacement Value:**	$14,361
Building Name:	PBunyan SF Schoolcraft Fire Tower	**Address:**	SCHOOLCRAFT	**Deferred Maintenance:**	$10,771
Facility Condition Index:	0.75 - Crisis	**City Code:**	GUTHRIE	**Ext. Gross Area:**	64
Building Code:	R2900107300	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$3,939
Building Name:	Paul Bunyan SF Mantrap Lk CG Shed	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$562
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	48
Building Code:	R2900107310	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Paul Bunyan SF Mantrap Site15 Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35

Building Code:	R2900107320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Paul Bunyan SF Mantrap Site22 Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35
Building Code:	R2900107330	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Paul Bunyan SF Mantrap Site19 Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35
Building Code:	R2900107340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Paul Bunyan SF Mantrap Site27 Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35
Building Code:	R2900107350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,200
Building Name:	Paul Bunyan SF Mantrap CG WAS Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$2,832
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	42
Building Code:	R2900107360	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$20,923
Building Name:	Paul Bunyan SF Mantrap Pic Shel 1	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$4,773
Facility Condition Index:	0.23 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	624
Building Code:	R2900107370	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$2,660
Building Name:	Paul Bunyan SF Mantrap Lk CG Kiosk	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$511
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	64
Building Code:	R2900107610	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$11,864
Building Name:	Paul Bunyan W Gulch Trl Adirondack	**Address:**	W. Gulch Trail	**Deferred Maintenance:**	$3,011
Facility Condition Index:	0.25 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	100
Building Code:	R2900107620	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,195
Building Name:	Paul Bunyan SF Gulch Lk CG Kiosk	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$999
Facility Condition Index:	0.19 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	120
Building Code:	R2900107630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,939
Building Name:	Paul Bunyan SF Gulch CG Site2 Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$1,494
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	42
Building Code:	R2900107640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,939
Building Name:	Paul Bunyan SF Nelson Access Vault	**Address:**	NELSON ACCESS	**Deferred Maintenance:**	$1,494
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	42
Building Code:	R2900107650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,718
Building Name:	Paul Bunyan SF Gulch Lake CG Vault	**Address:**	3401 STATE PARK RD NE	**Deferred Maintenance:**	$3,755
Facility Condition Index:	0.26 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	42
Building Code:	R2900107660	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$16,811
Building Name:	Paul Bunyan Lake 21 Day-Use Adiron	**Address:**	Lake 21 day use area	**Deferred Maintenance:**	$1,681
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	168

Building Code:	R2900107940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,435
Building Name:	Paul Bunyan SF Mantrap Lk CG Vault	**Address:**	36750 MAIN PARK DR	**Deferred Maintenance:**	$1,644
Facility Condition Index:	0.10 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	48

Site: R290092 - Sand Dunes State Forest

Building Code:	R2900305550	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,318
Building Name:	Sand Dunes SF Fire Tower	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,745
Facility Condition Index:	0.33 - Poor	**City Code:**	MONTICELLO	**Ext. Gross Area:**	60
Building Code:	R2900307400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,945
Building Name:	Sand Dunes SF Horse CG Vault Concr	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,794
Facility Condition Index:	0.10 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	55
Building Code:	R2900307410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,945
Building Name:	Sand Dunes SF Horse CG Vault Concr	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,794
Facility Condition Index:	0.10 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	55
Building Code:	R2900307930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,317
Building Name:	Sand Dunes SF Horse CG Site13 Vault	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,840
Facility Condition Index:	0.23 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	39
Building Code:	R2900307940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,181
Building Name:	Sand Dunes SF Ann Lk Site 8 R Vault	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,036
Facility Condition Index:	0.20 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	32
Building Code:	R2900307950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,181
Building Name:	Sand Dunes SF Ann Lk Site 9 L Vault	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,601
Facility Condition Index:	0.26 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	32
Building Code:	R2900307960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand Dunes SF Ann Lk CG Ste2/3 Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,006
Facility Condition Index:	0.21 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30
Building Code:	R2900307970	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand Dunes SF Ann Lk CG Ste 8 Vault	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,006
Facility Condition Index:	0.21 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30
Building Code:	R2900307980	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand Dunes SF Ann Lk CG Ste21 Vault	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,476
Facility Condition Index:	0.15 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30
Building Code:	R2900307990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand DunesSF AnnLk CG Ste31/33 Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,444
Facility Condition Index:	0.26 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30

Building Code:	R2900308000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand Dunes SF Ann Lk CG Lakevw Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$3,243
Facility Condition Index:	0.34 - Poor	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30
Building Code:	R2900308010	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand DunesSF AnnLk CG Lakevw 6 Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$3,243
Facility Condition Index:	0.34 - Poor	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30
Building Code:	R2900308020	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$9,561
Building Name:	Sand Dunes SF Ann Lk Fish Pier Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$2,444
Facility Condition Index:	0.26 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	30
Building Code:	R2900308030	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,812
Building Name:	Sand DunesSF AnnLk CG Pinevw 1 Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$654
Facility Condition Index:	0.04 - Excellent	**City Code:**	MONTICELLO	**Ext. Gross Area:**	49
Building Code:	R2900308040	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,812
Building Name:	Sand DunesSF AnnLk CG Pinevw 2 Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,086
Facility Condition Index:	0.07 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	49
Building Code:	R2900308050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,812
Building Name:	Sand DunesSF AnnLk CG Pinevw 3 Vaul	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$1,381
Facility Condition Index:	0.09 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	49
Building Code:	R2900308060	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,041
Building Name:	Sand Dunes SF Ann Lk CG Wood Storag	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$3,236
Facility Condition Index:	0.29 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	71
Building Code:	R2900308070	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$24,245
Building Name:	Sand Dunes SF Ann Lk CG Wood Storag	**Address:**	11411 CLEMENTA AVE NW	**Deferred Maintenance:**	$3,940
Facility Condition Index:	0.16 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	311
Building Code:	R2900308080	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,281
Building Name:	Sand Dunes SF Vault Toilet	**Address:**	940 INDUSTRIAL DR S #103	**Deferred Maintenance:**	$1,677
Facility Condition Index:	0.10 - Good	**City Code:**	SAUK RAPIDS	**Ext. Gross Area:**	49
Building Code:	R2900308090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,281
Building Name:	Sand Dunes SF Vault Toilet	**Address:**	940 INDUSTRIAL DR S #103	**Deferred Maintenance:**	$3,255
Facility Condition Index:	0.20 - Fair	**City Code:**	SAUK RAPIDS	**Ext. Gross Area:**	49

Site: R290093 - George Washington State Forest

Building Code:	R2900206000	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,647
Building Name:	GWash SF Bear Lk CG S2 Vault Toilet	**Address:**	55334 W BEAR LAKE FOREST RD	**Deferred Maintenance:**	$4,173
Facility Condition Index:	0.33 - Poor	**City Code:**	NASHWAUK	**Ext. Gross Area:**	35

Building Code:	R2900206020	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,647
Building Name:	GWash SF Bear Lk CG S21 Vault Toil	**Address:**	55334 W BEAR LAKE FOREST RD	**Deferred Maintenance:**	$3,226
Facility Condition Index:	0.26 - Fair	**City Code:**	NASHWAUK	**Ext. Gross Area:**	35
Building Code:	R2900206030	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,647
Building Name:	GWash SF Thistledew CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$4,173
Facility Condition Index:	0.33 - Poor	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900206050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,647
Building Name:	GWash SF Thistledew CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$4,173
Facility Condition Index:	0.33 - Poor	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900206060	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,647
Building Name:	GWash SF Thistledew CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$4,173
Facility Condition Index:	0.33 - Poor	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900206070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,647
Building Name:	GWash SF Thistledew CG Vault Toilet	**Address:**	7622 MCCARTHY BEACH RD	**Deferred Maintenance:**	$4,173
Facility Condition Index:	0.33 - Poor	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	35
Building Code:	R2900206270	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	GWash SF Owen Lake CG Vault Toilet	**Address:**	55379 OWEN LAKE CAMPGROUN	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	30
Building Code:	R2900206280	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	GWash SF Owen Lake CG Vault Toilet	**Address:**	55379 OWEN LAKE CAMPGROUN	**Deferred Maintenance:**	$2,063
Facility Condition Index:	0.20 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	30
Building Code:	R2900206290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	GWash SF Owen Lake CG Vault Toilet	**Address:**	55379 OWEN LAKE CAMPGROUN	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	30
Building Code:	R2900206330	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	GWash SF Larson Lk CG Vault Toilet	**Address:**	61186 LARSON LAKE STATE FOR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	EFFIE	**Ext. Gross Area:**	30
Building Code:	R2900206340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,341
Building Name:	GWash SF Larson Lk CG Vault Toilet	**Address:**	61186 LARSON LAKE STATE FOR	**Deferred Maintenance:**	$2,640
Facility Condition Index:	0.26 - Fair	**City Code:**	EFFIE	**Ext. Gross Area:**	30
Building Code:	R2900206360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,905
Building Name:	GWash SF Bear Lk CG Vault Toilet	**Address:**	54669 E BEAR LAKE FOREST RD	**Deferred Maintenance:**	$2,784
Facility Condition Index:	0.26 - Fair	**City Code:**	NASHWAUK	**Ext. Gross Area:**	30
Building Code:	R2900206380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,905
Building Name:	GWash SF Btn Bx CG S12 Vault Toilet	**Address:**	BUTTON BOX RD	**Deferred Maintenance:**	$2,784
Facility Condition Index:	0.26 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	30

Building Code:	R2900207990	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,409
Building Name:	GWash SF Lost Lake CG Vault Toilet	**Address:**	55659 LOST LAKE CAMPGROUNI	**Deferred Maintenance:**	$3,168
Facility Condition Index:	0.26 - Fair	**City Code:**	BIGFORK	**Ext. Gross Area:**	30
Building Code:	R2900208260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	GWash SF Thistledew CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$2,316
Facility Condition Index:	0.15 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900208270	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	GWash SF Togo Horse CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$2,316
Facility Condition Index:	0.15 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900208280	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,176
Building Name:	GWash SF Togo Horse CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$2,316
Facility Condition Index:	0.15 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	42
Building Code:	R2900208350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,440
Building Name:	GWash SF Larson Lk CG Vault Toilet	**Address:**	61186 LARSON LAKE STATE FOR	**Deferred Maintenance:**	$2,359
Facility Condition Index:	0.15 - Fair	**City Code:**	EFFIE	**Ext. Gross Area:**	45
Building Code:	R2900208360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,282
Building Name:	GWash SF Larson Lk CG Vault Toilet	**Address:**	CO RD 551	**Deferred Maintenance:**	$2,488
Facility Condition Index:	0.15 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	45
Building Code:	R2900208370	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,327
Building Name:	GWash SF Button Box CG S8 Vault	**Address:**	BUTTON BOX RD	**Deferred Maintenance:**	$1,826
Facility Condition Index:	0.10 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	50
Building Code:	R2900208380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,905
Building Name:	GWash SF Button Box CG Vault	**Address:**	BUTTON BOX RD	**Deferred Maintenance:**	$2,501
Facility Condition Index:	0.23 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	30
Building Code:	R2900208480	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$50,552
Building Name:	GWash SF Bear Lk CG Picnic Shelt 1	**Address:**	55334 W BEAR LAKE FOREST RD	**Deferred Maintenance:**	$3,322
Facility Condition Index:	0.07 - Good	**City Code:**	NASHWAUK	**Ext. Gross Area:**	1,080
Building Code:	R2900208700	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,728
Building Name:	GWash SF Stony Brk CG Vault Toilet	**Address:**	SNAKE TRAIL FOREST RD	**Deferred Maintenance:**	$1,234
Facility Condition Index:	0.07 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	47
Building Code:	R2900208710	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,728
Building Name:	GWash SF Stony Brk CG Vault Toilet	**Address:**	SNAKE TRAIL FOREST RD	**Deferred Maintenance:**	$1,234
Facility Condition Index:	0.07 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	47
Building Code:	R2900208720	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,728
Building Name:	GWash SF Stony Brk CG Vault Toilet	**Address:**	SNAKE TRAIL FOREST RD	**Deferred Maintenance:**	$1,234
Facility Condition Index:	0.07 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	47

Site: R290094 - Kabetogama State Forest

Building Code:	R2900203060	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$244,453
Building Name:	Kabetogama Woodenfrog CG Refectory	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$58,376
Facility Condition Index:	0.24 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	1,447
Building Code:	R2900203070	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$88,039
Building Name:	Kabetogama Woodenfrog Cold Storage	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$23,987
Facility Condition Index:	0.27 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	252
Building Code:	R2900203200	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$462,690
Building Name:	Kabetogama SF Office	**Address:**	8730 HWY 53	**Deferred Maintenance:**	$61,412
Facility Condition Index:	0.13 - Good	**City Code:**	ORR	**Ext. Gross Area:**	2,464
Building Code:	R2900203210	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$43,450
Building Name:	Kabetogama Woodenfrog Guard Shack	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$12,485
Facility Condition Index:	0.29 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	252
Building Code:	R2900203220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,419
Building Name:	Kabetogama SF Garage	**Address:**	8730 HWY 53	**Deferred Maintenance:**	$13,253
Facility Condition Index:	0.41 - Poor	**City Code:**	ORR	**Ext. Gross Area:**	384
Building Code:	R2900203610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,508
Building Name:	Kabetogama Woodenfrog Spring House	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$5,664
Facility Condition Index:	0.42 - Poor	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	144
Building Code:	R2900204400	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$73,753
Building Name:	Kabetogama Woodenfrog CG Sanitation	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$8,002
Facility Condition Index:	0.11 - Good	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	288
Building Code:	R2900206080	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,132
Building Name:	Kabetogama Woodenfrog Vault Toilet	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,130
Facility Condition Index:	0.19 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	30
Building Code:	R2900206090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,132
Building Name:	Kabetogama Woodenfrog Vault Toilet	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,242
Facility Condition Index:	0.20 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	30
Building Code:	R2900206100	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,132
Building Name:	Kabetogama Woodenfrog Vault Toilet	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,851
Facility Condition Index:	0.26 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	30
Building Code:	R2900206110	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,132
Building Name:	Kabetogama Woodenfrog Vault Toilet	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,130
Facility Condition Index:	0.19 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	30

Building Code:	R2900206120	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,132
Building Name:	Kabetogama Woodenfrog Vault Toilet	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,851
Facility Condition Index:	0.26 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	30
Building Code:	R2900206130	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,132
Building Name:	Kabetogama Woodenfrog Vault Toilet	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,851
Facility Condition Index:	0.26 - Fair	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	30
Building Code:	R2900206220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,019
Building Name:	Kabetogama Wakemup CG Vault Toilet	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$2,920
Facility Condition Index:	0.27 - Fair	**City Code:**	COOK	**Ext. Gross Area:**	30
Building Code:	R2900206230	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,019
Building Name:	Kabetogama Wakemup CG Vault Toilet	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$2,611
Facility Condition Index:	0.24 - Fair	**City Code:**	COOK	**Ext. Gross Area:**	30
Building Code:	R2900206240	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,019
Building Name:	Kabetogama Wakemup CG Vault Toilet	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$1,717
Facility Condition Index:	0.16 - Fair	**City Code:**	COOK	**Ext. Gross Area:**	30
Building Code:	R2900206250	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,019
Building Name:	Kabetogama Wakemup CG Vault Toilet	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$2,002
Facility Condition Index:	0.18 - Fair	**City Code:**	COOK	**Ext. Gross Area:**	30
Building Code:	R2900206260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,019
Building Name:	Kabetogama Wakemup CG Vault Toilet	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$2,002
Facility Condition Index:	0.18 - Fair	**City Code:**	COOK	**Ext. Gross Area:**	30
Building Code:	R2900206390	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,208
Building Name:	Kabetogama SF Ash R CG Vault Toilet	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$2,554
Facility Condition Index:	0.23 - Fair	**City Code:**	SOUDAN	**Ext. Gross Area:**	30
Building Code:	R2900206400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,208
Building Name:	Kabetogama SF Ash R CG Vault Toilet	**Address:**	1379 STUNTZ BAY RD	**Deferred Maintenance:**	$2,699
Facility Condition Index:	0.24 - Fair	**City Code:**	SOUDAN	**Ext. Gross Area:**	30
Building Code:	R2900207140	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,425
Building Name:	Kabetogama SF Fire Tower	**Address:**	CO RD 422	**Deferred Maintenance:**	$5,090
Facility Condition Index:	0.33 - Poor	**City Code:**	COOK	**Ext. Gross Area:**	64
Building Code:	R2900207160	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,425
Building Name:	Kabetogama Subsite Fire Tower	**Address:**	8730 HWY 53	**Deferred Maintenance:**	$5,090
Facility Condition Index:	0.33 - Poor	**City Code:**	ORR	**Ext. Gross Area:**	64
Building Code:	R2900207170	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,425
Building Name:	Kabetogama Gheen Hill Fire Tower	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$11,569
Facility Condition Index:	0.75 - Crisis	**City Code:**	ORR	**Ext. Gross Area:**	64

Building Code:	R2900207260	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,425
Building Name:	Kabetogama Elephant Lake Fire Tower	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$11,569
Facility Condition Index:	0.75 - Crisis	**City Code:**	ORR	**Ext. Gross Area:**	64
Building Code:	R2900207440	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$38,013
Building Name:	Kabetogama Wakemup CG Picnic Shel 1	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$13,816
Facility Condition Index:	0.36 - Poor	**City Code:**	COOK	**Ext. Gross Area:**	486
Building Code:	R2900208390	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,270
Building Name:	Kabetogama Wakemup CG Spring House	**Address:**	8501 PETERSON RD	**Deferred Maintenance:**	$1,276
Facility Condition Index:	0.10 - Good	**City Code:**	COOK	**Ext. Gross Area:**	64
Building Code:	R2900208610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,407
Building Name:	Kabetogama Woodenfrog CG Shed	**Address:**	10449 WALTZ RD	**Deferred Maintenance:**	$2,506
Facility Condition Index:	0.11 - Good	**City Code:**	KABETOGAMA	**Ext. Gross Area:**	120

Site: R290095 - Finland State Forest

Building Code:	R2900206160	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Eckbeck CG Men's Vault	**Address:**	6120 STATE HWY 1	**Deferred Maintenance:**	$2,271
Facility Condition Index:	0.19 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900206170	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Eckbeck CG Women's Vault	**Address:**	6120 STATE HWY 1	**Deferred Maintenance:**	$2,927
Facility Condition Index:	0.25 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900206180	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Eckbeck CG Men's Vault	**Address:**	6120 STATE HWY 1	**Deferred Maintenance:**	$2,271
Facility Condition Index:	0.19 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900206190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Eckbeck CG Women's Vault	**Address:**	6120 STATE HWY 1	**Deferred Maintenance:**	$2,927
Facility Condition Index:	0.25 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900206200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Finland CG Women's Vault	**Address:**	5244 COUNTY RD 6	**Deferred Maintenance:**	$2,271
Facility Condition Index:	0.19 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900206210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Finland CG Men's Vault	**Address:**	5244 COUNTY RD 6	**Deferred Maintenance:**	$2,927
Facility Condition Index:	0.25 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30
Building Code:	R2900206410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Finland CG Vault Toilet	**Address:**	5244 COUNTY RD 6	**Deferred Maintenance:**	$2,860
Facility Condition Index:	0.24 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	30

Building Code:	R2900206420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,914
Building Name:	Finland SF Sullivan Lk Vault Toilet	**Address:**	6253 SULLIVAN LAKE RD	**Deferred Maintenance:**	$1,663
Facility Condition Index:	0.14 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	30
Building Code:	R2900207230	**Cost Model Name:**	Tower	**Current Replacement Value:**	$20,777
Building Name:	Finland SF Fire Tower	**Address:**	6686 HWY 1	**Deferred Maintenance:**	$6,856
Facility Condition Index:	0.33 - Poor	**City Code:**	FINLAND	**Ext. Gross Area:**	64
Building Code:	R2900208040	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,832
Building Name:	Finland SF Finland CG Vault Toilet	**Address:**	5244 COUNTY RD 6	**Deferred Maintenance:**	$2,960
Facility Condition Index:	0.21 - Fair	**City Code:**	FINLAND	**Ext. Gross Area:**	35
Building Code:	R2900208290	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,832
Building Name:	Finland SF Finland CG Vault Toilet	**Address:**	5244 COUNTY RD 6	**Deferred Maintenance:**	$1,026
Facility Condition Index:	0.07 - Good	**City Code:**	FINLAND	**Ext. Gross Area:**	35
Building Code:	R2900210670	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$32,070
Building Name:	Finland SF Sullivan Vault Concrete	**Address:**	6253 Sullivan Lake Rd	**Deferred Maintenance:**	$641
Facility Condition Index:	0.02 - Excellent	**City Code:**	Two Harbors	**Ext. Gross Area:**	51

Site: R290096 - Cloquet Valley State Forest

Building Code:	R2900206430	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,078
Building Name:	Cloquet SF Indian Lk CG Vault Toil	**Address:**	2147 INDIAN LAKE RD, BRIMSON	**Deferred Maintenance:**	$1,711
Facility Condition Index:	0.14 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	30
Building Code:	R2900206440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,078
Building Name:	Cloquet SF Indian Lk CG Vault Toil	**Address:**	2147 INDIAN LAKE RD, BRIMSON	**Deferred Maintenance:**	$1,711
Facility Condition Index:	0.14 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	30
Building Code:	R2900207770	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,598
Building Name:	Cloquet SF Indian Lk CG Vault Toil	**Address:**	2147 INDIAN LAKE RD, BRIMSON	**Deferred Maintenance:**	$1,231
Facility Condition Index:	0.07 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	42

Site: R290097 - St Croix Valley State Forest

Building Code:	R2900306630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,887
Building Name:	St Croix Valley SF Boulder CG Vault	**Address:**	TAMARACK FOREST RD	**Deferred Maintenance:**	$1,895
Facility Condition Index:	0.15 - Good	**City Code:**	HINCKLEY	**Ext. Gross Area:**	40
Building Code:	R2900306640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$12,887
Building Name:	St Croix Val SF Graces Lake Vault	**Address:**	TAMARACK FOREST RD	**Deferred Maintenance:**	$4,002
Facility Condition Index:	0.31 - Poor	**City Code:**	HINCKLEY	**Ext. Gross Area:**	40

Building Code: R2900306650
Building Name: St Croix Val SF Tamarack Upr Vault
Facility Condition Index: 0.22 - Fair

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $12,887
Deferred Maintenance: $2,894
Ext. Gross Area: 40

Building Code: R2900306660
Building Name: St Croix Val SF Tamarack Upr Vault
Facility Condition Index: 0.22 - Fair

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $12,887
Deferred Maintenance: $2,894
Ext. Gross Area: 40

Building Code: R2900307520
Building Name: St Croix Val SF Tamarack Low Vault
Facility Condition Index: 0.47 - Poor

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $8,802
Deferred Maintenance: $4,152
Ext. Gross Area: 27

Building Code: R2900307530
Building Name: St Croix Val SF Tamarack Low Vault
Facility Condition Index: 0.10 - Good

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $13,943
Deferred Maintenance: $1,394
Ext. Gross Area: 42

Building Code: R2900307540
Building Name: St Croix Val SF Tamarack Pic Shel 1
Facility Condition Index: 0.17 - Fair

Cost Model Name: Open Air Shelter
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $32,359
Deferred Maintenance: $5,487
Ext. Gross Area: 720

Building Code: R2900307790
Building Name: St Croix Valley SF Boulder CG Vault
Facility Condition Index: 0.20 - Fair

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $13,943
Deferred Maintenance: $2,803
Ext. Gross Area: 42

Building Code: R2900307800
Building Name: St Croix Valley SF Boulder CG Vault
Facility Condition Index: 0.15 - Good

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $13,943
Deferred Maintenance: $2,031
Ext. Gross Area: 42

Building Code: R2900307810
Building Name: St Croix Val SF Tamarack S34 Vault
Facility Condition Index: 0.20 - Fair

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $13,943
Deferred Maintenance: $2,803
Ext. Gross Area: 42

Building Code: R2900307820
Building Name: St Croix Val SF Tamarack S27 Vault
Facility Condition Index: 0.20 - Fair

Cost Model Name: Vault Toilet
Address: TAMARACK FOREST RD
City Code: HINCKLEY

Current Replacement Value: $13,943
Deferred Maintenance: $2,803
Ext. Gross Area: 42

Site: R290098 - Chengwatana State Forest

Building Code: R2900307550
Building Name: Chengwatana Snake R CG Vault Toilet
Facility Condition Index: 0.20 - Fair

Cost Model Name: Vault Toilet
Address: 39797 PARK TRAIL
City Code: CENTER CITY

Current Replacement Value: $9,640
Deferred Maintenance: $1,915
Ext. Gross Area: 27

Building Code: R2900307560
Building Name: Chengwatana Snake R CG Vault Toilet
Facility Condition Index: 0.07 - Good

Cost Model Name: Vault Toilet
Address: 39797 PARK TRAIL
City Code: CENTER CITY

Current Replacement Value: $15,308
Deferred Maintenance: $1,135
Ext. Gross Area: 42

Building Code:	R2900308520	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,913
Building Name:	Chengwatana Snake R CG Vault Concrt	**Address:**	39797 PARK TRAIL	**Deferred Maintenance:**	$518
Facility Condition Index:	0.02 - Excellent	**City Code:**	CENTER CITY	**Ext. Gross Area:**	51

Site: R290099 - Beltrami Island State Forest

Building Code:	R2900104010	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,469
Building Name:	Beltrami Is Bemis Hill CG Wellhouse	**Address:**	48990 CO RD 4	**Deferred Maintenance:**	$1,847
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	64
Building Code:	R2900104020	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,348,537
Building Name:	Beltrami Is Bemis Hill CG Trls Ctr	**Address:**	48990 CO RD 4	**Deferred Maintenance:**	$448,201
Facility Condition Index:	0.33 - Poor	**City Code:**	ROSEAU	**Ext. Gross Area:**	960
Building Code:	R2900105550	**Cost Model Name:**	Tower	**Current Replacement Value:**	$19,946
Building Name:	Beltrami Is SF Faunce Fire Tower	**Address:**	FAUNCE	**Deferred Maintenance:**	$14,960
Facility Condition Index:	0.75 - Crisis	**City Code:**	WILLIAMS	**Ext. Gross Area:**	49
Building Code:	R2900105640	**Cost Model Name:**	Tower	**Current Replacement Value:**	$19,115
Building Name:	Beltrami Is SF Norris Fire Tower	**Address:**	NORRIS	**Deferred Maintenance:**	$6,308
Facility Condition Index:	0.33 - Poor	**City Code:**	WARROAD	**Ext. Gross Area:**	64
Building Code:	R2900106500	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,541
Building Name:	Beltrami Is Bemis Hill CG Vault 1	**Address:**	48990 CO RD 4	**Deferred Maintenance:**	$2,509
Facility Condition Index:	0.17 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	42
Building Code:	R2900106510	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,045
Building Name:	Beltrami Is Bemis Hill CG Vault 2	**Address:**	48990 CO RD 4	**Deferred Maintenance:**	$3,838
Facility Condition Index:	0.26 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	42
Building Code:	R2900107440	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,699
Building Name:	Beltrami Is Blueberry Hill CG Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$3,940
Facility Condition Index:	0.25 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900107450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,745
Building Name:	Beltrami Is Faunce CG Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$3,760
Facility Condition Index:	0.25 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42

Site: R290100 - General Andrews State Forest

Building Code:	R2900300160	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$185,659
Building Name:	GenAndr SF Nursery Tin Pole	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$110,297
Facility Condition Index:	0.59 - Crisis	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	3,258

Building Code:	R2900300170	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$186,082
Building Name:	GenAndr SF Nursery Fertilizer Bldg	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$126,796
Facility Condition Index:	0.68 - Crisis	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	2,040
Building Code:	R2900300180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$296,457
Building Name:	GenAndr SF Nursery Greenhouse	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$69,750
Facility Condition Index:	0.24 - Fair	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	1,844
Building Code:	R2900300190	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,014,384
Building Name:	General Andrews SF Shop	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$1,934,157
Facility Condition Index:	0.39 - Poor	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	29,331
Building Code:	R2900300200	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,120,923
Building Name:	GenAndr SF Cement Seedling Pack Hse	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$772,596
Facility Condition Index:	0.36 - Poor	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	12,927
Building Code:	R2900300220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$33,219
Building Name:	GenAndr SF Nursry F Block Pumphouse	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$6,898
Facility Condition Index:	0.21 - Fair	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	332
Building Code:	R2900300230	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,855
Building Name:	GenAndr SF Nursery 2 Stall Garage	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$17,354
Facility Condition Index:	0.32 - Poor	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	480
Building Code:	R2900300240	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$640,142
Building Name:	GenAndr SF Metal Seedling Pack Hse	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$98,730
Facility Condition Index:	0.15 - Fair	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	4,466
Building Code:	R2900300250	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$490,440
Building Name:	General Andrews SF Nursery Office	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$139,684
Facility Condition Index:	0.28 - Fair	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	4,417
Building Code:	R2900303190	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$664,169
Building Name:	GenAndr SF Nursery South Garage	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$252,093
Facility Condition Index:	0.38 - Poor	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	4,228
Building Code:	R2900303730	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$87,162
Building Name:	GenAndr SF Nursery Shop Pumphouse	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$22,926
Facility Condition Index:	0.26 - Fair	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	224
Building Code:	R2900303810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,801
Building Name:	GenAndr SF Nursery Oil House	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$2,075
Facility Condition Index:	0.12 - Good	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	96
Building Code:	R2900303980	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$212,129
Building Name:	GenAndr SF Nursery Machine Shed	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$66,797
Facility Condition Index:	0.31 - Poor	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	3,303

Building Code:	R2900304210	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$37,590
Building Name:	GenAndr SF Nursery Lumber Shed	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$9,980
Facility Condition Index:	0.27 - Fair	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	650
Building Code:	R2900307030	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,632
Building Name:	GenAndr Willow CG St 5 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$1,002
Facility Condition Index:	0.09 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307040	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,632
Building Name:	GenAndr Willow CG St 5 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$784
Facility Condition Index:	0.07 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,954
Building Name:	GenAndr Willow CG St20 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$808
Facility Condition Index:	0.07 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307060	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,954
Building Name:	GenAndr Willow CG St20 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$2,501
Facility Condition Index:	0.23 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,954
Building Name:	GenAndr Willow CG St37 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$2,776
Facility Condition Index:	0.25 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307080	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,954
Building Name:	GenAndr Willow CG St37 Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$1,245
Facility Condition Index:	0.11 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307090	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,954
Building Name:	GenAndr Willow Grp CG Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$808
Facility Condition Index:	0.07 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307100	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,954
Building Name:	GenAndr Willow Grp CG Vault Toilet	**Address:**	61101 BANNING PARK RD	**Deferred Maintenance:**	$808
Facility Condition Index:	0.07 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	30
Building Code:	R2900307660	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$476,313
Building Name:	GenAndr SF Nursery Walk-in-Freezer	**Address:**	85894 CO HWY 61	**Deferred Maintenance:**	$10,084
Facility Condition Index:	0.02 - Excellent	**City Code:**	WILLOW RIVER	**Ext. Gross Area:**	3,062

Site: R290101 - Bemidji Glidden

Building Code:	R2900100950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$219,285
Building Name:	Bemidji Glidden Shop	**Address:**	7902 GLIDDEN RD NE	**Deferred Maintenance:**	$45,983
Facility Condition Index:	0.21 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	1,171

Building Code:	R2900100960	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$351,017
Building Name:	Bemidji Glidden Cold Storage	**Address:**	7902 GLIDDEN RD NE	**Deferred Maintenance:**	$57,089
Facility Condition Index:	0.16 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	3,608
Building Code:	R2900104670	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,471
Building Name:	Bemidji Glidden Oil House	**Address:**	7902 GLIDDEN RD NE	**Deferred Maintenance:**	$908
Facility Condition Index:	0.17 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	57

Site: R290102 - Bagley

Building Code:	R2900103340	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$109,867
Building Name:	Bagley 4-Stall Storage	**Address:**	36452 STATE 92	**Deferred Maintenance:**	$21,417
Facility Condition Index:	0.19 - Fair	**City Code:**	BAGLEY	**Ext. Gross Area:**	1,300
Building Code:	R2900103360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$369,744
Building Name:	Bagley Shop Office	**Address:**	36452 STATE 92	**Deferred Maintenance:**	$52,823
Facility Condition Index:	0.14 - Good	**City Code:**	BAGLEY	**Ext. Gross Area:**	2,432
Building Code:	R2900103480	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$307,081
Building Name:	Bagley Office	**Address:**	36452 STATE 92	**Deferred Maintenance:**	$36,095
Facility Condition Index:	0.12 - Good	**City Code:**	BAGLEY	**Ext. Gross Area:**	3,072
Building Code:	R2900106720	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,646
Building Name:	Bagley Pump House	**Address:**	36452 STATE 92	**Deferred Maintenance:**	$1,709
Facility Condition Index:	0.22 - Fair	**City Code:**	BAGLEY	**Ext. Gross Area:**	80
Building Code:	R2900107780	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$67,016
Building Name:	Bagley Cold Storage	**Address:**	36452 STATE 92	**Deferred Maintenance:**	$6,702
Facility Condition Index:	0.10 - Good	**City Code:**	BAGLEY	**Ext. Gross Area:**	640

Site: R290103 - Pine Island State Forest

Building Code:	R2900103700	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$53,348
Building Name:	Pine Island SF Lost River Cabin	**Address:**	10.5 mi. E. of State 72 Lost River R	**Deferred Maintenance:**	$8,720
Facility Condition Index:	0.16 - Fair	**City Code:**	KELLIHER	**Ext. Gross Area:**	374

Site: R290104 - Land O'Lakes State Forest

Building Code:	R2900108190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,310
Building Name:	LO'Lakes SF Converse CG Ste 1 Vault	**Address:**	Washburn Lake solitude area	**Deferred Maintenance:**	$3,656
Facility Condition Index:	0.26 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	39
Building Code:	R2900108200	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,271
Building Name:	LO'Lakes SF Converse CG Ste 8 Vault	**Address:**	C/o CUYUNA COUNTRY SRA 307	**Deferred Maintenance:**	$3,646
Facility Condition Index:	0.26 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	42

Building Code:	R2900108210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,916
Building Name:	LO'Lakes SF Converse CG Ste18 Vault	**Address:**	C/o CUYUNA COUNTRY SRA 307	**Deferred Maintenance:**	$3,045
Facility Condition Index:	0.26 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	35
Building Code:	R2900108220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,271
Building Name:	LO'Lakes SF Converse CG Ste30 Vault	**Address:**	C/o CUYUNA COUNTRY SRA 307	**Deferred Maintenance:**	$2,556
Facility Condition Index:	0.18 - Fair	**City Code:**	IRONTON	**Ext. Gross Area:**	42
Building Code:	R2900108230	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,599
Building Name:	LO'Lakes SF Converse CG Adirondack	**Address:**	C/o CUYUNA COUNTRY SRA 307	**Deferred Maintenance:**	$3,498
Facility Condition Index:	0.33 - Poor	**City Code:**	IRONTON	**Ext. Gross Area:**	96
Building Code:	R2900300610	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$423,663
Building Name:	Land O'Lakes SF Washburn Lk Office	**Address:**	1145 MN HWY 6 NE	**Deferred Maintenance:**	$59,719
Facility Condition Index:	0.14 - Good	**City Code:**	OUTING	**Ext. Gross Area:**	2,978
Building Code:	R2900303270	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,524
Building Name:	Land O'Lakes SF Washburn Lk Oil Hse	**Address:**	1145 STATE 6 NE	**Deferred Maintenance:**	$1,747
Facility Condition Index:	0.14 - Good	**City Code:**	OUTING	**Ext. Gross Area:**	96
Building Code:	R2900305500	**Cost Model Name:**	Tower	**Current Replacement Value:**	$11,489
Building Name:	LO'Lakes SF Ben Draper Fire Tower	**Address:**	BEN DRAPER	**Deferred Maintenance:**	$8,617
Facility Condition Index:	0.75 - Crisis	**City Code:**	BRAINERD	**Ext. Gross Area:**	2,750
Building Code:	R2900306600	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$14,271
Building Name:	LO'Lakes SF Baker Lake CG Vault	**Address:**	Draper Rd ATV Trail	**Deferred Maintenance:**	$3,714
Facility Condition Index:	0.26 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	39

Site: R290105 - Lac Qui Parle WMA

Building Code:	R2900402010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$722,974
Building Name:	Lac Qui Parle WMA Shop	**Address:**	14040 20TH ST NW	**Deferred Maintenance:**	$329,979
Facility Condition Index:	0.46 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	2,424
Building Code:	R2900402080	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$147,603
Building Name:	Lac Qui Parle WMA Cold Storage	**Address:**	14040 20TH ST NW	**Deferred Maintenance:**	$49,472
Facility Condition Index:	0.34 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	1,536
Building Code:	R2900402090	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,245,777
Building Name:	Lac Qui Parle WMA Residence	**Address:**	14042 20TH ST NW	**Deferred Maintenance:**	$505,826
Facility Condition Index:	0.41 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	3,224
Building Code:	R2900402670	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$385,554
Building Name:	Lac Qui Parle WMA Cold Storage	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$127,233
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	7,040

Building Code:	R2900403790	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$22,480
Building Name:	Lac Qui Parle WMA Cold Storage	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$7,418
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	352
Building Code:	R2900404110	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,274,400
Building Name:	Lac Qui Parle WMA Main Office	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$214,704
Facility Condition Index:	0.17 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	3,670
Building Code:	R2900404120	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$118,832
Building Name:	LQParle WMA Watson Picnic Shelter 2	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$42,014
Facility Condition Index:	0.35 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	612
Building Code:	R2900404130	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$48,495
Building Name:	Lac Qui Parle WMA Watson Sanitation	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$16,003
Facility Condition Index:	0.33 - Poor	**City Code:**	WATSON	**Ext. Gross Area:**	270
Building Code:	R2900404600	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$272,109
Building Name:	Lac Qui Parle WMA Cold Storage	**Address:**	14006 20TH ST NW	**Deferred Maintenance:**	$27,211
Facility Condition Index:	0.10 - Good	**City Code:**	WATSON	**Ext. Gross Area:**	2,880
Building Code:	R2900404620	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$23,894
Building Name:	LQParle WMA Watson Picnic Shelter 1	**Address:**	14047 20TH ST NW	**Deferred Maintenance:**	$16,864
Facility Condition Index:	0.71 - Crisis	**City Code:**	WATSON	**Ext. Gross Area:**	144
Building Code:	R2900405080	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,256
Building Name:	Lac Qui Parle WMA Residence Garage	**Address:**	14042 20TH ST NW	**Deferred Maintenance:**	$6,001
Facility Condition Index:	0.11 - Good	**City Code:**	WATSON	**Ext. Gross Area:**	592
Building Code:	R2900405710	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$354,642
Building Name:	LQParle WMA Larson Cold Storage	**Address:**	14005 20TH ST NW	**Deferred Maintenance:**	$74,527
Facility Condition Index:	0.21 - Fair	**City Code:**	WATSON	**Ext. Gross Area:**	3,283

Site: R290106 - Red Lake WMA

Building Code:	R2900100230	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$342,984
Building Name:	Red Lake WMA Norris Remote Residnce	**Address:**	2879 N ROOSEVELT RD	**Deferred Maintenance:**	$48,591
Facility Condition Index:	0.14 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,928
Building Code:	R2900100240	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$397,426
Building Name:	Red Lake WMA Norris Onsite Residnce	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$61,840
Facility Condition Index:	0.16 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	3,072
Building Code:	R2900100280	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$217,246
Building Name:	Red Lake WMA Norris Shop	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$77,827
Facility Condition Index:	0.36 - Poor	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,048

Building Code:	R2900100320	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$141,089
Building Name:	Red Lake WMA Norris Sanitation	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$59,713
Facility Condition Index:	0.42 - Poor	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,240
Building Code:	R2900100330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,305
Building Name:	Red Lake WMA Norris Garbage Shed	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$3,503
Facility Condition Index:	0.28 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	100
Building Code:	R2900100340	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$544,208
Building Name:	Red Lake WMA Norris Office	**Address:**	11536 FAUNCE BUTTERFIELD FO	**Deferred Maintenance:**	$76,560
Facility Condition Index:	0.14 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	3,091
Building Code:	R2900100350	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$226,282
Building Name:	Red Lake WMA Norris Dining Hall	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$66,320
Facility Condition Index:	0.29 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,248
Building Code:	R2900100360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,653
Building Name:	Red Lake WMA Norris Blacksmith Shop	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$36,282
Facility Condition Index:	0.62 - Crisis	**City Code:**	WILLIAMS	**Ext. Gross Area:**	768
Building Code:	R2900100370	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$71,233
Building Name:	Red Lake WMA Norris Pump House	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$20,646
Facility Condition Index:	0.29 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	400
Building Code:	R2900100380	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$171,120
Building Name:	Red Lake WMA Norris Old CCC shop	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$127,998
Facility Condition Index:	0.75 - Crisis	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,976
Building Code:	R2900100390	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$208,403
Building Name:	Red Lake WMA Norris Wolf Shack	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$46,793
Facility Condition Index:	0.22 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,000
Building Code:	R2900100420	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$84,578
Building Name:	Red Lake WMA Norris Cabin	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$22,656
Facility Condition Index:	0.27 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	480
Building Code:	R2900100430	**Cost Model Name:**	Single-story Hotel/Dorm	**Current Replacement Value:**	$424,870
Building Name:	Red Lake WMA Norris Duplex	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$54,271
Facility Condition Index:	0.13 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,684
Building Code:	R2900100440	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,836
Building Name:	Red Lake WMA Norris Oil House	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$3,394
Facility Condition Index:	0.29 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	84
Building Code:	R2900100450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$77,269
Building Name:	Red Lake WMA Norris NW Garage	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$27,237
Facility Condition Index:	0.35 - Poor	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,000

Building Code:	R2900100460	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$248,935
Building Name:	Red Lake WMA Norris Asst Mgr Garage	**Address:**	2879 N ROOSEVELT RD	**Deferred Maintenance:**	$24,894
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,580
Building Code:	R2900100830	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$395,455
Building Name:	Red Lake WMA Norris CCC Rec Hall	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$92,562
Facility Condition Index:	0.23 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	2,220
Building Code:	R2900100840	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$241,637
Building Name:	Red Lake WMA Norris Tool House	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$58,670
Facility Condition Index:	0.24 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	1,480
Building Code:	R2900100990	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$6,956
Building Name:	Red Lake WMA Oaks Cabin	**Address:**	11536 FAUNCE BUTTERFIELD FO	**Deferred Maintenance:**	$696
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	252
Building Code:	R2900101060	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$16,305
Building Name:	Red Lake WMA Gates Corner Cabin	**Address:**	11536 FAUNCE BUTTERFIELD FO	**Deferred Maintenance:**	$1,631
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	196
Building Code:	R2900101080	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$23,531
Building Name:	Red Lake WMA Blue Kettle Trl Cabin	**Address:**	11536 FAUNCE BUTTERFIELD FO	**Deferred Maintenance:**	$2,353
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	182
Building Code:	R2900104370	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$150,453
Building Name:	Red Lake WMA Norris Metal Building	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$40,777
Facility Condition Index:	0.27 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	2,048
Building Code:	R2900105210	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$38,577
Building Name:	Red Lake WMA Norris Picnic Shel 1	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$3,858
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	800
Building Code:	R2900106570	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$65,876
Building Name:	Red Lake WMA Norris Gas Building	**Address:**	11536 FAUNCE BUTTERFIELD RD	**Deferred Maintenance:**	$8,373
Facility Condition Index:	0.13 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	156

Site: R290107 - Roseau River WMA

Building Code:	R2900100080	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,672
Building Name:	Roseau River WMA Wildlife Shed	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$14,754
Facility Condition Index:	0.75 - Crisis	**City Code:**	ROSEAU	**Ext. Gross Area:**	140
Building Code:	R2900100470	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$45,007
Building Name:	Roseau River WMA HQ Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$900
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROSEAU	**Ext. Gross Area:**	254

Building Code:	R2900100520	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$559,113
Building Name:	Roseau River WMA Double Quonset	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$258,806
Facility Condition Index:	0.46 - Poor	**City Code:**	ROSEAU	**Ext. Gross Area:**	3,296
Building Code:	R2900100530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$653,172
Building Name:	Roseau River WMA Metal Storage Shed	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$72,803
Facility Condition Index:	0.11 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	4,000
Building Code:	R2900100540	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$573,860
Building Name:	Roseau River WMA Office	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$133,019
Facility Condition Index:	0.23 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	2,393
Building Code:	R2900100550	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$732,958
Building Name:	Roseau River WMA Shop	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$135,802
Facility Condition Index:	0.19 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	2,800
Building Code:	R2900100560	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$996,702
Building Name:	Roseau River WMA Residence Near Ofc	**Address:**	39943 280TH AVE	**Deferred Maintenance:**	$124,406
Facility Condition Index:	0.12 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	3,672
Building Code:	R2900100570	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$45,007
Building Name:	Roseau River WMA Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$4,501
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	254
Building Code:	R2900101100	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,534
Building Name:	Roseau River WMA Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$5,698
Facility Condition Index:	0.31 - Poor	**City Code:**	ROSEAU	**Ext. Gross Area:**	152
Building Code:	R2900103800	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$931,653
Building Name:	Roseau River WMA Residence	**Address:**	27909 400TH ST	**Deferred Maintenance:**	$122,956
Facility Condition Index:	0.13 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	2,912
Building Code:	R2900104460	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,934
Building Name:	Roseau River WMA Office Pump House	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$2,782
Facility Condition Index:	0.16 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	42
Building Code:	R2900105200	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,801
Building Name:	Roseau River WMA Pump House	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$2,949
Facility Condition Index:	0.25 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	80
Building Code:	R2900105300	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$49,101
Building Name:	Roseau River WMA Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$4,910
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	176
Building Code:	R2900105310	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$24,551
Building Name:	Roseau River WMA Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$2,455
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	122

Building Code:	R2900105320	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$247,629
Building Name:	Roseau River WMA Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$24,763
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	706
Building Code:	R2900107670	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,713
Building Name:	Roseau River WMA Granary Storage	**Address:**	27952 400TH ST	**Deferred Maintenance:**	$1,871
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	143

Site: R290108 - Thief Lake WMA

Building Code:	R2900100260	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$11,393
Building Name:	Thief Lake WMA Office Picnic Shel 1	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$2,487
Facility Condition Index:	0.22 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	288
Building Code:	R2900100670	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$639,345
Building Name:	Thief Lake WMA Barracks Office	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$121,578
Facility Condition Index:	0.19 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	3,091
Building Code:	R2900100680	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$799,587
Building Name:	Thief Lake WMA Office Log Residence	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$194,415
Facility Condition Index:	0.24 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	2,906
Building Code:	R2900100690	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$408,999
Building Name:	Thief Lake WMA Residence Near Dam	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$62,617
Facility Condition Index:	0.15 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	2,448
Building Code:	R2900100710	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$44,641
Building Name:	Thief Lake WMA Office Area Garage	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$15,148
Facility Condition Index:	0.34 - Poor	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	252
Building Code:	R2900100730	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,595
Building Name:	Thief Lake WMA Office Granary Stor	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$1,759
Facility Condition Index:	0.10 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	154
Building Code:	R2900100740	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,595
Building Name:	Thief Lake WMA Office Granary Stor	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$1,759
Facility Condition Index:	0.10 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	154
Building Code:	R2900100750	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,190
Building Name:	Thief Lake WMA Office Granary Stor	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$3,519
Facility Condition Index:	0.10 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	255
Building Code:	R2900100760	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,081
Building Name:	Thief Lake WMA Office Area Garage	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$13,441
Facility Condition Index:	0.41 - Poor	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	240

Building Code:	R2900100810	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$335,422
Building Name:	Thief Lake WMA Office	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$43,519
Facility Condition Index:	0.13 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	1,535
Building Code:	R2900100820	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$67,961
Building Name:	Thief Lake WMA Office Pump House	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$12,815
Facility Condition Index:	0.19 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	170
Building Code:	R2900104610	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$942,749
Building Name:	Thief Lake WMA Shop	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$114,186
Facility Condition Index:	0.12 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	6,900
Building Code:	R2900105070	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$12,649
Building Name:	Thief Lake WMA Office Cold Storage	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$4,694
Facility Condition Index:	0.37 - Poor	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	156
Building Code:	R2900105080	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,190
Building Name:	Thief Lake WMA Office Granary Stor	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$3,519
Facility Condition Index:	0.10 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	255
Building Code:	R2900107420	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$49,889
Building Name:	Thief Lake WMA Farm Residnce Garage	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$20,580
Facility Condition Index:	0.41 - Poor	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	625
Building Code:	R2900107430	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$618,093
Building Name:	Thief Lake WMA Farm Residence	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$121,226
Facility Condition Index:	0.20 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	3,780
Building Code:	R2900107490	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$356,232
Building Name:	Thief Lake WMA Farm Barn	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$98,423
Facility Condition Index:	0.28 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	2,501
Building Code:	R2900107500	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$139,742
Building Name:	Thief Lake WMA Farm Quonset	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$42,067
Facility Condition Index:	0.30 - Poor	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	2,100
Building Code:	R2900107510	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,148
Building Name:	Thief Lake WMA Farm Oil House	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$3,562
Facility Condition Index:	0.24 - Fair	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	99
Building Code:	R2900107520	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$40,479
Building Name:	Thief Lake WMA Farm Barn Silo	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$4,048
Facility Condition Index:	0.10 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	230
Building Code:	R2900107530	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$315,898
Building Name:	Thief Lake WMA Farm Metal Shop	**Address:**	42280 240TH AVE NE	**Deferred Maintenance:**	$31,590
Facility Condition Index:	0.10 - Good	**City Code:**	MIDDLE RIVER	**Ext. Gross Area:**	2,597

Building Code: R2900107540
Building Name: Thief Lake WMA Granary Storage
Facility Condition Index: 0.10 - Good

Cost Model Name: Utility Shed
Address: 42280 240TH AVE NE
City Code: MIDDLE RIVER

Current Replacement Value: $35,190
Deferred Maintenance: $3,519
Ext. Gross Area: 255

Building Code: R2900107580
Building Name: Thief Lake WMA Granary Storage
Facility Condition Index: 0.10 - Good

Cost Model Name: Utility Shed
Address: 42280 240TH AVE NE
City Code: MIDDLE RIVER

Current Replacement Value: $31,668
Deferred Maintenance: $3,167
Ext. Gross Area: 200

Building Code: R2900108830
Building Name: Thief Lake WMA North Vault Toilet
Facility Condition Index: 0.26 - Fair

Cost Model Name: Vault Toilet
Address: 42280 240TH AVE NE
City Code: MIDDLE RIVER

Current Replacement Value: $17,162
Deferred Maintenance: $4,377
Ext. Gross Area: 48

Site: R290109 - Heartland State Trail

Building Code: R2900106740
Building Name: Heartland ST Nevis Picnic Shelter
Facility Condition Index: 0.13 - Good

Cost Model Name: Open Air Shelter
Address: 603 1ST ST W
City Code: PARK RAPIDS

Current Replacement Value: $13,791
Deferred Maintenance: $1,749
Ext. Gross Area: 160

Building Code: R2900106750
Building Name: Heartland ST Dorset Picnic Shelter
Facility Condition Index: 0.34 - Poor

Cost Model Name: Open Air Shelter
Address: 603 1ST ST W
City Code: PARK RAPIDS

Current Replacement Value: $44,132
Deferred Maintenance: $14,983
Ext. Gross Area: 512

Building Code: R2900106760
Building Name: Heartland ST Kabakona Picnic Shel
Facility Condition Index: 0.37 - Poor

Cost Model Name: Open Air Shelter
Address: 603 1ST ST W
City Code: PARK RAPIDS

Current Replacement Value: $44,132
Deferred Maintenance: $16,166
Ext. Gross Area: 512

Building Code: R2900106770
Building Name: Heartland ST Akeley Picnic Shelter
Facility Condition Index: 0.12 - Good

Cost Model Name: Open Air Shelter
Address: ACKLEY
City Code: NEVIS

Current Replacement Value: $49,881
Deferred Maintenance: $6,171
Ext. Gross Area: 512

Site: R290110 - R J Dorer State Forest

Building Code: R2900502700
Building Name: RJDorer Zumbro Btm M Vault Toilet
Facility Condition Index: 0.24 - Fair

Cost Model Name: Vault Toilet
Address: 29223 CO 28 BLVD
City Code: LAKE CITY

Current Replacement Value: $22,699
Deferred Maintenance: $5,377
Ext. Gross Area: 64

Building Code: R2900502710
Building Name: RJDorer Zumbro Btm F Vault Toilet
Facility Condition Index: 0.24 - Fair

Cost Model Name: Vault Toilet
Address: 29223 CO 28 BLVD
City Code: LAKE CITY

Current Replacement Value: $22,699
Deferred Maintenance: $5,377
Ext. Gross Area: 64

Building Code: R2900502720
Building Name: RJDorer Zumbro Btm U Vault Toilet
Facility Condition Index: 0.24 - Fair

Cost Model Name: Vault Toilet
Address: 29223 CO 28 BLVD
City Code: LAKE CITY

Current Replacement Value: $22,699
Deferred Maintenance: $5,377
Ext. Gross Area: 64

Building Code:	R2900502730	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,263
Building Name:	RJDorer Zumbro Btm M Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$5,932
Facility Condition Index:	0.27 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900502740	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$23,170
Building Name:	RJDorer SF Snake Crk Vault Toilet	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$5,463
Facility Condition Index:	0.24 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	36
Building Code:	R2900502750	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,194
Building Name:	RJDorer SF Kruger Vault Concrete	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$24,895
Facility Condition Index:	0.75 - Crisis	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900502760	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,194
Building Name:	RJDorer SF Kruger Vault Concrete	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$24,895
Facility Condition Index:	0.75 - Crisis	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900502770	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$23,021
Building Name:	RJDorer SF Kruger Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$6,089
Facility Condition Index:	0.26 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900502780	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,263
Building Name:	RJDorer SF Kruger Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,784
Facility Condition Index:	0.21 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900502800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,672
Building Name:	RJDorer SF Wet Bark Vault Concrete	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$14,004
Facility Condition Index:	0.75 - Crisis	**City Code:**	CALEDONIA	**Ext. Gross Area:**	36
Building Code:	R2900502810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,672
Building Name:	RJDorer SF Reno Unit Low Vault Conc	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$14,004
Facility Condition Index:	0.75 - Crisis	**City Code:**	CALEDONIA	**Ext. Gross Area:**	36
Building Code:	R2900503350	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$31,597
Building Name:	RJDorer SF Zumbro Btm Picnic Shel 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$11,127
Facility Condition Index:	0.35 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	384
Building Code:	R2900503360	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$45,290
Building Name:	RJDorer SF Kruger Picnic Shelter 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$11,919
Facility Condition Index:	0.26 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	527
Building Code:	R2900503370	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$31,597
Building Name:	RJDorer SF Kruger Picnic Shelter 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$10,432
Facility Condition Index:	0.33 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	384
Building Code:	R2900503660	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$27,914
Building Name:	RJDorer SF Kruger Picnic Shelter 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$10,359
Facility Condition Index:	0.37 - Poor	**City Code:**	LAKE CITY	**Ext. Gross Area:**	384

Building Code:	R2900503820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$23,046
Building Name:	RJDorer Zumbro Btm U Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$3,852
Facility Condition Index:	0.17 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,314
Building Name:	RJDorer SF Kruger Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,972
Facility Condition Index:	0.22 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,314
Building Name:	RJDorer SF Kruger Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$4,801
Facility Condition Index:	0.22 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900503850	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$79,080
Building Name:	RJDorer SF Zumbro Btm Picnic Shel 1	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$5,863
Facility Condition Index:	0.07 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	816
Building Code:	R2900504790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,194
Building Name:	RJDorer SF Vinegar Rdg Vault Concr	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$10,954
Facility Condition Index:	0.33 - Poor	**City Code:**	CALEDONIA	**Ext. Gross Area:**	64
Building Code:	R2900504810	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$8,722
Building Name:	RJDorer SF Hay Crk Picnic Shelter 1	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$1,961
Facility Condition Index:	0.22 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	430
Building Code:	R2900504870	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$26,451
Building Name:	RJDorer SF Reno Unit Low Vault Conc	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$529
Facility Condition Index:	0.02 - Excellent	**City Code:**	CALEDONIA	**Ext. Gross Area:**	51
Building Code:	R2900504880	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$15,656
Building Name:	RJDorer SF Reno Unit Low Adirondack	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$1,816
Facility Condition Index:	0.12 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	144
Building Code:	R2900504890	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$13,718
Building Name:	RJDorer SF Reno Unit Up Adirondack	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$2,362
Facility Condition Index:	0.17 - Fair	**City Code:**	CALEDONIA	**Ext. Gross Area:**	115
Building Code:	R2900504900	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$27,047
Building Name:	RJDorer SF Wet Bark Adirondack	**Address:**	15954 CO RD 1	**Deferred Maintenance:**	$3,362
Facility Condition Index:	0.12 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	210
Building Code:	R2900504940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$22,263
Building Name:	RJDorer Zumbro Btm W F Vault Toilet	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$3,773
Facility Condition Index:	0.17 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900504950	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,194
Building Name:	RJDorer SF Zumbro Btm W Vault Concr	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$3,319
Facility Condition Index:	0.10 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64

Building Code:	R2900504960	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$33,194
Building Name:	RJDorer SF Zumbro Btm W Vault Concr	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$3,319
Facility Condition Index:	0.10 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	64
Building Code:	R2900505370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,324
Building Name:	RJDorer SF Zumbro Btm Cold Storage	**Address:**	29223 CO 28 BLVD	**Deferred Maintenance:**	$286
Facility Condition Index:	0.02 - Excellent	**City Code:**	LAKE CITY	**Ext. Gross Area:**	160
Building Code:	R2900505480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,113
Building Name:	RJDorer SF Hay Crk Vault Concrete	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$2,511
Facility Condition Index:	0.10 - Good	**City Code:**	ROCHESTER	**Ext. Gross Area:**	48
Building Code:	R2900505500	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,729
Building Name:	RJDorer SF Snake Crk Vault Concrete	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$2,773
Facility Condition Index:	0.10 - Good	**City Code:**	ROCHESTER	**Ext. Gross Area:**	53

Site: R290111 - Crow Wing State Forest

Building Code:	R2900305480	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,388
Building Name:	CWSF Greer Lk CG Fish Cleaning Hse	**Address:**	17447 GREER LAKE RD	**Deferred Maintenance:**	$13,856
Facility Condition Index:	0.65 - Crisis	**City Code:**	CROSBY	**Ext. Gross Area:**	140
Building Code:	R2900305490	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,502
Building Name:	CWSF Greer Lake CG Cold Storage	**Address:**	17447 GREER LAKE RD	**Deferred Maintenance:**	$1,018
Facility Condition Index:	0.23 - Fair	**City Code:**	CROSBY	**Ext. Gross Area:**	48
Building Code:	R2900308330	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,929
Building Name:	CWSF Greer Lake CG Vault Concrete	**Address:**	17447 GREER LAKE RD	**Deferred Maintenance:**	$359
Facility Condition Index:	0.02 - Excellent	**City Code:**	CROSBY	**Ext. Gross Area:**	33
Building Code:	R2900308340	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,709
Building Name:	CWSF Greer Lake CG Vault Concrete	**Address:**	17447 GREER LAKE RD	**Deferred Maintenance:**	$554
Facility Condition Index:	0.02 - Excellent	**City Code:**	CROSBY	**Ext. Gross Area:**	51
Building Code:	R2900308350	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,929
Building Name:	CWSF Greer Lake CG 6 Vault Concrete	**Address:**	17447 GREER LAKE RD	**Deferred Maintenance:**	$359
Facility Condition Index:	0.02 - Excellent	**City Code:**	CROSBY	**Ext. Gross Area:**	33
Building Code:	R2900308360	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,929
Building Name:	CWSF Greer Lake CG 24 Vault Concret	**Address:**	17447 GREER LAKE RD	**Deferred Maintenance:**	$359
Facility Condition Index:	0.02 - Excellent	**City Code:**	CROSBY	**Ext. Gross Area:**	33

Site: R290112 - Bowstring State Forest

Building Code:	R2900206310	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,628
Building Name:	Bowstring Moose Lk CG Vault Toilet	**Address:**	880 GARY ST	**Deferred Maintenance:**	$2,725
Facility Condition Index:	0.26 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	30
Building Code:	R2900206320	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,628
Building Name:	Bowstring Moose Lk CG Vault Toilet	**Address:**	880 GARY ST	**Deferred Maintenance:**	$2,725
Facility Condition Index:	0.26 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	30
Building Code:	R2900208300	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,485
Building Name:	Bowstring Cottonwd Lk CG Vault Toil	**Address:**	880 GARY ST	**Deferred Maintenance:**	$2,682
Facility Condition Index:	0.26 - Fair	**City Code:**	CALUMET	**Ext. Gross Area:**	30

Site: R290114 - Grand Portage State Forest

Building Code:	R2900207800	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Grnd Port SF Esther Lk CG Vault	**Address:**	1127 ESTER LAKE RD	**Deferred Maintenance:**	$4,339
Facility Condition Index:	0.26 - Fair	**City Code:**	HOVLAND	**Ext. Gross Area:**	42
Building Code:	R2900207810	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Grnd Port SF McFarl Lk CG Vault	**Address:**	3505 ARROWHEAD TRAIL	**Deferred Maintenance:**	$3,550
Facility Condition Index:	0.21 - Fair	**City Code:**	HOVLAND	**Ext. Gross Area:**	42
Building Code:	R2900207820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,008
Building Name:	Grnd Port SF Devilfish CG Vault	**Address:**	951 ESTER LAKE RD	**Deferred Maintenance:**	$1,675
Facility Condition Index:	0.10 - Good	**City Code:**	HOVLAND	**Ext. Gross Area:**	42

Site: R290115 - R1 HQ Bemidji

Building Code:	R2900100010	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$2,467,623
Building Name:	Bemidji R1 HQ Main Office	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$461,940
Facility Condition Index:	0.19 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	8,883
Building Code:	R2900100020	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$57,449
Building Name:	Bemidji R1 HQ Enforcement Garage	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$10,678
Facility Condition Index:	0.19 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	885
Building Code:	R2900104350	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$2,017,619
Building Name:	Bemidji R1 HQ Shop	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$444,851
Facility Condition Index:	0.22 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	8,353
Building Code:	R2900105250	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$53,148
Building Name:	Bemidji R1 HQ HazMat Storage	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$5,315
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	217

Building Code:	R2900105260	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,243
Building Name:	Bemidji R1 HQ HazMat Storage	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$924
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	35
Building Code:	R2900105270	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$244,613
Building Name:	Bemidji R1 HQ CCM Office	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$32,596
Facility Condition Index:	0.13 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	2,846
Building Code:	R2900107240	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$974,153
Building Name:	Bemidji R1 HQ Annex Office	**Address:**	2115 BIRCHMONT BEACH RD NE	**Deferred Maintenance:**	$82,698
Facility Condition Index:	0.08 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	5,741

Site: R290116 - Whitewater WMA

Building Code:	R2900500130	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$174,328
Building Name:	Whitewater WMA HQ Cold Storage	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$32,775
Facility Condition Index:	0.19 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	1,440
Building Code:	R2900500150	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$529,711
Building Name:	Whitewater WMA Shop	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$140,054
Facility Condition Index:	0.26 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	2,246
Building Code:	R2900500160	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$583,264
Building Name:	Whitewater WMA Main Office	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$123,128
Facility Condition Index:	0.21 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	3,829
Building Code:	R2900500190	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,782
Building Name:	Whitewater WMA Oil House	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$9,792
Facility Condition Index:	0.62 - Crisis	**City Code:**	ALTURA	**Ext. Gross Area:**	80
Building Code:	R2900502010	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$128,472
Building Name:	Whitewater WMA HQ Cold Storage	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$47,420
Facility Condition Index:	0.37 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	1,792
Building Code:	R2900502130	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$64,195
Building Name:	Whitewater WMA HQ Cold Storage	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$24,133
Facility Condition Index:	0.38 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	936
Building Code:	R2900503190	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,549
Building Name:	Whitewater WMA Granary Storage	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$5,131
Facility Condition Index:	0.33 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	176
Building Code:	R2900503200	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$1,159,441
Building Name:	Whitewater WMA Marnach House	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$455,949
Facility Condition Index:	0.39 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	1,200

Building Code:	R2900503340	**Cost Model Name:**	Tower	**Current Replacement Value:**	$22,967
Building Name:	Whitewater WMA Elba Fire Tower	**Address:**	19041 HWY 74	**Deferred Maintenance:**	$7,014
Facility Condition Index:	0.31 - Poor	**City Code:**	ALTURA	**Ext. Gross Area:**	64
Building Code:	R2900504750	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$487,169
Building Name:	Whitewater WMA Heated Storage	**Address:**	15035 HWY 74	**Deferred Maintenance:**	$34,919
Facility Condition Index:	0.07 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	5,025

Site: R290117 - Twin Lakes WMA

Building Code:	R2900104530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$290,642
Building Name:	Twin Lakes WMA Heated Storage	**Address:**	1&1/2 mi. E. of Karlstad Hwy. 11	**Deferred Maintenance:**	$41,688
Facility Condition Index:	0.14 - Good	**City Code:**	KARLSTAD	**Ext. Gross Area:**	1,920

Site: R290118 - Franz Jevne State Park

Building Code:	R2900107050	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,778
Building Name:	Franz Jevne SP Entry Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$4,028
Facility Condition Index:	0.26 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900107060	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,778
Building Name:	Franz Jevne SP Rapid Trail Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$4,028
Facility Condition Index:	0.26 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900107070	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$15,778
Building Name:	Franz Jevne SP CG Site 8 Vault	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$4,028
Facility Condition Index:	0.26 - Fair	**City Code:**	WILLIAMS	**Ext. Gross Area:**	42
Building Code:	R2900107080	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,523
Building Name:	Franz Jevne SP CG Picnic Shelter	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$552
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	96
Building Code:	R2900107090	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,523
Building Name:	Franz Jevne SP CG Site 7 Shelter	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$552
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	96
Building Code:	R2900107100	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,523
Building Name:	Franz Jevne SP CG Site 8 Shelter	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$552
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	96
Building Code:	R2900107110	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$5,523
Building Name:	Franz Jevne SP CG Site 9 Shelter	**Address:**	3684 54TH AVE NW	**Deferred Maintenance:**	$552
Facility Condition Index:	0.10 - Good	**City Code:**	WILLIAMS	**Ext. Gross Area:**	96

Building Code: R2900107120
Building Name: Franz Jevne SP CG Site 10 Shelter
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Shelter
Address: 3684 54TH AVE NW
City Code: WILLIAMS

Current Replacement Value: $5,523
Deferred Maintenance: $552
Ext. Gross Area: 96

Building Code: R2900107130
Building Name: Franz Jevne SP CG Site 12 Shelter
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Shelter
Address: 3684 54TH AVE NW
City Code: WILLIAMS

Current Replacement Value: $5,523
Deferred Maintenance: $552
Ext. Gross Area: 96

Building Code: R2900107140
Building Name: Franz Jevne SP CG Picnic Shelter
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Shelter
Address: 3684 54TH AVE NW
City Code: WILLIAMS

Current Replacement Value: $30,421
Deferred Maintenance: $3,042
Ext. Gross Area: 460

Site: R290119 - Elysian

Building Code: R2900402930
Building Name: Elysian Trails Center
Facility Condition Index: 0.36 - Poor

Cost Model Name: Single-story Restroom Facility
Address: 101 4TH ST SW
City Code: ELYSIAN

Current Replacement Value: $343,544
Deferred Maintenance: $122,658
Ext. Gross Area: 448

Building Code: R2900404060
Building Name: Elysian Office
Facility Condition Index: 0.18 - Fair

Cost Model Name: Single-story Work Facility
Address: 101 4TH ST SW
City Code: ELYSIAN

Current Replacement Value: $365,954
Deferred Maintenance: $67,584
Ext. Gross Area: 1,890

Site: R290120 - Spicer

Building Code: R2900401760
Building Name: Spicer Pump House
Facility Condition Index: 0.48 - Poor

Cost Model Name: Utility Shed
Address: 10590 CO RD 8 NE
City Code: SPICER

Current Replacement Value: $8,260
Deferred Maintenance: $3,952
Ext. Gross Area: 67

Building Code: R2900401780
Building Name: Spicer Office
Facility Condition Index: 0.21 - Fair

Cost Model Name: Joint Office/Warehouse Facility
Address: 164 CTY RD 8 NE
City Code: SPICER

Current Replacement Value: $931,882
Deferred Maintenance: $191,648
Ext. Gross Area: 4,608

Site: R290122 - Floodwood

Building Code: R2900202620
Building Name: Floodwood Office
Facility Condition Index: 0.28 - Fair

Cost Model Name: Single-story Work Facility
Address: 11809 FLOODWOOD RD
City Code: FLOODWOOD

Current Replacement Value: $302,212
Deferred Maintenance: $84,267
Ext. Gross Area: 1,845

Building Code: R2900202630
Building Name: Floodwood River Garage
Facility Condition Index: 0.25 - Fair

Cost Model Name: Single-story Work Facility
Address: 307 RAILROAD ST
City Code: FLOODWOOD

Current Replacement Value: $93,250
Deferred Maintenance: $23,051
Ext. Gross Area: 1,040

Building Code: R2900207120
Building Name: Floodwood Fire Tower
Facility Condition Index: 1.00 - Crisis

Cost Model Name: Tower
Address: 306 RAILROAD AVE
City Code: FLOODWOOD

Current Replacement Value: $19,281
Deferred Maintenance: $19,281
Ext. Gross Area: 64

Site: R290123 - International Wolf Center

Building Code:	R2900207050	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$5,167,510
Building Name:	International Wolf Center	**Address:**	1396 HWY 169	**Deferred Maintenance:**	$930,516
Facility Condition Index:	0.18 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	19,649
Building Code:	R2900208590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$68,836
Building Name:	International Wolf Ctr Cold Storage	**Address:**	1396 HWY 169	**Deferred Maintenance:**	$5,976
Facility Condition Index:	0.09 - Good	**City Code:**	ELY	**Ext. Gross Area:**	1,056

Site: R290124 - State Fairgrounds

Building Code:	R2900601890	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$89,851
Building Name:	State Fairgrounds Nature Bldg	**Address:**	1265 NELSON ST	**Deferred Maintenance:**	$7,597
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	640
Building Code:	R2900601900	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$58,812
Building Name:	State Fairgrounds DNR Outdoor Stage	**Address:**	1251 NELSON ST	**Deferred Maintenance:**	$5,240
Facility Condition Index:	0.09 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	317
Building Code:	R2900602040	**Cost Model Name:**	Tower	**Current Replacement Value:**	$58,560
Building Name:	State Fairgrounds Fire Tower	**Address:**	1765 CARNES AVE	**Deferred Maintenance:**	$4,909
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	121
Building Code:	R2900602220	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$56,922
Building Name:	State Fairgrnd Fire Prevention Bldg	**Address:**	1265 SNELLING AVE N	**Deferred Maintenance:**	$3,236
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	301
Building Code:	R2900602380	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$48,587
Building Name:	State Fairgrounds Cabin Display	**Address:**	1265 SNELLING AVE N	**Deferred Maintenance:**	$972
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	334

Site: R290127 - Hutchinson

Building Code:	R2900401810	**Cost Model Name:**	Recreation Center	**Current Replacement Value:**	$4,352,287
Building Name:	Hutchinson Office	**Address:**	20596 HWY 7	**Deferred Maintenance:**	$849,383
Facility Condition Index:	0.20 - Fair	**City Code:**	HUTCHINSON	**Ext. Gross Area:**	17,485
Building Code:	R2900402850	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,799
Building Name:	Hutchinson Cold Storage	**Address:**	20596 HWY 7	**Deferred Maintenance:**	$4,728
Facility Condition Index:	0.54 - Crisis	**City Code:**	HUTCHINSON	**Ext. Gross Area:**	83

Site: R290128 - Brainerd

Building Code:	R2900303720	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$325,595
Building Name:	Brainerd HeatColdStorage	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$66,187
Facility Condition Index:	0.20 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,700
Building Code:	R2900304020	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$10,013,985
Building Name:	Brainerd Office	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$1,681,142
Facility Condition Index:	0.17 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	38,027
Building Code:	R2900304040	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,096,634
Building Name:	Brainerd Shop	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$189,895
Facility Condition Index:	0.17 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	6,529
Building Code:	R2900304050	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,224,105
Building Name:	Brainerd Heated Storage	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$177,195
Facility Condition Index:	0.14 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	13,351
Building Code:	R2900304060	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,103,641
Building Name:	Brainerd Cold Storage	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$131,716
Facility Condition Index:	0.12 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	19,878
Building Code:	R2900304070	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$124,231
Building Name:	Brainerd Central Heat Plant	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$11,455
Facility Condition Index:	0.09 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	798
Building Code:	R2900305090	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$57,677
Building Name:	Brainerd Hazardous Mat Storage	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$43,258
Facility Condition Index:	0.75 - Crisis	**City Code:**	BRAINERD	**Ext. Gross Area:**	209
Building Code:	R2900305100	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,134
Building Name:	Brainerd Hazardous Mat Storage	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$6,100
Facility Condition Index:	0.75 - Crisis	**City Code:**	BRAINERD	**Ext. Gross Area:**	34
Building Code:	R2900307650	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$383,026
Building Name:	Brainerd Cold Storage	**Address:**	1601 MINNESOTA DR	**Deferred Maintenance:**	$7,661
Facility Condition Index:	0.02 - Excellent	**City Code:**	BRAINERD	**Ext. Gross Area:**	3,566

Site: R290129 - Pine River

Building Code:	R2900300760	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,207
Building Name:	Pine River Cold Storage	**Address:**	36765 PIN KNOLLS CR	**Deferred Maintenance:**	$9,442
Facility Condition Index:	0.23 - Fair	**City Code:**	JENKINS	**Ext. Gross Area:**	539
Building Code:	R2900305070	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$23,927
Building Name:	Pine River Contact Station	**Address:**	36765 PIN KNOLLS CR	**Deferred Maintenance:**	$7,536
Facility Condition Index:	0.31 - Poor	**City Code:**	JENKINS	**Ext. Gross Area:**	180

Building Code:	R2900305080	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,565
Building Name:	Pine River Cold Storage	**Address:**	36765 PIN KNOLLS CR	**Deferred Maintenance:**	$2,167
Facility Condition Index:	0.33 - Poor	**City Code:**	JENKINS	**Ext. Gross Area:**	122

Site: R290130 - Gull Lake

Building Code:	R2900306260	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$91,666
Building Name:	Gull Lake East WAS Sanitation	**Address:**	5056 NASHWAY RD	**Deferred Maintenance:**	$9,094
Facility Condition Index:	0.10 - Good	**City Code:**	NISSWA	**Ext. Gross Area:**	272

Site: R290131 - Badoura State Forest

Building Code:	R2900105580	**Cost Model Name:**	Tower	**Current Replacement Value:**	$17,952
Building Name:	Badoura SF Fire Tower	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$13,464
Facility Condition Index:	0.75 - Crisis	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	64
Building Code:	R2900108160	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$61,838
Building Name:	Badoura SF Residence Garage	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$1,720
Facility Condition Index:	0.03 - Excellent	**City Code:**	AKELEY	**Ext. Gross Area:**	768
Building Code:	R2900300010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,640,430
Building Name:	Badoura SF Old Seedling Pack House	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$503,496
Facility Condition Index:	0.19 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	6,732
Building Code:	R2900300020	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$288,175
Building Name:	Badoura SF Residence	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$31,008
Facility Condition Index:	0.11 - Good	**City Code:**	AKELEY	**Ext. Gross Area:**	2,128
Building Code:	R2900300060	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,618
Building Name:	Badoura SF Old Carpenters Shop	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$18,961
Facility Condition Index:	0.18 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	1,536
Building Code:	R2900300070	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$50,283
Building Name:	Badoura SF Oil House	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$8,667
Facility Condition Index:	0.17 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	286
Building Code:	R2900300080	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$475,677
Building Name:	Badoura SF Office	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$35,036
Facility Condition Index:	0.07 - Good	**City Code:**	AKELEY	**Ext. Gross Area:**	2,240
Building Code:	R2900300100	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,125,585
Building Name:	Badoura SF Shop	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$222,390
Facility Condition Index:	0.20 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	6,043

Building Code:	R2900300110	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$144,248
Building Name:	Badoura SF Two Stall Garage	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$21,430
Facility Condition Index:	0.15 - Good	**City Code:**	AKELEY	**Ext. Gross Area:**	1,059
Building Code:	R2900300120	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$508,502
Building Name:	Badoura SF Cold Storage Ike's Bldg	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$52,239
Facility Condition Index:	0.10 - Good	**City Code:**	AKELEY	**Ext. Gross Area:**	4,473
Building Code:	R2900300130	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$124,488
Building Name:	Badoura SF Fertilizer Building	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$25,504
Facility Condition Index:	0.20 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	1,319
Building Code:	R2900300150	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$608,815
Building Name:	Badoura SF Pine Cone Storage	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$156,845
Facility Condition Index:	0.26 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	5,084
Building Code:	R2900300360	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$204,375
Building Name:	Badoura SF Mamie's Building	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$21,053
Facility Condition Index:	0.10 - Good	**City Code:**	AKELEY	**Ext. Gross Area:**	1,612
Building Code:	R2900300400	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$57,655
Building Name:	Badoura SF Quonset	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$14,452
Facility Condition Index:	0.25 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	1,600
Building Code:	R2900303640	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$258,494
Building Name:	Badoura SF Open Cold Storage	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$41,500
Facility Condition Index:	0.16 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	2,703
Building Code:	R2900304770	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,102,492
Building Name:	Badoura SF Seed Extractory	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$174,956
Facility Condition Index:	0.16 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	10,118
Building Code:	R2900305800	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,452,217
Building Name:	Badoura SF New Seedling Pack House	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$48,525
Facility Condition Index:	0.03 - Excellent	**City Code:**	AKELEY	**Ext. Gross Area:**	6,294
Building Code:	R2900305810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,224
Building Name:	Badoura SF Radio Shelter	**Address:**	13885 STATE HWY 64	**Deferred Maintenance:**	$1,912
Facility Condition Index:	0.19 - Fair	**City Code:**	AKELEY	**Ext. Gross Area:**	39

Site: R290133 - Cambridge

Building Code:	R2900305190	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,003,518
Building Name:	Cambridge Office	**Address:**	800 OAK SAVANA LN SW	**Deferred Maintenance:**	$187,629
Facility Condition Index:	0.19 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	5,000

Building Code:	R2900305200	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$538,038
Building Name:	Cambridge Shop	**Address:**	800 OAK SAVANA LN SW	**Deferred Maintenance:**	$169,504
Facility Condition Index:	0.32 - Poor	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	3,270
Building Code:	R2900305210	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$166,000
Building Name:	Cambridge Cold Storage	**Address:**	800 OAK SAVANA LN SW	**Deferred Maintenance:**	$30,223
Facility Condition Index:	0.18 - Fair	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	2,715

Site: R290134 - Dalbo WMA

Building Code:	R2900306760	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$394,579
Building Name:	Dalbo WMA Cold Storage	**Address:**	421ST AVE NW	**Deferred Maintenance:**	$219,176
Facility Condition Index:	0.56 - Crisis	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	3,431
Building Code:	R2900306930	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,160,291
Building Name:	Dalbo WMA HeatColdStorage	**Address:**	421ST AVE NW	**Deferred Maintenance:**	$1,653,171
Facility Condition Index:	0.52 - Crisis	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	18,937
Building Code:	R2900306950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$363,562
Building Name:	Dalbo WMA Cold Storage	**Address:**	421ST AVE NW	**Deferred Maintenance:**	$174,795
Facility Condition Index:	0.48 - Poor	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	3,655

Site: R290135 - Ruff-Nik WMA

Building Code:	R2900307450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$203,857
Building Name:	Ruff-Nik WMA Lrg Pole Cold Storage	**Address:**	16543 HAVEN RD	**Deferred Maintenance:**	$42,599
Facility Condition Index:	0.21 - Fair	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	2,268
Building Code:	R2900307460	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$110,777
Building Name:	Ruff-Nik WMA Sm Steel Cold Storage	**Address:**	16543 HAVEN RD	**Deferred Maintenance:**	$14,261
Facility Condition Index:	0.13 - Good	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	1,080
Building Code:	R2900307470	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$133,080
Building Name:	Ruff-Nik WMA Concrete Cold Storage	**Address:**	16543 HAVEN RD	**Deferred Maintenance:**	$76,510
Facility Condition Index:	0.57 - Crisis	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	1,248

Site: R290136 - Cook

Building Code:	R2900203140	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$263,114
Building Name:	Cook Office	**Address:**	310 2ND ST SE	**Deferred Maintenance:**	$64,811
Facility Condition Index:	0.25 - Fair	**City Code:**	COOK	**Ext. Gross Area:**	1,344
Building Code:	R2900203150	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$235,677
Building Name:	Cook HeatColdStorage	**Address:**	310 2ND ST SE	**Deferred Maintenance:**	$34,181
Facility Condition Index:	0.15 - Good	**City Code:**	COOK	**Ext. Gross Area:**	1,449

Site: R290138 - Mentor Prairie WMA

Building Code:	R2900106950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$279,592
Building Name:	Mentor Prairie WMA Cold Storage	**Address:**	.3 mile E. of intersection of 295th St	**Deferred Maintenance:**	$63,211
Facility Condition Index:	0.23 - Fair	**City Code:**	CROOKSTON	**Ext. Gross Area:**	2,952

Site: R290139 - Deer River City

Building Code:	R2900201790	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$176,126
Building Name:	Deer River City Cold Storage	**Address:**	403 DIVISION ST	**Deferred Maintenance:**	$37,818
Facility Condition Index:	0.21 - Fair	**City Code:**	DEER RIVER	**Ext. Gross Area:**	1,560
Building Code:	R2900201800	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$501,870
Building Name:	Deer River City Office	**Address:**	403 DIVISION ST	**Deferred Maintenance:**	$104,464
Facility Condition Index:	0.21 - Fair	**City Code:**	DEER RIVER	**Ext. Gross Area:**	2,576
Building Code:	R2900201810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,262
Building Name:	Deer River City Oil House	**Address:**	403 DIVISION ST	**Deferred Maintenance:**	$6,878
Facility Condition Index:	0.31 - Poor	**City Code:**	DEER RIVER	**Ext. Gross Area:**	168
Building Code:	R2900203560	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$383,795
Building Name:	Deer River City Shop	**Address:**	403 DIVISION ST	**Deferred Maintenance:**	$123,073
Facility Condition Index:	0.32 - Poor	**City Code:**	DEER RIVER	**Ext. Gross Area:**	2,141

Site: R290140 - Detroit Lakes

Building Code:	R2900100910	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$222,940
Building Name:	Detroit Lakes Cold Storage	**Address:**	14583 CTY HWY 19	**Deferred Maintenance:**	$27,340
Facility Condition Index:	0.12 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	2,881
Building Code:	R2900100930	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,831
Building Name:	Detroit Lakes Sign Shed	**Address:**	14583 CTY HWY 19	**Deferred Maintenance:**	$7,642
Facility Condition Index:	0.27 - Fair	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	220
Building Code:	R2900105240	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,131,568
Building Name:	Detroit Lakes Office	**Address:**	14583 CTY HWY 19	**Deferred Maintenance:**	$157,904
Facility Condition Index:	0.14 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	5,013
Building Code:	R2900105690	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$2,596,403
Building Name:	Detroit Lakes Fish Hatchery	**Address:**	14583 CTY HWY 19	**Deferred Maintenance:**	$359,534
Facility Condition Index:	0.14 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	20,114
Building Code:	R2900106350	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$39,463
Building Name:	Detroit Lakes Tree Storage	**Address:**	14583 CTY HWY 19	**Deferred Maintenance:**	$5,243
Facility Condition Index:	0.13 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	515

Site: R290141 - Sedan Pond WMA

Building Code:	R2900101210	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,487
Building Name:	Sedan Pond WMA Pump House	**Address:**	23070 N LAKESHORE DR	**Deferred Maintenance:**	$5,225
Facility Condition Index:	0.27 - Fair	**City Code:**	GLENWOOD	**Ext. Gross Area:**	144

Site: R290142 - Finland

Building Code:	R2900201920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$415,861
Building Name:	Finland Shop	**Address:**	6686 HWY 1	**Deferred Maintenance:**	$125,275
Facility Condition Index:	0.30 - Poor	**City Code:**	FINLAND	**Ext. Gross Area:**	1,860
Building Code:	R2900201930	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$129,950
Building Name:	Finland Cold Storage	**Address:**	6686 HWY 1	**Deferred Maintenance:**	$65,240
Facility Condition Index:	0.50 - Crisis	**City Code:**	FINLAND	**Ext. Gross Area:**	864
Building Code:	R2900201950	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$884,683
Building Name:	Finland Office	**Address:**	6686 HWY 1	**Deferred Maintenance:**	$78,314
Facility Condition Index:	0.09 - Good	**City Code:**	FINLAND	**Ext. Gross Area:**	3,654
Building Code:	R2900204140	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,910
Building Name:	Finland Oil House	**Address:**	6686 HWY 1	**Deferred Maintenance:**	$6,305
Facility Condition Index:	0.32 - Poor	**City Code:**	FINLAND	**Ext. Gross Area:**	96
Building Code:	R2900204290	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$327,413
Building Name:	Finland Cold Storage	**Address:**	6686 HWY 1	**Deferred Maintenance:**	$41,788
Facility Condition Index:	0.13 - Good	**City Code:**	FINLAND	**Ext. Gross Area:**	2,880

Site: R290143 - Grand Marais

Building Code:	R2900201980	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$468,448
Building Name:	Grand Marais 6-Stall Cold Storage	**Address:**	1356 E HWY 61	**Deferred Maintenance:**	$65,406
Facility Condition Index:	0.14 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	2,821
Building Code:	R2900202030	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$977,888
Building Name:	Grand Marais Office	**Address:**	1356 E HWY 61	**Deferred Maintenance:**	$54,375
Facility Condition Index:	0.06 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	3,685
Building Code:	R2900203810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,003
Building Name:	Grand Marais Oil House	**Address:**	1356 E HWY 61	**Deferred Maintenance:**	$2,419
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	300
Building Code:	R2900204170	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$12,051
Building Name:	Grand Marais Cold Storage	**Address:**	1356 E HWY 61	**Deferred Maintenance:**	$6,436
Facility Condition Index:	0.53 - Crisis	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	96

Site: R290144 - Hibbing Minerals

Building Code:	R2900204640	**Cost Model Name:**	Single-story Educational Facility	**Current Replacement Value:**	$3,185,190
Building Name:	Hibbing Minerals Office	**Address:**	1525 3RD AVE E	**Deferred Maintenance:**	$879,565
Facility Condition Index:	0.28 - Fair	**City Code:**	HIBBING	**Ext. Gross Area:**	22,513
Building Code:	R2900204650	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$31,785
Building Name:	Hibbing Minerals Cold Storage	**Address:**	1525 3RD AVE E	**Deferred Maintenance:**	$19,458
Facility Condition Index:	0.61 - Crisis	**City Code:**	HIBBING	**Ext. Gross Area:**	121
Building Code:	R2900204660	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$824,205
Building Name:	Hibbing Minerals Core Library 1	**Address:**	1525 3RD AVE E	**Deferred Maintenance:**	$93,604
Facility Condition Index:	0.11 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	5,000
Building Code:	R2900204680	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,056,010
Building Name:	Hibbing Minerals Core Library 2	**Address:**	1525 3RD AVE E	**Deferred Maintenance:**	$123,518
Facility Condition Index:	0.12 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	8,010
Building Code:	R2900206580	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,727,888
Building Name:	Hibbing Minerals Core Library 3	**Address:**	1525 3RD AVE E	**Deferred Maintenance:**	$148,123
Facility Condition Index:	0.05 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	16,000
Building Code:	R2900207530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$134,171
Building Name:	Hibbing Minerals Laboratory	**Address:**	1525 3RD AVE E	**Deferred Maintenance:**	$14,038
Facility Condition Index:	0.10 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	864

Site: R290145 - Hill City

Building Code:	R2900303840	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$468,606
Building Name:	Hill City Office	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$115,534
Facility Condition Index:	0.25 - Fair	**City Code:**	HILL CITY	**Ext. Gross Area:**	1,472
Building Code:	R2900303850	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$503,505
Building Name:	Hill City Shop	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$110,970
Facility Condition Index:	0.22 - Fair	**City Code:**	HILL CITY	**Ext. Gross Area:**	2,992
Building Code:	R2900303970	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,859
Building Name:	Hill City Oil House	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$1,873
Facility Condition Index:	0.15 - Good	**City Code:**	HILL CITY	**Ext. Gross Area:**	96
Building Code:	R2900303990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$401,657
Building Name:	Hill City Cold Storage	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$103,752
Facility Condition Index:	0.26 - Fair	**City Code:**	HILL CITY	**Ext. Gross Area:**	2,051
Building Code:	R2900304000	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,424
Building Name:	Hill City Radio Shelter	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$3,212
Facility Condition Index:	0.21 - Fair	**City Code:**	HILL CITY	**Ext. Gross Area:**	120

Site: R290146 - International Falls

Building Code:	R2900200310	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$488,742
Building Name:	International Falls Repair Shop	**Address:**	392 HWY 11 E	**Deferred Maintenance:**	$55,333
Facility Condition Index:	0.11 - Good	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	3,003
Building Code:	R2900202720	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$613,899
Building Name:	International Falls Office	**Address:**	392 HWY 11 E	**Deferred Maintenance:**	$161,202
Facility Condition Index:	0.26 - Fair	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	3,045
Building Code:	R2900203720	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,102
Building Name:	International Falls Oil House	**Address:**	392 HWY 11 E	**Deferred Maintenance:**	$6,351
Facility Condition Index:	0.52 - Crisis	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	96
Building Code:	R2900207550	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$209,132
Building Name:	International Falls Modular Office	**Address:**	392 HWY 11 E	**Deferred Maintenance:**	$37,110
Facility Condition Index:	0.18 - Fair	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	984
Building Code:	R2900209480	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,653
Building Name:	International Falls Storage Shed	**Address:**	392 HWY 11 E	**Deferred Maintenance:**	$5,844
Facility Condition Index:	0.28 - Fair	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	200

Site: R290147 - Iron Range OHVRA

Building Code:	R2900208310	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$316,123
Building Name:	Iron Range OHVRA Contact Sta	**Address:**	7196 PETTIT RD	**Deferred Maintenance:**	$42,162
Facility Condition Index:	0.13 - Good	**City Code:**	GILBERT	**Ext. Gross Area:**	1,104
Building Code:	R2900208320	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$278,030
Building Name:	Iron Range OHVRA Cold Storage	**Address:**	7196 PETTIT RD	**Deferred Maintenance:**	$5,886
Facility Condition Index:	0.02 - Excellent	**City Code:**	GILBERT	**Ext. Gross Area:**	3,200
Building Code:	R2900208330	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$330,448
Building Name:	Iron Range OHVRA Office	**Address:**	7196 PETTIT RD	**Deferred Maintenance:**	$27,928
Facility Condition Index:	0.08 - Good	**City Code:**	GILBERT	**Ext. Gross Area:**	1,169
Building Code:	R2900208500	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$121,343
Building Name:	Iron Range OHVRA Wash Building	**Address:**	7196 PETTIT RD	**Deferred Maintenance:**	$9,181
Facility Condition Index:	0.08 - Good	**City Code:**	GILBERT	**Ext. Gross Area:**	1,840
Building Code:	R2900208570	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,026
Building Name:	Iron Range OHVRA Pump House	**Address:**	7196 PETTIT RD	**Deferred Maintenance:**	$781
Facility Condition Index:	0.04 - Excellent	**City Code:**	GILBERT	**Ext. Gross Area:**	64

Site: R290149 - Lewiston

Building Code:	R2900501820	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$408,688
Building Name:	Lewiston Office	**Address:**	140 FREMONT ST N	**Deferred Maintenance:**	$79,289
Facility Condition Index:	0.19 - Fair	**City Code:**	LEWISTON	**Ext. Gross Area:**	2,384
Building Code:	R2900501970	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$40,926
Building Name:	Lewiston Oil House	**Address:**	Hwy 14 & Fremont St	**Deferred Maintenance:**	$12,926
Facility Condition Index:	0.32 - Poor	**City Code:**	LEWISTON	**Ext. Gross Area:**	216

Site: R290151 - Baudette Fairgrounds

Building Code:	R2900103830	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$79,540
Building Name:	Baudette Fairgrnd Interp Unoccupied	**Address:**	FAIRGOUNDS	**Deferred Maintenance:**	$10,211
Facility Condition Index:	0.13 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	355

Site: R290152 - Brainerd-Crow Wing County Airport

Building Code:	R2900306740	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$48,895
Building Name:	Brainerd Airport Shed	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$4,429
Facility Condition Index:	0.09 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	204
Building Code:	R2900306750	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$290,331
Building Name:	Brainerd Airport Office	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$32,257
Facility Condition Index:	0.11 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	1,727
Building Code:	R2900308370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,867
Building Name:	Brainerd Airport Cold Storage	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$972
Facility Condition Index:	0.17 - Fair	**City Code:**	BRAINERD	**Ext. Gross Area:**	42
Building Code:	R2900308380	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,793
Building Name:	Brainerd Airport Cold Storage 2	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$1,851
Facility Condition Index:	0.06 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	128
Building Code:	R2900308390	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,558
Building Name:	Brainerd Airport Cold Storage 3	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$776
Facility Condition Index:	0.02 - Excellent	**City Code:**	BRAINERD	**Ext. Gross Area:**	128
Building Code:	R2900308400	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$30,328
Building Name:	Brainerd Airport Cold Storage 4	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$1,172
Facility Condition Index:	0.04 - Excellent	**City Code:**	BRAINERD	**Ext. Gross Area:**	120
Building Code:	R2900308410	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$30,372
Building Name:	Brainerd Airport Cold Storage 5	**Address:**	12834 HWY 210 E	**Deferred Maintenance:**	$1,500
Facility Condition Index:	0.05 - Excellent	**City Code:**	BRAINERD	**Ext. Gross Area:**	120

Site: R290154 - Foot Hills State Forest

Building Code:	R2900301160	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,153
Building Name:	Foot Hills Spider Lake Vault Toilet	**Address:**	Spider Lake Rec. Area	**Deferred Maintenance:**	$1,208
Facility Condition Index:	0.12 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	38
Building Code:	R2900301420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,153
Building Name:	Foot Hills Spider Lake Vault Toilet	**Address:**	Spider Lake Rec. Area	**Deferred Maintenance:**	$1,208
Facility Condition Index:	0.12 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	38

Site: R290155 - Chisholm-Hibbing Airport

Building Code:	R2900207680	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$380,578
Building Name:	Hibbing Airport Main Dispatch Of	**Address:**	10956 HWY 37	**Deferred Maintenance:**	$48,864
Facility Condition Index:	0.13 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	1,717
Building Code:	R2900208400	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$72,696
Building Name:	Hibbing Airport Spring House	**Address:**	10956 HWY 37	**Deferred Maintenance:**	$1,454
Facility Condition Index:	0.02 - Excellent	**City Code:**	HIBBING	**Ext. Gross Area:**	432
Building Code:	R2900209030	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$180,384
Building Name:	Hibbing Airport Crew Trailer/Office	**Address:**	10956 HWY 37	**Deferred Maintenance:**	$13,539
Facility Condition Index:	0.08 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	840

Site: R290156 - Hibbing Forestry

Building Code:	R2900201550	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$478,181
Building Name:	Hibbing Forestry Office	**Address:**	1208 E HOWARD ST	**Deferred Maintenance:**	$102,396
Facility Condition Index:	0.21 - Fair	**City Code:**	HIBBING	**Ext. Gross Area:**	2,447
Building Code:	R2900201570	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$372,353
Building Name:	Hibbing Forestry Shop	**Address:**	1208 E HOWARD ST	**Deferred Maintenance:**	$98,075
Facility Condition Index:	0.26 - Fair	**City Code:**	HIBBING	**Ext. Gross Area:**	2,460
Building Code:	R2900201590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$184,186
Building Name:	Hibbing Forestry Cold Storage	**Address:**	1208 E HOWARD ST	**Deferred Maintenance:**	$47,348
Facility Condition Index:	0.26 - Fair	**City Code:**	HIBBING	**Ext. Gross Area:**	1,040
Building Code:	R2900204280	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,207
Building Name:	Hibbing Forestry Oil House	**Address:**	1208 E HOWARD ST	**Deferred Maintenance:**	$1,791
Facility Condition Index:	0.15 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	96
Building Code:	R2900209900	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$331,246
Building Name:	Hibbing Forestry Fire Truck Storage	**Address:**	1208 E HOWARD ST	**Deferred Maintenance:**	$6,625
Facility Condition Index:	0.02 - Excellent	**City Code:**	HIBBING	**Ext. Gross Area:**	2,992

Site: R290157 - Munson Lake

Building Code:	R2900104540	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,407
Building Name:	Munson Lake Spring House	**Address:**	14583 CTY HWY 19	**Deferred Maintenance:**	$16,333
Facility Condition Index:	0.84 - Crisis	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	128

Site: R290158 - Littlefork

Building Code:	R2900202670	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$641,190
Building Name:	Littlefork Office	**Address:**	421 3RD AVE	**Deferred Maintenance:**	$137,494
Facility Condition Index:	0.21 - Fair	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	3,436
Building Code:	R2900202680	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$47,826
Building Name:	Littlefork Oil House	**Address:**	421 3RD AVE	**Deferred Maintenance:**	$4,783
Facility Condition Index:	0.10 - Good	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	168
Building Code:	R2900202690	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$258,761
Building Name:	Littlefork Cold Storage	**Address:**	421 3RD AVE	**Deferred Maintenance:**	$60,820
Facility Condition Index:	0.24 - Fair	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	1,300
Building Code:	R2900202700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$440,960
Building Name:	Littlefork Heat/Cold Storage	**Address:**	421 3RD AVE	**Deferred Maintenance:**	$139,694
Facility Condition Index:	0.32 - Poor	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	1,345
Building Code:	R2900204300	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$329,228
Building Name:	Littlefork Shop	**Address:**	421 3RD AVE	**Deferred Maintenance:**	$35,570
Facility Condition Index:	0.11 - Good	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	2,237

Site: R290160 - McGrath

Building Code:	R2900303950	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$384,062
Building Name:	McGrath Shop	**Address:**	16082 STATE HWY 65	**Deferred Maintenance:**	$101,214
Facility Condition Index:	0.26 - Fair	**City Code:**	MCGRATH	**Ext. Gross Area:**	1,860
Building Code:	R2900303960	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$320,704
Building Name:	McGrath Office	**Address:**	16082 STATE HWY 65	**Deferred Maintenance:**	$78,579
Facility Condition Index:	0.25 - Fair	**City Code:**	MCGRATH	**Ext. Gross Area:**	2,141
Building Code:	R2900304110	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,073
Building Name:	McGrath Oil House	**Address:**	16082 STATE HWY 65	**Deferred Maintenance:**	$2,692
Facility Condition Index:	0.16 - Fair	**City Code:**	MCGRATH	**Ext. Gross Area:**	96

Site: R290161 - Otter Tail Lake

Building Code:	R2900102750	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$68,035
Building Name:	Otter Tail Lk Pleasure Park Storage	**Address:**	42911 Pleasure Park Rd., Ottertail M	**Deferred Maintenance:**	$13,235
Facility Condition Index:	0.19 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	644

Site: R290162 - Dead River-Walker Lake

Building Code:	R2900101110	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$747,919
Building Name:	Dead River-Walker Lake Hatchery	**Address:**	32870 HWY 14	**Deferred Maintenance:**	$83,852
Facility Condition Index:	0.11 - Good	**City Code:**	RICHVILLE	**Ext. Gross Area:**	1,787
Building Code:	R2900104630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$46,487
Building Name:	Dead River-Walker Lake Garage	**Address:**	32870 CO HWY 14	**Deferred Maintenance:**	$8,621
Facility Condition Index:	0.19 - Fair	**City Code:**	RICHVILLE	**Ext. Gross Area:**	583
Building Code:	R2900107020	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$109,996
Building Name:	Dead River-Walker Lake Cold Storage	**Address:**	32870 CO HWY 14	**Deferred Maintenance:**	$11,000
Facility Condition Index:	0.10 - Good	**City Code:**	RICHVILLE	**Ext. Gross Area:**	1,179

Site: R290163 - Birchdale

Building Code:	R2900101120	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,292
Building Name:	Birchdale Fire Tower	**Address:**	HWY 11 BIRCHDALE	**Deferred Maintenance:**	$306
Facility Condition Index:	0.02 - Excellent	**City Code:**	BAUDETTE	**Ext. Gross Area:**	64
Building Code:	R2900103940	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$345,925
Building Name:	Birchdale Office	**Address:**	HWY 11 BIRCHDALE	**Deferred Maintenance:**	$54,789
Facility Condition Index:	0.16 - Fair	**City Code:**	BAUDETTE	**Ext. Gross Area:**	3,618
Building Code:	R2900104250	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,645
Building Name:	Birchdale Oil House	**Address:**	HWY 11 BIRCHDALE	**Deferred Maintenance:**	$4,458
Facility Condition Index:	0.67 - Crisis	**City Code:**	BAUDETTE	**Ext. Gross Area:**	60

Site: R290164 - Lake of the Woods State Forest

Building Code:	R2900105570	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,976
Building Name:	LOTW SF Rapid River Fire Tower	**Address:**	RAPID RIVER	**Deferred Maintenance:**	$2,962
Facility Condition Index:	0.33 - Poor	**City Code:**	BAUDETTE	**Ext. Gross Area:**	36

Site: R290165 - Smoky Hills State Forest

Building Code:	R2900105600	**Cost Model Name:**	Tower	**Current Replacement Value:**	$14,361
Building Name:	Smoky Hills SF Fire Tower	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$4,739
Facility Condition Index:	0.33 - Poor	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	176

Site: R290166 - Two Inlets State Forest

Building Code:	R2900107380	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Two Inlets SF Hungryman CG Vault	**Address:**	36750 MAIN PARK DRIVE	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35

Building Code:	R2900107390	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,775
Building Name:	Two Inlets SF Hungryman CG S2 Vault	**Address:**	36750 MAIN PARK DRIVE	**Deferred Maintenance:**	$3,004
Facility Condition Index:	0.26 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	35
Building Code:	R2900107400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,188
Building Name:	Two Inlets SF Hungrymn CG S11 Vault	**Address:**	36750 MAIN PARK DRIVE	**Deferred Maintenance:**	$2,476
Facility Condition Index:	0.15 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	48

Site: R290167 - Park Rapids Area

Building Code:	R2900100030	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$500,400
Building Name:	Park Rapids Wildlife Office	**Address:**	603 1ST ST W	**Deferred Maintenance:**	$85,707
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,593
Building Code:	R2900103510	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$605,692
Building Name:	Park Rapids Forestry Office	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$84,790
Facility Condition Index:	0.14 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,416
Building Code:	R2900103520	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$143,242
Building Name:	Park Rapids Second Garage	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$28,436
Facility Condition Index:	0.20 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,367
Building Code:	R2900103530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$228,057
Building Name:	Park Rapids First Garage	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$47,511
Facility Condition Index:	0.21 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,622
Building Code:	R2900103540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$108,421
Building Name:	Park Rapids Ice House	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$25,507
Facility Condition Index:	0.24 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,062
Building Code:	R2900103550	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$71,576
Building Name:	Park Rapids Oil House	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$7,524
Facility Condition Index:	0.11 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	195
Building Code:	R2900103570	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,994
Building Name:	Park Rapids 1-Stall Garage	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$6,684
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	306
Building Code:	R2900103580	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$485,678
Building Name:	Park Rapids Forestry Shop	**Address:**	607 W 1ST ST	**Deferred Maintenance:**	$63,477
Facility Condition Index:	0.13 - Good	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	3,027
Building Code:	R2900104560	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,817
Building Name:	Park Rapids Trails Shed	**Address:**	115 BUNYAN TRAILS DR	**Deferred Maintenance:**	$1,686
Facility Condition Index:	0.14 - Good	**City Code:**	NEVIS	**Ext. Gross Area:**	144

Building Code: R2900106160
Building Name: Park Rapids Deer Hunters Assn
Facility Condition Index: 0.21 - Fair

Cost Model Name: Single-story Work Facility
Address: 607 W 1ST ST
City Code: PARK RAPIDS

Current Replacement Value: $39,515
Deferred Maintenance: $8,255
Ext. Gross Area: 646

Building Code: R2900106730
Building Name: Park Rapids Trails Shed 2
Facility Condition Index: 0.19 - Fair

Cost Model Name: Utility Shed
Address: 603 W 1ST
City Code: PARK RAPIDS

Current Replacement Value: $9,003
Deferred Maintenance: $1,690
Ext. Gross Area: 96

Building Code: R2900107250
Building Name: Park Rapids Wildlife Metal Building
Facility Condition Index: 0.10 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 603 1ST ST W
City Code: PARK RAPIDS

Current Replacement Value: $292,062
Deferred Maintenance: $29,206
Ext. Gross Area: 3,562

Building Code: R2900109440
Building Name: Park Rapids Trails Shed
Facility Condition Index: 0.22 - Fair

Cost Model Name: Utility Shed
Address: 603 1ST ST W
City Code: PARK RAPIDS

Current Replacement Value: $9,848
Deferred Maintenance: $2,172
Ext. Gross Area: 120

Site: R290168 - Crystal Springs Hatchery

Building Code: R2900502140
Building Name: Crystal Springs - Spring House
Facility Condition Index: 0.05 - Good

Cost Model Name: Bunker
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $70,359
Deferred Maintenance: $3,610
Ext. Gross Area: 1,656

Building Code: R2900503240
Building Name: Crystal Springs - Raceway Shelter 4
Facility Condition Index: 0.12 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $300,790
Deferred Maintenance: $34,922
Ext. Gross Area: 3,192

Building Code: R2900503250
Building Name: Crystal Springs - Raceway Shelter 6
Facility Condition Index: 0.19 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $300,790
Deferred Maintenance: $58,110
Ext. Gross Area: 3,192

Building Code: R2900503260
Building Name: Crystal Springs - Raceway Shelter 8
Facility Condition Index: 0.18 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $300,790
Deferred Maintenance: $54,952
Ext. Gross Area: 3,192

Building Code: R2900503270
Building Name: Crystal Springs - Raceway Shelter 9
Facility Condition Index: 0.18 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $339,138
Deferred Maintenance: $61,979
Ext. Gross Area: 3,192

Building Code: R2900503280
Building Name: Crystal Springs - Raceway Shelter 2
Facility Condition Index: 0.11 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $545,004
Deferred Maintenance: $58,539
Ext. Gross Area: 6,300

Building Code: R2900503290
Building Name: Crystal Springs -Raceway Shelter 12
Facility Condition Index: 0.47 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 14674 CO RD 112
City Code: ALTURA

Current Replacement Value: $117,865
Deferred Maintenance: $55,926
Ext. Gross Area: 1,500

Building Code:	R2900503720	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$1,514,949
Building Name:	Crystal Springs - Fish Hatchery	**Address:**	14674 COUNTY RD 112	**Deferred Maintenance:**	$262,280
Facility Condition Index:	0.17 - Fair	**City Code:**	ALTURA	**Ext. Gross Area:**	8,102
Building Code:	R2900504150	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$623,810
Building Name:	Crystal Springs-Intermediate Hatch	**Address:**	14674 CO RD 112	**Deferred Maintenance:**	$89,159
Facility Condition Index:	0.14 - Good	**City Code:**	ALTURA	**Ext. Gross Area:**	6,006
Building Code:	R2900505530	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$619,652
Building Name:	Crystal Springs - Residence	**Address:**	14672 CO RD 112	**Deferred Maintenance:**	$12,393
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	1,900
Building Code:	R2900505610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,911
Building Name:	Crystal Springs - Cold Storage	**Address:**	14674 CO RD 112	**Deferred Maintenance:**	$438
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALTURA	**Ext. Gross Area:**	100

Site: R290169 - Woman Lake

Building Code:	R2900106410	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$86,133
Building Name:	Woman Lake Bungey Bay Heated Stor	**Address:**	07316 STATE 371 NW	**Deferred Maintenance:**	$14,931
Facility Condition Index:	0.17 - Fair	**City Code:**	WALKER	**Ext. Gross Area:**	520

Site: R290170 - Walker

Building Code:	R2900103370	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$377,620
Building Name:	Walker Office	**Address:**	7316 MN HWY 371 NW	**Deferred Maintenance:**	$67,775
Facility Condition Index:	0.18 - Fair	**City Code:**	WALKER	**Ext. Gross Area:**	2,019
Building Code:	R2900104660	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,328
Building Name:	Walker Cold Storage Shed	**Address:**	07316 MN HWY 371 NW	**Deferred Maintenance:**	$3,396
Facility Condition Index:	0.28 - Fair	**City Code:**	WALKER	**Ext. Gross Area:**	100
Building Code:	R2900105220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$212,295
Building Name:	Walker Cold Storage	**Address:**	07316 MN HWY 371 NW	**Deferred Maintenance:**	$21,229
Facility Condition Index:	0.10 - Good	**City Code:**	WALKER	**Ext. Gross Area:**	2,340

Site: R290171 - Longville Fire Tower

Building Code:	R2900305600	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,101
Building Name:	Longville Fire Tower	**Address:**	LONGVILLE	**Deferred Maintenance:**	$2,673
Facility Condition Index:	0.33 - Poor	**City Code:**	BRAINERD	**Ext. Gross Area:**	64

Site: R290172 - Linder Fire Tower

Building Code:	R2900105680	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,602
Building Name:	Linder Fire Tower	**Address:**	LINDER	**Deferred Maintenance:**	$2,839
Facility Condition Index:	0.33 - Poor	**City Code:**	GRYGLA	**Ext. Gross Area:**	36

Site: R290173 - Lawson Fire Tower

Building Code:	R2900105480	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,602
Building Name:	Lawson Fire Tower	**Address:**	LAWSON	**Deferred Maintenance:**	$2,839
Facility Condition Index:	0.33 - Poor	**City Code:**	WANNASKA	**Ext. Gross Area:**	64

Site: R290174 - Prosper Fire Tower

Building Code:	R2900105560	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,976
Building Name:	Prosper Fire Tower	**Address:**	PROSPER	**Deferred Maintenance:**	$2,962
Facility Condition Index:	0.33 - Poor	**City Code:**	WILLIAMS	**Ext. Gross Area:**	36

Site: R290175 - Moose Lake City

Building Code:	R2900300300	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$525,322
Building Name:	Moose Lake City Shop	**Address:**	701 S KENWOOD	**Deferred Maintenance:**	$149,573
Facility Condition Index:	0.28 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	2,952
Building Code:	R2900300310	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$628,238
Building Name:	Moose Lake City Office	**Address:**	701 S KENWOOD	**Deferred Maintenance:**	$136,231
Facility Condition Index:	0.22 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	4,386
Building Code:	R2900304130	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$11,271
Building Name:	Moose Lake City Oil House	**Address:**	701 S KENWOOD	**Deferred Maintenance:**	$1,353
Facility Condition Index:	0.12 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	36
Building Code:	R2900304580	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,802
Building Name:	Moose Lake City Oil House	**Address:**	701 S KENWOOD	**Deferred Maintenance:**	$3,063
Facility Condition Index:	0.11 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	160

Site: R290176 - Waskish

Building Code:	R2900101030	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$480,898
Building Name:	Waskish Fish Hatchery	**Address:**	55478 TAMARAC RIVER ACCESS	**Deferred Maintenance:**	$102,263
Facility Condition Index:	0.21 - Fair	**City Code:**	WASKISH	**Ext. Gross Area:**	3,672
Building Code:	R2900101040	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$302,066
Building Name:	Waskish Garage	**Address:**	55478 TAMARAC RIVER ACCESS	**Deferred Maintenance:**	$70,939
Facility Condition Index:	0.23 - Fair	**City Code:**	WASKISH	**Ext. Gross Area:**	3,060

Building Code: R2900101070
Building Name: Waskish Cold Storage
Facility Condition Index: 0.27 - Fair

Cost Model Name: Utility Shed
Address: 55478 TAMARAC RIVER ACCESS
City Code: WASKISH

Current Replacement Value: $25,889
Deferred Maintenance: $7,109
Ext. Gross Area: 192

Site: R290177 - Bemidji-Beltrami County Airport

Building Code: R2900104510
Building Name: Bemidji Airport Cold Storage
Facility Condition Index: 0.24 - Fair

Cost Model Name: Utility Shed
Address: 2823 GILLETT DR NW
City Code: BEMIDJI

Current Replacement Value: $15,109
Deferred Maintenance: $3,700
Ext. Gross Area: 96

Building Code: R2900106180
Building Name: Bemidji Airport Office
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-story Office/Public Access Facility
Address: 3219 GILLETT NW
City Code: BEMIDJI

Current Replacement Value: $533,804
Deferred Maintenance: $53,380
Ext. Gross Area: 2,400

Building Code: R2900106560
Building Name: Bemidji Airport Cold Storage
Facility Condition Index: 0.29 - Fair

Cost Model Name: Utility Shed
Address: 2823 GILLETT DR NW
City Code: BEMIDJI

Current Replacement Value: $18,756
Deferred Maintenance: $5,353
Ext. Gross Area: 195

Building Code: R2900108590
Building Name: Bemidji Airport Cold Storage
Facility Condition Index: 0.21 - Fair

Cost Model Name: Utility Shed
Address: 2823 GILLETT DR NW
City Code: BEMIDJI

Current Replacement Value: $18,905
Deferred Maintenance: $4,064
Ext. Gross Area: 122

Building Code: R2900109500
Building Name: Bemidji Airport Cold Storage Shed
Facility Condition Index: 0.02 - Excellent

Cost Model Name: Utility Shed
Address: 2823 GILLETT DR NW
City Code: BEMIDJI

Current Replacement Value: $60,515
Deferred Maintenance: $1,210
Ext. Gross Area: 320

Site: R290178 - Mora

Building Code: R2900300340
Building Name: Mora Office
Facility Condition Index: 0.25 - Fair

Cost Model Name: Single-story Work Facility
Address: 460 W MAPLE
City Code: MORA

Current Replacement Value: $350,217
Deferred Maintenance: $86,399
Ext. Gross Area: 1,800

Building Code: R2900300350
Building Name: Mora Cold Storage
Facility Condition Index: 0.28 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 460 W MAPLE
City Code: MORA

Current Replacement Value: $164,001
Deferred Maintenance: $46,728
Ext. Gross Area: 1,800

Building Code: R2900304190
Building Name: Mora Oil House
Facility Condition Index: 0.15 - Fair

Cost Model Name: Utility Shed
Address: 460 W MAPLE
City Code: MORA

Current Replacement Value: $16,417
Deferred Maintenance: $2,493
Ext. Gross Area: 96

Site: R290179 - Big Falls

Building Code: R2900202770
Building Name: Big Falls Cold Storage
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-story Work Facility
Address: 7754 TOWN RD 293
City Code: BIG FALLS

Current Replacement Value: $217,864
Deferred Maintenance: $21,431
Ext. Gross Area: 2,309

Building Code: R2900202780
Building Name: Big Falls Garage
Facility Condition Index: 0.06 - Good

Cost Model Name: Single-story Work Facility
Address: 7754 TOWN RD 293
City Code: BIG FALLS

Current Replacement Value: $25,952
Deferred Maintenance: $1,553
Ext. Gross Area: 600

Building Code: R2900202800
Building Name: Big Falls Cold Storage
Facility Condition Index: 0.21 - Fair

Cost Model Name: Single-story Work Facility
Address: 7754 TOWN RD 293
City Code: BIG FALLS

Current Replacement Value: $295,437
Deferred Maintenance: $63,316
Ext. Gross Area: 1,747

Building Code: R2900202810
Building Name: Big Falls Office
Facility Condition Index: 0.22 - Fair

Cost Model Name: Single-story Office/Public Access Facility
Address: 7754 TOWN RD 293
City Code: BIG FALLS

Current Replacement Value: $372,411
Deferred Maintenance: $81,387
Ext. Gross Area: 1,651

Building Code: R2900203790
Building Name: Big Falls Oil House
Facility Condition Index: 0.27 - Fair

Cost Model Name: Utility Shed
Address: 7754 TOWN RD 293
City Code: BIG FALLS

Current Replacement Value: $12,102
Deferred Maintenance: $3,260
Ext. Gross Area: 96

Building Code: R2900209490
Building Name: Big Falls Vault Toilet
Facility Condition Index: 0.72 - Crisis

Cost Model Name: Vault Toilet
Address: 7754 TOWN RD 293
City Code: BIG FALLS

Current Replacement Value: $3,129
Deferred Maintenance: $2,247
Ext. Gross Area: 17

Site: R290180 - Big Fork River

Building Code: R2900206450
Building Name: Big Fork R Johnson's Lnd Vault Toil
Facility Condition Index: 0.26 - Fair

Cost Model Name: Vault Toilet
Address: CO RD VT 83
City Code: BIG FALLS

Current Replacement Value: $11,111
Deferred Maintenance: $2,848
Ext. Gross Area: 30

Building Code: R2900206460
Building Name: Big Fork R Sturgeon R Vault Toilet
Facility Condition Index: 0.16 - Fair

Cost Model Name: Vault Toilet
Address: STATE FOREST RD 0852
City Code: BIG FALLS

Current Replacement Value: $11,111
Deferred Maintenance: $1,747
Ext. Gross Area: 30

Building Code: R2900206470
Building Name: Big Fork R Benn Lynn Vault Toilet
Facility Condition Index: 0.16 - Fair

Cost Model Name: Vault Toilet
Address: STATE FOREST RD 0948
City Code: BIG FALLS

Current Replacement Value: $11,111
Deferred Maintenance: $1,747
Ext. Gross Area: 30

Site: R290181 - Cloquet

Building Code: R2900200080
Building Name: Cloquet Wildlife Cold Storage
Facility Condition Index: 0.08 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1604 S HWY 33
City Code: CLOQUET

Current Replacement Value: $381,728
Deferred Maintenance: $28,930
Ext. Gross Area: 2,232

Building Code: R2900202510
Building Name: Cloquet Office
Facility Condition Index: 0.23 - Fair

Cost Model Name: Single-story Office/Public Access Facility
Address: 1604 S HWY 33
City Code: CLOQUET

Current Replacement Value: $847,508
Deferred Maintenance: $195,918
Ext. Gross Area: 3,600

Building Code:	R2900202520	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$448,494
Building Name:	Cloquet Shop	**Address:**	1604 S HWY 33	**Deferred Maintenance:**	$97,846
Facility Condition Index:	0.22 - Fair	**City Code:**	CLOQUET	**Ext. Gross Area:**	2,428
Building Code:	R2900202530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$130,587
Building Name:	Cloquet Cold Storage	**Address:**	1604 S HWY 33	**Deferred Maintenance:**	$66,264
Facility Condition Index:	0.51 - Crisis	**City Code:**	CLOQUET	**Ext. Gross Area:**	1,223
Building Code:	R2900202540	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,805
Building Name:	Cloquet Oil House	**Address:**	1604 S HWY 33	**Deferred Maintenance:**	$12,898
Facility Condition Index:	0.33 - Poor	**City Code:**	CLOQUET	**Ext. Gross Area:**	168
Building Code:	R2900206920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$184,264
Building Name:	Cloquet STS Cold Storage	**Address:**	1604 S HWY 33	**Deferred Maintenance:**	$38,669
Facility Condition Index:	0.21 - Fair	**City Code:**	CLOQUET	**Ext. Gross Area:**	1,753
Building Code:	R2900210170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,764
Building Name:	Cloquet Sign Storage	**Address:**	1604 S HWY 33	**Deferred Maintenance:**	$6,812
Facility Condition Index:	0.49 - Poor	**City Code:**	CLOQUET	**Ext. Gross Area:**	87
Building Code:	R2900210180	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$18,772
Building Name:	Cloquet Smoking Shelter	**Address:**	1604 S HWY 33	**Deferred Maintenance:**	$1,877
Facility Condition Index:	0.10 - Good	**City Code:**	CLOQUET	**Ext. Gross Area:**	230

Site: R290182 - Effie

Building Code:	R2900201730	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$299,242
Building Name:	Effie East Garage Cold Storage	**Address:**	205 1/2 SE HWY 1	**Deferred Maintenance:**	$28,861
Facility Condition Index:	0.10 - Good	**City Code:**	EFFIE	**Ext. Gross Area:**	2,016
Building Code:	R2900201830	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$435,198
Building Name:	Effie Main Office	**Address:**	205 1/2 SE HWY 1	**Deferred Maintenance:**	$86,951
Facility Condition Index:	0.20 - Fair	**City Code:**	EFFIE	**Ext. Gross Area:**	2,197
Building Code:	R2900201840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,979
Building Name:	Effie Oil House	**Address:**	205 1/2 SE HWY 1	**Deferred Maintenance:**	$2,437
Facility Condition Index:	0.08 - Good	**City Code:**	EFFIE	**Ext. Gross Area:**	168
Building Code:	R2900201850	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$45,677
Building Name:	Effie South Garage	**Address:**	205 1/2 SE HWY 1	**Deferred Maintenance:**	$23,888
Facility Condition Index:	0.52 - Crisis	**City Code:**	EFFIE	**Ext. Gross Area:**	576
Building Code:	R2900201870	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$228,784
Building Name:	Effie West Garage Shop	**Address:**	205 1/2 SE HWY 1	**Deferred Maintenance:**	$51,256
Facility Condition Index:	0.22 - Fair	**City Code:**	EFFIE	**Ext. Gross Area:**	1,920

Building Code:	R2900207510	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$116,091
Building Name:	Effie Modular Office	**Address:**	205 1/2 SE HWY 1	**Deferred Maintenance:**	$13,033
Facility Condition Index:	0.11 - Good	**City Code:**	EFFIE	**Ext. Gross Area:**	588

Site: R290183 - Madelia WMA

Building Code:	R2900402400	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$266,588
Building Name:	Madelia WMA Cold Storage Barn	**Address:**	35365 800TH AVE	**Deferred Maintenance:**	$73,181
Facility Condition Index:	0.27 - Fair	**City Code:**	MADELIA	**Ext. Gross Area:**	1,920
Building Code:	R2900402410	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$1,766,184
Building Name:	Madelia WMA Office	**Address:**	35365 800TH AVE	**Deferred Maintenance:**	$282,363
Facility Condition Index:	0.16 - Fair	**City Code:**	MADELIA	**Ext. Gross Area:**	9,653
Building Code:	R2900402430	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$321,078
Building Name:	Madelia WMA Cold Storage	**Address:**	35365 800TH AVE	**Deferred Maintenance:**	$112,750
Facility Condition Index:	0.35 - Poor	**City Code:**	MADELIA	**Ext. Gross Area:**	2,160
Building Code:	R2900402480	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,997
Building Name:	Madelia WMA Cold Storage by Barn	**Address:**	35365 800TH AVE	**Deferred Maintenance:**	$13,741
Facility Condition Index:	0.35 - Poor	**City Code:**	MADELIA	**Ext. Gross Area:**	160

Site: R290184 - Mille Lacs WMA

Building Code:	R2900300650	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$184,027
Building Name:	Mille Lacs WMA Cold Storage Barn	**Address:**	29172 100TH AVE	**Deferred Maintenance:**	$129,321
Facility Condition Index:	0.70 - Crisis	**City Code:**	ONAMIA	**Ext. Gross Area:**	2,010
Building Code:	R2900300670	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$820,437
Building Name:	Mille Lacs WMA Office/Shop	**Address:**	29172 100TH AVE	**Deferred Maintenance:**	$233,930
Facility Condition Index:	0.29 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	4,502
Building Code:	R2900300700	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$230,030
Building Name:	Mille Lacs WMA Cold Storage	**Address:**	29172 100TH AVE	**Deferred Maintenance:**	$143,285
Facility Condition Index:	0.62 - Crisis	**City Code:**	ONAMIA	**Ext. Gross Area:**	2,312

Site: R290185 - New London

Building Code:	R2900404630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$829,535
Building Name:	New London Office	**Address:**	500 1st Ave NW, Box 508	**Deferred Maintenance:**	$117,347
Facility Condition Index:	0.14 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	4,704

Site: R290186 - Woodland WMA

Building Code:	R2900300770	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$272,983
Building Name:	Woodland WMA Montrose Shop	**Address:**	7372 STATE HWY 25 SW	**Deferred Maintenance:**	$135,619
Facility Condition Index:	0.50 - Poor	**City Code:**	MONTROSE	**Ext. Gross Area:**	2,400
Building Code:	R2900300790	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$281,241
Building Name:	Woodland WMA Montrose Cold Storage	**Address:**	7372 STATE HWY 25 SW	**Deferred Maintenance:**	$103,934
Facility Condition Index:	0.37 - Poor	**City Code:**	MONTROSE	**Ext. Gross Area:**	3,000
Building Code:	R2900300800	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$202,780
Building Name:	Woodland WMA Montrose Office	**Address:**	7372 STATE HWY 25 SW	**Deferred Maintenance:**	$71,585
Facility Condition Index:	0.35 - Poor	**City Code:**	MONTROSE	**Ext. Gross Area:**	1,200
Building Code:	R2900303200	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$63,843
Building Name:	Woodland WMA Montrose Shed	**Address:**	7372 STATE HWY 25 SW	**Deferred Maintenance:**	$40,033
Facility Condition Index:	0.63 - Crisis	**City Code:**	MONTROSE	**Ext. Gross Area:**	1,440
Building Code:	R2900303580	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$31,304
Building Name:	Woodland WMA Montrose Pump House	**Address:**	7372 STATE HWY 25 SW	**Deferred Maintenance:**	$16,322
Facility Condition Index:	0.52 - Crisis	**City Code:**	MONTROSE	**Ext. Gross Area:**	160
Building Code:	R2900304140	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,702
Building Name:	Woodland WMA Montrose Oil House	**Address:**	7372 STATE HWY 25 SW	**Deferred Maintenance:**	$4,402
Facility Condition Index:	0.24 - Fair	**City Code:**	MONTROSE	**Ext. Gross Area:**	96

Site: R290187 - Nickerson

Building Code:	R2900300330	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$369,568
Building Name:	Nickerson Cold Storage	**Address:**	701 S KENWOOD RR 2	**Deferred Maintenance:**	$210,479
Facility Condition Index:	0.57 - Crisis	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	2,064
Building Code:	R2900305570	**Cost Model Name:**	Tower	**Current Replacement Value:**	$10,739
Building Name:	Nickerson Fire Tower	**Address:**	701 S KENWOOD RR 2	**Deferred Maintenance:**	$7,615
Facility Condition Index:	0.71 - Crisis	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	64

Site: R290188 - Nicollet

Building Code:	R2900404450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$455,335
Building Name:	Nicollet Cold Storage	**Address:**	501 9TH ST	**Deferred Maintenance:**	$180,296
Facility Condition Index:	0.40 - Poor	**City Code:**	NICOLLET	**Ext. Gross Area:**	3,212

Site: R290189 - Ortonville

Building Code:	R2900405470	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$20,618
Building Name:	Ortonville Shed	**Address:**	811 PINE AVE	**Deferred Maintenance:**	$412
Facility Condition Index:	0.02 - Excellent	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	160

Site: R290190 - Orr

Building Code:	R2900202870	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$392,619
Building Name:	Orr Main Office	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$95,210
Facility Condition Index:	0.24 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	2,429
Building Code:	R2900202880	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$117,666
Building Name:	Orr 1-Stall FOR Garage	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$28,213
Facility Condition Index:	0.24 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	1,202
Building Code:	R2900202890	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,822
Building Name:	Orr Oil House	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$5,224
Facility Condition Index:	0.28 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	120
Building Code:	R2900202900	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$170,348
Building Name:	Orr Shop	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$18,016
Facility Condition Index:	0.11 - Good	**City Code:**	ORR	**Ext. Gross Area:**	1,040
Building Code:	R2900202910	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,762
Building Name:	Orr Pine Cone Storage	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$5,814
Facility Condition Index:	0.42 - Poor	**City Code:**	ORR	**Ext. Gross Area:**	120
Building Code:	R2900202930	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,169
Building Name:	Orr 1-Stall FOR Garage	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$13,631
Facility Condition Index:	0.28 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	576
Building Code:	R2900202940	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$385,731
Building Name:	Orr 5-Stall Garage	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$67,033
Facility Condition Index:	0.17 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	1,920
Building Code:	R2900202950	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$378,868
Building Name:	Orr Hilltop Office	**Address:**	4656 HWY 53	**Deferred Maintenance:**	$66,497
Facility Condition Index:	0.18 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	2,121
Building Code:	R2900203340	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$53,423
Building Name:	Orr 2-Stall Garage	**Address:**		**Deferred Maintenance:**	$4,518
Facility Condition Index:	0.08 - Good	**City Code:**	ORR	**Ext. Gross Area:**	624
Building Code:	R2900204260	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$12,886
Building Name:	Orr 1-Stall ENF Garage	**Address:**		**Deferred Maintenance:**	$2,245
Facility Condition Index:	0.17 - Fair	**City Code:**	ORR	**Ext. Gross Area:**	264

Site: R290191 - Pelican Lake

Building Code:	R2900305220	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$52,850
Building Name:	Pelican Lake Beach Day-Use Area San	**Address:**	30483 STATE HWY 371	**Deferred Maintenance:**	$11,601
Facility Condition Index:	0.22 - Fair	**City Code:**	PEQUOT LAKES	**Ext. Gross Area:**	288

Site: R290194 - Peterson Hatchery

Building Code:	R2900502160	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$1,579,142
Building Name:	Peterson Hatchery Office/Residence	**Address:**	28376 COUNTY RD 25 S	**Deferred Maintenance:**	$269,786
Facility Condition Index:	0.17 - Fair	**City Code:**	PETERSON	**Ext. Gross Area:**	7,347
Building Code:	R2900502170	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$322,311
Building Name:	Peterson Hatchery Shop	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$54,209
Facility Condition Index:	0.17 - Fair	**City Code:**	PETERSON	**Ext. Gross Area:**	2,496
Building Code:	R2900502200	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$137,660
Building Name:	Peterson Hatchery Raceway Shel W1-3	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$18,656
Facility Condition Index:	0.14 - Good	**City Code:**	PETERSON	**Ext. Gross Area:**	1,280
Building Code:	R2900502210	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$276,962
Building Name:	Peterson Hatchery Raceway Shel W8-9	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$24,448
Facility Condition Index:	0.09 - Good	**City Code:**	PETERSON	**Ext. Gross Area:**	2,560
Building Code:	R2900502250	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$65,462
Building Name:	Peterson Hatchery Cold Storage W7	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$5,917
Facility Condition Index:	0.09 - Good	**City Code:**	PETERSON	**Ext. Gross Area:**	704
Building Code:	R2900504050	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$12,416
Building Name:	Peterson Hatchery Raceway Shel 20-1	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,312
Facility Condition Index:	0.75 - Crisis	**City Code:**	PETERSON	**Ext. Gross Area:**	314
Building Code:	R2900504060	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$12,416
Building Name:	Peterson Hatchery Raceway Shel 20-2	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,312
Facility Condition Index:	0.75 - Crisis	**City Code:**	PETERSON	**Ext. Gross Area:**	314
Building Code:	R2900504070	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$12,416
Building Name:	Peterson Hatchery Raceway Shel 20-3	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,312
Facility Condition Index:	0.75 - Crisis	**City Code:**	PETERSON	**Ext. Gross Area:**	314
Building Code:	R2900504080	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$12,416
Building Name:	Peterson Hatchery Raceway Shel 20-4	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,312
Facility Condition Index:	0.75 - Crisis	**City Code:**	PETERSON	**Ext. Gross Area:**	314
Building Code:	R2900504090	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$12,416
Building Name:	Peterson Hatchery Raceway Shel 20-5	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,312
Facility Condition Index:	0.75 - Crisis	**City Code:**	PETERSON	**Ext. Gross Area:**	314
Building Code:	R2900504100	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$12,416
Building Name:	Peterson Hatchery Raceway Shel 20-6	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,312
Facility Condition Index:	0.75 - Crisis	**City Code:**	PETERSON	**Ext. Gross Area:**	314

Building Code:	R2900504110	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatch Raceway Shel 30-1-3	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900504120	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatch Raceway Shel 30-4-6	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900504130	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 7	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	2,421
Building Code:	R2900504760	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,238,440
Building Name:	Peterson Main Fish Hatchery	**Address:**	28376 COUNTY RD 25 S	**Deferred Maintenance:**	$82,099
Facility Condition Index:	0.07 - Good	**City Code:**	PETERSON	**Ext. Gross Area:**	5,513
Building Code:	R2900505080	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$54,330
Building Name:	Peterson Hatchery Vault Concrete	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$5,433
Facility Condition Index:	0.10 - Good	**City Code:**	PETERSON	**Ext. Gross Area:**	100
Building Code:	R2900505300	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 2	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900505310	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 5	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900505320	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 8	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900505330	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 3	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900505340	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 6	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900505350	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$27,917
Building Name:	Peterson Hatchery Raceway Shelter 9	**Address:**	28376 CO RD S	**Deferred Maintenance:**	$9,213
Facility Condition Index:	0.33 - Poor	**City Code:**	PETERSON	**Ext. Gross Area:**	706
Building Code:	R2900505840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$14,237
Building Name:	Peterson Hatchery Shed	**Address:**	28376 CO HWY 25	**Deferred Maintenance:**	$285
Facility Condition Index:	0.02 - Excellent	**City Code:**	RUSHFORD VILLAGE	**Ext. Gross Area:**	128

Site: R290196 - Grand Rapids Resource Assessment

Building Code:	R2900207560	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$3,879,801
Building Name:	Grand Rapids Res Assesmt Office	**Address:**	483 PETERSON RD	**Deferred Maintenance:**	$441,301
Facility Condition Index:	0.11 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	19,340
Building Code:	R2900208340	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$73,760
Building Name:	Grand Rapids Res Asses Cold Storage	**Address:**	483 PETERSON RD	**Deferred Maintenance:**	$5,542
Facility Condition Index:	0.08 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	847

Site: R290197 - R4 HQ New Ulm

Building Code:	R2900400010	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,874,547
Building Name:	New Ulm R4 HQ Office	**Address:**	21371 STATE HWY 15	**Deferred Maintenance:**	$1,066,038
Facility Condition Index:	0.22 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	16,550
Building Code:	R2900402980	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,090,999
Building Name:	New Ulm R4 HQ Shop	**Address:**	21371 STATE HWY 15	**Deferred Maintenance:**	$232,678
Facility Condition Index:	0.21 - Fair	**City Code:**	NEW ULM	**Ext. Gross Area:**	5,808
Building Code:	R2900402990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$289,600
Building Name:	New Ulm R4 HQ Cold Storage	**Address:**	21371 STATE HWY 15	**Deferred Maintenance:**	$88,923
Facility Condition Index:	0.31 - Poor	**City Code:**	NEW ULM	**Ext. Gross Area:**	2,728
Building Code:	R2900403780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$131,964
Building Name:	New Ulm R4 HQ HazMat Storage	**Address:**	21371 STATE HWY 15	**Deferred Maintenance:**	$87,276
Facility Condition Index:	0.66 - Crisis	**City Code:**	NEW ULM	**Ext. Gross Area:**	209

Site: R290200 - Rochester

Building Code:	R2900500010	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$2,297,342
Building Name:	Rochester Shop	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$1,089,838
Facility Condition Index:	0.47 - Poor	**City Code:**	ROCHESTER	**Ext. Gross Area:**	8,890
Building Code:	R2900500080	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$238,039
Building Name:	Rochester Heated Storage Barn	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$70,326
Facility Condition Index:	0.30 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	1,128
Building Code:	R2900502050	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$506,119
Building Name:	Rochester Cold Storage	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$108,633
Facility Condition Index:	0.21 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	5,225
Building Code:	R2900504740	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$9,837
Building Name:	Rochester Cave Shed	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$3,246
Facility Condition Index:	0.33 - Poor	**City Code:**	ROCHESTER	**Ext. Gross Area:**	108

Building Code:	R2900505550	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$64,085
Building Name:	Rochester HazMat Storage	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$1,282
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	207

Site: R290202 - Savanna State Forest

Building Code:	R2900303890	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$274,629
Building Name:	Savanna SF Sandy Lake Shop	**Address:**	49928 LAKE AVENUE	**Deferred Maintenance:**	$56,549
Facility Condition Index:	0.21 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	1,860
Building Code:	R2900303900	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$399,653
Building Name:	Savanna SF Sandy Lake Office	**Address:**	49928 LAKE AVENUE	**Deferred Maintenance:**	$126,627
Facility Condition Index:	0.32 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	2,236
Building Code:	R2900303920	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,488
Building Name:	Savanna SF Sandy Lake Shed	**Address:**	49928 LAKE AVENUE	**Deferred Maintenance:**	$3,461
Facility Condition Index:	0.33 - Poor	**City Code:**	MCGREGOR	**Ext. Gross Area:**	92
Building Code:	R2900304010	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,339
Building Name:	Savanna SF Sandy Lake Oil House	**Address:**	49928 LAKE AVENUE	**Deferred Maintenance:**	$589
Facility Condition Index:	0.05 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	96
Building Code:	R2900305120	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$151,036
Building Name:	Savanna SF Sandy Lake Cold Storage	**Address:**	49928 LAKE AVENUE	**Deferred Maintenance:**	$5,427
Facility Condition Index:	0.04 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	1,764
Building Code:	R2900305540	**Cost Model Name:**	Tower	**Current Replacement Value:**	$21,283
Building Name:	Savanna SF Sandy Lake Fire Tower	**Address:**	49928 LAKE AVENUE	**Deferred Maintenance:**	$2,128
Facility Condition Index:	0.10 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	64
Building Code:	R2900308450	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,713
Building Name:	Savanna SF Hay Lk CG M Vault Concr	**Address:**	64893 170TH PLACE	**Deferred Maintenance:**	$354
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	33
Building Code:	R2900308460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,713
Building Name:	Savanna SF Hay Lk CG W Vault Concr	**Address:**	64893 170TH PLACE	**Deferred Maintenance:**	$354
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	33
Building Code:	R2900308470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,176
Building Name:	Savanna SF Hay Lk CG S4 Vault Concr	**Address:**	64893 170TH PLACE	**Deferred Maintenance:**	$344
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	32
Building Code:	R2900308480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$17,713
Building Name:	Savanna SF HayLk CG S14 Vault Concr	**Address:**	64893 170TH PLACE	**Deferred Maintenance:**	$354
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	33

Site: R290204 - Side Lake

Building Code:	R2900201640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$458,063
Building Name:	Side Lake Shop	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$105,964
Facility Condition Index:	0.23 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	2,366
Building Code:	R2900201650	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$572,778
Building Name:	Side Lake Office	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$148,459
Facility Condition Index:	0.26 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	2,427
Building Code:	R2900201660	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$313,419
Building Name:	Side Lake Shed	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$87,734
Facility Condition Index:	0.28 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	1,320
Building Code:	R2900201670	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,051
Building Name:	Side Lake Garage	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$25,330
Facility Condition Index:	0.24 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	864
Building Code:	R2900201680	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,535
Building Name:	Side Lake Cold Storage	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$8,675
Facility Condition Index:	0.25 - Fair	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	384
Building Code:	R2900201690	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,317
Building Name:	Side Lake Oil House	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$2,332
Facility Condition Index:	0.10 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	120
Building Code:	R2900204230	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,952
Building Name:	Side Lake Radio Shelter	**Address:**	7711 HWY %	**Deferred Maintenance:**	$2,038
Facility Condition Index:	0.41 - Poor	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	16
Building Code:	R2900207200	**Cost Model Name:**	Tower	**Current Replacement Value:**	$19,281
Building Name:	Side Lake Fire Tower	**Address:**	7711 HWY 5	**Deferred Maintenance:**	$1,928
Facility Condition Index:	0.10 - Good	**City Code:**	SIDE LAKE	**Ext. Gross Area:**	64

Site: R290206 - Albion WMA

Building Code:	R2900307590	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$129,027
Building Name:	Albion WMA Quonset	**Address:**	940 INDUSTRIAL DR S #103	**Deferred Maintenance:**	$78,969
Facility Condition Index:	0.61 - Crisis	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	2,100

Site: R290207 - Talcot Lake WMA

Building Code:	R2900402260	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$580,467
Building Name:	Talcot Lake WMA Dormitory	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$166,635
Facility Condition Index:	0.29 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	2,660

Building Code:	R2900402330	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$403,477
Building Name:	Talcot Lake WMA Office	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$117,322
Facility Condition Index:	0.29 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	2,366
Building Code:	R2900402340	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,037
Building Name:	Talcot Lake WMA Cold Storage	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$3,791
Facility Condition Index:	0.31 - Poor	**City Code:**	DUNDEE	**Ext. Gross Area:**	64
Building Code:	R2900402350	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$256,080
Building Name:	Talcot Lake WMA Shop	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$75,761
Facility Condition Index:	0.30 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	1,680
Building Code:	R2900402390	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$123,635
Building Name:	Talcot Lake WMA In-Ground Cold Stor	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$40,800
Facility Condition Index:	0.33 - Poor	**City Code:**	DUNDEE	**Ext. Gross Area:**	640
Building Code:	R2900402750	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$20,011
Building Name:	Talcot Lake WMA Trailer Cold Stor	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$6,604
Facility Condition Index:	0.33 - Poor	**City Code:**	DUNDEE	**Ext. Gross Area:**	320
Building Code:	R2900402760	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$15,835
Building Name:	Talcot Lake WMA 1-Stall Cold Stor	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$4,382
Facility Condition Index:	0.28 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	336
Building Code:	R2900403080	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$25,247
Building Name:	Talcot Lake WMA Garage	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$2,525
Facility Condition Index:	0.10 - Good	**City Code:**	DUNDEE	**Ext. Gross Area:**	384
Building Code:	R2900403090	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$283,961
Building Name:	Talcot Lake WMA Cold Storage	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$93,707
Facility Condition Index:	0.33 - Poor	**City Code:**	DUNDEE	**Ext. Gross Area:**	2,400
Building Code:	R2900404010	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$334,509
Building Name:	Talcot Lake WMA Cold Storage	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$110,388
Facility Condition Index:	0.33 - Poor	**City Code:**	DUNDEE	**Ext. Gross Area:**	3,600
Building Code:	R2900404210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$8,043
Building Name:	Talcot Lake WMA Vault Toilet	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$1,827
Facility Condition Index:	0.23 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	24
Building Code:	R2900404460	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$130,185
Building Name:	Talcot Lake WMA Cold Storage	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$2,604
Facility Condition Index:	0.02 - Excellent	**City Code:**	DUNDEE	**Ext. Gross Area:**	1,728
Building Code:	R2900404530	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$247,887
Building Name:	Talcot Lake WMA Bennett Shed	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$33,238
Facility Condition Index:	0.13 - Good	**City Code:**	DUNDEE	**Ext. Gross Area:**	2,400

Building Code:	R2900404540	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$267,607
Building Name:	Talcot Lake WMA HQ Shed	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$5,352
Facility Condition Index:	0.02 - Excellent	**City Code:**	DUNDEE	**Ext. Gross Area:**	2,880
Building Code:	R2900405040	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,379
Building Name:	Talcot Lake WMA Shed	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$3,184
Facility Condition Index:	0.18 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	160
Building Code:	R2900405050	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,803
Building Name:	Talcot Lake WMA Shed	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$5,973
Facility Condition Index:	0.21 - Fair	**City Code:**	DUNDEE	**Ext. Gross Area:**	192
Building Code:	R2900405060	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,342
Building Name:	Talcot Lake WMA Granary Storage	**Address:**	40249 CO RD 7	**Deferred Maintenance:**	$4,073
Facility Condition Index:	0.33 - Poor	**City Code:**	DUNDEE	**Ext. Gross Area:**	155

Site: R290208 - Tower

Building Code:	R2900207720	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,416,313
Building Name:	Tower Office	**Address:**	650 HWY 169	**Deferred Maintenance:**	$190,647
Facility Condition Index:	0.08 - Good	**City Code:**	TOWER	**Ext. Gross Area:**	10,590
Building Code:	R2900207730	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$2,361,415
Building Name:	Tower Heated Storage	**Address:**	650 HWY 169	**Deferred Maintenance:**	$97,999
Facility Condition Index:	0.04 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	10,430
Building Code:	R2900207740	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$785,340
Building Name:	Tower Cold Storage Bldg A	**Address:**	650 HWY 169	**Deferred Maintenance:**	$21,043
Facility Condition Index:	0.03 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	7,794
Building Code:	R2900207750	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$745,875
Building Name:	Tower Cold Storage Bldg B	**Address:**	650 HWY 169	**Deferred Maintenance:**	$26,619
Facility Condition Index:	0.04 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	7,378
Building Code:	R2900207760	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,290
Building Name:	Tower HazMat Storage	**Address:**	650 HWY 169	**Deferred Maintenance:**	$2,729
Facility Condition Index:	0.10 - Good	**City Code:**	TOWER	**Ext. Gross Area:**	120
Building Code:	R2900208560	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$68,107
Building Name:	Tower Refrigerated Storage	**Address:**	650 HWY 169	**Deferred Maintenance:**	$6,811
Facility Condition Index:	0.10 - Good	**City Code:**	TOWER	**Ext. Gross Area:**	186
Building Code:	R2900208820	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$30,098
Building Name:	Tower Recycling Shed	**Address:**	650 HWY 169	**Deferred Maintenance:**	$711
Facility Condition Index:	0.02 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	140

Building Code:	R2900210360	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$54,362
Building Name:	Tower Wood Pellet Boiler Enclosure	**Address:**	650 HWY 169	**Deferred Maintenance:**	$1,087
Facility Condition Index:	0.02 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	250
Building Code:	R2900210370	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,003
Building Name:	Tower Wood Pellet Storage	**Address:**	650 HWY 169	**Deferred Maintenance:**	$500
Facility Condition Index:	0.02 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	196

Site: R290209 - Pike River Hatchery

Building Code:	R2900203620	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$552,895
Building Name:	Pike River Fish Hatchery	**Address:**	9380 ANGUS RD VERMILION LK T	**Deferred Maintenance:**	$84,234
Facility Condition Index:	0.15 - Fair	**City Code:**	TOWER	**Ext. Gross Area:**	3,037
Building Code:	R2900203730	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,758
Building Name:	Pike River Hatchery Ice House	**Address:**	9380 ANGUS RD VERMILION LK T	**Deferred Maintenance:**	$3,849
Facility Condition Index:	0.28 - Fair	**City Code:**	TOWER	**Ext. Gross Area:**	98
Building Code:	R2900208190	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$10,905
Building Name:	Pike River Hatchery Vault Toilet	**Address:**	9380 ANGUS RD VERMILION LK T	**Deferred Maintenance:**	$2,465
Facility Condition Index:	0.23 - Fair	**City Code:**	TOWER	**Ext. Gross Area:**	30
Building Code:	R2900208460	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$55,973
Building Name:	Pike River Hatchery Cold Storage	**Address:**	9380 ANGUS RD VERMILION LK T	**Deferred Maintenance:**	$1,435
Facility Condition Index:	0.03 - Excellent	**City Code:**	TOWER	**Ext. Gross Area:**	578

Site: R290211 - Lake Vermilion

Building Code:	R2900203310	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$403,941
Building Name:	Lake Vermillion Cook Boathouse	**Address:**	2505 Pederson Landing	**Deferred Maintenance:**	$260,101
Facility Condition Index:	0.64 - Crisis	**City Code:**	COOK	**Ext. Gross Area:**	1,200
Building Code:	R2900207830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$3,754
Building Name:	Lake Vermillion Peterson Vault	**Address:**	PEDERSON RD	**Deferred Maintenance:**	$2,463
Facility Condition Index:	0.66 - Crisis	**City Code:**	TOWER	**Ext. Gross Area:**	36

Site: R290212 - Jasper Peak Fire Tower

Building Code:	R2900207150	**Cost Model Name:**	Tower	**Current Replacement Value:**	$13,883
Building Name:	Jasper Peak Fire Tower	**Address:**	5080 HWY169	**Deferred Maintenance:**	$4,581
Facility Condition Index:	0.33 - Poor	**City Code:**	TOWER	**Ext. Gross Area:**	64

Site: R290213 - Two Harbors

Building Code:	R2900207060	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$2,035,745
Building Name:	Two Harbors Office	**Address:**	1568 HWY 2	**Deferred Maintenance:**	$288,687
Facility Condition Index:	0.14 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	7,505
Building Code:	R2900207070	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$932,549
Building Name:	Two Harbors Heated Storage	**Address:**	1568 HWY 2	**Deferred Maintenance:**	$132,807
Facility Condition Index:	0.14 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	4,284
Building Code:	R2900207590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,155,542
Building Name:	Two Harbors Cold Storage	**Address:**	1568 HWY 2	**Deferred Maintenance:**	$142,150
Facility Condition Index:	0.12 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	9,296

Site: R290214 - Silver Bay Marina

Building Code:	R2900208240	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$721,823
Building Name:	Silver Bay Marina Interp Center	**Address:**	99 BEACH DR.	**Deferred Maintenance:**	$16,114
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	2,736
Building Code:	R2900208250	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$343,745
Building Name:	Silver Bay Marina Picnic Shelter 2	**Address:**	156 MARINA DRIVE	**Deferred Maintenance:**	$6,875
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	256
Building Code:	R2900208410	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$5,321
Building Name:	Silver Bay Marina Spring House	**Address:**	156 MARINA DRIVE	**Deferred Maintenance:**	$894
Facility Condition Index:	0.17 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	16
Building Code:	R2900208860	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$7,893
Building Name:	Silver Bay Marina Picnic Shelter 1	**Address:**	156 MARINA DRIVE	**Deferred Maintenance:**	$158
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	289
Building Code:	R2900208900	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$43,548
Building Name:	Silver Bay Marina Fish Cleaning Hse	**Address:**	156 MARINA DRIVE	**Deferred Maintenance:**	$871
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	305
Building Code:	R2900210330	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$64,140
Building Name:	Silver Bay Marina Vault Concrete	**Address:**	156 MARINA DRIVE	**Deferred Maintenance:**	$1,283
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	102

Site: R290215 - Knife River Marina

Building Code:	R2900208510	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$446,021
Building Name:	Knife River Marina Shop	**Address:**	115 Marina Road	**Deferred Maintenance:**	$71,809
Facility Condition Index:	0.16 - Fair	**City Code:**	Knife River	**Ext. Gross Area:**	2,800

Building Code: R2900208520
Building Name: Knife River Marina Office
Facility Condition Index: 0.16 - Fair

Cost Model Name: Single-story Office/Public Access Facility
Address: 115 Marina Road
City Code: KNIFE RIVER

Current Replacement Value: $122,680
Deferred Maintenance: $19,545
Ext. Gross Area: 576

Building Code: R2900208530
Building Name: Knife River Marina Sanitation
Facility Condition Index: 0.25 - Fair

Cost Model Name: Single-story Restroom Facility
Address: 115 Marina Road
City Code: KNIFE RIVER

Current Replacement Value: $315,437
Deferred Maintenance: $77,806
Ext. Gross Area: 864

Building Code: R2900208540
Building Name: Knife River Marina Yacht Club Bldg
Facility Condition Index: 0.22 - Fair

Cost Model Name: Single-story Work Facility
Address: 115 Marina Road
City Code: KNIFE RIVER

Current Replacement Value: $100,596
Deferred Maintenance: $21,945
Ext. Gross Area: 660

Site: R290216 - McQuade Road Harbor

Building Code: R2900208910
Building Name: McQuade Road Harbor Sanitation
Facility Condition Index: 0.08 - Good

Cost Model Name: Single-story Restroom Facility
Address: 5107 McQUADE RD
City Code: DULUTH

Current Replacement Value: $263,414
Deferred Maintenance: $20,024
Ext. Gross Area: 640

Building Code: R2900209430
Building Name: McQuade Road Harbor Cold Storage
Facility Condition Index: 0.16 - Fair

Cost Model Name: Single-story Work Facility
Address: 5107 McQUADE RD
City Code: DULUTH

Current Replacement Value: $43,831
Deferred Maintenance: $7,080
Ext. Gross Area: 384

Building Code: R2900210830
Building Name: McQuade Rd Harbor Picnic Shelter
Facility Condition Index: 0.17 - Fair

Cost Model Name: Open Air Shelter
Address: 5107 McQUADE RD
City Code: DULUTH

Current Replacement Value: $75,268
Deferred Maintenance: $12,661
Ext. Gross Area: 0

Site: R290218 - Winona

Building Code: R2900500100
Building Name: Winona Boat House
Facility Condition Index: 0.11 - Good

Cost Model Name: Single-story Work Facility
Address:
City Code: WINONA

Current Replacement Value: $46,706
Deferred Maintenance: $5,220
Ext. Gross Area: 504

Site: R290219 - Wood-Rill SNA

Building Code: R2900601980
Building Name: Wood-Rill SNA Garage
Facility Condition Index: 0.26 - Fair

Cost Model Name: Single-story Work Facility
Address: 845 OLD LONG LAKE RD
City Code: ORONO

Current Replacement Value: $145,951
Deferred Maintenance: $38,515
Ext. Gross Area: 1,440

Site: R290220 - Zimmerman

Building Code: R2900300420
Building Name: Zimmerman Heated Storage
Facility Condition Index: 0.35 - Poor

Cost Model Name: Single-story Work Facility
Address: 12969 FREMONT AVE
City Code: ZIMMERMAN

Current Replacement Value: $273,502
Deferred Maintenance: $96,677
Ext. Gross Area: 1,860

Building Code:	R2900300430	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$474,305
Building Name:	Zimmerman Office	**Address:**	12969 FREMONT AVE	**Deferred Maintenance:**	$275,709
Facility Condition Index:	0.58 - Crisis	**City Code:**	ZIMMERMAN	**Ext. Gross Area:**	2,296
Building Code:	R2900303260	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$137,496
Building Name:	Zimmerman Cold Storage	**Address:**	12969 FREMONT AVE	**Deferred Maintenance:**	$73,332
Facility Condition Index:	0.53 - Crisis	**City Code:**	ZIMMERMAN	**Ext. Gross Area:**	1,260
Building Code:	R2900304080	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,548
Building Name:	Zimmerman Oil House	**Address:**	12969 FREMONT AVE	**Deferred Maintenance:**	$3,563
Facility Condition Index:	0.17 - Fair	**City Code:**	ZIMMERMAN	**Ext. Gross Area:**	128
Building Code:	R2900308510	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$114,051
Building Name:	Zimmerman Fire Truck Storage	**Address:**	12969 FREMONT AVE	**Deferred Maintenance:**	$2,281
Facility Condition Index:	0.02 - Excellent	**City Code:**	ZIMMERMAN	**Ext. Gross Area:**	1,120

Site: R290222 - Douglas State Trail

Building Code:	R2900502460	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,835
Building Name:	Douglas ST Co 4 Vault Concrete	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$14,126
Facility Condition Index:	0.75 - Crisis	**City Code:**	ROCHESTER	**Ext. Gross Area:**	36
Building Code:	R2900502470	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,835
Building Name:	Douglas ST Co 4 Vault Concrete	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$14,126
Facility Condition Index:	0.75 - Crisis	**City Code:**	ROCHESTER	**Ext. Gross Area:**	36
Building Code:	R2900502550	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$13,360
Building Name:	Douglas ST Co 4 Adirondack	**Address:**	2300 SILVER CREEK RD NE	**Deferred Maintenance:**	$2,671
Facility Condition Index:	0.20 - Fair	**City Code:**	ROCHESTER	**Ext. Gross Area:**	126
Building Code:	R2900504590	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$13,360
Building Name:	Douglas ST Pine Island Adirondack	**Address:**		**Deferred Maintenance:**	$2,461
Facility Condition Index:	0.18 - Fair	**City Code:**	PINE ISLAND	**Ext. Gross Area:**	128

Site: R290226 - Park Rapids Fisheries

Building Code:	R2900101000	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$232,283
Building Name:	Park Rapids Fisheries Hatchery	**Address:**	301 S GROVE AVE	**Deferred Maintenance:**	$39,567
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	1,948
Building Code:	R2900101010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$81,243
Building Name:	Park Rapids Fisheries Garage	**Address:**	301 S GROVE AVE	**Deferred Maintenance:**	$13,678
Facility Condition Index:	0.17 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	635

Building Code:	R2900101020	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$670,769
Building Name:	Park Rapids Fisheries Office	**Address:**	301 S GROVE AVE	**Deferred Maintenance:**	$126,320
Facility Condition Index:	0.19 - Fair	**City Code:**	PARK RAPIDS	**Ext. Gross Area:**	2,921

Site: R290227 - Bemidji Area Forestry

Building Code:	R2900103290	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$142,896
Building Name:	Bemidji Area Forestry Cold Storage	**Address:**	2220 BEMIDJI AVE	**Deferred Maintenance:**	$25,139
Facility Condition Index:	0.18 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	2,001
Building Code:	R2900103300	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$102,776
Building Name:	Bemidji Area Forestry Cold Storage	**Address:**	2220 BEMIDJI AVE	**Deferred Maintenance:**	$18,031
Facility Condition Index:	0.18 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	890
Building Code:	R2900103310	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$524,573
Building Name:	Bemidji Area Forestry Office	**Address:**	2220 BEMIDJI AVE	**Deferred Maintenance:**	$92,668
Facility Condition Index:	0.18 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	2,338
Building Code:	R2900103320	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$471,802
Building Name:	Bemidji Area Forestry Shop	**Address:**	2220 BEMIDJI AVE	**Deferred Maintenance:**	$77,491
Facility Condition Index:	0.16 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	6,638

Site: R290230 - Carlos Avery WMA

Building Code:	R2900600480	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$917,934
Building Name:	Carlos Avery WMA Zodiac Shop	**Address:**	18310 ZODIAC ST	**Deferred Maintenance:**	$233,096
Facility Condition Index:	0.25 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	5,600
Building Code:	R2900600490	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$358,528
Building Name:	Carlos Avery WMA Zodiac Residence	**Address:**	18306 ZODIAC ST NE	**Deferred Maintenance:**	$98,395
Facility Condition Index:	0.27 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	2,021
Building Code:	R2900600510	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$655,998
Building Name:	Carlos Avery WMA Zodiac Office	**Address:**	18310 ZODIAC ST	**Deferred Maintenance:**	$284,404
Facility Condition Index:	0.43 - Poor	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	3,967
Building Code:	R2900600530	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$144,765
Building Name:	Carlos Avery WMA Zodiac Garage	**Address:**	18310 ZODIAC ST	**Deferred Maintenance:**	$55,760
Facility Condition Index:	0.39 - Poor	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,025
Building Code:	R2900600540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$124,134
Building Name:	Carlos Avery WMA Zodiac Hanger	**Address:**	18310 ZODIAC ST	**Deferred Maintenance:**	$110,980
Facility Condition Index:	0.89 - Crisis	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,163

Building Code:	R2900600560	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$903,304
Building Name:	Carlos Avery Zodiac Cold Storage	**Address:**	18310 ZODIAC ST	**Deferred Maintenance:**	$357,427
Facility Condition Index:	0.40 - Poor	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	6,534
Building Code:	R2900600570	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$703,047
Building Name:	Carlos Av Game Farm Research Office	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$182,372
Facility Condition Index:	0.26 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	3,558
Building Code:	R2900600580	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$632,489
Building Name:	Carlos Avery Game Farm Residence	**Address:**	5463-A WEST BROADWAY	**Deferred Maintenance:**	$102,630
Facility Condition Index:	0.16 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	3,386
Building Code:	R2900600590	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$149,743
Building Name:	Carlos Avery Game Farm Garage	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$39,309
Facility Condition Index:	0.26 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,267
Building Code:	R2900600630	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,443,975
Building Name:	Carlos Avery Game Farm Office	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$327,045
Facility Condition Index:	0.23 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	5,916
Building Code:	R2900600640	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$416,067
Building Name:	Carlos Avery Game Farm Cold Storage	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$84,970
Facility Condition Index:	0.20 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	2,880
Building Code:	R2900600770	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$98,255
Building Name:	Carlos Av Game Farm Brooder House	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$23,787
Facility Condition Index:	0.24 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,032
Building Code:	R2900600840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$79,856
Building Name:	Carlos Avery Game Farm Spring House	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$18,988
Facility Condition Index:	0.24 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	210
Building Code:	R2900600870	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$254,149
Building Name:	Carlos Avery Game Farm Cold Storage	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$62,691
Facility Condition Index:	0.25 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	2,425
Building Code:	R2900600890	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$409,607
Building Name:	Carlos Avery Game Farm Garage	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$129,901
Facility Condition Index:	0.32 - Poor	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	3,467
Building Code:	R2900602030	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$35,373
Building Name:	Carlos Avery Zodiac Picnic Shelter	**Address:**	18310 ZODIAC ST	**Deferred Maintenance:**	$4,745
Facility Condition Index:	0.13 - Good	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	98
Building Code:	R2900602060	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$158,050
Building Name:	Carlos Avery Game Farm Cold Storage	**Address:**	5463-C WEST BROADWAY	**Deferred Maintenance:**	$12,766
Facility Condition Index:	0.08 - Good	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,736

Site: R290231 - Eveleth

Building Code:	R2900205150	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$242,206
Building Name:	Eveleth Main Office	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$24,644
Facility Condition Index:	0.10 - Good	**City Code:**	EVELETH	**Ext. Gross Area:**	1,056
Building Code:	R2900205160	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$31,866
Building Name:	Eveleth Garage	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$10,936
Facility Condition Index:	0.34 - Poor	**City Code:**	EVELETH	**Ext. Gross Area:**	250
Building Code:	R2900205170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,925
Building Name:	Eveleth Oil House	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$5,835
Facility Condition Index:	0.49 - Poor	**City Code:**	EVELETH	**Ext. Gross Area:**	123
Building Code:	R2900205180	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,140
Building Name:	Eveleth Spring House	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$1,927
Facility Condition Index:	0.27 - Fair	**City Code:**	EVELETH	**Ext. Gross Area:**	98
Building Code:	R2900205190	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$464,278
Building Name:	Eveleth 5-Stall Garage Shop	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$229,919
Facility Condition Index:	0.50 - Poor	**City Code:**	EVELETH	**Ext. Gross Area:**	2,411
Building Code:	R2900205200	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$539,402
Building Name:	Eveleth Wildlife 5-Stall Gar Shop	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$103,082
Facility Condition Index:	0.19 - Fair	**City Code:**	EVELETH	**Ext. Gross Area:**	2,302
Building Code:	R2900205210	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$664,251
Building Name:	Eveleth Pine Cone Storage	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$372,487
Facility Condition Index:	0.56 - Crisis	**City Code:**	EVELETH	**Ext. Gross Area:**	5,145
Building Code:	R2900205220	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$2,436,268
Building Name:	Eveleth Main Office/Shop	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$382,073
Facility Condition Index:	0.16 - Fair	**City Code:**	EVELETH	**Ext. Gross Area:**	9,602
Building Code:	R2900205230	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$62,523
Building Name:	Eveleth Block Cold Storage	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$26,347
Facility Condition Index:	0.42 - Poor	**City Code:**	EVELETH	**Ext. Gross Area:**	583
Building Code:	R2900205240	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$216,762
Building Name:	Eveleth ENF 4-Stall Cold Storage	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$39,417
Facility Condition Index:	0.18 - Fair	**City Code:**	EVELETH	**Ext. Gross Area:**	1,964
Building Code:	R2900205270	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$33,171
Building Name:	Eveleth Cold Storage	**Address:**	7979 HWY 37	**Deferred Maintenance:**	$33,171
Facility Condition Index:	1.00 - Crisis	**City Code:**	EVELETH	**Ext. Gross Area:**	392

Site: R290233 - Warroad Boathouse

Building Code:	R2900108610	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$82,642
Building Name:	Warroad Boathouse	**Address:**	1101 LAKE ST NE	**Deferred Maintenance:**	$1,653
Facility Condition Index:	0.02 - Excellent	**City Code:**	WARROAD	**Ext. Gross Area:**	524

Site: R290234 - R3 HQ St Paul

Building Code:	R2900308750	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$56,199
Building Name:	St Paul R3 HQ HazMat Storage	**Address:**	1200 Warner Rd	**Deferred Maintenance:**	$1,124
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	224
Building Code:	R2900601080	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$130,352
Building Name:	St Paul R3 HQ 4-Stall Garage	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$40,350
Facility Condition Index:	0.31 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,170
Building Code:	R2900601260	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,205,994
Building Name:	St Paul R3 HQ Warehouse	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$251,263
Facility Condition Index:	0.21 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	6,211
Building Code:	R2900601290	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,145
Building Name:	St Paul R3 HQ Garage	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$6,195
Facility Condition Index:	0.29 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	250
Building Code:	R2900601300	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$181,419
Building Name:	St Paul R3 HQ 4-Stall Cold Storage	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$29,445
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	2,079
Building Code:	R2900601310	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$233,253
Building Name:	St Paul R3 HQ 3-Stall Cold Storage	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$42,547
Facility Condition Index:	0.18 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	2,663
Building Code:	R2900601320	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$8,657,136
Building Name:	St Paul R3 HQ Main Office	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$1,245,559
Facility Condition Index:	0.14 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	35,179
Building Code:	R2900601330	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$423,834
Building Name:	St Paul R3 HQ Cold Storage	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$136,247
Facility Condition Index:	0.32 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	4,430
Building Code:	R2900601840	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$117,441
Building Name:	St Paul R3 HQ EWR Cold Storage	**Address:**	1200 WARNER ROAD	**Deferred Maintenance:**	$18,434
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	885

Site: R290235 - R2 HQ Grand Rapids

Building Code:	R2900200020	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$260,450
Building Name:	Grand Rapids R2 HQ Wildlife Warehse	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$55,178
Facility Condition Index:	0.21 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	2,230
Building Code:	R2900203860	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$99,750
Building Name:	Grand Rapids R2 HQ Oil House	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$28,796
Facility Condition Index:	0.29 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	720
Building Code:	R2900203880	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$223,253
Building Name:	Grand Rapids R2 HQ Carpenter Shop	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$79,666
Facility Condition Index:	0.36 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,515
Building Code:	R2900203930	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,577,948
Building Name:	Grand Rapids R2 HQ G1 Shop	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$392,817
Facility Condition Index:	0.25 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	9,478
Building Code:	R2900203940	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$777,371
Building Name:	Grand Rapids R2 HQ Cold Storage W1	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$128,115
Facility Condition Index:	0.16 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	6,395
Building Code:	R2900203980	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$17,386,551
Building Name:	Grand Rapids R2 HQ Main Office	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$4,648,341
Facility Condition Index:	0.27 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	54,667
Building Code:	R2900204540	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$137,299
Building Name:	Grand Rapids R2 HQ Cold Storage N5	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$69,704
Facility Condition Index:	0.51 - Crisis	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	976
Building Code:	R2900204550	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$216,357
Building Name:	Grand Rapids R2 HQ Cold Storage N7	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$83,686
Facility Condition Index:	0.39 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,712
Building Code:	R2900204570	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$190,759
Building Name:	Grand Rapids R2 HQ Cold Storage N15	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$82,407
Facility Condition Index:	0.43 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,352
Building Code:	R2900204580	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$203,181
Building Name:	Grand Rapids R2 HQ Fire Control Ctr	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$66,508
Facility Condition Index:	0.33 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,905
Building Code:	R2900204600	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$374,585
Building Name:	Grand Rapids R2 HQ Sign Shop	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$108,293
Facility Condition Index:	0.29 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	2,312
Building Code:	R2900204630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$80,556
Building Name:	Grand Rapids R2 HQ Cold Storage N1	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$38,620
Facility Condition Index:	0.48 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	570

Building Code:	R2900204690	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$902,112
Building Name:	Grand Rapids R2 HQ Cold Storage N9	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$272,567
Facility Condition Index:	0.30 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	4,798
Building Code:	R2900204730	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$298,565
Building Name:	Grand Rapids R2 HQ Cntrl Heat Plant	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$83,289
Facility Condition Index:	0.28 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,430
Building Code:	R2900206830	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$51,967
Building Name:	Grand Rapids R2 HQ HazMat Storage	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$38,975
Facility Condition Index:	0.75 - Crisis	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	209
Building Code:	R2900206840	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$51,967
Building Name:	Grand Rapids R2 HQ HazMat Storage	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$38,975
Facility Condition Index:	0.75 - Crisis	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	209
Building Code:	R2900206870	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,801
Building Name:	Grand Rapids R2 HQ Engineering Shed	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$1,370
Facility Condition Index:	0.05 - Excellent	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	181
Building Code:	R2900207080	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,101,095
Building Name:	Grand Rapids R2 HQ Fish Hatchery	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$193,545
Facility Condition Index:	0.18 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	6,230
Building Code:	R2900207700	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$179,048
Building Name:	Grand Rapids R2 HQ Cold Storage N13	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$11,858
Facility Condition Index:	0.07 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,432
Building Code:	R2900208580	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,523
Building Name:	Grand Rapids R2 HQ Explosives Shed	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$270
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	134
Building Code:	R2900210600	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$35,464
Building Name:	Grand Rapids R2 HQ Wild Resrch Stor	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$709
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	441

Site: R290236 - Lake City

Building Code:	R2900501790	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$594,675
Building Name:	Lake City Shop	**Address:**	1801 S OAK ST	**Deferred Maintenance:**	$49,017
Facility Condition Index:	0.08 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	4,577
Building Code:	R2900501800	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,384
Building Name:	Lake City Oil House	**Address:**	1801 S OAK ST	**Deferred Maintenance:**	$7,367
Facility Condition Index:	0.22 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	168

Building Code:	R2900501810	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$622,706
Building Name:	Lake City Office	**Address:**	1801 S OAK ST	**Deferred Maintenance:**	$116,567
Facility Condition Index:	0.19 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	6,386
Building Code:	R2900503810	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$408,173
Building Name:	Lake City EWR Shop	**Address:**	1801 S OAK ST	**Deferred Maintenance:**	$31,132
Facility Condition Index:	0.08 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	3,296

Site: R290237 - Waterville

Building Code:	R2900401870	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$38,033
Building Name:	Waterville Duck Lake Pump House	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$2,998
Facility Condition Index:	0.08 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	63
Building Code:	R2900401880	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$2,470,976
Building Name:	Waterville Office	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$631,192
Facility Condition Index:	0.26 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	10,174
Building Code:	R2900401900	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$513,254
Building Name:	Waterville Cold Storage	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$109,802
Facility Condition Index:	0.21 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	4,200
Building Code:	R2900401910	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$367,365
Building Name:	Waterville Residence	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$74,779
Facility Condition Index:	0.20 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	2,016
Building Code:	R2900401920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$38,636
Building Name:	Waterville Residence Garage	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$8,634
Facility Condition Index:	0.22 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	308
Building Code:	R2900401930	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$24,386
Building Name:	Waterville Hatchery Area Pump House	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$3,258
Facility Condition Index:	0.13 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	78
Building Code:	R2900401940	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,673
Building Name:	Waterville Hatchery Area Pump House	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$922
Facility Condition Index:	0.08 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	36
Building Code:	R2900401950	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$33,511
Building Name:	Waterville Pike Pond Pump House	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$2,659
Facility Condition Index:	0.08 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	56
Building Code:	R2900401960	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$33,511
Building Name:	Waterville Cedar Lake Pump House	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$7,691
Facility Condition Index:	0.23 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	56

Building Code:	R2900404330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,384
Building Name:	Waterville Hatchery Area Shed	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$2,530
Facility Condition Index:	0.14 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	128
Building Code:	R2900404340	**Cost Model Name:**	Bunker	**Current Replacement Value:**	$37,225
Building Name:	Waterville Clear Lake Pump House	**Address:**	50317 FISH HATCHERY RD	**Deferred Maintenance:**	$8,643
Facility Condition Index:	0.23 - Fair	**City Code:**	WATERVILLE	**Ext. Gross Area:**	63

Site: R290238 - Minnesota Interagency Fire Center

Building Code:	R2900208470	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$185,758
Building Name:	MIFC Modular Office	**Address:**	402 11TH ST SE	**Deferred Maintenance:**	$29,702
Facility Condition Index:	0.16 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	1,068

Site: R290240 - Duluth Area

Building Code:	R2900201880	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$456,474
Building Name:	Duluth Office	**Address:**	4805 RICE LAKE RD	**Deferred Maintenance:**	$131,111
Facility Condition Index:	0.29 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	1,834
Building Code:	R2900201890	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$441,365
Building Name:	Duluth Shop	**Address:**	4805 RICE LAKE RD	**Deferred Maintenance:**	$100,259
Facility Condition Index:	0.23 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	3,115
Building Code:	R2900201900	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,392
Building Name:	Duluth Area Fuel Shed	**Address:**	4805 RICE LAKE RD	**Deferred Maintenance:**	$14,714
Facility Condition Index:	0.45 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	168
Building Code:	R2900201910	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$34,188
Building Name:	Duluth Area Fire Cache	**Address:**	4805 RICE LAKE RD	**Deferred Maintenance:**	$9,316
Facility Condition Index:	0.27 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	299
Building Code:	R2900202010	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,734
Building Name:	Duluth Area Lower Garage	**Address:**	4805 RICE LAKE RD	**Deferred Maintenance:**	$7,337
Facility Condition Index:	0.13 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	582

Site: R290242 - Lanesboro Area

Building Code:	R2900501580	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$27,122
Building Name:	Lanesboro Area Cold Storage Garage	**Address:**	23785 GROSBEAK RD	**Deferred Maintenance:**	$8,858
Facility Condition Index:	0.33 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	294
Building Code:	R2900501720	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$999,429
Building Name:	Lanesboro Area Office	**Address:**	23785 GROSBEAK RD	**Deferred Maintenance:**	$142,269
Facility Condition Index:	0.14 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	5,600

Building Code:	R2900504640	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$26,847
Building Name:	Lanesboro Area Oil House	**Address:**	23785 GROSBEAK RD	**Deferred Maintenance:**	$3,065
Facility Condition Index:	0.11 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	160
Building Code:	R2900505290	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$291,768
Building Name:	Lanesboro Area Cold Storage	**Address:**	23785 GROSBEAK RD	**Deferred Maintenance:**	$18,255
Facility Condition Index:	0.06 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	4,620

Site: R290243 - Onamia

Building Code:	R2900300460	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$334,322
Building Name:	Onamia Office	**Address:**	303 ROOSEVELT RD	**Deferred Maintenance:**	$74,960
Facility Condition Index:	0.22 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	1,800
Building Code:	R2900300480	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$99,730
Building Name:	Onamia Cold Storage	**Address:**	303 ROOSEVELT RD	**Deferred Maintenance:**	$24,504
Facility Condition Index:	0.25 - Fair	**City Code:**	ONAMIA	**Ext. Gross Area:**	960
Building Code:	R2900304090	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$19,091
Building Name:	Onamia Oil House	**Address:**	303 ROOSEVELT RD	**Deferred Maintenance:**	$1,499
Facility Condition Index:	0.08 - Good	**City Code:**	ONAMIA	**Ext. Gross Area:**	96

Site: R290263 - Crane Lake - St Louis

Building Code:	R2900203090	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$339,460
Building Name:	Crane Lake Boat House	**Address:**	7144 COUNTY RD 425	**Deferred Maintenance:**	$65,483
Facility Condition Index:	0.19 - Fair	**City Code:**	CRANE LAKE	**Ext. Gross Area:**	1,200
Building Code:	R2900210930	**Cost Model Name:**	Single-story Restroom Facility	**Current Replacement Value:**	$10,502
Building Name:	Crane Lake Handberg Sanitation	**Address:**	7128 Handberg Rd	**Deferred Maintenance:**	$210
Facility Condition Index:	0.02 - Excellent	**City Code:**	CRANE LAKE	**Ext. Gross Area:**	120
Building Code:	R2900210940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$27,165
Building Name:	Crane Lake Handberg Vault Concrete	**Address:**	7128 Handberg Vault Concrete	**Deferred Maintenance:**	$543
Facility Condition Index:	0.02 - Excellent	**City Code:**	CRANE LAKE	**Ext. Gross Area:**	54

Site: R290264 - Namakan Lake

Building Code:	R2900203330	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$159,705
Building Name:	Namakan Lake Cabin	**Address:**	1201 E HWY 2	**Deferred Maintenance:**	$21,231
Facility Condition Index:	0.13 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	600
Building Code:	R2900204210	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$2,015
Building Name:	Namakan Lake Oil House	**Address:**	Namakan Island	**Deferred Maintenance:**	$665
Facility Condition Index:	0.33 - Poor	**City Code:**	ORR	**Ext. Gross Area:**	20

Building Code:	R2900204220	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,692
Building Name:	Namakan Lake Cold Storage	**Address:**		**Deferred Maintenance:**	$1,479
Facility Condition Index:	0.32 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	30

Site: R290265 - Sauk Centre

Building Code:	R2900307440	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$185,054
Building Name:	Sauk Centre Cold Storage	**Address:**		**Deferred Maintenance:**	$18,820
Facility Condition Index:	0.10 - Good	**City Code:**	SAUK CENTRE	**Ext. Gross Area:**	2,016

Site: R290267 - Mille Lacs Lake

Building Code:	R2900303070	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$83,903
Building Name:	Mille Lacs Lake Isle Boat House	**Address:**	41294 HENNEPIN PK RD	**Deferred Maintenance:**	$22,692
Facility Condition Index:	0.27 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	720

Site: R290268 - Hastings

Building Code:	R2900602180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,954
Building Name:	Hastings Boat House	**Address:**	1350 DAM RD	**Deferred Maintenance:**	$3,295
Facility Condition Index:	0.10 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	320

Site: R290269 - Lake Minnetonka

Building Code:	R2900308900	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$160,502
Building Name:	Lake Minnetonka Boat House	**Address:**	941 Excelsior Blvd	**Deferred Maintenance:**	$3,210
Facility Condition Index:	0.02 - Excellent	**City Code:**	EXCELSIOR	**Ext. Gross Area:**	0

Site: R290270 - Lake Saganaga

Building Code:	R2900203390	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$39,417
Building Name:	Lake Saganga Cabin	**Address:**		**Deferred Maintenance:**	$9,199
Facility Condition Index:	0.23 - Fair	**City Code:**	UNASSIGNED	**Ext. Gross Area:**	240

Site: R290271 - Nemadji State Forest

Building Code:	R2900305560	**Cost Model Name:**	Tower	**Current Replacement Value:**	$15,910
Building Name:	Nemadji SF Askov Fire Tower	**Address:**	701 S KENWOOD RR 2	**Deferred Maintenance:**	$5,250
Facility Condition Index:	0.33 - Poor	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	64
Building Code:	R2900306620	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,093
Building Name:	Nemadji SF Garfvert CG Site 1 Vault	**Address:**	67491 STATE FOREST RD	**Deferred Maintenance:**	$2,348
Facility Condition Index:	0.18 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	40

Building Code:	R2900308210	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,093
Building Name:	Nemadji SF Garfvert CG Ste6/7 Vault	**Address:**	67491 STATE FOREST RD	**Deferred Maintenance:**	$968
Facility Condition Index:	0.07 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	40
Building Code:	R2900308220	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,842
Building Name:	Nemadji SF Garfvert CG Site14 Vault	**Address:**	67491 STATE FOREST RD	**Deferred Maintenance:**	$2,408
Facility Condition Index:	0.14 - Good	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	51

Site: R290272 - Cross Lake

Building Code:	R2900306610	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$13,161
Building Name:	Cross Lake Vault Toilet	**Address:**	701 S KENWOOD RR 2	**Deferred Maintenance:**	$3,360
Facility Condition Index:	0.26 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	40

Site: R290274 - McCarthy Lake WMA

Building Code:	R2900308160	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$224,219
Building Name:	McCarthy Lake WMA Cold Storage	**Address:**	HWY 61	**Deferred Maintenance:**	$20,457
Facility Condition Index:	0.09 - Good	**City Code:**	KELLOGG	**Ext. Gross Area:**	2,560

Site: R290275 - New London Hatchery

Building Code:	R2900403710	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$997,631
Building Name:	New London Fish Hatchery	**Address:**	308 1ST AVE NW	**Deferred Maintenance:**	$181,907
Facility Condition Index:	0.18 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	3,276
Building Code:	R2900403720	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$164,964
Building Name:	New London Hatchery Pump House	**Address:**	308 1ST AVE NW	**Deferred Maintenance:**	$54,063
Facility Condition Index:	0.33 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	1,094
Building Code:	R2900403730	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$26,501
Building Name:	New London Hatchery Pump House	**Address:**	308 1ST AVE NW	**Deferred Maintenance:**	$4,423
Facility Condition Index:	0.17 - Fair	**City Code:**	NEW LONDON	**Ext. Gross Area:**	282
Building Code:	R2900404730	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$185,165
Building Name:	New London Hatchery Raceway Shelter	**Address:**	308 1ST AVE NW	**Deferred Maintenance:**	$13,862
Facility Condition Index:	0.07 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	2,106
Building Code:	R2900405280	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$7,631
Building Name:	New London Hatchery Shed	**Address:**	308 1ST AVE NW	**Deferred Maintenance:**	$3,289
Facility Condition Index:	0.43 - Poor	**City Code:**	NEW LONDON	**Ext. Gross Area:**	64

Site: R290276 - Red Wing

Building Code: R2900500090
Building Name: Red Wing Boat House
Facility Condition Index: 0.05 - Good

Cost Model Name: Single-story Work Facility
Address:
City Code: RED WING

Current Replacement Value: $44,800
Deferred Maintenance: $2,298
Ext. Gross Area: 504

Site: R290277 - Wabasha

Building Code: R2900500120
Building Name: Wabasha Boat House
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-story Work Facility
Address:
City Code: WABASHA

Current Replacement Value: $60,385
Deferred Maintenance: $6,039
Ext. Gross Area: 528

Site: R290278 - La Crescent

Building Code: R2900503700
Building Name: La Crescent Boat House
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-story Work Facility
Address:
City Code: LA CRESCENT

Current Replacement Value: $83,335
Deferred Maintenance: $8,713
Ext. Gross Area: 864

Site: R290281 - Rainy Lake

Building Code: R2900207250
Building Name: Rainy Lake Black Bay Fire Tower
Facility Condition Index: 0.10 - Good

Cost Model Name: Tower
Address: 392 HWY 11 E
City Code: INTL. FALLS

Current Replacement Value: $15,292
Deferred Maintenance: $1,529
Ext. Gross Area: 64

Site: R290282 - Lake Winnibigoshish

Building Code: R2900208450
Building Name: Lake Winnibigoshish Boat House
Facility Condition Index: 0.03 - Excellent

Cost Model Name: Single-story Work Facility
Address: 1201 E HWY 2
City Code: GRAND RAPIDS

Current Replacement Value: $21,039
Deferred Maintenance: $581
Ext. Gross Area: 250

Site: R290283 - Coleraine

Building Code: R2900203870
Building Name: Coleraine Radio Shelter
Facility Condition Index: 0.42 - Poor

Cost Model Name: Utility Shed
Address: 403 DIVISION ST
City Code: DEER RIVER

Current Replacement Value: $8,481
Deferred Maintenance: $3,583
Ext. Gross Area: 64

Building Code: R2900207210
Building Name: Coleraine Fire Tower
Facility Condition Index: 0.75 - Crisis

Cost Model Name: Tower
Address: 403 DIVISION ST
City Code: DEER RIVER

Current Replacement Value: $10,532
Deferred Maintenance: $7,899
Ext. Gross Area: 64

Site: R290284 - Devil Track Hatchery

Building Code: R2900204510
Building Name: Devil Track Hatchery
Facility Condition Index: 0.23 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 137 SOUTH SHORE DRIVE
City Code: GRAND MARAIS

Current Replacement Value: $367,598
Deferred Maintenance: $82,913
Ext. Gross Area: 1,400

Site: R290285 - Cromwell

Building Code:	R2900207090	**Cost Model Name:**	Tower	**Current Replacement Value:**	$28,846
Building Name:	Cromwell Fire Tower	**Address:**	CO RD 5	**Deferred Maintenance:**	$16,757
Facility Condition Index:	0.58 - Crisis	**City Code:**	CROMWELL	**Ext. Gross Area:**	64
Building Code:	R2900207110	**Cost Model Name:**	Tower	**Current Replacement Value:**	$29,661
Building Name:	Cromwell City Fire Tower	**Address:**	824 CO RD 120	**Deferred Maintenance:**	$9,788
Facility Condition Index:	0.33 - Poor	**City Code:**	CROMWELL	**Ext. Gross Area:**	64

Site: R290286 - Hill River State Forest

Building Code:	R2900305510	**Cost Model Name:**	Tower	**Current Replacement Value:**	$17,735
Building Name:	Hill River SF Ball Bluff Fire Tower	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$1,774
Facility Condition Index:	0.10 - Good	**City Code:**	HILL CITY	**Ext. Gross Area:**	64
Building Code:	R2900305530	**Cost Model Name:**	Tower	**Current Replacement Value:**	$14,898
Building Name:	Hill River SF Quadna Fire Tower	**Address:**	454 N HWY 169	**Deferred Maintenance:**	$1,490
Facility Condition Index:	0.10 - Good	**City Code:**	HILL CITY	**Ext. Gross Area:**	64

Site: R290287 - Cannon Falls

Building Code:	R2900504980	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$54,087
Building Name:	Cannon Falls Picnic Shelter 1	**Address:**		**Deferred Maintenance:**	$7,021
Facility Condition Index:	0.13 - Good	**City Code:**	CANNON FALLS	**Ext. Gross Area:**	360
Building Code:	R2900504990	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$83,542
Building Name:	Cannon Falls Cold Storage	**Address:**		**Deferred Maintenance:**	$14,891
Facility Condition Index:	0.18 - Fair	**City Code:**	CANNON FALLS	**Ext. Gross Area:**	1,650

Site: R290289 - Vermillion Highlands WMA

Building Code:	R2900308170	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$136,305
Building Name:	Vermillion Highlands WMA Cold Stor	**Address:**	15325 BABCOCK AVE	**Deferred Maintenance:**	$22,272
Facility Condition Index:	0.16 - Fair	**City Code:**	ROSEMOUNT	**Ext. Gross Area:**	1,563

Site: R290290 - Sand Prairie WMA & Environmental Ed

Building Code:	R2900308150	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$20,740
Building Name:	Sand Prairie WMA Info Center	**Address:**	East side of Hwy 10, South of Hwy 2	**Deferred Maintenance:**	$1,402
Facility Condition Index:	0.07 - Good	**City Code:**	SAUK RAPIDS	**Ext. Gross Area:**	192

Site: R290291 - Bemidji Hatchery

Building Code:	R2900100980	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$336,213
Building Name:	Bemidji Hatchery	**Address:**	10307 POWER DAM RD NE	**Deferred Maintenance:**	$81,532
Facility Condition Index:	0.24 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	2,016

Site: R290292 - Bemidji Area Fish & Wildlife

Building Code:	R2900100200	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$575,908
Building Name:	Bemidji FAW Office	**Address:**	2114 BEMIDJI AVE	**Deferred Maintenance:**	$93,415
Facility Condition Index:	0.16 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	3,002

Site: R290293 - Bemidji Area Wildlife Research

Building Code:	R2900103270	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$411,094
Building Name:	Bemidji Wildlife Research Office	**Address:**	102 23RD ST NE	**Deferred Maintenance:**	$124,747
Facility Condition Index:	0.30 - Poor	**City Code:**	BEMIDJI	**Ext. Gross Area:**	2,088
Building Code:	R2900103280	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,101
Building Name:	Bemidji Wild Research Cold Storage	**Address:**	102 23RD ST NE	**Deferred Maintenance:**	$7,483
Facility Condition Index:	0.26 - Fair	**City Code:**	BEMIDJI	**Ext. Gross Area:**	278
Building Code:	R2900106150	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$482,598
Building Name:	Bemidji Wild Research Modular Ofc	**Address:**	102 23RD ST NE	**Deferred Maintenance:**	$64,242
Facility Condition Index:	0.13 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	2,010

Site: R290294 - Duluth French River

Building Code:	R2900200320	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$3,204,417
Building Name:	Duluth French River Hatchery	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$894,906
Facility Condition Index:	0.28 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	12,016
Building Code:	R2900200330	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$76,887
Building Name:	Duluth French River Clarifier	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$23,855
Facility Condition Index:	0.31 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	217
Building Code:	R2900200340	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,273,224
Building Name:	Duluth French R Burrows/Biofilters	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$3,532,819
Facility Condition Index:	0.67 - Crisis	**City Code:**	DULUTH	**Ext. Gross Area:**	16,946
Building Code:	R2900200350	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,798
Building Name:	Duluth F Sump Pump Pipe-Lk Superior	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$4,048
Facility Condition Index:	0.46 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	26
Building Code:	R2900200370	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$437,705
Building Name:	Duluth French River Residence	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$88,250
Facility Condition Index:	0.20 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	2,342

Building Code:	R2900200400	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$71,961
Building Name:	Duluth French River Pump House	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$22,878
Facility Condition Index:	0.32 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	606
Building Code:	R2900203630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$271,248
Building Name:	Duluth French River Shop	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$57,752
Facility Condition Index:	0.21 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	1,930
Building Code:	R2900206970	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$122,972
Building Name:	Duluth French River Cold Storage	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$17,640
Facility Condition Index:	0.14 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	957
Building Code:	R2900208430	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$364,283
Building Name:	Duluth Fra R Bruder Stock-Pole Shed	**Address:**	5357 NORTH SHORE DR	**Deferred Maintenance:**	$192,256
Facility Condition Index:	0.53 - Crisis	**City Code:**	DULUTH	**Ext. Gross Area:**	3,293

Site: R290295 - Duluth Area Fisheries

Building Code:	R2900200380	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$509,062
Building Name:	Duluth Fisheries Garage	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$125,473
Facility Condition Index:	0.25 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	4,240
Building Code:	R2900200390	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$2,372,103
Building Name:	Duluth Fisheries Office	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$764,858
Facility Condition Index:	0.32 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	8,499
Building Code:	R2900200410	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$136,227
Building Name:	Duluth Fisheries 2-Stall Garage	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$18,980
Facility Condition Index:	0.14 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	673
Building Code:	R2900200420	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,900
Building Name:	Duluth Fisheries Net Shed	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$6,231
Facility Condition Index:	0.20 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	331
Building Code:	R2900200430	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$533,055
Building Name:	Duluth Fisheries Shop	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$96,393
Facility Condition Index:	0.18 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	4,480
Building Code:	R2900206140	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,949
Building Name:	Duluth Fisheries Cold Storage	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$9,082
Facility Condition Index:	0.70 - Crisis	**City Code:**	DULUTH	**Ext. Gross Area:**	96
Building Code:	R2900206150	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,609
Building Name:	Duluth Fisheries Wood Shed	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$10,609
Facility Condition Index:	1.00 - Crisis	**City Code:**	DULUTH	**Ext. Gross Area:**	146

Building Code:	R2900206850	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$37,002
Building Name:	Duluth Fish Walk-In Freezer Bldg	**Address:**	5351 NORTH SHORE DR	**Deferred Maintenance:**	$12,211
Facility Condition Index:	0.33 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	131

Site: R290296 - Baudette Fish & Wildlife

Building Code:	R2900103860	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,173
Building Name:	Baudette FAW Garage	**Address:**	204 MAIN ST E	**Deferred Maintenance:**	$6,630
Facility Condition Index:	0.23 - Fair	**City Code:**	BAUDETTE	**Ext. Gross Area:**	331
Building Code:	R2900103890	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$425,752
Building Name:	Baudette FAW Office	**Address:**	204 MAIN ST E	**Deferred Maintenance:**	$57,404
Facility Condition Index:	0.13 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	1,057
Building Code:	R2900104520	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$488,804
Building Name:	Baudette FAW Shop	**Address:**	204 MAIN ST E	**Deferred Maintenance:**	$71,457
Facility Condition Index:	0.15 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	4,284

Site: R290297 - Lanesboro Hatchery

Building Code:	R2900501560	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$241,996
Building Name:	Lanesboro Hatchery Shop	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$17,412
Facility Condition Index:	0.07 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	2,000
Building Code:	R2900501600	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$205,413
Building Name:	Lanesboro Hatchery Spring House	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$68,330
Facility Condition Index:	0.33 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	2,480
Building Code:	R2900501610	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$13,741
Building Name:	Lanesboro Hatchery Cold Storage	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$2,876
Facility Condition Index:	0.21 - Fair	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900501940	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,211
Building Name:	Lanesboro Hatchery Cold Storage	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$7,345
Facility Condition Index:	0.66 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	80
Building Code:	R2900502110	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,893,627
Building Name:	Lanesboro Hatch Pole Shed Raceway	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$187,774
Facility Condition Index:	0.06 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	29,785
Building Code:	R2900502410	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$354,128
Building Name:	Lanesboro Hatchery Raceway Shel 1	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$320,931
Facility Condition Index:	0.91 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	1,032

Building Code:	R2900502420	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$344,390
Building Name:	Lanesboro Hatchery Raceway Shel 2	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$311,194
Facility Condition Index:	0.90 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	1,032
Building Code:	R2900502430	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$77,881
Building Name:	Lanesboro Hatch Broodstock Raceway	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$8,240
Facility Condition Index:	0.11 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	1,025
Building Code:	R2900504650	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$30,164
Building Name:	Lanesboro Hatch Gazebo Spring House	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$3,965
Facility Condition Index:	0.13 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	254
Building Code:	R2900504710	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$74,695
Building Name:	Lanesboro Hatchery Generator Shed	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$22,126
Facility Condition Index:	0.30 - Fair	**City Code:**	LANESBORO	**Ext. Gross Area:**	200
Building Code:	R2900505000	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$65,245
Building Name:	Lanesboro Hatchery Coverall Shelter	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$21,531
Facility Condition Index:	0.33 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	1,650
Building Code:	R2900505360	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$270,220
Building Name:	Lanesboro Hatch Fingerlings Raceway	**Address:**	23789 GROSBEAK RD	**Deferred Maintenance:**	$16,296
Facility Condition Index:	0.06 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	4,200

Site: R290318 - Agate Bay

Building Code:	R2900210650	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$54,750
Building Name:	Agate Bay Vault Concrete	**Address:**		**Deferred Maintenance:**	$5,475
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	102

Site: R290322 - LaSalle Lake SRA

Building Code:	R2900108890	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$465,900
Building Name:	LaSalle Lake SRA Black Bear Cabin	**Address:**	9887 CO RD 9	**Deferred Maintenance:**	$15,748
Facility Condition Index:	0.03 - Excellent	**City Code:**	SOLWAY	**Ext. Gross Area:**	1,264
Building Code:	R2900108910	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$39,240
Building Name:	LaSalle Lake SRA CG Fish Cleang Hse	**Address:**	9887 CO RD 9	**Deferred Maintenance:**	$5,267
Facility Condition Index:	0.13 - Good	**City Code:**	SOLWAY	**Ext. Gross Area:**	120
Building Code:	R2900108920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$213,007
Building Name:	LaSalle Lake SRA Shop	**Address:**	10221 COUNTY RD 9	**Deferred Maintenance:**	$22,706
Facility Condition Index:	0.11 - Good	**City Code:**	SOLWAY	**Ext. Gross Area:**	1,789

Building Code: R2900108930
Building Name: LaSalle Lake SRA CG Sanitation
Facility Condition Index: 0.17 - Fair

Cost Model Name: Single-story Restroom Facility
Address: 9887 CO RD 9
City Code: SOLWAY

Current Replacement Value: $309,976
Deferred Maintenance: $52,386
Ext. Gross Area: 1,216

Building Code: R2900108960
Building Name: LaSalle Lake SRA Lone Wolf Cabin
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-family Residence
Address: 9887 CO RD 9
City Code: SOLWAY

Current Replacement Value: $108,182
Deferred Maintenance: $10,818
Ext. Gross Area: 616

Building Code: R2900108980
Building Name: LaSalle Lake SRA Black Bear Garage
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-story Work Facility
Address: 9887 CO RD 9
City Code: SOLWAY

Current Replacement Value: $55,663
Deferred Maintenance: $5,566
Ext. Gross Area: 720

Building Code: R2900109400
Building Name: LaSalle Lake SRA Day Vault Concr
Facility Condition Index: 0.10 - Good

Cost Model Name: Vault Toilet
Address: 9887 CO RD 9
City Code: SOLWAY

Current Replacement Value: $76,546
Deferred Maintenance: $7,655
Ext. Gross Area: 51

Building Code: R2900109410
Building Name: LaSalle Lake SRA Day Vault Concr
Facility Condition Index: 0.10 - Good

Cost Model Name: Vault Toilet
Address: 9887 CO RD 9
City Code: SOLWAY

Current Replacement Value: $55,417
Deferred Maintenance: $5,542
Ext. Gross Area: 102

Building Code: R2900109420
Building Name: LaSalle Lake SRA Day Picnic Shel 2
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Shelter
Address: 9887 CO RD 9
City Code: SOLWAY

Current Replacement Value: $185,065
Deferred Maintenance: $18,506
Ext. Gross Area: 1,280

Site: R290323 - McDougall WMA

Building Code: R2900308260
Building Name: McDougall WMA Brooder House
Facility Condition Index: 0.72 - Crisis

Cost Model Name: Single-story Work Facility
Address: 5815 HILTON RD
City Code: ROYALTON

Current Replacement Value: $47,296
Deferred Maintenance: $33,852
Ext. Gross Area: 480

Building Code: R2900308270
Building Name: McDougall WMA Barn
Facility Condition Index: 0.75 - Crisis

Cost Model Name: Single-story Work Facility
Address: 5815 HILTON RD
City Code: ROYALTON

Current Replacement Value: $314,018
Deferred Maintenance: $235,513
Ext. Gross Area: 3,223

Site: R290324 - Lake Christina WAS - Grant

Building Code: R2900109040
Building Name: Lake Christina-Grant Pump House
Facility Condition Index: 0.10 - Good

Cost Model Name: Single-story Work Facility
Address:
City Code: ASHBY

Current Replacement Value: $41,945
Deferred Maintenance: $4,195
Ext. Gross Area: 352

Building Code: R2900109480
Building Name: Lake Christina-Grant Fish Cntrl Bld
Facility Condition Index: 0.10 - Good

Cost Model Name: Utility Shed
Address:
City Code: ASHBY

Current Replacement Value: $12,496
Deferred Maintenance: $1,250
Ext. Gross Area: 120

Site: R290325 - Moose Lake

Building Code:	R2900206480	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$11,111
Building Name:	Moose Lake South Shore WAS Vault	**Address:**	CO RD 217	**Deferred Maintenance:**	$2,245
Facility Condition Index:	0.20 - Fair	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	30

Site: R290357 - Root River State Trail

Building Code:	R2900502790	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Trout Valley Trl Vault Toilet	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900502820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Gribbon Valley Vault Toilet	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900502830	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Isinour Women's Vault Toilet	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900502840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Isinour Men's Vault Toilet	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900503030	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$19,697
Building Name:	Root River ST Fountain Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$7,620
Facility Condition Index:	0.39 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	160
Building Code:	R2900503040	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$15,511
Building Name:	RR ST Upper Isinour Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$5,119
Facility Condition Index:	0.33 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	126
Building Code:	R2900503910	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Petersn/Lanesb Riv Acc Vault	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900503920	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Peterson River Access Vault	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900503930	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Whalan Trail Men's Vault	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900503940	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Whalan Trail Women's Vault	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$26,079
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	64

Building Code:	R2900504660	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$18,824
Building Name:	RR ST South Branch Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$3,271
Facility Condition Index:	0.17 - Fair	**City Code:**	LANESBORO	**Ext. Gross Area:**	160
Building Code:	R2900504680	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$18,223
Building Name:	RR ST Vinegar Ridge CG Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$3,986
Facility Condition Index:	0.22 - Fair	**City Code:**	LANESBORO	**Ext. Gross Area:**	160
Building Code:	R2900504820	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Brightdale Mgmt Unit Vault	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$11,475
Facility Condition Index:	0.33 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900504830	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$18,223
Building Name:	Root River ST Whalen Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$13,667
Facility Condition Index:	0.75 - Crisis	**City Code:**	LANESBORO	**Ext. Gross Area:**	160
Building Code:	R2900504840	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$34,771
Building Name:	RR ST Eagle Bluff Center Vault	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$11,475
Facility Condition Index:	0.33 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	64
Building Code:	R2900504850	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$12,310
Building Name:	Root River ST Preston Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$1,614
Facility Condition Index:	0.13 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	100
Building Code:	R2900504910	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$17,470
Building Name:	RR ST Wet Bark/Oak Ridge Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$1,994
Facility Condition Index:	0.11 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	144
Building Code:	R2900504920	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$16,400
Building Name:	RR ST Wet Bark Unit Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$1,887
Facility Condition Index:	0.12 - Good	**City Code:**	LANESBORO	**Ext. Gross Area:**	144
Building Code:	R2900505520	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$10,022
Building Name:	RR ST North of Peterson Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$2,192
Facility Condition Index:	0.22 - Fair	**City Code:**	LANESBORO	**Ext. Gross Area:**	88

Site: R290358 - Harmony-Preston State Trail

Building Code:	R2900504670	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$18,223
Building Name:	Harmony-Preston ST Adirondack	**Address:**	100 MILWAUKEE RD	**Deferred Maintenance:**	$6,523
Facility Condition Index:	0.36 - Poor	**City Code:**	LANESBORO	**Ext. Gross Area:**	160

Site: R290362 - Round-Rice Bed WMA

Building Code:	R2900209390	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$10,355
Building Name:	Round-Rice Bed WMA Heated Storage	**Address:**	STATE HWY 17 & CROW WING C(	**Deferred Maintenance:**	$240
Facility Condition Index:	0.02 - Excellent	**City Code:**	GARRISON	**Ext. Gross Area:**	64

Site: R290363 - Oak Lake WAS

Building Code:	R2900209400	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$18,487
Building Name:	Oak Lake WAS Vault Toilet Concrete	**Address:**	89999 OAK LAKE RD S	**Deferred Maintenance:**	$1,849
Facility Condition Index:	0.10 - Good	**City Code:**	KERRICK	**Ext. Gross Area:**	35

Site: R290364 - Sturgeon Lake WAS

Building Code:	R2900209410	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$16,877
Building Name:	Sturgeon Lake WAS Vault Toilet	**Address:**	38714 LAUNCH DR	**Deferred Maintenance:**	$1,742
Facility Condition Index:	0.10 - Good	**City Code:**	STURGEON LAKE	**Ext. Gross Area:**	51

Site: R290367 - Ray Berglund State Wayside

Building Code:	R2900209500	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$130,967
Building Name:	Ray Berglund State Wayside San Bldg	**Address:**		**Deferred Maintenance:**	$12,724
Facility Condition Index:	0.10 - Good	**City Code:**	TOFTE	**Ext. Gross Area:**	320

Site: R290453 - White Earth State Forest

Building Code:	R2900105510	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,228
Building Name:	White Earth SF Tulaby Fire Tower	**Address:**	TULBAY	**Deferred Maintenance:**	$2,715
Facility Condition Index:	0.33 - Poor	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	64
Building Code:	R2900105610	**Cost Model Name:**	Tower	**Current Replacement Value:**	$8,228
Building Name:	White Earth SF HeightO'L Fire Tower	**Address:**	Height of Land	**Deferred Maintenance:**	$2,715
Facility Condition Index:	0.33 - Poor	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	64

Site: R290605 - C J Ramstad State Trail

Building Code:	R2900210620	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,736
Building Name:	CJRamstad ST Finland Vault Concrete	**Address:**	6866 Cramer Rd	**Deferred Maintenance:**	$1,055
Facility Condition Index:	0.02 - Excellent	**City Code:**	Finland	**Ext. Gross Area:**	105
Building Code:	R2900210630	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$25,656
Building Name:	CJRamstad ST Martin Vault Concrete	**Address:**	Martin Rd.	**Deferred Maintenance:**	$513
Facility Condition Index:	0.02 - Excellent	**City Code:**	DULUTH	**Ext. Gross Area:**	51

Building Code:	R2900210640	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$52,736
Building Name:	CJRamstad ST Normanna Vault Concret	**Address:**	Normanna Rd	**Deferred Maintenance:**	$1,055
Facility Condition Index:	0.02 - Excellent	**City Code:**	DULUTH	**Ext. Gross Area:**	105

Site: R290622 - Un-Named Creek - Site 1A

Building Code:	R2900405790	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$41,275
Building Name:	Un-Named Creek Site 1A - Control E	**Address:**		**Deferred Maintenance:**	$826
Facility Condition Index:	0.02 - Excellent	**City Code:**		**Ext. Gross Area:**	899

Site: R290623 - Mayhew Creek - Site 2B

Building Code:	R2900405780	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$49,703
Building Name:	Mayhew Creek Site 2B - Control Equi	**Address:**		**Deferred Maintenance:**	$994
Facility Condition Index:	0.02 - Excellent	**City Code:**		**Ext. Gross Area:**	896

Site: R290635 - Peterson

Building Code:	R2900504770	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$547,460
Building Name:	Peterson T&W Storage	**Address:**	416 PARK ST	**Deferred Maintenance:**	$45,738
Facility Condition Index:	0.08 - Good	**City Code:**	PETERSON	**Ext. Gross Area:**	3,520

Site: R290643 - Sea Gull Lake

Building Code:	R2900204200	**Cost Model Name:**	Single-family Residence	**Current Replacement Value:**	$88,268
Building Name:	Sea Gull River Cabin	**Address:**	92 Gull Lake Lane	**Deferred Maintenance:**	$17,093
Facility Condition Index:	0.19 - Fair	**City Code:**	Grand Marais	**Ext. Gross Area:**	436

Site: R290644 - Windom

Building Code:	R2900401860	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$339,975
Building Name:	Windom Cold Storage	**Address:**	175 CTY RD 26	**Deferred Maintenance:**	$130,311
Facility Condition Index:	0.38 - Poor	**City Code:**	WINDOM	**Ext. Gross Area:**	2,877
Building Code:	R2900404300	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$4,950,433
Building Name:	Windom Office	**Address:**	175 CTY RD 26	**Deferred Maintenance:**	$941,364
Facility Condition Index:	0.19 - Fair	**City Code:**	WINDOM	**Ext. Gross Area:**	22,145
Building Code:	R2900404810	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,922
Building Name:	Windom Shed	**Address:**	175 CTY RD 26	**Deferred Maintenance:**	$2,140
Facility Condition Index:	0.12 - Good	**City Code:**	WINDOM	**Ext. Gross Area:**	197

Site: R290824 - Cloquet Area

Building Code:	R2900210950	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,971,859
Building Name:	Cloquet Area Office	**Address:**	305 Business Park Drive E	**Deferred Maintenance:**	$118,941
Facility Condition Index:	0.04 - Excellent	**City Code:**	CLOQUET	**Ext. Gross Area:**	32,000

Agency: R32 - Pollution Control Agency

FCI Rating:	Good	**Current Replacement Value:**	$11,329,612	**Ext. Gross Area:**	25,198
Facility Condition Index:	0.13	**Deferred Maintenance:**	$1,507,560	**Building Count:**	18

Site: R32B30 - BECKER COUNTY LANDFILL

Building Code:	R32B30B3001	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,007,400
Building Name:	Groundwater Treatment Building	**Address:**	24413 County Road 144	**Deferred Maintenance:**	$400,740
Facility Condition Index:	0.10 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	100

Site: R32E10 - EAST BETHEL LANDFILL

Building Code:	R32E10E1001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$203,367
Building Name:	GroundwateTreatment Building	**Address:**	217th Avenue Northeast	**Deferred Maintenance:**	$36,198
Facility Condition Index:	0.18 - Fair	**City Code:**	EAST BETHEL	**Ext. Gross Area:**	1,456

Site: R32F40 - FLYING CLOUD LANDFILL

Building Code:	R32F40F4001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,008,853
Building Name:	Former Gas to Energy Building	**Address:**	9813 Flying Cloud Drive	**Deferred Maintenance:**	$221,591
Facility Condition Index:	0.22 - Fair	**City Code:**	EDEN PRAIRIE	**Ext. Gross Area:**	6,730

Site: R32I20 - IRONWOOD LANDFILL

Building Code:	R32I20I2001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$19,802
Building Name:	Manifold Building	**Address:**	Sec. 22, Bloomfield Twp.	**Deferred Maintenance:**	$1,980
Facility Condition Index:	0.10 - Good	**City Code:**	Spring Valley	**Ext. Gross Area:**	100

Site: R32K40 - KOOCHICHING COUNTY LANDFILL

Building Code:	R32K40K4001	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$4,298,144
Building Name:	Leachate Pump Control Building	**Address:**	4100 Highway 11 West	**Deferred Maintenance:**	$429,814
Facility Condition Index:	0.10 - Good	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	120

Site: R32L80 - LINDENFELSER LANDFILL

Building Code:	R32L80L8001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$921,422
Building Name:	Garage	**Address:**	1890 Kadler Avenue	**Deferred Maintenance:**	$285,476
Facility Condition Index:	0.31 - Poor	**City Code:**	St. Michael	**Ext. Gross Area:**	8,107

Site: R32L90 - LONG PRAIRIE LANDFILL

Building Code:	R32L90L9002	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$200,529
Building Name:	Pole Barn	**Address:**	28824 State Highway 27	**Deferred Maintenance:**	$43,618
Facility Condition Index:	0.22 - Fair	**City Code:**	Long Prairie	**Ext. Gross Area:**	2,600

Site: R32W40 - WASHINGTON COUNTY LANDFILL

Building Code:	R32W40W4001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$63,817
Building Name:	Storage Building	**Address:**	3855 Jamaca Avenue	**Deferred Maintenance:**	$6,382
Facility Condition Index:	0.10 - Good	**City Code:**	Lake Elmo	**Ext. Gross Area:**	675
Building Code:	R32W40W4003	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$9,545
Building Name:	Leachate Pump Control Building	**Address:**	3855 Jamaca Avenue	**Deferred Maintenance:**	$191
Facility Condition Index:	0.02 - Excellent	**City Code:**	LAKE ELMO	**Ext. Gross Area:**	100

Site: R32W50 - ANOKA-RAMSEY LANDFILL

Building Code:	R32W50W5001	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$74,052
Building Name:	Equipment Storage Bldg	**Address:**	14730 Sunfish Lake Blvd.	**Deferred Maintenance:**	$7,589
Facility Condition Index:	0.10 - Good	**City Code:**	RAMSEY	**Ext. Gross Area:**	720
Building Code:	R32W50W5002	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$145,461
Building Name:	Former Air Stripper Blower Bldg	**Address:**	14730 Sunfish Lake Blvd.	**Deferred Maintenance:**	$16,476
Facility Condition Index:	0.11 - Good	**City Code:**	RAMSEY	**Ext. Gross Area:**	1,140
Building Code:	R32W50W5003	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$47,357
Building Name:	Former Flare Blower Bldg	**Address:**	14730 Sunfish Lake Blvd.	**Deferred Maintenance:**	$11,624
Facility Condition Index:	0.25 - Fair	**City Code:**	RAMSEY	**Ext. Gross Area:**	528
Building Code:	R32W50W5004	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$6,719
Building Name:	Emergency Blower Building	**Address:**	14730 Sunfish Lake Blvd.	**Deferred Maintenance:**	$3,688
Facility Condition Index:	0.55 - Crisis	**City Code:**	RAMSEY	**Ext. Gross Area:**	64
Building Code:	R32W50W5005	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$10,069
Building Name:	Control Panel Building	**Address:**	14730 Sunfish Lake Blvd.	**Deferred Maintenance:**	$2,054
Facility Condition Index:	0.20 - Fair	**City Code:**	RAMSEY	**Ext. Gross Area:**	100

Site: R32W70 - WASTE DISPOSAL ENGINEERING LANDFILL

Building Code:	R32W70W7001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$35,517
Building Name:	Groundwater Treatment Bldg	**Address:**	14437 Crosstown Blvd.	**Deferred Maintenance:**	$6,179
Facility Condition Index:	0.17 - Fair	**City Code:**	Andover	**Ext. Gross Area:**	300
Building Code:	R32W70W7002	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$122,064
Building Name:	Former Turbine Building	**Address:**	14437 Crosstown Blvd.	**Deferred Maintenance:**	$10,289
Facility Condition Index:	0.08 - Good	**City Code:**	ANDOVER	**Ext. Gross Area:**	1,134

Site: R32W90 - WOODLAKE LANDFILL

Building Code:	R32W90W9003	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$95,486
Building Name:	Former Blower Building	**Address:**	4000 Hamel Road	**Deferred Maintenance:**	$9,846
Facility Condition Index:	0.10 - Good	**City Code:**	Medina	**Ext. Gross Area:**	648

Site: R32X20 - OLMSTED COUNTY LANDFILL

Building Code:	R32X20X2001	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$60,008
Building Name:	Garage	**Address:**	2683 - 85th Street NW	**Deferred Maintenance:**	$13,826
Facility Condition Index:	0.23 - Fair	**City Code:**	ORONOCO	**Ext. Gross Area:**	576

Agency: T79 - Department of Transportation

FCI Rating:	Good	**Current Replacement Value:**	$1,286,262,146	**Ext. Gross Area:**	6,593,033
Facility Condition Index:	0.15	**Deferred Maintenance:**	$186,805,779	**Building Count:**	884

Site: T791092020 - MAPLEWOOD - MATERIALS LAB

Building Code:	T7907792020	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$23,313,224
Building Name:	MATERIALS LAB - OFFICE/LAB	**Address:**	1400 GERVAIS AVE	**Deferred Maintenance:**	$2,552,296
Facility Condition Index:	0.11 - Good	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	80,340
Building Code:	T7907792050	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,294,807
Building Name:	MATERIALS LAB - POLE STORAGE	**Address:**	1400 GERVAIS AVE	**Deferred Maintenance:**	$167,690
Facility Condition Index:	0.13 - Good	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	11,776

Site: T791092026 - ST PAUL - CENTRAL SERVICES

Building Code:	T7909192026	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$20,052,956
Building Name:	CENTRAL SERVICES - MAIN BLDG	**Address:**	6000 MINNEHAHA AVE	**Deferred Maintenance:**	$3,148,945
Facility Condition Index:	0.16 - Fair	**City Code:**	RICHFIELD	**Ext. Gross Area:**	93,704
Building Code:	T7909192027	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$607,018
Building Name:	CENTRAL SERVICES - POLE STORAGE	**Address:**	6000 MINNEHAHA AVE	**Deferred Maintenance:**	$105,249
Facility Condition Index:	0.17 - Fair	**City Code:**	RICHFIELD	**Ext. Gross Area:**	6,080
Building Code:	T7909192059	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$568,579
Building Name:	CENTRAL SERVICES - POLE STORAGE	**Address:**	6000 MINNEHAHA AVE	**Deferred Maintenance:**	$28,575
Facility Condition Index:	0.05 - Good	**City Code:**	RICHFIELD	**Ext. Gross Area:**	5,163

Site: T791092036 - ARDEN HILLS - TRAINING CENTER

Building Code:	T7900092034	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$76,531
Building Name:	ARDEN HILLS - MISC STORAGE	**Address:**	1900 W CO RD I	**Deferred Maintenance:**	$3,041
Facility Condition Index:	0.04 - Excellent	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	888
Building Code:	T7900092036	**Cost Model Name:**	Low-rise Office Building, 2 to 4 story	**Current Replacement Value:**	$9,137,332
Building Name:	ARDEN HILLS - TRAINING CENTER	**Address:**	1900 W CO RD I	**Deferred Maintenance:**	$1,307,782
Facility Condition Index:	0.14 - Good	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	40,992
Building Code:	T7900092057	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$97,589
Building Name:	ARDEN HILLS TC - MISC STORAGE	**Address:**	1900 W CO RD I	**Deferred Maintenance:**	$4,775
Facility Condition Index:	0.05 - Excellent	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	1,081

Site: T791092043 - PLYMOUTH - DRIVERS EXAM

Building Code:	T7900092043	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,815,893
Building Name:	PLYMOUTH - DRIVERS EXAM	**Address:**	2455 FERNBROOK LN	**Deferred Maintenance:**	$257,838
Facility Condition Index:	0.14 - Good	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	6,633
Building Code:	T7900092047	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$6,287
Building Name:	PLYMOUTH - EXAM MISC STORAGE	**Address:**	2455 FERNBROOK LN	**Deferred Maintenance:**	$3,594
Facility Condition Index:	0.57 - Crisis	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	199

Site: T791092051 - MONTICELLO - MnROAD RESEARCH

Building Code:	T7907792051	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$975,132
Building Name:	MNROAD RESEARCH - OFFICE	**Address:**	9011 77TH ST NE	**Deferred Maintenance:**	$127,820
Facility Condition Index:	0.13 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	4,724
Building Code:	T7907792053	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,103,474
Building Name:	MNROAD RESEARCH - POLE STORAGE	**Address:**	907 77TH ST NE	**Deferred Maintenance:**	$77,568
Facility Condition Index:	0.07 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	6,781
Building Code:	T7907792066	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,271
Building Name:	MNROAD RESEARCH - WIM BUILDING	**Address:**	907 77TH ST NE	**Deferred Maintenance:**	$3,227
Facility Condition Index:	0.10 - Good	**City Code:**	ALBERTVILLE	**Ext. Gross Area:**	250

Site: T791092055 - ST PAUL - AERONAUTICS OFFICE

Building Code:	T7906092055	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$5,058,397
Building Name:	ST PAUL - AERONAUTICS OFFICE	**Address:**	222 EAST PLATO BLVD	**Deferred Maintenance:**	$1,381,318
Facility Condition Index:	0.27 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	20,301

Site: T791092063 - MINNEAPOLIS - NIT EQUIPMENT

Building Code:	T7990092063	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$37,278
Building Name:	NIT EQUIPMENT BUILDING - SERVICE BU	**Address:**	I394 AND PENN AVENUE	**Deferred Maintenance:**	$7,276
Facility Condition Index:	0.20 - Fair	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	288

Site: T791092067 - PINEY/PINE CREEK - AIRPORT

Building Code:	T7906092067	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$171,111
Building Name:	PINEY/PINE CREEK - AIRPORT BLDG	**Address:**	41937 MN HWY 89	**Deferred Maintenance:**	$48,735
Facility Condition Index:	0.28 - Fair	**City Code:**	ROSEAU	**Ext. Gross Area:**	1,380

Site: T791A20210 - CROMWELL - LOADING SITE

Building Code:	T7910020210	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$91,356
Building Name:	CROMWELL - SALT/SAND STORAGE	**Address:**	1353 Hwy 73	**Deferred Maintenance:**	$13,413
Facility Condition Index:	0.15 - Good	**City Code:**	CROMWELL	**Ext. Gross Area:**	1,218

Site: T791A20211 - FOND DU LAC - LOADING SITE

Building Code:	T7910020211	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$84,407
Building Name:	FOND DU LAC - SALT/SAND STORAGE	**Address:**	2923 Fon Du Lac Road	**Deferred Maintenance:**	$9,948
Facility Condition Index:	0.12 - Good	**City Code:**	SUPERIOR	**Ext. Gross Area:**	1,068
Building Code:	T7910090220	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$106,566
Building Name:	FOND DU LAC - MISC STORAGE	**Address:**	2923 Fon Du Lac Road	**Deferred Maintenance:**	$7,237
Facility Condition Index:	0.07 - Good	**City Code:**	SUPERIOR	**Ext. Gross Area:**	780

Site: T791A20212 - SAGINAW - LOADING SITE

Building Code:	T7910020212	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$146,918
Building Name:	SAGINAW - SALT/SAND STORAGE	**Address:**	6886 US Hwy 2	**Deferred Maintenance:**	$24,046
Facility Condition Index:	0.16 - Fair	**City Code:**	SAGINAW	**Ext. Gross Area:**	1,852
Building Code:	T7910090282	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$76,509
Building Name:	SAGINAW - LOADER STORAGE	**Address:**	6886 US Hwy 2	**Deferred Maintenance:**	$3,667
Facility Condition Index:	0.05 - Excellent	**City Code:**	SAGINAW	**Ext. Gross Area:**	560

Site: T791A20214 - JACOBSON - LOADING SITE

Building Code:	T7910020214	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$65,381
Building Name:	JACOBSON - SALT/SAND STORAGE	**Address:**	18907 HWY200	**Deferred Maintenance:**	$24,808
Facility Condition Index:	0.38 - Poor	**City Code:**	JACOBSON	**Ext. Gross Area:**	1,054
Building Code:	T7910090264	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,290
Building Name:	JACOBSON - MISC STORAGE	**Address:**	18907 HWY200	**Deferred Maintenance:**	$4,878
Facility Condition Index:	0.09 - Good	**City Code:**	JACOBSON	**Ext. Gross Area:**	580

Site: T791A20218 - THOMPSON HILL - LOADING SITE

Building Code:	T7910020218	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$239,892
Building Name:	THOMPSON HILL - SALT/SAND STORAGE	**Address:**	I35 At US 2	**Deferred Maintenance:**	$42,410
Facility Condition Index:	0.18 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	3,024
Building Code:	T7910090279	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$73,753
Building Name:	THOMPSON HILL - MISC STORAGE	**Address:**	I 35 At US 2	**Deferred Maintenance:**	$9,288
Facility Condition Index:	0.13 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	606

Site: T791A20219 - MCGRATH - LOADING SITE

Building Code:	T7910020219	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$56,837
Building Name:	MCGRATH - SALT/SAND STORAGE	**Address:**	1/2 Mile South of McGrath Hwy 65	**Deferred Maintenance:**	$12,503
Facility Condition Index:	0.22 - Fair	**City Code:**	MCGRATH	**Ext. Gross Area:**	798
Building Code:	T7910090255	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$79,172
Building Name:	MCGRATH - MISC STORAGE	**Address:**	1/2 Mile South of McGrath Hwy 65	**Deferred Maintenance:**	$10,285
Facility Condition Index:	0.13 - Good	**City Code:**	MCGRATH	**Ext. Gross Area:**	630

Site: T791A20221 - ISABELLA - LOADING SITE

Building Code:	T7910020221	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$46,738
Building Name:	ISABELLA - SALT/SAND STORAGE	**Address:**	2111 Minn Hwy 1	**Deferred Maintenance:**	$5,158
Facility Condition Index:	0.11 - Good	**City Code:**	ISABELLA	**Ext. Gross Area:**	459
Building Code:	T7910090275	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$86,149
Building Name:	ISABELLA - MISC STORAGE	**Address:**	2111 Minn Hwy 1	**Deferred Maintenance:**	$9,926
Facility Condition Index:	0.12 - Good	**City Code:**	ISABELLA	**Ext. Gross Area:**	582

Site: T791A20222 - LESTER RIVER - LOADING SITE

Building Code:	T7910020222	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$105,941
Building Name:	LESTER RIVER - SALT/SAND STORAGE	**Address:**	6831 East Superior Street	**Deferred Maintenance:**	$26,914
Facility Condition Index:	0.25 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	1,067
Building Code:	T7910090274	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,398
Building Name:	LESTER RIVER - MISC STORAGE	**Address:**	6831 East Superior Street	**Deferred Maintenance:**	$17,611
Facility Condition Index:	0.30 - Poor	**City Code:**	DULUTH	**Ext. Gross Area:**	513

Site: T791A20225 - LIBBY - LOADING SITE

Building Code:	T7910020225	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$52,557
Building Name:	LIBBY - SALT/SAND STORAGE	**Address:**	59420 MN-65	**Deferred Maintenance:**	$5,964
Facility Condition Index:	0.11 - Good	**City Code:**	LIBBY	**Ext. Gross Area:**	635
Building Code:	T7910090283	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$70,375
Building Name:	LIBBY - LOADER STORAGE	**Address:**	59420 MN-65	**Deferred Maintenance:**	$6,323
Facility Condition Index:	0.09 - Good	**City Code:**	LIBBY	**Ext. Gross Area:**	560

Site: T791A20228 - GOOSEBERRY FALLS - LOADING SITE

Building Code:	T7910020228	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$196,735
Building Name:	GOOSEBERRY FALLS-SALT/SAND STORAGE	**Address:**		**Deferred Maintenance:**	$15,880
Facility Condition Index:	0.08 - Good	**City Code:**	BEAVER BAY	**Ext. Gross Area:**	1,597

Site: T791A20230 - TEMPERANCE RIVER - LOADING SITE

Building Code:	T7910020230	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$97,425
Building Name:	TEMPERANCE RIVER - SALT/SAND STRG	**Address:**	7631 HIGHWAY 61	**Deferred Maintenance:**	$19,216
Facility Condition Index:	0.20 - Fair	**City Code:**	TOFTE	**Ext. Gross Area:**	798
Building Code:	T7910090270	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$78,970
Building Name:	TEMPERANCE RIVER - MISC STORAGE	**Address:**	7631 HIGHWAY 61	**Deferred Maintenance:**	$20,824
Facility Condition Index:	0.26 - Fair	**City Code:**	TOFTE	**Ext. Gross Area:**	240

Site: T791A20231 - RESERVATION RIVER - LOADING SITE

Building Code:	T7910020217	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$6,057
Building Name:	RESERVATION RIVER - SALT/SAND STRG	**Address:**	6081 MN HWY 61	**Deferred Maintenance:**	$2,393
Facility Condition Index:	0.40 - Poor	**City Code:**	HOVLAND	**Ext. Gross Area:**	80
Building Code:	T7910020231	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$130,388
Building Name:	RESERVATION RIVER - SALT/SAND STRG	**Address:**	6081 MN HWY 61	**Deferred Maintenance:**	$27,612
Facility Condition Index:	0.21 - Fair	**City Code:**	HOVLAND	**Ext. Gross Area:**	1,068
Building Code:	T7910090265	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$99,417
Building Name:	RESERVATION RIVER - MISC STORAGE	**Address:**	6081 MN HWY 61	**Deferred Maintenance:**	$13,853
Facility Condition Index:	0.14 - Good	**City Code:**	HOVLAND	**Ext. Gross Area:**	705

Site: T791A90200 - FOND DU LAC (SPRUNG)

Building Code:	T7910090200	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$231,319
Building Name:	FON DU LAC - MISC STORAGE (SPRUNG)	**Address:**		**Deferred Maintenance:**	$4,626
Facility Condition Index:	0.02 - Excellent	**City Code:**	FON DU LAC	**Ext. Gross Area:**	2,700

Site: T791A90209 - DUXBURY - TOWER SITE

Building Code:	T7910090209	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$366,859
Building Name:	DUXBURY - MISC STORAGE	**Address:**	60449 Duxbury Road	**Deferred Maintenance:**	$76,483
Facility Condition Index:	0.21 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	624
Building Code:	T7910090210	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$247,680
Building Name:	DUXBURY - POLE STORAGE	**Address:**	60449 Duxbury Road	**Deferred Maintenance:**	$29,612
Facility Condition Index:	0.12 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	1,760

Site: T791A90211 - GRAND MARAIS - TRUCK STATION

Building Code:	T7910020239	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$637,140
Building Name:	GRAND MARAIS - SALT/SAND STORAGE	**Address:**	1361 East US Hwy 61	**Deferred Maintenance:**	$12,743
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	8,000
Building Code:	T7910090211	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,207,740
Building Name:	GRAND MARAIS - TRUCK STATION	**Address:**	1361 East US Hwy 61	**Deferred Maintenance:**	$284,133
Facility Condition Index:	0.24 - Fair	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	5,286
Building Code:	T7910090287	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$44,976
Building Name:	GRAND MARAIS - BRINE BUILDING	**Address:**	1361 East US Hwy 61	**Deferred Maintenance:**	$4,317
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	117
Building Code:	T7910090291	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$303,669
Building Name:	GRAND MARAIS - POLE STORAGE BLDG	**Address:**	1361 East US Hwy 61	**Deferred Maintenance:**	$38,264
Facility Condition Index:	0.13 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	2,560

Site: T791A90221 - DULUTH - HEADQUARTERS

Building Code:	T7910020223	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$814,574
Building Name:	DULUTH - SALT/SAND STORAGE	**Address:**	1123 Mesaba Avenue	**Deferred Maintenance:**	$76,190
Facility Condition Index:	0.09 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	6,104
Building Code:	T7910090208	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$440,319
Building Name:	DULUTH - POLE STORAGE	**Address:**	1123 Mesaba Avenue	**Deferred Maintenance:**	$68,382
Facility Condition Index:	0.16 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	4,160
Building Code:	T7910090221	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$38,705,119
Building Name:	DULUTH - HEADQUARTERS	**Address:**	1123 Mesaba Avenue	**Deferred Maintenance:**	$10,632,114
Facility Condition Index:	0.27 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	125,938
Building Code:	T7910090228	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$494,887
Building Name:	DULUTH - POLE STORAGE	**Address:**	1123 Mesaba Avenue	**Deferred Maintenance:**	$75,037
Facility Condition Index:	0.15 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	3,978
Building Code:	T7910090289	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$546,642
Building Name:	DULUTH - POLE STORAGE BLDG	**Address:**	1123 Mesaba Avenue	**Deferred Maintenance:**	$69,133
Facility Condition Index:	0.13 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	4,160

Site: T791A90222 - FLOODWOOD - TRUCK STATION

Building Code:	T7910020209	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$170,154
Building Name:	FLOODWOOD - SALT/SAND STORAGE	**Address:**	106 WEST HWY 2	**Deferred Maintenance:**	$24,983
Facility Condition Index:	0.15 - Good	**City Code:**	FLOODWOOD	**Ext. Gross Area:**	1,852

Building Code:	T7910090222	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,126,701
Building Name:	FLOODWOOD - TRUCK STATION	**Address:**	106 WEST HWY 2	**Deferred Maintenance:**	$247,181
Facility Condition Index:	0.22 - Fair	**City Code:**	FLOODWOOD	**Ext. Gross Area:**	6,508
Building Code:	T7910090225	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$269,298
Building Name:	FLOODWOOD - MISC STORAGE	**Address:**	106 WEST HWY 2	**Deferred Maintenance:**	$40,354
Facility Condition Index:	0.15 - Good	**City Code:**	FLOODWOOD	**Ext. Gross Area:**	1,590
Building Code:	T7910090252	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,288
Building Name:	FLOODWOOD - MISC STORAGE	**Address:**	106 WEST HWY 2	**Deferred Maintenance:**	$10,852
Facility Condition Index:	0.22 - Fair	**City Code:**	FLOODWOOD	**Ext. Gross Area:**	400
Building Code:	T7910090288	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$40,132
Building Name:	FLOODWOOD - BRINE BUILDING	**Address:**	106 WEST HWY 2	**Deferred Maintenance:**	$803
Facility Condition Index:	0.02 - Excellent	**City Code:**	FLOODWOOD	**Ext. Gross Area:**	117

Site: T791A90223 - SILVER CLIFF - TUNNEL

Building Code:	T7910090223	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,601,524
Building Name:	SILVER CLIFF - TUNNEL SERVICE	**Address:**	TH 61 5 MI NE of Two Harbors	**Deferred Maintenance:**	$1,799,906
Facility Condition Index:	0.32 - Poor	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	1,113

Site: T791A90224 - SILVER BAY - TRUCK STATION

Building Code:	T7910020235	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$451,497
Building Name:	SILVER BAY - SALT/SAND STORAGE	**Address:**	5163 Highway 61	**Deferred Maintenance:**	$77,131
Facility Condition Index:	0.17 - Fair	**City Code:**	SILVER BAY	**Ext. Gross Area:**	4,800
Building Code:	T7910090224	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,443,364
Building Name:	SILVER BAY - TRUCK STATION	**Address:**	5163 Highway 61	**Deferred Maintenance:**	$39,120
Facility Condition Index:	0.03 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	7,187
Building Code:	T7910090232	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$458,222
Building Name:	SILVER BAY - POLE STORAGE	**Address:**	5163 Highway 61	**Deferred Maintenance:**	$10,049
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	4,032
Building Code:	T7910090240	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$41,534
Building Name:	SILVER BAY - BRINE BUILDING	**Address:**	5163 Highway 61	**Deferred Maintenance:**	$831
Facility Condition Index:	0.02 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	117

Site: T791A90227 - LAFAYETTE BLUFF - TUNNEL

Building Code:	T7910090227	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$3,518,296
Building Name:	LAFAYETTE BLUFF - TUNNEL SERVICE	**Address:**	TH 61-7.5 MI NE of Two Harbors	**Deferred Maintenance:**	$348,056
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	654

Site: T791A90229 - PINE CITY - TRUCK STATION

Building Code:	T7910020229	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$661,480
Building Name:	PINE CITY - SALT/SAND STORAGE	**Address:**	905 Hillside SW	**Deferred Maintenance:**	$131,000
Facility Condition Index:	0.20 - Fair	**City Code:**	PINE CITY	**Ext. Gross Area:**	8,297
Building Code:	T7910090229	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,467,310
Building Name:	PINE CITY - TRUCK STATION	**Address:**	905 Hillside SW	**Deferred Maintenance:**	$395,280
Facility Condition Index:	0.27 - Fair	**City Code:**	PINE CITY	**Ext. Gross Area:**	8,598
Building Code:	T7910090244	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,326
Building Name:	PINE CITY - BRINE BUILDING	**Address:**	905 Hillside SW	**Deferred Maintenance:**	$727
Facility Condition Index:	0.02 - Excellent	**City Code:**	PINE CITY	**Ext. Gross Area:**	117

Site: T791A90230 - SANDSTONE - TRUCK STATION

Building Code:	T7910020202	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$263,875
Building Name:	SANDSTONE - SALT/SAND STORAGE	**Address:**	1618 HWY 23 N	**Deferred Maintenance:**	$30,137
Facility Condition Index:	0.11 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	2,676
Building Code:	T7910090202	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$403,266
Building Name:	SANDSTONE - EQUIP STORAGE	**Address:**	1618 Hwy 23 N	**Deferred Maintenance:**	$86,806
Facility Condition Index:	0.22 - Fair	**City Code:**	SANDSTONE	**Ext. Gross Area:**	2,889
Building Code:	T7910090230	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,639,522
Building Name:	SANDSTONE - TRUCK STATION	**Address:**	1618 Hwy 23 N	**Deferred Maintenance:**	$63,629
Facility Condition Index:	0.04 - Excellent	**City Code:**	SANDSTONE	**Ext. Gross Area:**	11,012
Building Code:	T7910090243	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,326
Building Name:	SANDSTONE - BRINE BUILDING	**Address:**	1618 Hwy 23 N	**Deferred Maintenance:**	$727
Facility Condition Index:	0.02 - Excellent	**City Code:**	SANDSTONE	**Ext. Gross Area:**	117
Building Code:	T7910090277	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$239,070
Building Name:	SANDSTONE - MISC STORAGE	**Address:**	1618 Hwy 23 N	**Deferred Maintenance:**	$29,247
Facility Condition Index:	0.12 - Good	**City Code:**	SANDSTONE	**Ext. Gross Area:**	2,058

Site: T791A90245 - TWO HARBORS - TRUCK STATION

Building Code:	T7910020240	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$761,901
Building Name:	TWO HARBORS - SALT/SAND STORAGE	**Address:**	1561 Hwy 2	**Deferred Maintenance:**	$15,238
Facility Condition Index:	0.02 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	8,100
Building Code:	T7910090204	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$43,246
Building Name:	TWO HARBORS - BRINE BUILDING	**Address:**	1561 Hwy 2	**Deferred Maintenance:**	$4,151
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	117

Building Code:	T7910090235	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$373,981
Building Name:	TWO HARBORS-COLD STORAGE	**Address:**	1561 Hwy 2	**Deferred Maintenance:**	$7,480
Facility Condition Index:	0.02 - Excellent	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	4,032
Building Code:	T7910090245	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,680,623
Building Name:	TWO HARBORS - TRUCK STATION	**Address:**	1561 Hwy 2	**Deferred Maintenance:**	$341,797
Facility Condition Index:	0.20 - Fair	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	8,705

Site: T791A90246 - CARLTON - TRUCK STATION

Building Code:	T7910020233	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,489,896
Building Name:	CARLTON - SALT/SAND STORAGE	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$223,601
Facility Condition Index:	0.15 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	14,950
Building Code:	T7910090207	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$95,081
Building Name:	CARLTON - MISC STORAGE	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$24,469
Facility Condition Index:	0.26 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	720
Building Code:	T7910090217	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$960,607
Building Name:	CARLTON - OLD BRIDGE CREW	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$143,469
Facility Condition Index:	0.15 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	5,288
Building Code:	T7910090218	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$246,585
Building Name:	CARLTON - MISC STORAGE	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$47,278
Facility Condition Index:	0.19 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	2,100
Building Code:	T7910090234	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,164,056
Building Name:	CARLTON - BRIDGE CREW BLDG	**Address:**	1515 HWY 210	**Deferred Maintenance:**	$23,281
Facility Condition Index:	0.02 - Excellent	**City Code:**	CARLTON	**Ext. Gross Area:**	6,571
Building Code:	T7910090246	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,338,499
Building Name:	CARLTON - TRUCK STATION	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$409,714
Facility Condition Index:	0.18 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	12,333
Building Code:	T7910090253	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$86,623
Building Name:	CARLTON - MISC STORAGE	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$25,340
Facility Condition Index:	0.29 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	796
Building Code:	T7910090296	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$283,757
Building Name:	CARLTON - BRIDGE CREW STORAGE	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$20,546
Facility Condition Index:	0.07 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	2,586
Building Code:	T7910090297	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$103,400
Building Name:	CARLTON - LOADER STORAGE BLDG	**Address:**	1515 Hwy 210	**Deferred Maintenance:**	$6,840
Facility Condition Index:	0.07 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	847

Site: T791A90256 - NOPEMING - TRUCK STATION

Building Code:	T7910020236	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,479,700
Building Name:	NOPEMING - SALT/SAND STORAGE	**Address:**	2650 Midway Road	**Deferred Maintenance:**	$29,594
Facility Condition Index:	0.02 - Excellent	**City Code:**	NOPEMING	**Ext. Gross Area:**	16,800
Building Code:	T7910090231	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$147,595
Building Name:	NOPEMING - BRINE BUILDING	**Address:**	2650 Midway Road	**Deferred Maintenance:**	$2,952
Facility Condition Index:	0.02 - Excellent	**City Code:**	NOPEMING	**Ext. Gross Area:**	1,012
Building Code:	T7910090256	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,100,323
Building Name:	NOPEMING - TRUCK STATION	**Address:**	2650 Midway Road	**Deferred Maintenance:**	$464,933
Facility Condition Index:	0.15 - Good	**City Code:**	NOPEMING	**Ext. Gross Area:**	16,023
Building Code:	T7910090276	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$312,132
Building Name:	NOPEMING - MISC STORAGE	**Address:**	2650 Midway Road	**Deferred Maintenance:**	$51,657
Facility Condition Index:	0.17 - Fair	**City Code:**	NOPEMING	**Ext. Gross Area:**	2,184
Building Code:	T7910090286	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$101,660
Building Name:	NOPEMING - HAZ MAT BLDG	**Address:**	2650 Midway Road	**Deferred Maintenance:**	$33,548
Facility Condition Index:	0.33 - Poor	**City Code:**	NOPEMING	**Ext. Gross Area:**	80
Building Code:	T7910090290	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$459,444
Building Name:	NOPEMING - POLE STORAGE BLDG	**Address:**	2650 Midway Road	**Deferred Maintenance:**	$76,465
Facility Condition Index:	0.17 - Fair	**City Code:**	NOPEMING	**Ext. Gross Area:**	4,232

Site: T791A90257 - MOOSE LAKE - TRUCK STATION

Building Code:	T7910020241	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$520,124
Building Name:	MOOSE LAKE - SALT/SAND STORAGE	**Address:**	975 Hwy 73	**Deferred Maintenance:**	$10,402
Facility Condition Index:	0.02 - Excellent	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	6,400
Building Code:	T7910090237	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$47,011
Building Name:	MOOSE LAKE - MISC STORAGE	**Address:**	975 Hwy 73	**Deferred Maintenance:**	$10,822
Facility Condition Index:	0.23 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	421
Building Code:	T7910090238	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,732
Building Name:	MOOSE LAKE - BRINE BUILDING	**Address:**	975 Hwy 73	**Deferred Maintenance:**	$675
Facility Condition Index:	0.02 - Excellent	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	130
Building Code:	T7910090257	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$931,128
Building Name:	MOOSE LAKE - TRUCK STATION	**Address:**	975 Hwy 73	**Deferred Maintenance:**	$171,108
Facility Condition Index:	0.18 - Fair	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	5,520
Building Code:	T7910090295	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$421,002
Building Name:	MOOSE LAKE - POLE STORAGE BLDG	**Address:**	975 Hwy 73	**Deferred Maintenance:**	$9,086
Facility Condition Index:	0.02 - Excellent	**City Code:**	MOOSE LAKE	**Ext. Gross Area:**	3,513

Site: T791A90260 - DULUTH ERICKSON - TUNNEL

Building Code:	T7910090260	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$11,023,523
Building Name:	DULUTH - ERICKSON TUNNEL - SVC BLDG	**Address:**	Lief Erickson Tunnel	**Deferred Maintenance:**	$1,099,298
Facility Condition Index:	0.10 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	6,403

Site: T791A90266 - MCGREGOR - TRUCK STATION

Building Code:	T7910020238	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$578,096
Building Name:	McGREGOR - SALT/SAND STORAGE	**Address:**	38182 Mn Hwy 65	**Deferred Maintenance:**	$11,562
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	7,200
Building Code:	T7910090273	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,523,532
Building Name:	MCGREGOR- TRUCK STATION(NEW)	**Address:**	38182 Mn Hwy 65	**Deferred Maintenance:**	$30,471
Facility Condition Index:	0.02 - Excellent	**City Code:**	MCGREGOR	**Ext. Gross Area:**	7,460
Building Code:	T7910090292	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$245,763
Building Name:	MCGREGOR - POLE STORAGE BLDG	**Address:**	38182 Mn Hwy 65	**Deferred Maintenance:**	$15,607
Facility Condition Index:	0.06 - Good	**City Code:**	MCGREGOR	**Ext. Gross Area:**	2,560

Site: T791A90281 - BLACK BEAR - SCALE SITE

Building Code:	T7910090281	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$142,974
Building Name:	CARLTON - HAZARD MATL STORAGE	**Address:**	1369 Interstate 35	**Deferred Maintenance:**	$20,538
Facility Condition Index:	0.14 - Good	**City Code:**	CARLTON	**Ext. Gross Area:**	1,124
Building Code:	T7910090284	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$312,523
Building Name:	CARLTON SB35 - OFFICE BUILDING	**Address:**	1369 Interstate 35	**Deferred Maintenance:**	$59,300
Facility Condition Index:	0.19 - Fair	**City Code:**	CARLTON	**Ext. Gross Area:**	1,352

Site: T791A90294 - DULUTH - AIR QUALITY

Building Code:	T7910090294	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$52,429
Building Name:	DULUTH - AIR QUALITY - SVC BLDG	**Address:**	Superior Street Near Lief Erickson T	**Deferred Maintenance:**	$5,129
Facility Condition Index:	0.10 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	312

Site: T791A90298 - PIKE LAKE - TRUCK STATION

Building Code:	T7910020237	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$840,435
Building Name:	PIKE LAKE - SALT/SAND STORAGE	**Address:**	4787 Midway Road	**Deferred Maintenance:**	$16,809
Facility Condition Index:	0.02 - Excellent	**City Code:**	DULUTH	**Ext. Gross Area:**	9,542

Building Code: T7910090285
Building Name: PIKE LAKE - BRINE BUILDING
Facility Condition Index: 0.13 - Good

Cost Model Name: Single-story Work Facility
Address: 4787 Midway Road
City Code: DULUTH

Current Replacement Value: $111,841
Deferred Maintenance: $14,775
Ext. Gross Area: 784

Building Code: T7910090299
Building Name: PIKE LAKE - POLE STORAGE
Facility Condition Index: 0.06 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 4787 Midway Road
City Code: DULUTH

Current Replacement Value: $632,482
Deferred Maintenance: $39,495
Ext. Gross Area: 4,664

Site: T791A92125 - SAGINAW - WEIGH SCALE

Building Code: T7910090216
Building Name: SAGINAW - WS MISC STORAGE
Facility Condition Index: 0.18 - Fair

Cost Model Name: Single-story Work Facility
Address: 7426 Hwy 2
City Code: SAGINAW

Current Replacement Value: $105,250
Deferred Maintenance: $19,170
Ext. Gross Area: 624

Building Code: T7910092125
Building Name: SAGINAW - WEIGH SCALE
Facility Condition Index: 0.12 - Good

Cost Model Name: Single-story Office/Public Access Facility
Address: 7426 Highway 2
City Code: SAGINAW

Current Replacement Value: $673,134
Deferred Maintenance: $80,975
Ext. Gross Area: 3,065

Site: T791AR035880 - KETTLE RIVER - REST AREA

Building Code: T7910095105
Building Name: KETTLE RIVER - REST AREA
Facility Condition Index: 0.09 - Good

Cost Model Name: Single-story Office/Public Access Facility
Address: I-35 North Bound
City Code: SANDSTONE

Current Replacement Value: $958,752
Deferred Maintenance: $89,507
Ext. Gross Area: 3,182

Building Code: T7910095130
Building Name: KETTLE RIVER - RA MISC STORAGE
Facility Condition Index: 0.11 - Good

Cost Model Name: Single-story Work Facility
Address: I-35 Northbound
City Code: SANDSTONE

Current Replacement Value: $17,090
Deferred Maintenance: $1,925
Ext. Gross Area: 144

Site: T791AR045880 - GENERAL ANDREWS - REST AREA

Building Code: T7910095106
Building Name: GENERAL ANDREWS - REST AREA
Facility Condition Index: 0.09 - Good

Cost Model Name: Single-story Office/Public Access Facility
Address: I-35 Southbound
City Code: WILLOW RIVER

Current Replacement Value: $958,752
Deferred Maintenance: $83,865
Ext. Gross Area: 3,182

Building Code: T7910095131
Building Name: GENERAL ANDREWS - RA MISC STORAGE
Facility Condition Index: 0.13 - Good

Cost Model Name: Single-story Work Facility
Address: I-35 Southbound
City Code: WILLOW RIVER

Current Replacement Value: $14,769
Deferred Maintenance: $1,878
Ext. Gross Area: 157

Site: T791AR216982 - THOMPSON HILL - REST AREA TIC

Building Code: T7910092141
Building Name: THOMPSON HILL- PATROL OFFICE
Facility Condition Index: 0.16 - Fair

Cost Model Name: Single-story Office/Public Access Facility
Address: 8525 West Skyline Drive
City Code: DULUTH

Current Replacement Value: $783,800
Deferred Maintenance: $127,240
Ext. Gross Area: 2,731

Building Code:	T7910095104	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,342,467
Building Name:	THOMPSON HILL - REST AREA TIC	**Address:**	8525 West Skyline Drive	**Deferred Maintenance:**	$309,469
Facility Condition Index:	0.23 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	4,185
Building Code:	T7910095132	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,846
Building Name:	THOMPSON HILL - RA MISC STORAGE	**Address:**	8525 West Skyline Drive	**Deferred Maintenance:**	$1,449
Facility Condition Index:	0.09 - Good	**City Code:**	DULUTH	**Ext. Gross Area:**	120

Site: T791AR340980 - CULKIN - REST AREA

Building Code:	T7910095103	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$450,879
Building Name:	CULKIN - REST AREA	**Address:**	I-35 Northbound	**Deferred Maintenance:**	$58,126
Facility Condition Index:	0.13 - Good	**City Code:**	MAHTOWA	**Ext. Gross Area:**	1,964
Building Code:	T7910095133	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,311
Building Name:	CULKIN - RA MISC STORAGE	**Address:**	I-35 Northbound	**Deferred Maintenance:**	$4,260
Facility Condition Index:	0.14 - Good	**City Code:**	MAHTOWA	**Ext. Gross Area:**	384

Site: T791AR356917 - INDEPENDANCE - REST AREA

Building Code:	T7910095117	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$162,460
Building Name:	INDEPENDENCE - REST AREA	**Address:**	Junction TH 53 and TH 33	**Deferred Maintenance:**	$30,370
Facility Condition Index:	0.19 - Fair	**City Code:**	INDEPENDENCE	**Ext. Gross Area:**	154

Site: T791AR363880 - KNIFE RIVER - REST AREA

Building Code:	T7910095116	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$125,899
Building Name:	KNIFE RIVER - REST AREA	**Address:**	TH 61	**Deferred Maintenance:**	$34,608
Facility Condition Index:	0.27 - Fair	**City Code:**	DULUTH	**Ext. Gross Area:**	322

Site: T791AR371604 - MOUNT JOSEPHINE - REST AREA

Building Code:	T7910095126	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$154,182
Building Name:	MOUNT JOSEPHINE: RA	**Address:**	Hwy 61	**Deferred Maintenance:**	$3,084
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRAND PORTAGE	**Ext. Gross Area:**	392

Site: T791AR380121 - MCGREGOR - REST AREA

Building Code:	T7910095122	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$149,435
Building Name:	McGREGOR - REST AREA	**Address:**	TH 210	**Deferred Maintenance:**	$36,012
Facility Condition Index:	0.24 - Fair	**City Code:**	MCGREGOR	**Ext. Gross Area:**	492

Site: T791AR743806 - TETTEGOUCHE - REST AREA

Building Code:	T7910095127	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,715,872
Building Name:	TETTEGOUCHE - REST AREA	**Address:**	474 HIGHWAY 61 E	**Deferred Maintenance:**	$77,381
Facility Condition Index:	0.05 - Excellent	**City Code:**	SILVER BAY	**Ext. Gross Area:**	4,154

Site: T791AR876906 - FLOODWOOD RA

Building Code:	T7910095135	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$392,253
Building Name:	FLOODWOOD - REST AREA	**Address:**	223 W HIGHWAY 2	**Deferred Maintenance:**	$105,998
Facility Condition Index:	0.27 - Fair	**City Code:**	FLOODWOOD	**Ext. Gross Area:**	1,600

Site: T791AR883805 - GOOSEBERRY FALLS - REST AREA

Building Code:	T7910095121	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,155,114
Building Name:	GOOSEBERRY FALLS - REST AREA	**Address:**	3206 Highway 61	**Deferred Maintenance:**	$117,404
Facility Condition Index:	0.10 - Good	**City Code:**	TWO HARBORS	**Ext. Gross Area:**	3,137

Site: T791AR921602 - CUT FACE CREEK - REST AREA

Building Code:	T7910095119	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$161,182
Building Name:	CUT FACE CREEK - REST AREA	**Address:**	Highway 61	**Deferred Maintenance:**	$13,945
Facility Condition Index:	0.09 - Good	**City Code:**	GRAND MARAIS	**Ext. Gross Area:**	492

Site: T791AR931601 - CROSS RIVER - REST AREA

Building Code:	T7910095123	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$161,182
Building Name:	CROSS RIVER - REST AREA	**Address:**	Highway 61	**Deferred Maintenance:**	$13,945
Facility Condition Index:	0.09 - Good	**City Code:**	SCHROEDER	**Ext. Gross Area:**	492

Site: T791AR940102 - BIG SANDY LAKE - REST AREA

Building Code:	T7910095124	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$30,997
Building Name:	BIG SANDY LAKE - REST AREA	**Address:**	Trunk Highway 65	**Deferred Maintenance:**	$1,764
Facility Condition Index:	0.06 - Good	**City Code:**	PALISADE	**Ext. Gross Area:**	154

Site: T791B20107 - MELRUDE - LOADING SITE

Building Code:	T7915020107	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$47,959
Building Name:	MELRUDE - SALT/SAND STORAGE	**Address:**	1919 US 53	**Deferred Maintenance:**	$5,561
Facility Condition Index:	0.12 - Good	**City Code:**	COTTON	**Ext. Gross Area:**	533
Building Code:	T7915090164	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$90,172
Building Name:	MELRUDE - MISC STORAGE	**Address:**	1919 US 53	**Deferred Maintenance:**	$6,124
Facility Condition Index:	0.07 - Good	**City Code:**	COTTON	**Ext. Gross Area:**	660

Site: T791B20111 - CANYON - LOADING SITE

Building Code:	T7915020111	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$87,925
Building Name:	CANYON - SALT/SAND STORAGE	**Address:**	7285 Hwy 53	**Deferred Maintenance:**	$6,688
Facility Condition Index:	0.08 - Good	**City Code:**	CANYON	**Ext. Gross Area:**	957
Building Code:	T7915090163	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$59,021
Building Name:	CANYON - MISC STORAGE	**Address:**	7285 Hwy 53	**Deferred Maintenance:**	$4,008
Facility Condition Index:	0.07 - Good	**City Code:**	CANYON	**Ext. Gross Area:**	432

Site: T791B20112 - BUCK LAKE - LOADING SITE

Building Code:	T7915020112	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$49,642
Building Name:	BUCK LAKE - SALT/SAND STORAGE	**Address:**	49256 MN HWY 65	**Deferred Maintenance:**	$3,908
Facility Condition Index:	0.08 - Good	**City Code:**	NASHWAUK	**Ext. Gross Area:**	554
Building Code:	T7915090167	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$72,552
Building Name:	BUCK LAKE - MISC STORAGE	**Address:**	49256 MN HWY 65	**Deferred Maintenance:**	$2,005
Facility Condition Index:	0.03 - Excellent	**City Code:**	NASHWAUK	**Ext. Gross Area:**	560

Site: T791B20116 - TALMOON - LOADING SITE

Building Code:	T7915020116	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$45,478
Building Name:	TALMOON - SALT/SAND STORAGE	**Address:**	TH 6 - 1.75 MI So of TH286	**Deferred Maintenance:**	$5,800
Facility Condition Index:	0.13 - Good	**City Code:**	TALMOON	**Ext. Gross Area:**	533
Building Code:	T7915090161	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$72,552
Building Name:	TALMOON - MISC STORAGE	**Address:**	TH 6 - 1.75 MI So of TH286	**Deferred Maintenance:**	$4,927
Facility Condition Index:	0.07 - Good	**City Code:**	TALMOON	**Ext. Gross Area:**	560

Site: T791B20120 - BIG FALLS - LOADING SITE

Building Code:	T7915020120	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$286,735
Building Name:	BIG FALLS - SALT/SAND STORAGE	**Address:**	7515 COUNTY ROAD 13	**Deferred Maintenance:**	$28,792
Facility Condition Index:	0.10 - Good	**City Code:**	BIG FALLS	**Ext. Gross Area:**	2,528

Site: T791B20121 - KINMOUNT - LOADING SITE

Building Code:	T7915020121	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$285,567
Building Name:	KINMOUNT - SALT/SAND STORAGE	**Address:**	TH 53 & Sheep Ranch Road	**Deferred Maintenance:**	$27,771
Facility Condition Index:	0.10 - Good	**City Code:**	ORR	**Ext. Gross Area:**	2,496

Site: T791B20122 - BIWABIK - LOADING SITE

Building Code: T7915020122
Building Name: BIWABIK - SALT/SAND STORAGE
Facility Condition Index: 0.21 - Fair

Cost Model Name: Open Air Storage Structure
Address: 600 1st St So
City Code: BIWABIK

Current Replacement Value: $174,132
Deferred Maintenance: $37,040
Ext. Gross Area: 1,522

Site: T791B20125 - LINDEN GROVE - LOADING SITE

Building Code: T7915020125
Building Name: LINDEN GROVE - SALT/SAND STORAGE
Facility Condition Index: 0.18 - Fair

Cost Model Name: Open Air Storage Structure
Address: 11193 Hwy 1
City Code: LINDEN GROVE

Current Replacement Value: $74,682
Deferred Maintenance: $13,508
Ext. Gross Area: 830

Site: T791B20132 - ELY - LOADING SITE

Building Code: T7915020132
Building Name: ELY - SALT/SAND STORAGE
Facility Condition Index: 0.04 - Excellent

Cost Model Name: Open Air Storage Structure
Address: 1389 Hidden Valley Trail
City Code: ELY

Current Replacement Value: $146,918
Deferred Maintenance: $5,267
Ext. Gross Area: 12,000

Site: T791B90110 - HIBBING - STORAGE SITE

Building Code: T7915020113
Building Name: HIBBING - SALT/SAND STORAGE
Facility Condition Index: 0.37 - Poor

Cost Model Name: Open Air Storage Structure
Address: 3801 Marksmanship Center Road
City Code: HIBBING

Current Replacement Value: $243,678
Deferred Maintenance: $90,328
Ext. Gross Area: 2,528

Building Code: T7915090110
Building Name: HIBBING - STORAGE FACILITY
Facility Condition Index: 0.32 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 3801 Marksmanship Center Road
City Code: HIBBING

Current Replacement Value: $1,488,575
Deferred Maintenance: $475,817
Ext. Gross Area: 10,353

Building Code: T7915090139
Building Name: HIBBING - MISC STORAGE
Facility Condition Index: 0.28 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 3801 Marksmanship Center Road
City Code: HIBBING

Current Replacement Value: $360,108
Deferred Maintenance: $101,850
Ext. Gross Area: 2,721

Site: T791B90112 - COOK - TRUCK STATION

Building Code: T7915020109
Building Name: COOK - SALT/SAND STORAGE
Facility Condition Index: 0.15 - Fair

Cost Model Name: Open Air Storage Structure
Address: 305 River Street
City Code: COOK

Current Replacement Value: $275,396
Deferred Maintenance: $41,629
Ext. Gross Area: 2,528

Building Code: T7915090112
Building Name: COOK - TRUCK STATION
Facility Condition Index: 0.17 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 305 South River Street
City Code: COOK

Current Replacement Value: $1,039,020
Deferred Maintenance: $175,772
Ext. Gross Area: 6,658

Building Code: T7915090145
Building Name: COOK - POLE STORAGE BLDG
Facility Condition Index: 0.19 - Fair

Cost Model Name: Single-story Work Facility
Address: 305 South River Street
City Code: COOK

Current Replacement Value: $239,814
Deferred Maintenance: $46,191
Ext. Gross Area: 1,590

Site: T791B90122 - ELY - TRUCK STATION

Building Code:	T7915020123	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$170,154
Building Name:	ELY - SALT/SAND STORAGE	**Address:**	2100 East Sheridan Street	**Deferred Maintenance:**	$13,752
Facility Condition Index:	0.08 - Good	**City Code:**	ELY	**Ext. Gross Area:**	1,852
Building Code:	T7915090122	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$742,849
Building Name:	ELY - TRUCK STATION	**Address:**	2100 East Sheridan Street	**Deferred Maintenance:**	$86,082
Facility Condition Index:	0.12 - Good	**City Code:**	ELY	**Ext. Gross Area:**	3,778
Building Code:	T7915090146	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$118,726
Building Name:	ELY - MISC STORAGE	**Address:**	2100 East Sheridan Street	**Deferred Maintenance:**	$20,192
Facility Condition Index:	0.17 - Fair	**City Code:**	ELY	**Ext. Gross Area:**	1,003

Site: T791B90123 - VIRGINIA - HEADQUARTERS

Building Code:	T7915020118	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$580,375
Building Name:	VIRGINIA - SALT/SAND STORAGE	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$192,242
Facility Condition Index:	0.33 - Poor	**City Code:**	VIRGINIA	**Ext. Gross Area:**	5,011
Building Code:	T7915090102	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$57,130
Building Name:	VIRGINIA - MISC STORAGE	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$7,391
Facility Condition Index:	0.13 - Good	**City Code:**	VIRGINIA	**Ext. Gross Area:**	540
Building Code:	T7915090123	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$22,309,813
Building Name:	VIRGINIA - MAINTENANCE HEADQUARTERS	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$6,195,187
Facility Condition Index:	0.28 - Fair	**City Code:**	VIRGINIA	**Ext. Gross Area:**	81,823
Building Code:	T7915090127	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$117,635
Building Name:	VIRGINIA - EQUIP STORAGE	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$76,866
Facility Condition Index:	0.65 - Crisis	**City Code:**	VIRGINIA	**Ext. Gross Area:**	1,537
Building Code:	T7915090134	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,964
Building Name:	VIRGINIA - MISC STORAGE	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$17,292
Facility Condition Index:	0.52 - Crisis	**City Code:**	VIRGINIA	**Ext. Gross Area:**	502
Building Code:	T7915090138	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$316,694
Building Name:	VIRGINIA - MISC STORAGE	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$107,969
Facility Condition Index:	0.34 - Poor	**City Code:**	VIRGINIA	**Ext. Gross Area:**	2,875
Building Code:	T7915090142	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$56,697
Building Name:	VIRGINIA - MISC STORAGE	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$28,315
Facility Condition Index:	0.50 - Poor	**City Code:**	VIRGINIA	**Ext. Gross Area:**	780
Building Code:	T7915090149	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$838,008
Building Name:	VIRGINIA - POLE STORAGE BLDG	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$38,129
Facility Condition Index:	0.05 - Excellent	**City Code:**	VIRGINIA	**Ext. Gross Area:**	7,414

Building Code:	T7915090159	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$89,117
Building Name:	VIRGINIA - BRINE BUILDING	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$4,926
Facility Condition Index:	0.06 - Good	**City Code:**	VIRGINIA	**Ext. Gross Area:**	619
Building Code:	T7915090160	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$520,480
Building Name:	VIRGINIA - POLE STORAGE BLDG	**Address:**	101 N Hoover Road	**Deferred Maintenance:**	$13,646
Facility Condition Index:	0.03 - Excellent	**City Code:**	VIRGINIA	**Ext. Gross Area:**	5,261

Site: T791B90133 - LITTLEFORK - TRUCK STATION

Building Code:	T7915020124	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$329,789
Building Name:	LITTLEFORK - SALT/SAND STORAGE	**Address:**	4892 Co Rd 22	**Deferred Maintenance:**	$27,382
Facility Condition Index:	0.08 - Good	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	2,568
Building Code:	T7915090133	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,333,425
Building Name:	LITTLEFORK - TRUCK STATION	**Address:**	4892 Co Rd 22	**Deferred Maintenance:**	$278,145
Facility Condition Index:	0.21 - Fair	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	6,637
Building Code:	T7915090154	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$201,583
Building Name:	LITTLEFORK - MISC STORAGE	**Address:**	4892 Co Rd 22	**Deferred Maintenance:**	$38,103
Facility Condition Index:	0.19 - Fair	**City Code:**	LITTLEFORK	**Ext. Gross Area:**	1,360

Site: T791B90140 - INTERNATIONAL FALLS - TRUCK STATION

Building Code:	T7915020115	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$200,014
Building Name:	INTERNATIONAL FALLS - SALT/SAND STO	**Address:**	2407 Highway 332 South	**Deferred Maintenance:**	$23,971
Facility Condition Index:	0.12 - Good	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	1,852
Building Code:	T7915020129	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$603,805
Building Name:	INTERNATIONAL FALLS - SALT/SAND STO	**Address:**	2407 Highway 332 South	**Deferred Maintenance:**	$113,890
Facility Condition Index:	0.19 - Fair	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	6,915
Building Code:	T7915090144	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$146,380
Building Name:	INTERNATIONAL FALLS - MISC STORAGE	**Address:**	2407 Highway 332 South	**Deferred Maintenance:**	$17,871
Facility Condition Index:	0.12 - Good	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	1,070
Building Code:	T7915090148	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$142,270
Building Name:	INTERNATIONAL FALLS - MISC STORAGE	**Address:**	2407 Highway 332 South	**Deferred Maintenance:**	$20,785
Facility Condition Index:	0.15 - Good	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	893
Building Code:	T7915090168	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,710,922
Building Name:	INTERNATIONAL FALLS-TRUCK STATION	**Address:**	2407 Highway 332 South	**Deferred Maintenance:**	$35,080
Facility Condition Index:	0.02 - Excellent	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	8,862

Building Code:	T7915090170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$39,786
Building Name:	INTERNATIONAL FALLS-BRINE BLDG	**Address:**	2407 Highway 332 South	**Deferred Maintenance:**	$796
Facility Condition Index:	0.02 - Excellent	**City Code:**	INTL. FALLS	**Ext. Gross Area:**	117

Site: T791B90143 - GRAND RAPIDS - TRUCK STATION

Building Code:	T7915020119	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$261,151
Building Name:	GRAND RAPIDS - SALT/SAND STORAGE	**Address:**	2606 Hwy 2 East	**Deferred Maintenance:**	$45,835
Facility Condition Index:	0.18 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	2,528
Building Code:	T7915020131	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,052,457
Building Name:	GRAND RAPIDS - SALT/SAND STORAGE	**Address:**	2606 Hwy 2 East	**Deferred Maintenance:**	$198,515
Facility Condition Index:	0.19 - Fair	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	12,601
Building Code:	T7915090130	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$39,540
Building Name:	GRAND RAPIDS - MISC STORAGE	**Address:**	2606 Hwy 2 East	**Deferred Maintenance:**	$12,177
Facility Condition Index:	0.31 - Poor	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	432
Building Code:	T7915090143	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,277,644
Building Name:	GRAND RAPIDS - TRUCK STATION	**Address:**	2606 Hwy 2 East	**Deferred Maintenance:**	$461,435
Facility Condition Index:	0.14 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	17,668
Building Code:	T7915090152	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$77,754
Building Name:	GRAND RAPIDS - MISC STORAGE	**Address:**	2606 Hwy 2 East	**Deferred Maintenance:**	$7,738
Facility Condition Index:	0.10 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	576
Building Code:	T7915090153	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$501,053
Building Name:	GRAND RAPIDS - POLE STORAGE BLDG	**Address:**	2606 Hwy 2 East	**Deferred Maintenance:**	$34,845
Facility Condition Index:	0.07 - Good	**City Code:**	GRAND RAPIDS	**Ext. Gross Area:**	4,992

Site: T791B90155 - HIBBING - TRUCK STATION

Building Code:	T7915020127	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,036,144
Building Name:	HIBBING - SALT/SAND STORAGE	**Address:**	1425 East 23rd Street	**Deferred Maintenance:**	$137,282
Facility Condition Index:	0.13 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	5,163
Building Code:	T7915020128	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$309,593
Building Name:	HIBBING - SALT/SAND STORAGE	**Address:**	1425 East 23rd Street	**Deferred Maintenance:**	$24,994
Facility Condition Index:	0.08 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	2,706
Building Code:	T7915090155	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,699,330
Building Name:	HIBBING - TRUCK STATION	**Address:**	1425 East 23rd Street	**Deferred Maintenance:**	$409,290
Facility Condition Index:	0.11 - Good	**City Code:**	HIBBING	**Ext. Gross Area:**	51,214

Building Code:	T7915090162	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$467,416
Building Name:	HIBBING - POLE STORAGE BLDG	**Address:**	1425 East 23rd Street	**Deferred Maintenance:**	$22,683
Facility Condition Index:	0.05 - Excellent	**City Code:**	HIBBING	**Ext. Gross Area:**	4,416

Site: T791B90156 - DEER LAKE - TRUCK STATION

Building Code:	T7915020126	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$680,734
Building Name:	DEER LAKE - SALT/SAND STORAGE	**Address:**	27267 State Highway 1	**Deferred Maintenance:**	$47,116
Facility Condition Index:	0.07 - Good	**City Code:**	EFFIE	**Ext. Gross Area:**	5,417
Building Code:	T7915090156	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,225,517
Building Name:	DEER LAKE - TRUCK STATION	**Address:**	27267 State Hwy 1	**Deferred Maintenance:**	$69,419
Facility Condition Index:	0.06 - Good	**City Code:**	EFFIE	**Ext. Gross Area:**	6,823
Building Code:	T7915090157	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$324,452
Building Name:	DEER LAKE - POLE STORAGE BLDG	**Address:**	27267 State Highway 1	**Deferred Maintenance:**	$11,181
Facility Condition Index:	0.03 - Excellent	**City Code:**	EFFIE	**Ext. Gross Area:**	2,400
Building Code:	T7915090171	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$38,056
Building Name:	DEER LAKE - BRINE BUILDING	**Address:**	27267 State Hwy 1	**Deferred Maintenance:**	$3,653
Facility Condition Index:	0.10 - Good	**City Code:**	EFFIE	**Ext. Gross Area:**	117

Site: T791BR406917 - ANCHOR LAKE - REST AREA TIC

Building Code:	T7915095161	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$876,138
Building Name:	ANCHOR LAKE - REST AREA TIC	**Address:**	2702 Highway 53	**Deferred Maintenance:**	$186,624
Facility Condition Index:	0.21 - Fair	**City Code:**	EVELETH	**Ext. Gross Area:**	3,867
Building Code:	T7915095180	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$33,198
Building Name:	ANCHOR LAKE - RA MISC STORAGE	**Address:**	2702 Highway 53	**Deferred Maintenance:**	$7,041
Facility Condition Index:	0.21 - Fair	**City Code:**	EVELETH	**Ext. Gross Area:**	256

Site: T792A20311 - WASKISH - LOADING SITE

Building Code:	T7920020311	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$229,588
Building Name:	WASHKISH - SALT/SAND STORAGE	**Address:**	51701 MN 72	**Deferred Maintenance:**	$51,009
Facility Condition Index:	0.22 - Fair	**City Code:**	WASKISH	**Ext. Gross Area:**	4,985

Site: T792A20317 - LOMAN PIT - LOADING SITE

Building Code:	T7920020317	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$124,649
Building Name:	LOMAN PIT - SALT/SAND STORAGE	**Address:**	7602 MN-11	**Deferred Maintenance:**	$10,262
Facility Condition Index:	0.08 - Good	**City Code:**	LOMAN	**Ext. Gross Area:**	1,008

Site: T792A20318 - LAKE ITASCA - LOADING SITE

Building Code:	T7920020318	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$407,605
Building Name:	LAKE ITASCA - SALT/SAND STORAGE	**Address:**	16379 CR 108	**Deferred Maintenance:**	$35,737
Facility Condition Index:	0.09 - Good	**City Code:**	LAKE ITASCA	**Ext. Gross Area:**	3,757

Site: T792A20518 - WARROAD - LOADING SITE

Building Code:	T7925020518	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$155,267
Building Name:	WARROAD - SALT/SAND STORAGE	**Address:**	210 EAST GARFIELD	**Deferred Maintenance:**	$15,191
Facility Condition Index:	0.10 - Good	**City Code:**	WARROAD	**Ext. Gross Area:**	1,852

Site: T792A20521 - GREENBUSH - LOADING SITE

Building Code:	T7925020521	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$155,267
Building Name:	GREENBUSH - SALT/SAND STORAGE	**Address:**	234 Co Rd 4	**Deferred Maintenance:**	$11,424
Facility Condition Index:	0.07 - Good	**City Code:**	GREENBUSH	**Ext. Gross Area:**	1,852

Site: T792A90308 - BAUDETTE - TRUCK STATION

Building Code:	T7920020304	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$122,612
Building Name:	BAUDETTE - SALT/SAND STORAGE	**Address:**	504 Main Street E	**Deferred Maintenance:**	$14,695
Facility Condition Index:	0.12 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	1,037
Building Code:	T7920020312	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$165,887
Building Name:	BAUDETTE - SALT/SAND STORAGE	**Address:**	504 Main Street E	**Deferred Maintenance:**	$13,905
Facility Condition Index:	0.08 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	1,037
Building Code:	T7920020321	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$522,183
Building Name:	BAUDETTE - SALT/SAND STORAGE	**Address:**	504 Main Street E	**Deferred Maintenance:**	$28,184
Facility Condition Index:	0.05 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	5,589
Building Code:	T7920090312	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$107,023
Building Name:	BAUDETTE - MISC STORAGE	**Address:**	504 Main Street E	**Deferred Maintenance:**	$16,773
Facility Condition Index:	0.16 - Fair	**City Code:**	BAUDETTE	**Ext. Gross Area:**	532
Building Code:	T7920090332	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$282,134
Building Name:	BAUDETTE - POLE STORAGE	**Address:**	504 Main Street E	**Deferred Maintenance:**	$35,577
Facility Condition Index:	0.13 - Good	**City Code:**	BAUDETTE	**Ext. Gross Area:**	2,586
Building Code:	T7920090339	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,613,038
Building Name:	BAUDETTE - TRUCK STATION	**Address:**	504 Main Street E	**Deferred Maintenance:**	$42,143
Facility Condition Index:	0.03 - Excellent	**City Code:**	BAUDETTE	**Ext. Gross Area:**	8,017

Site: T792A90316 - WALKER - TRUCK STATION

Building Code:	T7920020308	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$88,951
Building Name:	WALKER - SALT/SAND STORAGE	**Address:**	8005 Sautbine Road NW	**Deferred Maintenance:**	$7,189
Facility Condition Index:	0.08 - Good	**City Code:**	WALKER	**Ext. Gross Area:**	1,037
Building Code:	T7920020316	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$474,870
Building Name:	WALKER - SALT/SAND STORAGE	**Address:**	8005 Sautbine Road NW	**Deferred Maintenance:**	$72,756
Facility Condition Index:	0.15 - Fair	**City Code:**	WALKER	**Ext. Gross Area:**	4,669
Building Code:	T7920090316	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,708,075
Building Name:	WALKER - TRUCK STATION	**Address:**	8005 Sautbine Road NW	**Deferred Maintenance:**	$310,820
Facility Condition Index:	0.18 - Fair	**City Code:**	WALKER	**Ext. Gross Area:**	7,184
Building Code:	T7920090333	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$371,479
Building Name:	WALKER - POLE STORAGE	**Address:**	8005 Sautbine Road NW	**Deferred Maintenance:**	$25,623
Facility Condition Index:	0.07 - Good	**City Code:**	WALKER	**Ext. Gross Area:**	3,098

Site: T792A90317 - BAGLEY - TRUCK STATION

Building Code:	T7920020307	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$107,126
Building Name:	BAGLEY - SALT/SAND STORAGE	**Address:**	20602 US 2	**Deferred Maintenance:**	$12,839
Facility Condition Index:	0.12 - Good	**City Code:**	BAGLEY	**Ext. Gross Area:**	1,037
Building Code:	T7920020315	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$375,817
Building Name:	BAGLEY - SALT/SAND STORAGE	**Address:**	20602 US 2	**Deferred Maintenance:**	$31,299
Facility Condition Index:	0.08 - Good	**City Code:**	BAGLEY	**Ext. Gross Area:**	3,424
Building Code:	T7920090317	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$971,323
Building Name:	BAGLEY - STORAGE FACILITY	**Address:**	20602 US 2	**Deferred Maintenance:**	$169,191
Facility Condition Index:	0.17 - Fair	**City Code:**	BAGLEY	**Ext. Gross Area:**	4,944
Building Code:	T7920090324	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$213,580
Building Name:	BAGLEY - MISC STORAGE	**Address:**	20602 US 2	**Deferred Maintenance:**	$32,576
Facility Condition Index:	0.15 - Fair	**City Code:**	BAGLEY	**Ext. Gross Area:**	1,793
Building Code:	T7920090340	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,582,785
Building Name:	BAGLEY TRUCK STATION	**Address:**	20602 US 2	**Deferred Maintenance:**	$40,446
Facility Condition Index:	0.03 - Excellent	**City Code:**	BAGLEY	**Ext. Gross Area:**	8,798

Site: T792A90319 - DEER RIVER - TRUCK STATION

Building Code:	T7920020309	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$426,017
Building Name:	DEER RIVER - SALT/SAND STORAGE	**Address:**	44703 Chase Lake Road	**Deferred Maintenance:**	$56,565
Facility Condition Index:	0.13 - Good	**City Code:**	DEER RIVER	**Ext. Gross Area:**	5,497

Building Code: T7920090319
Building Name: DEER RIVER - TRUCK STATION
Facility Condition Index: 0.20 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 44703 Chase Lake Road
City Code: DEER RIVER

Current Replacement Value: $990,105
Deferred Maintenance: $202,504
Ext. Gross Area: 5,144

Building Code: T7920090334
Building Name: DEER RIVER - POLE STORAGE
Facility Condition Index: 0.11 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 44703 Chase Lake Road
City Code: DEER RIVER

Current Replacement Value: $256,950
Deferred Maintenance: $27,657
Ext. Gross Area: 266

Site: T792A90323 - NORTHOME - TRUCK STATION

Building Code: T7920020319
Building Name: NORTHOME - SALT/SAND STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Open Air Storage Structure
Address: 12080 Town Road 299
City Code: NORTHOME

Current Replacement Value: $1,100,459
Deferred Maintenance: $137,219
Ext. Gross Area: 10,106

Building Code: T7920090322
Building Name: NORTHOME - UNHEATED STORAGE
Facility Condition Index: 0.25 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 12080 Town Road 299
City Code: NORTHOME

Current Replacement Value: $612,521
Deferred Maintenance: $150,236
Ext. Gross Area: 4,800

Building Code: T7920090323
Building Name: NORTHOME - TRUCK STATION
Facility Condition Index: 0.23 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 12080 Town Road 299
City Code: NORTHOME

Current Replacement Value: $759,381
Deferred Maintenance: $178,046
Ext. Gross Area: 4,283

Site: T792A90329 - PARK RAPIDS - TRUCK STATION

Building Code: T7920020302
Building Name: PARK RAPIDS - SALT/SAND STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Open Air Storage Structure
Address: 505 Industrial Park Road
City Code: PARK RAPIDS

Current Replacement Value: $108,322
Deferred Maintenance: $12,982
Ext. Gross Area: 1,068

Building Code: T7920020313
Building Name: PARK RAPIDS - SALT/SAND STORAGE
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Storage Structure
Address: 505 Industrial Park Road
City Code: PARK RAPIDS

Current Replacement Value: $351,177
Deferred Maintenance: $36,699
Ext. Gross Area: 3,008

Building Code: T7920090329
Building Name: PARK RAPIDS - TRUCK STATION
Facility Condition Index: 0.15 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 505 Industrial Park Road
City Code: PARK RAPIDS

Current Replacement Value: $1,260,227
Deferred Maintenance: $183,873
Ext. Gross Area: 7,618

Building Code: T7920090331
Building Name: PARK RAPIDS - POLE STORAGE
Facility Condition Index: 0.14 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 505 Industrial Park Road
City Code: PARK RAPIDS

Current Replacement Value: $471,314
Deferred Maintenance: $68,120
Ext. Gross Area: 4,800

Site: T792A90330 - BEMIDJI - HEADQUARTERS

Building Code: T7920020320
Building Name: BEMIDJI - SALT/SAND STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Open Air Storage Structure
Address: 3920 Hwy 2 West
City Code: BEMIDJI

Current Replacement Value: $1,070,734
Deferred Maintenance: $131,818
Ext. Gross Area: 9,382

Building Code:	T7920090330	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$33,258,176
Building Name:	BEMIDJI - HEADQUARTERS	**Address:**	3920 Hwy 2 West	**Deferred Maintenance:**	$3,317,740
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	113,625
Building Code:	T7920090335	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$945,437
Building Name:	BEMIDJI - POLE STORAGE	**Address:**	3920 Hwy 2 West	**Deferred Maintenance:**	$119,165
Facility Condition Index:	0.13 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	8,064
Building Code:	T7920090336	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,086,555
Building Name:	BEMIDJI - POLE STORAGE	**Address:**	3920 Hwy 2 West	**Deferred Maintenance:**	$149,691
Facility Condition Index:	0.14 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	8,064
Building Code:	T7920090337	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$94,060
Building Name:	BEMIDJI - HAZARD MATL STORAGE	**Address:**	3920 Hwy 2 West	**Deferred Maintenance:**	$9,029
Facility Condition Index:	0.10 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	384
Building Code:	T7920090338	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$405,486
Building Name:	BEMIDJI - MISC STORAGE	**Address:**	3920 Hwy 2 West	**Deferred Maintenance:**	$32,220
Facility Condition Index:	0.08 - Good	**City Code:**	BEMIDJI	**Ext. Gross Area:**	3,906
Building Code:	T7920090341	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,073,293
Building Name:	BEMIDJI - POLE STORAGE	**Address:**	3920 Hwy 2 West	**Deferred Maintenance:**	$21,466
Facility Condition Index:	0.02 - Excellent	**City Code:**	BEMIDJI	**Ext. Gross Area:**	7,300

Site: T792A90511 - WARREN - TRUCK STATION

Building Code:	T7925020502	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$214,845
Building Name:	WARREN - SALT/SAND STORAGE	**Address:**	417 South Main Street	**Deferred Maintenance:**	$16,742
Facility Condition Index:	0.08 - Good	**City Code:**	WARREN	**Ext. Gross Area:**	2,100
Building Code:	T7925020526	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$314,345
Building Name:	WARREN - SALT/SAND STORAGE	**Address:**	417 South Main Street	**Deferred Maintenance:**	$24,429
Facility Condition Index:	0.08 - Good	**City Code:**	WARREN	**Ext. Gross Area:**	3,615
Building Code:	T7925090514	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$28,831
Building Name:	WARREN - MISC STORAGE	**Address:**	417 South Main Street	**Deferred Maintenance:**	$20,451
Facility Condition Index:	0.71 - Crisis	**City Code:**	WARREN	**Ext. Gross Area:**	280
Building Code:	T7925090544	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,315,408
Building Name:	WARREN - TRUCK STATION	**Address:**	417 South Main Street	**Deferred Maintenance:**	$47,406
Facility Condition Index:	0.04 - Excellent	**City Code:**	WARREN	**Ext. Gross Area:**	7,260

Site: T792A90516 - HALLOCK - TRUCK STATION

Building Code:	T7925020520	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$509,337
Building Name:	HALLOCK - SALT/SAND STORAGE	**Address:**	307 SOUTH COLUMBUS AVENUE	**Deferred Maintenance:**	$34,425
Facility Condition Index:	0.07 - Good	**City Code:**	HALLOCK	**Ext. Gross Area:**	3,162
Building Code:	T7925090516	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$990,453
Building Name:	HALLOCK - TRUCK STATION	**Address:**	307 SOUTH COLUMBUS AVENUE	**Deferred Maintenance:**	$127,265
Facility Condition Index:	0.13 - Good	**City Code:**	HALLOCK	**Ext. Gross Area:**	6,056
Building Code:	T7925090542	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$265,400
Building Name:	HALLOCK - POLE STORAGE	**Address:**	307 SOUTH COLUMBUS AVENUE	**Deferred Maintenance:**	$16,650
Facility Condition Index:	0.06 - Good	**City Code:**	HALLOCK	**Ext. Gross Area:**	2,560

Site: T792A90517 - ADA - TRUCK STATION

Building Code:	T7925020515	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$193,292
Building Name:	ADA - SALT/SAND STORAGE	**Address:**	508 Fourth Street East	**Deferred Maintenance:**	$12,319
Facility Condition Index:	0.06 - Good	**City Code:**	ADA	**Ext. Gross Area:**	1,855
Building Code:	T7925020525	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$400,904
Building Name:	ADA-SALT/SAND STORAGE	**Address:**	508 Fourth Street East	**Deferred Maintenance:**	$8,018
Facility Condition Index:	0.02 - Excellent	**City Code:**	ADA	**Ext. Gross Area:**	4,800
Building Code:	T7925090517	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$957,062
Building Name:	ADA - TRUCK STATION	**Address:**	508 Fourth Street East	**Deferred Maintenance:**	$86,335
Facility Condition Index:	0.09 - Good	**City Code:**	ADA	**Ext. Gross Area:**	6,132
Building Code:	T7925090534	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$280,794
Building Name:	ADA - POLE STORAGE BLDG	**Address:**	508 Fourth Street East	**Deferred Maintenance:**	$21,247
Facility Condition Index:	0.08 - Good	**City Code:**	ADA	**Ext. Gross Area:**	2,586

Site: T792A90524 - ERSKINE - TRUCK STATION

Building Code:	T7925020504	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$135,700
Building Name:	ERSKINE - SALT/SAND STORAGE	**Address:**	34659 Hwy 59 SE	**Deferred Maintenance:**	$15,118
Facility Condition Index:	0.11 - Good	**City Code:**	ERSKINE	**Ext. Gross Area:**	1,852
Building Code:	T7925020512	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$373,491
Building Name:	ERSKINE - SALT/SAND STORAGE	**Address:**	34659 Hwy 59 SE	**Deferred Maintenance:**	$58,719
Facility Condition Index:	0.16 - Fair	**City Code:**	ERSKINE	**Ext. Gross Area:**	1,020
Building Code:	T7925090519	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$65,078
Building Name:	ERSKINE - MISC STORAGE	**Address:**	34659 Hwy 59 SE	**Deferred Maintenance:**	$14,683
Facility Condition Index:	0.23 - Fair	**City Code:**	ERSKINE	**Ext. Gross Area:**	616

Building Code: T7925090524
Building Name: ERSKINE - TRUCK STATION
Facility Condition Index: 0.18 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 34659 Hwy 59 SE
City Code: ERSKINE

Current Replacement Value: $1,260,613
Deferred Maintenance: $224,519
Ext. Gross Area: 8,871

Building Code: T7925090541
Building Name: ERSKINE - POLE STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 34659 Hwy 59 SE
City Code: ERSKINE

Current Replacement Value: $336,329
Deferred Maintenance: $40,839
Ext. Gross Area: 2,560

Site: T792A90525 - DELORME - STORAGE SITE

Building Code: T7925090525
Building Name: DELORME - MISC STORAGE
Facility Condition Index: 0.29 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: TH 2, 16 Mi East of Crookston
City Code: CROOKSTON

Current Replacement Value: $332,364
Deferred Maintenance: $96,731
Ext. Gross Area: 3,648

Site: T792A90526 - KARLSTAD - TRUCK STATION

Building Code: T7925020509
Building Name: KARLSTAD - SALT/SAND STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Open Air Storage Structure
Address: 312 Harding Street South
City Code: KARLSTAD

Current Replacement Value: $109,310
Deferred Maintenance: $7,637
Ext. Gross Area: 1,336

Building Code: T7925020516
Building Name: KARLSTAD - SALT/SAND STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Open Air Storage Structure
Address: 312 Harding Street South
City Code: KARLSTAD

Current Replacement Value: $244,070
Deferred Maintenance: $16,366
Ext. Gross Area: 2,472

Building Code: T7925090526
Building Name: KARLSTAD - TRUCK STATION
Facility Condition Index: 0.19 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 312 Harding Street South
City Code: KARLSTAD

Current Replacement Value: $613,732
Deferred Maintenance: $116,926
Ext. Gross Area: 3,699

Building Code: T7925090535
Building Name: KARLSTAD - POLE STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 312 Harding Street South
City Code: KARLSTAD

Current Replacement Value: $268,630
Deferred Maintenance: $18,458
Ext. Gross Area: 2,586

Site: T792A90527 - GRYGLA - TRUCK STATION

Building Code: T7925020507
Building Name: GRYGLA - SALT/SAND STORAGE
Facility Condition Index: 0.06 - Good

Cost Model Name: Open Air Storage Structure
Address: 410 South Marshall Ave
City Code: GRYGLA

Current Replacement Value: $111,038
Deferred Maintenance: $6,560
Ext. Gross Area: 1,190

Building Code: T7925020517
Building Name: GRYGLA - SALT/SAND STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Open Air Storage Structure
Address: 410 South Marshall Ave
City Code: GRYGLA

Current Replacement Value: $238,392
Deferred Maintenance: $28,271
Ext. Gross Area: 2,367

Building Code: T7925090523
Building Name: GRYGLA - MISC STORAGE
Facility Condition Index: 0.35 - Poor

Cost Model Name: Single-story Work Facility
Address: 410 South Marshall Ave
City Code: GRYGLA

Current Replacement Value: $175,254
Deferred Maintenance: $61,254
Ext. Gross Area: 1,200

Building Code:	T7925090527	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$569,586
Building Name:	GRYGLA - TRUCK STATION	**Address:**	410 South Marshall Ave	**Deferred Maintenance:**	$127,542
Facility Condition Index:	0.22 - Fair	**City Code:**	GRYGLA	**Ext. Gross Area:**	4,303

Site: T792A90528 - EAST GRAND FORKS - TRUCK STATION

Building Code:	T7925020510	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$358,411
Building Name:	EAST GRAND FORKS - SALT/SAND STRG	**Address:**	2512 10th Street NE	**Deferred Maintenance:**	$38,896
Facility Condition Index:	0.11 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	2,496
Building Code:	T7925020524	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$301,498
Building Name:	EAST GRAND FORKS - SALT/SAND STRG	**Address:**	2512 10th Street NE	**Deferred Maintenance:**	$18,821
Facility Condition Index:	0.06 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	3,615
Building Code:	T7925090528	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$631,031
Building Name:	EAST GRAND FORKS - TRUCK STATION	**Address:**	2512 10th Street NE	**Deferred Maintenance:**	$80,414
Facility Condition Index:	0.13 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	4,281
Building Code:	T7925090532	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$680,785
Building Name:	EAST GRAND FORKS - POLE STORAGE	**Address:**	2512 10th Street NE	**Deferred Maintenance:**	$83,093
Facility Condition Index:	0.12 - Good	**City Code:**	EAST GRAND FORKS	**Ext. Gross Area:**	5,632

Site: T792A90530 - CROOKSTON - HEADQUARTERS

Building Code:	T7925020511	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$337,545
Building Name:	CROOKSTON - SALT/SAND STORAGE	**Address:**	1320 Sunflower	**Deferred Maintenance:**	$57,107
Facility Condition Index:	0.17 - Fair	**City Code:**	CROOKSTON	**Ext. Gross Area:**	2,816
Building Code:	T7925020519	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$230,970
Building Name:	CROOKSTON - SALT/SAND STORAGE	**Address:**	1320 Sunflower	**Deferred Maintenance:**	$17,214
Facility Condition Index:	0.07 - Good	**City Code:**	CROOKSTON	**Ext. Gross Area:**	2,176
Building Code:	T7925020522	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$738,869
Building Name:	CROOKSTON - SALT/SAND	**Address:**	319 3RD AVENUE SOUTH	**Deferred Maintenance:**	$43,327
Facility Condition Index:	0.06 - Good	**City Code:**	CROOKSTON	**Ext. Gross Area:**	10,000
Building Code:	T7925090500	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,588,704
Building Name:	CROOKSTON - EQUIP STORAGE	**Address:**	1320 Sunflower	**Deferred Maintenance:**	$366,673
Facility Condition Index:	0.23 - Fair	**City Code:**	CROOKSTON	**Ext. Gross Area:**	10,275
Building Code:	T7925090501	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$891,504
Building Name:	CROOKSTON - EQUIP STORAGE	**Address:**	1320 Sunflower	**Deferred Maintenance:**	$178,314
Facility Condition Index:	0.20 - Fair	**City Code:**	CROOKSTON	**Ext. Gross Area:**	7,284

Building Code:	T7925090530	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$5,244,986
Building Name:	CROOKSTON - MAINT HEADQUARTERS	**Address:**	1320 Sunflower	**Deferred Maintenance:**	$428,424
Facility Condition Index:	0.08 - Good	**City Code:**	CROOKSTON	**Ext. Gross Area:**	25,225
Building Code:	T7925090531	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$914,152
Building Name:	CROOKSTON - POLE STORAGE	**Address:**	1320 Sunflower	**Deferred Maintenance:**	$110,440
Facility Condition Index:	0.12 - Good	**City Code:**	CROOKSTON	**Ext. Gross Area:**	4,480

Site: T792A90533 - THIEF RIVER FALLS - TRUCK STATION

Building Code:	T7925020514	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$582,096
Building Name:	THIEF RIVER FALLS - SALT/SAND STRG	**Address:**	248 125th Ave NE	**Deferred Maintenance:**	$52,987
Facility Condition Index:	0.09 - Good	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	5,238
Building Code:	T7925020523	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$680,322
Building Name:	THIEF RIVER FALLS - SAND/SALT STRG	**Address:**	248 125th Ave NE	**Deferred Maintenance:**	$52,869
Facility Condition Index:	0.08 - Good	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	8,403
Building Code:	T7925090533	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$16,531,388
Building Name:	THIEF RIVER FALLS - TRUCK STATION	**Address:**	248 125th Ave NE	**Deferred Maintenance:**	$1,710,807
Facility Condition Index:	0.10 - Good	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	68,400
Building Code:	T7925090540	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$602,243
Building Name:	THIEF RIVER FALLS - POLE STORGE	**Address:**	248 125th Ave NE	**Deferred Maintenance:**	$86,179
Facility Condition Index:	0.14 - Good	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	4,800
Building Code:	T7925090543	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$638,322
Building Name:	THIEF RIVER FALLS - UNHEATED STRG	**Address:**	248 125th Ave NE	**Deferred Maintenance:**	$21,959
Facility Condition Index:	0.03 - Excellent	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	5,760

Site: T792A90536 - ROSEAU - TRUCK STATION

Building Code:	T7925020513	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$594,239
Building Name:	ROSEAU - SALT/SAND STORAGE	**Address:**	1190 Center Street West	**Deferred Maintenance:**	$35,630
Facility Condition Index:	0.06 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	4,697
Building Code:	T7925090536	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,672,162
Building Name:	ROSEAU - TRUCK STATION	**Address:**	1190 Center Street West	**Deferred Maintenance:**	$82,382
Facility Condition Index:	0.05 - Excellent	**City Code:**	ROSEAU	**Ext. Gross Area:**	11,415
Building Code:	T7925090539	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$522,353
Building Name:	ROSEAU - POLE STORAGE	**Address:**	1190 Center Street West	**Deferred Maintenance:**	$37,763
Facility Condition Index:	0.07 - Good	**City Code:**	ROSEAU	**Ext. Gross Area:**	3,072

Site: T792A90547 - THIEF RIVER FALLS 6TH ST - STORAGE SITE

Building Code:	T7925090547	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$109,941
Building Name:	THIEF RIVER FALLS - MISC STRG	**Address:**	1090 6TH ST W	**Deferred Maintenance:**	$25,938
Facility Condition Index:	0.24 - Fair	**City Code:**	THIEF RIVER FALL	**Ext. Gross Area:**	1,360

Site: T792A92042 - ERSKINE - WEIGH SCALE

Building Code:	T7925090537	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,064
Building Name:	ERSKINE - SCALE - MISC STORAGE	**Address:**	23647 US HWY 2 SE	**Deferred Maintenance:**	$344
Facility Condition Index:	0.02 - Excellent	**City Code:**	ERSKINE	**Ext. Gross Area:**	96
Building Code:	T7925092042	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$954,720
Building Name:	ERSKINE - WEIGH SCALE	**Address:**	23647 US HWY 2 SE	**Deferred Maintenance:**	$40,777
Facility Condition Index:	0.04 - Excellent	**City Code:**	ERSKINE	**Ext. Gross Area:**	2,587

Site: T792AR141102 - CASS LAKE - REST AREA

Building Code:	T7920095211	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,460,212
Building Name:	CASS LAKE - REST AREA TIC	**Address:**	2 MILES EAST CASS LAKE ON US	**Deferred Maintenance:**	$108,754
Facility Condition Index:	0.07 - Good	**City Code:**	CASS LAKE	**Ext. Gross Area:**	4,566
Building Code:	T7920095231	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$36,736
Building Name:	CASS LAKE - RA MISC STORAGE	**Address:**	2 MILES EAST CASS LAKE ON US	**Deferred Maintenance:**	$1,015
Facility Condition Index:	0.03 - Excellent	**City Code:**	CASS LAKE	**Ext. Gross Area:**	192

Site: T792AR256005 - OAK LAKE - REST AREA

Building Code:	T7925095261	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$200,805
Building Name:	OAK LAKE - REST AREA	**Address:**	US2, MP59, 1 Mi E of Jct TH59	**Deferred Maintenance:**	$23,282
Facility Condition Index:	0.12 - Good	**City Code:**	MCINTOSH	**Ext. Gross Area:**	924
Building Code:	T7925095280	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,976
Building Name:	OAK LAKE - RA MISC STORAGE	**Address:**	US2, MP59, 1 Mi E of Jct TH59	**Deferred Maintenance:**	$9,009
Facility Condition Index:	0.27 - Fair	**City Code:**	MCINTOSH	**Ext. Gross Area:**	196

Site: T792AR436005 - LENGBY - REST AREA

Building Code:	T7925095260	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$77,260
Building Name:	LENGBY - REST AREA	**Address:**	TH 2 - 2 Mi No of Lengby	**Deferred Maintenance:**	$10,429
Facility Condition Index:	0.13 - Good	**City Code:**	LENGBY	**Ext. Gross Area:**	193

Site: T792AR446001 - FISHERS LANDING - REST AREA TIC

Building Code:	T7925095262	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$654,014
Building Name:	FISHERS LANDING - REST AREA TIC	**Address:**	US 2 9 Mi West of Crookston	**Deferred Maintenance:**	$194,753
Facility Condition Index:	0.30 - Fair	**City Code:**	FISHER	**Ext. Gross Area:**	2,270
Building Code:	T7925095281	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$33,976
Building Name:	FISHERS LANDING - RA MISC STORAGE	**Address:**	US 2 9 Mi West of Crookston	**Deferred Maintenance:**	$6,677
Facility Condition Index:	0.20 - Fair	**City Code:**	FISHER	**Ext. Gross Area:**	192

Site: T793A90413 - REMER - TRUCK STATION

Building Code:	T7930020419	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$584,118
Building Name:	REMER - SALT/SAND STORAGE	**Address:**	112 Eagle Ave NE	**Deferred Maintenance:**	$46,531
Facility Condition Index:	0.08 - Good	**City Code:**	REMER	**Ext. Gross Area:**	5,788
Building Code:	T7930090413	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$958,707
Building Name:	REMER - TRUCK STATION	**Address:**	112 Eagle Ave. NE	**Deferred Maintenance:**	$80,745
Facility Condition Index:	0.08 - Good	**City Code:**	REMER	**Ext. Gross Area:**	5,888
Building Code:	T7930090463	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$184,302
Building Name:	REMER - MISC STORAGE	**Address:**	112 Eagle Ave NE	**Deferred Maintenance:**	$17,047
Facility Condition Index:	0.09 - Good	**City Code:**	REMER	**Ext. Gross Area:**	1,384

Site: T793A90415 - MOTLEY - TRUCK STATION

Building Code:	T7930020417	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$656,902
Building Name:	MOTLEY - SALT/SAND STORAGE	**Address:**	149 River Front Lane	**Deferred Maintenance:**	$53,272
Facility Condition Index:	0.08 - Good	**City Code:**	MOTLEY	**Ext. Gross Area:**	6,240
Building Code:	T7930090415	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,514,049
Building Name:	MOTLEY - TRUCK STATION	**Address:**	149 River Front Lane	**Deferred Maintenance:**	$190,366
Facility Condition Index:	0.13 - Good	**City Code:**	MOTLEY	**Ext. Gross Area:**	8,549
Building Code:	T7930090435	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$317,084
Building Name:	MOTLEY - MISC STORAGE	**Address:**	149 River Front Lane	**Deferred Maintenance:**	$56,150
Facility Condition Index:	0.18 - Fair	**City Code:**	MOTLEY	**Ext. Gross Area:**	1,889
Building Code:	T7930090456	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$140,491
Building Name:	MOTLEY - MISC STORAGE	**Address:**	149 River Front Lane	**Deferred Maintenance:**	$5,678
Facility Condition Index:	0.04 - Excellent	**City Code:**	MOTLEY	**Ext. Gross Area:**	1,384
Building Code:	T7930090473	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$71,409
Building Name:	MOTLEY - COVERED STORAGE BINS	**Address:**	149 River Front Lane	**Deferred Maintenance:**	$1,428
Facility Condition Index:	0.02 - Excellent	**City Code:**	MOTLEY	**Ext. Gross Area:**	1,155

Site: T793A90438 - AITKIN - TRUCK STATION

Building Code:	T7930020423	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$588,176
Building Name:	AITKIN - SALT/SAND STORAGE	**Address:**	1158 Air Park Drive	**Deferred Maintenance:**	$100,108
Facility Condition Index:	0.17 - Fair	**City Code:**	AITKIN	**Ext. Gross Area:**	7,260
Building Code:	T7930090438	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,031,782
Building Name:	AITKIN - TRUCK STATION	**Address:**	1158 Air Park Drive	**Deferred Maintenance:**	$202,912
Facility Condition Index:	0.20 - Fair	**City Code:**	AITKIN	**Ext. Gross Area:**	5,306
Building Code:	T7930090449	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$278,315
Building Name:	AITKIN - POLE STORAGE BLDG	**Address:**	1158 Air Park Drive	**Deferred Maintenance:**	$28,840
Facility Condition Index:	0.10 - Good	**City Code:**	AITKIN	**Ext. Gross Area:**	2,560
Building Code:	T7930090466	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$152,805
Building Name:	AITKIN - MISC STORAGE	**Address:**	1158 Air Park Drive	**Deferred Maintenance:**	$10,908
Facility Condition Index:	0.07 - Good	**City Code:**	AITKIN	**Ext. Gross Area:**	1,424

Site: T793A90442 - PINE RIVER - TRUCK STATION

Building Code:	T7930020421	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$875,896
Building Name:	PINE RIVER - SALT/SAND STORAGE	**Address:**	3019 MN Hwy 371 SW	**Deferred Maintenance:**	$132,067
Facility Condition Index:	0.15 - Fair	**City Code:**	PINE RIVER	**Ext. Gross Area:**	8,424
Building Code:	T7930090442	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$813,583
Building Name:	PINE RIVER - TRUCK STATION	**Address:**	3019 MN Hwy 371 SW	**Deferred Maintenance:**	$175,043
Facility Condition Index:	0.22 - Fair	**City Code:**	PINE RIVER	**Ext. Gross Area:**	4,927
Building Code:	T7930090461	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$304,585
Building Name:	PINE RIVER - POLE STORAGE	**Address:**	3019 MN Hwy 371 SW	**Deferred Maintenance:**	$19,534
Facility Condition Index:	0.06 - Good	**City Code:**	PINE RIVER	**Ext. Gross Area:**	3,072

Site: T793A90443 - BAXTER - HEADQUARTERS

Building Code:	T7930020412	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,292,676
Building Name:	BAXTER - SALT/SAND STORAGE	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$204,535
Facility Condition Index:	0.16 - Fair	**City Code:**	BAXTER	**Ext. Gross Area:**	10,354
Building Code:	T7930020422	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,127,369
Building Name:	BAXTER - SALT/SAND STORAGE	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$22,547
Facility Condition Index:	0.02 - Excellent	**City Code:**	BAXTER	**Ext. Gross Area:**	13,872
Building Code:	T7930090439	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$748,267
Building Name:	BAXTER - POLE STORAGE	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$124,827
Facility Condition Index:	0.17 - Fair	**City Code:**	BAXTER	**Ext. Gross Area:**	3,200

Building Code:	T7930090443	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$30,605,837
Building Name:	BAXTER - DISTRICT HEADQUARTERS	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$4,904,850
Facility Condition Index:	0.16 - Fair	**City Code:**	BAXTER	**Ext. Gross Area:**	104,845
Building Code:	T7930090444	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,060,674
Building Name:	BAXTER - POLE STORAGE BLDG	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$167,355
Facility Condition Index:	0.16 - Fair	**City Code:**	BAXTER	**Ext. Gross Area:**	9,600
Building Code:	T7930090451	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$126,961
Building Name:	BAXTER - PATROL POLE STORAGE	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$9,921
Facility Condition Index:	0.08 - Good	**City Code:**	BAXTER	**Ext. Gross Area:**	1,040
Building Code:	T7930090452	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$449,602
Building Name:	BAXTER - POLE STORAGE	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$74,328
Facility Condition Index:	0.17 - Fair	**City Code:**	BAXTER	**Ext. Gross Area:**	3,837
Building Code:	T7930090464	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$36,479
Building Name:	BAXTER - HAZ MAT STORAGE	**Address:**	1991 Industrial Park Road S	**Deferred Maintenance:**	$3,648
Facility Condition Index:	0.10 - Good	**City Code:**	BAXTER	**Ext. Gross Area:**	190

Site: T793A90445 - ISLE - TRUCK STATION

Building Code:	T7930020418	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$579,057
Building Name:	ISLE - SALT/SAND STORAGE	**Address:**	1100 MN Hwy 47	**Deferred Maintenance:**	$48,174
Facility Condition Index:	0.08 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	4,980
Building Code:	T7930090447	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$60,715
Building Name:	ISLE - MISC STORAGE	**Address:**	1100 MN Hwy 47	**Deferred Maintenance:**	$7,274
Facility Condition Index:	0.12 - Good	**City Code:**	ISLE	**Ext. Gross Area:**	500
Building Code:	T7930090460	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$136,002
Building Name:	ISLE - MISC STORAGE	**Address:**	1100 Mn Hwy 47	**Deferred Maintenance:**	$27,971
Facility Condition Index:	0.21 - Fair	**City Code:**	ISLE	**Ext. Gross Area:**	1,120
Building Code:	T7930090471	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$824,286
Building Name:	ISLE - TRUCK STATION	**Address:**	1100 Mn Hwy 47	**Deferred Maintenance:**	$16,486
Facility Condition Index:	0.02 - Excellent	**City Code:**	ISLE	**Ext. Gross Area:**	4,695
Building Code:	T7930090472	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$73,734
Building Name:	ISLE - BRINE BUILDING	**Address:**	1100 Mn Hwy 47	**Deferred Maintenance:**	$1,475
Facility Condition Index:	0.02 - Excellent	**City Code:**	ISLE	**Ext. Gross Area:**	576

Site: T793A90450 - WADENA - TRUCK STATION

Building Code: T7930020416
Building Name: WADENA - SALT/SAND STORAGE
Facility Condition Index: 0.22 - Fair

Cost Model Name: Open Air Storage Structure
Address: 1701 Industrial Drive
City Code: WADENA

Current Replacement Value: $651,633
Deferred Maintenance: $144,293
Ext. Gross Area: 3,951

Building Code: T7930090450
Building Name: WADENA - TRUCK STATION
Facility Condition Index: 0.07 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1701 Industrial Drive
City Code: WADENA

Current Replacement Value: $1,159,167
Deferred Maintenance: $83,856
Ext. Gross Area: 7,073

Building Code: T7930090453
Building Name: WADENA - MISC STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Single-story Work Facility
Address: 1701 Industrial Drive
City Code: WADENA

Current Replacement Value: $48,164
Deferred Maintenance: $3,598
Ext. Gross Area: 448

Building Code: T7930090457
Building Name: WADENA - POLE STORAGE BLDG
Facility Condition Index: 0.07 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1701 Industrial Drive
City Code: WADENA

Current Replacement Value: $373,136
Deferred Maintenance: $25,365
Ext. Gross Area: 3,840

Building Code: T7930090474
Building Name: WADENA - COVERED STORAGE BINS
Facility Condition Index: 0.02 - Excellent

Cost Model Name: Open Air Storage Structure
Address: 1701 Industrial Drive
City Code: WADENA

Current Replacement Value: $73,449
Deferred Maintenance: $1,469
Ext. Gross Area: 1,155

Site: T793A90458 - LONG PRAIRIE - TRUCK STATION

Building Code: T7930020420
Building Name: LONG PRAIRIE - SALT/SAND STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Open Air Storage Structure
Address: 24291 STATE HWY 71
City Code: LONG PRAIRIE

Current Replacement Value: $569,576
Deferred Maintenance: $38,729
Ext. Gross Area: 5,788

Building Code: T7930090458
Building Name: LONG PRAIRIE - TRUCK STATION
Facility Condition Index: 0.18 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 24291 STATE HWY 71
City Code: LONG PRAIRIE

Current Replacement Value: $1,116,945
Deferred Maintenance: $200,833
Ext. Gross Area: 6,852

Building Code: T7930090459
Building Name: LONG PRAIRIE - POLE STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 24291 STATE HWY 71
City Code: LONG PRAIRIE

Current Replacement Value: $291,599
Deferred Maintenance: $20,153
Ext. Gross Area: 3,072

Site: T793A90462 - GARRISON - TRUCK STATION

Building Code: T7930020415
Building Name: GARRISON - SALT/SAND STORAGE
Facility Condition Index: 0.17 - Fair

Cost Model Name: Open Air Storage Structure
Address: 27365 MN Hwy 18
City Code: GARRISON

Current Replacement Value: $544,352
Deferred Maintenance: $94,343
Ext. Gross Area: 4,954

Building Code: T7930090441
Building Name: GARRISON - STORAGE FACILITY
Facility Condition Index: 0.31 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 27365 MN Hwy 18
City Code: GARRISON

Current Replacement Value: $541,017
Deferred Maintenance: $169,490
Ext. Gross Area: 3,229

Building Code:	T7930090455	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$163,060
Building Name:	GARRISON - MISC STORAGE	**Address:**	27365 MN Hwy 18	**Deferred Maintenance:**	$38,226
Facility Condition Index:	0.23 - Fair	**City Code:**	GARRISON	**Ext. Gross Area:**	1,652

Building Code:	T7930090462	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,294,983
Building Name:	GARRISON - TRUCK STATION	**Address:**	27365 MN HWY 18	**Deferred Maintenance:**	$129,698
Facility Condition Index:	0.10 - Good	**City Code:**	GARRISON	**Ext. Gross Area:**	8,383

Site: T793A90468 - LITTLE FALLS - TRUCK STATION

Building Code:	T7930020424	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$511,602
Building Name:	LITTLE FALLS - SALT/SAND STORAGE	**Address:**	15038 PINE AVENUE	**Deferred Maintenance:**	$10,232
Facility Condition Index:	0.02 - Excellent	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	6,660

Building Code:	T7930090468	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$5,942,730
Building Name:	LITTLE FALLS - TRUCK STATION	**Address:**	15038 PINE AVENUE	**Deferred Maintenance:**	$118,855
Facility Condition Index:	0.02 - Excellent	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	21,290

Building Code:	T7930090469	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$707,382
Building Name:	LITTLE FALLS - UNHEATED STORAGE	**Address:**	15038 PINE AVENUE	**Deferred Maintenance:**	$14,148
Facility Condition Index:	0.02 - Excellent	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	6,120

Building Code:	T7930090470	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$115,058
Building Name:	LITTLE FALLS - COVERED STORAGE BINS	**Address:**	15038 PINE AVENUE	**Deferred Maintenance:**	$2,301
Facility Condition Index:	0.02 - Excellent	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	1,861

Building Code:	T7930090475	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$71,409
Building Name:	LITTLE FALLS - COVERED STRG BINS	**Address:**	15038 PINE AVENUE	**Deferred Maintenance:**	$1,428
Facility Condition Index:	0.02 - Excellent	**City Code:**	LITTLE FALLS	**Ext. Gross Area:**	990

Site: T793AR961806 - BRAINERD LAKES - REST AREA TIC

Building Code:	T7930095312	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,840,964
Building Name:	BRAINERD LAKES - REST AREA TIC	**Address:**	7393 STATE HIGHWAY 371	**Deferred Maintenance:**	$202,819
Facility Condition Index:	0.11 - Good	**City Code:**	BRAINERD	**Ext. Gross Area:**	5,550

Building Code:	T7930095313	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,685
Building Name:	BRAINERD LAKES - MISC STRG	**Address:**	7393 STATE HIGHWAY 371	**Deferred Maintenance:**	$254
Facility Condition Index:	0.02 - Excellent	**City Code:**	BRAINERD	**Ext. Gross Area:**	0

Site: T793B20718 - CLEARWATER - LOADING SITE

Building Code:	T7935020718	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$86,395
Building Name:	CLEARWATER - SALT/SAND STORAGE	**Address:**	County Rd 75 1 Mi S TH 24	**Deferred Maintenance:**	$6,982
Facility Condition Index:	0.08 - Good	**City Code:**	CLEARWATER	**Ext. Gross Area:**	1,080

Site: T793B90713 - MORA - TRUCK STATION

Building Code:	T7935020702	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$429,950
Building Name:	MORA - SALT/SAND STORAGE	**Address:**	807 Howe Street	**Deferred Maintenance:**	$80,590
Facility Condition Index:	0.19 - Fair	**City Code:**	MORA	**Ext. Gross Area:**	5,054
Building Code:	T7935090713	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$996,550
Building Name:	MORA - TRUCK STATION	**Address:**	807 Howe Street	**Deferred Maintenance:**	$185,459
Facility Condition Index:	0.19 - Fair	**City Code:**	MORA	**Ext. Gross Area:**	6,176
Building Code:	T7935090780	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$359,497
Building Name:	MORA - UNHEATED STORAGE	**Address:**	807 Howe Street	**Deferred Maintenance:**	$7,881
Facility Condition Index:	0.02 - Excellent	**City Code:**	MORA	**Ext. Gross Area:**	3,840

Site: T793B90714 - FOLEY - TRUCK STATION

Building Code:	T7935020712	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$124,957
Building Name:	FOLEY - SALT/SAND STORAGE	**Address:**	531 Norman Ave No	**Deferred Maintenance:**	$19,958
Facility Condition Index:	0.16 - Fair	**City Code:**	FOLEY	**Ext. Gross Area:**	1,852
Building Code:	T7935090714	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$437,642
Building Name:	FOLEY - TRUCK STATION	**Address:**	531 Norman Ave No	**Deferred Maintenance:**	$72,867
Facility Condition Index:	0.17 - Fair	**City Code:**	FOLEY	**Ext. Gross Area:**	2,963

Site: T793B90735 - SAINT CLOUD - HEADQUARTERS

Building Code:	T7935090726	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$43,155
Building Name:	ST CLOUD - MISC STORAGE	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$11,469
Facility Condition Index:	0.27 - Fair	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	156
Building Code:	T7935090735	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$44,696,429
Building Name:	ST CLOUD - MAINTENANCE HEADQUARTERS	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$8,231,122
Facility Condition Index:	0.18 - Fair	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	169,970
Building Code:	T7935090736	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$150,946
Building Name:	ST CLOUD - SIGN STORAGE	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$16,329
Facility Condition Index:	0.11 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	1,610
Building Code:	T7935090745	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$432,102
Building Name:	ST CLOUD - BRIDGE HEATED SHOP	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$33,852
Facility Condition Index:	0.08 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	2,712
Building Code:	T7935090748	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$31,778
Building Name:	ST CLOUD - ESS/TRAFFIC STORAGE	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$3,724
Facility Condition Index:	0.12 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	289

Building Code:	T7935090756	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$779,546
Building Name:	ST CLOUD - MAINT STRG BARNES BARN	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$48,073
Facility Condition Index:	0.06 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	7,184
Building Code:	T7935090771	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,455,772
Building Name:	ST CLOUD - SHARED POLE STRG INVENT	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$122,800
Facility Condition Index:	0.08 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	9,222
Building Code:	T7935090775	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$268,060
Building Name:	ST CLOUD - POLE STRG PATROL IMPOUND	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$18,389
Facility Condition Index:	0.07 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	2,836
Building Code:	T7935090777	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$510,163
Building Name:	ST CLOUD - NEW SHARED POLE STRG	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$32,657
Facility Condition Index:	0.06 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	5,376
Building Code:	T7935090778	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$123,928
Building Name:	ST CLOUD - EMULSION STORAGE	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$8,042
Facility Condition Index:	0.06 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	1,050
Building Code:	T7935090786	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$131,502
Building Name:	ST CLOUD - PATROL STRG OLD DNR	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$16,514
Facility Condition Index:	0.13 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	1,363
Building Code:	T7935090787	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$43,441
Building Name:	ST CLOUD - PATROL POST BLDG	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$6,952
Facility Condition Index:	0.16 - Fair	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	231
Building Code:	T7935090788	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$43,534
Building Name:	ST CLOUD - TRASH COMPACTOR BLDG	**Address:**	3725 12th Street North	**Deferred Maintenance:**	$5,375
Facility Condition Index:	0.12 - Good	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	401

Site: T793B90740 - ALBANY - TRUCK STATION

Building Code:	T7935020710	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$18,868
Building Name:	ALBANY - SALT/SAND STORAGE	**Address:**	34916 County Road 10	**Deferred Maintenance:**	$5,213
Facility Condition Index:	0.28 - Fair	**City Code:**	ALBANY	**Ext. Gross Area:**	290
Building Code:	T7935020719	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$292,071
Building Name:	ALBANY - SALT/SAND STORAGE	**Address:**	34916 County Road 10	**Deferred Maintenance:**	$37,481
Facility Condition Index:	0.13 - Good	**City Code:**	ALBANY	**Ext. Gross Area:**	2,360
Building Code:	T7935090740	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$708,960
Building Name:	ALBANY - TRUCK STATION	**Address:**	34916 County Road 10	**Deferred Maintenance:**	$56,458
Facility Condition Index:	0.08 - Good	**City Code:**	ALBANY	**Ext. Gross Area:**	4,904

Building Code:	T7935090763	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$92,564
Building Name:	ALBANY - MISC STORAGE	**Address:**	34916 County Road 10	**Deferred Maintenance:**	$8,191
Facility Condition Index:	0.09 - Good	**City Code:**	ALBANY	**Ext. Gross Area:**	800
Building Code:	T7935090773	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$291,522
Building Name:	ALBANY - POLE STORAGE BLDG	**Address:**	34916 County Road 10	**Deferred Maintenance:**	$18,335
Facility Condition Index:	0.06 - Good	**City Code:**	ALBANY	**Ext. Gross Area:**	3,072

Site: T793B90741 - ELK RIVER - TRUCK STATION

Building Code:	T7935020713	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$88,162
Building Name:	ELK RIVER - SALT/SAND STORAGE	**Address:**	18938 Dodge Avenue Northwest	**Deferred Maintenance:**	$17,239
Facility Condition Index:	0.20 - Fair	**City Code:**	ELK RIVER	**Ext. Gross Area:**	1,425
Building Code:	T7935020720	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$194,449
Building Name:	ELK RIVER - SALT/SAND STORAGE	**Address:**	18938 Dodge Avenue Northwest	**Deferred Maintenance:**	$14,358
Facility Condition Index:	0.07 - Good	**City Code:**	ELK RIVER	**Ext. Gross Area:**	4,373
Building Code:	T7935090741	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,396,414
Building Name:	ELK RIVER - TRUCK STATION	**Address:**	18938 Dodge Avenue Northwest	**Deferred Maintenance:**	$308,920
Facility Condition Index:	0.13 - Good	**City Code:**	ELK RIVER	**Ext. Gross Area:**	11,406
Building Code:	T7935090743	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$47,773
Building Name:	ELK RIVER - BRINE BLDG	**Address:**	18938 Dodge Avenue Northwest	**Deferred Maintenance:**	$3,150
Facility Condition Index:	0.07 - Good	**City Code:**	ELK RIVER	**Ext. Gross Area:**	318
Building Code:	T7935090764	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$720,652
Building Name:	ELK RIVER - POLE STORAGE BLDG	**Address:**	18938 Dodge Avenue Northwest	**Deferred Maintenance:**	$88,224
Facility Condition Index:	0.12 - Good	**City Code:**	ELK RIVER	**Ext. Gross Area:**	5,375

Site: T793B90742 - MONTICELLO - TRUCK STATION

Building Code:	T7935020721	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$488,295
Building Name:	MONTICELLO - SALT/SAND STORAGE	**Address:**	112 Chelsea Road	**Deferred Maintenance:**	$60,944
Facility Condition Index:	0.12 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	5,227
Building Code:	T7935090742	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,092,186
Building Name:	MONTICELLO - TRUCK STATION	**Address:**	112 Chelsea Road	**Deferred Maintenance:**	$382,471
Facility Condition Index:	0.18 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	11,221
Building Code:	T7935090762	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$46,251
Building Name:	MONTICELLO - MISC STORAGE	**Address:**	112 Chelsea Road	**Deferred Maintenance:**	$11,531
Facility Condition Index:	0.25 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	444

Building Code:	T7935090779	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,787,502
Building Name:	MONTICELLO - EQUIP STORAGE	**Address:**	112 Chelsea Road	**Deferred Maintenance:**	$98,509
Facility Condition Index:	0.06 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	11,289
Building Code:	T7935090789	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$27,186
Building Name:	MONTICELLO - BRINE BUILDING	**Address:**	112 Chelsea Road	**Deferred Maintenance:**	$4,814
Facility Condition Index:	0.18 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	318

Site: T793B90749 - MILACA - TRUCK STATION

Building Code:	T7935020714	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$379,796
Building Name:	MILACA - SALT/SAND STORAGE	**Address:**	605 8th Street Northeast	**Deferred Maintenance:**	$46,325
Facility Condition Index:	0.12 - Good	**City Code:**	MILACA	**Ext. Gross Area:**	4,558
Building Code:	T7935090749	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,358,511
Building Name:	MILACA - STORAGE FACILITY	**Address:**	605 8th Street Northeast	**Deferred Maintenance:**	$219,972
Facility Condition Index:	0.16 - Fair	**City Code:**	MILACA	**Ext. Gross Area:**	5,543
Building Code:	T7935090770	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$270,035
Building Name:	MILACA - POLE STORAGE BLDG	**Address:**	605 8th Street Northeast	**Deferred Maintenance:**	$36,615
Facility Condition Index:	0.14 - Good	**City Code:**	MILACA	**Ext. Gross Area:**	2,560
Building Code:	T7935090784	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,532,893
Building Name:	MILACA - TRUCK STATION	**Address:**	605 8th Street Northeast	**Deferred Maintenance:**	$37,596
Facility Condition Index:	0.02 - Excellent	**City Code:**	MILACA	**Ext. Gross Area:**	8,845
Building Code:	T7935090791	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$47,688
Building Name:	MILACA - BRINE BUILDING	**Address:**	605 8th Street Northeast	**Deferred Maintenance:**	$5,908
Facility Condition Index:	0.12 - Good	**City Code:**	MILACA	**Ext. Gross Area:**	318

Site: T793B90753 - BUFFALO - TRUCK STATION

Building Code:	T7935020705	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$130,545
Building Name:	BUFFALO - SALT/SAND STORAGE	**Address:**	1137 TH 25 SE	**Deferred Maintenance:**	$15,974
Facility Condition Index:	0.12 - Good	**City Code:**	BUFFALO	**Ext. Gross Area:**	1,890
Building Code:	T7935020726	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$603,931
Building Name:	BUFFALO - SALT/SAND STORAGE	**Address:**	1137 TH 25 SE	**Deferred Maintenance:**	$110,997
Facility Condition Index:	0.18 - Fair	**City Code:**	BUFFALO	**Ext. Gross Area:**	6,513
Building Code:	T7935090753	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$906,357
Building Name:	BUFFALO - TRUCK STATION	**Address:**	1137 TH 25 SE	**Deferred Maintenance:**	$112,856
Facility Condition Index:	0.12 - Good	**City Code:**	BUFFALO	**Ext. Gross Area:**	7,628

Building Code:	T7935090757	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$337,785
Building Name:	BUFFALO - POLE STORAGE	**Address:**	1137 TH 25 SE	**Deferred Maintenance:**	$37,163
Facility Condition Index:	0.11 - Good	**City Code:**	BUFFALO	**Ext. Gross Area:**	2,586
Building Code:	T7935090792	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$54,560
Building Name:	BUFFALO - BRINE BUILDING	**Address:**	1137 TH 25 SE	**Deferred Maintenance:**	$3,960
Facility Condition Index:	0.07 - Good	**City Code:**	BUFFALO	**Ext. Gross Area:**	318

Site: T793B90769 - LAKE GEORGE - LIFT STATION

Building Code:	T7935090769	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$110,410
Building Name:	ST CLOUD - LAKE GEORGE - LIFT STAT	**Address:**	TH 23 at Lake George	**Deferred Maintenance:**	$59,164
Facility Condition Index:	0.54 - Crisis	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	636

Site: T793B90772 - SAUK CENTRE - TRUCK STATION

Building Code:	T7935020723	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$560,436
Building Name:	SAUK CENTRE - SALT/SAND STORAGE	**Address:**	1218 Beltline Road	**Deferred Maintenance:**	$25,118
Facility Condition Index:	0.04 - Excellent	**City Code:**	SAUK CENTRE	**Ext. Gross Area:**	4,160
Building Code:	T7935090772	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,422,155
Building Name:	SAUK CENTRE - TRUCK STATION	**Address:**	1218 Beltline Road	**Deferred Maintenance:**	$247,758
Facility Condition Index:	0.10 - Good	**City Code:**	SAUK CENTRE	**Ext. Gross Area:**	11,086
Building Code:	T7935090774	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$425,452
Building Name:	SAUK CENTRE - POLE STORAGE	**Address:**	1218 Beltine Road	**Deferred Maintenance:**	$95,130
Facility Condition Index:	0.22 - Fair	**City Code:**	SAUK CENTRE	**Ext. Gross Area:**	4,480

Site: T793B90781 - CAMBRIDGE - TRUCK STATION

Building Code:	T7935020728	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$432,794
Building Name:	CAMBRIDGE - SALT/SAND STORAGE	**Address:**	1620 KENNEDY STREET NORTH	**Deferred Maintenance:**	$8,656
Facility Condition Index:	0.02 - Excellent	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	7,200
Building Code:	T7935090781	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,276,588
Building Name:	CAMBRIDGE - TRUCK STATION	**Address:**	1620 KENNEDY STREET NORTH	**Deferred Maintenance:**	$69,200
Facility Condition Index:	0.03 - Excellent	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	13,949
Building Code:	T7935090785	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$390,522
Building Name:	CAMBRIDGE - UNHEATED STORAGE	**Address:**	1620 KENNEDY STREET NORTH	**Deferred Maintenance:**	$7,810
Facility Condition Index:	0.02 - Excellent	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	4,199
Building Code:	T7935090790	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$66,704
Building Name:	CAMBRIDGE - CVRD STRG BIN	**Address:**	1620 KENNEDY STREET NORTH	**Deferred Maintenance:**	$1,334
Facility Condition Index:	0.02 - Excellent	**City Code:**	CAMBRIDGE	**Ext. Gross Area:**	1,153

Site: T793B90782 - PAYNESVILLE - TRUCK STATION

Building Code:	T7935020727	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$505,382
Building Name:	PAYNESVILLE- SALT/SAND STORAGE	**Address:**	223 Industrial Loop W	**Deferred Maintenance:**	$24,336
Facility Condition Index:	0.05 - Excellent	**City Code:**	PAYNESVILLE	**Ext. Gross Area:**	6,403
Building Code:	T7935090782	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,663,960
Building Name:	PAYNESVILLE - TRUCK STATION	**Address:**	223 Industrial Loop W	**Deferred Maintenance:**	$91,046
Facility Condition Index:	0.05 - Good	**City Code:**	PAYNESVILLE	**Ext. Gross Area:**	9,441
Building Code:	T7935090783	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$406,961
Building Name:	PAYNESVILLE - UNHEATED STORAGE	**Address:**	223 Industrial Loop W	**Deferred Maintenance:**	$8,139
Facility Condition Index:	0.02 - Excellent	**City Code:**	PAYNESVILLE	**Ext. Gross Area:**	4,043

Site: T793BR307380 - FULLER LAKE - REST AREA

Building Code:	T7935095351	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$467,351
Building Name:	FULLER LAKE - REST AREA	**Address:**	I94 WB N of Jct TH 24 Clearwater	**Deferred Maintenance:**	$67,837
Facility Condition Index:	0.15 - Good	**City Code:**	CLEARWATER	**Ext. Gross Area:**	1,722
Building Code:	T7935095380	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$25,196
Building Name:	FULLER LAKE - RA MISC STORAGE	**Address:**	I94 WB N of Jct TH 24 Clearwater	**Deferred Maintenance:**	$8,297
Facility Condition Index:	0.33 - Poor	**City Code:**	CLEARWATER	**Ext. Gross Area:**	123

Site: T793BR317380 - MIDDLE SPUNK CREEK - REST AREA

Building Code:	T7935095352	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$567,738
Building Name:	MIDDLE SPUNK CREEK - REST AREA	**Address:**	I94WB 1 MI W of Avon Interchan	**Deferred Maintenance:**	$40,422
Facility Condition Index:	0.07 - Good	**City Code:**	AVON	**Ext. Gross Area:**	2,423
Building Code:	T7935095381	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$78,921
Building Name:	MIDDLE SPUNK CREEK - RA MISC STRG	**Address:**	I94WB 1 Mi W of Avon Interchan	**Deferred Maintenance:**	$7,328
Facility Condition Index:	0.09 - Good	**City Code:**	AVON	**Ext. Gross Area:**	473

Site: T793BR327380 - BIG SPUNK LAKE - REST AREA

Building Code:	T7935095353	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$549,169
Building Name:	BIG SPUNK LAKE - REST AREA	**Address:**	33202 INTERSTATE HWY 94	**Deferred Maintenance:**	$35,087
Facility Condition Index:	0.06 - Good	**City Code:**	AVON	**Ext. Gross Area:**	2,550
Building Code:	T7935095382	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$123,555
Building Name:	BIG SPUNK LAKE - RA MISC STORAGE	**Address:**	33202 INTERSTATE HWY 94	**Deferred Maintenance:**	$12,365
Facility Condition Index:	0.10 - Good	**City Code:**	AVON	**Ext. Gross Area:**	473

Site: T793BR498680 - ENFIELD - REST AREA

Building Code:	T7935095354	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$869,906
Building Name:	ENFIELD - REST AREA	**Address:**	I94 EB 6 Mi W of Jct TH 25	**Deferred Maintenance:**	$80,641
Facility Condition Index:	0.09 - Good	**City Code:**	MONTICELLO	**Ext. Gross Area:**	2,892
Building Code:	T7935095383	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,667
Building Name:	ENFIELD - RA MISC STORAGE	**Address:**	I94 EB 6 Mi W of Jct TH 25	**Deferred Maintenance:**	$15,052
Facility Condition Index:	0.26 - Fair	**City Code:**	MONTICELLO	**Ext. Gross Area:**	266

Site: T793BR734812 - RUM RIVER - REST AREA

Building Code:	T7935095361	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$429,865
Building Name:	RUM RIVER - REST AREA	**Address:**	TH 169, 11.0 Mi N of Milaca	**Deferred Maintenance:**	$90,558
Facility Condition Index:	0.21 - Fair	**City Code:**	MILACA	**Ext. Gross Area:**	1,637

Site: T793BR837103 - CENTRAL MINNESOTA - REST AREA

Building Code:	T7935095360	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$958,050
Building Name:	CENTRAL MINNESOTA - REST AREA TIC	**Address:**	TH 10 .2 Miles East of TH 23	**Deferred Maintenance:**	$171,098
Facility Condition Index:	0.18 - Fair	**City Code:**	ST. CLOUD	**Ext. Gross Area:**	3,367

Site: T794A20613 - PELICAN RAPIDS - LOADING SITE

Building Code:	T7940020613	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$293,156
Building Name:	PELICAN RAPIDS - SALT/SAND STORAGE	**Address:**	TH 59 N Edge of Town	**Deferred Maintenance:**	$104,921
Facility Condition Index:	0.36 - Poor	**City Code:**	PELICAN RAPIDS	**Ext. Gross Area:**	3,564

Site: T794A90611 - BRECKENRIDGE - TRUCK STATION

Building Code:	T7940020611	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$246,430
Building Name:	BRECKENRIDGE - SALT/SAND STORAGE	**Address:**	401 South 8th Street	**Deferred Maintenance:**	$66,761
Facility Condition Index:	0.27 - Fair	**City Code:**	BRECKENRIDGE	**Ext. Gross Area:**	2,696
Building Code:	T7940090611	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,060,319
Building Name:	BRECKENRIDGE - TRUCK STATION	**Address:**	401 South 8th Street	**Deferred Maintenance:**	$361,586
Facility Condition Index:	0.34 - Poor	**City Code:**	BRECKENRIDGE	**Ext. Gross Area:**	5,713
Building Code:	T7940090641	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$145,913
Building Name:	BRECKENRIDGE - POLE STORAGE	**Address:**	401 South 8th Street	**Deferred Maintenance:**	$33,824
Facility Condition Index:	0.23 - Fair	**City Code:**	BRECKENRIDGE	**Ext. Gross Area:**	1,459
Building Code:	T7940090669	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$28,570
Building Name:	BRECKENRIDGE - BRINE BUILDING	**Address:**	401 South 8th Street	**Deferred Maintenance:**	$6,298
Facility Condition Index:	0.22 - Fair	**City Code:**	BRECKENRIDGE	**Ext. Gross Area:**	144

Site: T794A90615 - FERGUS FALLS - TRUCK STATION

Building Code:	T7940020615	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,030,496
Building Name:	FERGUS FALLS - SALT/SAND STORAGE	**Address:**	1205 East Douglas Avenue	**Deferred Maintenance:**	$288,921
Facility Condition Index:	0.28 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	12,684
Building Code:	T7940090615	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$5,949,063
Building Name:	FERGUS FALLS - TRUCK STATION	**Address:**	1205 East Douglas Avenue	**Deferred Maintenance:**	$979,548
Facility Condition Index:	0.16 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	20,069
Building Code:	T7940090645	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$444,046
Building Name:	FERGUS FALLS - POLE STORAGE BLDG	**Address:**	1205 East Douglas Avenue	**Deferred Maintenance:**	$108,414
Facility Condition Index:	0.24 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	3,200
Building Code:	T7940090660	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$656,099
Building Name:	FERGUS FALLS - POLE STORAGE BLDG	**Address:**	1205 East Douglas Avenue	**Deferred Maintenance:**	$99,291
Facility Condition Index:	0.15 - Fair	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	6,720
Building Code:	T7940090670	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$28,486
Building Name:	FERGUS FALLS - BRINE BUILDING	**Address:**	1205 East Douglas Avenue	**Deferred Maintenance:**	$2,586
Facility Condition Index:	0.09 - Good	**City Code:**	FERGUS FALLS	**Ext. Gross Area:**	120

Site: T794A90616 - DETROIT LAKES - HEADQUARTERS

Building Code:	T7940020614	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,116,149
Building Name:	DETROIT LAKES - SALT/SAND STORAGE	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$133,813
Facility Condition Index:	0.12 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	14,120
Building Code:	T7940090616	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$43,890,943
Building Name:	DETROIT LAKES - HEADQUARTERS	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$10,133,605
Facility Condition Index:	0.23 - Fair	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	144,828
Building Code:	T7940090627	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,156,306
Building Name:	DETROIT LAKES - MISC STORAGE	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$384,772
Facility Condition Index:	0.33 - Poor	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	7,508
Building Code:	T7940090638	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,120,455
Building Name:	DETROIT LAKES - POLE STORAGE	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$832,914
Facility Condition Index:	0.39 - Poor	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	15,271
Building Code:	T7940090639	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,923
Building Name:	DETROIT LAKES - MISC STORAGE	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$5,360
Facility Condition Index:	0.30 - Fair	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	192
Building Code:	T7940090651	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$725,909
Building Name:	DETROIT LAKES - POLE STORAGE BLDG	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$71,703
Facility Condition Index:	0.10 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	7,200

Building Code:	T7940090656	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$814,428
Building Name:	DETROIT LAKES - EMERGENCY GENERATO	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$82,075
Facility Condition Index:	0.10 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	413
Building Code:	T7940090661	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$23,553
Building Name:	DETROIT LAKES - HAZ MATRL BLDG	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$2,355
Facility Condition Index:	0.10 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	720
Building Code:	T7940090676	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$482,039
Building Name:	DETROIT LAKES - UNHEATED STORAGE	**Address:**	1000 West TH 10	**Deferred Maintenance:**	$9,641
Facility Condition Index:	0.02 - Excellent	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	5,000

Site: T794A90624 - BARNESVILLE - TRUCK STATION

Building Code:	T7940020619	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$670,473
Building Name:	BARNESVILLE - SALT/SAND STORAGE	**Address:**	1201 Hwy 34	**Deferred Maintenance:**	$13,409
Facility Condition Index:	0.02 - Excellent	**City Code:**	BARNESVILLE	**Ext. Gross Area:**	8,100
Building Code:	T7940090624	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,735,892
Building Name:	BARNESVILLE - TRUCK STATION	**Address:**	1201 Hwy 34	**Deferred Maintenance:**	$487,998
Facility Condition Index:	0.28 - Fair	**City Code:**	BARNESVILLE	**Ext. Gross Area:**	8,880
Building Code:	T7940090630	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$89,524
Building Name:	BARNESVILLE - MISC STORAGE	**Address:**	1201 Hwy 34	**Deferred Maintenance:**	$7,098
Facility Condition Index:	0.08 - Good	**City Code:**	BARNESVILLE	**Ext. Gross Area:**	625
Building Code:	T7940090644	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$320,028
Building Name:	BARNESVILLE - POLE STORAGE BLDG	**Address:**	1201 Hwy 34	**Deferred Maintenance:**	$31,599
Facility Condition Index:	0.10 - Good	**City Code:**	BARNESVILLE	**Ext. Gross Area:**	3,200
Building Code:	T7940090668	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,285
Building Name:	BARNESVILLE - BRINE BUILDING	**Address:**	1201 Hwy 34	**Deferred Maintenance:**	$6,701
Facility Condition Index:	0.23 - Fair	**City Code:**	BARNESVILLE	**Ext. Gross Area:**	120

Site: T794A90625 - PERHAM - TRUCK STATION

Building Code:	T7940020618	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$517,929
Building Name:	PERHAM - SALT/SAND STORAGE	**Address:**	RR 3 Box 10	**Deferred Maintenance:**	$46,913
Facility Condition Index:	0.09 - Good	**City Code:**	PERHAM	**Ext. Gross Area:**	6,375
Building Code:	T7940090655	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$312,428
Building Name:	PERHAM - POLE STORAGE BLDG	**Address:**	711 3rd Avenue SE	**Deferred Maintenance:**	$47,022
Facility Condition Index:	0.15 - Fair	**City Code:**	PERHAM	**Ext. Gross Area:**	3,200

Building Code:	T7940090665	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,396,353
Building Name:	PERHAM - TRUCK STATION	**Address:**	711 3RD AVENUE SE	**Deferred Maintenance:**	$45,758
Facility Condition Index:	0.03 - Excellent	**City Code:**	PERHAM	**Ext. Gross Area:**	8,842
Building Code:	T7940090667	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,455
Building Name:	PERHAM - BRINE BUILDING	**Address:**	711 3RD AVENUE SE	**Deferred Maintenance:**	$1,074
Facility Condition Index:	0.04 - Excellent	**City Code:**	PERHAM	**Ext. Gross Area:**	576

Site: T794A90629 - HAWLEY - TRUCK STATION

Building Code:	T7940020605	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$246,430
Building Name:	HAWLEY - SALT/SAND STORAGE	**Address:**	500 US Hwy 10 East	**Deferred Maintenance:**	$111,904
Facility Condition Index:	0.45 - Poor	**City Code:**	HAWLEY	**Ext. Gross Area:**	2,696
Building Code:	T7940090629	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$731,601
Building Name:	HAWLEY - TRUCK STATION	**Address:**	500 US Hwy 10 East	**Deferred Maintenance:**	$345,033
Facility Condition Index:	0.47 - Poor	**City Code:**	HAWLEY	**Ext. Gross Area:**	4,261
Building Code:	T7940090654	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$321,188
Building Name:	HAWLEY - POLE STORAGE BLDG	**Address:**	500 US Hwy 10 East	**Deferred Maintenance:**	$45,514
Facility Condition Index:	0.14 - Good	**City Code:**	HAWLEY	**Ext. Gross Area:**	3,200
Building Code:	T7940090671	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,285
Building Name:	HAWLEY - BRINE BUILDING	**Address:**	500 US Hwy 10 East	**Deferred Maintenance:**	$4,939
Facility Condition Index:	0.17 - Fair	**City Code:**	HAWLEY	**Ext. Gross Area:**	120

Site: T794A90636 - HENNING - TRUCK STATION

Building Code:	T7940020607	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$271,513
Building Name:	HENNING - SALT/SAND STORAGE	**Address:**	100 Douglas Avenue	**Deferred Maintenance:**	$43,579
Facility Condition Index:	0.16 - Fair	**City Code:**	HENNING	**Ext. Gross Area:**	2,702
Building Code:	T7940090636	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,049,000
Building Name:	HENNING - TRUCK STATION	**Address:**	100 Douglas Avenue	**Deferred Maintenance:**	$241,674
Facility Condition Index:	0.23 - Fair	**City Code:**	HENNING	**Ext. Gross Area:**	5,337
Building Code:	T7940090653	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$312,428
Building Name:	HENNING - POLE STORAGE BLDG	**Address:**	100 Douglas Avenue	**Deferred Maintenance:**	$30,850
Facility Condition Index:	0.10 - Good	**City Code:**	HENNING	**Ext. Gross Area:**	3,200
Building Code:	T7940090672	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$28,486
Building Name:	HENNING - BRINE BUILDING	**Address:**	100 Douglas Avenue	**Deferred Maintenance:**	$3,215
Facility Condition Index:	0.11 - Good	**City Code:**	HENNING	**Ext. Gross Area:**	120

Site: T794A90640 - MAHNOMEN - TRUCK STATION

Building Code:	T7940020612	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$678,014
Building Name:	MAHNOMEN - SALT/SAND STORAGE	**Address:**	311 East Jefferson	**Deferred Maintenance:**	$176,150
Facility Condition Index:	0.26 - Fair	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	6,621
Building Code:	T7940090640	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,241,283
Building Name:	MAHNOMEN - TRUCK STATION	**Address:**	311 East Jefferson	**Deferred Maintenance:**	$336,289
Facility Condition Index:	0.27 - Fair	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	6,309
Building Code:	T7940090642	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$309,427
Building Name:	MAHNOMEN - POLE STORAGE BLDG	**Address:**	311 East Jefferson	**Deferred Maintenance:**	$39,392
Facility Condition Index:	0.13 - Good	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	3,094
Building Code:	T7940090673	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,417
Building Name:	MAHNOMEN - BRINE BUILDING	**Address:**	311 East Jefferson	**Deferred Maintenance:**	$2,671
Facility Condition Index:	0.09 - Good	**City Code:**	MAHNOMEN	**Ext. Gross Area:**	120

Site: T794A90646 - HAWLEY - LIFT STATION

Building Code:	T7940090646	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$47,564
Building Name:	HAWLEY - LIFT STATION	**Address:**	500 Hwy 10	**Deferred Maintenance:**	$7,278
Facility Condition Index:	0.15 - Fair	**City Code:**	HAWLEY	**Ext. Gross Area:**	152
Building Code:	T7940090650	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,048
Building Name:	HAWLEY - EMERGENCY GENERATOR	**Address:**	500 Hwy 10	**Deferred Maintenance:**	$7,337
Facility Condition Index:	0.15 - Fair	**City Code:**	HAWLEY	**Ext. Gross Area:**	266

Site: T794A90647 - MOORHEAD I94 - LIFT STATION

Building Code:	T7940090647	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$99,276
Building Name:	MOORHEAD I94&TH231 - LIFT STATION	**Address:**	I94/TH231	**Deferred Maintenance:**	$44,063
Facility Condition Index:	0.44 - Poor	**City Code:**	MOORHEAD	**Ext. Gross Area:**	480

Site: T794A90657 - MOORHEAD HWY 10 - LIFT STATION

Building Code:	T7940090663	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$536,439
Building Name:	MOORHEAD - LIFT STATION	**Address:**	TRUNK HIGHWAY 10	**Deferred Maintenance:**	$53,644
Facility Condition Index:	0.10 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	340

Site: T794A90658 - MOORHEAD - TRUCK STATION

Building Code:	T7940020617	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,059,389
Building Name:	MOORHEAD - SALT/SAND STORAGE	**Address:**	4150 30th Avenue South	**Deferred Maintenance:**	$455,475
Facility Condition Index:	0.43 - Poor	**City Code:**	MOORHEAD	**Ext. Gross Area:**	12,684

Building Code:	T7940090658	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$17,593,746
Building Name:	MOORHEAD - TRUCK STATION	**Address:**	4150 30th Avenue South	**Deferred Maintenance:**	$3,221,273
Facility Condition Index:	0.18 - Fair	**City Code:**	MOORHEAD	**Ext. Gross Area:**	62,943
Building Code:	T7940090659	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,181,279
Building Name:	MOORHEAD - UNHEATED STORAGE BLDG	**Address:**	4150 30th Avenue South	**Deferred Maintenance:**	$432,612
Facility Condition Index:	0.37 - Poor	**City Code:**	MOORHEAD	**Ext. Gross Area:**	12,013
Building Code:	T7940090674	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,285
Building Name:	MOORHEAD - BRINE BUILDING	**Address:**	4150 30th Avenue South	**Deferred Maintenance:**	$2,568
Facility Condition Index:	0.09 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	144
Building Code:	T7940090675	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$408,485
Building Name:	MOORHEAD - EMERGENGY GEN BLDG	**Address:**	4150 30th Avenue South	**Deferred Maintenance:**	$41,279
Facility Condition Index:	0.10 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	486

Site: T794A90662 - DILWORTH - ANTI-ICING BUILDING

Building Code:	T7940090662	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$66,624
Building Name:	DILWORTH ANTI-ICING BLDG	**Address:**		**Deferred Maintenance:**	$5,979
Facility Condition Index:	0.09 - Good	**City Code:**	DILWORTH	**Ext. Gross Area:**	168

Site: T794A90664 - GLYNDON TH10-TH336 - ANTI-ICING BUILDING

Building Code:	T7940090664	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$43,247
Building Name:	TH10-TH336 ANTI-ICING	**Address:**	22 HWY 336	**Deferred Maintenance:**	$7,547
Facility Condition Index:	0.17 - Fair	**City Code:**	GLYNDON	**Ext. Gross Area:**	168

Site: T794A90802 - APPLETON - LOADING SITE

Building Code:	T7945020808	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$105,178
Building Name:	APPLETON - SALT/SAND STORAGE	**Address:**	838 N Hering St	**Deferred Maintenance:**	$21,724
Facility Condition Index:	0.21 - Fair	**City Code:**	APPLETON	**Ext. Gross Area:**	1,037
Building Code:	T7945020814	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$224,961
Building Name:	APPLETON - SALT/SAND STORAGE	**Address:**	838 N Hering St	**Deferred Maintenance:**	$44,700
Facility Condition Index:	0.20 - Fair	**City Code:**	APPLETON	**Ext. Gross Area:**	2,696

Site: T794A90806 - WHEATON - TRUCK STATION

Building Code:	T7945020806	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$167,090
Building Name:	WHEATON - SALT/SAND STORAGE	**Address:**	505 2nd Avenue South	**Deferred Maintenance:**	$51,437
Facility Condition Index:	0.31 - Poor	**City Code:**	WHEATON	**Ext. Gross Area:**	1,828

Building Code:	T7945090806	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$868,067
Building Name:	WHEATON - TRUCK STATION	**Address:**	505 2nd Avenue South	**Deferred Maintenance:**	$195,231
Facility Condition Index:	0.22 - Fair	**City Code:**	WHEATON	**Ext. Gross Area:**	3,770
Building Code:	T7945090814	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$25,290
Building Name:	WHEATON - MISC STORAGE	**Address:**	505 2nd Avenue South	**Deferred Maintenance:**	$4,486
Facility Condition Index:	0.18 - Fair	**City Code:**	WHEATON	**Ext. Gross Area:**	224
Building Code:	T7945090840	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$29,285
Building Name:	WHEATON - BRINE BUILDING	**Address:**	505 2nd Avenue South	**Deferred Maintenance:**	$1,708
Facility Condition Index:	0.06 - Good	**City Code:**	WHEATON	**Ext. Gross Area:**	120

Site: T794A90808 - GLENWOOD - TRUCK STATION

Building Code:	T7945020816	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$786,511
Building Name:	GLENWOOD - SALT/SAND STORAGE	**Address:**	70 MN Hwy 55	**Deferred Maintenance:**	$148,477
Facility Condition Index:	0.19 - Fair	**City Code:**	GLENWOOD	**Ext. Gross Area:**	9,197
Building Code:	T7945090808	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,405,171
Building Name:	GLENWOOD - TRUCK STATION	**Address:**	70 MN Hwy 55	**Deferred Maintenance:**	$284,355
Facility Condition Index:	0.20 - Fair	**City Code:**	GLENWOOD	**Ext. Gross Area:**	6,475
Building Code:	T7945090829	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$315,348
Building Name:	GLENWOOD - POLE STORAGE BLDG	**Address:**	70 MN Hwy 55	**Deferred Maintenance:**	$21,669
Facility Condition Index:	0.07 - Good	**City Code:**	GLENWOOD	**Ext. Gross Area:**	3,200

Site: T794A90816 - EVANSVILLE - TRUCK STATION

Building Code:	T7945020821	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$725,941
Building Name:	EVANSVILLE - SALT/SAND STORAGE	**Address:**	20874 CO Rd 82 NW	**Deferred Maintenance:**	$14,519
Facility Condition Index:	0.02 - Excellent	**City Code:**	EVANSVILLE	**Ext. Gross Area:**	9,016
Building Code:	T7945090842	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,808,585
Building Name:	EVANSVILLE - TRUCK STATION	**Address:**	20874 CO Rd 82 NW	**Deferred Maintenance:**	$36,172
Facility Condition Index:	0.02 - Excellent	**City Code:**	EVANSVILLE	**Ext. Gross Area:**	11,454
Building Code:	T7945090844	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$518,899
Building Name:	EVANSVILLE - UNHEATED STRG	**Address:**	20874 CO Rd 82 NW	**Deferred Maintenance:**	$10,378
Facility Condition Index:	0.02 - Excellent	**City Code:**	EVANSVILLE	**Ext. Gross Area:**	5,000
Building Code:	T7945090845	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$93,955
Building Name:	EVANSVILLE - BRINE BLDG	**Address:**	20874 CO Rd 82 NW	**Deferred Maintenance:**	$1,879
Facility Condition Index:	0.02 - Excellent	**City Code:**	EVANSVILLE	**Ext. Gross Area:**	720

Building Code:	T7945090847	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$148,714
Building Name:	EVANSVILLE - CVRD STORAGE BINS(NEW)	**Address:**	20874 CO Rd 82 NW	**Deferred Maintenance:**	$2,974
Facility Condition Index:	0.02 - Excellent	**City Code:**	EVANSVILLE	**Ext. Gross Area:**	2,558

Site: T794A90818 - ALEXANDRIA - TRUCK STATION

Building Code:	T7945020813	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$918,659
Building Name:	ALEXANDRIA - SALT/SAND STORAGE	**Address:**	1405 Hwy 27 W	**Deferred Maintenance:**	$208,574
Facility Condition Index:	0.23 - Fair	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	9,080
Building Code:	T7945090818	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,554,778
Building Name:	ALEXANDRIA - TRUCK STATION	**Address:**	1405 Hwy 27 W	**Deferred Maintenance:**	$1,033,884
Facility Condition Index:	0.23 - Fair	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	20,278
Building Code:	T7945090835	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$689,863
Building Name:	ALEXANDRIA-UNHEATED STORAGE	**Address:**	1405 Hwy 27 W	**Deferred Maintenance:**	$13,797
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	5,100
Building Code:	T7945090836	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$282,065
Building Name:	ALEXANDRIA - UNHEATED STORAGE	**Address:**	1405 Hwy 27 W	**Deferred Maintenance:**	$59,984
Facility Condition Index:	0.21 - Fair	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	2,240

Site: T794A90819 - ORTONVILLE - TRUCK STATION

Building Code:	T7945020815	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$404,005
Building Name:	ORTONVILLE - SALT/SAND STORAGE	**Address:**	Ingersoll Ave TH 12	**Deferred Maintenance:**	$66,798
Facility Condition Index:	0.17 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	3,584
Building Code:	T7945090819	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,164,096
Building Name:	ORTONVILLE - TRUCK STATION	**Address:**	Ingersoll Ave TH 12	**Deferred Maintenance:**	$257,241
Facility Condition Index:	0.22 - Fair	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	4,946
Building Code:	T7945090831	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$335,787
Building Name:	ORTONVILLE - POLE STORAGE BLDG	**Address:**	Ingersoll Ave TH 12	**Deferred Maintenance:**	$20,570
Facility Condition Index:	0.06 - Good	**City Code:**	ORTONVILLE	**Ext. Gross Area:**	3,200

Site: T794A90820 - MORRIS - HEADQUARTERS

Building Code:	T7945020820	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$520,368
Building Name:	MORRIS - SALT/SAND STORAGE	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$10,407
Facility Condition Index:	0.02 - Excellent	**City Code:**	MORRIS	**Ext. Gross Area:**	6,403
Building Code:	T7945090820	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$10,079,860
Building Name:	MORRIS - HEADQUARTERS	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$1,847,794
Facility Condition Index:	0.18 - Fair	**City Code:**	MORRIS	**Ext. Gross Area:**	46,727

Building Code:	T7945090821	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$660,275
Building Name:	MORRIS - POLE STORAGE BLDG	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$85,636
Facility Condition Index:	0.13 - Good	**City Code:**	MORRIS	**Ext. Gross Area:**	5,050
Building Code:	T7945090827	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,747
Building Name:	MORRIS - HAZARD MATL STORAGE	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$5,856
Facility Condition Index:	0.33 - Poor	**City Code:**	MORRIS	**Ext. Gross Area:**	72
Building Code:	T7945090828	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,019,435
Building Name:	MORRIS - POLE STORAGE BLDG	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$63,999
Facility Condition Index:	0.06 - Good	**City Code:**	MORRIS	**Ext. Gross Area:**	9,408
Building Code:	T7945090832	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$117,066
Building Name:	MORRIS - WELLNESS BLDG	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$15,724
Facility Condition Index:	0.13 - Good	**City Code:**	MORRIS	**Ext. Gross Area:**	816
Building Code:	T7945090839	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$22,563
Building Name:	MORRIS - MISC STORAGE	**Address:**	610 MN Hwy 9 South	**Deferred Maintenance:**	$4,220
Facility Condition Index:	0.19 - Fair	**City Code:**	MORRIS	**Ext. Gross Area:**	100

Site: T794A90822 - BENSON - TRUCK STATION

Building Code:	T7945020811	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$206,770
Building Name:	BENSON - SALT/SAND STORAGE	**Address:**	500 22nd Street South	**Deferred Maintenance:**	$53,545
Facility Condition Index:	0.26 - Fair	**City Code:**	BENSON	**Ext. Gross Area:**	2,696
Building Code:	T7945090822	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,226,694
Building Name:	BENSON - TRUCK STATION	**Address:**	500 22nd Street South	**Deferred Maintenance:**	$227,214
Facility Condition Index:	0.19 - Fair	**City Code:**	BENSON	**Ext. Gross Area:**	6,195
Building Code:	T7945090825	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$153,472
Building Name:	BENSON - POLE STORAGE BLDG	**Address:**	500 22nd Street South	**Deferred Maintenance:**	$20,908
Facility Condition Index:	0.14 - Good	**City Code:**	BENSON	**Ext. Gross Area:**	1,563
Building Code:	T7945090837	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$28,050
Building Name:	BENSON - BRINE BUILDING	**Address:**	500 22nd Street South	**Deferred Maintenance:**	$1,446
Facility Condition Index:	0.05 - Good	**City Code:**	BENSON	**Ext. Gross Area:**	120

Site: T794A92054 - RED RIVER - WEIGH SCALE

Building Code:	T7940092054	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,653,120
Building Name:	RED RIVER - WEIGH SCALE	**Address:**	I94 EB 2 mi west of 34th ave.	**Deferred Maintenance:**	$60,453
Facility Condition Index:	0.04 - Excellent	**City Code:**	DILWORTH	**Ext. Gross Area:**	6,764

Site: T794AR015680 - HANSEL LAKE - REST AREA

Building Code:	T7940095400	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$235,153
Building Name:	HANSEL LAKE - REST AREA	**Address:**	11822 I94 WB	**Deferred Maintenance:**	$81,935
Facility Condition Index:	0.35 - Poor	**City Code:**	DALTON	**Ext. Gross Area:**	859
Building Code:	T7940095430	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$21,577
Building Name:	HANSEL LAKE - RA MISC STORAGE	**Address:**	11822 I94 WB	**Deferred Maintenance:**	$2,158
Facility Condition Index:	0.10 - Good	**City Code:**	DALTON	**Ext. Gross Area:**	174

Site: T794AR022180 - LAKE LATOKA - REST AREA

Building Code:	T7945095452	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$508,360
Building Name:	LAKE LATOKA - REST AREA	**Address:**	I94 EB - 1 MI NW Jct 94/29	**Deferred Maintenance:**	$46,877
Facility Condition Index:	0.09 - Good	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	1,652
Building Code:	T7945095481	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,539
Building Name:	LAKE LATOKA REST AREA - MISC STRG	**Address:**	I94 EB - 1 MI NW Jct 94/29	**Deferred Maintenance:**	$351
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	163

Site: T794AR051480 - MOORHEAD - REST AREA TIC

Building Code:	T7940090648	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$78,384
Building Name:	MOORHEAD REST AREA - LIFT STATION	**Address:**	2951 11 1/2 ST SOUTH	**Deferred Maintenance:**	$10,333
Facility Condition Index:	0.13 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	520
Building Code:	T7940095402	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,382,134
Building Name:	MOORHEAD - REST AREA TIC	**Address:**	2951 11 1/2 ST SOUTH	**Deferred Maintenance:**	$198,204
Facility Condition Index:	0.14 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	4,031
Building Code:	T7940095434	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$12,920
Building Name:	MOORHEAD - REST AREA MISC STRG	**Address:**	2951 11 1/2 ST SOUTH	**Deferred Maintenance:**	$1,292
Facility Condition Index:	0.10 - Good	**City Code:**	MOORHEAD	**Ext. Gross Area:**	120

Site: T794AR085607 - FRAZEE - REST AREA

Building Code:	T7940095411	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$686,749
Building Name:	FRAZEE - REST AREA	**Address:**	US 10, MP 55.25	**Deferred Maintenance:**	$116,452
Facility Condition Index:	0.17 - Fair	**City Code:**	FRAZEE	**Ext. Gross Area:**	2,067

Site: T794AR152180 - BURGEN LAKE - REST AREA

Building Code:	T7945095450	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$251,637
Building Name:	BURGEN LAKE - REST AREA	**Address:**	I-94 WB - 2 MI SW Alex	**Deferred Maintenance:**	$63,969
Facility Condition Index:	0.25 - Fair	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	912

Building Code:	T7945095480	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,539
Building Name:	BURGEN LAKE - RA MISC STRG OLD	**Address:**	I-94 WB - 2 MI SW Alex	**Deferred Maintenance:**	$351
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	163
Building Code:	T7945095482	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$26,541
Building Name:	BURGEN LAKE - MISC STRG NEW	**Address:**	I-94 WB - 2 MI SW Alex	**Deferred Maintenance:**	$6,487
Facility Condition Index:	0.24 - Fair	**City Code:**	ALEXANDRIA	**Ext. Gross Area:**	192

Site: T794AR535620 - OTTER TAIL LAKE - REST AREA

Building Code:	T7940095420	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$241,709
Building Name:	OTTER TAIL LAKE - REST AREA	**Address:**	TH78	**Deferred Maintenance:**	$61,018
Facility Condition Index:	0.25 - Fair	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	154
Building Code:	T7940095431	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,440
Building Name:	OTTER TAIL LAKE - RA MISC STORAGE	**Address:**	TH 78	**Deferred Maintenance:**	$329
Facility Condition Index:	0.02 - Excellent	**City Code:**	BATTLE LAKE	**Ext. Gross Area:**	96

Site: T794AR540304 - SAURER'S LAKE - REST AREA

Building Code:	T7940095421	**Cost Model Name:**	Vault Toilet	**Current Replacement Value:**	$109,693
Building Name:	SAUER'S LAKE - REST AREA	**Address:**	TH59	**Deferred Maintenance:**	$16,830
Facility Condition Index:	0.15 - Fair	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	154
Building Code:	T7940095433	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,440
Building Name:	SAUERS LAKE - MISC STORAGE	**Address:**	TH59	**Deferred Maintenance:**	$1,644
Facility Condition Index:	0.10 - Good	**City Code:**	DETROIT LAKES	**Ext. Gross Area:**	96

Site: T795C91194 - ROSEVILLE - WATERSEDGE HEADQUARTERS

Building Code:	T7990091194	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$29,918,900
Building Name:	ROSEVILLE - WATERSEDGE - DIVISION	**Address:**	1500 County Rd B2 W	**Deferred Maintenance:**	$5,565,341
Facility Condition Index:	0.19 - Fair	**City Code:**	ROSEVILLE	**Ext. Gross Area:**	162,759
Building Code:	T7990091195	**Cost Model Name:**	Mid-rise Office Building, 5 to 10 story	**Current Replacement Value:**	$12,431,610
Building Name:	ROSEVILLE - WATERSEDGE - TRAFFIC M	**Address:**	1500 County Rd B2 W	**Deferred Maintenance:**	$1,224,514
Facility Condition Index:	0.10 - Good	**City Code:**	ROSEVILLE	**Ext. Gross Area:**	56,223
Building Code:	T7990091196	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$373,964
Building Name:	ROSEVILLE - EMERG GEN BLDG	**Address:**	1500 County Rd B2 W	**Deferred Maintenance:**	$10,648
Facility Condition Index:	0.03 - Excellent	**City Code:**	ROSEVILLE	**Ext. Gross Area:**	840

Site: T795E91111 - HASTINGS ANTI-ICING BLDG

Building Code:	T7990091111	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$167,749
Building Name:	HASTINGS HWY 61 - ANTI-ICING BLDG	**Address:**		**Deferred Maintenance:**	$3,355
Facility Condition Index:	0.02 - Excellent	**City Code:**	HASTINGS	**Ext. Gross Area:**	952

Site: T795E91117 - MAPLEWOOD - METRO FLEET

Building Code:	T7990090918	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$26,605
Building Name:	MAPLEWOOD - MISC STRG	**Address:**	1771 MC MENEMY	**Deferred Maintenance:**	$4,966
Facility Condition Index:	0.19 - Fair	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	2,400
Building Code:	T7990090925	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$15,976
Building Name:	MAPLEWOOD - HAZMAT STORAGE	**Address:**	1771 MC MENEMY	**Deferred Maintenance:**	$11,982
Facility Condition Index:	0.75 - Crisis	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	60
Building Code:	T7990091117	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,519,271
Building Name:	MAPLEWOOD - METRO FLEET BUILDING	**Address:**	1779 McMenemy	**Deferred Maintenance:**	$502,290
Facility Condition Index:	0.14 - Good	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	15,913
Building Code:	T7990091161	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,140,526
Building Name:	MAPLEWOOD - POLE STORAGE BLDG	**Address:**	1779 McMenemy	**Deferred Maintenance:**	$94,977
Facility Condition Index:	0.08 - Good	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	9,032
Building Code:	T7990091182	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,200,977
Building Name:	MAPLEWOOD - BRIDGE CREW BLDG	**Address:**	1771 MC MENEMY	**Deferred Maintenance:**	$178,423
Facility Condition Index:	0.03 - Excellent	**City Code:**	MAPLEWOOD	**Ext. Gross Area:**	18,717

Site: T795E91118 - ARDEN HILLS - TRUCK STATION

Building Code:	T7990021116	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$665,055
Building Name:	ARDEN HILLS - SALT/SAND STORAGE	**Address:**	1905 W County Rd I	**Deferred Maintenance:**	$62,323
Facility Condition Index:	0.09 - Good	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	6,513
Building Code:	T7990091118	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,524,851
Building Name:	ARDEN HILLS - TRUCK STATION	**Address:**	1905 W County Rd I	**Deferred Maintenance:**	$1,473,249
Facility Condition Index:	0.23 - Fair	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	27,467
Building Code:	T7990091162	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$637,331
Building Name:	ARDEN HILLS - POLE STORAGE BLDG	**Address:**	1905 W County Rd I	**Deferred Maintenance:**	$98,461
Facility Condition Index:	0.15 - Fair	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	6,779
Building Code:	T7990091181	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$226,532
Building Name:	ARDEN HILLS - BRINE BUILDING	**Address:**	1905 W. COUNTY RD. I	**Deferred Maintenance:**	$10,484
Facility Condition Index:	0.05 - Excellent	**City Code:**	ARDEN HILLS	**Ext. Gross Area:**	1,581

Site: T795E91138 - OAKDALE - HEADQUARTERS

Building Code:	T7990021124	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,627,014
Building Name:	OAKDALE - SALT/SAND STORAGE	**Address:**	3485 Hadley Avenue North	**Deferred Maintenance:**	$95,872
Facility Condition Index:	0.06 - Good	**City Code:**	OAKDALE	**Ext. Gross Area:**	21,600
Building Code:	T7990091119	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$337,588
Building Name:	OAKDALE - COVERED STRG BINS	**Address:**	3485 Hadley Avenue North	**Deferred Maintenance:**	$11,449
Facility Condition Index:	0.03 - Excellent	**City Code:**	OAKDALE	**Ext. Gross Area:**	5,889
Building Code:	T7990091138	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$31,978,643
Building Name:	OAKDALE - HEADQUARTERS	**Address:**	3485 Hadley Avenue North	**Deferred Maintenance:**	$7,875,459
Facility Condition Index:	0.25 - Fair	**City Code:**	OAKDALE	**Ext. Gross Area:**	150,918
Building Code:	T7990091150	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,276
Building Name:	OAKDALE - HAZMAT STORAGE	**Address:**	3485 Hadley Avenue North	**Deferred Maintenance:**	$13,707
Facility Condition Index:	0.75 - Crisis	**City Code:**	OAKDALE	**Ext. Gross Area:**	168
Building Code:	T7990091155	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,853,542
Building Name:	OAKDALE - SIGN SHOP	**Address:**	3485 Hadley Avenue North	**Deferred Maintenance:**	$632,796
Facility Condition Index:	0.13 - Good	**City Code:**	OAKDALE	**Ext. Gross Area:**	26,528
Building Code:	T7990091166	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,127,263
Building Name:	OAKDALE - EQUIP STORAGE	**Address:**	3485 Hadley Avenue North	**Deferred Maintenance:**	$795,786
Facility Condition Index:	0.25 - Fair	**City Code:**	OAKDALE	**Ext. Gross Area:**	24,036
Building Code:	T7990091180	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,975,353
Building Name:	OAKDALE - EQUIP/SIGN STORAGE	**Address:**	3485 HADLEY AVE NO	**Deferred Maintenance:**	$56,541
Facility Condition Index:	0.03 - Excellent	**City Code:**	OAKDALE	**Ext. Gross Area:**	7,033

Site: T795E91139 - FOREST LAKE - TRUCK STATION

Building Code:	T7990021120	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$903,897
Building Name:	FOREST LAKE - SALT/SAND STORAGE	**Address:**	22010 Everton Avenue North	**Deferred Maintenance:**	$249,936
Facility Condition Index:	0.28 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	12,000
Building Code:	T7990091139	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,625,953
Building Name:	FOREST LAKE - TRUCK STATION	**Address:**	22010 Everton Avenue North	**Deferred Maintenance:**	$415,061
Facility Condition Index:	0.16 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	10,912
Building Code:	T7990091142	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,944,874
Building Name:	FOREST LAKE - EQUIP STORAGE	**Address:**	22010 Everton Avenue North	**Deferred Maintenance:**	$237,553
Facility Condition Index:	0.12 - Good	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	8,640
Building Code:	T7990091154	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$216,174
Building Name:	FOREST LAKE - MISC STORAGE	**Address:**	22010 Everton Avenue North	**Deferred Maintenance:**	$16,488
Facility Condition Index:	0.08 - Good	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,952

Building Code:	T7990091163	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,351,846
Building Name:	FOREST LAKE - BRIDGE CREW - EQUIP	**Address:**	22010 Everton Avenue North	**Deferred Maintenance:**	$146,688
Facility Condition Index:	0.11 - Good	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	7,680
Building Code:	T7990091177	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$451,847
Building Name:	FOREST LAKE - UNHEATED STORAGE BLDG	**Address:**	22010 Everton Avenue North	**Deferred Maintenance:**	$26,833
Facility Condition Index:	0.06 - Good	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	4,512

Site: T795E91140 - NORTH BRANCH - TRUCK STATION

Building Code:	T7990021125	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,185,630
Building Name:	NORTH BRANCH-SAND/SALT STORAGE	**Address:**	4841 Saint Croix Trail	**Deferred Maintenance:**	$80,652
Facility Condition Index:	0.07 - Good	**City Code:**	NORTH BRANCH	**Ext. Gross Area:**	10,000
Building Code:	T7990091140	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$3,013,009
Building Name:	NORTH BRANCH - TRUCK STATION	**Address:**	4841 Saint Croix Trail	**Deferred Maintenance:**	$632,863
Facility Condition Index:	0.21 - Fair	**City Code:**	NORTH BRANCH	**Ext. Gross Area:**	17,931
Building Code:	T7990091158	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$95,764
Building Name:	NORTH BRANCH - MISC STORAGE	**Address:**	4841 Saint Croix Trail	**Deferred Maintenance:**	$6,300
Facility Condition Index:	0.07 - Good	**City Code:**	NORTH BRANCH	**Ext. Gross Area:**	960
Building Code:	T7990091171	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$10,329
Building Name:	NORTH BRANCH - FUEL SYSTEM BLDG	**Address:**	4841 Saint Croix Trail	**Deferred Maintenance:**	$1,926
Facility Condition Index:	0.19 - Fair	**City Code:**	NORTH BRANCH	**Ext. Gross Area:**	144
Building Code:	T7990091175	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$235,953
Building Name:	NORTH BRANCH - POLE STORAGE	**Address:**	4841 Saint Croix Trail	**Deferred Maintenance:**	$14,985
Facility Condition Index:	0.06 - Good	**City Code:**	NORTH BRANCH	**Ext. Gross Area:**	2,531

Site: T795E91141 - LAKEVILLE - TRUCK STATION

Building Code:	T7990021119	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,096,346
Building Name:	LAKEVILLE - SALT/SAND STORAGE	**Address:**	16780 Kenrick Avenue	**Deferred Maintenance:**	$338,694
Facility Condition Index:	0.31 - Poor	**City Code:**	LAKEVILLE	**Ext. Gross Area:**	9,596
Building Code:	T7990091141	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$5,589,630
Building Name:	LAKEVILLE - TRUCK STATION	**Address:**	16780 Kenrick Avenue	**Deferred Maintenance:**	$540,304
Facility Condition Index:	0.10 - Good	**City Code:**	LAKEVILLE	**Ext. Gross Area:**	28,432
Building Code:	T7990091164	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$255,523
Building Name:	LAKEVILLE - UNHEATED STG	**Address:**	16780 Kenrick Avenue	**Deferred Maintenance:**	$40,032
Facility Condition Index:	0.16 - Fair	**City Code:**	LAKEVILLE	**Ext. Gross Area:**	2,560

Site: T795E91152 - MENDOTA HEIGHTS - TRUCK STATION

Building Code:	T7990021118	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,543,021
Building Name:	MENDOTA - SALT/SAND STORAGE	**Address:**	2229 Pilot Knob Road	**Deferred Maintenance:**	$574,376
Facility Condition Index:	0.37 - Poor	**City Code:**	MENDOTA HEIGHTS	**Ext. Gross Area:**	13,160
Building Code:	T7990091152	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$9,625,279
Building Name:	MENDOTA HEIGHTS - TRUCK STATION	**Address:**	2229 Pilot Knob Road	**Deferred Maintenance:**	$1,865,366
Facility Condition Index:	0.19 - Fair	**City Code:**	MENDOTA HEIGHTS	**Ext. Gross Area:**	44,573
Building Code:	T7990091167	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$897,261
Building Name:	MENDOTA HEIGHTS - POLE STRG	**Address:**	2229 Pilot Knob Road	**Deferred Maintenance:**	$67,204
Facility Condition Index:	0.07 - Good	**City Code:**	MENDOTA HEIGHTS	**Ext. Gross Area:**	8,529

Site: T795E91153 - HASTINGS - TRUCK STATION

Building Code:	T7990091153	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$8,465,565
Building Name:	HASTINGS - TRUCK STATION	**Address:**	951 E. 21st Street	**Deferred Maintenance:**	$1,304,118
Facility Condition Index:	0.15 - Fair	**City Code:**	HASTINGS	**Ext. Gross Area:**	32,693
Building Code:	T7990091174	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$199,068
Building Name:	HASTINGS - UNHEATED STORAGE BLDG	**Address:**		**Deferred Maintenance:**	$11,085
Facility Condition Index:	0.06 - Good	**City Code:**	HASTINGS	**Ext. Gross Area:**	1,813

Site: T795E91159 - INVER GROVE HEIGHTS - STORAGE SITE

Building Code:	T7990091159	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$796,986
Building Name:	INVER GROVE HEIGHTS - MISC STORAGE	**Address:**	Near Jct TH 52 and TH55	**Deferred Maintenance:**	$246,189
Facility Condition Index:	0.31 - Poor	**City Code:**	INVER GROVE HEIG	**Ext. Gross Area:**	5,640

Site: T795E91165 - ST PAUL MARYLAND AVE - TRUCK STATION

Building Code:	T7990021117	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,608,044
Building Name:	ST PAUL MARYLAND AVE - SALT/SAND	**Address:**	244 East Maryland Avenue	**Deferred Maintenance:**	$620,552
Facility Condition Index:	0.39 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	14,193
Building Code:	T7990090919	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$390,550
Building Name:	ST PAUL MARYLAND AVE - POLE STRG	**Address:**	244 East Maryland Avenue	**Deferred Maintenance:**	$29,435
Facility Condition Index:	0.08 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	3,910
Building Code:	T7990091165	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$13,263,807
Building Name:	ST PAUL MARYLAND AVE - TRUCK STA	**Address:**	244 East Maryland Avenue	**Deferred Maintenance:**	$2,430,010
Facility Condition Index:	0.18 - Fair	**City Code:**	ST. PAUL	**Ext. Gross Area:**	67,435
Building Code:	T7990091168	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$495,482
Building Name:	ST PAUL MARYLAND AVE - POLE STRG	**Address:**	244 East Maryland Avenue	**Deferred Maintenance:**	$48,900
Facility Condition Index:	0.10 - Good	**City Code:**	ST. PAUL	**Ext. Gross Area:**	5,120

Building Code:	T7990091170	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,276
Building Name:	ST PAUL MARYLAND AVE - HAZMAT	**Address:**	244 East Maryland Avenue	**Deferred Maintenance:**	$6,031
Facility Condition Index:	0.33 - Poor	**City Code:**	ST. PAUL	**Ext. Gross Area:**	80

Site: T795E91178 - MENDOTA 35E - ANTI-ICING

Building Code:	T7990091178	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$77,221
Building Name:	MENDOTA 35E - ANTI-ICING BLDG	**Address:**	I35E And TH13	**Deferred Maintenance:**	$5,097
Facility Condition Index:	0.07 - Good	**City Code:**	MENDOTA	**Ext. Gross Area:**	480

Site: T795E91179 - TAYLORS FALLS - TRUCK STATION

Building Code:	T7990021123	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$212,805
Building Name:	TAYLORS FALLS - SALT/SAND STRG	**Address:**	776 1ST STREET	**Deferred Maintenance:**	$4,256
Facility Condition Index:	0.02 - Excellent	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	3,525
Building Code:	T7990091179	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$321,988
Building Name:	TAYLORS FALLS -TRUCK STATION	**Address:**	776 1ST STREET	**Deferred Maintenance:**	$13,570
Facility Condition Index:	0.04 - Excellent	**City Code:**	TAYLORS FALLS	**Ext. Gross Area:**	2,080

Site: T795E91183 - LAFAYETTE TH52 - ANTI-ICING

Building Code:	T7990091183	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$194,508
Building Name:	ST PAUL TH52 - ANTI-ICING	**Address:**	344 HWY 52	**Deferred Maintenance:**	$3,890
Facility Condition Index:	0.02 - Excellent	**City Code:**	ST. PAUL	**Ext. Gross Area:**	1,056

Site: T795E92129 - SAINT CROIX - WEIGH SCALE

Building Code:	T7990092121	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$13,275
Building Name:	ST CROIX - WIM BUILDING	**Address:**	15800 Hudson Blvd	**Deferred Maintenance:**	$1,227
Facility Condition Index:	0.09 - Good	**City Code:**	WEST LAKELAND TW	**Ext. Gross Area:**	80
Building Code:	T7990092129	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,866,953
Building Name:	ST CROIX - WEIGH SCALE	**Address:**	15800 Hudson Blvd	**Deferred Maintenance:**	$171,987
Facility Condition Index:	0.09 - Good	**City Code:**	WEST LAKELAND TW	**Ext. Gross Area:**	5,478
Building Code:	T7990092144	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,814
Building Name:	ST CROIX - WS MISC STORAGE	**Address:**	15800 Hudson Blvd	**Deferred Maintenance:**	$1,176
Facility Condition Index:	0.02 - Excellent	**City Code:**	WEST LAKELAND TW	**Ext. Gross Area:**	768

Site: T795ER198280 - FOREST LAKE - REST AREA

Building Code:	T7990095900	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$646,676
Building Name:	FOREST LAKE - REST AREA	**Address:**	I-35 SB - 1 MI SO OF FOREST LAK	**Deferred Maintenance:**	$152,215
Facility Condition Index:	0.24 - Fair	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	1,871
Building Code:	T7990095933	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$42,642
Building Name:	FOREST LAKE - RA MISC STORAGE	**Address:**		**Deferred Maintenance:**	$1,267
Facility Condition Index:	0.03 - Excellent	**City Code:**	FOREST LAKE	**Ext. Gross Area:**	261

Site: T795ER708203 - SAINT CROIX - REST AREA

Building Code:	T7990095903	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,662,072
Building Name:	ST CROIX - REST AREA TIC	**Address:**	15800 Hudson Blvd	**Deferred Maintenance:**	$553,054
Facility Condition Index:	0.33 - Poor	**City Code:**	WEST LAKELAND TW	**Ext. Gross Area:**	4,981
Building Code:	T7990095931	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$69,811
Building Name:	ST CROIX - RA MISC STORAGE	**Address:**	PO BOX 305	**Deferred Maintenance:**	$19,979
Facility Condition Index:	0.29 - Fair	**City Code:**	WEST LAKELAND TW	**Ext. Gross Area:**	650

Site: T795W21115 - HAMPTON - LOADING SITE

Building Code:	T7990021115	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$224,505
Building Name:	HAMPTON - SALT/SAND STORAGE	**Address:**	TH56 at JCT 52 And 50	**Deferred Maintenance:**	$69,156
Facility Condition Index:	0.31 - Poor	**City Code:**	HAMPTON	**Ext. Gross Area:**	2,360

Site: T795W90902 - MAPLE GROVE I94 - STORAGE SITE

Building Code:	T7990090902	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$50,829
Building Name:	MAPLE GROVE - MISC STORAGE	**Address:**		**Deferred Maintenance:**	$1,017
Facility Condition Index:	0.02 - Excellent	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	528

Site: T795W90910 - CEDAR AVENUE - TRUCK STATION

Building Code:	T7990020921	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$2,876,967
Building Name:	CEDAR AVENUE - SALT/SAND STORAGE	**Address:**	1900 East 66th Street	**Deferred Maintenance:**	$696,762
Facility Condition Index:	0.24 - Fair	**City Code:**	RICHFIELD	**Ext. Gross Area:**	27,197
Building Code:	T7990090904	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$16,432
Building Name:	CEDAR AVENUE - HAZ MATERIAL STRG	**Address:**	1900 East 66th Street	**Deferred Maintenance:**	$16,432
Facility Condition Index:	1.00 - Crisis	**City Code:**	RICHFIELD	**Ext. Gross Area:**	72
Building Code:	T7990090906	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$1,797,930
Building Name:	CEDAR AVENUE - FIRST BUILDING	**Address:**	1900 East 66th Street	**Deferred Maintenance:**	$326,444
Facility Condition Index:	0.18 - Fair	**City Code:**	RICHFIELD	**Ext. Gross Area:**	12,680

Building Code:	T7990090910	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$20,276,016
Building Name:	CEDAR AVENUE - TRUCK STATION	**Address:**	1900 East 66th Street	**Deferred Maintenance:**	$2,442,762
Facility Condition Index:	0.12 - Good	**City Code:**	RICHFIELD	**Ext. Gross Area:**	77,943
Building Code:	T7990090917	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,098,543
Building Name:	CEDAR AVENUE - POLE STORAGE	**Address:**	1900 East 66th Street	**Deferred Maintenance:**	$35,209
Facility Condition Index:	0.03 - Excellent	**City Code:**	RICHFIELD	**Ext. Gross Area:**	9,120

Site: T795W90920 - MINNEAPOLIS LOWRY HILL - TUNNEL

Building Code:	T7990090920	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$5,667,954
Building Name:	MPLS LOWERY HILL - TUNNEL SERVICE	**Address:**	HENNEPIN AVE AT DOUGLAS AV	**Deferred Maintenance:**	$1,060,709
Facility Condition Index:	0.19 - Fair	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	1,072

Site: T795W90926 - CHASKA - TRUCK STATION

Building Code:	T7990020924	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,052,545
Building Name:	CHASKA - SALT/SAND STORAGE	**Address:**	4725 Chaska Blvd	**Deferred Maintenance:**	$54,185
Facility Condition Index:	0.05 - Good	**City Code:**	CHASKA	**Ext. Gross Area:**	11,200
Building Code:	T7990090926	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$11,124,655
Building Name:	CHASKA - TRUCK STATION	**Address:**	4725 Chaska Blvd	**Deferred Maintenance:**	$349,650
Facility Condition Index:	0.03 - Excellent	**City Code:**	CHASKA	**Ext. Gross Area:**	50,834
Building Code:	T7990090927	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$235,828
Building Name:	CHASKA BRINE BUILDING	**Address:**	4725 Chaska Blvd	**Deferred Maintenance:**	$5,462
Facility Condition Index:	0.02 - Excellent	**City Code:**	CHASKA	**Ext. Gross Area:**	1,581
Building Code:	T7990090951	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$908,817
Building Name:	CHASKA - POLE STORAGE	**Address:**	4725 Chaska Blvd	**Deferred Maintenance:**	$18,176
Facility Condition Index:	0.02 - Excellent	**City Code:**	CHASKA	**Ext. Gross Area:**	7,620

Site: T795W90929 - SHAKOPEE - TRUCK STATION

Building Code:	T7990020915	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$544,168
Building Name:	SHAKOPEE - SALT/SAND STORAGE	**Address:**	12550 Chestnut Boulevard	**Deferred Maintenance:**	$134,190
Facility Condition Index:	0.25 - Fair	**City Code:**	SHAKOPEE	**Ext. Gross Area:**	6,272
Building Code:	T7990090929	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$2,476,860
Building Name:	SHAKOPEE - TRUCK STATION	**Address:**	12550 Chestnut Boulevard	**Deferred Maintenance:**	$643,206
Facility Condition Index:	0.26 - Fair	**City Code:**	SHAKOPEE	**Ext. Gross Area:**	16,046
Building Code:	T7990090999	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$578,215
Building Name:	SHAKOPEE - POLE STORAGE	**Address:**	12550 Chestnut Boulevard	**Deferred Maintenance:**	$139,896
Facility Condition Index:	0.24 - Fair	**City Code:**	SHAKOPEE	**Ext. Gross Area:**	6,272

Site: T795W90930 - CAMDEN - TRUCK STATION

Building Code:	T7990020912	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$596,982
Building Name:	CAMDEN - SALT/SAND STORAGE	**Address:**	3636 Washington Avenue North	**Deferred Maintenance:**	$56,253
Facility Condition Index:	0.09 - Good	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	6,403
Building Code:	T7990090930	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$4,450,239
Building Name:	CAMDEN - TRUCK STATION	**Address:**	3636 Washington Avenue North	**Deferred Maintenance:**	$418,311
Facility Condition Index:	0.09 - Good	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	25,060

Site: T795W90931 - GOLDEN VALLEY - HEADQUARTERS

Building Code:	T7990020919	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$828,233
Building Name:	GOLDEN VALLEY - SALT/SAND STORAGE	**Address:**	2055 North Lilac Drive	**Deferred Maintenance:**	$293,148
Facility Condition Index:	0.35 - Poor	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	9,007
Building Code:	T7990090931	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$29,680,939
Building Name:	GOLDEN VALLEY - HEADQUARTERS	**Address:**	2055 North Lilac Drive	**Deferred Maintenance:**	$7,231,915
Facility Condition Index:	0.24 - Fair	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	121,542
Building Code:	T7990090938	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,277,234
Building Name:	GOLDEN VALLEY - PATROL OFFICE	**Address:**	2055 North Lilac Drive	**Deferred Maintenance:**	$248,466
Facility Condition Index:	0.19 - Fair	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	5,333
Building Code:	T7990090939	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$30,390
Building Name:	GOLDEN VALLEY - FUEL SYSTEM BLDG	**Address:**	2055 North Lilac Drive	**Deferred Maintenance:**	$1,855
Facility Condition Index:	0.06 - Good	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	208
Building Code:	T7990090991	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,287,229
Building Name:	GOLDEN VALLEY - POLE STORAGE	**Address:**	2055 North Lilac Drive	**Deferred Maintenance:**	$248,882
Facility Condition Index:	0.11 - Good	**City Code:**	GOLDEN VALLEY	**Ext. Gross Area:**	16,870

Site: T795W90940 - ANOKA - TRUCK STATION

Building Code:	T7990020923	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$701,574
Building Name:	ANOKA - SALT/SAND STORAGE	**Address:**	3601 - 7TH AVE. N.	**Deferred Maintenance:**	$54,380
Facility Condition Index:	0.08 - Good	**City Code:**	ANOKA	**Ext. Gross Area:**	9,231
Building Code:	T7990090923	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$28,000
Building Name:	ANOKA - MISC STORAGE	**Address:**	3601 7th Avenue North	**Deferred Maintenance:**	$6,761
Facility Condition Index:	0.24 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	320
Building Code:	T7990090940	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,642,506
Building Name:	ANOKA - TRUCK STATION	**Address:**	3601 7th Avenue North	**Deferred Maintenance:**	$507,295
Facility Condition Index:	0.19 - Fair	**City Code:**	ANOKA	**Ext. Gross Area:**	12,868

Building Code:	T7990090997	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$525,672
Building Name:	ANOKA - POLE STORAGE	**Address:**	3601 7th Avenue North	**Deferred Maintenance:**	$29,604
Facility Condition Index:	0.06 - Good	**City Code:**	ANOKA	**Ext. Gross Area:**	4,664

Site: T795W90944 - EDEN PRAIRIE TH169/I494 - ANTI-ICING

Building Code:	T7990090944	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$187,045
Building Name:	EDINA 169/494 - ANTI-ICING BLDG	**Address:**	8300 WEST 78TH STREET	**Deferred Maintenance:**	$3,741
Facility Condition Index:	0.02 - Excellent	**City Code:**	EDINA	**Ext. Gross Area:**	1,056

Site: T795W90945 - MINNEAPOLIS I35W BRIDGE - ANIT-ICING

Building Code:	T7990090945	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$164,258
Building Name:	MPLS I35W - ANTI-ICING PUMPHOUSE	**Address:**	921 2nd St SE	**Deferred Maintenance:**	$8,847
Facility Condition Index:	0.05 - Good	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	924
Building Code:	T7990090946	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$24,132
Building Name:	MPLS - 35W ANIT-ICING COMM	**Address:**	921 2nd St SE	**Deferred Maintenance:**	$2,413
Facility Condition Index:	0.10 - Good	**City Code:**	MINNEAPOLIS	**Ext. Gross Area:**	120

Site: T795W90963 - PLYMOUTH - TRUCK STATION

Building Code:	T7990020920	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,285,712
Building Name:	PLYMOUTH - SALT/SAND STORAGE	**Address:**	2315 Fernbrook Lane	**Deferred Maintenance:**	$317,236
Facility Condition Index:	0.25 - Fair	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	17,086
Building Code:	T7990090913	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$957,847
Building Name:	PLYMOUTH - POLE STORAGE	**Address:**	2315 Fernbrook Lane	**Deferred Maintenance:**	$120,125
Facility Condition Index:	0.13 - Good	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	8,092
Building Code:	T7990090941	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$10,647,962
Building Name:	PLYMOUTH - TS ADDITION	**Address:**	2315 Fernbrook Lane	**Deferred Maintenance:**	$212,959
Facility Condition Index:	0.02 - Excellent	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	62,080
Building Code:	T7990090963	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$5,168,940
Building Name:	PLYMOUTH - TRUCK STATION	**Address:**	2315 Fernbrook Lane	**Deferred Maintenance:**	$1,086,359
Facility Condition Index:	0.21 - Fair	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	27,743
Building Code:	T7990090989	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$232,425
Building Name:	PLYMOUTH - MISC STORAGE	**Address:**	2315 Fernbrook Lane	**Deferred Maintenance:**	$127,436
Facility Condition Index:	0.55 - Crisis	**City Code:**	PLYMOUTH	**Ext. Gross Area:**	2,400

Site: T795W90979 - SPRING LAKE PARK - TRUCK STATION

Building Code:	T7990020917	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,604,491
Building Name:	SPRING LAKE PARK - SALT/SAND STORAG	**Address:**	1530 County Hwy 10	**Deferred Maintenance:**	$71,153
Facility Condition Index:	0.04 - Excellent	**City Code:**	SPRING LAKE PARK	**Ext. Gross Area:**	9,984
Building Code:	T7990090979	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$7,344,386
Building Name:	SPRING LAKE PARK - TRUCK STATION	**Address:**	1530 County Hwy 10	**Deferred Maintenance:**	$573,183
Facility Condition Index:	0.08 - Good	**City Code:**	SPRING LAKE PARK	**Ext. Gross Area:**	39,317

Site: T795W90986 - EDEN PRAIRIE - TRUCK STATION

Building Code:	T7990090903	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$809,732
Building Name:	EDEN PRAIRIE - POLE STORAGE BLDG	**Address:**	7333 Bryant Lake Drive	**Deferred Maintenance:**	$59,600
Facility Condition Index:	0.07 - Good	**City Code:**	EDEN PRAIRIE	**Ext. Gross Area:**	8,094
Building Code:	T7990090986	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$6,702,955
Building Name:	EDEN PRAIRIE - TRUCK STATION	**Address:**	7333 Bryant Lake Drive	**Deferred Maintenance:**	$1,049,101
Facility Condition Index:	0.16 - Fair	**City Code:**	EDEN PRAIRIE	**Ext. Gross Area:**	27,593

Site: T795W90988 - BLOOMINGTON PENN AVE - LIFT STATION

Building Code:	T7990090988	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$43,843
Building Name:	BLOOMINGTON/PENN - LIFT STATION	**Address:**	I-494 and Penn Avenue	**Deferred Maintenance:**	$6,298
Facility Condition Index:	0.14 - Good	**City Code:**	BLOOMINGTON	**Ext. Gross Area:**	226

Site: T795W90992 - MAPLE GROVE - TRUCK STATION

Building Code:	T7990020925	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$911,145
Building Name:	MAPLE GROVE SAND/SALT STORAGE	**Address:**	9501 Hemlock Lane North	**Deferred Maintenance:**	$53,372
Facility Condition Index:	0.06 - Good	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	12,000
Building Code:	T7990090947	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$914,852
Building Name:	MAPLE GROVE - POLE STORAGE	**Address:**	9501 Hemlock Lane North	**Deferred Maintenance:**	$18,498
Facility Condition Index:	0.02 - Excellent	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	7,620
Building Code:	T7990090948	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$900,358
Building Name:	MAPLE GROVE - POLE STORAGE	**Address:**	9501 Hemlock Lane North	**Deferred Maintenance:**	$18,208
Facility Condition Index:	0.02 - Excellent	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	7,620
Building Code:	T7990090949	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$235,828
Building Name:	MAPLE GROVE - BRINE BLDG	**Address:**	9501 Hemlock Lane North	**Deferred Maintenance:**	$4,717
Facility Condition Index:	0.02 - Excellent	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	1,580
Building Code:	T7990090992	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$26,296,570
Building Name:	MAPLE GROVE - TRUCK STATION	**Address:**	9501 Hemlock Lane North	**Deferred Maintenance:**	$859,508
Facility Condition Index:	0.03 - Excellent	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	105,799

Site: T795W91148 - DAKOTA COUNTY - STORAGE SITE

Building Code:	T7990091176	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$63,363
Building Name:	DAKOTA COUNTY - LOADER STORAGE BLDG	**Address:**	HWY 50/61	**Deferred Maintenance:**	$2,220
Facility Condition Index:	0.04 - Excellent	**City Code:**	MIESVILLE	**Ext. Gross Area:**	560

Site: T795W92001 - DAYTONPORT - WEIGH SCALE

Building Code:	T7990092139	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$304,583
Building Name:	DAYTONPORT - WEIGH SCALE	**Address:**	US 10 - 6 MI NW OF ANOKA	**Deferred Maintenance:**	$67,974
Facility Condition Index:	0.22 - Fair	**City Code:**	ELK RIVER	**Ext. Gross Area:**	659

Site: T795WR090202 - DAYTONPORT - REST AREA

Building Code:	T7990095511	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$463,185
Building Name:	DAYTONPORT - REST AREA	**Address:**	US 10	**Deferred Maintenance:**	$52,900
Facility Condition Index:	0.11 - Good	**City Code:**	RAMSEY	**Ext. Gross Area:**	1,831

Site: T795WR232780 - ELM CREEK - REST AREA

Building Code:	T7990095500	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$801,157
Building Name:	ELM CREEK - REST AREA	**Address:**	I-94 EB - 2 MI NO I-494	**Deferred Maintenance:**	$105,107
Facility Condition Index:	0.13 - Good	**City Code:**	MAPLE GROVE	**Ext. Gross Area:**	3,191

Site: T796A21208 - ZUMBRO FALLS

Building Code:	T7960021208	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$89,012
Building Name:	ZUMBRO FALLS - SALT/SAND STORAGE	**Address:**	NEAR 36527 MN 60	**Deferred Maintenance:**	$62,770
Facility Condition Index:	0.71 - Crisis	**City Code:**	ZUMBRO FALLS	**Ext. Gross Area:**	898
Building Code:	T7960091245	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,759
Building Name:	ZUMBRO FALLS - MISC STORAGE	**Address:**	NEAR 36527 MN 60	**Deferred Maintenance:**	$7,788
Facility Condition Index:	0.16 - Fair	**City Code:**	ZUMBRO FALLS	**Ext. Gross Area:**	395

Site: T796A21212 - SPRING VALLEY - LOADING SITE

Building Code:	T7960021230	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$767,549
Building Name:	SPRING VALLEY- SALT/SAND STORAGE	**Address:**	512 East Guzwold Street	**Deferred Maintenance:**	$71,095
Facility Condition Index:	0.09 - Good	**City Code:**	SPRING VALLEY	**Ext. Gross Area:**	9,542

Site: T796A21219 - MARION - LOADING SITE

Building Code: T7960021219
Building Name: MARION - SALT/SAND STORAGE
Facility Condition Index: 0.16 - Fair

Cost Model Name: Open Air Storage Structure
Address: Hwy 52 and Co. Rd 19
City Code: MARION

Current Replacement Value: $56,602
Deferred Maintenance: $9,310
Ext. Gross Area: 644

Building Code: T7960091231
Building Name: MARION - MISC STORAGE
Facility Condition Index: 0.16 - Fair

Cost Model Name: Single-story Work Facility
Address: Hwy 52 and Co. Rd 19
City Code: MARION

Current Replacement Value: $42,240
Deferred Maintenance: $6,961
Ext. Gross Area: 384

Site: T796A21225 - LA CRESCENT - LOADING SITE

Building Code: T7960021225
Building Name: LA CRESENT- SALT/SAND STORAGE
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Storage Structure
Address: 511 Chestnut Blvd
City Code: LA CRESCENT

Current Replacement Value: $1,395,489
Deferred Maintenance: $139,549
Ext. Gross Area: 11,108

Site: T796A21229 - CHATFIELD - LOADING SITE CNTY

Building Code: T7960021229
Building Name: CHATFIELD - SALT/SAND STORAGE
Facility Condition Index: 0.13 - Good

Cost Model Name: Open Air Storage Structure
Address: 32647 LOST LOOP ROAD
City Code: CHATFIELD

Current Replacement Value: $534,325
Deferred Maintenance: $69,514
Ext. Gross Area: 5,788

Site: T796A21295 - DEXTER - LOADING SITE(LEASED)

Building Code: T7960021295
Building Name: DEXTER - SALT/SAND STORAGE
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Storage Structure
Address: NEAR 228 INDUSTRIAL PARK DR
City Code: DEXTER

Current Replacement Value: $839,427
Deferred Maintenance: $83,943
Ext. Gross Area: 7,560

Site: T796A91206 - LAKE CITY - STORAGE SITE

Building Code: T7960091206
Building Name: LAKE CITY - EQUIP STORAGE
Facility Condition Index: 0.68 - Crisis

Cost Model Name: Single-story Work Facility
Address: 2101 South Oak
City Code: LAKE CITY

Current Replacement Value: $269,011
Deferred Maintenance: $182,754
Ext. Gross Area: 2,000

Building Code: T7960091207
Building Name: LAKE CITY - EQUIP STORAGE
Facility Condition Index: 0.95 - Crisis

Cost Model Name: Single-story Work Facility
Address: 2101 South Oak
City Code: LAKE CITY

Current Replacement Value: $714,243
Deferred Maintenance: $675,970
Ext. Gross Area: 3,840

Site: T796A91216 - PRESTON - TRUCK STATION

Building Code: T7960021226
Building Name: PRESTON - SALT/SAND STORAGE
Facility Condition Index: 0.18 - Fair

Cost Model Name: Fabric Structure
Address: TH 52AndTH 16 South
City Code: PRESTON

Current Replacement Value: $830,052
Deferred Maintenance: $151,747
Ext. Gross Area: 8,369

Building Code:	T7960091216	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,204,637
Building Name:	PRESTON - TRUCK STATION	**Address:**	TH 52 And TH 16 South	**Deferred Maintenance:**	$115,295
Facility Condition Index:	0.10 - Good	**City Code:**	PRESTON	**Ext. Gross Area:**	6,642
Building Code:	T7960091274	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$136,009
Building Name:	PRESTON - UNHEATED STORAGE	**Address:**	TH 52 And TH 16 South	**Deferred Maintenance:**	$20,911
Facility Condition Index:	0.15 - Fair	**City Code:**	PRESTON	**Ext. Gross Area:**	952

Site: T796A91218 - WINONA - TRUCK STATION

Building Code:	T7960021220	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$976,490
Building Name:	WINONA - SALT/SAND STORAGE	**Address:**	5420 Highway 61 West	**Deferred Maintenance:**	$81,747
Facility Condition Index:	0.08 - Good	**City Code:**	GOODVIEW	**Ext. Gross Area:**	7,915
Building Code:	T7960091218	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$4,504,094
Building Name:	WINONA - TRUCK STATION	**Address:**	5420 Highway 61 West	**Deferred Maintenance:**	$479,745
Facility Condition Index:	0.11 - Good	**City Code:**	GOODVIEW	**Ext. Gross Area:**	20,663
Building Code:	T7960091219	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$477,822
Building Name:	WINONA - EQUIP STORAGE	**Address:**	5420 Highway 61 West	**Deferred Maintenance:**	$37,615
Facility Condition Index:	0.08 - Good	**City Code:**	GOODVIEW	**Ext. Gross Area:**	3,306
Building Code:	T7960091254	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$412,035
Building Name:	WINONA - POLE STORAGE BLDG	**Address:**	5420 Highway 61 West	**Deferred Maintenance:**	$23,364
Facility Condition Index:	0.06 - Good	**City Code:**	GOODVIEW	**Ext. Gross Area:**	3,639
Building Code:	T7960091261	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$435,591
Building Name:	WINONA (DUNN BLACKTOP) - EQUIP STG	**Address:**	5420 Highway 61 West	**Deferred Maintenance:**	$114,195
Facility Condition Index:	0.26 - Fair	**City Code:**	GOODVIEW	**Ext. Gross Area:**	2,301
Building Code:	T7960091275	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$228,841
Building Name:	WINONA- MISC STORAGE	**Address:**	5420 Highway 61 West	**Deferred Maintenance:**	$11,858
Facility Condition Index:	0.05 - Good	**City Code:**	GOODVIEW	**Ext. Gross Area:**	1,995

Site: T796A91220 - STEWARTVILLE - TRUCK STATION

Building Code:	T7960021202	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$82,088
Building Name:	STEWARTVILLE - BITUMINOUS STORAGE	**Address:**	401 10th St NW	**Deferred Maintenance:**	$27,089
Facility Condition Index:	0.33 - Poor	**City Code:**	STEWARTVILLE	**Ext. Gross Area:**	829
Building Code:	T7960021224	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$680,618
Building Name:	STEWARTVILLE - SALT/SAND STORAGE	**Address:**	401 10th St NW	**Deferred Maintenance:**	$63,033
Facility Condition Index:	0.09 - Good	**City Code:**	STEWARTVILLE	**Ext. Gross Area:**	6,512

Building Code:	T7960091220	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,980,773
Building Name:	STEWARTVILLE - TRUCK STATION	**Address:**	401 10th St NW	**Deferred Maintenance:**	$443,067
Facility Condition Index:	0.15 - Good	**City Code:**	STEWARTVILLE	**Ext. Gross Area:**	16,187
Building Code:	T7960091267	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$825,211
Building Name:	STEWARTVILLE - POLE STG BLDG	**Address:**	401 10th St NW	**Deferred Maintenance:**	$33,605
Facility Condition Index:	0.04 - Excellent	**City Code:**	STEWARTVILLE	**Ext. Gross Area:**	5,831

Site: T796A91225 - ROCHESTER - HEADQUARTERS

Building Code:	T7960021235	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,295,041
Building Name:	ROCHESTER - SALT/SAND STORAGE	**Address:**	2900 48TH STREET N.W.	**Deferred Maintenance:**	$25,901
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	16,400
Building Code:	T7960091225	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$32,795,752
Building Name:	ROCHESTER - DISTRICT HEADQUARTERS	**Address:**	2900 48th Street NW	**Deferred Maintenance:**	$1,136,634
Facility Condition Index:	0.03 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	104,561
Building Code:	T7960091256	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$335,996
Building Name:	ROCHESTER - UNHEATED STG	**Address:**	2900 48th Street NW	**Deferred Maintenance:**	$13,517
Facility Condition Index:	0.04 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	3,240
Building Code:	T7960091259	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$449,073
Building Name:	ROCHESTER - UNHEATED STG	**Address:**	2900 48th Street NW	**Deferred Maintenance:**	$42,864
Facility Condition Index:	0.10 - Good	**City Code:**	ROCHESTER	**Ext. Gross Area:**	3,840
Building Code:	T7960091260	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$18,988
Building Name:	ROCHESTER - HAZARD MATLS	**Address:**	2900 48th Street NW	**Deferred Maintenance:**	$14,241
Facility Condition Index:	0.75 - Crisis	**City Code:**	ROCHESTER	**Ext. Gross Area:**	142
Building Code:	T7960091266	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,067,385
Building Name:	ROCHESTER - POLE STORAGE BLDG	**Address:**	2900 48th Street NW	**Deferred Maintenance:**	$21,348
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	9,120
Building Code:	T7960091270	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$31,791,808
Building Name:	ROCHESTER - MAINTENANCE FACILITY	**Address:**	2900 48TH STREET N.W.	**Deferred Maintenance:**	$635,836
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	114,084
Building Code:	T7960091271	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$271,645
Building Name:	ROCHESTER - BRINE BLDG	**Address:**	2900 48th Street NW	**Deferred Maintenance:**	$5,433
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	1,581
Building Code:	T7960091272	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,045,656
Building Name:	ROCHESTER - UNHEATED STORAGE BLDG	**Address:**	2900 48TH STREET N.W.	**Deferred Maintenance:**	$20,913
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	9,120

Building Code:	T7960091273	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$433,090
Building Name:	ROCHESTER - CVRD STORAGE BINS	**Address:**	2900 48TH STREET N.W.	**Deferred Maintenance:**	$8,662
Facility Condition Index:	0.02 - Excellent	**City Code:**	ROCHESTER	**Ext. Gross Area:**	7,068

Site: T796A91229 - SAINT CHARLES - TRUCK STATION

Building Code:	T7960021205	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$152,932
Building Name:	ST CHARLES - SALT/SAND STORAGE	**Address:**	I-90 And TH74	**Deferred Maintenance:**	$12,826
Facility Condition Index:	0.08 - Good	**City Code:**	ST. CHARLES	**Ext. Gross Area:**	2,010
Building Code:	T7960021221	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$636,801
Building Name:	ST CHARLES - SALT/SAND STORAGE	**Address:**	I-90 And TH74	**Deferred Maintenance:**	$65,548
Facility Condition Index:	0.10 - Good	**City Code:**	ST. CHARLES	**Ext. Gross Area:**	10,399
Building Code:	T7960091229	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$2,051,934
Building Name:	ST CHARLES - TRUCK STATION	**Address:**	I-90 And TH74	**Deferred Maintenance:**	$317,332
Facility Condition Index:	0.15 - Fair	**City Code:**	ST. CHARLES	**Ext. Gross Area:**	11,829
Building Code:	T7960091257	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$394,036
Building Name:	ST CHARLES - POLE STORAGE BLDG	**Address:**	I-90 And TH74	**Deferred Maintenance:**	$31,463
Facility Condition Index:	0.08 - Good	**City Code:**	ST. CHARLES	**Ext. Gross Area:**	3,200

Site: T796A91230 - CALEDONIA - TRUCK STATION

Building Code:	T7960021228	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$524,820
Building Name:	CALEDONIA - SALT/SAND STORAGE	**Address:**	174 Bisson Street	**Deferred Maintenance:**	$32,762
Facility Condition Index:	0.06 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	6,403
Building Code:	T7960091265	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$449,768
Building Name:	CALEDONIA - POLE STORAGE BLDG	**Address:**	174 Bisson Street	**Deferred Maintenance:**	$22,723
Facility Condition Index:	0.05 - Good	**City Code:**	CALEDONIA	**Ext. Gross Area:**	4,020
Building Code:	T7960091269	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,673,270
Building Name:	CALEDONIA -TRUCK STATION	**Address:**	174 BISSEN ST N	**Deferred Maintenance:**	$33,465
Facility Condition Index:	0.02 - Excellent	**City Code:**	CALEDONIA	**Ext. Gross Area:**	8,845

Site: T796A91233 - CHATFIELD - OLD LOADING SITE

Building Code:	T7960091228	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$58,833
Building Name:	CHATFIELD - MISC STORAGE	**Address:**	NEAR 1306 WINONA ST SE	**Deferred Maintenance:**	$24,876
Facility Condition Index:	0.42 - Poor	**City Code:**	CHATFIELD	**Ext. Gross Area:**	480
Building Code:	T7960091233	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$31,294
Building Name:	CHATFIELD - SALT/SAND STORAGE	**Address:**	NEAR 1306 WINONA ST SE	**Deferred Maintenance:**	$18,107
Facility Condition Index:	0.58 - Crisis	**City Code:**	CHATFIELD	**Ext. Gross Area:**	586

Site: T796A91247 - HOUSTON - LOADING SITE

Building Code:	T7960021231	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$359,125
Building Name:	HOUSTON LS- SALT/SAND STORAGE	**Address:**	15298 MN 16	**Deferred Maintenance:**	$21,743
Facility Condition Index:	0.06 - Good	**City Code:**	HOUSTON	**Ext. Gross Area:**	3,615
Building Code:	T7960091268	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$328,848
Building Name:	HOUSTON LS - EQUIP STORAGE	**Address:**	15298 State Hwy 16	**Deferred Maintenance:**	$16,490
Facility Condition Index:	0.05 - Good	**City Code:**	HOUSTON	**Ext. Gross Area:**	1,728

Site: T796A91249 - WABASHA - TRUCK STATION

Building Code:	T7960021236	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$275,555
Building Name:	WABASHA - SALT/SAND STORAGE	**Address:**	736 Hiawatha Drive West	**Deferred Maintenance:**	$6,572
Facility Condition Index:	0.02 - Excellent	**City Code:**	WABASHA	**Ext. Gross Area:**	8,640
Building Code:	T7960091249	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$1,117,550
Building Name:	WABASHA - TRUCK STATION	**Address:**	736 Hiawatha Drive West	**Deferred Maintenance:**	$101,707
Facility Condition Index:	0.09 - Good	**City Code:**	WABASHA	**Ext. Gross Area:**	5,294
Building Code:	T7960091276	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$254,762
Building Name:	WABASHA - UNHEATED STORAGE	**Address:**	736 Hiawatha Drive West	**Deferred Maintenance:**	$5,095
Facility Condition Index:	0.02 - Excellent	**City Code:**	WABASHA	**Ext. Gross Area:**	3,480

Site: T796A91252 - DRESBACH - TRUCK STATION

Building Code:	T7960021218	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$675,266
Building Name:	DRESBACH - SALT/SAND STORAGE	**Address:**	201 Riverview Drive	**Deferred Maintenance:**	$79,524
Facility Condition Index:	0.12 - Good	**City Code:**	DRESBACH	**Ext. Gross Area:**	5,425
Building Code:	T7960091252	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,355,546
Building Name:	DRESBACH - TRUCK STATION	**Address:**	201 Riverview Drive	**Deferred Maintenance:**	$394,918
Facility Condition Index:	0.17 - Fair	**City Code:**	DRESBACH	**Ext. Gross Area:**	13,323

Site: T796A91255 - WILSON - TRUCK STATION

Building Code:	T7960021227	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$336,758
Building Name:	WILSON - SALT/SAND STORAGE	**Address:**	RR2 Box 180-A1	**Deferred Maintenance:**	$33,676
Facility Condition Index:	0.10 - Good	**City Code:**	WILSON TWP	**Ext. Gross Area:**	4,013
Building Code:	T7960091255	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$565,772
Building Name:	WILSON - TRUCK STATION	**Address:**	RR2 Box 180-A1	**Deferred Maintenance:**	$74,513
Facility Condition Index:	0.13 - Good	**City Code:**	WILSON TWP	**Ext. Gross Area:**	3,926

Site: T796A91262 - RUSHFORD - TRUCK STATION

Building Code:	T7960021223	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$786,602
Building Name:	RUSHFORD - SALT/SAND STORAGE	**Address:**	902 Enterprise Drive	**Deferred Maintenance:**	$55,243
Facility Condition Index:	0.07 - Good	**City Code:**	RUSHFORD	**Ext. Gross Area:**	10,000
Building Code:	T7960091262	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,523,129
Building Name:	RUSHFORD - TRUCK STATION	**Address:**	902 Enterprise Drive	**Deferred Maintenance:**	$195,555
Facility Condition Index:	0.13 - Good	**City Code:**	RUSHFORD	**Ext. Gross Area:**	8,264
Building Code:	T7960091263	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$346,883
Building Name:	RUSHFORD - POLE STORAGE BLDG	**Address:**	902 Enterprise Drive	**Deferred Maintenance:**	$12,688
Facility Condition Index:	0.04 - Excellent	**City Code:**	RUSHFORD	**Ext. Gross Area:**	3,211

Site: T796A92138 - WINONA - WEIGH SCALE

Building Code:	T7960092138	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$53,909
Building Name:	WINONA - WEIGH SCALE	**Address:**	5420 Hwy 61 West	**Deferred Maintenance:**	$14,741
Facility Condition Index:	0.27 - Fair	**City Code:**	GOODVIEW	**Ext. Gross Area:**	256

Site: T796AR075080 - HIGH FOREST - REST AREA

Building Code:	T7960095600	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$528,151
Building Name:	HIGH FOREST - REST AREA	**Address:**	95600 East I-90	**Deferred Maintenance:**	$32,997
Facility Condition Index:	0.06 - Good	**City Code:**	STEWARTVILLE	**Ext. Gross Area:**	2,135

Site: T796AR188580 - DRESBACH - REST AREA TIC

Building Code:	T7960095603	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,767,181
Building Name:	DRESBACH - REST AREA TIC	**Address:**	I-90 WB/US61	**Deferred Maintenance:**	$99,922
Facility Condition Index:	0.06 - Good	**City Code:**	LACRESCENT	**Ext. Gross Area:**	3,723
Building Code:	T7960095631	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$8,652
Building Name:	DRESBACH - RA MISC STORAGE	**Address:**	I-90 WB/US61	**Deferred Maintenance:**	$749
Facility Condition Index:	0.09 - Good	**City Code:**	LACRESCENT	**Ext. Gross Area:**	80

Site: T796AR225580 - MARION - REST AREA

Building Code:	T7960095604	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$569,502
Building Name:	MARION - REST AREA	**Address:**	I90 WB,11MI W OF TH74	**Deferred Maintenance:**	$47,269
Facility Condition Index:	0.08 - Good	**City Code:**	ST. CHARLES	**Ext. Gross Area:**	2,234

Site: T796AR278580 - ENTERPRISE - REST AREA

Building Code:	T7960095602	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$905,632
Building Name:	ENTERPRISE - REST AREA	**Address:**	I-90 10 mi E of St. Charles	**Deferred Maintenance:**	$89,062
Facility Condition Index:	0.10 - Good	**City Code:**	ST. CHARLES	**Ext. Gross Area:**	3,405

Site: T796B21303 - ELLENDALE - LOADING SITE

Building Code:	T7965021334	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$250,322
Building Name:	ELLENDALE - SALT/SAND STORAGE	**Address:**	1/8 Mi E of Jct I-35 And TH 30	**Deferred Maintenance:**	$21,843
Facility Condition Index:	0.09 - Good	**City Code:**	ELLENDALE	**Ext. Gross Area:**	2,358

Site: T796B21309 - BLOOMING PRAIRIE - LOADING SITE

Building Code:	T7965021333	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$157,023
Building Name:	BLOOMING PRAIRIE - SALT/SAND STRG	**Address:**	TH 30-1Mi E of Jct TH 218	**Deferred Maintenance:**	$20,917
Facility Condition Index:	0.13 - Good	**City Code:**	BLOOMING PRAIRIE	**Ext. Gross Area:**	1,925
Building Code:	T7965091356	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$50,258
Building Name:	BLOOMING PRAIRIE - MISC STORAGE	**Address:**	TH 30 - 1 MI E of Jct TH 218	**Deferred Maintenance:**	$6,776
Facility Condition Index:	0.13 - Good	**City Code:**	BLOOMING PRAIRIE	**Ext. Gross Area:**	497

Site: T796B21313 - KASSON - LOADING SITE

Building Code:	T7965021332	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$328,328
Building Name:	KASSON - SALT/SAND STORAGE	**Address:**	63767 260th St	**Deferred Maintenance:**	$53,896
Facility Condition Index:	0.16 - Fair	**City Code:**	KASSON	**Ext. Gross Area:**	2,360

Site: T796B21317 - ALBERT LEA WEST - LOADING SITE

Building Code:	T7965021317	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$225,470
Building Name:	ALBERT LEA WEST - SALT/SAND STRG	**Address:**	72618 225th	**Deferred Maintenance:**	$48,971
Facility Condition Index:	0.22 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	1,951

Site: T796B21326 - NORTHFIELD I35 - LOADING SITE

Building Code:	T7965021326	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$382,979
Building Name:	NORTHFIELD - SALT/SAND STORAGE	**Address:**	1765 IONSDALE BLVD WEST	**Deferred Maintenance:**	$116,597
Facility Condition Index:	0.30 - Poor	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	3,605

Site: T796B21336 - FILLMORE COUNTY - LOADING SITE

Building Code:	T7965021336	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$536,932
Building Name:	FILLMORE CNTY - SALT/SAND STORAGE	**Address:**	Jct TH 56 and TH 63	**Deferred Maintenance:**	$32,585
Facility Condition Index:	0.06 - Good	**City Code:**	CHESTER	**Ext. Gross Area:**	4,544

Site: T796B91317 - NORTHFIELD - TRUCK STATION

Building Code:	T7965021318	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$90,687
Building Name:	NORTHFIELD - SALT/SAND STORAGE	**Address:**	510 West Woodley Street	**Deferred Maintenance:**	$50,890
Facility Condition Index:	0.56 - Crisis	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	1,440
Building Code:	T7965091317	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$893,753
Building Name:	NORTHFIELD - TRUCK STATION	**Address:**	510 West Woodley Street	**Deferred Maintenance:**	$330,311
Facility Condition Index:	0.37 - Poor	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	4,678
Building Code:	T7965091318	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$266,510
Building Name:	NORTHFIELD - MISC STORAGE	**Address:**	510 West Woodley Street	**Deferred Maintenance:**	$100,329
Facility Condition Index:	0.38 - Poor	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	2,304

Site: T796B91319 - ALBERT LEA - TRUCK STATION

Building Code:	T7965021321	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$130,290
Building Name:	ALBERT LEA - SALT/SAND STORAGE	**Address:**	22231 - 770th Avenue	**Deferred Maintenance:**	$22,335
Facility Condition Index:	0.17 - Fair	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,356
Building Code:	T7965021331	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$566,905
Building Name:	ALBERT LEA - SALT/SAND STORAGE	**Address:**	22231 - 770th Avenue	**Deferred Maintenance:**	$67,626
Facility Condition Index:	0.12 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	7,505
Building Code:	T7965021338	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$731,425
Building Name:	ALBERT LEA - SALT/SAND STORAGE	**Address:**	22231 - 770th Avenue	**Deferred Maintenance:**	$14,628
Facility Condition Index:	0.02 - Excellent	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	9,000
Building Code:	T7965091319	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$3,648,420
Building Name:	ALBERT LEA - TRUCK STATION	**Address:**	22231 - 770th Avenue	**Deferred Maintenance:**	$204,144
Facility Condition Index:	0.06 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	18,999
Building Code:	T7965091346	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$54,218
Building Name:	ALBERT LEA - MISC STORAGE	**Address:**	22231 - 770th Avenue	**Deferred Maintenance:**	$7,306
Facility Condition Index:	0.13 - Good	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	680
Building Code:	T7965091353	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$251,367
Building Name:	ALBERT LEA - POLE STORAGE BLDG	**Address:**	22231 - 770th Avenue	**Deferred Maintenance:**	$9,210
Facility Condition Index:	0.04 - Excellent	**City Code:**	ALBERT LEA	**Ext. Gross Area:**	2,560

Site: T796B91327 - OWATONNA - HEADQUARTERS

Building Code:	T7965021322	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$118,229
Building Name:	OWATONNA - SALT/SAND STORAGE	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$54,523
Facility Condition Index:	0.46 - Poor	**City Code:**	OWATONNA	**Ext. Gross Area:**	1,824

Building Code:	T7965021327	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$805,135
Building Name:	OWATONNA - SALT/SAND STORAGE	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$219,861
Facility Condition Index:	0.27 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	6,715
Building Code:	T7965021339	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$702,303
Building Name:	OWATONNA - SALT/SAND STORAGE	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$14,046
Facility Condition Index:	0.02 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	9,000
Building Code:	T7965091327	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$17,025,785
Building Name:	OWATONNA - HEADQUARTERS	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$3,209,428
Facility Condition Index:	0.19 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	72,924
Building Code:	T7965091329	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,334,284
Building Name:	OWATONNA - POLE STORAGE BLDG	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$179,260
Facility Condition Index:	0.13 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	9,041
Building Code:	T7965091347	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,027,985
Building Name:	OWATONNA - POLE STORAGE BLDG	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$286,157
Facility Condition Index:	0.28 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	10,162
Building Code:	T7965091352	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$59,223
Building Name:	OWATONNA - MISC STORAGE	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$10,025
Facility Condition Index:	0.17 - Fair	**City Code:**	OWATONNA	**Ext. Gross Area:**	783
Building Code:	T7965091358	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$270,115
Building Name:	OWATONNA - POLE STORAGE BLDG	**Address:**	1010 - 21st Avenue NW	**Deferred Maintenance:**	$21,267
Facility Condition Index:	0.08 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	2,560
Building Code:	T7965091367	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$749,945
Building Name:	OWATONNA UNHEATED STORAGE	**Address:**	1010 21ST AVENUE NW	**Deferred Maintenance:**	$14,999
Facility Condition Index:	0.02 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	7,560

Site: T796B91331 - CANNON FALLS - TRUCK STATION

Building Code:	T7965021310	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$74,151
Building Name:	CANNON FALLS - SALT/SAND STORAGE	**Address:**	31664 County Road 24	**Deferred Maintenance:**	$54,124
Facility Condition Index:	0.73 - Crisis	**City Code:**	CANNON FALLS	**Ext. Gross Area:**	896
Building Code:	T7965021325	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$678,594
Building Name:	CANNON FALLS - SALT/SAND STORAGE	**Address:**	31664 County Road 24	**Deferred Maintenance:**	$122,117
Facility Condition Index:	0.18 - Fair	**City Code:**	CANNON FALLS	**Ext. Gross Area:**	5,538
Building Code:	T7965091331	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$675,783
Building Name:	CANNON FALLS - TRUCK STATION	**Address:**	31664 County Road 24	**Deferred Maintenance:**	$136,904
Facility Condition Index:	0.20 - Fair	**City Code:**	CANNON FALLS	**Ext. Gross Area:**	3,707

Building Code:	T7965091360	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$362,124
Building Name:	CANNON FALLS - POLE STORAGE BLDG	**Address:**	31664 County Road 24	**Deferred Maintenance:**	$13,560
Facility Condition Index:	0.04 - Excellent	**City Code:**	CANNON FALLS	**Ext. Gross Area:**	2,560

Site: T796B91339 - ZUMBROTA - TRUCK STATION

Building Code:	T7965021316	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$139,715
Building Name:	ZUMBROTA - SALT/SAND STORAGE	**Address:**	940 West 8th Street	**Deferred Maintenance:**	$84,198
Facility Condition Index:	0.60 - Crisis	**City Code:**	ZUMBROTA	**Ext. Gross Area:**	1,280
Building Code:	T7965021329	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$308,344
Building Name:	ZUMBROTA-SALT/SAND STORAGE	**Address:**	940 West 8th Street	**Deferred Maintenance:**	$38,394
Facility Condition Index:	0.12 - Good	**City Code:**	ZUMBROTA	**Ext. Gross Area:**	4,409
Building Code:	T7965091324	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$18,052
Building Name:	ZUMBROTA - MISC STORAGE	**Address:**	940 West 8th Street	**Deferred Maintenance:**	$11,860
Facility Condition Index:	0.66 - Crisis	**City Code:**	ZUMBROTA	**Ext. Gross Area:**	800
Building Code:	T7965091339	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$750,160
Building Name:	ZUMBROTA - TRUCK STATION	**Address:**	940 West 8th Street	**Deferred Maintenance:**	$88,253
Facility Condition Index:	0.12 - Good	**City Code:**	ZUMBROTA	**Ext. Gross Area:**	5,241
Building Code:	T7965091355	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$240,139
Building Name:	ZUMBROTA - POLE STORAGE BLDG	**Address:**	940 West 8th Street	**Deferred Maintenance:**	$23,172
Facility Condition Index:	0.10 - Good	**City Code:**	ZUMBROTA	**Ext. Gross Area:**	2,560

Site: T796B91344 - DODGE CENTER - STORAGE SITE

Building Code:	T7965021319	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$264,255
Building Name:	DODGE CENTER - SALT/SAND STORAGE	**Address:**	61923 MN Hwy 56	**Deferred Maintenance:**	$44,213
Facility Condition Index:	0.17 - Fair	**City Code:**	DODGE CENTER	**Ext. Gross Area:**	3,060
Building Code:	T7965091344	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$833,669
Building Name:	DODGE CENTER - STORAGE FACILITY	**Address:**	61923 MN Hwy 56	**Deferred Maintenance:**	$153,371
Facility Condition Index:	0.18 - Fair	**City Code:**	DODGE CENTER	**Ext. Gross Area:**	5,406
Building Code:	T7965091351	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$185,569
Building Name:	DODGE CENTER - POLE STORAGE BLDG	**Address:**	61923 MN Hwy 56	**Deferred Maintenance:**	$24,873
Facility Condition Index:	0.13 - Good	**City Code:**	DODGE CENTER	**Ext. Gross Area:**	1,536

Site: T796B91349 - AUSTIN - TRUCK STATION

Building Code:	T7965021323	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,035,912
Building Name:	AUSTIN - SALT/SAND STORAGE	**Address:**	1500 - 11th Drive NE	**Deferred Maintenance:**	$168,427
Facility Condition Index:	0.16 - Fair	**City Code:**	AUSTIN	**Ext. Gross Area:**	8,261

Building Code:	T7965091349	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,708,603
Building Name:	AUSTIN - TRUCK STATION	**Address:**	1500 - 11th Drive NE	**Deferred Maintenance:**	$377,420
Facility Condition Index:	0.14 - Good	**City Code:**	AUSTIN	**Ext. Gross Area:**	15,611
Building Code:	T7965091350	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$448,844
Building Name:	AUSTIN - POLE STORAGE BLDG	**Address:**	1500 - 11th Drive NE	**Deferred Maintenance:**	$36,375
Facility Condition Index:	0.08 - Good	**City Code:**	AUSTIN	**Ext. Gross Area:**	4,177

Site: T796B91354 - RED WING - TRUCK STATION

Building Code:	T7965021328	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$725,830
Building Name:	RED WING - SALT/SAND STORAGE	**Address:**	3890 Pepin Avenue	**Deferred Maintenance:**	$73,255
Facility Condition Index:	0.10 - Good	**City Code:**	RED WING	**Ext. Gross Area:**	10,198
Building Code:	T7965091354	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,294,839
Building Name:	RED WING - TRUCK STATION	**Address:**	3890 Pepin Avenue	**Deferred Maintenance:**	$90,001
Facility Condition Index:	0.07 - Good	**City Code:**	RED WING	**Ext. Gross Area:**	7,457
Building Code:	T7965091359	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$238,497
Building Name:	RED WING - POLE STORAGE BLDG	**Address:**	3890 Pepin Avenue	**Deferred Maintenance:**	$15,069
Facility Condition Index:	0.06 - Good	**City Code:**	RED WING	**Ext. Gross Area:**	2,560

Site: T796B91361 - DODGE CENTER - TRUCK STATION

Building Code:	T7965021341	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$704,335
Building Name:	DODGE CENTER - SALT/SAND STORAGE	**Address:**	201 Airport Road	**Deferred Maintenance:**	$202,622
Facility Condition Index:	0.29 - Fair	**City Code:**	DODGE CENTER	**Ext. Gross Area:**	9,000
Building Code:	T7965091361	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,696,053
Building Name:	DODGE CENTER - TRUCK STATION	**Address:**	201 Airport Road	**Deferred Maintenance:**	$120,886
Facility Condition Index:	0.07 - Good	**City Code:**	DODGE CENTER	**Ext. Gross Area:**	10,170
Building Code:	T7965091364	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$82,702
Building Name:	DODGE CENTER - BRINE BLDG	**Address:**	201 Airport Road	**Deferred Maintenance:**	$14,694
Facility Condition Index:	0.18 - Fair	**City Code:**	DODGE CENTER	**Ext. Gross Area:**	378

Site: T796B91365 - FARIBAULT - TRUCK STATION

Building Code:	T7965021306	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$111,392
Building Name:	FARIBAULT - SALT/SAND STORAGE	**Address:**	555 NW 14th Street	**Deferred Maintenance:**	$64,011
Facility Condition Index:	0.57 - Crisis	**City Code:**	FARIBAULT	**Ext. Gross Area:**	1,522
Building Code:	T7965021324	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$699,295
Building Name:	FARIBAULT - SALT/SAND STORAGE	**Address:**	555 NW 24th Street	**Deferred Maintenance:**	$213,268
Facility Condition Index:	0.30 - Poor	**City Code:**	FARIBAULT	**Ext. Gross Area:**	5,436

Building Code:	T7965091328	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,256,903
Building Name:	FARIBAULT - EQUIP STORAGE	**Address:**	555 NW 24th Street	**Deferred Maintenance:**	$305,331
Facility Condition Index:	0.24 - Fair	**City Code:**	FARIBAULT	**Ext. Gross Area:**	8,000
Building Code:	T7965091362	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$352,578
Building Name:	FARIBAULT - POLE STORAGE BLDG	**Address:**	555 NW 24th Street	**Deferred Maintenance:**	$11,858
Facility Condition Index:	0.03 - Excellent	**City Code:**	FARIBAULT	**Ext. Gross Area:**	3,067
Building Code:	T7965091365	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,802,782
Building Name:	FARIBAULT - TRUCK STATION	**Address:**	555 NW 14th Street	**Deferred Maintenance:**	$134,736
Facility Condition Index:	0.07 - Good	**City Code:**	FARIBAULT	**Ext. Gross Area:**	9,949

Site: T796BR242480 - ALBERT LEA - REST AREA TIC

Building Code:	T7965095662	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,169,433
Building Name:	ALBERT LEA - REST AREA TIC	**Address:**	10818 I-35	**Deferred Maintenance:**	$116,750
Facility Condition Index:	0.10 - Good	**City Code:**	GLENVILLE	**Ext. Gross Area:**	4,132
Building Code:	T7965095681	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,628
Building Name:	ALBERT LEA - RA MISC STRG	**Address:**	10818 I-35	**Deferred Maintenance:**	$233
Facility Condition Index:	0.02 - Excellent	**City Code:**	GLENVILLE	**Ext. Gross Area:**	128

Site: T796BR577480 - STRAIGHT RIVER NORTH - REST AREA

Building Code:	T7965095663	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,026,518
Building Name:	STRAIGHT RIVER NORTH - REST AREA	**Address:**	7223 I-35 N	**Deferred Maintenance:**	$20,530
Facility Condition Index:	0.02 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	4,092
Building Code:	T7965095689	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$94,047
Building Name:	STRAIGHT RIVER NORTH-RA-MISC STRG	**Address:**	7223 I-35 N	**Deferred Maintenance:**	$1,881
Facility Condition Index:	0.02 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	608

Site: T796BR587480 - STRAIGHT RIVER SOUTH - REST AREA

Building Code:	T7965095659	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$687,792
Building Name:	STRAIGHT RIVER SOUTH - REST AREA	**Address:**	I-35 SB - 6 MI S. OF OWATONNA	**Deferred Maintenance:**	$54,161
Facility Condition Index:	0.08 - Good	**City Code:**	OWATONNA	**Ext. Gross Area:**	2,454
Building Code:	T7965095685	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$11,683
Building Name:	STRAIGHT RIVER SB - RA MISC STORAGE	**Address:**	I-35 SB - 6 MI S. OF OWATONNA	**Deferred Maintenance:**	$234
Facility Condition Index:	0.02 - Excellent	**City Code:**	OWATONNA	**Ext. Gross Area:**	128

Site: T796BR596680 - HEATH CREEK - REST AREA

Building Code:	T7965095657	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$768,019
Building Name:	HEATH CREEK - REST AREA	**Address:**	I-35 NB - 10 MI NO OF FARIBAUL	**Deferred Maintenance:**	$72,650
Facility Condition Index:	0.09 - Good	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	2,765
Building Code:	T7965095688	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$83,199
Building Name:	HEATH CREEK - MISC STRG	**Address:**	I-35 NB - 10 MI NO OF FARIBAUL	**Deferred Maintenance:**	$1,664
Facility Condition Index:	0.02 - Excellent	**City Code:**	NORTHFIELD	**Ext. Gross Area:**	567

Site: T796BR607080 - NEW MARKET - REST AREA

Building Code:	T7965095658	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$868,276
Building Name:	NEW MARKET - REST AREA	**Address:**	I-35 SB - SO OF ELKO EXIT	**Deferred Maintenance:**	$104,990
Facility Condition Index:	0.12 - Good	**City Code:**	NEW MARKET	**Ext. Gross Area:**	2,765
Building Code:	T7965095687	**Cost Model Name:**	Open Air Shelter	**Current Replacement Value:**	$39,963
Building Name:	NEW MARKET - RA MISC STORAGE	**Address:**	I-35 SB - SO OF ELKO EXIT	**Deferred Maintenance:**	$928
Facility Condition Index:	0.02 - Excellent	**City Code:**	NEW MARKET	**Ext. Gross Area:**	567

Site: T796BR612482 - HAYWARD - REST AREA

Building Code:	T7965095655	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$298,059
Building Name:	HAYWARD - REST AREA	**Address:**	I90 EB-2.2 MI E OF I35	**Deferred Maintenance:**	$25,502
Facility Condition Index:	0.09 - Good	**City Code:**	HAYWARD	**Ext. Gross Area:**	1,637
Building Code:	T7965095684	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$43,119
Building Name:	HAYWARD - RA MISC STORAGE	**Address:**	I90 EB-2.2 MI E OF I35	**Deferred Maintenance:**	$2,804
Facility Condition Index:	0.07 - Good	**City Code:**	HAYWARD	**Ext. Gross Area:**	268

Site: T796BR622482 - OAKLAND WOODS - REST AREA

Building Code:	T7965095656	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$338,541
Building Name:	OAKLAND WOODS - REST AREA	**Address:**	I-90 WB - 1 MI WEST JCT CO RD	**Deferred Maintenance:**	$32,874
Facility Condition Index:	0.10 - Good	**City Code:**	OAKLAND WOODS	**Ext. Gross Area:**	1,648
Building Code:	T7965095683	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$35,573
Building Name:	OAKLAND WOODS - RA MISC STORAGE	**Address:**	I-90 WB - 1 MI WEST JCT CO RD	**Deferred Maintenance:**	$2,958
Facility Condition Index:	0.08 - Good	**City Code:**	OAKLAND WOODS	**Ext. Gross Area:**	268

Site: T796BR842513 - LAKE PEPIN - REST AREA

Building Code:	T7965095661	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$383,213
Building Name:	LAKE PEPIN - REST AREA	**Address:**	US 61 - 5 MI NO OF LAKE CITY	**Deferred Maintenance:**	$33,115
Facility Condition Index:	0.09 - Good	**City Code:**	LAKE CITY	**Ext. Gross Area:**	1,555

Building Code:	T7965095686	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$17,714
Building Name:	LAKE PEPIN - RA MISC STORAGE	**Address:**	US 61 - 5 MI NO OF LAKE CITY	**Deferred Maintenance:**	$2,920
Facility Condition Index:	0.16 - Fair	**City Code:**	LAKE CITY	**Ext. Gross Area:**	128

Site: T797E21429 - ALDEN - LOADING SITE

Building Code:	T7970021429	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$253,157
Building Name:	ALDEN - SALT/SAND STORAGE	**Address:**	64446 CO RD 46	**Deferred Maintenance:**	$43,418
Facility Condition Index:	0.17 - Fair	**City Code:**	ALDEN	**Ext. Gross Area:**	2,496
Building Code:	T7970091440	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$62,329
Building Name:	ALDEN - MISC STORAGE	**Address:**	64446 CO RD 46	**Deferred Maintenance:**	$5,600
Facility Condition Index:	0.09 - Good	**City Code:**	ALDEN	**Ext. Gross Area:**	490

Site: T797E21431 - WATERVILLE - LOADING SITE

Building Code:	T7970021431	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$250,813
Building Name:	WATERVILLE YARD - SALT/SAND STORAGE	**Address:**	411 Reed St	**Deferred Maintenance:**	$21,024
Facility Condition Index:	0.08 - Good	**City Code:**	WATERVILLE	**Ext. Gross Area:**	2,496

Site: T797E91415 - BLUE EARTH - TRUCK STATION

Building Code:	T7970021437	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$388,039
Building Name:	BLUE EARTH - SAND/SALT STORAGE	**Address:**	38379 115th STREET	**Deferred Maintenance:**	$7,761
Facility Condition Index:	0.02 - Excellent	**City Code:**	BLUE EARTH	**Ext. Gross Area:**	4,732
Building Code:	T7970091415	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,358,961
Building Name:	BLUE EARTH - TRUCK STATION	**Address:**	38379 115TH STREET	**Deferred Maintenance:**	$335,991
Facility Condition Index:	0.25 - Fair	**City Code:**	BLUE EARTH	**Ext. Gross Area:**	6,983
Building Code:	T7970091441	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$299,975
Building Name:	BLUE EARTH - POLE STORAGE BLDG	**Address:**	38379 115TH STREET	**Deferred Maintenance:**	$16,800
Facility Condition Index:	0.06 - Good	**City Code:**	BLUE EARTH	**Ext. Gross Area:**	3,044

Site: T797E91416 - WELLS - TRUCK STATION

Building Code:	T7970021438	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$347,092
Building Name:	WELLS - SALT/SAND STORAGE	**Address:**	585 7th Avenue SE	**Deferred Maintenance:**	$6,942
Facility Condition Index:	0.02 - Excellent	**City Code:**	WELLS	**Ext. Gross Area:**	5,400
Building Code:	T7970091416	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,662,921
Building Name:	WELLS - TRUCK STATION	**Address:**	585 7th Avenue SE	**Deferred Maintenance:**	$33,258
Facility Condition Index:	0.02 - Excellent	**City Code:**	WELLS	**Ext. Gross Area:**	4,680

Building Code:	T7970091429	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$332,811
Building Name:	WELLS - UNHEATED STORAGE	**Address:**	585 7th Avenue SE	**Deferred Maintenance:**	$30,215
Facility Condition Index:	0.09 - Good	**City Code:**	WELLS	**Ext. Gross Area:**	3,072
Building Code:	T7970091450	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$57,083
Building Name:	WELLS - BRINE BUILDING	**Address:**	585 7th Avenue SE	**Deferred Maintenance:**	$3,630
Facility Condition Index:	0.06 - Good	**City Code:**	WELLS	**Ext. Gross Area:**	402

Site: T797E91418 - SAINT PETER - TRUCK STATION

Building Code:	T7970021417	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$395,413
Building Name:	ST PETER - SALT/SAND STORAGE	**Address:**	415 Ritt Street	**Deferred Maintenance:**	$47,669
Facility Condition Index:	0.12 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	3,935
Building Code:	T7970091418	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$897,373
Building Name:	ST PETER - TRUCK STATION	**Address:**	415 Ritt Street	**Deferred Maintenance:**	$169,111
Facility Condition Index:	0.19 - Fair	**City Code:**	ST. PETER	**Ext. Gross Area:**	5,856
Building Code:	T7970091435	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$298,759
Building Name:	ST PETER - POLE STORAGE BLDG	**Address:**	415 Ritt Street	**Deferred Maintenance:**	$19,125
Facility Condition Index:	0.06 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	3,060
Building Code:	T7970091446	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$56,554
Building Name:	ST PETER - BRINE BUILDING	**Address:**	415 Ritt Street	**Deferred Maintenance:**	$3,779
Facility Condition Index:	0.07 - Good	**City Code:**	ST. PETER	**Ext. Gross Area:**	402

Site: T797E91423 - MAPLETON - TRUCK STATION

Building Code:	T7970021421	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$274,528
Building Name:	MAPLETON - SALT/SAND STORAGE	**Address:**	403 8th Avenue SE	**Deferred Maintenance:**	$40,658
Facility Condition Index:	0.15 - Good	**City Code:**	MAPLETON	**Ext. Gross Area:**	2,733
Building Code:	T7970091423	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,055,845
Building Name:	MAPLETON - TRUCK STATION	**Address:**	403 8th Avenue SE	**Deferred Maintenance:**	$71,878
Facility Condition Index:	0.07 - Good	**City Code:**	MAPLETON	**Ext. Gross Area:**	5,838
Building Code:	T7970091427	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$32,286
Building Name:	MAPLETON - MISC STORAGE	**Address:**	403 8th Avenue SE	**Deferred Maintenance:**	$8,153
Facility Condition Index:	0.25 - Fair	**City Code:**	MAPLETON	**Ext. Gross Area:**	384
Building Code:	T7970091428	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$330,037
Building Name:	MAPLETON - POLE STORAGE BLDG	**Address:**	403 8th Avenue SE	**Deferred Maintenance:**	$25,051
Facility Condition Index:	0.08 - Good	**City Code:**	MAPLETON	**Ext. Gross Area:**	3,088

Building Code:	T7970091447	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$55,505
Building Name:	MAPLETON - BRINE BUILDING	**Address:**	403 8th Avenue SE	**Deferred Maintenance:**	$3,674
Facility Condition Index:	0.07 - Good	**City Code:**	MAPLETON	**Ext. Gross Area:**	402

Site: T797E91430 - LE SUEUR - TRUCK STATION

Building Code:	T7970021427	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$264,881
Building Name:	LE SUEUR - SALT/SAND STORAGE	**Address:**	201 Minnesota Avenue	**Deferred Maintenance:**	$30,684
Facility Condition Index:	0.12 - Good	**City Code:**	LE SUEUR	**Ext. Gross Area:**	2,635
Building Code:	T7970091430	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,389,756
Building Name:	LE SUEUR - TRUCK STATION	**Address:**	201 Minnesota Avenue	**Deferred Maintenance:**	$123,042
Facility Condition Index:	0.09 - Good	**City Code:**	LE SUEUR	**Ext. Gross Area:**	8,473
Building Code:	T7970091433	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$319,815
Building Name:	LE SUEUR - POLE STORAGE BLDG	**Address:**	201 Minnesota Avenue	**Deferred Maintenance:**	$36,691
Facility Condition Index:	0.11 - Good	**City Code:**	LE SUEUR	**Ext. Gross Area:**	3,476

Site: T797E91437 - MONTGOMERY - TRUCK STATION

Building Code:	T7970021428	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$264,881
Building Name:	MONTGOMERY - SALT/SAND STORAGE	**Address:**	201 Boulevard Avenue West	**Deferred Maintenance:**	$31,745
Facility Condition Index:	0.12 - Good	**City Code:**	MONTGOMERY	**Ext. Gross Area:**	2,636
Building Code:	T7970091405	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$369,806
Building Name:	MONTGOMERY - EQUIP STORAGE	**Address:**	201 Boulevard Avenue West	**Deferred Maintenance:**	$95,492
Facility Condition Index:	0.26 - Fair	**City Code:**	MONTGOMERY	**Ext. Gross Area:**	2,698
Building Code:	T7970091437	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$774,119
Building Name:	MONTGOMERY - TRUCK STATION	**Address:**	201 Boulevard Avenue West	**Deferred Maintenance:**	$91,722
Facility Condition Index:	0.12 - Good	**City Code:**	MONTGOMERY	**Ext. Gross Area:**	4,722

Site: T797E91438 - GAYLORD - TRUCK STATION

Building Code:	T7970021434	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$531,108
Building Name:	GAYLORD - SALT/SAND STORAGE	**Address:**	330 Railroad Avenue	**Deferred Maintenance:**	$62,012
Facility Condition Index:	0.12 - Good	**City Code:**	GAYLORD	**Ext. Gross Area:**	6,513
Building Code:	T7970091438	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,266,986
Building Name:	GAYLORD - TRUCK STATION	**Address:**	330 Railroad Avenue	**Deferred Maintenance:**	$227,339
Facility Condition Index:	0.18 - Fair	**City Code:**	GAYLORD	**Ext. Gross Area:**	8,366
Building Code:	T7970091439	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$287,453
Building Name:	GAYLORD - POLE STORAGE BLDG	**Address:**	330 Railroad Avenue	**Deferred Maintenance:**	$18,254
Facility Condition Index:	0.06 - Good	**City Code:**	GAYLORD	**Ext. Gross Area:**	3,072

Site: T797E91445 - MANKATO - HEADQUARTERS

Building Code:	T7970021435	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$1,251,155
Building Name:	MANKATO - SALT/SAND STORAGE	**Address:**	2151 Bassett Drive	**Deferred Maintenance:**	$25,023
Facility Condition Index:	0.02 - Excellent	**City Code:**	MANKATO	**Ext. Gross Area:**	15,400
Building Code:	T7970091442	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,458,689
Building Name:	MANKATO - UNHEATED/BRINE STRG	**Address:**	2151 Bassett Drive	**Deferred Maintenance:**	$61,633
Facility Condition Index:	0.04 - Excellent	**City Code:**	MANKATO	**Ext. Gross Area:**	9,120
Building Code:	T7970091445	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$44,896,515
Building Name:	MANKATO - HEADQUARTERS	**Address:**	2151 Bassett Drive	**Deferred Maintenance:**	$2,255,179
Facility Condition Index:	0.05 - Good	**City Code:**	MANKATO	**Ext. Gross Area:**	175,808
Building Code:	T7970091453	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$39,072
Building Name:	MANKATO - HAZ MAT	**Address:**	2151 Bassett Drive	**Deferred Maintenance:**	$3,907
Facility Condition Index:	0.10 - Good	**City Code:**	MANKATO	**Ext. Gross Area:**	160

Site: T797E91452 - WASECA - TRUCK STATION

Building Code:	T7970021436	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$812,438
Building Name:	WASECA - SALT/SAND STORAGE	**Address:**	1500 State Street South	**Deferred Maintenance:**	$137,696
Facility Condition Index:	0.17 - Fair	**City Code:**	WASECA	**Ext. Gross Area:**	10,000
Building Code:	T7970091444	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$380,841
Building Name:	WASECA - POLE STORAGE BLDG	**Address:**	1500 State Street South	**Deferred Maintenance:**	$30,963
Facility Condition Index:	0.08 - Good	**City Code:**	WASECA	**Ext. Gross Area:**	3,072
Building Code:	T7970091452	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,529,344
Building Name:	WASECA - TRUCK STATION	**Address:**	1500 State Street South	**Deferred Maintenance:**	$63,329
Facility Condition Index:	0.04 - Excellent	**City Code:**	WASECA	**Ext. Gross Area:**	8,845

Site: T797E91456 - COURTLAND - TRUCK STATION

Building Code:	T7970021439	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$563,618
Building Name:	COURTLAND - SALT/SAND STORAGE	**Address:**	132 ZIESKE RD	**Deferred Maintenance:**	$11,272
Facility Condition Index:	0.02 - Excellent	**City Code:**	COURTLAND	**Ext. Gross Area:**	7,000
Building Code:	T7970091456	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$2,506,610
Building Name:	COURTLAND - TRUCK STATION	**Address:**	132 ZIESKE RD	**Deferred Maintenance:**	$50,132
Facility Condition Index:	0.02 - Excellent	**City Code:**	COURTLAND	**Ext. Gross Area:**	10,102
Building Code:	T7970091457	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$408,299
Building Name:	COURTLAND - UNHEATED STORAGE	**Address:**	132 ZIESKE RD	**Deferred Maintenance:**	$8,166
Facility Condition Index:	0.02 - Excellent	**City Code:**	COURTLAND	**Ext. Gross Area:**	3,400

Building Code:	T7970091458	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$150,299
Building Name:	COURTLAND - CVRD STORAGE BINS	**Address:**	132 ZIESKE RD	**Deferred Maintenance:**	$3,006
Facility Condition Index:	0.02 - Excellent	**City Code:**	COURTLAND	**Ext. Gross Area:**	2,208

Site: T797ER632280 - BLUE EARTH EAST - REST AREA

Building Code:	T7970095702	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$544,227
Building Name:	BLUE EARTH EAST - REST AREA	**Address:**	I90 EB - BLUE EARTH	**Deferred Maintenance:**	$60,889
Facility Condition Index:	0.11 - Good	**City Code:**	BLUE EARTH	**Ext. Gross Area:**	1,736

Site: T797ER642280 - BLUE EARTH WEST - REST AREA

Building Code:	T7970095703	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$538,162
Building Name:	BLUE EARTH WEST - REST AREA	**Address:**	I-90 WB - BLUE EARTH	**Deferred Maintenance:**	$41,411
Facility Condition Index:	0.08 - Good	**City Code:**	BLUE EARTH	**Ext. Gross Area:**	1,738
Building Code:	T7970095730	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$101,643
Building Name:	BLUE EARTH WEST - RA MISC STORAGE	**Address:**	I90 WB - BLUE EARTH	**Deferred Maintenance:**	$8,471
Facility Condition Index:	0.08 - Good	**City Code:**	BLUE EARTH	**Ext. Gross Area:**	765

Site: T797ER804013 - MINNESOTA VALLEY - REST AREA

Building Code:	T7970095710	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$569,523
Building Name:	MINNESOTA VALLEY - REST AREA	**Address:**	US 169 - NO OF LE SUEUR	**Deferred Maintenance:**	$106,261
Facility Condition Index:	0.19 - Fair	**City Code:**	LE SUEUR	**Ext. Gross Area:**	1,913

Site: T797W21633 - MADELIA - LOADING SITE

Building Code:	T7975021633	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$281,392
Building Name:	MADELIA - SALT/SAND STORAGE	**Address:**	19 EAGER AV. NE	**Deferred Maintenance:**	$53,076
Facility Condition Index:	0.19 - Fair	**City Code:**	MADELIA	**Ext. Gross Area:**	3,400
Building Code:	T7975091644	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$199,935
Building Name:	MADELIA - LOADER STORAGE	**Address:**	19 EAGER AV NE	**Deferred Maintenance:**	$11,889
Facility Condition Index:	0.06 - Good	**City Code:**	MADELIA	**Ext. Gross Area:**	560

Site: T797W91609 - LUVERNE - TRUCK STATION

Building Code:	T7975021622	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$217,773
Building Name:	LUVERNE - SALT/SAND STORAGE	**Address:**	301 W KOEHN AVENUE	**Deferred Maintenance:**	$21,967
Facility Condition Index:	0.10 - Good	**City Code:**	LUVERNE	**Ext. Gross Area:**	1,462

Building Code: T7975021626
Building Name: LUVERNE - SALT/SAND STORAGE
Facility Condition Index: 0.10 - Good

Cost Model Name: Open Air Storage Structure
Address: 301 W KOEHN AVENUE
City Code: LUVERNE

Current Replacement Value: $100,175
Deferred Maintenance: $10,449
Ext. Gross Area: 944

Building Code: T7975021632
Building Name: LUVERNE - SALT/SAND STORAGE
Facility Condition Index: 0.19 - Fair

Cost Model Name: Fabric Structure
Address: 301 W KOEHN AVENUE
City Code: LUVERNE

Current Replacement Value: $343,335
Deferred Maintenance: $66,081
Ext. Gross Area: 3,932

Building Code: T7975091609
Building Name: LUVERNE - TRUCK STATION
Facility Condition Index: 0.19 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 301 W KOEHN AVENUE
City Code: LUVERNE

Current Replacement Value: $2,277,611
Deferred Maintenance: $425,753
Ext. Gross Area: 10,307

Building Code: T7975091642
Building Name: LUVERNE - POLE STORAGE
Facility Condition Index: 0.06 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 301 W KOEHN AVENUE
City Code: LUVERNE

Current Replacement Value: $404,309
Deferred Maintenance: $25,545
Ext. Gross Area: 3,853

Building Code: T7975091646
Building Name: LUVERNE - BRINE BUILDING
Facility Condition Index: 0.33 - Poor

Cost Model Name: Utility Shed
Address: 301 W KOEHN AVENUE
City Code: LUVERNE

Current Replacement Value: $37,794
Deferred Maintenance: $12,472
Ext. Gross Area: 120

Site: T797W91613 - WORTHINGTON - TRUCK STATION

Building Code: T7975021627
Building Name: WORTHINGTON - SALT/SAND STORAGE
Facility Condition Index: 0.18 - Fair

Cost Model Name: Open Air Storage Structure
Address: 1475 SPRING AVENUE
City Code: WORTHINGTON

Current Replacement Value: $262,533
Deferred Maintenance: $46,078
Ext. Gross Area: 2,496

Building Code: T7975091613
Building Name: WORTHINGTON - TRUCK STATION
Facility Condition Index: 0.14 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1475 SPRING AVENUE
City Code: WORTHINGTON

Current Replacement Value: $2,934,985
Deferred Maintenance: $403,199
Ext. Gross Area: 15,414

Building Code: T7975091634
Building Name: WORTHINGTON - POLE STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1475 SPRING AVENUE
City Code: WORTHINGTON

Current Replacement Value: $322,734
Deferred Maintenance: $22,403
Ext. Gross Area: 3,087

Site: T797W91614 - WINDOM - HEADQUARTERS

Building Code: T7975021608
Building Name: WINDOM - SALT/SAND STORAGE
Facility Condition Index: 0.31 - Poor

Cost Model Name: Open Air Storage Structure
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $119,824
Deferred Maintenance: $36,695
Ext. Gross Area: 1,595

Building Code: T7975021624
Building Name: WINDOM - SALT/SAND STORAGE
Facility Condition Index: 0.14 - Good

Cost Model Name: Open Air Storage Structure
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $257,845
Deferred Maintenance: $34,934
Ext. Gross Area: 2,496

Building Code: T7975091614
Building Name: WINDOM - HEADQUARTERS
Facility Condition Index: 0.19 - Fair

Cost Model Name: Joint Office/Warehouse Facility
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $16,927,724
Deferred Maintenance: $3,206,498
Ext. Gross Area: 56,213

Building Code: T7975091619
Building Name: WINDOM - MISC STORAGE
Facility Condition Index: 0.10 - Good

Cost Model Name: Utility Shed
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $37,830
Deferred Maintenance: $3,783
Ext. Gross Area: 227

Building Code: T7975091628
Building Name: WINDOM - POLE STORAGE
Facility Condition Index: 0.15 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $697,690
Deferred Maintenance: $106,022
Ext. Gross Area: 5,877

Building Code: T7975091641
Building Name: WINDOM - POLE STORAGE
Facility Condition Index: 0.07 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $1,182,296
Deferred Maintenance: $79,972
Ext. Gross Area: 11,520

Building Code: T7975091645
Building Name: WINDOM - BRINE BUILDING
Facility Condition Index: 0.03 - Excellent

Cost Model Name: Butler-style Warehouse Building
Address: 180 County Road 26
City Code: WINDOM

Current Replacement Value: $498,119
Deferred Maintenance: $13,395
Ext. Gross Area: 3,460

Site: T797W91616 - JACKSON - TRUCK STATION

Building Code: T7975021607
Building Name: JACKSON - SALT/SAND STORAGE
Facility Condition Index: 0.34 - Poor

Cost Model Name: Open Air Storage Structure
Address: 149 County Road 34 East
City Code: JACKSON

Current Replacement Value: $103,931
Deferred Maintenance: $35,025
Ext. Gross Area: 1,335

Building Code: T7975021629
Building Name: JACKSON - SALT/SAND STORAGE
Facility Condition Index: 0.08 - Good

Cost Model Name: Open Air Storage Structure
Address: 149 County Road 34 East
City Code: JACKSON

Current Replacement Value: $283,570
Deferred Maintenance: $22,634
Ext. Gross Area: 2,696

Building Code: T7975091616
Building Name: JACKSON - TRUCK STATION
Facility Condition Index: 0.17 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 149 County Road 34 East
City Code: JACKSON

Current Replacement Value: $1,935,145
Deferred Maintenance: $332,630
Ext. Gross Area: 8,803

Building Code: T7975091643
Building Name: JACKSON - POLE STORAGE
Facility Condition Index: 0.05 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 149 County Road 34 East
City Code: JACKSON

Current Replacement Value: $434,979
Deferred Maintenance: $21,757
Ext. Gross Area: 3,500

Building Code: T7975091649
Building Name: JACKSON - BRINE BUILDING
Facility Condition Index: 0.33 - Poor

Cost Model Name: Utility Shed
Address: 149 County Road 3 East
City Code: JACKSON

Current Replacement Value: $30,673
Deferred Maintenance: $10,122
Ext. Gross Area: 120

Site: T797W91620 - FAIRMONT - TRUCK STATION

Building Code:	T7975021621	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$249,515
Building Name:	FAIRMONT - SALT/SAND STORAGE	**Address:**	1300 Marcus Street	**Deferred Maintenance:**	$36,467
Facility Condition Index:	0.15 - Good	**City Code:**	FAIRMONT	**Ext. Gross Area:**	1,935
Building Code:	T7975021628	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$140,120
Building Name:	FAIRMONT - SALT/SAND STORAGE	**Address:**	1300 Marcus Street	**Deferred Maintenance:**	$14,284
Facility Condition Index:	0.10 - Good	**City Code:**	FAIRMONT	**Ext. Gross Area:**	944
Building Code:	T7975091620	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,236,799
Building Name:	FAIRMONT - TRUCK STATION	**Address:**	1300 Marcus Street	**Deferred Maintenance:**	$236,569
Facility Condition Index:	0.19 - Fair	**City Code:**	FAIRMONT	**Ext. Gross Area:**	6,983
Building Code:	T7975091640	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$311,143
Building Name:	FAIRMONT - POLE STORAGE	**Address:**	1300 Marcus Street	**Deferred Maintenance:**	$21,380
Facility Condition Index:	0.07 - Good	**City Code:**	FAIRMONT	**Ext. Gross Area:**	3,072

Site: T797W91627 - SLEEPY EYE - TRUCK STATION

Building Code:	T7975021619	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$93,207
Building Name:	SLEEPY EYE - SALT/SAND STORAGE	**Address:**	900 Cedar Street NE	**Deferred Maintenance:**	$15,003
Facility Condition Index:	0.16 - Fair	**City Code:**	SLEEPY EYE	**Ext. Gross Area:**	944
Building Code:	T7975021630	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$264,881
Building Name:	SLEEPY EYE - SALT/SAND STORAGE	**Address:**	900 Cedar Street NE	**Deferred Maintenance:**	$45,429
Facility Condition Index:	0.17 - Fair	**City Code:**	SLEEPY EYE	**Ext. Gross Area:**	2,636
Building Code:	T7975091627	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$713,224
Building Name:	SLEEPY EYE - TRUCK STATION	**Address:**	900 Cedar Street NE	**Deferred Maintenance:**	$175,653
Facility Condition Index:	0.25 - Fair	**City Code:**	SLEEPY EYE	**Ext. Gross Area:**	4,338
Building Code:	T7975091631	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$300,404
Building Name:	SLEEPY EYE - POLE STORAGE	**Address:**	900 Cedar Street NE	**Deferred Maintenance:**	$49,830
Facility Condition Index:	0.17 - Fair	**City Code:**	SLEEPY EYE	**Ext. Gross Area:**	3,088
Building Code:	T7975091647	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$35,165
Building Name:	SLEEPY EYE - BRINE BUILDING	**Address:**	900 Cedar Street NE	**Deferred Maintenance:**	$11,604
Facility Condition Index:	0.33 - Poor	**City Code:**	SLEEPY EYE	**Ext. Gross Area:**	120

Site: T797W91629 - ADRIAN - TRUCK STATION

Building Code:	T7975021623	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$257,961
Building Name:	ADRIAN - SALT/SAND STORAGE	**Address:**	504 County Road 35	**Deferred Maintenance:**	$40,650
Facility Condition Index:	0.16 - Fair	**City Code:**	ADRIAN	**Ext. Gross Area:**	2,496

Building Code: T7975091629
Building Name: ADRIAN - TRUCK STATION
Facility Condition Index: 0.18 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 504 County Road 35
City Code: ADRIAN

Current Replacement Value: $1,087,488
Deferred Maintenance: $195,255
Ext. Gross Area: 6,224

Building Code: T7975091630
Building Name: ADRIAN - POLE STORAGE
Facility Condition Index: 0.17 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 504 County Road 35
City Code: ADRIAN

Current Replacement Value: $420,572
Deferred Maintenance: $70,048
Ext. Gross Area: 4,177

Site: T797W91632 - SAINT JAMES - TRUCK STATION

Building Code: T7975021625
Building Name: ST JAMES - SALT/SAND STORAGE
Facility Condition Index: 0.09 - Good

Cost Model Name: Open Air Storage Structure
Address: 1513 - 7th Avenue South
City Code: ST. JAMES

Current Replacement Value: $481,046
Deferred Maintenance: $41,561
Ext. Gross Area: 3,952

Building Code: T7975091632
Building Name: ST JAMES - TRUCK STATION
Facility Condition Index: 0.14 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1513 - 7th Avenue South
City Code: ST. JAMES

Current Replacement Value: $2,762,319
Deferred Maintenance: $388,764
Ext. Gross Area: 14,144

Building Code: T7975091633
Building Name: ST JAMES - POLE STORAGE
Facility Condition Index: 0.09 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1513 - 7th Avenue South
City Code: ST. JAMES

Current Replacement Value: $445,948
Deferred Maintenance: $38,812
Ext. Gross Area: 4,500

Building Code: T7975091648
Building Name: ST JAMES - BRINE BUILDING
Facility Condition Index: 0.33 - Poor

Cost Model Name: Utility Shed
Address: 1513 - 7th Avenue South
City Code: ST. JAMES

Current Replacement Value: $36,817
Deferred Maintenance: $12,150
Ext. Gross Area: 120

Site: T797W91694 - SHERBURN - TRUCK STATION(LEASED)

Building Code: T7975021631
Building Name: SHERBURN - SALT/SAND STORAGE
Facility Condition Index: 0.08 - Good

Cost Model Name: Open Air Storage Structure
Address: 221 FAIRMONT AVENUE
City Code: SHERBURN

Current Replacement Value: $109,872
Deferred Maintenance: $9,210
Ext. Gross Area: 1,054

Site: T797W91698 - STORDEN - TRUCK STATION(LEASED

Building Code: T7975021618
Building Name: STORDEN - SALT/SAND STORAGE
Facility Condition Index: 0.17 - Fair

Cost Model Name: Open Air Storage Structure
Address: 100 MN Hwy 30
City Code: STORDEN

Current Replacement Value: $93,691
Deferred Maintenance: $16,088
Ext. Gross Area: 1,025

Site: T797W92119 - WORTHINGTON - WEIGH SCALE

Building Code: T7975092119
Building Name: WORTHINGTON - WEIGH SCALE
Facility Condition Index: 0.11 - Good

Cost Model Name: Single-story Office/Public Access Facility
Address: I-90 EAST OF WORTHINGTON
City Code: WORTHINGTON

Current Replacement Value: $506,977
Deferred Maintenance: $55,641
Ext. Gross Area: 2,747

Building Code:	T7975092145	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$104,326
Building Name:	WORTHINGTON WS - WS MISC STORAGE	**Address:**		**Deferred Maintenance:**	$2,087
Facility Condition Index:	0.02 - Excellent	**City Code:**	WORTHINGTON	**Ext. Gross Area:**	960

Site: T797WR136780 - BEAVER CREEK - REST AREA TIC

Building Code:	T7975095750	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$1,249,011
Building Name:	BEAVER CREEK - REST AREA TIC	**Address:**	BOX 90	**Deferred Maintenance:**	$258,877
Facility Condition Index:	0.21 - Fair	**City Code:**	BEAVER CREEK	**Ext. Gross Area:**	3,655
Building Code:	T7975095782	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$35,191
Building Name:	BEAVER CREEK - RA MISC STORAGE	**Address:**	BOX 90	**Deferred Maintenance:**	$13,676
Facility Condition Index:	0.39 - Poor	**City Code:**	BEAVER CREEK	**Ext. Gross Area:**	320
Building Code:	T7975095787	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$42,436
Building Name:	BEAVER CREEK - RA MISC STORAGE	**Address:**	BOX 90	**Deferred Maintenance:**	$2,332
Facility Condition Index:	0.05 - Good	**City Code:**	BEAVER CREEK	**Ext. Gross Area:**	320

Site: T797WR165380 - ADRIAN WEST - REST AREA

Building Code:	T7975095751	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$403,695
Building Name:	ADRIAN WEST - REST AREA	**Address:**	14396 I-90 WESTBOUND	**Deferred Maintenance:**	$91,044
Facility Condition Index:	0.23 - Fair	**City Code:**	ADRIAN	**Ext. Gross Area:**	1,150
Building Code:	T7975095785	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,329
Building Name:	ARIAN WB - RA MISC STORAGE	**Address:**	14396 I-90 WESTBOUND	**Deferred Maintenance:**	$827
Facility Condition Index:	0.02 - Excellent	**City Code:**	ADRIAN	**Ext. Gross Area:**	225

Site: T797WR175380 - ADRIAN EAST - REST AREA

Building Code:	T7975095752	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$403,695
Building Name:	ADRIAN EAST - REST AREA	**Address:**	13605 I-90 EASTBOUND	**Deferred Maintenance:**	$93,168
Facility Condition Index:	0.23 - Fair	**City Code:**	ADRIAN	**Ext. Gross Area:**	1,150
Building Code:	T7975095784	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,329
Building Name:	ADRIAN EAST - RA MISC STORAGE	**Address:**	13605 I-90 EASTBOUND	**Deferred Maintenance:**	$827
Facility Condition Index:	0.02 - Excellent	**City Code:**	ADRIAN	**Ext. Gross Area:**	225

Site: T797WR283280 - CLEAR LAKE - REST AREA

Building Code:	T7975095753	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$412,763
Building Name:	CLEAR LAKE - REST AREA	**Address:**	49567 I-90 EASTBOUND	**Deferred Maintenance:**	$122,730
Facility Condition Index:	0.30 - Fair	**City Code:**	JACKSON	**Ext. Gross Area:**	1,150

Building Code:	T7975095786	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$41,329
Building Name:	CLEAR LAKE - RA MISC STORAGE	**Address:**	49567 I-90 EASTBOUND	**Deferred Maintenance:**	$827
Facility Condition Index:	0.02 - Excellent	**City Code:**	JACKSON	**Ext. Gross Area:**	205

Site: T797WR293280 - DES MOINES - REST AREA

Building Code:	T7975095754	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$826,297
Building Name:	DES MOINES - REST AREA	**Address:**	52688 I-90 WESTBOUND	**Deferred Maintenance:**	$145,909
Facility Condition Index:	0.18 - Fair	**City Code:**	JACKSON	**Ext. Gross Area:**	2,927

Site: T797WR669723 - WATONWAN - REST AREA

Building Code:	T7975095771	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$437,636
Building Name:	WATONWAN - REST AREA	**Address:**	77588 MN HWY 60	**Deferred Maintenance:**	$192,797
Facility Condition Index:	0.44 - Poor	**City Code:**	ST. JAMES	**Ext. Gross Area:**	1,576

Site: T797WR795305 - WORTHINGTON - REST AREA

Building Code:	T7975095770	**Cost Model Name:**	Single-story Office/Public Access Facility	**Current Replacement Value:**	$801,153
Building Name:	WORTHINGTON - REST AREA TIC	**Address:**	29328 MN HWY 59	**Deferred Maintenance:**	$108,096
Facility Condition Index:	0.13 - Good	**City Code:**	WORTHINGTON	**Ext. Gross Area:**	2,457

Site: T798A21016 - NEW LONDON - LOADING SITE

Building Code:	T7980021016	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$227,665
Building Name:	NEW LONDON - SALT/SAND STORAGE	**Address:**	9750 187TH AVE NE	**Deferred Maintenance:**	$16,113
Facility Condition Index:	0.07 - Good	**City Code:**	NEW LONDON	**Ext. Gross Area:**	2,219

Site: T798A21516 - FLORENCE - LOADING SITE

Building Code:	T7980021516	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$178,290
Building Name:	FLORENCE - SALT/SAND STORAGE	**Address:**	JCT TH23 And TH14	**Deferred Maintenance:**	$40,987
Facility Condition Index:	0.23 - Fair	**City Code:**	FLORENCE	**Ext. Gross Area:**	1,614

Site: T798A91015 - OLIVIA - TRUCK STATION

Building Code:	T7980021006	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$108,250
Building Name:	OLIVIA - SALT/SAND STORAGE	**Address:**	1509 LINCOLN ST W	**Deferred Maintenance:**	$18,560
Facility Condition Index:	0.17 - Fair	**City Code:**	OLIVIA	**Ext. Gross Area:**	1,080
Building Code:	T7980021519	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,046,494
Building Name:	OLIVIA - SALT/SAND STORAGE	**Address:**	1509 LINCOLN ST W	**Deferred Maintenance:**	$87,167
Facility Condition Index:	0.08 - Good	**City Code:**	OLIVIA	**Ext. Gross Area:**	9,166

Building Code:	T7980091015	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,586,195
Building Name:	OLIVIA - TRUCK STATION	**Address:**	1509 W LINCOLN AVE	**Deferred Maintenance:**	$375,140
Facility Condition Index:	0.24 - Fair	**City Code:**	OLIVIA	**Ext. Gross Area:**	7,619

Site: T798A91020 - CLARA CITY - STORAGE SITE

Building Code:	T7980021007	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$94,231
Building Name:	CLARA CITY - SALT/SAND STORAGE	**Address:**	20 1ST AVE NE	**Deferred Maintenance:**	$10,381
Facility Condition Index:	0.11 - Good	**City Code:**	CHISHOLM	**Ext. Gross Area:**	1,050
Building Code:	T7980091020	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$672,241
Building Name:	CLARA CITY - UNHEATED STORAGE	**Address:**	20 1ST AVE NE	**Deferred Maintenance:**	$93,027
Facility Condition Index:	0.14 - Good	**City Code:**	CLARA CITY	**Ext. Gross Area:**	4,320

Site: T798A91023 - WILLMAR - HEADQUARTERS

Building Code:	T7980021012	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,054,256
Building Name:	WILLMAR - SALT/SAND STORAGE	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$109,386
Facility Condition Index:	0.10 - Good	**City Code:**	WILLMAR	**Ext. Gross Area:**	10,923
Building Code:	T7980021017	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$274,266
Building Name:	WILLMAR - SALT/SAND STORAGE	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$26,725
Facility Condition Index:	0.10 - Good	**City Code:**	WILLMAR	**Ext. Gross Area:**	2,328
Building Code:	T7980091023	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$20,536,241
Building Name:	WILLMAR - HEADQUARTERS	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$3,246,707
Facility Condition Index:	0.16 - Fair	**City Code:**	WILLMAR	**Ext. Gross Area:**	106,870
Building Code:	T7980091024	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$339,324
Building Name:	WILLMAR - POLE STORAGE	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$67,123
Facility Condition Index:	0.20 - Fair	**City Code:**	WILLMAR	**Ext. Gross Area:**	8,493
Building Code:	T7980091027	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$436,615
Building Name:	WILLMAR - POLE STORAGE	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$32,320
Facility Condition Index:	0.07 - Good	**City Code:**	WILLMAR	**Ext. Gross Area:**	4,184
Building Code:	T7980091029	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$32,782
Building Name:	WILLMAR - HAZMAT STORAGE	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$3,278
Facility Condition Index:	0.10 - Good	**City Code:**	WILLMAR	**Ext. Gross Area:**	133
Building Code:	T7980091032	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$26,601
Building Name:	WILLMAR - BRINE BUILDING	**Address:**	2505 TRANSPORTATION RD	**Deferred Maintenance:**	$1,250
Facility Condition Index:	0.05 - Excellent	**City Code:**	WILLMAR	**Ext. Gross Area:**	513

Building Code: T7980091034
Building Name: WILLMAR - MISC STORAGE
Facility Condition Index: 0.08 - Good

Cost Model Name: Single-story Work Facility
Address: 2505 TRANSPORTATION RD
City Code: WILLMAR

Current Replacement Value: $77,920
Deferred Maintenance: $5,982
Ext. Gross Area: 779

Building Code: T7980091038
Building Name: WILLMAR - MISC STORAGE
Facility Condition Index: 0.04 - Excellent

Cost Model Name: Butler-style Warehouse Building
Address: 2505 TRANSPORTATION RD
City Code: WILLMAR

Current Replacement Value: $170,782
Deferred Maintenance: $6,103
Ext. Gross Area: 768

Building Code: T7980091042
Building Name: WILLMAR - MISC STORAGE
Facility Condition Index: 0.04 - Excellent

Cost Model Name: Butler-style Warehouse Building
Address: 2505 TRANSPORTATION RD
City Code: WILLMAR

Current Replacement Value: $260,239
Deferred Maintenance: $10,483
Ext. Gross Area: 550

Site: T798A91025 - MILAN - LOADING SITE

Building Code: T7980021019
Building Name: MILAN - SALT/SAND STORAGE
Facility Condition Index: 0.05 - Good

Cost Model Name: Open Air Storage Structure
Address: 0.5 MI NW OF MILAN ON HWY 7
City Code: MILAN

Current Replacement Value: $54,812
Deferred Maintenance: $2,875
Ext. Gross Area: 550

Building Code: T7980091025
Building Name: MILAN - MISC STORAGE
Facility Condition Index: 0.04 - Excellent

Cost Model Name: Single-story Work Facility
Address: 0.5 MI NW OF MILAN ON HWY 7
City Code: MILAN

Current Replacement Value: $94,366
Deferred Maintenance: $4,246
Ext. Gross Area: 773

Site: T798A91028 - MONTEVIDEO - TRUCK STATION

Building Code: T7980021009
Building Name: MONTEVIDEO - SALT/SAND STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 815 N 17TH ST
City Code: MONTEVIDEO

Current Replacement Value: $1,073,339
Deferred Maintenance: $124,147
Ext. Gross Area: 8,794

Building Code: T7980091028
Building Name: MONTEVIDEO - TRUCK STATION
Facility Condition Index: 0.15 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 815 N 17TH ST
City Code: MONTEVIDEO

Current Replacement Value: $1,272,395
Deferred Maintenance: $184,532
Ext. Gross Area: 6,457

Site: T798A91030 - HUTCHINSON - TRUCK STATION

Building Code: T7980021014
Building Name: HUTCHINSON - SALT/SAND STORAGE
Facility Condition Index: 0.25 - Fair

Cost Model Name: Open Air Storage Structure
Address: 1400 ADAMS ST SE
City Code: HUTCHINSON

Current Replacement Value: $1,554,265
Deferred Maintenance: $387,711
Ext. Gross Area: 12,497

Building Code: T7980091030
Building Name: HUTCHINSON - TRUCK STATION
Facility Condition Index: 0.17 - Fair

Cost Model Name: Joint Office/Warehouse Facility
Address: 1400 ADAMS ST SE
City Code: HUTCHINSON

Current Replacement Value: $13,534,773
Deferred Maintenance: $2,301,331
Ext. Gross Area: 26,161

Building Code: T7980091033
Building Name: HUTCHINSON - POLE STORAGE
Facility Condition Index: 0.09 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1400 ADAMS ST SE
City Code: HUTCHINSON

Current Replacement Value: $987,184
Deferred Maintenance: $93,209
Ext. Gross Area: 8,722

Building Code:	T7980091035	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$311,676
Building Name:	HUTCHINSON - BRINE BUILDING	**Address:**	1400 ADAMS ST SE	**Deferred Maintenance:**	$18,258
Facility Condition Index:	0.06 - Good	**City Code:**	HUTCHINSON	**Ext. Gross Area:**	1,860

Site: T798A91031 - GLENCOE - TRUCK STATION

Building Code:	T7980021003	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$153,291
Building Name:	GLENCOE - OLD SALT/SAND STORAGE	**Address:**	113 8TH ST E	**Deferred Maintenance:**	$41,299
Facility Condition Index:	0.27 - Fair	**City Code:**	GLENCOE	**Ext. Gross Area:**	1,050
Building Code:	T7980021015	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$848,228
Building Name:	GLENCOE - JOINT - SALT/SAND	**Address:**	310 13TH ST W	**Deferred Maintenance:**	$73,694
Facility Condition Index:	0.09 - Good	**City Code:**	GLENCOE	**Ext. Gross Area:**	9,907
Building Code:	T7980091003	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$312,728
Building Name:	GLENCOE - OLD MISC STORAGE	**Address:**	113 8TH ST E	**Deferred Maintenance:**	$97,414
Facility Condition Index:	0.31 - Poor	**City Code:**	GLENCOE	**Ext. Gross Area:**	10,118
Building Code:	T7980091031	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,831,618
Building Name:	GLENCOE - TRUCK STATION	**Address:**	310 13TH ST W	**Deferred Maintenance:**	$254,749
Facility Condition Index:	0.14 - Good	**City Code:**	GLENCOE	**Ext. Gross Area:**	9,422
Building Code:	T7980091039	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$83,194
Building Name:	GLENCOE - LOADER STORAGE	**Address:**	310 13TH ST W	**Deferred Maintenance:**	$6,151
Facility Condition Index:	0.07 - Good	**City Code:**	GLENCOE	**Ext. Gross Area:**	640
Building Code:	T7980091040	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$25,186
Building Name:	GLENCOE - BRINE BUILDING	**Address:**	310 13TH ST W	**Deferred Maintenance:**	$2,020
Facility Condition Index:	0.08 - Good	**City Code:**	GLENCOE	**Ext. Gross Area:**	288

Site: T798A91036 - LITCHFIELD - TRUCK STATION

Building Code:	T7980021018	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,024,652
Building Name:	LITCHFIELD - SALT/SAND STORAGE	**Address:**	422 S JOHNSON DRIVE	**Deferred Maintenance:**	$94,767
Facility Condition Index:	0.09 - Good	**City Code:**	LITCHFIELD	**Ext. Gross Area:**	12,120
Building Code:	T7980091036	**Cost Model Name:**	Joint Office/Warehouse Facility	**Current Replacement Value:**	$9,150,921
Building Name:	LITCHFIELD - TRUCK STATION	**Address:**	422 S JOHNSON DRIVE	**Deferred Maintenance:**	$885,922
Facility Condition Index:	0.10 - Good	**City Code:**	LITCHFIELD	**Ext. Gross Area:**	35,882
Building Code:	T7980091041	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,304,762
Building Name:	LITCHFIELD - POLE STORAGE	**Address:**	422 S JOHNSON DRIVE	**Deferred Maintenance:**	$119,524
Facility Condition Index:	0.09 - Good	**City Code:**	LITCHFIELD	**Ext. Gross Area:**	10,220

Site: T798A91514 - IVANHOE - LOADING SITE

Building Code: T7980021503
Building Name: IVANHOE - SALT/SAND STORAGE
Facility Condition Index: 0.08 - Good

Cost Model Name: Open Air Storage Structure
Address: 513 WEST DIVISION
City Code: IVANHOE

Current Replacement Value: $95,804
Deferred Maintenance: $8,116
Ext. Gross Area: 1,080

Building Code: T7980021520
Building Name: IVANHOE - SALT/SAND STORAGE
Facility Condition Index: 0.12 - Good

Cost Model Name: Open Air Storage Structure
Address: 513 WEST DIVISION
City Code: IVANHOE

Current Replacement Value: $847,467
Deferred Maintenance: $102,689
Ext. Gross Area: 8,200

Building Code: T7980091514
Building Name: IVANHOE - STORAGE FACILITY
Facility Condition Index: 0.31 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 513 WEST DIVISION
City Code: IVANHOE

Current Replacement Value: $526,559
Deferred Maintenance: $164,089
Ext. Gross Area: 2,695

Building Code: T7980091549
Building Name: IVANHOE - BRINE BLDG
Facility Condition Index: 0.11 - Good

Cost Model Name: Single-story Work Facility
Address: 513 WEST DIVISION
City Code: IVANHOE

Current Replacement Value: $57,219
Deferred Maintenance: $6,340
Ext. Gross Area: 361

Site: T798A91521 - MADISON - TRUCK STATION

Building Code: T7980021013
Building Name: MADISON - SALT/SAND STORAGE
Facility Condition Index: 0.16 - Fair

Cost Model Name: Open Air Storage Structure
Address: 2340 HWY 40 E
City Code: MADISON

Current Replacement Value: $961,675
Deferred Maintenance: $154,323
Ext. Gross Area: 8,855

Building Code: T7980091506
Building Name: MADISON - MISC STORAGE
Facility Condition Index: 0.14 - Good

Cost Model Name: Single-story Work Facility
Address: 2340 HWY 40 E
City Code: MADISON

Current Replacement Value: $125,008
Deferred Maintenance: $17,252
Ext. Gross Area: 1,024

Building Code: T7980091521
Building Name: MADISON - TRUCK STATION
Facility Condition Index: 0.13 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 2340 HWY 40 E
City Code: MADISON

Current Replacement Value: $1,106,629
Deferred Maintenance: $138,848
Ext. Gross Area: 5,818

Building Code: T7980091547
Building Name: MADISON - BRINE BUILDING
Facility Condition Index: 0.11 - Good

Cost Model Name: Single-story Work Facility
Address: 2340 HWY 40 E
City Code: MADISON

Current Replacement Value: $68,041
Deferred Maintenance: $7,525
Ext. Gross Area: 440

Site: T798A91523 - MARSHALL - HEADQUARTERS

Building Code: T7980021507
Building Name: MARSHALL - SALT/SAND STORAGE
Facility Condition Index: 0.21 - Fair

Cost Model Name: Open Air Storage Structure
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $175,898
Deferred Maintenance: $37,316
Ext. Gross Area: 1,890

Building Code: T7980021523
Building Name: MARSHALL - SALT/SAND STORAGE
Facility Condition Index: 0.09 - Good

Cost Model Name: Open Air Storage Structure
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $1,380,651
Deferred Maintenance: $120,384
Ext. Gross Area: 14,942

Building Code: T7980091523
Building Name: MARSHALL - HEADQUARTERS
Facility Condition Index: 0.19 - Fair

Cost Model Name: Joint Office/Warehouse Facility
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $16,112,812
Deferred Maintenance: $3,061,106
Ext. Gross Area: 63,034

Building Code: T7980091524
Building Name: MARSHALL - MISC STORAGE
Facility Condition Index: 0.31 - Poor

Cost Model Name: Single-story Work Facility
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $63,198
Deferred Maintenance: $19,648
Ext. Gross Area: 560

Building Code: T7980091532
Building Name: MARSHALL - MISC STORAGE
Facility Condition Index: 0.22 - Fair

Cost Model Name: Butler-style Warehouse Building
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $387,752
Deferred Maintenance: $87,058
Ext. Gross Area: 3,120

Building Code: T7980091535
Building Name: MARSHALL - MISC STORAGE
Facility Condition Index: 0.33 - Poor

Cost Model Name: Butler-style Warehouse Building
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $1,467,216
Deferred Maintenance: $481,784
Ext. Gross Area: 8,167

Building Code: T7980091537
Building Name: MARSHALL - MISC STORAGE
Facility Condition Index: 0.11 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $230,226
Deferred Maintenance: $25,736
Ext. Gross Area: 1,600

Building Code: T7980091543
Building Name: MARSHALL - POLE STORAGE BLDG
Facility Condition Index: 0.14 - Good

Cost Model Name: Butler-style Warehouse Building
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $265,812
Deferred Maintenance: $36,814
Ext. Gross Area: 2,601

Building Code: T7980091548
Building Name: MARSHALL - BRINE BLDG
Facility Condition Index: 0.05 - Excellent

Cost Model Name: Single-story Work Facility
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $284,787
Deferred Maintenance: $13,767
Ext. Gross Area: 1,757

Building Code: T7980091556
Building Name: MARSHALL - HAZMAT STORAGE
Facility Condition Index: 0.33 - Poor

Cost Model Name: Utility Shed
Address: 1800 EAST COLLEGE DRIVE
City Code: MARSHALL

Current Replacement Value: $34,507
Deferred Maintenance: $11,387
Ext. Gross Area: 135

Site: T798A91534 - SLAYTON - TRUCK STATION

Building Code: T7980021508
Building Name: SLAYTON - SALT/SAND STORAGE
Facility Condition Index: 0.20 - Fair

Cost Model Name: Open Air Storage Structure
Address: 891 US Hwy 59
City Code: SLAYTON

Current Replacement Value: $531,901
Deferred Maintenance: $108,111
Ext. Gross Area: 4,284

Building Code: T7980091550
Building Name: SLAYTON - BRINE BUILDING
Facility Condition Index: 0.08 - Good

Cost Model Name: Single-story Work Facility
Address: 891 US Hwy 59
City Code: SLAYTON

Current Replacement Value: $178,630
Deferred Maintenance: $14,690
Ext. Gross Area: 1,210

Building Code: T7980091553
Building Name: SLAYTON - TRUCK STATION
Facility Condition Index: 0.04 - Excellent

Cost Model Name: Butler-style Warehouse Building
Address: 891 US HWY 59
City Code: SLAYTON

Current Replacement Value: $979,525
Deferred Maintenance: $43,407
Ext. Gross Area: 5,888

Site: T798A91536 - REDWOOD FALLS - TRUCK STATION

Building Code:	T7980021512	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$262,387
Building Name:	REDWOOD FALLS - GRADER STORAGE	**Address:**	217 QUALITY DRIVE	**Deferred Maintenance:**	$24,127
Facility Condition Index:	0.09 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	1,440
Building Code:	T7980021525	**Cost Model Name:**	Fabric Structure	**Current Replacement Value:**	$528,469
Building Name:	REDWOOD FALLS-SALT/SAND STRG	**Address:**	217 QUALITY DRIVE	**Deferred Maintenance:**	$47,868
Facility Condition Index:	0.09 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	6,403
Building Code:	T7980091536	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$888,784
Building Name:	REDWOOD FALLS - TRUCK STATION	**Address:**	217 QUALITY DRIVE	**Deferred Maintenance:**	$208,277
Facility Condition Index:	0.23 - Fair	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	5,305
Building Code:	T7980091538	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$50,376
Building Name:	REDWOOD FALLS - MISC STORAGE	**Address:**	217 QUALITY DRIVE	**Deferred Maintenance:**	$5,850
Facility Condition Index:	0.12 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	411
Building Code:	T7980091546	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$81,253
Building Name:	REDWOOD FALLS - BRINE BUILDING	**Address:**	217 QUALITY DRIVE	**Deferred Maintenance:**	$8,125
Facility Condition Index:	0.10 - Good	**City Code:**	REDWOOD FALLS	**Ext. Gross Area:**	610

Site: T798A91539 - GRANITE FALLS - TRUCK STATION

Building Code:	T7980021513	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$273,754
Building Name:	GRANITE FALLS - SALT/SAND STORAGE	**Address:**	5530 HWY 67	**Deferred Maintenance:**	$46,313
Facility Condition Index:	0.17 - Fair	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	2,650
Building Code:	T7980021521	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$1,199,764
Building Name:	GRANITE FALLS - SALT/SAND STORAGE	**Address:**	5530 HWY 67	**Deferred Maintenance:**	$131,838
Facility Condition Index:	0.11 - Good	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	9,734
Building Code:	T7980091539	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,830,917
Building Name:	GRANITE FALLS - TRUCK STATION	**Address:**	5530 HWY 67	**Deferred Maintenance:**	$36,618
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	6,155
Building Code:	T7980091544	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$48,606
Building Name:	GRANITE FALLS - BRINE BUILDING	**Address:**	5530 HWY 67	**Deferred Maintenance:**	$3,378
Facility Condition Index:	0.07 - Good	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	256
Building Code:	T7980091557	**Cost Model Name:**	Utility Shed	**Current Replacement Value:**	$27,179
Building Name:	GRANITE FALLS - MISC STORAGE	**Address:**	5530 HWY 67	**Deferred Maintenance:**	$544
Facility Condition Index:	0.02 - Excellent	**City Code:**	GRANITE FALLS	**Ext. Gross Area:**	240

Site: T798A91541 - TRACY - TRUCK STATION

Building Code:	T7980021517	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$708,565
Building Name:	TRACY - SALT/SAND STORAGE	**Address:**	1040 4TH ST E	**Deferred Maintenance:**	$147,581
Facility Condition Index:	0.21 - Fair	**City Code:**	TRACY	**Ext. Gross Area:**	6,905
Building Code:	T7980091541	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$997,616
Building Name:	TRACY - TRUCK STATION	**Address:**	1040 4TH ST E	**Deferred Maintenance:**	$309,098
Facility Condition Index:	0.31 - Poor	**City Code:**	TRACY	**Ext. Gross Area:**	5,111

Site: T798A91542 - PIPESTONE - TRUCK STATION

Building Code:	T7980021518	**Cost Model Name:**	Open Air Storage Structure	**Current Replacement Value:**	$881,734
Building Name:	PIPESTONE - SALT/SAND STORAGE	**Address:**	604 4TH ST NW	**Deferred Maintenance:**	$106,116
Facility Condition Index:	0.12 - Good	**City Code:**	PIPESTONE	**Ext. Gross Area:**	8,200
Building Code:	T7980091542	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,554,386
Building Name:	PIPESTONE - TRUCK STATION	**Address:**	604 4TH ST NW	**Deferred Maintenance:**	$203,873
Facility Condition Index:	0.13 - Good	**City Code:**	PIPESTONE	**Ext. Gross Area:**	8,808
Building Code:	T7980091545	**Cost Model Name:**	Single-story Work Facility	**Current Replacement Value:**	$90,476
Building Name:	PIPESTONE - BRINE BUILDING	**Address:**	604 4TH ST NW	**Deferred Maintenance:**	$9,975
Facility Condition Index:	0.11 - Good	**City Code:**	PIPESTONE	**Ext. Gross Area:**	625

Site: T798A91552 - IVANHOE - TRUCK STATION

Building Code:	T7980091552	**Cost Model Name:**	Butler-style Warehouse Building	**Current Replacement Value:**	$1,406,193
Building Name:	IVANHOE - TRUCK STATION	**Address:**	513 WEST DIVISION	**Deferred Maintenance:**	$128,073
Facility Condition Index:	0.09 - Good	**City Code:**	IVANHOE	**Ext. Gross Area:**	19,983