

# Weekly Construction Update

Apr 13 – 17, 2015



## Minnesota State Capitol Restoration Project

Architectural Integrity. Building  
Functionality. Life Safety.

### What's New this Week

- The Quadriga charioteer's repairs are complete and preparations are underway to reinstall it the week of 4/20.
- Architects will assess exterior stone on the Capitol dome for repair and restoration needs.
- Quadriga level: New concrete floor slab and waterproofing systems are complete. Quarry tile being installed on top.



### New Website Launched!

- The Minnesota State Capitol Restoration Project has a new [website!](#)
- Expanded to include more content such as:
  - [Educators section](#) to bring the history of the original Capitol construction and new construction to the classroom.
  - [Behind-the-scenes](#) videos, pictures, weekly blog, and slide shows.
  - [Visiting the Capitol](#) page has links to all pertinent information and is a great page to bookmark.
- Easy-to-navigate design means you'll find information faster.
- The website will evolve as the restoration project continues.

Images of the Week ..... Page 2

More images of the Week ..... Page 3

### Looking Ahead - Interior

- All House Chamber light fixtures will be removed and either replaced or restored after 2015 session is over.

### Looking Ahead - Exterior

- South façade: All windows have been removed on south façade except areas occupied by tenants. These will be removed after session.
- West Wing: Demolition will continue on the south façade.

Cutting a channel  
in the floor for  
electrical conduit.



### Featured Notice

**"Prosperity," the charioteer removed from the Quadriga last fall for repairs, will be hoisted back into place the week of April 20, weather permitting.**

# Images of the Week

Apr 13 – 17, 2015



## Minnesota State Capitol Restoration Project


Architectural Integrity. Building  
Functionality. Life Safety.



Double shifts helped build the 7-story scaffolding in the Rotunda over spring break.

 See more!

A worker focuses on welding a pipe in the Capitol basement.



## Questions or Comments?

### Capitol Complex Tenant Inquiries

Cathy Klima, Communications Officer, Capitol Restoration  
Department of Administration  
[cathy.klima@state.mn.us](mailto:cathy.klima@state.mn.us) | 651-201-2627

### Press Inquiries

Curt Yoakum, Director, Communications and Legislation  
Department of Administration  
[curtis.yoakum@state.mn.us](mailto:curtis.yoakum@state.mn.us) | 651-201-2771

Visiting the Capitol? See the [Minnesota State Capitol Restoration Project website](#).

To browse planning and communications documents about this project visit the [Minnesota State Capitol Preservation Commission website](#).

# Images of the Week

Apr 13 – 17, 2015



## Minnesota State Capitol Restoration Project

Architectural Integrity. Building  
Functionality. Life Safety.



The Art Subcommittee of the Minnesota Capitol Preservation Commission review the Governor's Reception Room.

Scaffolding erected in the Rotunda will extend all the way to its ceiling for electrical work, plaster repairs and decorative painting restoration.

Learn the latest about parking, accessibility, news, and FAQs. Visit the [Minnesota State Capitol Restoration Project website](#).