Appendix M

MPCA What's In My Neighborhood Sites

County	MPCA Site Name	Туре	Status	Description	Nearest Project Route	Section	Approximate Distance to Centerline (feet)
Roseau	U.S. Customs Building	Leak Site	Inactive	Fuel Oil 1 & 2 release Site closure: June 2001 No offsite contamination	Border Crossing Hwy 310 Variation in Border Crossing Variation Area	West	400
	Mende Auto Body & Muffler	Haz Waste Site	Active	Small to Minimal Quantity Generator	Proposed Blue/Orange Route in the Roseau Lake WMA Variation Area	West	1,735
	Ray Horner Farm	Feedlot	Active	Registered feedlot with 10 or more animal units (AU)	Proposed Blue/Orange Route in the Roseau Lake WMA Variation Area	West	1,720
	Knudson Brothers Farm Inc	Tank Site	Inactive	Tank Data not available	Cedar Bend WMA Variation in the Cedar Bend Variation Area	West	660
	Quentin Grittner Farm	Feedlot	Active	Registered feedlot with 10 or more animal units (AU)	Roseau Lake WMA Variation 1 in the Roseau Lake WMA Variation Area	West	1,285
	Skoglund Farm	Feedlot	Active	Registered feedlot with 10 or more animal units (AU)	Roseau Lake WMA Variation 1 in the Roseau Lake WMA Variation Area	West	476
	Nelson Residence	Leak Site	Inactive	Petroleum tank release. Site closure: May 2013	Roseau Lake WMA Variation 1 in the Roseau Lake WMA Variation Area	West	1,900
	Harvey Johnson Farm	Feedlot	Active	Registered feedlot with 10 or more animal units (AU)	Border Crossing 500kV Variation in the Border Crossing Variation Area	West	2,094
Lake of the Woods	Williams Dump Site	Investigation and Cleanup	Inactive	State Assessment Site Unpermitted Dump Site closure: June 1978	Beltrami North Central Variation 4 in the Beltrami North Central Variation Area	West	116
	Calvin Carson Farm	Feedlot	Active	Registered feedlot with 10 or more animal units (AU)	Beltrami North Central Variation 4 in the Beltrami North Central Variation Area	West	1,226

County	MPCA Site Name	Type	Status	Description	Nearest Project Route	Section	Approximate Distance to Centerline (feet)
Lake of the Woods	Northstar Electric Cooperative	Haz Waste Site	Active	Small to Minimal Quantity Generator	Proposed Blue Route in the Pine Island Variation Area	Central	812
	MNDOT Truck Station	Leak Site (1504)	Inactive	Gasoline release. Groundwater cont. Closure date: 09/26/1995 Remaining soil contamination Offsite contamination unknown	Proposed Blue Route in the Pine Island Variation Area	Central	812
	Petal Pushers	Leak Site	Inactive	Diesel; Gasoline Leaded Release. Closure date: 02/23/2001 Remaining soil contamination Offsite contamination unknown	Proposed Blue Route in the Pine Island Variation Area	Central	812
Koochiching	Northome Modified Sanitary Landfill	Investigation and Cleanup	Active	State Assessment Site SA 7935 (Active) Unpermitted Dump Site REM04735 (Inactive)	J2 Segment Option Variation in the J2 Variation Area	Central	680
	Northome Modified Sanitary Landfill	Solid Waste	Inactive	Landfill Closed (SW-225). Owned by MPCA. Groundwater Monitoring Data.	J2 Segment Option Variation in the J2 Variation Area	Central	680
	Northome Modified Sanitary Landfill	Industrial Stormwater Permit	Inactive	Industrial SW Permit Termination: 03/17/2000	J2 Segment Option Variation in the J2 Variation Area	Central	680
Koochiching	Northome Modified Sanitary Landfill	Industrial Stormwater Permit	Active	ISW No Exposure Exclusion. Effective Start: 12/15/2010	J2 Segment Option Variation in the J2 Variation Area	Central	680

County	MPCA Site Name	Туре	Status	Description	Nearest Project Route	Section	Approximate Distance to Centerline (feet)
	Loman Dump	Investigation and Cleanup	Active	State Assessment Site SA 7925 (Active) Unpermitted Dump Site REM04478 (Inactive)	J2 Segment Option Variation in the J2 Variation Area	Central	62
Itasca	Balsam Lake II Dump	Investigation and Cleanup	Active	State Assessment Site SA 7858 (Active)Unpermitted Dump Site REM03558 (Inactive)	Proposed Orange Route in the Balsam Variation Area	East	530
	Balsam Store	Tank Site	Inactive	Last site inspection: 05/05/2014 Field Citation MPCA - Closure date: 07/15/14	Proposed Orange Route in the Balsam Variation Area	East	1,710
	Former Balsam Store	Leak Site	Inactive	Diesel; Gasoline, Unleaded release Site Closure: 09/12/2014 Contaminated Soils Remaining Offsite Contamination	Proposed Orange Route in the Balsam Variation Area	East	2,012
	Former Balsam Store	Tank Site	Inactive	Last tank removal: 11/16/1998 Last site inspection: 04/08/1999	Proposed Orange Route in the Balsam Variation Area	East	2,012
	Rhunde Media	Leak Site	Inactive	Fuel Oil 1 & 2; Gasoline release. Site closure: 12/31/1997 Unknown soil and offsite contamination	Proposed Blue/Orange Route near Taconite	East	2,078
Itasca	Bray Lake Outlying Canister	Solid Waste	Active	Permit-by-Rule landfill. Facility permit: 10/24/2010 Inspection: 09/24/2010	Proposed Blue Route in the Balsam Variation Area	East	1,312

County	MPCA Site Name	Туре	Status	Description	Nearest Project Route	Section	Approximate Distance to Centerline (feet)
	Bray Lake Demolition & Disposal	Solid Waste	Active	Open Landfill. Facility permit: 08/06/2008 Last routine inspection: 07/17/12	Proposed Blue Route in the Balsam Variation Area	East	1,600
	MNDOT District 1b Deer Lake	Haz Waste Site	Active	Small to Minimal Quantity Generator	Proposed Blue Route in the Pine Island Variation Area	Central	775
	Wamp Lake Dump	Investigation and Cleanup	Inactive	State Assessment Site SA 7862 (Inactive) Unpermitted Dump Site REM05349 (Inactive)	Effie Variation in the Effie Variation Area	East	1,834
	Reckinger Solid Waste Site	Solid Waste	Inactive	Permit-by-Rule landfill.	East Bear Lake Variation in the East Bear Lake Variation Area	East	1,710
	Balsam Elementary School	Leak Site	Inactive	Fuel Oil 1 & 2 release. Site closure: 01/02/2004 Contaminated Soils Remaining	Balsam Variation in the Balsam Variation Area	East	610
	Iron Range Sanitary Landfill	Investigation and Cleanup	Active	State Assessment Site SA 7864 (Active) Unpermitted Dump Site REM04283 (Inactive)	Balsam Variation in the Balsam Variation Area	East	2,074
	Iron Range Sanitary Landfill	Solid Waste	Inactive	Landfill Closed . Owned by MPCA. Groundwater Monitoring Data (EDA - 2764).	Balsam Variation in the Balsam Variation Area	East	2,074
Itasca	Iron Range Sanitary Landfill	Industrial Stormwater Permit	Active	ISW No Exposure Exclusion. Effective Start: 12/15/2010	Balsam Variation in the Balsam Variation Area	East	2,074

Source: Minnesota Pollution Control Agency 2015.