

## State Academies

### 1. Security Corridor/Smith and Quinn Hall renovation

Smith Hall: Doors swing into hallways which is a safety concern



Smith Hall: Outdated high school science lab



Quinn Hall: Outdated, inaccessible classrooms




Quinn Hall: Outdate inaccessible bathroom



## 2. Asset Preservation

ADA Non-Compliant entrance




Structural Concern



70+ Year Old Plumbing



3. Dorm renovation  
MSAB Dorm: Original Soaking Tub/Restroom



MSAB Dorm: Typical Laundry Room



MSAB Dorm: Typical Kitchen

